

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1903	3	47,850
Modular 1 (6-Classroom )	2003	1	5,645
Campus Total			53,495

Category : Exterior Building : Main

arogo	I y . Exterior			unung			
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Quantity	OOW	Ivalik	Replacement	Comments
trance	Exterior Doors - Exterior Wood Door	9 - Courtyard	1	EA	4	0-1 year	Changed to match current
	Exterior Doors - Exterior Wood Door	9 - Courtyard		LA	4	0-1 year	observations. broken door.
	Exterior Stairs - Wood	9 - Courtyard	9	LF	5	6-10 years	Changed to match current observations
	Stair Handrail - Steel_Stair Handrail	9 - Courtyard	9	LF	4	1-2 years	Rusted
	Entrance Control - Audio and Video	Door 3 - South	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 3 - South	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 3 - South	2	EA	6	10+ years	
	Entrance Control - Audio and Video	Door 4 - West	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 4 - West	3	EA	7	10+ years	Changed to match current observations
	Exterior Doors - Transom Lite	Door 4 - West	3	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 4 - West	20	LF	7	10+ years	Newly replaced
	Entrance Control - Audio and Video	Door 5 - North	1	EΑ	7	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 5 - North	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 5 - North	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 5 - North	10	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 6 - North	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 6 - North	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 6 - North	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 6.5 - East	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 7 - East	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 7 - East	3	LF	6	10+ years	



	ry : Exterior		R	uilding	· Main		
Jaiego	I Y . LAIGHUI		D	unung	. Iviaiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
о. о р	Exterior Doors - Exterior Wood Door	Door 8 - South	1	EA	4	1-2 years	Deteriorated/Peeling wood
	Exterior Doors - Transom Lite	Door 8 - South	1	EΑ	4	1-2 years	Deteriorated wood
	Exterior Stairs - Concrete	Door 8 - South	3	LF	5	1-2 years	Chipping /Cracking
	Exterior Doors - Exterior Steel Door	E Fire Escape 2nd & 3rd Floor	2	EA	6	6-10 years	Changed to match current
	Extendi Doors Extendi Oteol Door	E i ne Escape zna a cia i loci	2		O	o to years	observations
	Exterior Doors - Side lite	E Fire Escape 2nd & 3rd Floor	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	E Fire Escape 2nd & 3rd Floor	2	EA	6	10+ years	
	Exterior Stairs - Concrete	E Fire Escape 2nd & 3rd Floor	10	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	NW Fire Escape	1	EA	6	10+ years	
	Exterior Stairs - Concrete	NW Fire Escape	3	LF	6	10+ years	
Fire Esca	ape						
	Exterior Doors - Exterior Steel Door	East Façade	2	EA	6	10+ years	
	Exterior Doors - Side lite	East Façade	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	East Façade	2	EA	6	10+ years	
	Fire Escape	East Façade	120	LF	6	10+ years	Fence exit is chain locked
	Paints	East Façade	120	LF	5	6-10 years	
	Swing Stairs	East Façade	1	ĒΑ	5	10+ years	
	Exterior Doors - Exterior Steel Door	Façade- NW	1	EA	6	10+ years	
	Fire Escape	Façade- NW	20	LF	6	10+ years	
	Paints	Façade- NW	20	LF	5	10+ years	
Foundati	on						
	Foundation - Concrete	Entire Building	476	LF	6	10+ years	
	Foundation - Concrete	Entire Building	14	LF	5	0-1 year	Spalled bricks
	Superstructure - Heavy Timber	Entire Building	47,850	SF	7	10+ years	·
ighting							
0 0	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	5	1-2 years	Broken light fixture outside the 2nd floor fire escape door
Roof Sys							
	Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
	Coping - Clay Tile	Roof 1	180	LF	4	0-1 year	Cracking/Loose coping
	Coping - Stone	Roof 1	180	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	40	LF	7	10+ years	Replaced
	Downspouts - Exterior Downspouts	Roof 1	152	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 1	360	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	4,730	SF	6	10+ years	
	Roof Structure - Heavy Timber	Roof 1	4,730	SF	7	10+ years	
	<b>,</b>		,			,	
	Access Ladder - Metal	Roof 2	1	EA	7	10+ years	

Campus Name: Everett Page : 2 of 27 Assessment Date: 10/17/2023



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Exterior Downspouts	Roof 2	65	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 2	52	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 2	20	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 2	25	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 2	2,650	SF	6	6-10 years	
	Roof Structure - Heavy Timber	Roof 2	2,650	SF	7	10+ years	
	Access Ladder - Metal	Roof 3	1	EA	7	10+ years	
	Coping - Metal	Roof 3	101	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	80	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 3	55	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 3	20	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 3	26	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3	2,480	SF	6	10+ years	
	Roof Hatch - Metal	Roof 3	1	EA	7	10+ years	
	Roof Structure - Heavy Timber	Roof 3	2,480	SF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 4	63	LF	6	10+ years	
	Liner						
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 4	13	LF	5	10+ years	
	Liner					•	
	Chimney - Metal Flue	Roof 4	73	LF	6	10+ years	
	Coping - Clay Tile	Roof 4	162	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 4	90	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 4	162	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 4	2,650	SF	6	6-10 years	
	Roof Structure - Heavy Timber	Roof 4	2,650	SF	7	10+ years	
	Coping - Metal	Roof 5	75	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 5	4	LF	7	10+ years	
	Roof - Asphalt Shingle	Roof 5	362	SF	7	10+ years	
	Roof Structure - Heavy Timber	Roof 5	362	SF	7	10+ years	
	Coping - Metal	Roof 6	75	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 6	4	LF	6	10+ years	
	Roof - Asphalt Shingle	Roof 6	362	SF	7	10+ years	
	Roof Structure - Heavy Timber	Roof 6	362	SF	7	10+ years	
	Coping - Metal	Roof 7	75	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 7	4	LF	6	10+ years	
	Roof - Asphalt Shingle	Roof 7	360	SF	7	10+ years	
	Roof - Asphalt Shingle	Roof 7	2	SF	4	0-1 year	Missing shingle
	Roof Hatch - Metal	Roof 7	1	EA	3	1-2 years	Screwed shut
	Roof Structure - Heavy Timber	Roof 7	362	SF	7	10+ years	
	Coping - Metal	Roof 8	75	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 8	4	LF	6	10+ years	
	Roof - Asphalt Shingle	Roof 8	362	SF	7	10+ years	
	Roof Structure - Heavy Timber	Roof 8	362	SF	7	10+ years	
	·					·	



Group

Walls

**Category: Exterior** 

Wall

Item - Type

Cheek-Wall - Stone

Exterior Walls - Brick

Exterior Walls - Brick

Cornice - Metal Projecting

Exterior Walls - Stone-Cut

Exterior Walls - Prefabricated Metal Panel

#### **Edward Everett Elementary School**

Open joints/deteriorated

3419 S Bell AVENUE, Chicago, IL 60608

Exterior Walls - Stone-Cut Exterior Walls - Stone-Cut	Entire Building Entire Building	5,375	SF SF	5	10+ years 10+ years	
Exterior Walls - Stone-Cut	Entire Building	20	SF	4	1-2 years	Cracking
Exterior Walls - Terra Cotta	Entire Building	400	SF	6	10+ years	•
ndows						
Guard - Guards wire guard	Entire Building	1,410	SF	6	10+ years	
Lintels - Brick	Entire Building	525	LF	6	10+ years	
Lintels - Steel	Entire Building	44	LF	6	10+ years	
Lintels - Stone	Entire Building	110	LF	6	10+ years	
Lintels - Terra Cotta	Entire Building	20	LF	6	10+ years	
Skylite - Glass Single-Pane	Entire Building	64	SF	6	6-10 years	
Windows - Louver	Entire Building	2	SF	6	10+ years	
Windows - Sash Aluminum	Entire Building	270	SF	4	1-2 years	Deteriorating
Windows - Sash Aluminum	Entire Building	120	SF	3	0-1 year	Broken glass/deteriorating wood frame/leaking
Windows - Sash Aluminum Double-pane	Entire Building	6,014	SF	6	6-10 years	•
Windows - Sash Aluminum Double-pane	Entire Building	36	SF	4	0-1 year	Broken/cracked glass window
egory : Electrical		В	uilding	: Main		
					Recommend	
oup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ergency System						
Security System - CCTV	1st Floor	47,850	SF	6	6-10 years	
Security System - Intrusion Detection	1st Floor	47,850	SF	6	6-10 years	
Emergency Battery Packs - Multipurpose Room	3rd Floor	2	EA	7	10+ years	New battery packs emergency light LED
Automatic Transfer Switch	Basement	1	EΑ	6	6-10 years	
Exit Signs - Corridors and Stairs	Entire Building	17	EA	2	0-1 year	Exit signs over 20 years old
Exit Signs - Lunchroom	Entire Building	2	EA	2	0-1 year	Exit signs over 20 years old
Exit Signs - Multipurpose Room	Entire Building	6	EΑ	2	0-1 year	Exit signs over 20 years old
Emergency A/C Power - Corridors and Stairs	Entire Building	3,023	SF	6	6-10 years	
n Service						
PA System	1st Floor	47,850	SF	6	10+ years	
FA System	ISI FIOOI	,555			,	

Location

**Entire Building** 

Entire Building

Entire Building

**Entire Building** 

Entire Building

**Entire Building** 

**Building: Main** 

Rank

6

6

6

4

6

UOM

SF

LF

SF

SF

SF

SF

Quantity

20

80

360

5,375

550

16,095

Recommend

10+ years

10+ years

10+ years

1-2 years

10+ years

10+ years

Replacement Comments



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Independent Electrical Service for	Entire Building	1	EA	6	6-10 years	
	emergency power Main Electrical Service - 1200 A	Mechanical Room	1	EA	4	6 10 vooro	Danal over FOL years
	120/208/3PH	Mechanical Room	ı	EA	4	6-10 years	Panel over 50+ years
	120/200/3111						
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Rusted.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	ΕA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	3	1-2 years	Panel is rusted and in bad condition
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	2	1-2 years	Panel over 40 years old.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	Tallel over 40 years old.
	Main Distribution Panels - Less than 400	Entire Building	1	EA	6	6-10 years	
	amp	Entire Building	'	LA	O	0-10 years	
_	•						
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar	-		•			•	
	Fire Alarm Panel	Entire Building	1	EA	3	1-2 years	Fire panel obsolete over 50+ years
	Fire Alarm_System	Entire Building	47,850	SF	5	1-2 years	Fire alarm system over 50+ years
	Fire Pump Controller	Entire Building	1	EA	5	6-10 years	Fire pump controller in the
	The Full position of	Entire Ballating	· ·		· ·	o ro youro	construction area no access
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Basement	1	EA	5	6-10 years	Fire pump located inside construction
							area, no access.
Sprinkler	System						
Sprinklei	Dry Sprinkler System	Entire Building	47,850	SF	6	6 10 years	Dry sprinkler located inside
	Dry Sprinkier System	Entire building	47,650	SF	О	6-10 years	construction area, no access.
	Sprinkler Heads	Entire Building	47,850	SF	7	6-10 years	constituction area, no access.
	Sprinkler Piping	Entire Building	47,850	SF	6	6-10 years	
	op	g	,		-	5 . c , c c	
Catego	ry : Mechanical		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone-	Mechanical Room	1	EA	5	2-5 years	

Campus Name: Everett Page : 5 of 27 Assessment Date: 10/17/2023



Catego	Category : Mechanical		В	-			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Steam Coils - 25001 - 35000 cfm						
	Air Intake	Mechanical Room	1	EA	6	2-5 years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	5	2-5 years	
	Return Duct Work - Masonry and Ducts-	Mechanical Room	100	LF	5	2-5 years	
	Missing or Existing Shaft						
	Zone Dampers	Mechanical Room	15	EΑ	5	2-5 years	Zones dumpers over 60 years old.
	Zone Dampers	Mechanical Room	8	EA	3	2-5 years	Zones dumpers over 60 years old.
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	1	EA	5	6-10 years	
	Pressure Boiler - 101 - 150 HP				_		
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	5	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	5	6-10 years	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	5	6-10 years	
	Steam- Low Pressure Boiler - 101 - 150 HP						
	Piping - Condensate Pipe- Steel	Boiler Room	100	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	100	LF	5	6-10 years	
	Steam Traps	Boiler Room	20	EA	5	6-10 years	
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	1	EA	5	6-10 years	
	Pressure Boiler - 76 - 100 HP						
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EΑ	5	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EΑ	5	6-10 years	
	Steam- Low Pressure Boiler - 76 - 100 HP						
	Piping - Condensate Pipe- Steel	Boiler Room	100	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	100	LF	6	6-10 years	
	Steam Traps	Boiler Room	18	EA	5	6-10 years	
Heating	Devices						
	Cabinet Heaters - With Steam Coil	Basement	6	EA	6	10+ years	
	Radiators - Steam	Entire Building	4	EA	6	6-10 years	
	Radiators - Steam	Entire Building	2	EA	6	6-10 years	
	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years	
		Entire Building		EA	6	6-10 years	
	Unit Heater - Gas		2				Over 20 years old
	Wall Heater - Electric	Entire Building	8	EA	2	0-1 year	Over 20 years old



<u>Pumps</u>

#### **Edward Everett Elementary School**

3419 S Bell AVENUE, Chicago, IL 60608

700	JC110013						34 19 3 Bell AVENUE, Chicago, IL 60
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Tempera	ature Control						
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	
	Pneumatic System	Entire Building	47,850	SF	5	6-10 years	
	Thermostats - Pneumatic	Entire Building	6	EA	7	6-10 years	
	Thermostats - Pneumatic	Entire Building	20	EA	5	6-10 years	
√entilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	Exhaust fans room 106 in construction area no access
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	3	0-1 year	Exhaust fans not running
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	7	10+ years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	10+ years	Kitchen is under construction no access
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	47,850	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	47,850	SF	6	6-10 years	
	Domestic Pining-Hot Water from Risers to	Entire Building	47 850	SF	6	6-10 years	

Domestic Piping-Hot Water from Risers to **Entire Building** 47,850 6-10 years SF 6 **Fixtures** Domestic Piping-Hot/Cold Water Supply **Entire Building** SF 6-10 years 47,850 6 (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply **Entire Building** 47,850 SF 6 6-10 years (Risers) Domestic Piping-Hot/Cold Water Supply **Entire Building** 47,850 SF 6 6-10 years Pipes inside the wall (from Risers to Fixtures) Sanitary Piping **Entire Building** SF 6-10 years 47,850 6 Storm Piping Entire Building 47,850 6-10 years SF 6 Vent Piping Entire Building 47,850 6-10 years SF 6

Campus Name: Everett Page : 7 of 27 Assessment Date: 10/17/2023



**Building: Main Category: Plumbing** 

Recommend Location Group Item - Type Quantity UOM Rank Comments Replacement Pumps - Domestic Booster Pump-Simplex **Entire Building** 2-5 years Pump not running, building use city EΑ 5 water pressure.

Category: Room **Building: Main** 

0	Many Time	Lagation	Overetite	ПОМ	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices	4 (5)					
	Ceiling - Plaster/Drywall	1st Floor - Office (Main)	338	SF	6	10+ years	
	Doors - Side-lite	1st Floor - Office (Main)	85	SF	7	10+ years	
	Doors - Side-lite	1st Floor - Office (Main)	5	SF	4	1-2 years	Missing glass
	Doors - Transom Window	1st Floor - Office (Main)	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Office (Main)	1	EA	6	10+ years	
	Floor - Wood	1st Floor - Office (Main)	338	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor - Office (Main)	6	EA	7	6-10 years	
	Power Distribution	1st Floor - Office (Main)	14	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor - Office (Main)	906	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Office (Main)	10	SF	6	10+ years	Peeling paint
	AC Unit	1st Floor - Principal's Office (In Main Office)	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Principal's Office (In Main Office)	180	SF	6	10+ years	Extensive peeling paint throughout walls and ceiling
	Doors - Wood Doors inclu hw	1st Floor - Principal's Office (In Main Office)	1	EA	6	6-10 years	nano ano coming
	Floor - Wood	1st Floor - Principal's Office (In Main Office)	180	SF	7	6-10 years	
	Lighting - Chandelier, Incandescent	1st Floor - Principal's Office (In Main Office)	3	EA	7	6-10 years	
	Power Distribution	1st Floor - Principal's Office (In Main Office)	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor - Principal's Office (In Main Office)	328	SF	6	10+ years	Extensive peeling paint throughout
	Ceiling - Plaster/Drywall	1st Floor Teacher's Lounge	380	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Teacher's Lounge	20	SF	4	1-2 years	Water damage
	Doors - Transom Window	1st Floor Teacher's Lounge	9	SF	6	10+ years	ŭ
	Doors - Wood Doors inclu hw	1st Floor Teacher's Lounge	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor Teacher's Lounge	300	SF	6	10+ years	
	Floor - Tile	1st Floor Teacher's Lounge	100	SF	4	1-2 years	Damaged tiles
	Lighting - Lay-in	1st Floor Teacher's Lounge	6	ĒΑ	7	6-10 years	g
	Power Distribution	1st Floor Teacher's Lounge	30	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor Teacher's Lounge	720	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Teacher's Lounge	10	SF	6	10+ years	Peeling paint
	Work Sink	1st Floor Teacher's Lounge	1	EA	7	6-10 years	3
	AC Unit	204A	i	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	204A	920	SF	6	6-10 years	

Campus Name: Everett Page : 8 of 27 Assessment Date: 10/17/2023



Catono	ry : Room		D	uilding	· Main		3413 6 Bell Avelvoe, Officago, ie 60000
Calego	iy. Nooiii		Б	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Sioup	Doors - Side-lite	204A	256	SF	6	10+ years	Comments
	Doors - Transom Window	204A	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	204A 204A	1	EA	6	10+ years	
	Floor - Tile	204A 204A	880	SF	6	6-10 years	
	Floor - Tile	204A	40	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	204A 204A	10	EA	7		Damageu liles
	Power Distribution	204A 204A	5	EA	7	6-10 years 10+ years	
	Walls - Plaster/Drywall	204A 204A	1,530	SF	6	6-10 years	
			90	SF	6	•	Engineer does not have key no
	Ceiling - Plaster/Drywall	Basement - 007				10+ years	Engineer does not have key; no access
	Doors - Side-lite	Basement - 007	3	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - 007	1	EA	6	10+ years	
	Floor - Tile	Basement - 007	90	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	Basement - 007	2	EA	6	6-10 years	
	Power Distribution	Basement - 007	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement - 007	94	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - 007	94	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - Engineer's Office	280	SF	6	10+ years	Cracking and peeling paint.
	Floor - Concrete	Basement - Engineer's Office	280	SF	5	2-5 years	
	Lighting - Pendent/Surface	Basement - Engineer's Office	7	EΑ	6	6-10 years	
	Power Distribution	Basement - Engineer's Office	14	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement - Engineer's Office	246	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Engineer's Office	10	SF	4	0-1 year	Wall needs repair
Gymnas	ia						
-	Ceiling - Exposed	3rd Floor	4,335	SF	6	6-10 years	
	Ceiling - Exposed	3rd Floor	10	SF	5	1-2 years	Water damage
	Doors - Side-lite	3rd Floor	196	SF	6	6-10 years	•
	Doors - Transom Window	3rd Floor	36	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	6-10 years	
	Floor - Wood	3rd Floor	4,345	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	<sup>′</sup> 15	EA	7	6-10 years	
	Sound System	3rd Floor	1	EA	7	6-10 years	
	Stage	3rd Floor	512	SF	6	6-10 years	
	Stage Curtain	3rd Floor	9	ĒΑ	7	6-10 years	
	Stage Lighting System	3rd Floor	1	EA	7	10+ years	
	Stage-Stairs - Tile	3rd Floor	10	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4,680	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Water damage.
Kitchen							
	AC Unit	1st Floor - Kitchen - 106	1	EA	5	6-10 years	Currently under renovation
							Currently under renovation
	Cailing - Plaster/Drywall	1st Floor - Kitchen - 106	825	<	6	10± vaare	
	Ceiling - Plaster/Drywall Doors - Transom Window	1st Floor - Kitchen - 106 1st Floor - Kitchen - 106	825 9	SF SF	6 6	10+ years 10+ years	



Catego	ory : Room		В	uilding	: Main		, , , , , , , , , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor - Kitchen - 106	1	EA	6	10+ years	
	Floor - Tile	1st Floor - Kitchen - 106	625	SF	6	10+ years	
	Floor - Tile Quarry	1st Floor - Kitchen - 106	200	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor - Kitchen - 106	12	EΑ	6	6-10 years	
	Serving Line	1st Floor - Kitchen - 106	16	LF	6	10+ years	
	Storage/ Closet	1st Floor - Kitchen - 106	266	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor - Kitchen - 106	1,624	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	1st Floor - Lunch Room 105	945	SF	6	10+ years	No occupancy signage
	Doors - Transom Window	1st Floor - Lunch Room 105	9	SF	6	10+ years	, , 3
	Doors - Wood Doors inclu hw	1st Floor - Lunch Room 105	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor - Lunch Room 105	915	SF	6	10+ years	
	Floor - Tile	1st Floor - Lunch Room 105	30	SF	4	1-2 years	Damaged tiles
	Lighting - Chandelier, Incandescent	1st Floor - Lunch Room 105	14	EA	7	6-10 years	Damaged theo
	Storage/ Closet	1st Floor - Lunch Room 105	50	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor - Lunch Room 105	1,181	SF	6	10+ years	
	AC Unit	Basement - Faculty Room	1,101	EA	7	6-10 years	
			•				
	Ceiling - Plaster/Drywall	Basement - Faculty Room	1,025	SF	6	10+ years	Ob all based
	Chalk Board	Basement - Faculty Room	30	LF	4	2-5 years	Chalkboard
	Doors - Wood Doors inclu hw	Basement - Faculty Room	5	EA	6	10+ years	
	Floor - Tile	Basement - Faculty Room	1,020	SF	5	6-10 years	
	Floor - Tile	Basement - Faculty Room	5	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	Basement - Faculty Room	13	EA	7	6-10 years	
	Market Board	Basement - Faculty Room	25	LF	6	6-10 years	
	Walls - Masonry	Basement - Faculty Room	512	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Faculty Room	512	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement - Girls' Playroom North	945	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement - Girls' Playroom North	4	EΑ	6	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	Basement - Girls' Playroom North	945	SF	7	6-10 years	
	Lighting - Pendent/Surface	Basement - Girls' Playroom North	14	EΑ	7	6-10 years	
	Walls - Masonry	Basement - Girls' Playroom North	620	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement - Girls' Playroom North	620	SF	6	10+ years	
_MDF_ID	)F						
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Finishes	3rd Floor	249	SF	5	1-2 years	Relamp lighting in MDF Peeling paint on doors Cracks in walls in a few areas
	Window AC Unit	3rd Floor	1	EA	7	6-10 years	
_Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	6	SF	5	10+ years	

Campus Name: Everett Page : 10 of 27 Assessment Date: 10/17/2023



Category : Room			Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Storage Room	1st Floor	330	SF	5	10+ years	Under construction	
	Janitor's Closet	2nd Floor	6	SF	5	10+ years	Water damage at ceiling and walls	
	Storage Room	2nd Floor	566	SF	7	10+ years	Room under construction- no access	
	Storage Room	3rd Floor	354	SF	5	2-5 years		
	Air Intake Plenums	Basement	440	SF	5	10+ years		
	Air Tunnel	Basement	400	SF	5	10+ years		
	Boiler Room	Basement	1,440	SF	5	10+ years		
	Coal Room	Basement	720	SF	5	10+ years		
	Crawl Space - Unfinished	Basement	800	SF	5	10+ years	Not accessible, in construction zone	
	Janitor's Closet	Basement	150	SF	5	10+ years		
	Janitor's Closet	Basement	72	SF	5	10+ years		
	Mechanical/ Service Rooms	Basement	960	SF	5	6-10 years		
	Storage Room	Basement	150	SF	5	10+ years		
	Storage Room	Basement	150	SF	5	10+ years		
	Storage Room	Basement	825	SF	5	10+ years		
	Storage Room	Basement	150	SF	5	10+ years		
	3					,		
Restroor	n							
	Accessories	105	23	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	105	23	SF	6	10+ years		
	Doors - Wood Doors inclu hw	105	1	EΑ	6	10+ years		
	Floor - Tile	105	23	SF	5	10+ years		
	Floor Drain	105	1	EA	7	6-10 years		
	Lavatory	105	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	105	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	105	47	SF	6	10+ years		
	Water Closet	105	1	EA	6	6-10 years		
	Accessories	1st Floor - Principal's Office	25	SF	5	2-5 years		
	Ceiling - Plaster/Drywall	1st Floor - Principal's Office	25	SF	6	10+ years	Extensive peeling paint throughout	
	Doors - Wood Doors inclu hw	1st Floor - Principal's Office	1	ĒΑ	6	6-10 years	31	
	Floor - Tile	1st Floor - Principal's Office	20	SF	6	6-10 years		
	Floor - Tile	1st Floor - Principal's Office	5	SF	4	1-2 years	Broken tiles	
	Lavatory	1st Floor - Principal's Office	1	ĒΑ	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor - Principal's Office	1	EA	6	6-10 years		
	Walls - Plaster/Drywall	1st Floor - Principal's Office	55	SF	6	10+ years	Extensive peeling paint throughout	
	Water Closet	1st Floor - Principal's Office	1	ĒΑ	6	6-10 years		
	Accessories	1st Floor - Women Staff (Teacher's	65	SF	5	6-10 years		
	, 10000001100	Lounge)		О.	ŭ	0 .0 you.0		
	Ceiling - Plaster/Drywall	1st Floor - Women Staff (Teacher's	65	SF	6	10+ years		
	coming i lactor bij han	Lounge)	00	٥.	Ŭ	10. 700.0		
	Doors - Wood Doors inclu hw	1st Floor - Women Staff (Teacher's	1	EA	6	10+ years		
	200.0 11000 20010 III0I0 IIIV	Lounge)		_, 、	J	io. youro		
	Floor - Tile Ceramic/ Porcelain	1st Floor - Women Staff (Teacher's	65	SF	6	10+ years		
	. 100. The Coramie Foreign	Lounge)	00	<b>5</b> 1	J	ioi youis		
		Louingo,						



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	1st Floor - Women Staff (Teacher's Lounge)	2	EA	7	6-10 years	
	Lavatory	1st Floor - Women Staff (Teacher's Lounge)	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor - Women Staff (Teacher's Lounge)	2	EA	7	6-10 years	
	Partitions	1st Floor - Women Staff (Teacher's Lounge)	2	EA	5	6-10 years	
	Walls - Plaster/Drywall	1st Floor - Women Staff (Teacher's Lounge)	115	SF	6	10+ years	
	Water Closet	1st Floor - Women Staff (Teacher's Lounge)	2	EA	6	6-10 years	
	Accessories	2nd Floor - Boys	90	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Boys	90	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor - Boys	1	ĒΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Boys	90	SF	6	6-10 years	
	Floor Drain	2nd Floor - Boys	2	EA	7	6-10 years	
	Lavatory	2nd Floor - Boys	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor - Boys	2	EA	7		
		2nd Floor - Boys 2nd Floor - Boys	2	EA	7	6-10 years	
	Partitions					6-10 years	
	Urinals	2nd Floor - Boys	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor - Boys	199	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor - Boys	1	SF	5	1-2 years	Cracked plaster
	Water Closet	2nd Floor - Boys	2	EA	7	6-10 years	
	Accessories	2nd Floor - Girls	265	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Girls	255	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Girls	10	SF	5	1-2 years	Cracked and peeling paint
	Doors - Transom Window	2nd Floor - Girls	9	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Girls	260	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Girls	5	SF	4	1-2 years	Missing tiles
	Floor Drain	2nd Floor - Girls	2	EA	7	6-10 years	3
	Lavatory	2nd Floor - Girls	2	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor - Girls	4	ΕA	7	6-10 years	
	Partitions	2nd Floor - Girls	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor - Girls	640	SF	6	6-10 years	
	Water Closet	2nd Floor - Girls	3	EA	7	6-10 years	
	Accessories		32	SF	7		
		2nd Floor - Mens				6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Mens	32	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor - Mens	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor - Mens	32	SF	7	6-10 years	
	Lavatory	2nd Floor - Mens	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor - Mens	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor - Mens	65	SF	6	6-10 years	
	Water Closet	2nd Floor - Mens	1	EA	7	6-10 years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	Basement	5	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	80	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	80	SF	7	10+ years	
	Floor Drain	Basement	1	EA	7	10+ years	
	Lavatory	Basement	1	EA	7	10+ years	
	Lighting - Lay-in	Basement	2	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement	160	SF	7	10+ years	
	Water Closet	Basement	1	EA	7	10+ years	
	Accessories	Basement - Engineer's Toilet (Janitor's Closet South)	80	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Engineer's Toilet	70	SF	6	10+ years	
	Celling - Flaster/Drywali	(Janitor's Closet South)	70	SF	O	10+ years	
	Ceiling - Plaster/Drywall	Basement - Engineer's Toilet	10	SF	4	1-2 years	Water damage
		(Janitor's Closet South)			_		
	Doors - Wood Doors inclu hw	Basement - Engineer's Toilet (Janitor's Closet South)	1	EA	6	10+ years	
	Floor - Tile	Basement - Engineer's Toilet	80	SF	6	10+ years	
	11001 1110	(Janitor's Closet South)	00	O.	O	101 youro	
	Floor Drain	Basement - Engineer's Toilet	1	EA	7	6-10 years	
		(Janitor's Closet South)				,	
	Lavatory	Basement - Engineer's Toilet	1	EA	6	6-10 years	
		(Janitor's Closet South)					
	Lighting - Pendent/Surface	Basement - Engineer's Toilet	1	EA	6	6-10 years	
		(Janitor's Closet South)					
	Walls - Plaster/Drywall	Basement - Engineer's Toilet (Janitor's Closet South)	136	SF	6	2-5 years	
	Walls - Plaster/Drywall	Basement - Engineer's Toilet	10	SF	5	0-1 year	Damaged gyp
	Traile Tractor, 21 y trail	(Janitor's Closet South)		O.	Ŭ	o i youi	zamagoa gyp
	Water Closet	Basement - Engineer's Toilet	1	EA	6	10+ years	
		(Janitor's Closet South)				,	
	Accessories	Basement - North Girls Toilet	560	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - North Girls Toilet	560	SF	7	10+ years	
	Floor - Tile	Basement - North Girls Toilet	560	SF	7	10+ years	
	Floor Drain	Basement - North Girls Toilet	1	EA	7	6-10 years	
	Lavatory	Basement - North Girls Toilet	4	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement - North Girls Toilet	8	EA	7	10+ years	
	Partitions	Basement - North Girls Toilet	11	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - North Girls Toilet	25	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement - North Girls Toilet	1,208	SF	7	10+ years	
	Water Closet	Basement - North Girls Toilet	11	ĒA	7	10+ years	
	Accessories	Basement - South Boys Toilet	585	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - South Boys Toilet	585	SF	7	10+ years	
	Floor - Epoxy/ Painted	Basement - South Boys Toilet	585	SF	7	10+ years	
		•				·	

Campus Name: Everett Page : 13 of 27 Assessment Date: 10/17/2023



Catego	ry : Room		В	uilding	: Main		•		
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor Drain	Basement - South Boys Toilet	1	EΑ	7	10+ years			
	Lavatory	Basement - South Boys Toilet	4	EA	7	10+ years			
	Lighting - Pendent/Surface	Basement - South Boys Toilet	10	EA	7	10+ years			
	Partitions	Basement - South Boys Toilet	4	EA	7	10+ years			
	Urinals	Basement - South Boys Toilet	10	EA	7	10+ years			
	Walls - Plaster/Drywall	Basement - South Boys Toilet	1,217	SF	7	10+ years			
	Water Closet	Basement - South Boys Toilet	4	EA	7	6-10 years			
	Accessories	Toilet 101A - In room 101	21	SF	5	6-10 years			
	Ceiling - Plaster/Drywall	Toilet 101A - In room 101	21	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Toilet 101A - In room 101	1	EA	6	10+ years			
	Floor - Tile/Sheet	Toilet 101A - In room 101	21	SF	5	10+ years			
	Lavatory	Toilet 101A - In room 101	1	EA	6	6-10 years			
	Lighting - Pendent/Surface	Toilet 101A - In room 101	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	Toilet 101A - In room 101	40	SF	6	10+ years			
	Water Closet	Toilet 101A - In room 101	1	EA	6	6-10 years			

**Building: Main** Category : Classroom

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	om #101 (Regular Classroom)		,				
	AC Units	1st Floor	1	EA	5	6-10 years	
	Casework	1st Floor	20	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	940	SF	5	6-10 years	Peeling paint
	Chalk Board	1st Floor	8	LF	4	2-5 years	<b>.</b>
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Carpet	1st Floor	305	SF	6	6-10 years	
	Floor - Tile	1st Floor	635	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EΑ	7	6-10 years	
	Storage/ Closet	1st Floor	23	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,513	SF	6	10+ years	
Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	980	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
					7	-	
	Floor - Wood	1st Floor	980	SF	1	10+ years	
	Floor - Wood	1st Floor 1st Floor	980 14	SF EA	7 7	6-10 years	
					7 7 5	•	

Campus Name: Everett Page : 14 of 27 Assessment Date: 10/17/2023



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	1	EA	5	6-10 years	
	Casework	1st Floor	15	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	940	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	940	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,524	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
assroc	om #104 (Art Room)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	968	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	958	SF	7	6-10 years	
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Cracking tiles
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	Cracking tiles
	Storage/ Closet	1st Floor	164	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,535	SF	6	10+ years	
			.,		-	, , , , , , , , , , , , , , , , , , ,	
assroc	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	980	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	950	SF	6	6-10 years	
	Floor - Tile	2nd Floor	30	SF	4	1-2 years	Cracked tiles
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Storage/ Closet	2nd Floor	80	SF	5	1-2 years	Peeling paint throughout walls and
	Walls - Plaster/Drywall	2nd Floor	1,513	SF	6	6-10 years	ceiling
	, , , , , , , , , , , , , , , , , , ,					·	
aSS[00	om #202 (Regular Classroom)	Ond Floor		ΓΛ	7	0.40.4225	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	980	SF	6	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	960	SF	6	6-10 years	
	Floor - Tile	2nd Floor	20	SF	4	1-2 years	Cracked tiles
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	90	SF	5	1-2 years	Repair, paint, and Relamp

Campus Name: Everett Page : 15 of 27 Assessment Date: 10/17/2023



Item - Type Walls - Plaster/Drywall Work Sink  #203 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	Location 2nd Floor	Quantity 1,513 2  1 4 935 5 38	UOM SF EA LF SF	<b>Rank</b> 6 7 7 6	Recommend Replacement 6-10 years 6-10 years	Comments
Walls - Plaster/Drywall Work Sink  #203 (Regular Classroom)  AC Units Casework Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	2nd Floor 2nd Floor  2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1,513 2 1 4 935 5	SF EA EA LF	6 7 7	6-10 years 6-10 years 6-10 years	Comments
Work Sink  #203 (Regular Classroom)  AC Units Casework Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	2nd Floor  2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1 4 935 5	EA EA LF	7	6-10 years 6-10 years	
#203 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1 4 935 5	EA LF	7	6-10 years	
AC Units Casework Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	4 935 5	LF			
AC Units Casework Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	4 935 5	LF			
Casework Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	4 935 5	LF			
Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	2nd Floor 2nd Floor 2nd Floor 2nd Floor	935 5			6-10 years	
Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	2nd Floor 2nd Floor 2nd Floor	5		6	6-10 years	
Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	2nd Floor 2nd Floor		SF	5	1-2 years	Water damage
Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	2nd Floor		LF	4	2-5 years	Water damage
Doors - Wood Doors inclu hw Floor - Tile Floor - Tile		9	SF	6	6-10 years	
Floor - Tile Floor - Tile	/00 F1001	1	EA	6		
Floor - Tile				-	6-10 years	
	2nd Floor	930	SF	6	6-10 years	
	2nd Floor	10	SF	4	1-2 years	Cracked tiles
Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
Storage/ Closet	2nd Floor	120	SF	5	2-5 years	
Walls - Plaster/Drywall	2nd Floor	1,513	SF	6	6-10 years	
#204B (Regular Classroom)						
AC Units	2nd Floor	1	EΑ	7	6-10 years	
Casework	2nd Floor	15	LF	7	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	680	SF	7	6-10 years	
					•	
					•	
					•	
walls - Plaster/Drywall	2nd Floor	832	SF	7	10+ years	
#205 (Regular Classroom)						
AC Units		1	EA	7		
Casework	2nd Floor	4	LF	6	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor	940	SF	7	6-10 years	
Doors - Transom Window	2nd Floor	9	SF	6		
Doors - Wood Doors inclu hw		1			-	
		940			•	
					•	
					•	
·	2.10.1.1001	1,510	٥.	•	. o . youro	
	01.51		ΕΛ		0.40	Olasana is an description in
AL. LINITS	2na Floor	1	ĿΑ	1	6-10 years	Classroom is under construction- no
. Co Onito						access
	AC Units Casework Ceiling - Plaster/Drywall	Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Dighting - Pendent/Surface Valls - Plaster/Drywall  #205 (Regular Classroom)  #C Units Casework Ceiling - Plaster/Drywall  Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Dighting - Pendent/Surface  #206 (Regular Classroom)  #207 Floor  #208 Floor  #209 Floor  #209 Floor  #209 Plaster/Drywall  #200 Pendent/Surface  #200 Plaster/Drywall  #200 Plaster/Drywall	2000rs - Transom Window   2nd Floor   9	Doors - Transom Window         2nd Floor         9         SF           Doors - Wood Doors inclu hw         2nd Floor         1         EA           Floor - Wood         2nd Floor         680         SF           sighting - Pendent/Surface         2nd Floor         21         EA           Valls - Plaster/Drywall         2nd Floor         832         SF           #205 (Regular Classroom)         1         EA         EA           Casework         2nd Floor         4         LF           Ceiling - Plaster/Drywall         2nd Floor         940         SF           Doors - Transom Window         2nd Floor         9         SF           Doors - Wood Doors inclu hw         2nd Floor         1         EA           Floor - Tile         2nd Floor         940         SF           Scloor - Tile         2nd Floor         14         EA           Storage/ Closet         2nd Floor         14         EA           Storage/ Closet         2nd Floor         1,513         SF           #206 (Regular Classroom)         2nd Floor         1,513         SF	Doors - Transom Window         2nd Floor         9 SF 6           Doors - Wood Doors inclu hw         2nd Floor         1 EA 6           Floor - Wood         2nd Floor         680 SF 6           Lighting - Pendent/Surface         2nd Floor         21 EA 7           Valls - Plaster/Drywall         2nd Floor         832 SF 7           #205 (Regular Classroom)         2nd Floor         1 EA 7           Casework         2nd Floor         4 LF 6           Ceiling - Plaster/Drywall         2nd Floor         940 SF 7           Doors - Transom Window         2nd Floor         9 SF 6           Doors - Wood Doors inclu hw         2nd Floor         1 EA 6           Cloor - Tile         2nd Floor         940 SF 7           Cloor - Tile         2nd Floor         940 SF 7           Lighting - Pendent/Surface         2nd Floor         14 EA 7           Storage/ Closet         2nd Floor         80 SF 5           Valls - Plaster/Drywall         2nd Floor         1,513 SF 7	Doors - Transom Window         2nd Floor         9         SF         6         6-10 years           Doors - Wood Doors inclu hw         2nd Floor         1         EA         6         6-10 years           Floor - Wood         2nd Floor         680         SF         6         6-10 years           Lighting - Pendent/Surface         2nd Floor         21         EA         7         6-10 years           Valls - Plaster/Drywall         2nd Floor         832         SF         7         10+ years           #205 (Regular Classroom)         2nd Floor         4         LF         6         6-10 years           Ceiling - Plaster/Drywall         2nd Floor         940         SF         7         6-10 years           Ceiling - Plaster/Drywall         2nd Floor         9         SF         6         6-10 years           Ceiling - Plaster/Drywall         2nd Floor         9         SF         6         6-10 years           Ceiling - Plaster/Drywall         2nd Floor         9         SF         6         6-10 years           Ceiling - Plaster/Drywall         2nd Floor         1         EA         6         6-10 years           Ceiling - Plaster/Drywall         2nd Floor         1         EA <td< td=""></td<>

Campus Name: Everett Page : 16 of 27 Assessment Date: 10/17/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	1,005	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,005	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,475	SF	6	10+ years	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	980	SF	6	10+ years	Cracked and peeling paint throughout
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	Cracked and pecining paint infoagno
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	940	SF	6	6-10 years	
					_		Oranka dition
	Floor - Tile	3rd Floor	40	SF	4	1-2 years	Cracked tiles
	Lighting - Pendent/Surface	3rd Floor	14	EΑ	7	6-10 years	
	Marker Board	3rd Floor	3	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	80	SF	5	1-2 years	Cracked and peeling paint througho Water damage
	Walls - Plaster/Drywall	3rd Floor	1,513	SF	6	6-10 years	Cracked and peeling paint througho
Classroc	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	980	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	3rd Floor	975	SF	6	6-10 years	
	Floor - Tile	3rd Floor	5	SF	4	1-2 years	Missing and broken tiles
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	Wilsoling and broken tiles
	Marker Board	3rd Floor	12	LF	6	6-10 years	
		3rd Floor	80	SF	5		Missing and broken floor tiles and
	Storage/ Closet				-	10+ years	cracks in walls
	Walls - Plaster/Drywall	3rd Floor	1,513	SF	6	6-10 years	
Classroc	om #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	940	SF	6	10+ years	Extensive peeling paint throughout
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	. 3.
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	6-10 years	
	Floor - Tile	3rd Floor	930	SF	6	6-10 years	
	Floor - Tile	3rd Floor	10	SF	4	1-2 years	Cracked tiles
	1 1001 1 110	ora i iooi	10	01		i Z yodio	Cracked thes

Campus Name: Everett Page : 17 of 27 Assessment Date: 10/17/2023



Category	: Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	14	EΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	80	SF	5	10+ years	Extensive peeling paint throughout
	Walls - Plaster/Drywall	3rd Floor	1,503	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Large cracks and peeling paint
Classroom	n #306 (Computer Lab)						
	AC Units	3rd Floor	2	EA	7	6-10 years	Under construction- no access
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,005	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,005	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,575	SF	6	10+ years	

				aag		Dagamanand	
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
orridor	, ·		•			•	
	Ceiling - Plaster/Drywall	1st Floor	1,299	SF	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	5	10+ years	
	Floor - Tile/Sheet	1st Floor	1,249	SF	5	10+ years	
	Floor - Tile/Sheet	1st Floor	50	SF	4	1-2 years	Cracked tiles
	Lighting - Chandelier, Incandescent	1st Floor	16	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,348	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,299	SF	6	10+ years	Extensive areas of peeling pair throughout
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,299	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	2nd Floor	17	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,348	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	425	SF	6	10+ years	Extensive peeling and cracks throughout
	Floor - Tile/Sheet	3rd Floor	425	SF	7	10+ years	-
	Lighting - Chandelier, Incandescent	3rd Floor	6	EΑ	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	955	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,371	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement	8	EΑ	6	10+ years	
	Drinking Fountains - Single Fountain	Basement	3	EA	5	6-10 years	
	Floor - Asphalt Floor	Basement	1,371	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	16	EΑ	7	6-10 years	
	Stairs - Terrazzo	Basement	14	LF	6	10+ years	

Campus Name: Everett Page : 18 of 27 Assessment Date: 10/17/2023



Catego	ry : Interior	В	uilding				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Basement	3,722	SF	6	10+ years	
0-4-4							
Safety	Camera Viewing Station	1st Floor	3	EA	7	6-10 years	
	Security Cameras	1st Floor	12	EA	7	6-10 years	
	•					•	
Stairs	0 ::	N. d	500	05		0.40	
	Ceiling - Plaster/Drywall	North	588	SF	6	6-10 years	
	Floor - Asphalt	North	284	SF	6	6-10 years	5
	Floor - Asphalt	North	4	SF	5	1-2 years	Damaged floor
	Handrails	North	186	LF	7	10+ years	Handrail is secure
	Lighting - Pendent/Surface	North	6	EA	6	6-10 years	
	Stairs - Asphalt	North	80	LF	6	6-10 years	
	Stairs - Asphalt	North	10	LF	4	1-2 years	Asphalt worn away
	Stairs - Asphalt	North	3	LF	4	1-2 years	Damaged treads
	Walls - Plaster/Drywall	North	1,222	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	South	588	SF	6	6-10 years	
	Floor - Asphalt	South	288	SF	6	6-10 years	
	Handrails	South	186	LF	7	10+ years	Handrails are secure
	Lighting - Pendent/Surface	South	6	EA	7	6-10 years	
	Stairs - Asphalt	South	20	LF	6	6-10 years	
	Stairs - Asphalt	South	93	LF	6	6-10 years	
	Stairs - Asphalt	South	5	LF	4	1-2 years	Damaged nosing
	Walls - Plaster/Drywall	South	1,222	SF	6	10+ years	Paint cracking and peeling throughout.
	Ceiling - Plaster/Drywall	West	120	SF	6	10+ years	Extensive peeling paint throughout
	Floor - Asphalt	West	50	SF	6	6-10 years	1 31
	Handrails	West	36	LF	7	6-10 years	Handrail is secure
	Lighting - Chandelier, Incandescent	West	2	ĒΑ	7	6-10 years	
	Lighting - Wall Mounted	West	2	EA	7	6-10 years	
	Stairs - Asphalt	West	18	LF	6	6-10 years	
	Walls - Plaster/Drywall	West	392	SF	6	6-10 years	



Category : Exterior Building : Modular 1 (6-Classroom )						oom )	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance							
	Exterior Doors - Exterior Steel Door	Door 1 - West	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 1 - West	7	LF	5	1-2 years	Broken concrete around post bases
	Stair Handrail - Steel_Stair Handrail	Door 1 - West	17	LF	7	10+ years	Changed to match current observations
	Exterior Doors - Exterior Steel Door	Door 2 - East	2	EA	6	10+ years	
Foundati	on						
	Foundation - Masonry	Entire Building	310	LF	6	10+ years	
	Superstructure - Steel	Entire Building	5,645	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	7	10+ years	Quantity changed to match current observations
Roof Sys							
	Coping - Metal	Entire Building	310	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Entire Building	60	LF	7	10+ years	New
	Roof - EPDM/ Synthetic Rubber	Entire Building	5,645	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Entire Building	5,645	SF	7	10+ years	
_Walls							
	Exterior Walls - Hardie Board	Entire Building	2,650	SF	6	10+ years	
	Exterior Walls - Hardie Board	Entire Building	20	SF	4	1-2 years	Detached trim
Windows	3						
	Guard - Guards perforated	Entire Building	400	SF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	400	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Modul	ar 1 (6-Classro	om )
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	cy System						
	Security System - CCTV	1st Floor	5,645	SF	7	10+ years	
	Security System - Intrusion Detection	1st Floor	5,645	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	1st Floor	1	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	1st Floor	6	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	1st Floor	3	EA	6	6-10 years	

Campus Name: Everett Page : 20 of 27 Assessment Date: 10/17/2023



	Schools						3419 S Bell AVENUE, Chicago, IL 6060			
Catego	ry : Electrical		В	Building : Modular 1 (6-Classroom )						
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Emergency Battery Packs - Multipurpose Room	1st Floor	6	EA	6	6-10 years				
Main Se	rvice									
	PA System	1st Floor	5,645	SF	6	6-10 years	PA annunciation come from main building			
	Main Electrical Service - 800 A and 120/208/3PH	exterior cabinet	1	EA	6	6-10 years	·			
Power D	Distribution									
	Lighting and Power Panels - 100 A	1st Floor	3	EA	6	6-10 years				
	Main Distribution Panels - Less than 400 amp	1st Floor	1	EA	6	6-10 years				
Catego	ry : Fire Protection		В	uilding	: Modul	ar 1 (6-Classro	oom )			
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Sprinkle	r System									
	Sprinkler Heads	1st Floor	5,645	SF	7	6-10 years				
	Sprinkler Piping	1st Floor	5,645	SF	6	6-10 years				
	Wet Sprinkler System	1st Floor	5,645	SF	6	6-10 years	Wet sprinkler system serves from main building			
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (6-Classro	oom )			
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Tempera	ature Control									
	Electric Thermostat	1st Floor	6	EA	6	6-10 years				
Unit Ver	ntilation									
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	exterior surface	6	EA	6	6-10 years				
	·									
Ventilati										
Ventilati	on Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	6	EA	6	6-10 years				
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building				ar 1 (6-Classro	oom )			
Ventilation  Catego  Group	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building  Location				·				



	ry : Plumbing	Building : Modular 1 (6-Classroom )					
			Recommend				•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Electric Heater - Less than 20 KW	1st Floor	1	EA	5	6-10 years	
Piping							
iping	Domestic Piping-Hot Water Return Lines	Entire Building	5,645	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	5,645	SF	7	6-10 years	
	Fixtures Domestic Piping-Hot/Cold Water Supply	Entire Building	5,645	SF	6	6-10 years	
	(Horizontal Lines)	E // B // P	= 0.4F	0=	•	0.40	0 '' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '
	Sanitary Piping	Entire Building	5,645	SF	6	6-10 years	Sanitary pipes inside the wall
	Storm Piping	Entire Building	5,645	SF	6	6-10 years	
	Vent Piping	Entire Building	5,645	SF	6	6-10 years	Vent pipe inside the wall
Catego	ry : Classroom		В	uilding	: Modul	ar 1 (6-Classro	om )
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #401 (Office)						
	Ceiling - Lay-in	1st Floor	660	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	660	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	749	SF	6	10+ years	
Classroo	om #402 (Office)						
Classice	Ceiling - Lay-in	1st Floor	658	SF	7	6 10 voore	
		1st Floor		SF SF	4	6-10 years	Water demons
	Ceiling - Lay-in	1st Floor	2 12	LF	4	1-2 years	Water damage
	Chalk Board	1St Floor		ᄕ	4	2-5 years	
					-	0.40	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Doors - Wood Doors inclu hw Floor - Tile	1st Floor 1st Floor	1 658	EA SF	6 7	6-10 years	D 141
	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	1st Floor 1st Floor 1st Floor	1 658 2	EA SF SF	6 7 4	6-10 years 1-2 years	Damaged tile
	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor	1 658 2 12	EA SF SF EA	6 7 4 7	6-10 years 1-2 years 6-10 years	Damaged tile
	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in Storage/ Closet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 658 2 12 29	EA SF SF EA SF	6 7 4 7 7	6-10 years 1-2 years 6-10 years 10+ years	Damaged tile
	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in	1st Floor 1st Floor 1st Floor 1st Floor	1 658 2 12	EA SF SF EA	6 7 4 7	6-10 years 1-2 years 6-10 years	Damaged tile
Classroo	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in Storage/ Closet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 658 2 12 29	EA SF SF EA SF	6 7 4 7 7	6-10 years 1-2 years 6-10 years 10+ years	Damaged tile
Classroo	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Vinyl Coated Gypsum Panel	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 658 2 12 29 749	EA SF SF EA SF SF	6 7 4 7 7	6-10 years 1-2 years 6-10 years 10+ years 10+ years	Damaged tile
Classroo	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Vinyl Coated Gypsum Panel	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 658 2 12 29 749	EA SF SF EA SF	6 7 4 7 7 7	6-10 years 1-2 years 6-10 years 10+ years 10+ years	Damaged tile
Classroo	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Vinyl Coated Gypsum Panel om #403 (Store Room) Ceiling - Lay-in Chalk Board	1st Floor	1 658 2 12 29 749	EA SF SF SF SF	6 7 4 7 7 7	6-10 years 1-2 years 6-10 years 10+ years 10+ years 10+ years 2-5 years	Damaged tile
Classroo	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Vinyl Coated Gypsum Panel om #403 (Store Room) Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw	1st Floor	1 658 2 12 29 749 660 12 1	EA SF SF SF SF LF EA	6 7 4 7 7 7	6-10 years 1-2 years 6-10 years 10+ years 10+ years 10+ years 2-5 years 10+ years	Damaged tile
Classroo	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Vinyl Coated Gypsum Panel om #403 (Store Room) Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile	1st Floor	1 658 2 12 29 749 660 12 1 650	EA SF SF SF SF LF EA SF	6 7 4 7 7 7 7 4 7	6-10 years 1-2 years 6-10 years 10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years	
Classroo	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Vinyl Coated Gypsum Panel  om #403 (Store Room) Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile Floor - Tile	1st Floor	1 658 2 12 29 749 660 12 1 650 10	EA SF SF SF SF LF SF SF	6 7 4 7 7 7 4 7 4	6-10 years 1-2 years 6-10 years 10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years	Damaged tile  Damaged tiles
Classroo	Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Lay-in Storage/ Closet Walls - Vinyl Coated Gypsum Panel om #403 (Store Room) Ceiling - Lay-in Chalk Board Doors - Wood Doors inclu hw Floor - Tile	1st Floor	1 658 2 12 29 749 660 12 1 650	EA SF SF SF SF LF EA SF	6 7 4 7 7 7 7 4 7	6-10 years 1-2 years 6-10 years 10+ years 10+ years 10+ years 2-5 years 10+ years 10+ years	

Campus Name: Everett Page : 22 of 27 Assessment Date: 10/17/2023



Category : Classroom			Building : Modular 1 (6-Classroom )					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	749	SF	6	10+ years		
Classroo	om #404 (Store Room)							
	Ceiling - Lay-in	1st Floor	660	SF	7	6-10 years		
	Chalk Board	1st Floor	12	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years		
	Floor - Tile	1st Floor	660	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years		
	Storage/ Closet	1st Floor	50	SF	7	10+ years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	749	SF	7	10+ years		
Classroo	om #405 (Store Room)							
	Ceiling - Lay-in	1st Floor	660	SF	7	6-10 years		
	Chalk Board	1st Floor	12	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years		
	Floor - Tile	1st Floor	660	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	749	SF	7	10+ years		
Classroo	om #406 (Store Room)							
	Ceiling - Lay-in	1st Floor	660	SF	7	6-10 years		
	Chalk Board	1st Floor	12	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	660	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	749	SF	7	10+ years		
Catego	ry : Room		В	uilding	: Modul	ar 1 (6-Classro	oom )	
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Mechan	cal/ Service Rooms							
	Mechanical/ Service Rooms	Mechanical room in 402	52	SF	7	10+ years		
Restroo	n							
	Accessories	Boys	176	SF	7	6-10 years		

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	Mechanical/ Service Rooms						
	Mechanical/ Service Rooms	Mechanical room in 402	52	SF	7	10+ years	
_Restroor	m						
	Accessories	Boys	176	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys	176	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boys	1	EA	6	10+ years	
	Floor - Tile/Sheet	Boys	176	SF	7	10+ years	
	Floor Drain	Boys	1	EA	7	6-10 years	
	Hand Dryer	Boys	1	EA	5	6-10 years	
	Lavatory	Boys	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Boys	1	EA	7	10+ years	
	Partitions	Boys	2	EA	7	6-10 years	

Campus Name: Everett Page : 23 of 27 Assessment Date: 10/17/2023



Category : Room			Building : Modular 1 (6-Classroom )						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Urinals	Boys	2	EA	6	6-10 years			
	Walls - Vinyl Coated Gypsum Panel	Boys	432	SF	7	10+ years			
	Water Closet	Boys	2	EA	7	6-10 years			
	Accessories	Girls	176	SF	7	6-10 years			
	Ceiling - Lay-in	Girls	176	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Girls	1	EA	6	10+ years			
	Floor - Tile/Sheet	Girls	176	SF	7	10+ years			
	Floor Drain	Girls	1	EA	7	6-10 years			
	Lavatory	Girls	2	EA	6	6-10 years			
	Lighting - Pendent/Surface	Girls	2	EA	7	10+ years			
	Partitions	Girls	4	EA	7	6-10 years			
	Walls - Vinyl Coated Gypsum Panel	Girls	432	SF	6	10+ years			
	Water Closet	Girls	4	EA	6	6-10 years			

**Building: Modular 1 (6-Classroom)** Category : Interior

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Corridor							
	Ceiling - Lay-in	1st Floor	648	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	648	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	10	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,424	SF	6	10+ years	
Safety							
-	Security Cameras	1st Floor	1	EA	7	6-10 years	

Campus Name: Everett Page : 24 of 27 Assessment Date: 10/17/2023





Category: Site Building: Site

Catego	ory : Site	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	ninage						
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EΑ	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	2	EA	6	10+ years	
Fencina							
r choing	Fencing - Chain Link	Entire Site	255	LF	6	10+ years	
	Fencing - Iron and Concrete Post	Entire Site	390	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	40	LF	7	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	135	LF	6	10+ years	
Landasa							
Landsca	Benches	Entire Site	2	EA	7	10+ years	New
	Landscape - Hardscape- Concrete	Entire Site	840	SF	7	10+ years	New 2022
	Landscape - Hardscape- Concrete	Entire Site	3,172	SF	6	10+ years	New 2022
	Landscape - Hardscape- Concrete	Entire Site	338	SF	4		Cracking/ainking/agatation growth
				SF SF	-	1-2 years	Cracking/sinking/vegetation growth
	Landscape - Mulch	Entire Site	2,270	SF	6	10+ years	Replaced with mulch and planting beds. Changed to match current observations
	Parkway trees	Entire Site	9	EA	6	10+ years	
	Parkway trees	Entire Site	1	EA	4	1-2 years	Missing tree
	Planting Beds/ Area	Entire Site	630	SF	7	10+ years	New
	Trash Receptacles	Entire Site	7	EA	7	10+ years	11011
Parking	Lot						
T arking	Concrete Curbs	N Parking Lot	60	LF	7	10+ years	New
	Surface - Asphalt	N Parking Lot	3,340	SF	6	10+ years	Quantity changed due to the new
	0.4	NB II I I	405	0.5	_	40	playground
	Surface - Concrete	N Parking Lot	465	SF	7	10+ years	New
	Trash Enclosure - Chain Links	N Parking Lot	315	SF	7	10+ years	New
	Vehicular Screening	N Parking Lot	30	LF	6	10+ years	
Playgrou	und						
	Equipment - Combo 3-12	North	1	EA	7	10+ years	
	Surface - Poured Surface	North	1,260	SF	7	10+ years	
Sidewall	ks						
	Sidewalks - Perimeter Sidewalks	Entire Site	8,620	SF	7	10+ years	
0:							
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	



**Building: Site** Category: Site

						Recommend	
Group	Item - Type	Location	Quantity	UON	I Rank	Replacement	Comments
	Marquee - Building Mounted Back Lighted	Entire Site	•	EA	6	6-10 years	
	w/ LED						

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Everett Page: 26 of 27 Assessment Date: 10/17/2023

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



#### **Classroom Summary**

,			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-	
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board	
Building : Main					(31)	1100		0.00		
Art Room	Regular Classroom	1st Floor	104	104	968	240	72	N	N	
Computer Lab	Regular Classroom	3rd Floor	306	306	1,005	240	72	N	N	
Regular Classroom	Kindergarten	1st Floor	101	101	940	240	72	N	Υ	
Regular Classroom	Library	2nd Floor	203	203	940	175	68	N	Υ	
Regular Classroom	Regular Classroom	1st Floor	102	102	980	240	72	N	Υ	
Regular Classroom	Regular Classroom	1st Floor	103	103	940	200	45	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	201	201	980	240	72	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	202	202	980	240	72	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	204B	204A	680	120	60	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	205	205	940	240	72	N	Υ	
Regular Classroom	Regular Classroom	2nd Floor	206	206	1,005	240	72	N	N	
Regular Classroom	Regular Classroom	3rd Floor	301	301	980	240	72	N	Y	
Regular Classroom	Regular Classroom	3rd Floor	302	302	980	240	72	N	Υ	
Regular Classroom	Regular Classroom	3rd Floor	305	305	940	240	72	N	Υ	
Building : Modular 1 (6-Classroom )										
Office	Regular Classroom	1st Floor	401	401	660	60	26	N	N	
Office	Regular Classroom	1st Floor	402	402	660	60	26	N	N	
Store Room	Regular Classroom	1st Floor	403	403	660	60	26	N	N	
Store Room	Regular Classroom	1st Floor	404	404	660	60	26	N	N	
Store Room	Regular Classroom	1st Floor	405	405	660	60	26	N	N	
Store Room	Regular Classroom	1st Floor	406	406	660	60	26	N	N	