

## **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1974	3	42,300
Campus Total			42,300

atego	ry : Exterior		В				
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	)						
	Entrance Control - Audio and Video	1 main	1	EA	7	6-10 years	
	Exterior Doors - Exterior Wood Door	1 main	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	1 main	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	2	1	EA	7	10+ years	Newly replaced
	Exterior Stairs - Concrete	2	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	3	1	EA	5	2-5 years	
	Exterior Doors - Exterior Steel Door	4	1	EA	7	10+ years	Newly replaced
	Exterior Stairs - Concrete	4	3	LF	6	10+ years	•
	Exterior Doors - Exterior Steel Door	4.5 - South	2	EA	6	10+ years	Newly replaced
	Exterior Doors - Exterior Steel Door	5	2	EA	6	10+ years	•
	Exterior Doors - Transom Lite	5	1	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	6 south	3	EA	5	2-5 years	
	Exterior Stairs - Concrete	6 south	10	LF	5	0-1 year	Cracking
	Exterior Doors - Exterior Steel Door	7	1	EA	6	10+ years	· ·
	Exterior Doors - Side lite	7	2	EA	6	6-10 years	Revised assessment based or current observations
	Exterior Doors - Transom Lite	7	1	EA	6	6-10 years	Revised assessment based or current observations
	Exterior Doors - Exterior Steel Door	8	1	EA	6	10+ years	
	Exterior Doors - Side lite	8	2	EA	5	0-1 year	Rusted frame
	Exterior Doors - Transom Lite	8	1	EA	5	0-1 year	Rusted frame
	Exterior Doors - Exterior Steel Door	West roof entrance	1	EA	5	0-1 year	Corroded

Page: 1 of 21

Foundation



Catego	ry : Exterior		В	uilding	: Main			
_						Recommend	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Foundation - Concrete	Entire Building	575	LF	7	10+ years	No exposed foundation	
	Superstructure - Concrete	Entire Building	575	SF	7	10+ years	No exposed superstructure	
Lighting								
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	7	10+ years	Newly replaced	
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	7	6-10 years		
Roof Sys	tem							
•	Access Ladder - Metal	Main Roof	1	EA	7	10+ years		
	Coping - Metal	Main Roof	210	LF	6	10+ years		
	Downspouts - Exterior Downspouts	Main Roof	15	LF	6	10+ years	Not previously assessed	
	Downspouts - Interior Downspouts	Main Roof	30	LF	7	10+ years		
	Parapet - Parapet < 16" Height	Main Roof	210	LF	7	10+ years		
	Roof - Asphalt Gravel Ballast	Main Roof	2,660	SF	4	0-1 year	Bubbling/cracking	
	Roof - Modified Bitumen	Main Roof	440	SF	6	10+ years	Corrected quantity	
	Roof Hatch - Metal	Main Roof	1	ĒΑ	5	10+ years	, , , , , ,	
	Roof Structure - Steel / Metal Deck/	Main Roof	3,100	SF	7	10+ years		
	Concrete Topping		3,:33	•	•	,		
	Coping - Metal	Main South west	70	LF	7	10+ years		
	Downspouts - Interior Downspouts	Main South west	20	LF	4	0-1 year	Clogged	
	Parapet - Parapet < 16" Height	Main South west	70	LF	7	10+ years	Clogged	
	Roof - Asphalt Gravel Ballast	Main South west	600	SF	4	0-1 year	Cracking/bubbling	
	Roof Structure - Concrete	Main South west	600	SF	7	10+ years	Cracking/bubbling	
	Coping - Metal	Main West	230	LF	6	10+ years		
	Downspouts - Interior Downspouts	Main West	20	LF	6	10+ years		
	Parapet - Parapet < 16" Height	Main West	230	LF	6	10+ years		
	Roof - Asphalt Gravel Ballast	Main West	4,500	SF	4	0-1 year	Bubbling/cracking	
	Roof Structure - Concrete	Main West	4,500	SF	7		Bubbiing/cracking	
			•	SF LF	-	10+ years	Only comed now coaled in since at	
	Chimney - Metal Flue	North	30		5	2-5 years	Only served now-sealed incinerato	
	Coping - Metal	North	75	LF	7	10+ years		
	Downspouts - Interior Downspouts	North	20	LF	6	10+ years		
	Parapet - Parapet < 16" Height	North	75	LF	7	10+ years		
	Roof - Asphalt Gravel Ballast	North	900	SF	4	0-1 year	Vegetation growth/bubbling	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	North	900	SF	7	10+ years		
Walls								
- (4110)	Exterior Walls - Brick	Entire Building	14,718	SF	5	10+ years		
Windows								
	Guard - Guards wire guard	Entire Building	756	SF	5	6-10 years		
	Skylite - Lexan	Entire Building	16	SF	5	0-1 year	Leaking	
	Windows - Casement Lexan	Entire Building	2,862	SF	4	0-1 year	Single panel plastic. Leaking	





Categor	ry : Exterior		В	uilding	: Main		0.5 South Shore DRIVE, Chicago, IL 6062
	<b>,</b>		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							water/cracking
	Windows - Louver	Entire Building	360	SF	6	6-10 years	
Categor	ry : Electrical		В	uilding	: Main		
	<del></del>		0	11014	<b>D</b>	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-mergen	cy System						
	Automatic Transfer Switch	Electrical Room	1	EA	4	0-1 year	Non-functional
	Emergency A/C Power - Corridors and Stairs	Entire Building	8,000	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	4,500	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	3,000	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	4	EA	7	6-10 years	
	Security System - CCTV	Entire Building	42,300	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	42,300	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	13	ĒΑ	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	3	EA	7	6-10 years	Appears to have been replaced by LED
	Exit Signs - Gym	Entire Building	3	EA	7	6-10 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	7	6-10 years	
Main Ser	vice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	Since ATS is not functioning, independent feed does not work
	PA System	Entire Building	42,300	SF	6	6-10 years	independent lood dood not work
Power Di	stribution						
	Lighting and Power Panels - 100 A	Entire Building	6	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	4	EA	6	6-10 years	
Cataman	·		ь	يم منالم الدي	. Main		
Categor	ry : Fire Protection			uilding	: wain	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alarr							
	Fire ALarm Anunciator	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	42,300	SF	7	6-10 years	
	Fire Alarm_System	Entire Building	42,300	SF	6	6-10 years	

Page : 3 of 21




Catego	ry : Fire Protection	В	uilding	: Main			
	<b></b>		0			Recommend	<b>2</b>
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Mechanical		В	uilding	: Main		
Croun	Hom Tune	Location	Quantity	UOM	Rank	Recommend	Comments
Group	Item - Type	Location	Quantity	OOW	Kalik	Replacement	Comments
All Hallo	Iling Systems  Air Handling Unit- Package Single Zone-	Mechanical Room	1	EA	6	6-10 years	
	Indoor- Electric Coil - 4000-8000 cfm	Mechanical Room	ļ	EA	O	0-10 years	
	Air Handling Unit- Package Single Zone-	Mechanical Room	1	EA	6	6-10 years	
	Indoor- Electric Coil - 4000-8000 cfm		•		· ·	0 .0 ,00.0	
	Air Intake	Mechanical Room	2	EA	6	6-10 years	
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	5	1-2 years	Severely rusted out switchgear
	DX Cooling Only with Self Contained						panel. Unit unit looks worn.
	Compressor - 11 - 20 tons	5 (			_	4.0	
	Roof Top Unit-Single Zone-Roof Mounted-	Roof	1	EA	5	1-2 years	Severely rusted out switchgear
	DX Cooling Only with Self Contained Compressor - 5 - 10 tons						panel. Unit unit looks worn.
	Compressor - 3 - 10 tons						
_Heating_							
	Wall Heater - Electric	Entire Building	12	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	4	0-1 year	Missing a cover.
	PTAC - Electric Heating and Self Contained	Main Office	1	EA	6	6-10 years	
	Cooling	Main Office	1	Γ.	4	0.1	Non functional Dilanidated
	PTAC - Electric Heating and Self Contained Cooling	Main Office	I	EA	4	0-1 year	Non-functional. Dilapidated.
	Sooning						
Unit Ven							
	Unit Ventilators- Floor Mounted- Electric	Entire Building	21	EA	6	6-10 years	
	Heating & DX Cooling Coil W/ Self						
	Contained Compressor Unit Ventilators- Floor Mounted- Electric	Entire Building	4	EA	2	0.1 voor	Non-functional. In an occupied rooms
	Heating & DX Cooling Coil W/ Self	Entire Building	4	EA	2	0-1 year	Engineer stated that units were pulled
	Contained Compressor						apart for parts to repair other units in
	Comamou Compressor						the building.
							·
_Ventilation							
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	6	6-10 years	No damage observed
	CFM Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	4	0-1 year	Nonfunctional. Have been looked at
	CFM	Little building	Į	ĽA	4	u-i yeai	in the past. No current work order.
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	4	0-1 year	Nonfunctional. Have been looked at
	CFM	9	•	<b></b> · ·	•	,	in the past. No current work order
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	3	0-1 year	Non-functional. Has been looked at in
	CFM						the past. No current work order in



Catego	ry : Mechanical		В	uilding	: Main	7000	0.5 South Shore DRIVE, Chicago, IL 60649
	.,		_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	4	0-1 year	place. Nonfunctional. Have been looked at in the past. No current work order
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	6	6-10 years	in the past. No current work order
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	Not in use
Catego	ry : Plumbing		В	uilding	: Main		
	<del></del>	•	0	11014	<b>.</b>	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR	Entire Building	2	EA	6	6-10 years	Hot water heaters appear to be new. Replacing old nonfunctional.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	42,300	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	42,300	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	42,300	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	42,300	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	42,300	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	42,300	SF	6	6-10 years	
	Sanitary Piping	Entire Building	42,300	SF	6	6-10 years	
	Storm Piping	Entire Building	42,300	SF	6	6-10 years	
	Vent Piping	Entire Building	42,300	SF	6	6-10 years	
Pumps							
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Not accessible
Catego	ry : Room		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	rative Suites/Offices		•				
	Ceiling - Lay-in	102 Executive Director	245	SF	7	10+ years	
	Doors - Wood Doors inclu hw	102 Executive Director	1	EA	7	10+ years	
	Floor - Carpet	102 Executive Director	235	SF	6	6-10 years	
	Floor - Carpet	102 Executive Director	10	SF	4	1-2 years	Damaged carpet
	Lighting - Lay-in	102 Executive Director	6	EA	7	6-10 years	


Page : 5 of 21







**Building: Main** Category: Room Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments 102 Executive Director Power Distribution 6 EΑ 10+ years 7 578 SF 7 Walls - Concrete Block 102 Executive Director 10+ years Ceiling - Lav-in 112 Gymnasium Office 208 SF 6 6-10 years Doors - Wood Doors inclu hw 2 EΑ 7 112 Gymnasium Office 10+ years SF Floor - Tile 112 Gymnasium Office 208 6 10+ years 112 Gymnasium Office EΑ 7 Lighting - Lay-in 2 6-10 years Power Distribution 112 Gymnasium Office 6 EΑ 7 10+ years SF Storage/ Closet 112 Gymnasium Office 38 5 10+ years SF Walls - Concrete Block 112 Gymnasium Office 690 7 10+ years SF Ceiling - Lav-in 121 Engineer's Office 6 6-10 years 151 121 Engineer's Office Doors - Wood Doors inclu hw 1 EΑ 7 10+ years Floor - Carpet 121 Engineer's Office 151 SF 4 0-1 year Damaged carpet Lighting - Lay-in 121 Engineer's Office 2 EΑ 7 10+ years EΑ 7 Power Distribution 121 Engineer's Office 4 10+ years Storage/ Closet 121 Engineer's Office 25 SF 5 10+ years Walls - Concrete Block 585 SF 7 121 Engineer's Office 10+ years LF 7 Casework 213 Assistant Principal 6 6-10 years SF Ceiling - Lay-in 213 Assistant Principal 347 6 6-10 years Ceiling - Lav-in SF 213 Assistant Principal 10 4 0-1 vear Water damage Doors - Wood Doors inclu hw 213 Assistant Principal 1 EΑ 6 6-10 years Floor - Tile 213 Assistant Principal 357 SF 6 6-10 years 213 Assistant Principal 7 Lighting - Lay-in 2 EΑ 6-10 years 6 7 Power Distribution 213 Assistant Principal EΑ 6-10 years SF Walls - Concrete Block 213 Assistant Principal 600 6 10+ years Work SInk EΑ 7 6-10 years 213 Assistant Principal 1 Ceiling - Plaster/Drywall Kitchen Office 133 85 SF 7 10+ years Doors - Side-lite SF Kitchen Office 133 9 7 10+ years Doors - Wood Doors inclu hw Kitchen Office 133 1 EΑ 7 10+ years Kitchen Office 133 SF Floor - Tile 85 6 10+ years Lighting - Pendent/Surface Kitchen Office 133 1 EΑ 7 6-10 years Power Distribution Kitchen Office 133 4 FΑ 7 10+ years Storage/ Closet Kitchen Office 133 16 SF 7 10+ years Walls - Concrete Block SF 7 10+ years Kitchen Office 133 315 Ceiling - Lav-in Library Conference Room 214 105 SF 6 10+ years SF 5 Ceiling - Lay-in Library Conference Room 214 24 0-1 year Water damage Doors - Wood Doors inclu hw Library Conference Room 214 EΑ 6 1 10+ years Library Conference Room 214 SF Floor - Carpet 129 6 6-10 years Lighting - Lay-in Library Conference Room 214 EΑ 7 4 6-10 years Power Distribution Library Conference Room 214 9 EΑ 7 10+ years Library Conference Room 214 SF Walls - Concrete Block 418 7 10+ years SF Ceiling - Lav-in Library Work Room 212 209 6 10+ years Doors - Wood Doors inclu hw Library Work Room 212 FΑ 7 10+ years 1 Floor - Carpet Library Work Room 212 209 SF 6 6-10 years Library Work Room 212 EΑ 7 Lighting - Lay-in 6-10 years








Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Library Work Room 212 Walls - Concrete Block 229 SF 10+ vears 7 Walls - Metal Panel Library Work Room 212 250 SF 6 10+ years Ceiling - Lav-in Main Office 145 619 SF 6 10+ years Doors - Wood Doors inclu hw Main Office 145 2 EΑ 7 10+ years SF Floor - Carpet Main Office 145 571 6 6-10 years SF Floor - Tile 7 Main Office 145 48 10+ years Lighting - Lay-in Main Office 145 EΑ 7 6-10 years 10 Power Distribution Main Office 145 12 EΑ 7 10+ years Storage/ Closet Main Office 145 55 SF 7 10+ years Walls - Concrete Block SF Main Office 145 1.156 7 10+ years LF Casework Office 217 12 6 10+ years Ceiling - Lay-in Office 217 140 SF 6 10+ years No water damage observed Doors - Wood Doors inclu hw Office 217 EΑ 6 10+ years 1 SF 6 Floor - Carpet Office 217 140 6-10 years Lighting - Lay-in Office 217 EΑ 7 6-10 years 2 Walls - Concrete Block SF 7 Office 217 380 10+ years SF Ceiling - Lav-in Principal Office 135 165 6 6-10 years Doors - Wood Doors inclu hw Principal Office 135 2 EΑ 7 10+ years SF Floor - Carpet Principal Office 135 165 7 6-10 years Principal Office 135 Lighting - Lay-in 2 EΑ 7 6-10 years Power Distribution Principal Office 135 6 EΑ 7 10+ years Principal Office 135 SF 7 Storage/ Closet 16 10+ years Walls - Concrete Block SF 7 Principal Office 135 447 10+ years SF Ceiling - Lay-in Teachers Planning Room 309B 386 6 10+ years Ceiling - Lay-in Teachers Planning Room 309B SF 5 0-1 year 12 Water damage Doors - Wood Doors inclu hw Teachers Planning Room 309B 1 EΑ 6 10+ years Teachers Planning Room 309B 398 SF Floor - Carpet 6 6-10 years Lighting - Lay-in Teachers Planning Room 309B 3 EΑ 7 6-10 years Power Distribution Teachers Planning Room 309B 6 EΑ 7 10+ years Storage/ Closet Teachers Planning Room 309B 78 SF 7 10+ years Walls - Concrete Block Teachers Planning Room 309B SF 966 7 10+ years Gvmnasia Ceiling - Lay-in 1st Floor 4.155 SF 6 6-10 years Ceiling - Lay-in 1st Floor 100 SF 0-1 year 4 Water damaged Doors - Wood Doors inclu hw 6 1st Floor 6 EΑ 10+ years SF Floor - Tile 1st Floor 4.255 6 10+ years Lighting - Lay-in FΑ 7 6-10 years 1st Floor 12 Scoreboards 1st Floor 1 EΑ 7 6-10 years Sound System EΑ 7 6-10 years 1st Floor 1 600 SF 7 Stage 1st Floor 10+ years EΑ Stage Curtain 1st Floor 3 7 6-10 years Stage Lighting System 1st Floor 10 EΑ 5 6-10 years 1 F 7 Stage-Stairs - Wood 1st Floor 32 10+ years



Catego	ry : Room		B	uilding	· Main		0 3 30util Shore DRIVE, Chicago, it 6064
Calcgo	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			ananig	· Wall	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	267	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	4,356	SF	7	10+ years	
						j	
Kitchen							
	Ceiling - Plaster/Drywall	Kitchen 134	1,086	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen 134	2	EA	6	10+ years	
	Floor - Tile Quarry	Kitchen 134	1,086	SF	7	10+ years	
	Lighting - Pendent/Surface	Kitchen 134	12	EA	7	6-10 years	
	Storage/ Closet	Kitchen 134	170	SF	7	10+ years	
	Walls - Plaster/Drywall	Kitchen 134	1,245	SF	7	10+ years	
Locker/S	Shower Room						
	Accessories	Toilet/Locker Room Kitchen	88	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet/Locker Room Kitchen	88	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Toilet/Locker Room Kitchen	2	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Toilet/Locker Room Kitchen	38	SF	7	10+ years	
	Floor - Tile/Sheet	Toilet/Locker Room Kitchen	50	SF	5	6-10 years	
	Hand Dryer	Toilet/Locker Room Kitchen	1	ĒΑ	7	6-10 years	
	Lavatory	Toilet/Locker Room Kitchen	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Toilet/Locker Room Kitchen	2	ΕA	7	6-10 years	
	Student Lockers - One Tier	Toilet/Locker Room Kitchen	4	EΑ	7	10+ years	
	Walls - Concrete Block	Toilet/Locker Room Kitchen	486	SF	7	10+ years	
	Water Closet	Toilet/Locker Room Kitchen	1	EA	7	10+ years	
Lunah 0	Multinumana Daam						
Lunch &	Multipurpose Room Ceiling - Lay-in	117 Lunchroom	1,934	SF	6	6-10 years	No coouponou cignogo
	Doors - Wood Doors inclu hw	117 Lunchroom	1,934	EA	7	•	No occupancy signage
			-	SF	-	10+ years	
	Floor - Tile	117 Lunchroom	1,914	SF SF	6	6-10 years	Chinn ad flagring
	Floor - Tile	117 Lunchroom	20		4	0-1 year	Chipped flooring
	Lighting - Lay-in	117 Lunchroom	23	EA	7	6-10 years	
	Serving Line	117 Lunchroom	8	LF	7	10+ years	
	Walls - Concrete Block	117 Lunchroom	1,649	SF	7	10+ years	
	Casework	Library 216	60	LF	6	10+ years	
	Ceiling - Lay-in	Library 216	1,501	SF	6	10+ years	
	Ceiling - Lay-in	Library 216	10	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	Library 216	2	EA	6	10+ years	
	Floor - Carpet	Library 216	1,511	SF	6	6-10 years	
	Lighting - Lay-in	Library 216	14	EA	7	6-10 years	
	Lighting - Lay-in	Library 216	4	EA	6	6-10 years	Relamp
	Walls - Concrete Block	Library 216	1,418	SF	7	10+ years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	45	SF	5	10+ years	
					-	,	



Catego	ry : Room		В	uilding	: Main		<u> </u>
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Mechanical/ Service Rooms	1st Floor	75	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	210	SF	7	10+ years	
	Storage Room	1st Floor	612	SF	7	10+ years	
	Storage Room	1st Floor	210	SF	5	10+ years	Combined from separate line item
	Vaults	1st Floor	44	SF	7	10+ years	
	Janitor's Closet	2nd Floor	51	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	624	SF	7	10+ years	
	Storage Room	2nd Floor	245	SF	7	10+ years	
	Janitor's Closet	3rd Floor	51	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	1,315	SF	7	10+ years	
	Storage Room	3rd Floor	145	SF	5	1-2 years	Water damage at ceiling
Restroo	m						
	Accessories	1st floor staff Restroom next to Girls	38	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor staff Restroom next to Girls	38	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor staff Restroom next to Girls	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor staff Restroom next to Girls	38	SF	7	10+ years	
	Hand Dryer	1st floor staff Restroom next to Girls	1	EA	7	6-10 years	
	Lavatory	1st floor staff Restroom next to Girls	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st floor staff Restroom next to Girls	1	EA	7	6-10 years	
	Walls - Concrete Block	1st floor staff Restroom next to Girls	225	SF	7	10+ years	
	Water Closet	1st floor staff Restroom next to Girls	1	EA	7	10+ years	
	Accessories	Main office	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main office	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Main office	42	SF	7	10+ years	
	Lavatory	Main office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Main office	1	EΑ	7	6-10 years	
	Walls - Concrete Block	Main office	184	SF	7	10+ years	
	Water Closet	Main office	1	ĒΑ	7	10+ years	
	Accessories	Toilet Room (Boys 127)	487	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet Room (Boys 127)	487	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Toilet Room (Boys 127)	2	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Toilet Room (Boys 127)	487	SF	7	10+ years	
	Floor Drain	Toilet Room (Boys 127)	1	EΑ	7	10+ years	
	Lavatory	Toilet Room (Boys 127)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Toilet Room (Boys 127)	3	EΑ	6	6-10 years	
	Partitions	Toilet Room (Boys 127)	1	EA	7	10+ years	
	Urinals	Toilet Room (Boys 127)	3	EA	7	10+ years	
	Walls - Concrete Block	Toilet Room (Boys 127)	572	SF	7	10+ years	
	Water Closet	Toilet Room (Boys 127)	1	EA	7	10+ years	
	Accessories	Toilet Room (Boys 127) Toilet Room (Boys 204)	295	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Toilet Room (Boys 204)	295	SF	7		
	•		295	SF EA	6	10+ years	
	Doors - Wood Doors inclu hw	Toilet Room (Boys 204)	2	ĽΑ	ъ	10+ years	








Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Toilet Room (Boys 204) Floor - Tile Ceramic/ Porcelain 295 SF 6 10+ vears Toilet Room (Boys 204) EΑ 7 Floor Drain 1 10+ years Lavatory Toilet Room (Boys 204) 2 FΑ 6 10+ years Lighting - Pendent/Surface Toilet Room (Boys 204) 3 7 EΑ 6-10 years Partitions Toilet Room (Boys 204) 1 EΑ 7 10+ years Toilet Room (Boys 204) 3 7 Urinals EΑ 10+ years Walls - Concrete Block Toilet Room (Boys 204) 574 SF 7 10+ years 10+ years Water Closet Toilet Room (Boys 204) 1 EΑ 7 Accessories Toilet Room (Boys 304) 295 SF 4 0-1 year Missing components and parts SF Ceiling - Plaster/Drywall Toilet Room (Bovs 304) 295 6 10+ years Doors - Wood Doors inclu hw Toilet Room (Bovs 304) 1 EΑ 6 10+ years Floor - Tile Ceramic/ Porcelain Toilet Room (Boys 304) 295 SF 6 10+ years Floor Drain Toilet Room (Boys 304) EΑ 7 10+ years 1 5 Hand Dryer Toilet Room (Boys 304) 2 EΑ 0-1 year Not functioning Toilet Room (Boys 304) 2 EΑ 5 Lavatory 0-1 year Not functioning Lighting - Pendent/Surface Toilet Room (Boys 304) 3 FΑ 5 0-1 year Missing covers 2 EΑ 5 **Partitions** Toilet Room (Bovs 304) 10+ years Urinals Toilet Room (Boys 304) 3 EΑ 6 10+ years Walls - Concrete Block Toilet Room (Boys 304) 574 SF 7 10+ years Toilet Room (Boys 304) Water Closet 2 EΑ 6 10+ years Accessories Toilet Room (Engineers) 25 SF 7 6-10 years Toilet Room (Engineers) 25 SF 7 Ceiling - Plaster/Drywall 10+ years Doors - Wood Doors inclu hw 7 Toilet Room (Engineers) 1 EΑ 10+ years SF 7 Floor - Tile Ceramic/ Porcelain Toilet Room (Engineers) 25 10+ years Toilet Room (Engineers) FΑ 7 Lavatory 1 10+ years Lighting - Pendent/Surface Toilet Room (Engineers) 1 FΑ 7 6-10 years Walls - Concrete Block Toilet Room (Engineers) SF 180 7 10+ years Water Closet Toilet Room (Engineers) EΑ 7 1 10+ years Toilet Room (Girls 128) SF Accessories 487 7 6-10 years Ceiling - Plaster/Drywall Toilet Room (Girls 128) 487 SF 7 10+ years Doors - Wood Doors inclu hw Toilet Room (Girls 128) 2 FΑ 7 10+ years Floor - Tile Ceramic/ Porcelain Toilet Room (Girls 128) 487 SF 7 10+ years FΑ 7 Floor Drain Toilet Room (Girls 128) 10+ years 1 Toilet Room (Girls 128) 2 FΑ 6 6-10 years Lavatory Lighting - Pendent/Surface 3 7 Toilet Room (Girls 128) EΑ 6-10 years EΑ 7 Partitions Toilet Room (Girls 128) 4 10+ years SF Walls - Concrete Block Toilet Room (Girls 128) 572 7 10+ years Water Closet Toilet Room (Girls 128) EΑ 4 7 10+ years SF Accessories Toilet Room (Girls 205) 293 7 6-10 years SF Ceiling - Plaster/Drywall Toilet Room (Girls 205) 293 7 10+ years Doors - Wood Doors inclu hw Toilet Room (Girls 205) 2 EΑ 6 10+ years Floor - Tile Ceramic/ Porcelain 293 SF 7 Toilet Room (Girls 205) 10+ years Floor Drain Toilet Room (Girls 205) EΑ 7 10+ years 1 Lavatory Toilet Room (Girls 205) EΑ 10+ years


Page: 10 of 21







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lighting - Pendent/Surface Toilet Room (Girls 205) 3 EΑ 6-10 years 7 Toilet Room (Girls 205) 3 EΑ 7 Partitions 10+ years Walls - Concrete Block Toilet Room (Girls 205) 572 SF 7 10+ years Water Closet Toilet Room (Girls 205) 3 EΑ 7 10+ years SF Accessories Toilet Room (Girls 305 293 4 0-1 year Missing SF 6 Ceiling - Plaster/Drywall Toilet Room (Girls 305 293 10+ years Doors - Wood Doors inclu hw Toilet Room (Girls 305 EΑ 6 10+ years 4 SF Floor - Tile Ceramic/ Porcelain Toilet Room (Girls 305 293 6 10+ years Floor Drain Toilet Room (Girls 305 1 EΑ 7 10+ years Hand Dryer Toilet Room (Girls 305 FΑ 5 0-1 vear Out of order 1 Lavatory Toilet Room (Girls 305 2 EΑ 4 0-1 vear Not functioning Lighting - Lay-in Toilet Room (Girls 305 3 EΑ 5 0-1 year Missing covers Toilet Room (Girls 305 4 EΑ 5 **Partitions** 10+ years SF 7 Walls - Concrete Block Toilet Room (Girls 305 572 10+ years Toilet Room (Girls 305 EΑ Water Closet 4 4 1-2 years Out of order 38 SF 7 Accessories Toilet Room (Principals 136) 6-10 years SF 7 Ceiling - Plaster/Drywall Toilet Room (Principals 136) 38 10+ years Doors - Wood Doors inclu hw Toilet Room (Principals 136) 1 EΑ 7 10+ years Toilet Room (Principals 136) SF Floor - Tile Ceramic/ Porcelain 38 7 10+ vears Toilet Room (Principals 136) Lavatory 1 EΑ 7 10+ years Lighting - Pendent/Surface Toilet Room (Principals 136) 1 EΑ 7 6-10 years Walls - Concrete Block Toilet Room (Principals 136) SF 225 7 10+ years Water Closet EΑ 7 Toilet Room (Principals 136) 1 10+ years SF 7 Accessories Toilet Room (Staff 211) 25 6-10 years Ceiling - Plaster/Drywall Toilet Room (Staff 211) 25 SF 7 10+ years Doors - Wood Doors inclu hw Toilet Room (Staff 211) 1 EΑ 7 10+ years 25 SF Floor - Tile Ceramic/ Porcelain Toilet Room (Staff 211) 7 10+ years Floor Drain Toilet Room (Staff 211) 1 EΑ 7 10+ years Hand Dryer Toilet Room (Staff 211) 1 EΑ 7 6-10 years Lavatory Toilet Room (Staff 211) 1 EΑ 7 10+ years Lighting - Lay-in Toilet Room (Staff 211) 1 FΑ 7 6-10 years Walls - Concrete Block Toilet Room (Staff 211) 180 SF 7 10+ years Water Closet Toilet Room (Staff 211) FΑ 7 10+ vears 1 Accessories Toilet Room (Staff 217) 51 SF 7 6-10 years SF Ceiling - Plaster/Drywall Toilet Room (Staff 217) 51 6 10+ years EΑ 7 Doors - Wood Doors inclu hw Toilet Room (Staff 217) 10+ years 1 SF Floor - Tile Ceramic/ Porcelain Toilet Room (Staff 217) 51 6 10+ years Floor Drain Toilet Room (Staff 217) EΑ 7 1 10+ years Hand Dryer Toilet Room (Staff 217) 1 EΑ 7 6-10 years Lavatory Toilet Room (Staff 217) 1 EΑ 6 10+ vears Lighting - Pendent/Surface Toilet Room (Staff 217) 1 EΑ 7 6-10 years Walls - Concrete Block SF 7 Toilet Room (Staff 217) 268 10+ vears Water Closet Toilet Room (Staff 217) EΑ 7 10+ years 1 SF 7 Accessories Toilet Room (Staff 306) 51 6-10 years







**Building: Main** Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Ceiling - Plaster/Drywall Toilet Room (Staff 306) 51 SF 10+ years 6 Doors - Wood Doors inclu hw Toilet Room (Staff 306) EΑ 7 1 10+ years Floor - Tile Ceramic/ Porcelain Toilet Room (Staff 306) 51 SF 6 10+ years Hand Drver EΑ 7 Toilet Room (Staff 306) 1 6-10 years Lavatory Toilet Room (Staff 306) 1 EΑ 6 10+ years Lighting - Pendent/Surface 7 Toilet Room (Staff 306) 1 EΑ 6-10 years Walls - Concrete Block Toilet Room (Staff 306) SF 7 10+ years 268 Water Closet Toilet Room (Staff 306) 1 EΑ 7 10+ years Accessories Toilet Room gym office 36 SF 7 6-10 years SF Ceiling - Plaster/Drywall Toilet Room gym office 36 7 10+ years Doors - Wood Doors inclu hw Toilet Room avm office 1 EΑ 7 10+ years Floor - Tile Ceramic/ Porcelain Toilet Room gym office 36 SF 7 10+ years Toilet Room gym office EΑ 6 6-10 years Lavatory 1 7 Lighting - Pendent/Surface Toilet Room gym office 1 EΑ 6-10 years Walls - Concrete Block SF 7 Toilet Room gym office 252 10+ years Water Closet FΑ Toilet Room gym office 1 7 10+ years SF 7 Accessories Toilet Room next to 102 28 6-10 years Toilet Room next to 102 SF Ceiling - Plaster/Drywall 28 7 10+ years EΑ Doors - Wood Doors inclu hw Toilet Room next to 102 1 7 10+ years Floor - Tile Ceramic/ Porcelain Toilet Room next to 102 28 SF 7 10+ years Hand Dryer Toilet Room next to 102 1 EΑ 7 6-10 years 7 10+ years Lavatory Toilet Room next to 102 1 EΑ Lighting - Pendent/Surface 7 Toilet Room next to 102 1 EΑ 6-10 years Walls - Concrete Block SF Toilet Room next to 102 191 7 6-10 years Water Closet EΑ 7 Toilet Room next to 102 1 6-10 years SF Accessories Toilet Room next to 102 28 7 6-10 years SF Ceiling - Plaster/Drywall Toilet Room next to 102 28 7 10+ years Doors - Wood Doors inclu hw EΑ 7 Toilet Room next to 102 1 10+ years SF Floor - Tile Ceramic/ Porcelain Toilet Room next to 102 28 7 10+ years Hand Dryer Toilet Room next to 102 1 EΑ 7 6-10 years Toilet Room next to 102 1 FΑ 7 10+ vears Lavatory Lighting - Pendent/Surface Toilet Room next to 102 EΑ 7 6-10 years Walls - Concrete Block SF 7 Toilet Room next to 102 191 10+ years Water Closet FΑ 7 Toilet Room next to 102 10+ years **Building: Main** 

Category: Classroom

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroo	m #100 (Art Room)						
	Ceiling - Lay-in	1st Floor	1,250	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	24	SF	5	0-1 year	Water damaged
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,274	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
0	Ham. Time	Lagation	O. antitu	ПОМ	Donk	Recommend	Comments
Group	Item - Type Marker Board	Location 1st Floor	Quantity	UOM LF	Rank 7	Replacement	Comments
		1st Floor	6 28	SF	-	6-10 years	
	Storage/ Closet				5	10+ years	
	Walls - Concrete Block	1st Floor	1,166	SF	7	10+ years	
Classro	om #101 (Computer Lab)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	997	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	400	SF	4	0-1 year	Damaged carpet
	Floor - Tile	1st Floor	597	SF	7	10+ years	3
	Lighting - Lay-in	1st Floor	14	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	28	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,156	SF	7	10+ years	
Classro	om #103 (Regular Classroom)						
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,015	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1,010	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Carpet	1st Floor	418	SF	4	0-1 year	Damaged carpet
	Floor - Tile	1st Floor	597	SF	6	10+ years	Damaged carpet
	Lighting - Lay-in	1st Floor	14	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	28	SF	5	,	
	Walls - Concrete Block	1st Floor	1,166	SF	5 7	10+ years 10+ years	
			,			, , , , , ,	
Classro	om #105 (Faculty Lounge)						
	Ceiling - Lay-in	1st Floor	715	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Carpet	1st Floor	685	SF	6	2-5 years	
	Floor - Carpet	1st Floor	30	SF	4	0-1 year	Damaged carpet
	Lighting - Lay-in	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	967	SF	7	10+ years	
Classro	om #200 (Regular Classroom)						
	Casework	2nd Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	685	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	Č
	Floor - Tile	2nd Floor	691	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	ĒΑ	6	6-10 years	
						-	

Page : 13 of 21



Catego	Category: Classroom			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	732	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	210	SF	6	10+ years	
				-		, , , , , , , , , , , , , , , , , , , ,	
Classroo	om #201 (Computer Lab)						
	Ceiling - Lay-in	2nd Floor	670	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	36	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	water damage
	Floor - Tile	2nd Floor	706	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	961	SF	7	10+ years	
	Walls Concrete Block	2110 1 1001	301	O.	,	101 years	
Classroo	om #202 (Regular Classroom)						
	Casework	2nd Floor	16	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	664	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	42	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Ğ
	Floor - Tile	2nd Floor	706	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	529	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	432	SF	6	10+ years	
01	#000 (Office)						
Classroc	om #203 (Office)	0.15	10			0.40	
	Casework	2nd Floor	12	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	670	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	670	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	940	SF	7	10+ years	
Classroc	om #204 (Regular Classroom)						
	Casework	2nd Floor	15	LF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	770	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	10	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	-
	Floor - Carpet	2nd Floor	780	SF	6	2-5 years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	720	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	230	SF	7	•	

Page : 14 of 21





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #205 (Regular Classroom)						
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	682	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	6	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Carpet	2nd Floor	688	SF	4	0-1 year	Damaged throughout
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	720	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	230	SF	6	10+ years	
Classroo	m #207 (Regular Classroom)						
	Casework	2nd Floor	15	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	679	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	30	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	vvator damago
	Floor - Carpet	2nd Floor	709	SF	4	1-2 years	Damaged throughout
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	Damaged imoughout
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	709	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	250	SF	6	10+ years	
Classras	om #208 (Other Instructional Use)						
Classioo	Casework	2nd Floor	44	LF	6	10	
			764	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor			6	6-10 years	\\/_t
	Ceiling - Lay-in	2nd Floor	36	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Carpet	2nd Floor	800	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	968	SF	7	10+ years	
Classroo	om #300 (Vacant)						
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	691	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Carpet	3rd Floor	691	SF	4	1-2 years	Damaged throughout
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years	-
	Walls - Concrete Block	3rd Floor	624	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	4	SF	5	0-1 year	Cracks in masonry
		3rd Floor	320	SF	6	10+ years	•

Page : 15 of 21





**Building: Main** Category: Classroom Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Classroom #301 (Vacant) Ceiling - Lay-in 3rd Floor 649 SF 6 10+ years Ceiling - Lay-in 3rd Floor SF 5 0-1 year 18 Water damage Chalk Board 20 LF 4 2-5 years 3rd Floor Doors - Wood Doors inclu hw FΑ 3rd Floor 6 10+ years 1 Floor - Carpet 3rd Floor 667 SF 4 0-1 year Damaged throughout 7 Lighting - Lay-in 3rd Floor 8 FΑ 6-10 years Lighting - Lay-in 3rd Floor 2 EΑ 6 6-10 years Relamp Walls - Concrete Block SF 3rd Floor 745 6 10+ years Walls - Metal Panel 216 SF 6 3rd Floor 10+ years Classroom #302 (Vacant) Casework LF 3rd Floor 12 6 10+ years SF Ceiling - Lay-in 3rd Floor 688 6 10+ years Ceiling - Lay-in 3rd Floor 12 SF 5 0-1 year Water damage Doors - Wood Doors inclu hw EΑ 6 3rd Floor 1 10+ years Floor - Carpet SF 0-1 year 3rd Floor 700 4 Damaged throughout FΑ 7 Lighting - Lay-in 3rd Floor 10 6-10 years Walls - Concrete Block 3rd Floor 529 SF 6 10+ years SF Walls - Metal Panel 3rd Floor 432 10+ years Classroom #303 (Vacant) LF Casework 3rd Floor 12 6 10+ years SF Ceiling - Lay-in 3rd Floor 655 6 10+ years SF Ceiling - Lay-in 3rd Floor 12 4 0-1 year Water damage Chalk Board LF 4 3rd Floor 28 2-5 years Doors - Wood Doors inclu hw 3rd Floor 1 EΑ 6 10+ years Floor - Carpet 3rd Floor 667 SF 4 0-1 year Damaged throughout 7 Lighting - Lay-in 3rd Floor 10 EΑ 6-10 years Walls - Concrete Block 725 SF 3rd Floor 10+ years Classroom #304 (Vacant) 1st Floor 12 LF 6 Casework 10+ years SF Ceiling - Lay-in 1st Floor 691 6 10+ years LF Chalk Board 1st Floor 2-5 years 16 4 Doors - Wood Doors inclu hw 1st Floor 1 EΑ 6 10+ years Floor - Carpet 1st Floor 691 SF 4 0-1 year Damaged throughout Lighting - Lay-in 1st Floor EΑ 7 6-10 years 10 Walls - Concrete Block SF 1st Floor 840 6 10+ years SF Walls - Concrete Block 1st Floor 15 5 1-2 years Cracked masonry Walls - Metal Panel 1st Floor 320 SF 6 10+ years Work Sink 5 1st Floor EΑ 1-2 years Not functioning

Page: 16 of 21



Category : Classroom			В	Building : Main			
_							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #305 (Vacant)						
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	688	SF	6	10+ years	
	Chalk Board	3rd Floor	28	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Carpet	3rd Floor	688	SF	4	1-2 years	Stained and damaged throughout
	Lighting - Lay-in	3rd Floor	8	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	2	EA	6	6-10 years	Relamp
	Walls - Concrete Block	3rd Floor	688	SF	7	10+ years	•
	Walls - Metal Panel	3rd Floor	216	SF	6	10+ years	
Classroo	m #307 (Faculty Lounge)						
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	714	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Carpet	3rd Floor	714	SF	4	1-2 years	Stained and damaged throughout
	Lighting - Lay-in	3rd Floor	10	EA	7	6-10 years	Stained and damaged imoughou
	Walls - Concrete Block	3rd Floor	751	SF	7	10+ years	
	Walls - Metal Panel	3rd Floor	216	SF	6	•	
	Work Sink	3rd Floor	1	EA	7	10+ years 10+ years	
	Work Silik	310 1 1001	ı	LA	,	10+ years	
Classroo	m #309 A (Cosmetology)						
	Casework	3rd Floor	6	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,265	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	12	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	•
	Floor - Tile	3rd Floor	1,277	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	18	EΑ	6	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	85	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,402	SF	7	10+ years	
	Walls - Metal Panel	3rd Floor	216	SF	6	10+ years	
	Work Sink	3rd Floor	4	EA	7	10+ years	
Category : Interior		В	uilding	: Main			
_							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	2,125	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	36	SF	4	0-1 year	Water damage
	Doors - Wood Doors include hw	1st Floor	4	EΑ	7	10+ years	





**Building: Main** Category: Interior Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Drinking Fountains - Single Water Cooler 1st Floor 3 EΑ 6-10 years 7 Floor - Tile Ceramic/ Porcelain 1st Floor 300 SF 7 10+ years Floor - Tile/Sheet 1st Floor 1.861 SF 5 6-10 years 20 EΑ 7 Lighting - Lay-in 1st Floor 6-10 years SF Walls - Concrete Block 1st Floor 3,843 7 10+ years SF Ceiling - Lay-in 2nd Floor 1,064 6 10+ years Ceiling - Lay-in 2nd Floor SF 0-1 year 6 4 Water damage Drinking Fountains - Single Water Cooler 2nd Floor 2 EΑ 7 10+ years Floor - Tile/Sheet 2nd Floor 1.065 SF 7 10+ years SF Floor - Tile/Sheet 2nd Floor 4 0-1 vear Sunken floor area Lighting - Lav-in 2nd Floor 9 EΑ 6 6-10 years Walls - Concrete Block 2nd Floor 2.055 SF 7 10+ years Ceiling - Lay-in 3rd Floor 1,396 SF 6 10+ years SF Ceiling - Lay-in 3rd Floor 8 4 0-1 year Water damage Drinking Fountains - Single Water Cooler 2 EΑ 7 3rd Floor 10+ years Floor - Tile/Sheet SF 7 3rd Floor 1.404 10+ years EΑ Lighting - Lay-in 3rd Floor 12 6 6-10 years Walls - Concrete Block 3rd Floor 2.850 SF 7 10+ years Safety 1st Floor EΑ 7 Camera Viewing Station 1 6-10 years Metal Detector 1st Floor 1 EΑ 7 6-10 years Security Cameras 1st Floor 5 EΑ 7 10+ years Not previously assessed 1st Floor 2 EΑ Security Cameras 7 6-10 years Stairs Ceiling - Lay-in SF Stair #1 South 434 6 10+ years Ceiling - Lav-in Stair #1 South 6 SF 0-1 year 4 Water damaged Floor - Terrazzo Stair #1 South 432 SF 6 10+ years LF 7 Handrails Stair #1 South 48 10+ years 2 EΑ Lighting - Lay-in Stair #1 South 6 6-10 years LF Stairs - Terrazzo Stair #1 South 216 6 10+ years Walls - Concrete Block Stair #1 South SF 7 4,320 10+ years Ceiling - Lay-in Stairs #2 North 501 SF 6 10+ years Floor - Terrazzo Stairs #2 North 504 SF 6 10+ years LF Handrails Stairs #2 North 48 7 10+ years Stairs #2 North 2 EΑ 7 6-10 years Lighting - Lay-in Stairs - Terrazzo Stairs #2 North 216 LF 6 10+ years Walls - Concrete Block Stairs #2 North SF 7 5,040 10+ years Vertical Conveyance Elevator - Hvdraulic Elevator 1st to 3rd Floors 1 EΑ 7 10+ years

Page: 18 of 21



Category : Site			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	3						
	Civil/ Drainage - Catch Basin	Entire Site	10	EA	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	5	0-1 year	Sinking. Quantity changed to match current observations
	Civil/ Drainage - Site Manhole	Entire Site	3	EA	7	10+ years	current observations
Fencina							
	Fencing - Chain Link	Entire Site	1,650	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	825	LF	4	0-1 year	Broken/tress growing up in the fence
	Fencing - New Standard Ornamental	Entire Site	350	LF	6	10+ years	0 0 1
	Fencing - New Standard Ornamental	Entire Site	100	LF	4	0-1 year	Corroded/bent
Landsca	pe						
	Landscape - Grass	Entire Site	14,000	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	600	SF	6	10+ years	Added to match current observations
	Landscape - Hardscape- Concrete	Entire Site	2,200	SF	6	10+ years	
	Parkway trees	Entire Site	9	EA	6	10+ years	
	Trash Receptacles	Entire Site	1	EA	6	10+ years	
Parking	Lot						
- ansing	Lighting - Pole Mounted	South	2	EA	4	0-1 year	Newer LED lights but not connected to the power
	Surface - Asphalt	South	7,332	SF	7	10+ years	New asphalt replaced the two old Modulars
	Surface - Asphalt	South	35,318	SF	4	0-1 year	Corrected quantity, Cracking/dipping cracking/dipping
Playgrou	und						
	Equipment - Pre K 3-5	East	1	EA	5	2-5 years	
	Surface - Square Rubber Mats	East	1,750	SF	4	0-1 year	Gaps/loose. Corrected quantity
Sidewall	(S						
	Sidewalks - Internal Walks	Entire Site	468	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	12	LF	5	1-2 years	Cracking/settling
	Sidewalks - Perimeter Sidewalks	Entire Site	2,100	SF	7	10+ years	5
Signage							
<del>-0-0-</del>	Flag Pole - Flag Pole	East	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	East	1	EA	6	6-10 years	
	<b>5 5</b>					•	

Page : 19 of 21



## **Excel Academy of South Shore**

7530 S South Shore DRIVE, Chicago, IL 60649

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

## **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



**Classroom Summary** 

Classicom Cuminary			D	Floor Plan	A	Glazed	Operable	Window	0
Current Usage	Intended Usage	Room Location	Room Number	Room Number	Area (SF)	Window Area	Window Area	Window Stop	Smart- Board
Building : Main	monaca ecago	Troom Zoodion	- Italiaei	Trainiso.	(0. /	71100	7.1.00	- Clop	200.0
Art Room	Art Room	1st Floor	100	118	1,274	156	32		Υ
Computer Lab	Kindergarten	1st Floor	101	148	997	120	30		
Computer Lab	Regular Classroom	2nd Floor	201	201	706	104	16		
Cosmetology	Science Classroom	3rd Floor	309 A	314	1,277	182	32		
Faculty Lounge	Regular Classroom	1st Floor	105	147	715	104	16		N
Faculty Lounge	Regular Classroom	3rd Floor	307	316	714	104	16		
Office	Regular Classroom	2nd Floor	203	203	670	104	16		
Other Instructional Use	Regular Classroom	2nd Floor	208	219	800	104	16		
Regular Classroom	Kindergarten	1st Floor	103	149	1,015	104	16		Υ
Regular Classroom	Regular Classroom	2nd Floor	200	221	691	104	16		N
Regular Classroom	Regular Classroom	2nd Floor	202	202	706	104	16		Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	780	126	60		Υ
Regular Classroom	Regular Classroom	2nd Floor	205	220	688	104	16		Υ
Regular Classroom	Special Education	2nd Floor	207	222	709	104	16		Υ
Vacant	Regular Classroom	1st Floor	304	319	691	104	16		
Vacant	Regular Classroom	3rd Floor	300	318	691	104	16		
Vacant	Regular Classroom	3rd Floor	301	301	667	104	16		
Vacant	Regular Classroom	3rd Floor	302	302	700	104	16		
Vacant	Regular Classroom	3rd Floor	303	303	667	104	16		
Vacant	Regular Classroom	3rd Floor	305	317	688	104	16		