

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <u>http://www.cps.edu/facilityassessment</u>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1926	2	53,097
Boiler House	1925	1	3,200
Campus Total			56,297

Category : Exterior Building : Main							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio	#1 - Main - NE	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	#1 - Main - NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 - Main - NE	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#1 - Main - NE	24	LF	7	10+ years	
	Ramps - Concrete	#1 - Main - NE	20	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1 - Main - NE	7	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1 - Main - NE	3	LF	4	0-1 year	Damaged, bent
	Exterior Doors - Exterior Steel Door	#2 - NE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 - NE	2	EA	6	10+ years	
	Exterior Stairs - Stone	#2 - NE	14	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#3 - SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 - SE	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#4 - SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 - SW	2	EA	6	10+ years	
	Exterior Stairs - Stone	#4 - SW	14	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 - NW	2	EA	4	1-2 years	Corroded doors
	Exterior Doors - Transom Lite	#5 - NW	2	EA	6	10+ years	
	Exterior Stairs - Stone	#5 - NW	14	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#6 - NW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#6 - NW	1	EA	7	10+ years	
	Exterior Doors - Transom Lite	#6 - NW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 - NW	24	LF	7	10+ years	
	Ramps - Concrete	#6 - NW	30	LF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main			
J				Ŭ		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•	Stair Handrail - Steel_Stair Handrail	#6 - NW	10	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	#7 - N	1	EA	6	6-10 years		
	Exterior Doors - Transom Lite	#7 - N	1	EA	6	10+ years		
	Exterior Stairs - Stone	#7 - N	8	LF	6	10+ years		
oundat	on							
	Foundation - Concrete	Entire Building	808	LF	7	10+ years	Subtracted 230 ft.Â ² for Fieldhouse	
	Superstructure - Concrete	Entire Building	49,897	SF	7	10+ years	Subtracted 3200 ft.Â ² for Fieldhouse	
ighting								
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	14	EA	7	10+ years		
Roof Sys	stem							
	Coping - Terra Cotta	Low North Roofs	110	LF	7	10+ years		
	Downspouts - Exterior Downspouts	Low North Roofs	39	LF	7	10+ years		
	Parapet - 16" - 30" Height	Low North Roofs	110	LF	7	10+ years		
	Roof - Modified Bitumen	Low North Roofs	426	SF	6	10+ years		
	Roof Structure - Concrete	Low North Roofs	426	SF	7	10+ years		
	Access Ladder - Metal	Main Roof	4	EA	7	10+ years		
	Coping - Metal	Main Roof	40	LF	7	10+ years		
	Coping - Terra Cotta	Main Roof	801	LF	6	10+ years		
	Downspouts - Interior Downspouts	Main Roof	780	LF	7	10+ years		
	Parapet - 16" - 30" Height	Main Roof	316	LF	7	10+ years		
	Parapet - Parapet < 16" Height	Main Roof	172	LF	7	10+ years		
	Parapet - Parapet > 30"	Main Roof	313	LF	7	10+ years		
	Roof - Modified Bitumen	Main Roof	20,308	SF	6	10+ years		
	Roof - Modified Bitumen	Main Roof	2,000	SF	4	1-2 years	Blistering throughout, with some of the blistering showing beginnings o cracks. Minimum amount of pondin Small soft spots. Deteriorating sealant at counter flashing.	
	Roof Hatch - Metal	Main Roof	2	EA	7	10+ years		
	Roof Structure - Concrete	Main Roof	22,308	SF	7	10+ years		
/alls								
	Cornice - Cast Stone	Entire Building	914	LF	7	10+ years		
	Exterior Walls - Brick	Entire Building	19,619	SF	6	10+ years	Subtracted 4710 ft.Â ² for the Fieldhouse	
	Exterior Walls - Stone-Cast	Entire Building	822	SF	6	10+ years	Subtracted 690 ft.Â ² for Fieldhouse	
	Exterior Walls - Terra Cotta	Entire Building	1,900	SF	6	10+ years		
Vindows	3							
	Guard - Guards perforated	Entire Building	3,858	SF	6	10+ years	Subtracted 120 ft.Â ² for Fieldhouse	



Catego	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lintels - Steel	Entire Building	502	LF	7	10+ years	Subtracted 35linear feet for Fieldhouse
	Lintels - Stone	Entire Building	50	LF	7	10+ years	
	Lintels - Terra Cotta	Entire Building	145	LF	6	10+ years	
	Windows - Louver	Entire Building	48	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,028	SF	7	10+ years	Subtracted 120 ft.Â ² for Fieldhouse
	Windows - Wood- Single-pane	Entire Building	125	SF	5	2-5 years	

Catego	ry : Electrical		В	uilding	: Main		
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System						
	Emergency Battery Packs - Auditoium and Aisle Lighting	Auditorium	1	EA	4	1-2 years	Obsolete parts
	Exit Signs - Auditoium	Entire Building	8	EA	4	2-5 years	Over 20 years old with incandescen bulbs
	Exit Signs - Corridors and Stairs	Entire Building	18	EA	4	2-5 years	Over 20 years old with incandescen bulbs
	Exit Signs - Gym	Entire Building	4	EA	4	2-5 years	Over 20 years old with incandescen bulbs
	Security System - Intrusion Detection	Entire Building	53,097	SF	4	1-2 years	Majority obsolete system/parts
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	1,662	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	26,406	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	2,542	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	563	SF	6	6-10 years	
Main Se	rvice						
	PA System	Entire Building	53,097	SF	5	6-10 years	Muffled noise in certain areas
Power D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
Group	ltem - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	21	Location	Qualitity		INALIK	Replacement	Comments
Fire Alaı	m						



Category : Fire Protection

Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Fire ALarm Anunciator Entire Building ΕA 6 6-10 vears 1 Fire Alarm Strobe Lights 53.097 SF 6 6-10 vears Entire Building Fire Alarm_System Entire Building 53.097 SF 6 6-10 years Category : Mechanical **Building : Main** Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Group Air Handling Systems Air Handling Unit- Built Up- Single Zone w/ Basement - AHU1 ΕA 1 5 6-10 years Air Tunnel- Steam Coils - Greater than 35000 cfm Air Intake Basement - AHU1 1 ΕA 6 6-10 vears Auxiliaries - Greater than 35000 cfm Basement - AHU1 FΑ 5 2-5 years 1 Reheat Boxes - Reheat Boxes with Steam Basement - AHU1 ΕA 6 6-10 years 11 Coil 300 1 F 5 Return Duct Work - Masonry and Ducts-Basement - AHU1 2-5 years Missing or Existing Shaft 5 Zone Dampers Basement - AHU1 29 EΑ 2-5 years Air Handling Unit- Built Up- Single Zone-**Basement - Auditorium AHU** 1 ΕA 5 2-5 years Steam Coils - 4000 - 8000 cfm Air Intake Basement - Auditorium AHU 1 ΕA 6 6-10 years Auxiliaries - 4000 - 8000 cfm Basement - Auditorium AHU EΑ 5 2-5 years 1 Return Duct Work - Masonry and Ducts-Basement - Auditorium AHU 100 LF 5 2-5 vears Missing or Existing Shaft Air Handling Unit- Built Up- Single Zone-ΕA 5 Basement - Gym AHU 1 2-5 years Steam Coils - 4000 - 8000 cfm Air Intake 6 Basement - Gym AHU 1 ΕA 6-10 years Basement - Gym AHU Auxiliaries - 4000 - 8000 cfm 1 FΑ 5 2-5 years 1 F Return Duct Work - Masonry and Ducts-Basement - Gvm AHU 100 5 2-5 years Missing or Existing Shaft Boiler Systems Piping - Condensate Pipe- Steel LF 5 Entire Building 650 2-5 years Corroded/deteriorating LF Piping - Steam Pipe- Steel Entire Building 650 5 6-10 years ΕA Steam Traps Entire Building 15 5 2-5 years Deteriorating Heating Devices Entire Buildina Radiators - Steam 18 ΕA 5 6-10 years Wall Heater - Electric Entire Building 2 ΕA 5 2-5 years Fin Tube - Steam 50 LF 6 6-10 years Entire Building Temperature Control **Electric Thermostat** 2 6 For indoor fan and MDF cooling unit Entire Building EΑ 6-10 years

Building : Main



Catego	ry : Mechanical		B	uilding	: Main			
_	-	Location		-		Recommend	Commonto	
Group	Item - Type Pneumatic System	Entire Building	Quantity 53,097	UOM SF	Rank 5	2-5 years	Comments	
	Thermostats - Pneumatic	Entire Building	29	EA	5 5	2-5 years 2-5 years	Outdated parts	
		Entire Building	29	EA	5	2-5 years	Outdated parts	
entilatio	n							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	5	6-10 years		
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	6	6-10 years		
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	2	EA	6	6-10 years		
atego	ry : Plumbing		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Piping								
	Domestic Piping-Hot Water Return Lines	Entire Building	53,097	SF	4	1-2 years	Insulation damage throughout, pipe clamps installed, over 40 years old galvanized	
	Domestic Piping-Hot Water Return Risers	Entire Building	53,097	SF	4	1-2 years	Insulation damage throughout, pip clamps installed, over 40 years old	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	53,097	SF	4	1-2 years	galvanized Insulation damage throughout, pip clamps installed, over 40 years old galvanized	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	53,097	SF	4	1-2 years	Insulation damage throughout, pip clamps installed, over 40 years old galvanized	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	53,097	SF	4	1-2 years	Insulation damage throughout, pip clamps installed, over 40 years old galvanized	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	53,097	SF	4	1-2 years	Insulation damage throughout, pip clamps installed, over 40 years old galvanized	
	Sanitary Piping	Entire Building	53,097	SF	5	2-5 years	yaivanizeu	
	Storm Piping	Entire Building	53,097	SF	5	2-5 years		
	Vent Piping	Entire Building	53,097	SF	5	2-5 years		
			23,001	••	•	- 0 ,00.0		
	1 0							
umps								



Franklin Elementary Fine Arts Center 225 W Evergreen AVENUE, Chicago, IL 60610

Catego	ry : Room		В	uilding	: Main	-	
j	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices					-	
	Ceiling - Plaster/Drywall	105A	417	SF	7	10+ years	
	Doors - Wood Doors inclu hw	105A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	105A	417	SF	6	10+ years	
	Lighting - Pendent/Surface	105A	6	EA	6	6-10 years	
	Power Distribution	105A	6	EA	7	10+ years	
	Storage/ Closet	105A	120	SF	7	10+ years	
	Walls - Masonry	105A	377	SF	7	10+ years	
	Walls - Plaster/Drywall	105A	377	SF	7	10+ years	
	AC Unit	112	1	ĒA	7	6-10 years	
	Ceiling - Plaster/Drywall	112	275	SF	7	10+ years	
	Doors - Transom Window	112	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	112	1	ĒA	6	10+ years	
	Floor - Carpet	112	137	SF	7	6-10 years	
	Floor - Tile	112	138	SF	7	6-10 years	
	Lighting - Pendent/Surface	112	5	ĒA	7	6-10 years	
	Power Distribution	112	10	EA	7	10+ years	
	Storage/ Closet	112	40	SF	7	10+ years	Storage Room in good condition
	Walls - Plaster/Drywall	112	426	SF	7	10+ years	3
	AC Unit	112A	1	ĒA	7	6-10 years	
	Ceiling - Plaster/Drywall	112A	298	SF	7	10+ years	
	Doors - Wood Doors inclu hw	112A	1	EA	6	10+ years	
	Floor - Carpet	112A	298	SF	7	6-10 years	
	Lighting - Pendent/Surface	112A	2	EA	7	6-10 years	
	Power Distribution	112A	8	EA	7	10+ years	
	Walls - Plaster/Drywall	112A	453	SF	7	10+ years	
	AC Unit	113	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	113	98	SF	6	10+ years	Paint chipping and peeling
	Doors - Wood Doors inclu hw	113	1	EA	6	10+ years	
	Floor - Wood	113	98	SF	6	10+ years	
	Lighting - Pendent/Surface	113	6	EA	6	6-10 years	
	Power Distribution	113	8	EA	7	10+ years	
	Walls - Plaster/Drywall	113	628	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Auditorium Lobby	120	SF	5	2-5 years	Ceiling paint bubbling and cracking
	Doors - Wood Doors inclu hw	Auditorium Lobby	1	EA	6	10+ years	<u> </u>
	Floor - Tile Ceramic/ Porcelain	Auditorium Lobby	120	SF	7	10+ years	
	Lighting - Pendent/Surface	Auditorium Lobby	3	EA	6	6-10 years	
	Power Distribution	Auditorium Lobby	6	EA	7	10+ years	
	Walls - Masonry	Auditorium Lobby	330	SF	7	10+ years	
	Walls - Plaster/Drywall	Auditorium Lobby	110	SF	7	10+ years	
	Work SInk	Auditorium Lobby	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Auditorium Lobby	73	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Auditorium Lobby	1	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Auditorium Lobby	58	SF	7	10+ years	



ALLA .						225	W Evergreen AVENUE, Chicago, IL 60610
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Auditorium Lobby	15	SF	5	1-2 years	Tiles missing
	Lighting - Pendent/Surface	Auditorium Lobby	1	EA	7	6-10 years	
	Walls - Masonry	Auditorium Lobby	145	SF	7	10+ years	
	Walls - Plaster/Drywall	Auditorium Lobby	200	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Kitchen Manager	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Manager	1	EA	7	10+ years	
	Floor - Tile	Kitchen Manager	120	SF	7	10+ years	
	Lighting - Pendent/Surface	Kitchen Manager	4	EA	7	6-10 years	
	Power Distribution	Kitchen Manager	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Manager	440	SF	7	10+ years	
_Auditoriu	um & Theater						
	Balcony Seating	1st Floor	80	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,662	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	964	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	64	EA	6	6-10 years	
	Sound System	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	698	SF	7	10+ years	
	Stage Curtain	1st Floor	6	EA	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	18	LF	7	10+ years	
	Stairs - Terrazzo	1st Floor	130	LF	7	10+ years	
	Storage/ Closet	1st Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,087	SF	7	10+ years	
	Walls - Sound Panel	1st Floor	2,087	SF	7	10+ years	
_Gymnas	ia						
	Ceiling - Plaster/Drywall	105	2,542	SF	7	10+ years	
	Doors - Wood Doors inclu hw	105	2	EA	7	10+ years	
	Floor - Wood	105	2,542	SF	7	10+ years	
	Lighting - Pendent/Surface	105	10	EA	7	10+ years	
	Storage/ Closet	105	131	SF	7	10+ years	
	Walls - Masonry	105	2,669	SF	7	10+ years	
	Walls - Plaster/Drywall	105	3,559	SF	7	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	110	731	SF	7	10+ years	
	Doors - Wood Doors inclu hw	110	1	EA	6	10+ years	
	Floor - Tile	110	731	SF	6	6-10 years	
	Lighting - Pendent/Surface	110	14	EA	6	6-10 years	
	Serving Line	110	12	LF	7	10+ years	
	-					y -	



Catego	ory : Room		В	uilding	: Main		
Ŭ				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
- -	Walls - Plaster/Drywall	110	1,390	SF	7	10+ years	
	, , , , , , , , , , , , , , , , , , ,	-	,	-		, ,	
ibrary							
	AC Unit	118	1	EA	7	6-10 years	
	Casework	118	55	LF	7	10+ years	
	Ceiling - Plaster/Drywall	118	730	SF	7	10+ years	
	Doors - Transom Window	118	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	118	1	EA	7	10+ years	
	Floor - Wood	118	730	SF	7	10+ years	
	Lighting - Pendent/Surface	118	14	EA	6	6-10 years	
	Walls - Plaster/Drywall	118	1,118	SF	7	10+ years	
	-						
/IDF_ID	Doors - Side-lite	224	24	SF	7	10+ years	
	Doors - Transom Window	224	3	SF	7	10+ years	
	Doors - Wood Doors inclu hw	224	1	EA	7	10+ years	
	Finishes	224	167	SF	7	10+ years	
	Finishes	224	2	SF	5	0-1 year	Hole in wall
	Other Cooling Unit	224	2	EA	7	6-10 years	Heat pump
		227		L/\	'	o to years	
Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	15	SF	7	6-10 years	
	Janitor's Closet	1st Floor	15	SF	5	2-5 years	Drywall needs repair
	Storage Room	1st Floor	161	SF	7	10+ years	
	Storage Room	1st Floor	15	SF	5	2-5 years	Paint on ceiling is chipping and
	0					,	peeling
	Mechanical/ Service Rooms	2.5 Floor	23	SF	7	10+ years	
	Janitor's Closet	2nd Floor	16	SF	5	10+ years	No light
	Janitor's Closet	2nd Floor	16	SF	5	10+ years	No light
	Air Tunnel	Basement	2,592	SF	7	10+ years	5
	Auditorium Plenums	Basement	273	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,694	SF	7	10+ years	
	Storage Room	Basement	1,353	SF	7	6-10 years	
	-						
Restroo	M Accessories	1st Floor	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	263	SF	7	10+ years	
	Doors - Wood Doors inclu hw		203	EA	6	6-10 years	
		1st Floor	-	SF			
	Floor - Tile Ceramic/ Porcelain	1st Floor	263		6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	



Catego	ry : Room		R	uilding	· Main	220	W Evergreen AVENUE, Chicago, il 60610
Juiego				anang	· main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
P	Partitions	1st Floor	1	EA	7	10+ years	
	Urinals	1st Floor	6	EA	7	10+ years	
	Walls - Masonry	1st Floor	184	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	184	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor	300	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	300	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	300	SF	5	2-5 years	Cracks in the tile
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Partitions	1st Floor	6	EA	7	10+ years	
	Walls - Masonry	1st Floor	210	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	210	SF	7	10+ years	
	Water Closet	1st Floor	6	EA	7	10+ years	
	Accessories	213A	105	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	213A	95	SF	7	10+ years	
	Ceiling - Plaster/Drywall	213A	10	SF	5	1-2 years	Water damage
	Doors - Side-lite	213A	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	213A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	213A	105	SF	7	10+ years	
	Lavatory	213A	1	ĒA	7	10+ years	
	Lighting - Pendent/Surface	213A	1	EA	7	10+ years	
	Partitions	213A	2	EA	7	10+ years	
	Walls - Masonry	213A	237	SF	7	10+ years	
	Walls - Plaster/Drywall	213A	189	SF	7	10+ years	
	Water Closet	213A	2	EA	7	10+ years	
	Accessories	2nd Floor	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	263	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	263	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Partitions	2nd Floor		EA	7	6-10 years	Updated to match current
	T attuons	2110 1 1001	I	LA	,	0-10 years	observations
	Urinals	2nd Floor	7	EA	7	10+ years	
	Walls - Masonry	2nd Floor	184	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	184	SF	7	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	2nd Floor	300	SF	7	6-10 years	



Catego	ry : Room		В	uilding	: Main		
U	-			U		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	300	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Partitions	2nd Floor	7	EA	7	10+ years	
	Walls - Masonry	2nd Floor	210	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	210	SF	7	10+ years	
	Water Closet	2nd Floor	7	EA	7	10+ years	
	Accessories	2nd Floor - Unisex	27	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Unisex	27	SF	7	10+ years	
	Doors - Transom Window	2nd Floor - Unisex	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Unisex	1	EA	7	10+ years	
	Floor - Tile Quarry	2nd Floor - Unisex	27	SF	7	6-10 years	
	Lavatory	2nd Floor - Unisex	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor - Unisex	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor - Unisex	29	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor - Unisex	29	SF	7	10+ years	
	Water Closet	2nd Floor - Unisex	1	EA	7	10+ years	
	Accessories	Principal's Office	27	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Principal's Office	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Principal's Office	22	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Principal's Office	5	SF	4	0-1 year	Hole in the floor
	Lavatory	Principal's Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Principal's Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Principal's Office	52	SF	7	10+ years	
	Water Closet	Principal's Office	1	EA	7	10+ years	

Category : Classroom

Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroom #114 (Music Room)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	3	LF	7	10+ years	
Ceiling - Plaster/Drywall	1st Floor	336	SF	7	10+ years	
Chalk Board	1st Floor	15	LF	4	2-5 years	
Doors - Transom Window	1st Floor	9	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Wood	1st Floor	336	SF	7	10+ years	
Lighting - Pendent/Surface	1st Floor	6	EA	7	6-10 years	
Sound Panels	1st Floor	12	EA	7	10+ years	

Building : Main



Category : Classroom			B	uilding	: Main		
	,				Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	300	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	550	SF	7	10+ years	
						-	
lassroo	m #115 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	716	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	716	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,088	SF	7	10+ years	
	-		,			,	
lassroo	m #116 (Dance Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	21	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,430	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	396	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Storage/ Closet	1st Floor	215	SF	7	10+ years	
	Storage/ Closet	1st Floor	105	SF	7	10+ years	
	Wall Mirrors	1st Floor	4	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	300	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,420	SF	7	10+ years	
	Weight/ Fitness Room Floor Matting	1st Floor	1,034	SF	7	10+ years	
	Weight Filliess Room Floor Malling	13(1100)	1,004	0	'	TOF years	
lassroo	m #117 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	716	SF	7	10+ years	
	Chalk Board	1st Floor	19	LF	4	2-5 years	Not in use anymore
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	716	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,088	SF	7	10+ years	



Franklin Elementary Fine Arts Center 225 W Evergreen AVENUE, Chicago, IL 60610

Catego	ry : Classroom		В	uilding	: Main		
e	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #119 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	716	SF	7	10+ years	
	Chalk Board	1st Floor	19	LF	4	2-5 years	Not in use anymore
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	,
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	716	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,088	SF	7	10+ years	
Classroo	om #120 (Art Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	75	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	672	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	Not in use anymore
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	,
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	672	SF	7	10+ years	
	Kiln	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	30	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,000	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
	Work Sink	1st Floor	3	EA	5	6-10 years	Leaky faucet
Classroo	om #121 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	716	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	716	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,088	SF	7	10+ years	
Classroo	m #122 (Special Education)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	5	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	390	SF	7	10+ years	
		1st Floor	20	LF	4	2-5 years	



Catego	Category : Classroom		В	uilding	: Main		· · ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	390	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	986	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
lassroo	m #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	375	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	80	SF	7	10+ years	
	Floor - Tile	2nd Floor	295	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	6	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	104	SF	7	10+ years	
	Student Lockers - One Tier	2nd Floor	15	EA	7	10+ years	
	Walls - Metal Panel	2nd Floor	181	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	650	SF	7	10+ years	
lassroo	m #210 (Regular Classroom)						
1005100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	711	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Water damage
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	9	EA	7	10+ years	
	Floor - Tile	2nd Floor	716	SF	7	•	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
			20			6-10 years	
	Marker Board	2nd Floor			7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	7	10+ years	
lassroc	m #212 (Regular Classroom)	- · · - ·					
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	716	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	714	SF	7	6-10 years	
	Floor - Tile	2nd Floor	2	SF	4	0-1 year	Chipping tile



Catego	ry : Classroom		В	uilding	: Main		
-				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	7	10+ years	
	ý					5	
lassroc	m #213 (Office)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	186	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	186	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	5	ĒA	7	6-10 years	
	Marker Board	2nd Floor	5	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	632	SF	7	10+ years	
	Walls T laster/Drywall	21011001	002	01	,	for years	
Classroo	m #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	716	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒA	7	10+ years	
	Floor - Tile	2nd Floor	716	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	7	10+ years	
	Wallo Plastol, Drywall	21011001	1,102	01		ior youro	
Classroo	m #215 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	716	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	716	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	7	10+ years	
Noorco	m #216 (Regular Classroom)						
1022100		and Elean	4		7	0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	716	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	



Category : Classroom		В	Building : Main				
	, · · · · · · · · · · · · · · · · · · ·		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	716	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒA	6	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	7	10+ years	
Classroo	m #217 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	716	SF	7	10+ years	
	Chalk Board	2nd Floor	26	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	716	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	7	10+ years	
lassroo	m #218 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	716	SF	7	10+ years	
	Chalk Board	2nd Floor	26	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	716	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	7	10+ years	
Classroc	m #219 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	716	SF	7	10+ years	
	Chalk Board	2nd Floor	26	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	716	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	7	10+ years	
lassroc	m #220 (Music Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	



	Schools					225	W Evergreen AVENUE, Chic
Catego	ry : Classroom		В	uilding	: Main	Decommond	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Sioup	Casework	2nd Floor	10	LF	7	10+ years	Comments
	Ceiling - Plaster/Drywall	2nd Floor	716	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	716	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Sound Panels	2nd Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	7	10+ years	
lassroo	m #222 (Music Room)						
100000	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,091	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,091	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	15	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,527	SF	7	10+ years	
	Work Sink	2nd Floor	· 1	EA	7	10+ years	
lassroo	m #225 (Computer Lab)						
	AC Units	2nd Floor	2	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	476	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	440	SF	7	10+ years	
	Floor - Tile	2nd Floor	34	SF	7	10+ years	
	Floor - Tile	2nd Floor	2	SF	4	0-1 year	Damaged tile
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	-
	Marker Board	2nd Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	772	SF	7	10+ years	
atego	ry : Interior		В	uilding	: Main		

J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	7,895	SF	7	10+ years	
	Doors - Transom Window	1st Floor	40	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	6	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	4	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	750	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	7,145	SF	7	10+ years	



Catego	ategory : Interior			uilding	: Main		
	-					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	32	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor	197	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	12,384	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	7,895	SF	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	4	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	790	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	7,099	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	6	SF	4	0-1 year	Cracking
	Lighting - Pendent/Surface	2nd Floor	32	EA	7	10+ years	-
	Rescue Panel	2nd Floor	1	EA	7	6-10 years	
	Stairs - Concrete Stairs	2nd Floor	100	LF	7	10+ years	
	Student Lockers - One Tier	2nd Floor	208	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	12,384	SF	7	10+ years	
	ç		,			,	
afety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
tairs							
	Ceiling - Plaster/Drywall	North East	5,308	SF	7	10+ years	
	Floor - Terrazzo	North East	5,308	SF	7	10+ years	
	Handrails	North East	284	LF	7	10+ years	
	Lighting - Pendent/Surface	North East	4	EA	7	6-10 years	
	Stairs - Terrazzo	North East	284	LF	7	10+ years	
	Walls - Plaster/Drywall	North East	8,226	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North West	5,308	SF	7	10+ years	
	Floor - Terrazzo	North West	5,308	SF	7	10+ years	
	Handrails	North West	242	LF	7	10+ years	
	Lighting - Pendent/Surface	North West	4	EA	7	6-10 years	
	Stairs - Terrazzo	North West	242	LF	7	10+ years	
	Walls - Plaster/Drywall	North West	8,226	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North West - To Basement	50	SF	5	1-2 years	Water damage
	Handrails	North West - To Basement	42	LF	7	10+ years	
	Lighting - Wall Mounted	North West - To Basement	1	EA	7	6-10 years	
	Stairs - Concrete	North West - To Basement	60	LF	6	10+ years	
	Walls - Plaster/Drywall	North West - To Basement	232	SF	5	1-2 years	Water damage
ertical	Conveyance			F •	_	0.40	
	Elevator - Hydraulic Elevator	West	1	EA	7	6-10 years	



Category : Exterior			В				
_			•			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Steel Door	8	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	9	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	9	1	EA	6	10+ years	
	Exterior Stairs - Stone	9	3	LF	6	10+ years	
Foundati	on						
	Foundation - Concrete	Boiler House	228	LF	7	10+ years	
	Foundation - Concrete	Boiler House	2	LF	5	1-2 years	Cracks seeping water
	Superstructure - Concrete	Boiler House	3,190	SF	7	10+ years	1 0
	Superstructure - Concrete	Boiler House	10	SF	6	10+ years	Cracks, corroding rebar
Lighting							
	Exterior Lighting - Wall Mounted	Boiler House	6	EA	6	6-10 years	
Roof Sve	stem						
	Access Ladder - Metal	Boiler House	2	EA	4	0-1 year	Old, poor transition from one ladder
	Chimney Matel Flue	Boiler House	37	LF	7	10, , , , , , , , , , , , , , , , , , ,	to the next. Dangerous transition
	Chimney - Metal Flue		230	LF	6	10+ years	Varified dimension applant is in near
	Coping - Terra Cotta	Boiler House	230	LF	0	6-10 years	Verified dimension, sealant is in poor condition. Comes off in one's finger upon touch
	Downspouts - Exterior Downspouts	Boiler House	18	LF	7	10+ years	
	Parapet - Parapet > 30"	Boiler House	173	LF	7	10+ years	
	Parapet - Parapet > 30"	Boiler House	57	LF	5	0-1 year	Spoiled brick, open joints, parapet in very poor condition
	Roof - Modified Bitumen	Boiler House	3,000	SF	7	10+ years	Verified dimension
	Roof - Modified Bitumen	Boiler House	200	SF	4	0-1 year	Detached, damaged counter, flashin
	Roof Hatch - Metal	Boiler House	1	EA	7	6-10 years	Dotaonoa, aamagoa ooantor, naonin
	Roof Structure - Concrete	Boiler House	3,200	SF	7	10+ years	
Walls							
	Exterior Walls - Brick	Boiler House	4,710	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Boiler House	685	SF	7	10+ years	
	Exterior Walls - Stone-Cast	Boiler House	5	SF	5	1-2 years	Open joints
			Ŭ	2.	2)	
Windows							
	Guard - Guards perforated	Boiler House	120	SF	6	10+ years	
	Guard - Guards wire guard	Boiler House	24	SF	6	10+ years	
	Lintels - Steel	Boiler House	35	LF	7	10+ years	
	Windows - Louver	Boiler House	24	SF	6	10+ years	



						225	W Evergreen AVENUE, Chicago, IL 60610			
Catego	ry : Exterior		В	Building : Boiler House						
Ū				Ū		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
•	Windows - Sash Aluminum Double-pane	Boiler House	120	SF	6	10+ years				
Catego	ry : Electrical		В	uilding	: Boiler	House				
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Emerger	ncy System									
	Automatic Transfer Switch	Boiler Room	1	EA	6	10+ years				
Main Se	n ico									
	Main Electrical Service - 2000 A	Boiler Room	1	EA	4	1-2 years	Corroding throughout			
	120/208/3PH	Boller Room	I	LA	4	I-2 years	Corroding throughout			
	Independent Electrical Service for	Boiler Room	1	EA	6	6-10 years				
	emergency power	Dener Reem		_/ (Ũ	e re jeure				
Power D	istribution									
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	2-5 years				
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	2-5 years				
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years				
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	3	0-1 year	Corroded and exposed live parts			
Catego	ry : Fire Protection		В	uildina	: Boiler	House				
earege	. ,		Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Fire Alar						•				
	Fire Alarm Panel	Boiler Room	1	EA	6	6-10 years				
	Fire Alarm_System	Boiler Room	3,200	SF	5	6-10 years				
	_ ,					,				
Catego	ry : Mechanical		В	uilding	: Boiler					
_						Recommend	_			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Boiler Sy										
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Entire Building	2	EA	6	6-10 years				
	Chemical Feed System	Entire Building	1	EA	6	6-10 years				
	Combustion Dampers	Entire Building	3	EA	6	2-5 years				
	Condensate Pump	Entire Building	1	EA	4	0-1 year	Leaking, heavily corroded			
	Feed Water Pumps and Tank	Entire Building	1	EA	5	2-5 years	_calling, nearly bollouou			
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	6	6-10 years				
	Steam- Low Pressure Boiler - 101 - 150 HP	Entrie Banany	I		U	o io youro				
	Non Condensing- Fire Tube- Scotch Marine-	Entire Building	1	EA	6	6-10 years				
	Steam- Low Pressure Boiler - 101 - 150 HP	Entro Banany	I	L/\	U	o io youio				
	Piping - Condensate Pipe- Steel	Entire Building	100	LF	5	2-5 years				
	i ping condendator ipo otoci	Entro Danan'ig	100		0					



Catego	ry : Mechanical		В	uildina	: Boiler	House	
outogo	i incontantoat			unung	. Bonor	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Piping - Steam Pipe- Steel	Entire Building	100	LF	5	2-5 years	
	Steam Traps	Entire Building	3	EA	5	2-5 years	
Heating	Devices						
C C	Unit Heater - Steam	Boiler Room	1	EA	6	6-10 years	
	Wall Heater - Electric	Engineer's Office	1	EA	6	6-10 years	
	Wall Heater - Electric	Engineer's Office	2	EA	5	2-5 years	Outdated parts
Tempera	ature Control						
•	Electric Thermostat	Entire Building	1	EA	5	2-5 years	
	Pneumatic System	Entire Building	3,200	SF	5	2-5 years	
Catego	ry : Plumbing		В	uilding	: Boiler	House	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	er						
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	5	6-10 years	
	Hot Water Storage Tank_Gas - 201 - 500 Gallons	Mechanical Room	1	EA	3	0-1 year	Disconnected/abandoned
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	3,200	SF	4	1-2 years	Insulation damage throughout, pipe clamps installed, over 40 years old galvanized
	Domestic Piping-Hot Water Return Risers	Entire Building	3,200	SF	4	1-2 years	Insulation damage throughout, pipe clamps installed, over 40 years old galvanized
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	3,200	SF	4	1-2 years	Insulation damage throughout, pipe clamps installed, over 40 years old galvanized
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	3,200	SF	4	1-2 years	Insulation damage throughout, pipe clamps installed, over 40 years old galvanized
							5

Sanitary Piping

Storm Piping

Vent Piping

(Risers)

Domestic Piping-Hot/Cold Water Supply

Domestic Piping-Hot/Cold Water Supply

(from Risers to Fixtures)

3,200

3,200

3,200

3,200

3,200

SF

SF

SF

SF

SF

4

4

5

5

5

1-2 years

1-2 years

2-5 years

2-5 years

2-5 years

Entire Building

Entire Building

Entire Building

Entire Building

Entire Building

Insulation damage throughout, pipe

clamps installed, over 40 years old

Insulation damage throughout, pipe

clamps installed, over 40 years old

galvanized

galvanized



Franklin Elementary Fine Arts Center 225 W Evergreen AVENUE, Chicago, IL 60610

Catego	ry : Plumbing	R	Building : Boiler House						
Caleyo	ry . Fluinbing		D	unung	. Doner	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Pumps	Kom Type	Loodion	Quantity	00111	Nam	Replacement	Commente		
umps	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	5	2-5 years	Beginning to corrode		
	Pumps - Sump-Duplex	Mechanical Room	1	EA	6	2-5 years	Beginning to conode		
		moonanioal recom		-/ (Ū	2 0 90010			
Catego	ry : Room		В	uilding	: Boiler	House			
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Administ	rative Suites/Offices								
	AC Unit	Boiler House	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	Boiler House	95	SF	4	0-1 year	Large cracks, falling off		
	Doors - Wood Doors inclu hw	Boiler House	1	EA	7	6-10 years			
	Floor - Carpet	Boiler House	95	SF	7	6-10 years			
	Lighting - Pendent/Surface	Boiler House	2	EA	7	6-10 years			
	Power Distribution	Boiler House	4	EA	7	10+ years			
	Walls - Plaster/Drywall	Boiler House	140	SF	6	6-10 years			
	Walls - Plaster/Drywall	Boiler House	7	SF	5	1-2 years	Broken plaster		
Mechani	cal/ Service Rooms								
	Boiler Room	Entire Building	2,054	SF	5	10+ years			
	Coal Room	Entire Building	938	SF	7	6-10 years			
	Storage Room	Entire Building	91	SF	7	6-10 years			
Restroor	n								
	Accessories	Restroom in Engineer's Office	22	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Restroom in Engineer's Office	22	SF	4	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	Restroom in Engineer's Office	1	EA	7	6-10 years	5		
	Floor - Epoxy/ Painted	Restroom in Engineer's Office	22	SF	7	6-10 years			
	Lavatory	Restroom in Engineer's Office	1	EA	6	6-10 years			
	Lighting - Pendent/Surface	Restroom in Engineer's Office	1	EA	6	6-10 years			
	Walls - Plaster/Drywall	Restroom in Engineer's Office	175	SF	6	10+ years			
	Water Closet	Restroom in Engineer's Office	1	EA	7	6-10 years			



Category : Site			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Athletic							
	Metal Bleachers	SE	20	LF	7	10+ years	
	Surface - Natural	SE	50,298	SF	5	6-10 years	
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	11	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	15	EA	7	10+ years	
Fencing							
	Fencing - Chain Link	Entire Site	302	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	159	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	20	LF	5	1-2 years	Broken chain links
	Fencing - New Standard Ornamental	Entire Site	1,768	LF	6	10+ years	
Landscap	De						
	Benches	Entire Site	16	EA	6	10+ years	
	Benches	Entire Site	12	EA	6	10+ years	
	Irrigation	Entire Site	33,800	SF	6	10+ years	
	Landscape - Grass	Entire Site	8,769	SF	6	10+ years	
	Landscape - Grass	Entire Site	3,000	SF SF	4	1-2 years	Bare soil
	Landscape - Hardscape- Concrete Landscape - Hardscape- Concrete	Entire Site Entire Site	1,611 100	SF	6 5	10+ years 1-2 years	Damaged with exposed rebar, broken
	Lanuscape - Haruscape- Concrete		100	эг	5	1-2 years	concrete, upheaved
	Lighting - Pole Mounted	Entire Site	6	EA	6	10+ years	
	Parkway trees	Entire Site	20	EA	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	12,270	SF	6	6-10 years	Some repairs made
	Play Area - Hardscape- Asphalt	Entire Site	1,000	SF	5	1-2 years	Large cracks, alligatoring of surface
	Retaining Wall - Concrete	Entire Site	100	SF	6	10+ years	
	Trash Receptacles	Entire Site	4	EA	6	10+ years	
	Walking Path - Hardscape- Asphalt	Entire Site	1,873	SF	6	6-10 years	
	Walking Path - Hardscape- Asphalt	Entire Site	200	SF	4	0-1 year	Upheaved, tripping hazard
Parking L							
	Concrete Curbs	West	1,318	LF	6	10+ years	
	Interior Plantings	West	130	LF	6	10+ years	
	Lighting - Pole Mounted	West	7	EA	6	10+ years	
	Surface - Asphalt	West	32,000	SF	6	6-10 years	Cracks throughout
	Surface - Asphalt	West	3,307	SF	5	0-1 year	Large cracks, alligatored surface, potholes
	Trash Enclosure - Chain Links	West	503	SF	5	6-10 years	Some slats are missing
	Vehicular Screening	West	386	LF	6	10+ years	5



						225	W EVergreen AVENUE, Chicago, iE 00010	
Category : Site			Building : Site					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Playgrou	Ind							
,0	Equipment - Pre K 3-5	South	2	EA	6	10+ years		
	Equipment - Swingset	South	2	EA	6	10+ years		
	Surface - Poured Surface	South	600	SF	6	10+ years		
Sidewall	(S							
	Sidewalks - Internal Walks	Entire Site	87	LF	7	10+ years		
	Sidewalks - Internal Walks	Entire Site	1,660	LF	7	10+ years		
	Sidewalks - Perimeter Sidewalks	Entire Site	16,204	SF	6	10+ years		
	Sidewalks - Perimeter Sidewalks	Entire Site	20	SF	5	0-1 year	Cracks, broken	
Signage								
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years		
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years		
	Monument - Sign	Entire Site	1	EA	6	10+ years		

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Regular Classroom	1st Floor	120	120	672	135	110	N	N
Computer Lab	Regular Classroom	2nd Floor	225	225	476	42	42	N	N
Dance Room	Dance Room	1st Floor	116	116	1,430	140	71	N	N
Kindergarten	Regular Classroom	1st Floor	115	115	716	135	110	N	Y
Music Room	Multi Purpose Room	1st Floor	114	114	336	70	35	N	N
Music Room	Regular Classroom	2nd Floor	220	220	716	135	110	N	N
Music Room	Regular Classroom	2nd Floor	222	222	1,091	189	154	N	N
Office	Regular Classroom	2nd Floor	213	213	186	54	44	N	N
Regular Classroom	Regular Classroom	1st Floor	117	117	716	135	110	N	Y
Regular Classroom	Regular Classroom	1st Floor	119	119	716	135	110	N	Y
Regular Classroom	Regular Classroom	1st Floor	121	121	716	97	66	Ν	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	375	25	14	Ν	Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	716	135	110	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	716	124	88	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	716	135	110	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	716	113	66	N	Y
Regular Classroom	Regular Classroom	2nd Floor	216	216	716	135	110	N	Y
Regular Classroom	Regular Classroom	2nd Floor	217	217	716	135	110	N	Y
Regular Classroom	Regular Classroom	2nd Floor	218	218	716	135	110	N	Y
Regular Classroom	Regular Classroom	2nd Floor	219	219	716	135	110	N	N
Special Education	Regular Classroom	1st Floor	122	122	390	54	44	N	Y