

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1939	3	219,411
Campus Total			219,411

Catego	ry : Exterior		B	uilding	: Main		
		1				Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Cell Equ</u>	ipment						
	Cell Equipment - Antenna	Main Roof	2	EA	7	10+ years	
	Cell Equipment - Cabinets	Main Roof	2	EA	7	10+ years	
	Cell Equipment - Generator	Main Roof	2	EA	7	10+ years	
Entrance	2						
	Entrance Control - Audio and Video	Door 1 - East center	1	EA	4	0-1 year	Not functional
	Exterior Doors - Exterior FRP Door	Door 1 - East center	2	EA	6	6-10 years	
	Exterior Stairs - Stone	Door 1 - East center	12	LF	6	10+ years	
	Exterior Stairs - Stone	Door 1 - East center	140	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 1 - East center	20	LF	6	10+ years	
	Entrance Control - Audio and Video	Door 10 - Northeast	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 10 - Northeast	2	EA	6	6-10 years	
	Exterior Stairs - Stone	Door 10 - Northeast	168	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 10 - Northeast	10	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 2 - Southeast	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 2 - Southeast	160	LF	5	10+ years	Hairline cracks
	Stair Handrail - Steel_Stair Handrail	Door 2 - Southeast	8	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 3 - Southwest	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 3 - Southwest	25	LF	5	10+ years	
	Exterior Stairs - Stone	Door 3 - Southwest	68	LF	7	10+ years	
	Exterior Stairs - Stone	Door 3 - Southwest	35	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 3 - Southwest	20	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 3.5 - Courtyard south	2	EA	6	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	Door 3.5 - Courtyard south	65	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
	•			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ramps - Concrete	Door 3.5 - Courtyard south	47	LF	6	10+ years	
	Entrance Control - Audio and Video	Door 4 - West center	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 4 - West center	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 4 - West center	4	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 4 - West center	16	LF	5	6-10 years	
	Exterior Stairs - Stone	Door 4 - West center	96	LF	7	6-10 years	
	Power Door Operator and Controls	Door 4 - West center	1	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	Door 4 - West center	128	LF	6	10+ years	
	Ramps - Concrete	Door 4 - West center	61	LF	6	10+ years	
	Ramps - Concrete	Door 4 - West center	3	LF	5	1-2 years	Crack on the foundation wall with
	Stair Handrail - Steel_Stair Handrail	Door 4 - West center	30	LF	7	10+ years	corrosion peeking through
	Exterior Doors - Exterior FRP Door	Door 5 - Courtyard north	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 5 - Courtyard north	2	EA	7	10+ years	
	Exterior Stairs - Stone	Door 5 - Courtyard north	84	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 5 - Courtyard north	8	LF	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage	Door 5.5 - Northwest	1	EA	6	6-10 years	
	Door				-		
	Exterior Doors - Overhead Rolling/ Garage Door	Door 6 - Northwest	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	Door 6.5 - North dock	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 6.5 - North dock	1	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 7 - Northwest	2	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 7 - Northwest	120	LF	5	1-2 years	Cracked concrete, spalling
	Exterior Stairs - Stone	Door 7 - Northwest	8	LF	6	10+ years	3
	Stair Handrail - Steel_Stair Handrail	Door 7 - Northwest	30	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	Door 8 - North center	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 8 - North center	15	LF	5	1-2 years	Cracked, broken, landing, and the first tread
	Power Door Operator and Controls	Door 8 - North center	1	EA	7	6-10 years	listilead
	Ramp Handrail - Steel_Ramp Handrail	Door 8 - North center	60	LA	7	10+ years	
	Ramps - Concrete	Door 8 - North center	30	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 8 - North center	5	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	Door 9 - Northeast	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 9 - Northeast	15	LF	7	10+ years	
	Exterior Stairs - Concrete	Door 9 - Northeast	129	LF	7	10+ years	
	Exterior Stairs - Concrete	Door 9 - Northeast	129	LF	5	10+ years	Hairline cracks
			16	LF	5 7	-	
	Stair Handrail - Steel_Stair Handrail	Door 9 - Northeast	10	LF	/	10+ years	
oundat							
	Foundation - Concrete	Entire Building	1,000	LF	7	10+ years	
	Foundation - Concrete	Entire Building	691	LF	5	1-2 years	Water Peterson through holes and cracks in the building
	Superstructure - Concrete	Entire Building	129,739	SF	7	10+ years	J J J J J J J J J J J J J J J J J J J



Catego	ry : Exterior		В				
	- -			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Superstructure - Steel with Clay Tile Arch	Entire Building	94,885	SF	7	10+ years	
ighting							
0 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	21	EA	7	10+ years	New
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	10+ years	New
Roof Sys	stem						
	Access Ladder - Metal	Main Roof	5	EA	7	10+ years	
	Access Ladder - Metal	Main Roof	1	EA	4	0-1 year	Loose ladder
	Chimney - Brick Chimney- Concrete/ Mortar	Main Roof	105	LF	6	10+ years	
	Liner						
	Chimney - Brick Chimney- Concrete/ Mortar	Main Roof	25	LF	5	1-2 years	Open joints and cracks in the brick
	Liner						
	Chimney - Metal Flue	Main Roof	50	LF	6	10+ years	
	Coping - Stone	Main Roof	1,816	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	30	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	918	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	50	LF	5	10+ years	
	Parapet - 16" - 30" Height	Main Roof	20	LF	4	1-2 years	Reinforced match since 2010, joints
						,	are deteriorated mortar
	Parapet - Parapet < 16" Height	Main Roof	239	LF	5	10+ years	
	Parapet - Parapet > 30"	Main Roof	1,197	LF	5	10+ years	
	Parapet - Parapet > 30"	Main Roof	200	LF	5	10+ years	
	Parapet - Parapet > 30"	Main Roof	120	LF	4	1-2 years	Parapets are covered with meshing
	e an all a start and a start				-	,	since 2012. Engineer reports of
							continuous leaks through the
							parapets.
	Roof - Asphalt Gravel Ballast	Main Roof	20	SF	7	6-10 years	Repaired
	Roof - Asphalt Gravel Ballast	Main Roof	100	SF	6	6-10 years	There is no longer an asshole shing
	Rooi Asphalt Olaver Ballast	Main Roof	100	01	U	o io years	roof
	Roof - Asphalt Gravel Ballast	Main Roof	60,640	SF	4	2-5 years	Open seams, deteriorated counter-
			,	•		,	flash sealant, some blistering
	Roof - Metal	Main Roof	100	SF	5	1-2 years	Unable to access this roof, enginee
				•	· ·)	has mentioned that it is leaking wat
							to the space below
	Roof Hatch - Metal	Main Roof	4	EA	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	5	1-2 years	Broken, old and corroded hatch
	Roof Structure - Concrete	Main Roof	32,569	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	28,291	SF	7	10+ years	
	Coping - Stone	Roof 1	20,291	LF	6	10+ years	
	Doropot 16" 20" Hoight	Roof 1	50 50	LF	6	10+ years	
	Parapet - 16" - 30" Height						
	Roof - Modified Bitumen	Roof 1	200	SF	5	2-5 years	
	Roof Structure - Concrete	Roof 1	200	SF	7	10+ years	



Gage Park High School 5630 S Rockwell STREET, Chicago, IL 60629

Catego	ry : Exterior		В	uilding	: Main		
Ŭ				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Valls							
	Cheek-Wall - Concrete	Entire Building	250	SF	7	10+ years	
	Cheek-Wall - Concrete	Entire Building	50	SF	4	1-2 years	Open joints, shifting wall, cracked
		-				-	bricks
	Cheek-Wall - Stone	Entire Building	50	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	5	SF	5	10+ years	Broken stone at door three
	Exterior Walls - Brick	Entire Building	80,988	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	180	SF	4	10+ years	Open joints
	Exterior Walls - Brick	Entire Building	800	SF	4	1-2 years	Open joints
	Exterior Walls - Stone-Cast	Entire Building	1,700	SF	5	10+ years	Stone veneer @ foundation
	Exterior Walls - Stone-Cast	Entire Building	15	SF	3	1-2 years	Crushed, spalled stone at foundation
	Exterior Walls - Terra Cotta	Entire Building	3,500	SF	5	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	1,573	SF	3	1-2 years	Netted concrete coping and brick
							parapet have been in this condition
							since 2012. The engineer
							reportsseveral holes with birds
							nesting. Also broken terra-cotta.
							Open joints with vegetation
Vindows	3						
	Curtain wall - Insulated Panel	Entire Building	5,492	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	60	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	1,164	SF	7	10+ years	
	Lintels - Steel	Entire Building	1,225	LF	6	6-10 years	Some corrosion
	Lintels - Steel	Entire Building	42	LF	4	0-1 year	Corroded rental near door number
							four
	Lintels - Terra Cotta	Entire Building	300	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	308	LF	4	1-2 years	Terra-cotta lentils, haven't covered
							with mashing since 2012. Joints are
							deteriorating and engineer. Reports
							of leaks through the walls at these
	Windows - Decorative	Entire Building		<u>с</u> г	e	6 10 10000	locations.
		Entire Building	1,055 250	SF SF	6	6-10 years	
	Windows - Louver	Entire Building Entire Building	250 6,923	SF	5	2-5 years 6-10 years	
	Windows - Sash Aluminum Double-pane Windows - Sash Aluminum Double-pane	•	6,923 5,000	SF	6 4		Windows are screwed shit because
	windows - Sash Aluminum Double-pane	Entire Building	5,000	55	4	1-2 years	Windows are screwed shit because they are falling out of the frames.
	Windows - Sash Lexan/ Glass Double-pane	Entire Building	25	SF	5	1-2 years	Sealing is deficient. Several windows are falling out of the
	Williows - Sasii Lexall Glass Double-palle		25	36	0	1-2 years	fridge throughout the building. Most
							windows are screwed shut for safet
atego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
- oup			quantity	0.0111	. carine		

					Deplession	
0					Replacement	
ergency System Automatic Transfer Switch	Electrical Boom	1	E۸	6	2.5.0000	
	Electrical Room	1	EA	6	2-5 years	
Security System - CCTV	Entire Building	219,411	SF	6	6-10 years	
Security System - Intrusion Detection	Entire Building	219,411	SF	5	2-5 years	
Exit Signs - Auditoium	Entire Building	16	EA	7	10+ years	
Exit Signs - Corridors and Stairs	Entire Building	23	EA	7	10+ years	Over 20 veers ald and dire lighting
Exit Signs - Corridors and Stairs	Entire Building	36	EA	4	2-5 years	Over 20 years old and dim lighting
Exit Signs - Gym	Entire Building	4	EA	4	2-5 years	Over 20 years old and dim lighting
Exit Signs - Lunchroom	Entire Building	6	EA	4	2-5 years	Over 20 years old and dim lighting
Exit Signs - Pool	Entire Building	3	EA	4	2-5 years	Over 20 years old and dim lighting
Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	9	EA	7	6-10 years	
Emergency Battery Packs - Corridors and Stairs	Entire Building	1	EA	7	6-10 years	
Emergency Battery Packs - Pool	Entire Building	2	EA	7	6-10 years	
Emergency Battery Packs - Students Toilets	Entire Building	4	EA	7	6-10 years	
Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	7,485	SF	6	6-10 years	
Emergency A/C Power - Corridors and Stairs	Entire Building	26,112	SF	6	6-10 years	
Emergency A/C Power - Gym	Entire Building	12,000	SF	6	6-10 years	
Emergency A/C Power - Lunchrooms	Entire Building	5,175	SF	6	6-10 years	
Emergency A/C Power - Pool	Entire Building	3,356	SF	6	6-10 years	
n Service						
Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
Main Electrical Service - Greater than 3000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	
PA System	Entire Building	219,411	SF	4	1-2 years	No call buttons and not working in few areas
ver Distribution						
Lighting and Power Panels - 100 A	Entire Building	2	EA	6	2-5 years	
Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
Lighting and Power Panels - Above 100 A	Entire Building	16	EA	6	6-10 years	
Lighting and Power Panels - Above 100 A	Entire Building	7	EA	6	2-5 years	
Lighting and Power Panels - Above 100 A	Entire Building	19	EA	6	2-5 years	
Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Missing spare breaker cover
Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
Main Distribution Panels - 400 - 600 amp	Entire Building	6	EA	6	2-5 years	
Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	
Main Distribution Panels - Greater than 600	Entire Building	6	EA	6	2-5 years	
amp	Entire Bananig	Ũ		•	,	



Replacement

Catego	ry : Fire Protection	otection Building : Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	Entire Building	219,411	SF	7	10+ years	
	Fire Alarm_System	Entire Building	219,411	SF	7	10+ years	
Catego	ry : Mechanical		В	uilding	: Main		
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	itioning						
	Cooling Tower - Open Cell- Less the 50 tons	Dehumidification Unit - Pool	1	EA	6	10+ years	For dehumidification unit
	Glycol Feed	Dehumidification Unit - Pool	1	EA	6	6-10 years	For dehumidification unit
	Pipes - Dual Temperature Pipe- Copper	Dehumidification Unit - Pool	300	LF	6	10+ years	
	Condensing Unit- Ground Mounted - 5-10 tons	Entire Building	1	EA	6	6-10 years	Inaccessible (gate)
	Condensing Unit- Ground Mounted - Less than 5 tons	Entire Building	1	EA	6	2-5 years	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	6-10 years	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	6-10 years	
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	6	6-10 years	
Air Hand	ling Systems						
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 cfm	AHU1 - Auditorium	1	EA	6	10+ years	
	Air Intake	AHU1 - Auditorium	1	EA	6	6-10 years	Serving AHUs 1,2
	Auxiliaries - 15001 - 25000 cfm	AHU1 - Auditorium	1	EA	6	6-10 years	0
	Return Duct Work - Indoor- Vertical Shaft and Ducts	AHU1 - Auditorium	100	LF	6	10+ years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	AHU2 - Lunchroom	1	EA	6	10+ years	
	Air Intake	AHU2 - Lunchroom	1	EA	6	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	AHU2 - Lunchroom	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	AHU2 - Lunchroom	100	LF	6	10+ years	
	Zone Dampers	AHU2 - Lunchroom	8	EA	6	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - Greater than 35000 cfm	AHU3 - North	1	EA	6	10+ years	



Category : Mechanical **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Air Intake AHU3 - North ΕA 6 6-10 vears Serving AHU3 1 ΕA 6 Auxiliaries - Greater than 35000 cfm AHU3 - North 1 6-10 vears Reheat Boxes - Reheat Boxes with Steam AHU3 - North 7 FΑ 7 10+ years Coil Return Duct Work - Indoor- Vertical Shaft AHU3 - North 100 1 F 6 10+ years and Ducts Zone Dampers 25 ΕA 6 AHU3 - North 6-10 years Air Handling Unit- Built Up- Single Zone w/ AHU4 - South 1 ΕA 6 10+ years Air Tunnel- Steam Coils - Greater than 35000 cfm Air Intake AHU4 - South 1 ΕA 6 6-10 vears Serving AHU4 Auxiliaries - Greater than 35000 cfm AHU4 - South 1 EΑ 6 6-10 years Reheat Boxes - Reheat Boxes with Steam AHU4 - South 8 ΕA 7 10+ years Coil LF Return Duct Work - Indoor- Vertical Shaft AHU4 - South 100 6 10+ years and Ducts Zone Dampers AHU4 - South 26 ΕA 6 6-10 years Air Handling Unit- Built Up- Single Zone w/ AHU5 - South 1 FΑ 6 10+ years Air Tunnel- Steam Coils - 15001 - 25000 cfm Air Intake AHU5 - South 1 EΑ 6 6-10 years Serving AHUs 5,6,7 Auxiliaries - 15001 - 25000 cfm AHU5 - South 1 ΕA 5 6-10 years Reheat Boxes - Reheat Boxes with Steam AHU5 - South 3 ΕA 6 6-10 years Coil LF Return Duct Work - Indoor- Vertical Shaft AHU5 - South 100 6 10+ years and Ducts Zone Dampers AHU5 - South 11 ΕA 6 6-10 vears Air Handling Unit- Built Up-Multi Zone-AHU6 - Gyms and Pool ΕA 6 1 10+ years Steam Coils - 15001 - 25000 cfm Air Intake AHU6 - Gyms and Pool 1 EΑ 6 6-10 years Auxiliaries - 15001 - 25000 cfm AHU6 - Gyms and Pool 1 ΕA 5 6-10 years LF Return Duct Work - Indoor- Vertical Shaft AHU6 - Gyms and Pool 100 6 10+ years and Ducts FΑ 6 Zone Dampers AHU6 - Gyms and Pool 11 6-10 years Air Handling Unit- Built Up-Multi Zone-AHU7 - Gvm FΑ 6 1 10+ years Steam Coils - 15001 - 25000 cfm Air Intake AHU7 - Gym 1 EΑ 6 6-10 years Auxiliaries - 15001 - 25000 cfm AHU7 - Gym 1 EΑ 5 6-10 years LF Return Duct Work - Indoor- Vertical Shaft AHU7 - Gym 100 6 10+ years and Ducts ΕA Zone Dampers AHU7 - Gvm 12 6 6-10 vears Dehumidification Unit- Indoor- Steam Basement ΕA 6 6-10 years 1 Fan squealing Heating- DX Cooling with Self Contained Compressor - 4001 - 8000 cfm Air Handling Unit- Package Single Zone-Library Storage Room 1 EA 6 6-10 years



						56	30 S Rockwell STREET, Chicago, IL 60629
Catego	ry : Mechanical		В	uilding	: Main	_	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Indoor- Electric and DX Cooling Coil - 4000-						
	8000 cfm				-		
	Air Intake	Library Storage Room	1	EA	6	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	Lunchroom	1	EA	6	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	Lunchroom	1	EA	6	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	Lunchroom	1	EA	6	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	Lunchroom	1	EA	6	6-10 years	
Boiler Sy							
	Boiler Auxiliary- Steam Boiler - Greater than	Basement	3	EA	6	6-10 years	
	200 HP						
	Chemical Feed System	Basement	1	EA	6	10+ years	
	Combustion Dampers	Basement	3	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	6	6-10 years	
	Condensate Pump	Basement	1	EA	6	10+ years	
	Condensate Pump	Basement	1	EA	6	10+ years	
	Condensate Pump	Basement	1	EA	6	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Condensate Pump	Basement	1	EA	5	6-10 years	
	Feed Water Pumps and Tank	Basement	1	EA	6	6-10 years	
	Non Condensing- Water Tube- Flexible	Basement	1	EA	5	2-5 years	
	Tube- Force Draft- Steam Boiler - Greater than 200 HP						
	Non Condensing- Water Tube- Flexible	Basement	1	EA	5	2-5 years	
	Tube- Force Draft- Steam Boiler - Greater	Datomont	•		Ũ	2 0 90010	
	than 200 HP						
	Non Condensing- Water Tube- Flexible	Basement	1	EA	4	1-2 years	Right side brick wall cracking
	Tube- Force Draft- Steam Boiler - Greater	2000.000	•	<u> </u>	•	;00.0	extensively
	than 200 HP						enter lot of y
	Piping - Condensate Pipe- Steel	Basement	2,000	LF	4	2-5 years	40+ years old
			_,500		•	_ 0 ,00.0	




Catego	ry : Mechanical		В	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Piping - Steam Pipe- Steel	Basement	2,000	LF	3	1-2 years	A few leaks throughout and insulation
			_,		-	,	repair needed
	Steam Traps	Basement	149	EA	5	6-10 years	· - F
		2400		_/ (Ū	e le jeale	
Heating	Devices						
0	Fin Tube - Steam	Entire Building	75	LF	6	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	7	10+ years	
	Wall Heater - Electric	Entire Building	11	EA	5	6-10 years	
	Unit Heater - Electric	Entire Building	3	EA	7	10+ years	
	Unit Heater - Electric	Entire Building	11	EA	5	6-10 years	
	Radiators - Steam	Entire Building	47	EA	6	6-10 years	
	Cabinet Heaters - With Steam Coil	Entry Vestibule	1	EA	6	6-10 years	
Mechani	cal Plumbing						
	Dual Temperature Pump - Less than 10	Basement	1	EA	6	6-10 years	Glycol pump
	p				•	,) FF
Tempera	ature Control						
	Electric Thermostat	Entire Building	1	EA	6	2-5 years	
	Electric Thermostat	Entire Building	4	EA	6	6-10 years	
	Pneumatic System	Entire Building	219,411	SF	3	0-1 year	Not operational
	Thermostats - Pneumatic	Entire Building	96	EA	5	6-10 years	
Unit Ven	Unit Ventilators- Floor Mounted- Steam	3rd Floor	2	EA	2	0.1.voor	Not operational
		310 F1001	3	EA	2	0-1 year	Not operational
	Heating Coils Only		4	F A	0	0.4	
	Unit Ventilators- Floor Mounted- Steam	3rd Floor	1	EA	2	0-1 year	Not operational
	Heating Coils Only						
Ventilatio	מכ						
- continuation	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	2-5 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	5	6-10 years	Tearing at connection to ductwork
	CFM	Entite Building	I	EA	5	0-10 years	rearing at connection to ductwork
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	3	EA	5	2-5 years	Noisy or damaged cover
	CFM	Entire Building	5	LA	5	2-5 years	Noisy of damaged cover
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	3	0-1 year	No longer in use
	CFM		I	EA	3	0-i yeai	No longer in use
		Factor Dedials	•	Γ.	~	0.40	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	2	EA	6	6-10 years	
	CFM				_		
	Roof Mounted Duct Work	Entire Building	8	LF	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	6-10 years	



Gage Park High School 5630 S Rockwell STREET, Chicago, IL 60629

Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Steam Heat Exchanger	Boiler Room	2	EA	6	6-10 years	
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	5	2-5 years	Used primarily when main boilers and heat exchangers are not in use/dormant
	Gas Heater - 150000 - 300000 BTU/HR	Lunchroom Storage Room	1	EA	6	2-5 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	219,411	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	219,411	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	219,411	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	219,411	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	219,411	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	219,411	SF	6	6-10 years	
	Sanitary Piping	Entire Building	219,411	SF	5	2-5 years	
	Storm Piping	Entire Building	219,411	SF	5	2-5 years	
	Vent Piping	Entire Building	219,411	SF	5	2-5 years	
Pool Sys	stems						
	Pool Drain Piping	Entire Building	50	LF	6	2-5 years	
	Pool Filtration System including Pump	Entire Building	1	EA	5	6-10 years	One section above 1 pump missing
	Pool Hot Water Heater - Gas Fired	Entire Building	1	EA	3	0-1 year	Not operational
	Pool Supply and Return Piping	Entire Building	200	LF	7	6-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	6	6-10 years	Hot water
	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	5	2-5 years	Cold water
	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	5	2-5 years	Cold water
	Pumps - Ejector-Duplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Ejector-Duplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Ejector-Duplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Ejector-Duplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	
Catego	ry : Room		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
0.040			quantity	0.0111			





					5030 (
					Replacement	
Floor - Tile/Sheet	122C- Operations Mngr & Record Rm In Main Office	151	SF	7	10+ years	
Lighting - Lay-in	122C- Operations Mngr & Record	4	EA	7	2-5 years	
Power Distribution	Rm In Main Office 122C- Operations Mngr & Record	6	EA	7	2-5 years	
Storage/ Closet	Rm In Main Office 122C- Operations Mngr & Record	126	SF	5	6-10 years	
Walls - Plaster/Drywall	Rm In Main Office 122C- Operations Mngr & Record	588	SF	6	10+ years	
AC Unit	Rm In Main Office 128- Attendance Office	3	EA	7	2-5 years	
Ceiling - Lay-in	128- Attendance Office	728	SF	6	10+ years	
Doors - Transom Window			SF			
	128- Attendance Office	16		6	6-10 years	
Doors - Wood Doors inclu hw	128- Attendance Office	5	EA	6	6-10 years	
Floor - Tile	128- Attendance Office	728	SF	6	10+ years	
Lighting - Lay-in	128- Attendance Office	14	EA	7	2-5 years	
Power Distribution	128- Attendance Office	12	EA	7	2-5 years	
Walls - Plaster/Drywall	128- Attendance Office	1,050	SF	6	10+ years	
Ceiling - Plaster/Drywall	145C Assistant Eng Office	159	SF	6	10+ years	
Doors - Transom Window	145C Assistant Eng Office	9	SF	6	6-10 years	
Doors - Wood Doors inclu hw	145C Assistant Eng Office	1	EA	6	6-10 years	
Floor - Tile	145C Assistant Eng Office	159	SF	7	10+ years	
Lighting - Pendent/Surface	145C Assistant Eng Office	1	EA	7	2-5 years	
Power Distribution	145C Assistant Eng Office	4	EA	7	2-5 years	
Walls - Plaster/Drywall	145C Assistant Eng Office	480	SF	7	10+ years	
AC Unit	222A- Office	1	EA	7	6-10 years	
Ceiling - Lay-in	222A- Office	384	SF	6	10+ years	
Doors - Transom Window	222A- Office	8	SF	6	10+ years	
Doors - Wood Doors inclu hw	222A- Office	1	EA	7	10+ years	
Floor - Tile	222A- Office	384	SF	6	10+ years	
Lighting - Lay-in	222A- Office	9	EA	7	10+ years	
Power Distribution	222A- Office	6	EA	7	10+ years	
Storage/ Closet	222A- Office	40	SF	7	10+ years	
Walls - Plaster/Drywall	222A- Office	802	SF	6	10+ years	
Ceiling - Plaster/Drywall	3rd Floor Kitchen Manager's office in	30	SF	6	10+ years	
	lunchroom				,	
Ceiling - Splined	3rd Floor Kitchen Manager's office in lunchroom	50	SF	6	10+ years	
Doors - Side-lite	3rd Floor Kitchen Manager's office in lunchroom	72	SF	6	10+ years	
Doors - Transom Window	3rd Floor Kitchen Manager's office in lunchroom	18	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd Floor Kitchen Manager's office in	1	EA	6	10+ years	
Floor - Tile/Sheet	lunchroom 3rd Floor Kitchen Manager's office in	80	SF	7	10+ years	
Lighting - Pendent/Surface	lunchroom 3rd Floor Kitchen Manager's office in	2	EA	7	10+ years	



Gage Park High School 5630 S Rockwell STREET, Chicago, IL 60629

					Replacement	
	lunchroom					
Power Distribution	3rd Floor Kitchen Manager's office in	4	EA	7	10+ years	
	lunchroom	-		-	, e , j e e	
Walls - Plaster/Drywall	3rd Floor Kitchen Manager's office in	175	SF	6	10+ years	
	lunchroom		•	Ū	i e i jeale	
Walls - Structural Glazed Tile	3rd Floor Kitchen Manager's office in	150	SF	6	10+ years	
	lunchroom	100	0.	0	ior youro	
Ceiling - Plaster/Drywall	Engineers Office 145D	138	SF	6	10+ years	
Doors - Side-lite	Engineers Office 145D	45	SF	6	6-10 years	
Doors - Transom Window	Engineers Office 145D	9	SF	6	6-10 years	
Doors - Wood Doors inclu hw	Engineers Office 145D	1	EA	6	6-10 years	
Floor - Tile/Sheet	Engineers Office 145D	138	SF	7	10+ years	
Lighting - Pendent/Surface	Engineers Office 145D	2	EA	7	2-5 years	
Power Distribution	Engineers Office 145D	6	EA	6	2-5 years	
Storage/ Closet	Engineers Office 145D	36	SF	5	6-10 years	
Walls - Plaster/Drywall	Engineers Office 145D	444	SF	6	10+ years	
Walls - Plaster/Drywall	Engineers Office 145D	120	SF	5	1-2 years	Damaged, peeling paint
Ceiling - Lay-in	Office 333	120	SF	7	10+ years	Damagoa, pooling paint
Doors - Transom Window	Office 333	6	SF	7	6-10 years	
Doors - Wood Doors inclu hw	Office 333	1	EA	6	6-10 years	
Floor - Tile/Sheet	Office 333	120	SF	7	10+ years	
Lighting - Lay-in	Office 333	2	EA	7	10+ years	
Walls - Plaster/Drywall	Office 333	440	SF	6	10+ years	
Doors - Wood Doors inclu hw	Rm 104A- PE Office (In Pool area)	2	EA	6	6-10 years	Inaccessible
Floor - Tile Ceramic/ Porcelain	Rm 104A- PE Office (In Pool area)	64	SF	6	10+ years	
Lighting - Pendent/Surface	Rm 104A- PE Office (In Pool area)	1	ĒA	6	2-5 years	
Power Distribution	Rm 104A- PE Office (In Pool area)	2	EA	7	2-5 years	
Walls - Structural Glazed Tile	Rm 104A- PE Office (In Pool area)	266	SF	6	10+ vears	
AC Unit	Rm 116- Asst Principal Suite 1	1	EA	7	2-5 years	
Ceiling - Plaster/Drywall	Rm 116- Asst Principal Suite 1	175	SF	6	10+ years	
Ceiling - Splined	Rm 116- Asst Principal Suite 1	175	SF	6	10+ years	
Doors - Wood Doors inclu hw	Rm 116- Asst Principal Suite 1	3	EA	6	6-10 years	
Floor - Tile	Rm 116- Asst Principal Suite 1	350	SF	6	10+ years	
Lighting - Pendent/Surface	Rm 116- Asst Principal Suite 1	3	EA	7	2-5 years	
Power Distribution	Rm 116- Asst Principal Suite 1	12	EA	7	2-5 years	
Storage/ Closet	Rm 116- Asst Principal Suite 1	20	SF	5	6-10 years	
Walls - Plaster/Drywall	Rm 116- Asst Principal Suite 1	925	SF	6	10+ years	
AC Unit	Rm 123- Asst Principal Suite 2	1	EA	7	2-5 years	
Ceiling - Lay-in	Rm 123- Asst Principal Suite 2	12	SF	4	1-2 years	Water damage
Ceiling - Plaster/Drywall	Rm 123- Asst Principal Suite 2	338	SF	6	10+ years	-
Doors - Wood Doors inclu hw	Rm 123- Asst Principal Suite 2	2	EA	6	6-10 years	
Floor - Tile	Rm 123- Asst Principal Suite 2	350	SF	6	10+ years	
Lighting - Pendent/Surface	Rm 123- Asst Principal Suite 2	3	EA	7	2-5 years	
Power Distribution	Rm 123- Asst Principal Suite 2	12	EA	7	2-5 years	
Storage/ Closet	Rm 123- Asst Principal Suite 2	20	SF	5	6-10 years	
Walls - Plaster/Drywall	Rm 123- Asst Principal Suite 2	925	SF	6	10+ years	
AC Unit	Rm 125- Counselor/Nurse Suite	2	EA	7	2-5 years	



Gage Park High School 5630 S Rockwell STREET, Chicago, IL 60629

Replacement 10+ years Ceiling - Lay-in Rm 125- Counselor/Nurse Suite 970 SF 6 SF 6-10 vears Doors - Transom Window Rm 125- Counselor/Nurse Suite 8 6 Doors - Wood Doors inclu hw Rm 125- Counselor/Nurse Suite 7 ΕA 6 6-10 years Floor - Tile SF 6 Rm 125- Counselor/Nurse Suite 950 10+ years Floor - Tile SF Rm 125- Counselor/Nurse Suite 10 4 1-2 years Water damage deficiency fixed. Small cracks and chips throughout floor FΑ 7 Lighting - Lay-in Rm 125- Counselor/Nurse Suite 27 2-5 years Power Distribution Rm 125- Counselor/Nurse Suite 40 EΑ 7 2-5 years Walls - Metal Panel Rm 125- Counselor/Nurse Suite 357 SF 6 10+ years SF Walls - Plaster/Drvwall Rm 125- Counselor/Nurse Suite 968 6 10+ vears SF Walls - Tile Ceramic/ Porcelain Rm 125- Counselor/Nurse Suite 384 6 10+ years AC Unit Rm 134 Security Office 1 ΕA 7 2-5 years Ceiling - Plaster/Drywall Rm 134 Security Office 125 SF 6 10+ years Ceiling - Plaster/Drvwall Rm 134 Security Office SF 5 5 0-1 year Water Damage 9 SF 6 Doors - Transom Window Rm 134 Security Office 6-10 years Doors - Wood Doors inclu hw Rm 134 Security Office FΑ 6 6-10 years 1 7 Floor - Tile Rm 134 Security Office 130 SF 10+ vears Rm 134 Security Office Lighting - Pendent/Surface 2 EΑ 7 2-5 years Power Distribution Rm 134 Security Office 4 ΕA 7 2-5 years Rm 134 Security Office SF Storage/ Closet 12 5 6-10 years Walls - Plaster/Drywall Rm 134 Security Office 600 SF 4 1-2 years Extensive spalling, paint peeling, cracking Ceiling - Plaster/Drvwall Rm 204 & 204A- JROTC office (in 330 SF 6 10+ years Gvm 200) Doors - Wood Doors inclu hw Rm 204 & 204A- JROTC office (in 3 FΑ 6 10+ years Gym 200) Rm 204 & 204A- JROTC office (in SF Floor - Carpet 130 6 6-10 years Gym 200) Floor - Tile Rm 204 & 204A- JROTC office (in 200 SF 5 1-2 years Entire sections of tile missing Gym 200) ΕA Lighting - Pendent/Surface Rm 204 & 204A- JROTC office (in 2 7 10+ years Gvm 200) Rm 204 & 204A- JROTC office (in FΑ 7 Power Distribution 4 10+ years Gym 200) Walls - Plaster/Drywall Rm 204 & 204A- JROTC office (in 600 SF 6 10+ years Gym 200) Work SInk Rm 204 & 204A- JROTC office (in 1 EΑ 7 10+ years Gvm 200) Ceiling - Lay-in Rm 208 PE Office (in Gym 210) 220 SF 6 10+ years Doors - Side-lite SF Rm 208 PE Office (in Gvm 210) 28 6 10+ vears SF Doors - Transom Window Rm 208 PE Office (in Gym 210) 8 6 10+ vears 2 ΕA 7 Doors - Wood Doors inclu hw Rm 208 PE Office (in Gym 210) 10+ years Floor - Wood Rm 208 PE Office (in Gym 210) 220 SF 6 10+ years 5 ΕA 7 Lighting - Lay-in Rm 208 PE Office (in Gym 210) 10+ years **Power Distribution** 7 Rm 208 PE Office (in Gym 210) 6 EΑ 10+ years SF Walls - Plaster/Drvwall Rm 208 PE Office (in Gym 210) 6 600 10+ years Walls - Plaster/Drywall Rm 208 PE Office (in Gym 210) 5 SF 5 1-2 years Cracking



						50 S ROCKWEII STREET, Chicago, II
				_	Replacement	
Work SInk	Rm 208 PE Office (in Gym 210)	1	EA	7	10+ years	
Ceiling - Plaster/Drywall	Rm 208A PE Office (in Gym 210)	119	SF	6	10+ years	
Doors - Transom Window	Rm 208A PE Office (in Gym 210)	16	SF	6	10+ years	
Doors - Wood Doors inclu hw	Rm 208A PE Office (in Gym 210)	2	EA	7	10+ years	
Floor - Wood	Rm 208A PE Office (in Gym 210)	119	SF	6	10+ years	
Lighting - Pendent/Surface	Rm 208A PE Office (in Gym 210)	2	EA	7	10+ years	
Power Distribution	Rm 208A PE Office (in Gym 210)	6	EA	7	10+ years	
Walls - Plaster/Drywall	Rm 208A PE Office (in Gym 210)	480	SF	6	10+ years	
AC Unit	Rm 223- Guidance Counselor Office	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	Rm 223- Guidance Counselor Office	353	SF	6	10+ years	
Doors - Wood Doors inclu hw	Rm 223- Guidance Counselor Office	1	EA	6	10+ years	
Floor - Wood	Rm 223- Guidance Counselor Office	353	SF	6	10+ years	
					•	
Lighting - Pendent/Surface	Rm 223- Guidance Counselor Office	2	EA	7	10+ years	
Power Distribution	Rm 223- Guidance Counselor Office	12	EA	7	10+ years	
Walls - Plaster/Drywall	Rm 223- Guidance Counselor Office	982	SF	6	10+ years	
Ceiling - Lay-in	Rm 231 Storage	176	SF	6	10+ years	
Doors - Transom Window	Rm 231 Storage	9	SF	6	10+ years	
Doors - Wood Doors inclu hw	Rm 231 Storage	1	EA	6	10+ years	
Floor - Tile	Rm 231 Storage	176	SF	6	10+ years	
Lighting - Pendent/Surface	Rm 231 Storage	2	EA	7	10+ years	
Power Distribution	Rm 231 Storage	4	EA	7	10+ years	
Walls - Plaster/Drywall	Rm 231 Storage	360	SF	6	10+ years	
AC Unit	Rm 233 - Social Worker Office	1	EA	7	6-10 years	
Ceiling - Lay-in	Rm 233 - Social Worker Office	121	SF	4	1-2 years	Water damage around window
Doors - Transom Window	Rm 233 - Social Worker Office	9	SF	7	10+ years	Water damage around windo
Doors - Wood Doors inclu hw	Rm 233 - Social Worker Office	9 1	EA	6	10+ years	
		•	SF	-		
Floor - Tile	Rm 233 - Social Worker Office	121		6	10+ years	
Lighting - Pendent/Surface	Rm 233 - Social Worker Office	2	EA	6	10+ years	
Power Distribution	Rm 233 - Social Worker Office	4	EA	6	6-10 years	
Walls - Plaster/Drywall	Rm 233 - Social Worker Office	513	SF	6	10+ years	
Walls - Plaster/Drywall	Rm 233 - Social Worker Office	15	SF	5	1-2 years	Water damage
Ceiling - Lay-in	rm 232 office	176	SF	6	10+ years	
Doors - Transom Window	rm 232 office	9	SF	6	10+ years	
Doors - Wood Doors inclu hw	rm 232 office	1	EA	6	10+ years	
Floor - Tile	rm 232 office	176	SF	6	10+ years	
Lighting - Pendent/Surface	rm 232 office	1	EA	7	10+ years	
Power Distribution	rm 232 office	4	EA	7	10+ years	
Walls - Plaster/Drywall	rm 232 office	360	SF	6	10+ years	
· · · · · · · · · · · · · · · · · · ·				-	,	
ium & Theater						
Balcony Seating	1st Floor	268	EA	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	3,743	SF	6	10+ years	
Ceiling - Splined	1st Floor	3,742	SF	6	10+ years	
	1st Floor	2	EA	6	6-10 years	
Doors - Steel Doors incl hw	13(1)001					
Doors - Steel Doors Incl hw Doors - Wood Doors inclu hw	1st Floor	16	EA	6	6-10 years	



Schools						56	30 S Rockwell STREET, Chicago, IL 60629
						Replacement	
Floor - Tei		1st Floor	260	SF	6	10+ years	
Floor - Tile		1st Floor	1,579	SF	6	10+ years	
Lighting -	Pendent/Surface	1st Floor	72	EA	7	2-5 years	
	Wall Mounted	1st Floor	14	EA	7	2-5 years	
Main Floor		1st Floor	448	EA	7	6-10 years	
Sound Sys		1st Floor	1	EA	7	2-5 years	
Stage		1st Floor	786	SF	6	10+ years	
Stage Cur	tain	1st Floor	6	EA	5	2-5 years	
	nting System	1st Floor	1	EA	7	2-5 years	
	irs - Wood	1st Floor	8	LF	6	10+ years	
Stairs - Te		1st Floor	48	LF	6	10+ years	
	aster/Drywall	1st Floor	9,002	SF	6	10+ years	
	e Ceramic/ Porcelain	1st Floor	600	SF	6	10+ years	
	e Geranne, i Greelann	13111001	000	01	0	TO+ years	
Gymnasia							
Bleacher		Rm 210	138	EA	6	10+ years	
Ceiling - F	Plaster/Drywall	Rm 210	600	SF	6	10+ years	
Ceiling - S	Splined	Rm 210	5,388	SF	6	10+ years	
Ceiling - S	Splined	Rm 210	12	SF	4	1-2 years	Water damage, missing tiles
	ansom Window	Rm 210	15	SF	7	10+ years	3 4 5
Doors - Tr	ansom Window	Rm 210	17	SF	6	10+ years	
Doors - W	ood Doors inclu hw	Rm 210	6	EA	6	10+ years	
Floor - Wo		Rm 210	6,000	SF	6	10+ years	
	Pendent/Surface	Rm 210	22	ĒA	7	10+ years	
Scoreboar		Rm 210	1	EA	7	10+ years	
Storage/ C		Rm 210	135	SF	7	10+ years	No access
	aster/Drywall	Rm 210	635	SF	6	10+ years	
	aster/Drywall	Rm 210	5	SF	5	1-2 years	Water damage
	ructural Glazed Tile	Rm 210	7,000	SF	6	10+ years	Water damage
	Plaster/Drywall	Rm 200	590	SF	6	10+ years	
	Plaster/Drywall			SF	5	1-2 years	Cracking, minor water damage
Ceiling - S		Rm 200 Rm 200	10	SF		•	Cracking, minor water damage
	ansom Window		5,400	SF	6	10+ years	
		Rm 200	32		6	10+ years	
	ood Doors inclu hw	Rm 200	4	EA	6	10+ years	
Floor - Wo		Rm 200	6,000	SF	6	10+ years	
	Pendent/Surface	Rm 200	22	EA	7	10+ years	
Scoreboar		Rm 200	1	EA	7	10+ years	
Storage/ C		Rm 200	135	SF	7	10+ years	
	aster/Drywall	Rm 200	630	SF	6	10+ years	
	aster/Drywall	Rm 200	5	SF	5	1-2 years	Crumbling plaster
Walls - Str	ructural Glazed Tile	Rm 200	7,005	SF	6	10+ years	
Kitchen							
	Plaster/Drywall	3rd Floor	600	SF	6	10+ years	
	ood Doors inclu hw	3rd Floor	3	ĒA	6	10+ years	
Floor - Tei		3rd Floor	600	SF	6	10+ years	
		0.0	000	•.	•	,	

	Chicago						
ett	Chicago Public Schools					FA	Gage Park High Schoo 630 S Rockwell STREET, Chicago, IL 60629
	5010015					Replacement	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	10+ years	
	Storage/ Closet	3rd Floor	332	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	1,000	SF	6	10+ years	
Library							
	AC Unit	Rm 120- Library	2	EA	7	2-5 years	
	Casework	Rm 120- Library	160	LF	6	6-10 years	
	Ceiling - Splined	Rm 120- Library	1,771	SF	6	10+ years	
	Doors - Transom Window	Rm 120- Library	8	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Rm 120- Library	1	EA	6	6-10 years	
	Floor - Tile	Rm 120- Library	1,771	SF	6	10+ years	
	Lighting - Pendent/Surface	Rm 120- Library	32	EA	7	2-5 years	
	Storage/ Closet	Rm 120- Library	360	SF	5	6-10 years	
	Walls - Metal Panel	Rm 120- Library	100	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 120- Library	1,163	SF	6	10+ years	
	Walls - Tile	Rm 120- Library	1,163	SF	6	10+ years	
	AC Unit	Rm 1204 - Post Secondary	1,103	EA	7	2-5 years	
		Rm 120A - Post Secondary Rm 120A - Post Secondary	63		6		
	Casework Ceiling - Splined	J		SF	-	6-10 years	
	Doors - Transom Window	Rm 120A - Post Secondary	1,277	SF	6	10+ years	
		Rm 120A - Post Secondary	16		6	6-10 years	
	Doors - Wood Doors inclu hw	Rm 120A - Post Secondary	2	EA	6	6-10 years	
	Floor - Tile	Rm 120A - Post Secondary	1,277	SF	6	10+ years	
	Lighting - Pendent/Surface	Rm 120A - Post Secondary	24	EA	7	2-5 years	
	Lighting - Wall Mounted	Rm 120A - Post Secondary	2	EA	7	2-5 years	
	Walls - Metal Panel	Rm 120A - Post Secondary	100	SF	6	10+ years	
	Walls - Plaster/Drywall	Rm 120A - Post Secondary	312	SF	6	10+ years	
	Walls - Tile	Rm 120A - Post Secondary	400	SF	6	10+ years	
_Locker/	Shower Room						
	Accessories	Rm 102 - Girls Locker Room	3,284	SF	7	2-5 years	
	Benches, ped mounted	Rm 102 - Girls Locker Room	20	LF	6	2-5 years	
	Ceiling - Plaster/Drywall	Rm 102 - Girls Locker Room	3,284	SF	6	10+ years	
	Doors - Steel Doors incl hw	Rm 102 - Girls Locker Room	5	EA	6	6-10 years	
	Doors - Transom Window	Rm 102 - Girls Locker Room	48	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Rm 102 - Girls Locker Room	1	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	Rm 102 - Girls Locker Room	3,284	SF	7	10+ years	
	Floor Drain	Rm 102 - Girls Locker Room	9	EA	7	10+ years	Changed to match current
			-		_	-	observations
	Hand Dryer	Rm 102 - Girls Locker Room	2	EA	5	2-5 years	
	Lavatory	Rm 102 - Girls Locker Room	2	EA	6	2-5 years	
	Lighting - Pendent/Surface	Rm 102 - Girls Locker Room	69	EA	7	2-5 years	
	Partitions	Rm 102 - Girls Locker Room	4	EA	5	6-10 years	
	Showers	Rm 102 - Girls Locker Room	32	EA	5	2-5 years	
	Storage/ Closet	Rm 102 - Girls Locker Room	406	SF	5	6-10 years	
	Student Lockers - One Tier	Rm 102 - Girls Locker Room	6	EA	6	6-10 years	
	Student Lockers - Two Tier	Rm 102 - Girls Locker Room	120	EA	6	6-10 years	



X Schools					56	330 S Rockwell STREET, Chicago, IL 60629
					Replacement	
Walls - Plaster/Drywall	Rm 102 - Girls Locker Room	2,592	SF	6	10+ years	Material changed to match current observations
Walls - Plaster/Drywall	Rm 102 - Girls Locker Room	35	SF	4	1-2 years	Water damage, spalling, bubbling paint, and cracks
Water Closet	Rm 102 - Girls Locker Room	4	EA	6	2-5 years	F,
Accessories	Rm 110 - Boys Locker room	3,990	SF	5	2-5 years	
Benches, ped mounted	Rm 110 - Boys Locker room	48	LF	6	6-10 years	
Ceiling - Plaster/Drywall	Rm 110 - Boys Locker room	3,990	SF	6	10+ years	
Doors - Steel Doors incl hw	Rm 110 - Boys Locker room	5	EA	6	6-10 years	
Doors - Transom Window	Rm 110 - Boys Locker room	48	SF	6	6-10 years	
Floor - Concrete Epoxy/ Painted	Rm 110 - Boys Locker room	3,190	SF	7	10+ years	
Floor - Tile Ceramic/ Porcelain	Rm 110 - Boys Locker room	800	SF	6	10+ years	
Floor Drain	Rm 110 - Boys Locker room	5	EA	4	0-1 year	Rusted drain
Hand Dryer	Rm 110 - Boys Locker room	2	EA	5	2-5 years	
Lavatory	Rm 110 - Boys Locker room	2	EA	6	2-5 years	
Lighting - Pendent/Surface	Rm 110 - Boys Locker room	67	EA	7	2-5 years	
Lighting - Pendent/Surface	Rm 110 - Boys Locker room	14	EA	6	2-5 years	
Partitions	Rm 110 - Boys Locker room	2	EA	5	6-10 years	
Showers	Rm 110 - Boys Locker room	14	EA	5	2-5 years	
Student Lockers - One Tier	Rm 110 - Boys Locker room	4	EA	6	6-10 years	
Student Lockers - Two Tier	Rm 110 - Boys Locker room	215	EA	6	6-10 years	
Urinals	Rm 110 - Boys Locker room	5	EA	6	2-5 years	
Walls - Structural Glazed Tile	Rm 110 - Boys Locker room	4,805	SF	6	10+ years	
Water Closet	Rm 110 - Boys Locker room	2	EA	6	2-5 years	
unch & Multipurpose Room						
Ceiling - Splined	3rd Floor	4,100	SF	6	10+ years	
Doors - Transom Window	3rd Floor	72	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	10	EA	6	10+ years	
Floor - Tile	3rd Floor	4,100	SF	6	10+ years	
Lighting - Pendent/Surface	3rd Floor	101	EA	7	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,700	SF	6	10+ years	
Walls - Structural Glazed Tile	3rd Floor	1,450	SF	6	10+ years	
Ceiling - Splined	3rd Floor Serving Room	1,075	SF	6	10+ years	
Doors - Transom Window	3rd Floor Serving Room	27	SF	6	6-10 years	
Doors - Wood Doors inclu hw	3rd Floor Serving Room	5	EA	6	6-10 years	
Floor - Terrazzo	3rd Floor Serving Room	1,075	SF	6	10+ years	
Lighting - Pendent/Surface	3rd Floor Serving Room	24	EA	7	6-10 years	
Serving Line	3rd Floor Serving Room	105	LF	6	6-10 years	
Storage/ Closet	3rd Floor Serving Room	320	SF	7	6-10 years	
Walls - Plaster/Drywall	3rd Floor Serving Room	498	SF	6	10+ years	
Walls - Structural Glazed Tile	3rd Floor Serving Room	782	SF	6	10+ years	
Ceiling - Exposed	Laundry room bsmt	675	SF	6	6-10 years	
Doors - Wood Doors inclu hw	Laundry room bsmt	1	EA	7	6-10 years	
Floor - Concrete	Laundry room bsmt	675	SF	7	6-10 years	
Lighting - Wall Mounted	Laundry room bsmt	2	EA	7	6-10 years	



ALL A	SCHOOIS					56	30 S Rockwell STREET, Chicago, IL 60629
						Replacement	
	Storage/ Closet	Laundry room bsmt	75	SF	7	6-10 years	
	Walls - Plaster/Drywall	Laundry room bsmt	1,400	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Prep Room next to 330	240	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Prep Room next to 330	1	EA	6	10+ years	
	Floor - Terrazzo	Prep Room next to 330	240	SF	6	10+ years	
	Lighting - Pendent/Surface	Prep Room next to 330	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	Prep Room next to 330	380	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Weight Room 100	1,920	SF	6	10+ years	
	Doors - Transom Window	Weight Room 100	8	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Weight Room 100	1	ĒA	6	6-10 years	
	Floor - Weight/ Fitness Room Floor Matting	Weight Room 100	1,920	SF	6	10+ years	
	Lighting - Pendent/Surface	Weight Room 100	50	EA	7	2-5 years	
	Student Lockers - Two Tier	Weight Room 100	24	EA	6	6-10 years	
	Walls - Concrete Block	Weight Room 100	620	SF	6	10+ years	
	Walls - Conclete Block Walls - Structural Glazed Tile	Weight Room 100	1,420	SF	6	10+ years	
	Walls - Structural Glazed The	Weight Room 100	1,420	36	0	IUT years	
MDF ID)F						
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Finishes	1st Floor	65	SF	4	1-2 years	Spalling ceiling, extensive bubbling,
				•	•)	water damage
	Other Cooling Unit	1st Floor	1	EA	5	6-10 years	
	0					,	
Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	23	SF	5	6-10 years	
	Janitor's Closet	1st Floor	76	SF	4	1-2 years	Water damaged ceiling, peeling paint and bowing plaster
	Loading Docks	1st Floor	550	SF	7	6-10 years	01
	Mechanical/ Service Rooms	1st Floor	194	SF	7	6-10 years	
	Storage Room	1st Floor	122	SF	5	6-10 years	
	Storage Room	1st Floor	363	SF	5	6-10 years	
	Vaults	1st Floor	75	SF	5	6-10 years	
	Janitor's Closet	2nd Floor	86	SF	7	10+ years	
	Janitor's Closet	2nd Floor	86	SF	7	10+ years	
	Storage Room	2nd Floor	27	SF	7	10+ years	
	Janitor's Closet	3rd Floor	120	SF	7	6-10 years	
	Janitor's Closet	3rd Floor	86	SF	7	10+ years	Light bulb nonfunctional
	Janitor's Closet	3rd Floor	120	SF	7	10+ years	Eight buib homunctional
		3rd Floor	120	SF	7		
	Mechanical/ Service Rooms		430	SF	7	10+ years	
	Storage Room	3rd Floor				10+ years	
	Air Intake Plenums	Basement	1,200	SF	7	2-5 years	
	Auditorium Plenums	Basement	4,900	SF	5	2-5 years	
	Boiler Room	Basement	1,905	SF	5	6-10 years	
	Crawl Space - Unfinished	Basement	15,700	SF	5	2-5 years	
	Mechanical/ Service Rooms	Basement	12,000	SF	5	6-10 years	
	Mechanical/ Service Rooms	Basement	6,818	SF	5	6-10 years	
	Storage Room	Basement	7,596	SF	5	6-10 years	

Chicago Public Schools					56	Gage Park High Sc 30 S Rockwell STREET, Chicago, II
					Replacement	
Storage Room	Basement	2,744	SF	5	6-10 years	
U U		, -		-	, · ·	
Natatorium						
Accessories	1st Floor	3,356	SF	7	2-5 years	
Bleachers Seating/Plank Seating	1st Floor	32	EA	6	6-10 years	
Ceiling - Lay-in	1st Floor	3,356	SF	6	10+ years	
Doors - Side-lite	1st Floor	8	SF	6	6-10 years	
Doors - Transom Window	1st Floor	16	SF	6	6-10 years	
Doors - Wood Doors inclu hw	1st Floor	4	EA	6	6-10 years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
Lighting - Pendent/Surface	1st Floor	13	EA	7	2-5 years	
Lighting - Wall Mounted	1st Floor	14	EA	7	2-5 years	
Pool Basin	1st Floor	1,900	SF	7	6-10 years	Deficiency fixed
Pool Deck	1st Floor	1,456	SF	6	10+ years	
Pool Deck Drains	1st Floor	8	EA	7	6-10 years	
Storage/ Closet	1st Floor	35	SF	5	6-10 years	
Walls - Structural Glazed Tile	1st Floor	4,932	SF	6	10+ years	
Room						
Casework	Inside Rm 222A- Kitchenette	36	LF	6	6-10 years	
Ceiling - Lay-in	Inside Rm 222A- Kitchenette	110	SF	7	10+ years	
Doors - Wood Doors inclu hw	Inside Rm 222A- Kitchenette	1	EA	6	6-10 years	
Floor - Tile	Inside Rm 222A- Kitchenette	110	SF	6	10+ years	
Lighting - Lay-in	Inside Rm 222A- Kitchenette	2	EA	7	6-10 years	
Walls - Plaster/Drywall	Inside Rm 222A- Kitchenette	534	SF	6	10+ years	
Work Sink	Inside Rm 222A- Kitchenette	1	EA	7	10+ years	
Casework	Rm 217A- Prep Rm/Storage	36	LF	6	6-10 years	
Ceiling - Plaster/Drywall	Rm 217A- Prep Rm/Storage	148	SF	5	1-2 years	Peeling paint throughout
Doors - Steel Doors incl hw	Rm 217A- Prep Rm/Storage	1	EA	6	10+ years	
Floor - Tile	Rm 217A- Prep Rm/Storage	138	SF	6	10+ years	
Floor - Tile	Rm 217A- Prep Rm/Storage	10	SF	5	1-2 years	Cracking and chipping
Lighting - Pendent/Surface	Rm 217A- Prep Rm/Storage	4	EA	7	10+ years	
Walls - Plaster/Drywall	Rm 217A- Prep Rm/Storage	684	SF	7	10+ years	
Work Sink	Rm 217A- Prep Rm/Storage	1	EA	5	1-2 years	Appears nonfunctional
Casework	Rm 219- Prep Rm/Storage	36	LF	6	6-10 years	
Ceiling - Plaster/Drywall	Rm 219- Prep Rm/Storage	148	SF	5	1-2 years	Damage
Doors - Transom Window	Rm 219- Prep Rm/Storage	8	SF	6	10+ years	
Doors - Wood Doors inclu hw	Rm 219- Prep Rm/Storage	1	EA	7	10+ years	
Floor - Wood	Rm 219- Prep Rm/Storage	148	SF	6	10+ years	
Lighting - Pendent/Surface	Rm 219- Prep Rm/Storage	4	EA	7	10+ years	
Walls - Plaster/Drywall	Rm 219- Prep Rm/Storage	684	SF	6	10+ years	
Work Sink	Rm 219- Prep Rm/Storage	1	EA	5	1-2 years	Appears nonfunctional
Casework	Rm 317A- Prep Rm/Storage	36	LF	6	6-10 years	
Ceiling - Plaster/Drywall	Rm 317A- Prep Rm/Storage	148	SF	6	10+ years	
Doors - Wood Doors inclu hw	Rm 317A- Prep Rm/Storage	1	EA	6	10+ years	
Floor - Tile	Rm 317A- Prep Rm/Storage	148	SF	6	10+ years	



						30 S Rockwell STREET, Chicago, IL 60629
					Replacement	
Lighting - Pendent/Surface	Rm 317A- Prep Rm/Storage	4	EA	7	10+ years	
Walls - Plaster/Drywall	Rm 317A- Prep Rm/Storage	684	SF	6	10+ years	
Work Sink	Rm 317A- Prep Rm/Storage	1	EA	7	10+ years	
Accessories	135A	24	SF	7		
Accessories		24	SF		2-5 years	Deint neeling
Ceiling - Plaster/Drywall	135A	24		5	1-2 years	Paint peeling
Doors - Wood Doors inclu hw	135A	1	EA	6	6-10 years	
Floor - Tile Ceramic/ Porcelain	135A	24	SF	6	10+ years	
Lavatory	135A	1	EA	6	2-5 years	A
Valls - Plaster/Drywall	135A	187	SF	4	1-2 years	Spalling, cracking plaster and paint
Vater Closet	135A	1	EA	6	2-5 years	
ccessories	145G Police Office Toilet	45	SF	7	2-5 years	
Ceiling - Plaster/Drywall	145G Police Office Toilet	45	SF	6	1-2 years	Large crack, water damage and pain
Doors - Wood Doors inclu hw	145G Police Office Toilet	1	EA	6	1.2 voore	cracking Damaged door, chipped, bent, hole i
	143G Folice Office Tollet	1	LA	0	1-2 years	door
Floor - Tile Ceramic/ Porcelain	145G Police Office Toilet	45	SF	7	10+ years	
avatory	145G Police Office Toilet	1	EA	6	2-5 years	
ighting - Pendent/Surface	145G Police Office Toilet	1	EA	7	2-5 years	
Showers	145G Police Office Toilet	1	EA	5	2-5 years	
Walls - Plaster/Drywall	145G Police Office Toilet	255	SF	6	1-2 years	Extensive spalling, paint chipping ar
				-	,	bubbling
/ater Closet	145G Police Office Toilet	1	EA	6	2-5 years	
ccessories	1st Floor Women's North 1MN	93	SF	7	6-10 years	
eiling - Plaster/Drywall	1st Floor Women's North 1MN	93	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor Women's North 1MN	1	EA	7	10+ years	
Floor - Tile Ceramic/ Porcelain	1st Floor Women's North 1MN	93	SF	7	10+ years	
Floor Drain	1st Floor Women's North 1MN	1	EA	7	10+ years	
Hand Dryer	1st Floor Women's North 1MN	1	EA	7	6-10 years	
Lavatory	1st Floor Women's North 1MN	1	EA	7	10+ years	
Lighting - Pendent/Surface	1st Floor Women's North 1MN	1	EA	7	6-10 years	
Walls - Plaster/Drywall	1st Floor Women's North 1MN	100	SF	7	10+ years	
Walls - Tile Ceramic/ Porcelain	1st Floor Women's North 1MN	300	SF	7	10+ years	
Water Closet	1st Floor Women's North 1MN	1	EA	7	10+ years	
Accessories	1st Fir- Auditorium Men	139	SF	7	2-5 years	
Ceiling - Plaster/Drywall	1st FIr- Auditorium Men	139	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st FIr- Auditorium Men	139	EA	6	6-10 years	
Floor - Tile Ceramic/ Porcelain	1st FIr- Auditorium Men	139	SF	6	10+ years	
			EA	7		Deficiency fixed
Floor Drain	1st FIr- Auditorium Men	2			6-10 years	Deficiency fixed
Lavatory	1st FIr- Auditorium Men	2	EA	6	2-5 years	
Lighting - Pendent/Surface	1st FIr- Auditorium Men	1	EA	7	6-10 years	De lanar fintuna
Lighting - Pendent/Surface	1st FIr- Auditorium Men	3	EA	6	6-10 years	Re-lamp fixture
Partitions	1st FIr- Auditorium Men	1	EA	5	6-10 years	
Urinals	1st FIr- Auditorium Men	2	EA	6	2-5 years	
Walls - Plaster/Drywall	1st FIr- Auditorium Men	422	SF	6	10+ years	



						So o Rockwell O I REET, Officag
				-	Replacement	
Water Closet	1st FIr- Auditorium Men	2	EA	6	2-5 years	
Accessories	1st FIr- Auditorium Women	139	SF	5	6-10 years	
Ceiling - Plaster/Drywall	1st FIr- Auditorium Women	139	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st Flr- Auditorium Women	1	EA	6	6-10 years	
Floor - Tile Ceramic/ Porcelain	1st Flr- Auditorium Women	139	SF	6	10+ years	
Lavatory	1st Flr- Auditorium Women	2	EA	6	2-5 years	
Lighting - Pendent/Surface	1st FIr- Auditorium Women	4	EA	7	2-5 years	
Partitions	1st Flr- Auditorium Women	2	EA	5	6-10 years	
Walls - Plaster/Drywall	1st Flr- Auditorium Women	422	SF	6	10+ years	
Water Closet	1st Flr- Auditorium Women	2	EA	6	2-5 years	
Accessories	1st floor Boys North	245	SF	7	2-5 years	
Ceiling - Plaster/Drywall	1st floor Boys North	245	SF	6	10+ years	
Doors - Transom Window	1st floor Boys North	18	SF	6	6-10 years	
Doors - Wood Doors inclu hw	1st floor Boys North	2	EA	6	6-10 years	
Floor - Tile Ceramic/ Porcelain	1st floor Boys North	237	SF	6	10+ years	
Floor - Tile Ceramic/ Porcelain	1st floor Boys North	8	SF	4	1-2 years	Missing, cracked tile
Floor Drain	1st floor Boys North	1	ĒA	4	1-2 years	Rusted drain
Hand Dryer	1st floor Boys North	2	EA	5	2-5 years	
Lavatory	1st floor Boys North	2	EA	6	2-5 years	
Lighting - Pendent/Surface	1st floor Boys North	4	EA	7	2-5 years	
Partitions	1st floor Boys North	2	EA	5	6-10 years	
Urinals	1st floor Boys North	7	EA	6	2-5 years	
Walls - Structural Glazed Tile	1st floor Boys North	675	SF	5	10+ years	
Water Closet	1st floor Boys North	2	EA	6	2-5 years	
Accessories	1st floor Girls South 1GS	352	SF	7	2-5 years	
Ceiling - Plaster/Drywall	1st floor Girls South 1GS	352	SF	6	10+ years	
Doors - Transom Window	1st floor Girls South 1GS	18	SF	6	6-10 years	
Doors - Wood Doors inclu hw	1st floor Girls South 1GS	2	EA	6	6-10 years	
Floor - Tile Ceramic/ Porcelain	1st floor Girls South 1GS	352	SF	6	10+ years	
Floor Drain	1st floor Girls South 1GS	1	EA	7	6-10 years	
Hand Dryer	1st floor Girls South 1GS	2	EA	5	2-5 years	
Lavatory	1st floor Girls South 1GS	2	EA	6	2-5 years 2-5 years	
Lighting - Pendent/Surface	1st floor Girls South 1GS	6	EA	7	2-5 years 2-5 years	
Partitions	1st floor Girls South 1GS	8	EA	7	6-10 years	Deficiency fixed
Walls - Structural Glazed Tile	1st floor Girls South 1GS	886	SF	6	10+ years	Denciency fixed
Walls - Structural Glazed The Water Closet	1st floor Girls South 1GS	8	EA	6	2-5 years	
			SF		•	
Accessories	1st floor Men's South 1BS	245	SF	7 6	2-5 years	
Ceiling - Plaster/Drywall	1st floor Men's South 1BS	245			10+ years	
Doors - Wood Doors inclu hw	1st floor Men's South 1BS	2	EA	6	6-10 years	
Floor - Tile Ceramic/ Porcelain	1st floor Men's South 1BS	245	SF	6	10+ years	Durate di dura in
Floor Drain	1st floor Men's South 1BS	1	EA	4	1-2 years	Rusted drain
Hand Dryer	1st floor Men's South 1BS	2	EA	5	2-5 years	
Lavatory	1st floor Men's South 1BS	2	EA	6	2-5 years	
Lighting - Pendent/Surface	1st floor Men's South 1BS	4	EA	7	2-5 years	
Partitions	1st floor Men's South 1BS	3	EA	5	6-10 years	
Urinals	1st floor Men's South 1BS	7	EA	6	2-5 years	
Walls - Structural Glazed Tile	1st floor Men's South 1BS	655	SF	6	10+ years	



					Replacement	
Walls - Structural Glazed Tile	1st floor Men's South 1BS	20	SF	4	1-2 years	Cracked and missing tiles
Water Closet	1st floor Men's South 1BS	3	ĒΑ	6	2-5 years	3
Accessories	1st floor Women's North 1GN	352	SF	7	6-10 years	
Ceiling - Plaster/Drywall	1st floor Women's North 1GN	352	SF	6	10+ years	
Doors - Transom Window	1st floor Women's North 1GN	18	SF	6	10+ years	
Doors - Wood Doors inclu hw	1st floor Women's North 1GN	2	ĒΑ	6	10+ years	
Floor - Tile Ceramic/ Porcelain	1st floor Women's North 1GN	352	SF	6	10+ years	
Floor Drain	1st floor Women's North 1GN	1	EA	7	10+ years	
Hand Dryer	1st floor Women's North 1GN	2	EA	5	6-10 years	
Lavatory	1st floor Women's North 1GN	2	EA	6	10+ years	
Lighting - Pendent/Surface	1st floor Women's North 1GN	6	EA	7	6-10 years	
Partitions	1st floor Women's North 1GN	8	EA	7	6-10 years	Deficiency fixed
Walls - Tile Ceramic/ Porcelain	1st floor Women's North 1GN	886	SF	6	10+ years	5
Water Closet	1st floor Women's North 1GN	8	ĒΑ	6	10+ years	
Accessories	2nd Floor Boys North	245	SF	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor Boys North	245	SF	6	10+ years	
Doors - Transom Window	2nd Floor Boys North	18	SF	6	6-10 years	
Doors - Wood Doors inclu hw	2nd Floor Boys North	2	EA	6	6-10 years	
Floor - Tile Ceramic/ Porcelain	2nd Floor Boys North	245	SF	6	10+ years	
Floor Drain	2nd Floor Boys North	1	EA	7	6-10 years	
Hand Dryer	2nd Floor Boys North	2	EA	7	6-10 years	
Lavatory	2nd Floor Boys North	2	EA	6	6-10 years	
Lighting - Pendent/Surface	2nd Floor Boys North	4	EA	7	6-10 years	
Partitions	2nd Floor Boys North	4	EA	7	6-10 years	
Urinals	2nd Floor Boys North	7	EA	6	6-10 years	
Walls - Structural Glazed Tile	2nd Floor Boys North	587	SF	6	10+ years	
Water Closet	2nd Floor Boys North	4	EA	6	6-10 years	
Accessories	2nd Floor Boys South	245	SF	7	10+ years	
Ceiling - Plaster/Drywall	2nd Floor Boys South	245	SF	6	10+ years	
Doors - Transom Window	2nd Floor Boys South	18	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor Boys South	2	EA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	2nd Floor Boys South	245	SF	6	10+ years	
Floor Drain	2nd Floor Boys South	1	EA	7	10+ years	
Hand Dryer	2nd Floor Boys South	2	EA	7	10+ years	
Lavatory	2nd Floor Boys South	1	EA	6	10+ years	
Lighting - Pendent/Surface	2nd Floor Boys South	4	EA	7	10+ years	
Partitions	2nd Floor Boys South	4	EA	7	10+ years	
Urinals	2nd Floor Boys South	7	EA	6	10+ years	
Walls - Structural Glazed Tile	2nd Floor Boys South	587	SF	6	10+ years	
Water Closet	2nd Floor Boys South	4	EA	6	10+ years	
Accessories	2nd Floor Girls North	352	SF	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor Girls North	352	SF	6	10+ years	
Doors - Transom Window	2nd Floor Girls North	18	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor Girls North	2	EA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	2nd Floor Girls North	352	SF	6	10+ years	
Floor Drain	2nd Floor Girls North	1	EA	7	10+ years	
Hand Dryer	2nd Floor Girls North	2	EA	7	6-10 years	



					50	SUS ROCKWEILSTREET, CHI
					Replacement	
Lavatory	2nd Floor Girls North	2	EA	6	10+ years	
Lighting - Pendent/Surface	2nd Floor Girls North	6	EA	7	10+ years	
Partitions	2nd Floor Girls North	9	EA	7	10+ years	
Walls - Structural Glazed Tile	2nd Floor Girls North	902	SF	6	10+ years	
Water Closet	2nd Floor Girls North	9	EA	6	10+ years	
Accessories	2nd Floor Girls South	352	SF	7	6-10 years	
Ceiling - Plaster/Drywall	2nd Floor Girls South	352	SF	6	10+ years	
Doors - Transom Window	2nd Floor Girls South	18	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor Girls South	2	ĒA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	2nd Floor Girls South	352	SF	6	10+ years	
Floor Drain	2nd Floor Girls South	1	EA	7	10+ years	
Hand Dryer	2nd Floor Girls South	2	EA	7	6-10 years	
Lavatory	2nd Floor Girls South	2	EA	6	6-10 years	
Lighting - Pendent/Surface	2nd Floor Girls South	6	EA	7	6-10 years	
Partitions	2nd Floor Girls South	9	EA	7		
		-			10+ years	
Walls - Structural Glazed Tile	2nd Floor Girls South	902	SF	6	10+ years	
Water Closet	2nd Floor Girls South	9	EA	6	10+ years	
	3rd Floor Boys North	245	SF	7	10+ years	
Ceiling - Plaster/Drywall	3rd Floor Boys North	245	SF	6	10+ years	
Doors - Transom Window	3rd Floor Boys North	18	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd Floor Boys North	2	EA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	3rd Floor Boys North	245	SF	6	10+ years	
Floor Drain	3rd Floor Boys North	2	EA	7	10+ years	
Hand Dryer	3rd Floor Boys North	2	EA	7	10+ years	
Lavatory	3rd Floor Boys North	1	EA	6	10+ years	Updated quantity
Lighting - Pendent/Surface	3rd Floor Boys North	4	EA	7	10+ years	
Partitions	3rd Floor Boys North	4	EA	7	10+ years	
Urinals	3rd Floor Boys North	7	EA	6	10+ years	
Walls - Structural Glazed Tile	3rd Floor Boys North	587	SF	6	10+ years	
Water Closet	3rd Floor Boys North	4	EA	6	10+ years	
Accessories	3rd Floor Boys South	245	SF	7	10+ years	
Ceiling - Plaster/Drywall	3rd Floor Boys South	245	SF	6	10+ years	
Doors - Transom Window	3rd Floor Boys South	18	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd Floor Boys South	3	EA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	3rd Floor Boys South	245	SF	7	10+ years	
Floor Drain	3rd Floor Boys South	2	EA	7	10+ years	
Hand Dryer	3rd Floor Boys South	2	EA	7	10+ years	
Lavatory	3rd Floor Boys South	2	EA	6	10+ years	
Lighting - Pendent/Surface	3rd Floor Boys South	4	EA	7	10+ years	
Partitions	3rd Floor Boys South	4	EA	7	10+ years	
Urinals	3rd Floor Boys South	7	EA	6	10+ years	
Walls - Structural Glazed Tile	3rd Floor Boys South	587	SF	6	10+ years	
Water Closet	3rd Floor Boys South	4	EA	6	•	
	3rd Floor Girls North	4 352	SF	7	10+ years	
Accessories			SF		10+ years	
Ceiling - Plaster/Drywall	3rd Floor Girls North	352		6	10+ years	
Doors - Transom Window	3rd Floor Girls North	18	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd Floor Girls North	2	EA	6	10+ years	



					50	
					Replacement	
Floor - Tile Ceramic/ Porcelain	3rd Floor Girls North	352	SF	6	10+ years	
Floor Drain	3rd Floor Girls North	1	EA	7	6-10 years	
Hand Dryer	3rd Floor Girls North	2	EA	7	6-10 years	
Lavatory	3rd Floor Girls North	2	EA	6	10+ years	
Lighting - Pendent/Surface	3rd Floor Girls North	6	EA	6	10+ years	
Partitions	3rd Floor Girls North	9	EA	7	10+ years	
Walls - Structural Glazed Tile	3rd Floor Girls North	902	SF	6	10+ years	
Water Closet	3rd Floor Girls North	9	EA	6	10+ years	
Accessories	3rd Floor Girls South	352	SF	7	6-10 years	
Ceiling - Plaster/Drywall	3rd Floor Girls South	352	SF	6	10+ years	
Doors - Transom Window	3rd Floor Girls South	18	SF	6	6-10 years	
Doors - Wood Doors inclu hw		2	EA	6		
	3rd Floor Girls South			-	6-10 years	
Floor - Tile Ceramic/ Porcelain	3rd Floor Girls South	344	SF	6	10+ years	
Floor - Tile Ceramic/ Porcelain	3rd Floor Girls South	8	SF	6	10+ years	
Floor Drain	3rd Floor Girls South	1	EA	7	10+ years	Updated to match current
						observations
Hand Dryer	3rd Floor Girls South	2	EA	7	6-10 years	
Lavatory	3rd Floor Girls South	2	EA	6	6-10 years	
Lighting - Pendent/Surface	3rd Floor Girls South	6	EA	7	6-10 years	
Partitions	3rd Floor Girls South	9	EA	7	6-10 years	
Walls - Structural Glazed Tile	3rd Floor Girls South	902	SF	6	10+ years	
Water Closet	3rd Floor Girls South	9	EA	6	10+ years	
Accessories	3rd Floor Staff North	93	SF	7	6-10 years	
Ceiling - Plaster/Drywall	3rd Floor Staff North	93	SF	6	10+ years	
Doors - Transom Window	3rd Floor Staff North	9	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd Floor Staff North	1	EA	6	10+ years	
Floor - Tile Ceramic/ Porcelain	3rd Floor Staff North	93	SF	6	10+ years	
Lavatory	3rd Floor Staff North	1	ĒA	6	10+ years	
Lighting - Pendent/Surface	3rd Floor Staff North	2	EA	7	10+ years	
Partitions	3rd Floor Staff North	2	EA	7	10+ years	
Walls - Plaster/Drywall	3rd Floor Staff North	400	SF	6	10+ years	
Water Closet	3rd Floor Staff North	2	EA	6	10+ years	
Accessories	Asst. Engineer's Toilet 145H	160	SF	5	2-5 years	
Ceiling - Plaster/Drywall	Asst. Engineer's Toilet 145H	152	SF	6	10+ years	
Ceiling - Plaster/Drywall	Asst. Engineer's Toilet 145H	8	SF	5	•	
					10+ years	
Doors - Wood Doors inclu hw	Asst. Engineer's Toilet 145H	1	EA	6	6-10 years	
Floor - Tile Ceramic/ Porcelain	Asst. Engineer's Toilet 145H	44	SF	6	10+ years	
Floor - Tile/Sheet	Asst. Engineer's Toilet 145H	116	SF	5	10+ years	
Lavatory	Asst. Engineer's Toilet 145H	1	EA	6	2-5 years	
Lighting - Pendent/Surface	Asst. Engineer's Toilet 145H	2	EA	7	2-5 years	
Lighting - Wall Mounted	Asst. Engineer's Toilet 145H	1	EA	7	2-5 years	
Showers	Asst. Engineer's Toilet 145H	1	EA	5	2-5 years	
Walls - Plaster/Drywall	Asst. Engineer's Toilet 145H	12	SF	6	10+ years	
Walls - Plaster/Drywall	Asst. Engineer's Toilet 145H	480	SF	6	10+ years	
Walls - Structural Glazed Tile	Asst. Engineer's Toilet 145H	80	SF	6	10+ years	
Water Closet	Asst. Engineer's Toilet 145H	1	EA	6	2-5 years	
Accessories	In 116- Asst. Principal Suite	44	SF	7	2-5 years	



Replacement In 116- Asst. Principal Suite Ceiling - Plaster/Drywall SF 5 1-2 vears Bubbling paint 44 ΕA 6 6-10 vears Doors - Wood Doors inclu hw In 116- Asst, Principal Suite 1 Floor - Tile Ceramic/ Porcelain In 116- Asst. Principal Suite 36 SF 6 10+ years Floor - Tile Ceramic/ Porcelain 8 SF 0-1 year In 116- Asst. Principal Suite 4 Missing tiles 6 Lavatory In 116- Asst. Principal Suite 1 EA 2-5 years ΕA Lighting - Pendent/Surface 7 In 116- Asst. Principal Suite 1 2-5 years Lighting - Wall Mounted In 116- Asst. Principal Suite 7 1 FΑ 2-5 years SF Walls - Plaster/Drvwall In 116- Asst, Principal Suite 130 6 10+ years SF Walls - Tile Ceramic/ Porcelain In 116- Asst. Principal Suite 136 6 10+ years Water Closet In 116- Asst, Principal Suite 1 EΑ 6 2-5 vears Accessories In 122 Dean's Office 65 SF 7 6-10 years Ceiling - Plaster/Drywall In 122 Dean's Office 65 SF 7 6-10 years Doors - Wood Doors inclu hw ΕA 7 6-10 years In 122 Dean's Office 1 SF 7 Floor - Tile Ceramic/ Porcelain In 122 Dean's Office 65 6-10 years In 122 Dean's Office FΑ 7 6-10 years Lavatory 1 Lighting - Pendent/Surface FΑ 7 In 122 Dean's Office 1 6-10 years Walls - Plaster/Drvwall In 122 Dean's Office 300 SF 7 6-10 vears Water Closet In 122 Dean's Office EA 7 6-10 years 1 SF 5 Accessories In 123- Asst. Principal Suite 44 2-5 years Ceiling - Plaster/Drywall SF In 123- Asst. Principal Suite 44 6 10+ years Doors - Wood Doors inclu hw In 123- Asst. Principal Suite 1 ΕA 6 6-10 years SF Floor - Concrete In 123- Asst. Principal Suite 21 5 6-10 years Material updated to match current observations SF Floor - Tile Ceramic/ Porcelain In 123- Asst. Principal Suite 23 6 10+ years In 123- Asst. Principal Suite FΑ 6 2-5 vears Lavatorv 1 Lighting - Pendent/Surface In 123- Asst. Principal Suite 1 EΑ 6 6-10 years Re-lamp fixture Lighting - Wall Mounted 7 In 123- Asst. Principal Suite 1 EΑ 2-5 years SF Walls - Plaster/Drywall In 123- Asst. Principal Suite 130 6 10+ years SF Walls - Tile In 123- Asst. Principal Suite 16 5 10+ years SF Walls - Tile Ceramic/ Porcelain In 123- Asst. Principal Suite 120 6 10+ years ΕA Water Closet In 123- Asst. Principal Suite 6 2-5 vears 1 Accessories In Office 232 24 SF 7 10+ years SF Ceiling - Plaster/Drywall In Office 232 24 6 10+ years Doors - Wood Doors inclu hw In Office 232 1 EA 6 10+ years Floor - Tile Ceramic/ Porcelain SF 6 In Office 232 24 10+ years ΕA 6 Lavatory In Office 232 1 10+ years Lighting - Pendent/Surface In Office 232 1 EA 7 10+ years Walls - Plaster/Drvwall In Office 232 187 SF 6 10+ vears Water Closet In Office 232 1 EA 6 10+ years SF Accessories In Office 233 24 7 6-10 years SF Ceiling - Plaster/Drywall In Office 233 24 6 10+ vears Doors - Wood Doors inclu hw ΕA 6 6-10 years In Office 233 1 Floor - Tile Ceramic/ Porcelain In Office 233 24 SF 6 10+ years ΕA 6 Lavatorv In Office 233 1 6-10 years 2 7 Lighting - Pendent/Surface In Office 233 ΕA 6-10 years EΑ 7 Partitions In Office 233 2 6-10 years Walls - Plaster/Drywall In Office 233 177 SF 6 10+ years



						50	SO O ROCKWEII O I REET, Officago, IE OC
						Replacement	
Walls	- Plaster/Drywall	In Office 233	10	SF	5	1-2 years	Water damage
Water	r Closet	In Office 233	2	EA	6	10+ years	
Acces	ssories	Rm 102C- Unisex in Pool area	113	SF	5	6-10 years	
Bench	hes	Rm 102C- Unisex in Pool area	4	LF	6	2-5 years	
Ceilin	ig - Lay-in	Rm 102C- Unisex in Pool area	113	SF	6	10+ years	
Doors	s - Steel Doors incl hw	Rm 102C- Unisex in Pool area	1	EA	6	6-10 years	
Floor	- Tile Ceramic/ Porcelain	Rm 102C- Unisex in Pool area	113	SF	6	10+ years	
Floor	Drain	Rm 102C- Unisex in Pool area	2	EA	7	6-10 years	Deficiency fixed
Lavat	ory	Rm 102C- Unisex in Pool area	1	EA	6	2-5 years	
Lighti	ng - Lay-in	Rm 102C- Unisex in Pool area	1	EA	7	2-5 years	
Show	vers	Rm 102C- Unisex in Pool area	1	EA	5	6-10 years	
Stude	ent Lockers - One Tier	Rm 102C- Unisex in Pool area	3	EA	6	6-10 years	
Walls	- Concrete Block	Rm 102C- Unisex in Pool area	422	SF	6	10+ years	
Walls	- Tile Ceramic/ Porcelain	Rm 102C- Unisex in Pool area	119	SF	6	10+ years	
Water	r Closet	Rm 102C- Unisex in Pool area	1	EA	6	2-5 years	
Acces	ssories	Rm 145J	160	SF	5	6-10 years	
Ceilin	g - Plaster/Drywall	Rm 145J	160	SF	6	6-10 years	
Doors	s - Wood Doors inclu hw	Rm 145J	1	EA	7	6-10 years	
Floor	- Tile Ceramic/ Porcelain	Rm 145J	160	SF	7	10+ years	
Lavat	ory	Rm 145J	1	EA	6	6-10 years	
Lighti	ng - Pendent/Surface	Rm 145J	1	EA	7	10+ years	
Walls	- Plaster/Drywall	Rm 145J	550	SF	6	6-10 years	Updated to match current observations.
Water	r Closet	Rm 145J	1	EA	7	10+ years	

Category : Classroom

Building	• Main
Banang	

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #103 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	2-5 years	
	Casework	1st Floor	87	LF	6	2-5 years	
	Ceiling - Plaster/Drywall	1st Floor	1,874	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Eye Wash Station	1st Floor	1	EA	6	2-5 years	
	Floor - Wood	1st Floor	1,874	SF	5	2-5 years	
	Lighting - Pendent/Surface	1st Floor	46	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	71	SF	5	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,125	SF	7	10+ years	
	Work Sink	1st Floor	4	EA	5	2-5 years	
Classroo	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	2-5 years	
	Casework	1st Floor	12	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	826	SF	6	10+ years	



Building : Main Category : Classroom Recommend Quantity Group Item - Type Location UOM Rank Replacement Comments Doors - Transom Window SF 1st Floor 8 6 6-10 vears Doors - Wood Doors inclu hw 1st Floor ΕA 6 6-10 years 1 Floor - Wood 1st Floor 826 SF 6 10+ years Lighting - Pendent/Surface 22 ΕA 7 2-5 years 1st Floor 1 F 7 Marker Board 1st Floor 18 6-10 years SF Storage/ Closet 1st Floor 75 5 6-10 years Walls - Plaster/Drywall 1,269 SF 1st Floor 6 10+ years Classroom #107 (Regular Classroom) AC Units 1st Floor 1 EΑ 7 2-5 years Casework 1st Floor 34 LF 6-10 years 6 Ceiling - Plaster/Drywall 1st Floor 713 SF 6 10+ years SF Doors - Transom Window 1st Floor 8 6 6-10 years Doors - Wood Doors inclu hw 1st Floor 1 EΑ 6 6-10 years 713 SF 6 Floor - Wood 1st Floor 10+ years Lighting - Pendent/Surface 1st Floor 18 FΑ 7 2-5 years Walls - Plaster/Drywall SF 1st Floor 868 6 10+ years 2-5 years Work Sink 1st Floor 2 FA 5 Classroom #113 (Regular Classroom) AC Units 1st Floor 1 ΕA 7 2-5 years SF Ceiling - Lav-in 1st Floor 360 10+ years 6 SF Doors - Transom Window 1st Floor 8 6 6-10 years Doors - Wood Doors inclu hw ΕA 5 6-10 years 1st Floor 1 Floor - Tile 1st Floor 360 SF 6 10+ years Lighting - Lay-in 1st Floor 9 ΕA 7 2-5 years LF Marker Board 1st Floor 6 7 6-10 years SF Walls - Plaster/Drywall 1st Floor 714 6 10+ years Classroom #115 (Regular Classroom) AC Units 1st Floor 7 1 EA 2-5 years LF Casework 1st Floor 14 6 6-10 years Ceiling - Lay-in 1st Floor 864 SF 6 10+ years SF Doors - Transom Window 1st Floor 8 6 6-10 years Doors - Wood Doors inclu hw 1st Floor EΑ 6 6-10 years 1 Floor - Tile 1st Floor 864 SF 6 10+ vears 2-5 years Lighting - Lay-in 1st Floor 22 EΑ 7 Marker Board 1st Floor 8 LF 7 6-10 years Walls - Plaster/Drywall 990 SF 1st Floor 6 10+ years Classroom #121 (Regular Classroom) AC Units 1st Floor 1 ΕA 7 6-10 years Casework LF 1st Floor 14 6 6-10 years



						56	30 S Rockwell STREET, Chicago, IL 60629
Catego	ry : Classroom		В	uilding	: Main	_	
0			•		D . 1	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	864	SF	6	10+ years	
	Doors - Transom Window	1st Floor	8	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	864	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	22	EA	7	2-5 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	78	SF	5	6-10 years	
	Walls - Plaster/Drywall	1st Floor	990	SF	6	10+ years	
Classroo	m #124 (Other Instructional Use)						
	AC Units	1st Floor	1	EA	7	2-5 years	
	Casework	1st Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	408	SF	6	10+ years	
	Doors - Transom Window	1st Floor	1	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	6-10 years	
	Floor - Tile	1st Floor	408	SF	6	10+ vears	
	Lighting - Lay-in	1st Floor	6	EA	7	2-5 years	
	Walls - Plaster/Drywall	1st Floor	934	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	50	SF	5	1-2 years	Cracked drywall
Classroo	om #126 (Faculty Lounge)						
	AC Units	1st Floor	1	EA	7	2-5 years	
	Casework	1st Floor	7	LF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	732	SF	6	10+ years	
	Doors - Transom Window	1st Floor	16	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	5	6-10 years	
	Floor - Tile	1st Floor	732	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	7	2-5 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,064	SF	6	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	6-10 years	
	Casework Ceiling - Lay-in	2nd Floor	723	SF	6	10+ years	
	Chalk Board	2nd Floor	32	LF	6 4	2-5 years	
	Doors - Transom Window	2nd Floor 2nd Floor	32	SF	4 6	2-5 years 6-10 years	
			o 1	EA		•	
	Doors - Wood Doors inclu hw	2nd Floor	-	EA SF	6	6-10 years	
	Floor - Wood	2nd Floor	723		6	10+ years	
	Lighting - Lay-in Marker Board	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	918	25	6	10+ years	



Catego	ry : Classroom		Building : Main				
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	723	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Wood	2nd Floor	723	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	38	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	918	SF	6	10+ years	
lassroo	om #205 (Other Instructional Use)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	943	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	16	SF	5	1-2 years	Sagging tile
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	959	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	27	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,079	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	6	1-2 years	Water damage
	Work Sink	2nd Floor	10	EA	7	6-10 years	Water damage
				_ /(·	o ro youro	
lassroc	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	959	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	959	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	27	EA	7	6-10 years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,076	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
lassroc	om #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	727	SF	6	10+ years	
				SF	•		



Catago				ب الماني	. Mein	20	30 S Rockwell STREET, Chicago, IL 60629
Catego	ry : Classroom		В	uilding	Decemand		
C	litere Truce	Leastien	Quantitu		Denk	Recommend	Commente
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	727	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	987	SF	6	10+ years	
Classroc	om #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	14	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	701	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒA	6	10+ years	
	Floor - Wood	2nd Floor		SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	ĒA	7	10+ years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	18	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	939	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	5	1-2 years	Missing hardware
Classroc	om #214 (Regular Classroom) AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6		
			-	SF	-	6-10 years	
	Ceiling - Lay-in	2nd Floor	727	SF	6	10+ years	
	Doors - Transom Window Doors - Wood Doors inclu hw	2nd Floor	16	EA	6 6	6-10 years	
		2nd Floor	2	SF	-	10+ years	
	Floor - Wood	2nd Floor 2nd Floor	727 21	EA	6 7	10+ years	
	Lighting - Lay-in Marker Board	2nd Floor	21	LF	7	6-10 years 6-10 years	
				SF	6		
	Walls - Plaster/Drywall	2nd Floor	987	эг	0	10+ years	
Classroc	om #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	21	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	701	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	16	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Wood	2nd Floor	701	SF	6	10+ years	
	Gas Line	2nd Floor	1	EA	6	6-10 years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	939	SF	6	10+ years	



Catego	ry : Classroom		В	Building : Main			
Ŭ			Recomme				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassror	m #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	733	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	733	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	997	SF	6	10+ years	
lassror	m #217 (Science)						
1000100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	65		6	6-10 years	
	Ceiling - Lay-in	2nd Floor	1,116	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,116	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	30	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Science Lab Elements	2nd Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,214	SF	6	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	Updated quantity
laceroc	m #218 (Special Program)						
1422100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	518	SF	6	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	518	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	10+ years	
	Marker Board	2nd Floor	13		7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	816	SF	6	10+ years	
	m #220 (Office)						
19922100	AC Units	2nd Floor	A	EA	7	6 10 10000	
		2nd Floor 2nd Floor	1			6-10 years	
	Casework		5	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	596	SF	6	10+ years	Water demogra
	Ceiling - Lay-in	2nd Floor	6	SF	4	1-2 years	Water damage
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	



					Main	00	30 S Rockwell STREET, Chicago, IL 60629
Catego	ry : Classroom		В	uilding			
0	Hama Tama	Leaster	Oursetting		Daula	Recommend	0
Group	Item - Type		Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	602	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	915	SF	6	10+ years	
Classroo	om #221 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,071	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,066	SF	7	10+ years	
	Floor - Tile	2nd Floor	5	SF	5	1-2 years	Broken and missing tile
	Lighting - Lay-in	2nd Floor	30	EA	7	10+ years	Broken and meening de
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,196	SF	6	10+ years	
	Work Sink	2nd Floor	1,100	EA	7	10+ years	
Classro	om #222 (Multi Purpose Room)						
_01005104	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	5	LA	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	648	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	648	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	13	EA	7	10+ years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	925	SF	6	10+ years	
	waiis - Plastel/Drywaii	2110 F1001	925	ЪГ	0	TO+ years	
Classroo	om #224 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	733	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	733	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	997	SF	6	10+ years	
Classroo	om #225 (Special Program)						
01033100	AC Units	2nd Floor	1	EA	7	6-10 years	
			I	EA	1	0-10 years	



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments LF Casework 2nd Floor 30 6 6-10 vears 2nd Floor 1.108 SF 6 Ceiling - Lav-in 10+ vears Ceiling - Lay-in 2nd Floor SF 4 1-2 years Broken tile 8 Doors - Transom Window 2nd Floor 16 SF 6 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 EΑ 6 10+ years Floor - Tile 596 SF 7 2nd Floor 10+ years Floor - Tile 2nd Floor 500 SF 5 1-2 years Broken and missing tiles Lighting - Lay-in 2nd Floor 30 EΑ 7 10+ years Walls - Plaster/Drywall 2nd Floor 1.214 SF 6 10+ years Work Sink 2nd Floor 3 FΑ 7 10+ years Work Sink 2nd Floor 6 ΕA 5 1-2 vears Hardware removed Classroom #226 (Regular Classroom) AC Units 2nd Floor 1 ΕA 7 6-10 years Casework 2nd Floor 8 LF 6 6-10 years Ceiling - Lay-in 2nd Floor 727 SF 6 10+ years SF Doors - Transom Window 2nd Floor 16 6 6-10 years Doors - Wood Doors inclu hw 2nd Floor 2 EΑ 6 10+ years SF Floor - Wood 2nd Floor 727 6 10+ years Lighting - Lay-in 2nd Floor ΕA 7 10+ years 21 LF Marker Board 2nd Floor 20 7 6-10 years SF Walls - Plaster/Drvwall 2nd Floor 987 6 10+ vears Classroom #228 (Regular Classroom) AC Units 2nd Floor 1 EΑ 7 6-10 years Casework 2nd Floor 8 LF 6-10 years 6 SF Ceiling - Lav-in 2nd Floor 727 6 10+ years Doors - Transom Window 2nd Floor SF 6 16 10+ years Doors - Wood Doors inclu hw 2nd Floor 2 FΑ 6 10+ years SF Floor - Wood 2nd Floor 727 6 10+ years 7 Lighting - Lay-in 2nd Floor 21 FA 10+ years LF Marker Board 2nd Floor 20 7 6-10 years Walls - Plaster/Drywall SF 2nd Floor 987 6 10+ years Classroom #301 (Store Room) AC Units 3rd Floor 2 EΑ 7 6-10 vears 3rd Floor 32 LF Casework 5 1-2 years Cabinet doors loose and falling Ceiling - Lay-in 3rd Floor 814 SF 6 10+ years Doors - Transom Window 3rd Floor 9 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 2 ΕA 6 10+ years SF 6 Floor - Wood 3rd Floor 814 10+ years Lighting - Lay-in 3rd Floor 21 FΑ 7 10+ years Walls - Plaster/Drywall SF 3rd Floor 974 6 10+ years



Catago	ry : Classroom		В	Building : Main			30 S ROCKWEII STREET, Chicago, IL 606
Jaleyo			В	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Walls - Plaster/Drywall	3rd Floor	80	SF	5	1-2 years	Cracking and peeling paint
	Work Sink	3rd Floor	1	EA	7	10+ years	Chacking and peeling paint
	Work Cirik			LA	,	for years	
lassroc	m #303 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	774	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	774	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	10+ years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	967	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
						2	
lassroc	m #305 (Regular Classroom) AC Units	3rd Floor	1		7	6-10 years	
		3rd Floor	1 54	EA LF	7		
	Casework				6	6-10 years	
	Ceiling - Lay-in	3rd Floor	720	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	710	SF	6	10+ years	- ···
	Floor - Tile	3rd Floor	10	SF	5	1-2 years	Cracking
	Lighting - Lay-in	3rd Floor	21	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	979	SF	6	10+ years	
lassroc	m #306 (Office)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,462	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	2	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Floor - Wood	3rd Floor	1,462	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	42	EA	7	10+ years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	28	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,440	SF	6	10+ years	
	-		1,440	0	0	ior years	
lassroc	m #307 (Computer Lab)			- ^			
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	970	SF	6	10+ years	



	tegory : Classroom 5630 S Rockwell STREET, Chicago, IL 60629 Building : Main						
Catego	ry : Classroom		B	uilding	: Main	_	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile	3rd Floor	970	SF	7	10+ years	
	Floor - Tile	3rd Floor	10	SF	5	1-2 years	Broken tile
	Lighting - Lay-in	3rd Floor	27	EA	7	10+ years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,120	SF	6	10+ years	
	Wireless System	3rd Floor	1	EA	7	6-10 years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #312 (Computer Lab)						
	AC Units	3rd Floor	4	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	703	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	703	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	ĒA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	882	SF	6	10+ years	
	Wireless System	3rd Floor	1	EA	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
Classroo	om #313 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	750	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	750	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	21	EA	7	10+ years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,007	SF	6	10+ years	
Classroo	om #314 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	749	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Water damage, crumbling plaster
	c				-	-	over window
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood Lighting - Lay-in	3rd Floor 3rd Floor	749 21	SF EA	7 7	10+ years 10+ years	



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments LF Marker Board 3rd Floor 20 6-10 years 7 3rd Floor 1.073 SF 6 Walls - Plaster/Drvwall 10+ years Work Sink 3rd Floor FΑ 5 1-2 years Missing hardware 1 Classroom #315 (Regular Classroom) AC Units 3rd Floor 1 FΑ 7 6-10 vears Casework 3rd Floor 8 LF 6 6-10 years SF Ceiling - Lay-in 3rd Floor 701 6 10+ years LF Chalk Board 3rd Floor 20 4 2-5 years Doors - Wood Doors inclu hw 3rd Floor 2 EΑ 6 10+ years Floor - Wood 701 SF 6 3rd Floor 10+ years Lighting - Lay-in 3rd Floor 21 EΑ 7 10+ years Marker Board 3rd Floor 25 LF 7 6-10 years SF Walls - Plaster/Drywall 3rd Floor 1.007 6 10+ years Classroom #316 (Regular Classroom) AC Units 3rd Floor ΕA 7 1 6-10 years Casework 3rd Floor 9 LF 6 6-10 years 3rd Floor SF Ceiling - Lav-in 749 6 10+ years Doors - Transom Window 3rd Floor 18 SF 6 10+ years Doors - Wood Doors inclu hw 3rd Floor 2 FΑ 6 10+ years SF Floor - Wood 3rd Floor 749 6 10+ years Lighting - Lay-in 3rd Floor 21 EA 7 10+ years Marker Board LF 7 6-10 years 3rd Floor 20 Walls - Plaster/Drywall 3rd Floor 1,073 SF 6 10+ years Classroom #317 (Science) 3rd Floor AC Units 1 ΕA 7 6-10 vears Casework 3rd Floor 94 LF 6 6-10 years 3rd Floor SF 6 Ceiling - Lay-in 1.105 10+ years Doors - Transom Window SF 6 6-10 years 3rd Floor 18 3 Doors - Wood Doors inclu hw 3rd Floor EΑ 6 10+ years Eve Wash Station 3rd Floor FΑ 6 1 10+ years Floor - Tile/Sheet SF 3rd Floor 1.105 7 10+ years Gas Line 3rd Floor 30 EΑ 10+ years 6 Lighting - Lav-in 3rd Floor 15 EΑ 7 10+ vears Marker Board LF 3rd Floor 9 7 6-10 years Science Lab Fume Hood 3rd Floor 1 ΕA 6 10+ years 3rd Floor ΕA 7 Science Lab Shower 1 10+ years 3rd Floor 85 SF 7 10+ years Storage/ Closet Walls - Plaster/Drywall 1.290 SF 3rd Floor 6 10+ years Work Sink 3rd Floor FΑ 7 10 10+ years



atego	ry : Classroom		В	Building : Main			
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
assroc	om #318 (Store Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	510	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	6	SF	4	1-2 years	Sagging tile
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	516	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	15	EA	7	10+ years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	905	SF	6	10+ years	
assroo	om #320 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	599	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	6	10+ years	
	Floor - Wood	3rd Floor	599	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	15	EA	7	10+ years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,030	SF	6	10+ years	
assror	om #321 (Science)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	73	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,008	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	2	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
	Eye Wash Station	3rd Floor	5	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,008	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	30	EA	7	10+ years	
	Marker Board	3rd Floor					
				EA	6	6-10 years	Lindotod quantity
	Science Lab Shower	3rd Floor	1	EA SF	7 7	10+ years	Updated quantity
	Storage/ Closet	3rd Floor	293			10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,270	SF	6	10+ years	l la dete d'au contitui
	Work Sink	3rd Floor	5	EA	7	10+ years	Updated quantity
assroc	om #322 (Science)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	84	LF	6	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,050	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	



Catego	ry : Classroom		R	uilding	• Main		30 S Rockwell STREET, Chicago, IL 6062	
Jacyo			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
oreup	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	Updated to match current	
			_		-	, ,	observations	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years		
	Floor - Wood	3rd Floor	1,050	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	30	EA	6	10+ years		
	Marker Board	3rd Floor	22	LF	6	6-10 years		
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	Updated quantity	
	Walls - Plaster/Drywall	3rd Floor	1,270	SF	6	10+ years		
	Work Sink	3rd Floor	5	EA	7	10+ years	Updated quantity	
Classroc	m #323 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	9	LF	6	6-10 years		
	Ceiling - Lay-in	3rd Floor	718	SF	6	6-10 years		
	Ceiling - Lay-in	3rd Floor	6	SF	4	1-2 years	Water damage	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years		
	Floor - Wood	3rd Floor	724	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	21	EA	7	10+ years		
	Marker Board	3rd Floor	20	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,007	SF	6	10+ years		
Classroc	m #324 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	3rd Floor	749	SF	6	10+ years		
	Doors - Side-lite	3rd Floor	18	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒA	6	10+ years		
	Floor - Wood	3rd Floor	749	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	21	EA	7	10+ years		
	Marker Board	3rd Floor	20	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,073	SF	6	10+ years		
Classroo	m #325 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	9	LF	6	6-10 years		
	Ceiling - Lay-in	3rd Floor	724	SF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	4	SF	4	1-2 years	Water damage	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	Updated to match current	
	Floor - Wood	3rd Floor	724	SF	6	10+ years	observations	
	Lighting - Lay-in	3rd Floor	21	EA	7	6-10 years		



Gage Park High School 5630 S Rockwell STREET, Chicago, IL 60629

Category : Classroom		В	uilding	: Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Plaster/Drywall	3rd Floor	1,007	SF	6	10+ years		
Classroc	m #326 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	9	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	749	SF	6	10+ years		
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years		
	Floor - Wood	3rd Floor	749	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	21	EA	7	10+ years		
	Marker Board	3rd Floor	20	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,073	SF	6	10+ years		
Classror	m #328 (Regular Classroom)							
21022100	AC Units	3rd Floor	1	EA	7	6-10 years		
	Ceiling - Lay-in	3rd Floor	710	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	20	SF	5	1-2 years	Water damage	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	water damage	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years		
	Floor - Wood	3rd Floor	730	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	21	EA LF	7	10+ years		
	Marker Board	3rd Floor	22	SF	7 6	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,016	SF	6	10+ years		
Classroc	m #330 (Choral Room)							
	AC Units	3rd Floor	2	EA	7	6-10 years		
	Ceiling - Splined	3rd Floor	1,620	SF	6	10+ years		
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years		
	Floor - Tile	3rd Floor	692	SF	6	10+ years		
	Floor - Tile	3rd Floor	8	SF	5	1-2 years	Broken tile, subfloor exposed	
	Floor - Wood	3rd Floor	920	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	30	ĒA	7	10+ years		
	Marker Board	3rd Floor	12	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	2,200	SF	6	10+ years		
0	-							
Jassroo	m #332 (Multi Purpose Room)			۲	7	0.40		
	AC Units	3rd Floor	2	EA	7	6-10 years		
	Casework	3rd Floor	100	LF	6	6-10 years		
	Ceiling - Splined	3rd Floor	1,620	SF	6	10+ years		
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years		
	Floor - Tile	3rd Floor	1,620	SF	6	10+ years		



Category : Classroom **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Lighting - Pendent/Surface 3rd Floor 30 ΕA 10+ vears 7 Marker Board 3rd Floor 46 LF 7 6-10 years Walls - Plaster/Drywall 3rd Floor 1.640 SF 6 10+ years Classroom #B01 (Carpentry) Ceiling - Exposed SF Basement 2.000 5 6-10 vears Doors - Wood Doors inclu hw Basement 2 FΑ 7 6-10 years SF Floor - Concrete Basement 2.000 7 10+ years ΕA Lighting - Pendent/Surface Basement 7 6-10 years 12 SF Walls - Concrete Block **Basement** 1,450 6 6-10 years Wood Shop Equipment ΕA 7 Basement 14 6-10 years **Category : Interior Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Corridor Ceiling - Plaster/Drywall 1st Floor 889 SF 6 10+ years Ceiling - Splined 1st Floor 7.742 SF 6 6-10 years SF Ceiling - Splined 1st Floor 1 5 10+ years Doors - Steel Doors incl hw FΑ 6 6-10 years 1st Floor 1 SF Doors - Transom Window 1st Floor 32 6 6-10 vears Doors - Wood Doors include hw 1st Floor 6 EΑ 6 6-10 years Doors - Wood Doors include hw 1st Floor 3 ΕA 5 2-5 years Drinking Fountains - Single Fountain 1st Floor 10 EΑ 5 2-5 years Floor - Terrazzo 1st Floor SF 7 1.476 10+ vears SF Floor - Tile/Sheet 1st Floor 6.926 7 10+ years Floor - Tile/Sheet 1st Floor 230 SF 5 2-5 vears 7 Lighting - Pendent/Surface 1st Floor 144 FΑ 2-5 years 7 Student Lockers - One Tier 459 ΕA 6-10 years 1st Floor SF Walls - Plaster/Drywall 1st Floor 7,817 6 10+ years SF Walls - Structural Glazed Tile 1st Floor 7,239 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 478 SF 6 10+ years SF Ceiling - Splined 2nd Floor 7.696 6 10+ years Doors - Steel Doors incl hw 2nd Floor 3 ΕA 6 6-10 years Drinking Fountains - Single Fountain 2nd Floor 7 FΑ 7 6-10 years Floor - Concrete 2nd Floor 478 SF 7 10+ vears Floor - Terrazzo SF 7 2nd Floor 770 10+ years Floor - Tile/Sheet 2nd Floor 6.826 SF 7 10+ years SF 5 Floor - Tile/Sheet 2nd Floor 100 1-2 years Cracking tiles Lighting - Pendent/Surface ΕA 7 2nd Floor 118 6-10 years Student Lockers - One Tier 2nd Floor 530 FΑ 6 6-10 years Walls - Plaster/Drvwall 2nd Floor 5.469 SF 6 10+ years SF Walls - Structural Glazed Tile 2nd Floor 7,239 6 10+ years SF Ceiling - Plaster/Drywall 3rd Floor 7.696 6 10+ years



	egory : Interior Building : Main							
Category : Interior			В	unaing	: wain	Decemand		
Group	Itom Turno	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Group	Item - Type Doors - Steel Doors incl hw	3rd Floor	Quantity 2	EA	6	10+ years	Comments	
	Doors - Transom Window	3rd Floor	18	SF	6	-		
	Drinking Fountains - Single Fountain	3rd Floor	10	EA	7	10+ years 10+ years	Indeted to moteb ourrest quantity	
	Floor - Terrazzo	3rd Floor	770	SF	7	10+ years	Updated to match current quantity	
	Floor - Tile/Sheet	3rd Floor	7,126	SF	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	118	EA	7	10+ years		
	Student Lockers - One Tier	3rd Floor	530	EA	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	4,815	SF	7	10+ years		
	Walls - Structural Glazed Tile	3rd Floor	7,239	SF	6	10+ years		
	Walls - Structural Glazed The	310 FI001	1,239	36	0	10+ years		
Safety								
	Camera Viewing Station	1st Floor	4	EA	7	2-5 years		
	Metal Detector	1st Floor	3	EA	7	2-5 years		
	Security Cameras	1st Floor	45	EA	7	2-5 years		
	Security Cameras	1st Floor	9	EA	7	2-5 years		
	Security Cameras	1st Floor	1	EA	7	2-5 years		
Stairs								
	Ceiling - Exposed	Boys Locker Room Stair	119	SF	6	10+ years		
	Floor - Terrazzo	Boys Locker Room Stair	58	SF	7	10+ years		
	Handrails	Boys Locker Room Stair	64	LF	7	6-10 years		
	Lighting - Pendent/Surface	Boys Locker Room Stair	2	EA	6	6-10 years	Re-lamp fixture	
	Stairs - Terrazzo	Boys Locker Room Stair	26	LF	7	10+ years		
	Walls - Structural Glazed Tile	Boys Locker Room Stair	900	SF SF	6	10+ years		
	Ceiling - Splined	East Stairs (B)	524	SF SF	6	10+ years		
	Floor - Terrazzo	East Stairs (B) East Stairs (B)	292 114	SF LF	7 7	10+ years		
	Handrails Lighting - Pendent/Surface	East Stairs (B)	6	EA	7	6-10 years		
	Stairs - Terrazzo	East Stairs (B)	57		7	6-10 years 10+ years		
	Walls - Plaster/Drywall	East Stairs (B)	1,374	SF	6			
	Walls - Flaster/Drywall Walls - Structural Glazed Tile	East Stairs (B)	1,050	SF	6	10+ years 6-10 years		
	Ceiling - Plaster/Drywall	Engineering Corridor (E)	156	SF	6	10+ years		
	Floor - Terrazzo	Engineering Corridor (E)	85	SF	7	10+ years		
	Handrails	Engineering Corridor (E)	124	LF	7	6-10 years		
	Lighting - Wall Mounted	Engineering Corridor (E)	3	EA	7	6-10 years		
	Stairs - Terrazzo	Engineering Corridor (E)	62	LF	7	10+ years		
	Walls - Plaster/Drywall	Engineering Corridor (E)	1,047	SF	6	10+ years		
	Walls - Plaster/Drywall	Engineering Corridor (E)	86	SF	5	1-2 years	Minor cracking and water damage	
	Ceiling - Plaster/Drywall	Girls Locker Room Stair	119	SF	6	10+ years	which blacking and water damage	
	Floor - Terrazzo	Girls Locker Room Stair	58	SF	7	10+ years		
	Handrails	Girls Locker Room Stair	64	LF	7	6-10 years		
	Lighting - Pendent/Surface	Girls Locker Room Stair	2	EA	7	6-10 years		
	Stairs - Terrazzo	Girls Locker Room Stair	26	LF	7	6-10 years		
	Walls - Structural Glazed Tile	Girls Locker Room Stair	900	SF	7	10+ years		
			500	5	'	ior yours		



Building : Main Category : Interior Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Ceiling - Plaster/Drvwall North East Stair (C) 494 SF 10+ vears 6 Ceiling - Plaster/Drywall North East Stair (C) 6 SF 4 0-1 year Water damage, ceiling missing pierces of plaster 275 SF 7 Floor - Terrazzo North East Stair (C) 10+ years LF Handrails North East Stair (C) 120 7 6-10 years Lighting - Pendent/Surface 7 6-10 years North East Stair (C) 6 EΑ Stairs - Terrazzo North East Stair (C) 60 LF 7 10+ years SF Walls - Plaster/Drywall North East Stair (C) 1.220 6 10+ years Walls - Plaster/Drywall North East Stair (C) 50 SF 5 1-2 years Cracking, minor water damage SF Walls - Structural Glazed Tile North East Stair (C) 6 6-10 vears 1.100 SF Ceiling - Plaster/Drvwall North Stair (D) 497 6 10+ vears Floor - Terrazzo North Stair (D) 264 SF 7 10+ years Handrails North Stair (D) 109 LF 7 6-10 years ΕA 7 Lighting - Pendent/Surface North Stair (D) 6 6-10 years Stairs - Terrazzo 58 LF 7 North Stair (D) 10+ years Walls - Plaster/Drywall SF North Stair (D) 1.210 6 10+ years SF Walls - Structural Glazed Tile North Stair (D) 1.050 6 6-10 years SF Ceiling - Plaster/Drvwall South East Stair (A) 468 6 10+ years Ceiling - Plaster/Drywall SF South East Stair (A) 30 5 1-2 vears Water damage Floor - Terrazzo SF South East Stair (A) 265 7 10+ years Handrails South East Stair (A) 109 LF 7 6-10 years ΕA 7 Lighting - Pendent/Surface South East Stair (A) 6 6-10 years LF 7 Stairs - Terrazzo South East Stair (A) 58 10+ years SF Walls - Plaster/Drywall South East Stair (A) 1,235 6 10+ years Walls - Plaster/Drvwall SF 5 1-2 vears South East Stair (A) 30 Water damage Walls - Structural Glazed Tile SF South East Stair (A) 1.000 6 6-10 vears SF Ceiling - Lay-in South Stairs (H) by 306 244 6 10+ years Floor - Terrazzo South Stairs (H) by 306 SF 7 48 10+ years LF Handrails South Stairs (H) by 306 52 7 6-10 years Lighting - Pendent/Surface South Stairs (H) by 306 5 ΕA 7 6-10 years LF Stairs - Terrazzo South Stairs (H) by 306 26 7 10+ vears SF Walls - Plaster/Drvwall South Stairs (H) by 306 684 6 10+ vears Ceiling - Plaster/Drywall SF South West Stair (G) 500 6 10+ years Floor - Terrazzo South West Stair (G) 265 SF 7 10+ vears LF Handrails South West Stair (G) 109 5 6-10 years Lighting - Pendent/Surface ΕA 7 South West Stair (G) 6 2-5 years LF Stairs - Terrazzo South West Stair (G) 58 7 10+ years Walls - Plaster/Drywall SF South West Stair (G) 1,275 6 10+ years SF Walls - Structural Glazed Tile South West Stair (G) 1.000 6 6-10 years Vertical Conveyance Elevator - Freight Elevator 1st Floor 1 ΕA 4 1-2 years Freight elevator always breaking down



Category : Site			В	uilding				
				Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Athletic								
	Surface - Natural	Entire Site	82,516	SF	6	10+ years		
Civil/Drai	nage							
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	7	10+ years	Repaired	
	Civil/ Drainage - Catch Basin	Entire Site	8	EA	6	10+ years	-	
	Civil/ Drainage - Site Manhole	Entire Site	22	EA	6	10+ years		
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	6	10+ years	Repaired	
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	4	1-2 years	Broken cover	
Fencing								
	Fencing - Chain Link	Entire Site	1,320	LF	6	2-5 years		
	Fencing - Guard Rail	Entire Site	90	LF	7	10+ years		
	Fencing - New Standard Ornamental	Entire Site	1,469	LF	6	10+ years		
	Fencing - New Standard Ornamental	Entire Site	30	LF	5	1-2 years	Fence and post, and gate damaged	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	97	LF	6	6-10 years	out of shape	
			57	LI	0	o to years		
andsca								
	Benches	Entire Site	7	EA	6	6-10 years		
	Landscape - Grass	Entire Site	91,532	SF	6	10+ years		
	Parkway trees	Entire Site	52	EA	6	10+ years	The second	
	Parkway trees	Entire Site	15	EA	4	1-2 years	Trees are missing from the parkway	
	Planting Beds/ Area	Entire Site	5,525	SF	6	6-10 years	On alle dub nations natainin a coall	
	Retaining Wall - Concrete	Entire Site	30	SF	5	1-2 years	Spalled, broken retaining wall	
	Retaining Wall - Masonry	Entire Site	50	SF	5	1-2 years	Crumbled stone	
	Trash Receptacles	Entire Site	2	EA	6	10+ years		
Parking I								
	Lighting - Pole Mounted	Drivers Ed Lot	6	EA	6	10+ years		
	Surface - Asphalt	Drivers Ed Lot	32,600	SF	6	10+ years	Verified sf	
	Surface - Asphalt	Drivers Ed Lot	400	SF	5	1-2 years	Potholes, alligatoring	
	Concrete Curbs	N & NE parking lots	350	LF	6	10+ years		
	Surface - Asphalt	N & NE parking lots	1,000	SF	7	10+ years	Repaired	
	Surface - Asphalt	N & NE parking lots	40,853	SF	6	6-10 years		
	Surface - Asphalt	N & NE parking lots	150	SF	5	10+ years	Repaired	
	Surface - Concrete	N & NE parking lots	250	SF	4	1-2 years	Disintegrated concrete surface	
	Concrete Curbs	Parking Lot- West	360	LF	7	10+ years		
	Interior Plantings	Parking Lot- West	20	LF	6	6-10 years		
	Interior Plantings	Parking Lot- West	40	LF	4	1-2 years	Dead trees	
	Lighting - Pole Mounted	Parking Lot- West	3	EA	7	10+ years		
	Surface - Asphalt	Parking Lot- West	10,000	SF	7	10+ years	New	



Building : Site Category : Site Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Surface - Asphalt Parking Lot-West 20.782 SF 6 6-10 years Surface - Asphalt Parking Lot- West 100 SF 5 1-2 years Potholes, large cracks Surface - Concrete Parking Lot- West 1.188 SF 6 10+ years Trash Enclosure - Wood Parking Lot- West 586 SF 4 2-5 years Rotting fence SF Trash Enclosure - Wood Parking Lot-West 50 4 1-2 years Damaged, broken wood fence Sidewalks LF Sidewalks - Internal Walks Entire Site 2,281 6 10+ years LF Sidewalks - Internal Walks Entire Site 500 4 1-2 years Broken sidewalk, spalled sidewalk SF Sidewalks - Perimeter Sidewalks Entire Site 20,614 6 10+ years Sidewalks - Perimeter Sidewalks Entire Site 4,000 SF 1-2 years 4 Upheaved cracked, disintegrated, spalled concrete Signage Flag Pole - Flag Pole North 1 EΑ 6 10+ years Marguee - Free Standing Back lighted w/ North 1 ΕA 7 6-10 years LED 3 Monument - Building Mounted Cut Letter EA 6 10+ years North Sign

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

•			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	Composition	Decement	D01	D04	0.000	0	0	1	
Carpentry	Carpentry	Basement	B01	B01	2,000	0	0	N	
Choral Room	Choral Room	3rd Floor	330	330	1,620	392	224	N	N
Computer Lab	Regular Classroom	2nd Floor	221	221	1,071	198	90	N	Y
Computer Lab	Regular Classroom	3rd Floor	307	307	970	176	80	N	Y
Computer Lab	Regular Classroom	3rd Floor	312	312	703	112	50	N	N
Faculty Lounge	Regular Classroom	1st Floor	126	126	732	132	60	N	N
Multi Purpose Room	Band Room	3rd Floor	332	332	1,620	392	224	N	N
Multi Purpose Room	Regular Classroom	2nd Floor	222	222	648	73	38	N	N
Office	Regular Classroom	2nd Floor	220	220	602	73	38	N	N
Office	Regular Classroom	3rd Floor	306	306	1,462	54	22	N	N
Other Instructional Use	Office	1st Floor	124	124	408	105	30	N	Y
Other Instructional Use	Regular Classroom	2nd Floor	205	205	959	176	80	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	826	245	70	N	Y
Regular Classroom	Regular Classroom	1st Floor	107	107	713	210	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	115	115	864	210	60	N	Y
Regular Classroom	Regular Classroom	1st Floor	121	121	864	210	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	723	132	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	735	121	49	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	959	176	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	727	104	45	N	Y
Regular Classroom	Regular Classroom	2nd Floor	214	214	727	112	49	N	Y
Regular Classroom	Regular Classroom	2nd Floor	216	216	733	112	49	N	Y
Regular Classroom	Regular Classroom	2nd Floor	224	224	733	112	49	N	N
Regular Classroom	Regular Classroom	2nd Floor	226	226	727	112	49	N	Y
Regular Classroom	Regular Classroom	2nd Floor	228	228	727	104	45	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	774	143	50	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	305	305	720	143	53	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	313	313	750	121	66	N	Y
Regular Classroom	Regular Classroom	3rd Floor	314	314	727	112	50	N	Ý
Regular Classroom	Regular Classroom	3rd Floor	315	315	701	132	60	N	Ý
Regular Classroom	Regular Classroom	3rd Floor	316	316	749	112	50	N	Ý
Regular Classroom	Regular Classroom	3rd Floor	320	320	599	76	34	N	Ý
Regular Classroom	Regular Classroom	3rd Floor	323	323	724	121	50	N	Y
Regular Classroom	Regular Classroom	3rd Floor	323	324	749	154	70	N	N N
Regular Classroom	Regular Classroom	3rd Floor	325	325	743	121	50	N	N
Regular Classroom	Regular Classroom	3rd Floor	325	326	749	154	75	N	N
Regular Classroom	Regular Classroom	3rd Floor	328	328	749	112	49	N	N
Regular Classroom Regular Classroom		1st Floor	103	328 103	1,874	420	49 120	N N	N
Regular Classroom	Science	IST FIOOF	103	103	1,874	420	120	IN	IN



Classroom Summary

	101
5630 S Rockwell STREET, Chicago, IL 60	629

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Science	2nd Floor	213	213	701	132	60	N	N
Regular Classroom	Science	2nd Floor	215	215	701	132	60	N	N
Regular Classroom	Special Education	1st Floor	113	113	360	105	30	N	Y
Science	Science	2nd Floor	217	217	1,116	198	89	N	Y
Science	Science	3rd Floor	317	317	1,105	176	70	N	N
Science	Science	3rd Floor	321	321	1,008	144	63	N	N
Science	Science	3rd Floor	322	322	1,050	144	63	N	Y
Special Program	Regular Classroom	2nd Floor	218	218	518	72	32	N	N
Special Program	Science	2nd Floor	225	225	1,116	176	60	N	N
Store Room	Regular Classroom	3rd Floor	301	301	814	143	60	N	Ν
Store Room	Regular Classroom	3rd Floor	318	318	516	80	36	N	Y