

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1937	2	60,700
Addition	1961	2	30,600
Campus Total			91,300

Category : Exterior Building : Main

Catego	Ty . Exterior		unung	. IVICIII			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	71	Location	Quantity	OOW	Naiik	Replacement	Comments
Entrance		#4 Main \M	4	ΓΛ		40	Chairmand to martch assument
	Entrance Control - Audio and Video	#1 - Main - W	1	EA	6	10+ years	Changed to match current observations
	Exterior Doors - Exterior Steel Door	#1 - Main - W	2	EΑ	4	1-2 years	Corroded at the bottom
	Exterior Doors - Transom Lite	#1 - Main - W	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#1 - Main - W	78	LF	6	10+ years	
	Exterior Stairs - Stone	#1 - Main - W	6	LF	5	6-10 years	
	Entrance Control - Audio and Video	#2 - SW	1	EA	7	10+ years	
	Exterior Doors - Exterior Wood Door	#2 - SW	2	EA	4	0-1 year	Deteriorating. Does not lock properly
	Exterior Doors - Transom Lite	#2 - SW	1	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	#2 - SW	100	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#2 - SW	260	LF	7	10+ years	
	Ramps - Concrete	#2 - SW	110	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#2 - SW	24	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	#5.1 - SE	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#5.1 - SE	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	#5.1 - SE	50	LF	5	0-1 year	Cracking/chipping/missing pieces
	Stair Handrail - Steel_Stair Handrail	#5.1 - SE	45	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5.2 - E	1	EA	4	1-2 years	Corroded
	Exterior Doors - Exterior Steel Door	#5.3 - E	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5.3 - E	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#5.3 - E	44	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	#5.3 - E	50	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#6 - NE	2	EA	4	1-2 years	Corroded/does not lock properly



Catego	ry : Exterior		В	uilding	: Main		-
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Transom Lite	#6 - NE	1	EA	5	6-10 years	
	Exterior Stairs - Concrete	#6 - NE	80	LF	6	10+ years	
	Exterior Stairs - Concrete	#6 - NE	20	LF	4	1-2 years	Separated from the wall
	Exterior Stairs - Stone	#6 - NE	6	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#7- NE	2	EΑ	4	0-1 year	Corroded/does not lock properly
	Exterior Doors - Transom Lite	#7- NE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#7- NE	90	LF	6	10+ years	
	Exterior Stairs - Concrete	#7- NE	10	LF	4	1-2 years	Large gap/cracking between the first two steps
	Exterior Stairs - Stone	#7- NE	6	LF	6	10+ years	two steps
	Exterior Doors - Exterior Steel Door	#8 - NW	2	EΑ	7	10+ years	Newly replaced
	Exterior Doors - Transom Lite	#8 - NW	1	ĒΑ	6	10+ years	,,
	Exterior Stairs - Concrete	#8 - NW	218	LF	5	6-10 years	
	Exterior Stairs - Stone	#8 - NW	6	LF	6	10+ years	
Foundat	ion						
	Foundation - Concrete	Entire Building	5	LF	6	10+ years	
	Foundation - Concrete	Entire Building	795	LF	6	10+ years	
	Foundation - Concrete	Entire Building	20	LF	5	1-2 years	Cracking in the hallway. Seepage in
	Superstructure - Concrete	Entire Building	52,643	SF	7	10+ years	the basement
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	3	EA	6	6-10 years	Fixed
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	7	10+ years	Newly replaced
Roof Sy	stem						
_	Access Ladder - Metal	Main Roof	3	EA	7	10+ years	
	Access Ladder - Wood	Main Roof	3	EA	5	1-2 years	Homemade/not supported
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	51	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	61	LF	5	6-10 years	
	Chimney - Metal Flue	Main Roof	26	LF	6	6-10 years	
	Coping - Stone	Main Roof	1,142	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	216	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	728	LF	5	10+ years	
	Parapet - 16" - 30" Height	Main Roof	120	LF	4	0-1 year	Deteriorating/displaced
	Parapet - Parapet > 30"	Main Roof	294	LF	4	1-2 years	Open joints/cracking/displaced
	Roof - Asphalt Gravel Ballast	Main Roof	21,222	SF	3	0-1 year	Soft spots/bubbling/cracking
					-	-	throughout
	Roof Hatch - Metal	Main Roof	3	EA	7	10+ years	

Campus Name: Gillespie Page : 2 of 41 Assessment Date: 03/04/2024



atego	ry : Exterior		В	uilding	: Main		
	•					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Roof Structure - Steel with Clay Tile Arch	Main Roof	21,222	SF	7	10+ years	
	Access Ladder - Wood	Mid N roof	, 1	ĒΑ	4	1-2 years	Changed to match current
						,	observations Handmade/not
							supported
	Coping - Stone	Mid N roof	155	LF	6	10+ years	
	Downspouts - Interior Downspouts	Mid N roof	58	LF	6	10+ years	
	Parapet - 16" - 30" Height	Mid N roof	155	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Mid N roof	3,556	SF	3	0-1 year	Soft spots/bubbling/cracking
	•		•			,	throughout
	Roof Hatch - Metal	Mid N roof	1	EA	7	10+ years	ŭ
	Roof Structure - Steel with Clay Tile Arch	Mid N roof	3,556	SF	7	10+ years	
	,		-,	-		, , , , , , , , , , , , , , , , , , , ,	
/alls							
	Cheek-Wall - Stone	Entire Building	112	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	100	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	80	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	112	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	80	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	12	SF	5	1-2 years	Cracking
	Exterior Walls - Brick	Entire Building	21,011	SF	6	10+ years	3
	Exterior Walls - Brick	Entire Building	20	SF	5	1-2 years	Spalled
	Exterior Walls - Brick	Entire Building	40	SF	5	1-2 years	Open joints/displayed bricks
	Exterior Walls - Brick	Entire Building	5,000	SF	5	10+ years	. , ,
	Exterior Walls - Brick	Entire Building	500	SF	4	1-2 years	Open joints
	Exterior Walls - Prefabricated Metal Panel	Entire Building	160	SF	6	10+ years	,
	Wall	ŭ				,	
	Exterior Walls - Stone-Cast	Entire Building	2,460	SF	5	10+ years	
		ű	,			,	
indows							
	Curtain wall - Insulated Panel	Entire Building	1,090	SF	5	6-10 years	
	Guard - Guards perforated	Entire Building	1,760	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	20	SF	6	10+ years	
	Lintels - Steel	Entire Building	316	LF	6	10+ years	
	Lintels - Steel	Entire Building	15	LF	4	1-2 years	Corroded
	Lintels - Steel	Entire Building	40	LF	4	1-2 years	Corroded
	Lintels - Stone	Entire Building	346	LF	6	10+ years	
	Windows - Sash Lexan	Entire Building	2,840	SF	5	6-10 years	
	Windows - Sash Lexan	Entire Building	1,000	SF	5	1-2 years	Bad balancers
atego	ry : Electrical		В	uilding	: Main		
				. 9		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	cy System						



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Automatic Transfer Switch	Basement	1	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	22	EΑ	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	9,043	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	2,909	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	892	SF	6	6-10 years	
	Security System - CCTV	Entire Building	60,700	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	60,700	SF	6	6-10 years	
	Emergency Generator- Outdoor- Diesel - Below 60 KW	Site - East	1	EA	6	6-10 years	
ain Sei	vice						
	PA System	1st Floor	60,700	SF	7	6-10 years	
	Main Electrical Service - 1600 A 120/240/3PH	Electrical Room	1	EA	6	6-10 years	
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building Entire Building	1	EA	6	6-10 years	
			1		-		
	Main Distribution Panels - 400 - 600 amp Main Distribution Panels - Greater than 600	Entire Building Entire Building	1	EA EA	6 6	6-10 years 6-10 years	
	amp	Limito Dullaling	1	LA	5	o To years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	6	6-10 years	
atego	ry : Fire Protection		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Jup	nem - Type	Location	Quantity	OOW	Italik	Replacement	Comments



ategor	y : Fire Protection		В	uilding	: Main		
	_			11611		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire ALarm Anunciator	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	60,700	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	60,700	SF	6	6-10 years	
ategoi	y : Mechanical		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ing Systems					Порисоннени	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Basement	1	EA	6	6-10 years	AHU-2
	Air Intake	Basement	1	EA	4	0-1 year	Dampers are not open and close properly. Propped open.
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	2-5 years	proporty. I Topped open.
	Return Duct Work - Indoor- Vertical Shaft	Basement	200	LF	6		
	and Ducts	basement		LF	0	6-10 years	
	Zone Dampers	Basement	15	EA	6	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU-1
	Air Intake	Mechanical Room	1	EA	4	0-1 year	Dampers are not open and close properly. PO in place for repair.
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	6-10 years	property • prace to repain
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	200	LF	6	6-10 years	
	Zone Dampers	Mechanical Room	15	EA	6	6-10 years	
	Outdoor Return Fans- Air Handling Unit	Roof	1	EA	6	6-10 years	
	Type - 10001 - 20000 CFM		·			-	
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	6-10 years	Operational, per engineer
iler Sy	stems						
·	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	6	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	7	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	7	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	
	Condensate Pump	Boiler Room	1	EA	7	10+ years	2022 install
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	2022 Hotali
			1	EA			
	Condensate Pump	Boiler Room	1		6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EΑ	5	2-5 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	6	6-10 years	

Campus Name: Gillespie Page : 5 of 41 Assessment Date: 03/04/2024



Categor	W · Machanical		R	uilding	· Main		
_	y : Mechanical		<u> </u>	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
O. Gup	Piping - Condensate Pipe- Steel	Boiler Room	2,200	LF	5	2-5 years	
	Piping - Steam Pipe- Steel	Boiler Room	2,200	LF	5	2-5 years	
	Steam Traps	Boiler Room	50	EA	6	6-10 years	
	Vacuum Pump	Boiler Room	2	EA	6	6-10 years	Vacuum pump works in concert with
	vacuum rump	Bollet Room	2	LA	U	0-10 years	condensate system
Gas Boos	ster						
	Gas Booster	Boiler Room	1	EA	6	6-10 years	
Heating D	Devices						
	Fin Tube - Steam	2nd Floor	25	LF	6	6-10 years	
	Wall Heater - Electric	Entire Building	13	EA	6	6-10 years	
	Radiators - Steam	Entire Building	12	EA	5	2-5 years	Needs to be painted. Repairs on
	radiatoro Glodini	Entire Ballating	12		Ü	2 o youro	controls.
	Unit Heater - Steam	Entire Building	1	EA	6	6-10 years	controlo.
Tempera	ture Control						
	DDC System	Entire Building	60,700	SF	6	6-10 years	Upgraded
	Hybrid Pneumatic/DDC System	Entire Building	1	SF	4	0-1 year	Not not connected to system does no work properly. Running manually off
	Thermostats - DDC	Entire Building	40	EA	4	0-1 year	of two compressors. Thermostat not working, leaking air. Most are broken, some are missing
<u>Ventilatio</u>	n						
	Roof Mounted Duct Work	Main Roof	114	LF	6	6-10 years	
Categor	y : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	r						
	Gas Heater - Greater than 600000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
	Hot Water Storage Tank_Gas - 201 - 500	Boiler Room	1	EA	6	6-10 years	
	Gallons					,	
Piping							
. •	Domestic Piping-Hot Water Return Lines	Entire Building	60,700	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	60,700	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	60,700	SF	6	6-10 years	
	Fixtures		33,. 00	٠.	-	- 1- ,00.0	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	60,700	SF	6	6-10 years	



Catego	ry : Plumbing		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	60,700	SF	6	6-10 years		
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	60,700	SF	6	6-10 years		
	Sanitary Piping	Entire Building	60,700	SF	6	6-10 years		
	Storm Piping	Entire Building	60,700	SF	6	6-10 years		
	Vent Piping	Entire Building	60,700	SF	6	6-10 years		
Pumps								
•	Pumps - Domestic Booster Pump-Duplex	Boiler Room	1	EA	6	6-10 years		
	Pumps - Sump-Duplex	Boiler Room	1	EA	6	6-10 years		
	Pumps - Sump-Duplex	Boiler Room	1	EA	6	6-10 years		

Category : Room **Building: Main**

	. ,			w			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	AC Unit	1st Floor - Assistant Principle 152	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Assistant Principle 152	351	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Assistant Principle 152	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Assistant Principle 152	351	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Assistant Principle 152	2	EA	7	10+ years	
	Power Distribution	1st Floor - Assistant Principle 152	4	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Assistant Principle 152	951	SF	7	10+ years	
	AC Unit	1st Floor - Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Main Office	434	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Main Office	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Main Office	2	EA	7	10+ years	
	Floor - Carpet	1st Floor - Main Office	234	SF	7	6-10 years	
	Floor - Tile	1st Floor - Main Office	200	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Main Office	7	EA	7	10+ years	
	Power Distribution	1st Floor - Main Office	10	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Main Office	1,411	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Main Office	5	SF	6	10+ years	
	AC Unit	1st Floor - Principal 100	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Principal 100	301	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Principal 100	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Principal 100	1	EA	7	10+ years	
	Floor - Wood	1st Floor - Principal 100	301	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Principal 100	4	EA	7	10+ years	
	Power Distribution	1st Floor - Principal 100	4	EA	7	10+ years	
	Storage/ Closet	1st Floor - Principal 100	20	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Principal 100	882	SF	7	10+ years	
	AC Unit	1st Floor - Principal 150A	1	EA	7	6-10 years	

Campus Name: Gillespie Page : 7 of 41 Assessment Date: 03/04/2024



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor - Principal 150A	132	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Principal 150A	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Principal 150A	1	EΑ	7	10+ years	
	Floor - Carpet	1st Floor - Principal 150A	132	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor - Principal 150A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Principal 150A	1	EΑ	6	10+ years	
	Power Distribution	1st Floor - Principal 150A	4	EΑ	7	10+ years	
	Storage/ Closet	1st Floor - Principal 150A	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Principal 150A	558	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - Case Manager 250	307	SF	7	10+ years	
	Doors - Transom Window	2nd Floor - Case Manager 250	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Case Manager 250	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor - Case Manager 250	297	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor - Case Manager 250	10	SF	4	0-1 year	Damaged floor
	Lighting - Pendent/Surface	2nd Floor - Case Manager 250	2	EA	7	10+ years	Damaged 11001
	Lighting - Pendent/Surface	2nd Floor - Case Manager 250 2nd Floor - Case Manager 250	1	EA	5	1-2 years	Missing cover
	Power Distribution	2nd Floor - Case Manager 250 2nd Floor - Case Manager 250	4	EA	7	•	wissing cover
	Walls - Plaster/Drywall	2nd Floor - Case Manager 250 2nd Floor - Case Manager 250		SF	7	10+ years	
			1,299	SF SF		10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - Counselor 250 (4)	222		7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Counselor 250 (4)	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor - Counselor 250 (4)	222	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor - Counselor 250 (4)	4	EA	7	10+ years	
	Power Distribution	2nd Floor - Counselor 250 (4)	4	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Counselor 250 (4)	230	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor - Counselor 250 (4)	15	SF	7	10+ years	
	Work SInk	2nd Floor - Counselor 250 (4)	1	EA	7	10+ years	
	AC Unit	2nd Floor - Nurse 250 (2)	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Nurse 250 (2)	58	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Nurse 250 (2)	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor - Nurse 250 (2)	48	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor - Nurse 250 (2)	10	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor - Nurse 250 (2)	2	EA	7	10+ years	
	Power Distribution	2nd Floor - Nurse 250 (2)	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Nurse 250 (2)	186	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Psychologist 250 (1)	67	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Psychologist 250 (1)	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor - Psychologist 250 (1)	67	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor - Psychologist 250 (1)	1	EΑ	7	10+ years	
	Power Distribution	2nd Floor - Psychologist 250 (1)	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Psychologist 250 (1)	132	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - Social Worker 250 (3)	54	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - Social Worker 250 (3)	5	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor - Social Worker 250 (3)	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor - Social Worker 250 (3)	49	SF	7	10+ years	
		=::0: 255:0: 1:5:::0: 255 (0)	.0	•	•	,	

Campus Name: Gillespie Page : 8 of 41 Assessment Date: 03/04/2024



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	2nd Floor - Social Worker 250 (3)	10	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor - Social Worker 250 (3)	2	EA	7	10+ years	
	Power Distribution	2nd Floor - Social Worker 250 (3)	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Social Worker 250 (3)	188	SF	7	10+ years	
	AC Unit	Basement - Engineer	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Engineer	119	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - Engineer	5	SF	4	0-1 year	Water damaged
	Doors - Wood Doors inclu hw	Basement - Engineer	1	EA	7	10+ years	
	Floor - Tile	Basement - Engineer	124	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement - Engineer	1	EA	7	10+ years	
	Power Distribution	Basement - Engineer	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - Engineer	415	SF	7	10+ years	
Gymnas	ia						
	Ceiling - Plaster/Drywall	1st Floor - Gym	2,900	SF	7	10+ years	Repaired
	Doors - Wood Doors inclu hw	1st Floor - Gym	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Gym	2,895	SF	7	10+ years	
	Floor - Tile	1st Floor - Gym	5	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	1st Floor - Gym	10	EA	7	10+ years	Damagoa moo
	Lighting - Pendent/Surface	1st Floor - Gym	2	EA	6	6-10 years	
	Power Distribution	1st Floor - Gym	2	EΑ	7	10+ years	
	Stage	1st Floor - Gym	400	SF	6	2-5 years	
	Stage Curtain	1st Floor - Gym	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor - Gym	6	LF	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor - Gym	507	SF	6	6-10 years	
Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	25	SF	7	10+ years	
	Janitor's Closet	1st Floor	49	SF	7	10+ years	
	Storage Room	1st Floor	249	SF	7	10+ years	
	Storage Room	1st Floor	49	SF	7	10+ years	
	Storage Room	1st Floor	83	SF	7	10+ years	
	Vaults	1st Floor	93	SF	7	10+ years	
	Janitor's Closet	2nd Floor	52	SF	7	10+ years	
	Janitor's Closet	2nd Floor	25	SF	7	10+ years	
	Storage Room	2nd Floor	191	SF	7	10+ years	Locked-Engineer has no access to
	Boiler Room	Basement	1,406	SF	7	10+ years	
	Coal Room	Basement	522	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	27,134	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	4,438	SF	7	10+ years	
	Storage Room	Basement	96	SF	7	10+ years	
	Storage Room	Basement	40	SF	7	10+ years	
	2.2.390 (.00	Bassmont	10	٥.	•	io. youro	



Category : Room			В	uilding	: Main		•
				J		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
estrooi	n						
	Accessories	1st Floor - Inside 102	119	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Inside 102	119	SF	7	10+ years	
	Doors - Side-lite	1st Floor - Inside 102	16	SF	7	10+ years	
	Doors - Transom Window	1st Floor - Inside 102	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Inside 102	2	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor - Inside 102	86	SF	7	10+ years	
	Floor - Tile	1st Floor - Inside 102	5	SF	4	0-1 year	Cracked tiles
	Floor - Tile Ceramic/ Porcelain	1st Floor - Inside 102	28	SF	6	10+ years	
	Lavatory	1st Floor - Inside 102	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Inside 102	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Inside 102	723	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Inside 102	5	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - Inside 102	25	SF	7	10+ years	
	Water Closet	1st Floor - Inside 102	1	EA	7	10+ years	
	Accessories	1st Floor - Men	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Men	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Men	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Men	28	SF	7	10+ years	
	Lavatory	1st Floor - Men	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Men	1	EA	7	10+ years	
	Partitions	1st Floor - Men	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Men	189	SF	6	10+ years	
	Water Closet	1st Floor - Men	103	EA	7	10+ years	
	Accessories	1st Floor - North	237	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - North	237	SF	7	10+ years	
	Doors - Transom Window	1st Floor - North	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - North	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - North	237	SF	7	10+ years	
	Floor Drain	1st Floor - North	1	EA	7	10+ years	
		1st Floor - North	2	EA	7	10+ years	
	Lavatory Lighting - Pendent/Surface	1st Floor - North	4	EA	7	10+ years	
	Partitions	1st Floor - North	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - North	30	SF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor - North	120	SF	6		
		1st Floor - North		SF SF	7	10+ years	
	Walls - Structural Glazed Tile Walls - Structural Glazed Tile	1st Floor - North 1st Floor - North	729 15	SF SF	<i>7</i> 5	10+ years	Cracked tile
	Walls - Structural Glazed Tile Walls - Tile Ceramic/ Porcelain	1st Floor - North	22	SF SF	5 7	1-2 years	Cracked life
						10+ years	
	Water Closet	1st Floor - North	6	EA	7	10+ years	
	Accessories	1st Floor - North	206	SF SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - North	194		7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - North	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - North	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - North	206	SF	7	10+ years	

Campus Name: Gillespie Page : 10 of 41 Assessment Date: 03/04/2024



Catego	ry : Room	<u> </u>	В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	1st Floor - North	1	EA	7	10+ years	
	Lavatory	1st Floor - North	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - North	3	EΑ	7	10+ years	
	Partitions	1st Floor - North	2	EΑ	7	10+ years	
	Urinals	1st Floor - North	4	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - North	122	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - North	518	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - North	42	SF	7	10+ years	
	Water Closet	1st Floor - North	1	ĒΑ	7	10+ years	
	Accessories	1st Floor - Principal 100	27	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Principal 100	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Principal 100	 1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Principal 100	27	SF	7	10+ years	
	Lavatory	1st Floor - Principal 100	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Principal 100	1	EA	7	10+ years	
	Partitions	1st Floor - Principal 100	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Principal 100	240	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Principal 100	6	SF	6	10+ years	
	Water Closet		1	EA			
		1st Floor - Principal 100	=	SF	7 7	10+ years	
	Accessories	1st Floor - Principal in Main Office	18			6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Principal in Main Office	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Principal in Main Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Principal in Main Office	18	SF	7	10+ years	
	Lavatory	1st Floor - Principal in Main Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Principal in Main Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Principal in Main Office	216	SF	7	10+ years	
	Water Closet	1st Floor - Principal in Main Office	1	EA	7	10+ years	
	Accessories	1st Floor - South	251	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - South	241	SF	6	10+ years	
	Doors - Transom Window	1st Floor - South	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - South	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - South	1	EA	6	0-1 year	Loose door hardware
	Floor - Tile Ceramic/ Porcelain	1st Floor - South	239	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - South	12	SF	5	1-2 years	Damaged or missing tiles
	Floor Drain	1st Floor - South	1	EA	7	10+ years	
	Lavatory	1st Floor - South	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - South	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - South	1	EA	5	1-2 years	Missing cover
	Partitions	1st Floor - South	2	EA	7	10+ years	-
	Urinals	1st Floor - South	4	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - South	150	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - South	746	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - South	28	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor - South	12	SF	4	0-1 year	Missing or damaged tiles
	The Column Followin	1001 0041	12	٥.	•	o i your	comg or damagod thoo

Campus Name: Gillespie Page : 11 of 41 Assessment Date: 03/04/2024



Category : Room			Building : Main							
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Water Closet	1st Floor - South	2	EA	7	10+ years				
	Accessories	1st Floor - South	188	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor - South	188	SF	7	10+ years				
	Doors - Transom Window	1st Floor - South	16	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor - South	2	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor - South	188	SF	7	10+ years				
	Floor Drain	1st Floor - South	1	EA	7	10+ years				
	Lavatory	1st Floor - South	2	EA	7	10+ years				
	Lighting - Pendent/Surface	1st Floor - South	4	EA	7	10+ years				
	Partitions	1st Floor - South	4	EA	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - South	193	SF	7	10+ years				
	Walls - Structural Glazed Tile	1st Floor - South	655	SF	7	10+ years				
	Water Closet	1st Floor - South	4	EA	7	10+ years				
	Accessories	1st Floor - Women	99	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor - Women	99	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor - Women	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor - Women	99	SF	7	10+ years				
	Lavatory	1st Floor - Women	1	EA	7	10+ years				
	Lighting - Pendent/Surface	1st Floor - Women	1	EA	4	0-1 year	Missing cover			
	Partitions	1st Floor - Women	1	EA	7	10+ years	•			
	Walls - Plaster/Drywall	1st Floor - Women	500	SF	7	10+ years				
	Water Closet	1st Floor - Women	1	EA	7	10+ years				
	Accessories	2nd Floor - North	237	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor - North	232	SF	6	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor - North	5	SF	5	1-2 years	Water damage			
	Doors - Transom Window	2nd Floor - North	36	SF	7	10+ years	C			
	Doors - Wood Doors inclu hw	2nd Floor - North	2	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor - North	232	SF	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor - North	5	SF	4	0-1 year	Damaged tiles			
	Floor Drain	2nd Floor - North	1	EA	7	10+ years	Ç			
	Lavatory	2nd Floor - North	1	EA	7	10+ years				
	Lavatory	2nd Floor - North	1	EA	5	1-2 years	Running			
	Lighting - Pendent/Surface	2nd Floor - North	4	EA	7	10+ years	3			
	Partitions	2nd Floor - North	6	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor - North	150	SF	7	10+ years				
	Walls - Structural Glazed Tile	2nd Floor - North	764	SF	7	10+ years				
	Water Closet	2nd Floor - North	4	ĒΑ	7	10+ years				
	Water Closet	2nd Floor - North	2	EA	4	0-1 year	Out of order			
	Accessories	2nd Floor - North Boys	206	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor - North Boys	206	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor - North Boys	2	EΑ	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor - North Boys	206	SF	7	10+ years				
	Floor Drain	2nd Floor - North Boys	1	EA	7	10+ years				
	Lavatory	2nd Floor - North Boys	2	EA	7	10+ years				
	Laratory	Zha i looi Mortii Boyo	۷	_/\	,	ioi youis				

Campus Name: Gillespie Page : 12 of 41 Assessment Date: 03/04/2024



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor - North Boys	3	EA	7	10+ years	
	Partitions	2nd Floor - North Boys	2	EA	7	10+ years	
	Urinals	2nd Floor - North Boys	4	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - North Boys	122	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - North Boys	520	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor - North Boys	44	SF	7	10+ years	
	Water Closet	2nd Floor - North Boys	2	EA	7	10+ years	
	Accessories	2nd Floor - South	251	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - South	251	SF	6	10+ years	
	Doors - Transom Window	2nd Floor - South	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - South	2	ĒA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - South	221	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - South	30	SF	5	1-2 years	Cracks across floor
	Floor Drain	2nd Floor - South	1	EΑ	7	10+ years	
	Lavatory	2nd Floor - South	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor - South	3	EΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor - South	1	EA	5	1-2 years	Missing cover
	Partitions	2nd Floor - South	2	EA	7	10+ years	whoshing devel
	Urinals	2nd Floor - South	4	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - South	150	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - South	786	SF	7	10+ years	
	Water Closet	2nd Floor - South	2	EA	7	10+ years	
	Accessories	2nd Floor - South	219	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - South	219	SF	6		
	Doors - Transom Window	2nd Floor - South	32	SF	7	10+ years	
				EA	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - South	2 209	SF		10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - South		SF SF	6 5	10+ years	Cracks
	Floor - Tile Ceramic/ Porcelain	2nd Floor - South	10			1-2 years	Cracks
	Floor Drain	2nd Floor - South	1	EΑ	7	10+ years	
	Lavatory	2nd Floor - South	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor - South	4	EΑ	7	10+ years	
	Partitions	2nd Floor - South	4	EΑ	7	10+ years	D 1.11.11
	Partitions	2nd Floor - South	1	EA	5	1-2 years	Damaged at bottom
	Walls - Plaster/Drywall	2nd Floor - South	193	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - South	655	SF	7	10+ years	
	Water Closet	2nd Floor - South	4	EA	7	10+ years	0 1 1
	Water Closet	2nd Floor - South	1	EA	4	0-1 year	Out of order
	Accessories	2nd Floor - Women	173	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Women	167	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - Women	6	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor - Women	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor - Women	163	SF	7	10+ years	
	Floor - Tile	2nd Floor - Women	10	SF	5	1-2 years	Damaged tiles
	Lavatory	2nd Floor - Women	1	EA	7	10+ years	

Campus Name: Gillespie Page : 13 of 41 Assessment Date: 03/04/2024



Catego	ry : Room	Ві					
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor - Women	2	EA	7	10+ years	
	Partitions	2nd Floor - Women	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Women	480	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Women	2	SF	5	1-2 years	Water damage
	Water Closet	2nd Floor - Women	1	EA	7	10+ years	
	Accessories	Engineer's	24	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's	24	SF	6	0-1 year	Peeling paint
	Doors - Wood Doors inclu hw	Engineer's	1	EΑ	7	10+ years	
	Floor - Tile	Engineer's	24	SF	6	10+ years	
	Lavatory	Engineer's	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Engineer's	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Engineer's	138	SF	7	10+ years	
	Water Closet	Engineer's	1	EΑ	7	10+ years	
	Accessories	In 154	67	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In 154	67	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In 154	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In 154	67	SF	7	10+ years	
	Floor Drain	In 154	1	EΑ	7	10+ years	
	Hand Dryer	In 154	1	EΑ	7	6-10 years	
	Lavatory	In 154	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	In 154	1	EA	7	10+ years	
	Walls - Plaster/Drywall	In 154	86	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	In 154	189	SF	7	10+ years	
	Water Closet	In 154	1	EA	7	10+ years	Repaired

Category : Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #101 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	706	SF	6	10+ years	
	Chalk Board	1st Floor	44	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	713	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	707	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	6	SF	6	2-5 years	
Classroo	om #102 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	828	SF	7	10+ years	

Campus Name: Gillespie Page : 14 of 41 Assessment Date: 03/04/2024



Calego	Category : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	808	SF	7	10+ years	
	Floor - Tile	1st Floor	20	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Storage/ Closet	1st Floor	66	SF	5	1-2 years	Damaged tiles
	Walls - Plaster/Drywall	1st Floor	4,139	SF	7	10+ years	·
Classroc	om #103 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	708	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	5	SF	6	10+ years	
	Chalk Board	1st Floor	56	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	713	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	5	1-2 years	Damaged covers
	Walls - Plaster/Drywall	1st Floor	1,299	SF	7	10+ years	Damaged covers
Classroc	om #104 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	10	SF	6	2-5 years	
	Ceiling - Plaster/Drywall	1st Floor	703	SF	6	2-5 years 2-5 years	
	Chalk Board	1st Floor	58	LF	4	2-5 years 2-5 years	
	Doors - Transom Window			SF	7		
		1st Floor 1st Floor	9			10+ years	
	Doors - Wood Doors inclu hw		1	EA	7	10+ years	
	Floor - Wood	1st Floor	713	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,299	SF	7	10+ years	
Classroc	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	713	SF	7	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	713	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	11	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	



Category : Classroom			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,299	SF	7	10+ years	
Classra	am #106 (Store Boom)						
Classion	om #106 (Store Room)	4-4-51		Ε.	7	0.40	
	AC Units	1st Floor	1	EA LF	7	6-10 years	
	Casework	1st Floor	9		7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	713	SF LF	7	10+ years	
	Chalk Board	1st Floor	22		4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	703	SF	6	10+ years	D 107
	Floor - Tile	1st Floor	10	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,290	SF	7	10+ years	Hala Sancall
	Walls - Plaster/Drywall	1st Floor	1	SF	5	1-2 years	Hole in wall
	Walls - Plaster/Drywall	1st Floor	8	SF	5	6-10 years	Broken moldings
_Classroo	om #107 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	713	SF	7	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	713	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EΑ	5	1-2 years	Missing cover
	Walls - Plaster/Drywall	1st Floor	1,299	SF	7	10+ years	Wildowing Gover
01	W450 (Q)						
_Classroc	om #153 (Store Room)	4 . 5				0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	704	SF	7	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	704	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,160	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #154 (Kindergarten)						
	zan a na r (randza grantari)						



Catego	ory : Classroom		В	uilding	: Main		3301 G Glate GTNEET, Glicago, 12 00013
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	96	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,058	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,058	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,434	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #155 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	684	SF	7	10+ years	
	Chalk Board	1st Floor	48	LF	4	2-5 years	
	Doors - Hardware	1st Floor	1	EA	6	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	664	SF	7	10+ years	
	Floor - Tile	1st Floor	20	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	Damaged tiles
	Walls - Plaster/Drywall	1st Floor	1,142	SF	7	10+ years	
Classroo	om #156 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	714	SF	7	10+ years	
	Chalk Board	1st Floor	37	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	714	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,174	SF	7	10+ years	
Classro	om #157 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	704	SF	7	10+ years	
	Chalk Board	1st Floor	70 4 51	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7		
	Doors - Transom Window Doors - Wood Doors inclu hw			SF EA	7	10+ years	
		1st Floor	1 701	SF	7 7	10+ years	
	Floor - Tile	1st Floor	701	SF	1	10+ years	



Catego	ory : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	3	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,159	SF	7	10+ years	
Classro	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	713	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	713	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,296	SF	7	10+ years	
Classroo	om #201 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	40	SF	5	1-2 years	Water damage
	Chalk Board	2nd Floor	30	LF	4	2-5 years	Water damage
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Bools Inclu IIW	2nd Floor	713	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2			1-2 years	Missing sover
	Walls - Plaster/Drywall	2nd Floor	1,299	EA SF	5 7	10+ years	Missing cover
Classro	om #202 (Regular Classroom)						
Classio	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	713	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
			-	SF	7	-	
	Floor - Wood	2nd Floor	713			10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	6	LF SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,294		7	10+ years	NA/ 4 1
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Water damage
Classroo	om #203 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	713	SF	6	10+ years	



Catego	ry : Classroom	_	B	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	713	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	8	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	5	1-2 years	Missing covers
	Walls - Plaster/Drywall	2nd Floor	1,297	SF	7	10+ years	Triboning covere
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	1-2 years	Damaged wall trim
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	713	SF	6	10+ years	
	Chalk Board	2nd Floor	15	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
					7	•	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA		10+ years	
	Floor - Wood	2nd Floor	713	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,289	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Drywall cracks
Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	713	SF	6	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	713	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	11	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	ĒΑ	5	0-1 year	Damaged cover
	Walls - Plaster/Drywall	2nd Floor	1,299	SF	7	10+ years	zamagou coro.
Classroo	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	713	SF	6	10+ years	
	Chalk Board	2nd Floor	15	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7		
	Floor - Tile	2nd Floor 2nd Floor	713	SF	7	10+ years	
						10+ years	
	Lighting - Pendent/Surface Walls - Plaster/Drywall	2nd Floor	12 1,299	EA	7	10+ years 10+ years	
	vvaus - Piaster/DrVWall	2nd Floor	1.299	SF	7	TU+ vears	

Campus Name: Gillespie Page : 19 of 41 Assessment Date: 03/04/2024



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ocoroc	om #207 (Regular Classroom)						
assioc	,	2nd Floor		ΓΛ	7	C 40	
	AC Units		1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	710	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3	SF	5	1-2 years	Water stains (rust colored-
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	discoloration)
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	713	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
				SF			
	Walls - Plaster/Drywall	2nd Floor	1,201	SF	7	10+ years	
assroc	om #252 (Counseling Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	5	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	710	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	4	0-1 year	Water damage
	Chalk Board	2nd Floor	27	LF	4	2-5 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	712	SF	7	10+ years	0 " 1:
	Floor - Tile	2nd Floor	3	SF	4	0-1 year	Small chips
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,168	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	6	SF	6	6-10 years	
lassroc	om #253 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	704	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
			1	EA	7	•	
	Doors - Wood Doors inclu hw Floor - Tile	2nd Floor	704	SF	7	10+ years	
		2nd Floor				10+ years	
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	10+ years	N. dr
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Missing cover
	Walls - Plaster/Drywall	2nd Floor	1,156	SF	7	10+ years	
assroc	om #254 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	690	SF	7	10+ years	
	Doors - Transom Window		9	SF	7		
		2nd Floor	1		7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	1	10+ years	



Category : Classroom			В	uilding	: Main		-
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	690	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	11	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EΑ	5	1-2 years	Loose cover
	Storage/ Closet	2nd Floor	3	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,141	SF	7	10+ years	
Classroo	om #255 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	14	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	675	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	675	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	0-1 year	Water damage
	Work Sink	2nd Floor	1	EA	7	10+ years	Water damage
	WORK SILIK	2110 F1001	ı	LA	,	10+ years	
Classroc	om #256 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	714	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	714	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,157	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Wall cracks (extends to ceiling)
Classroo	om #257 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	712	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	712	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Storage/ Closet	2nd Floor	23	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,160	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	1-2 years	Drywall cracks
Catego	ry : Interior		В	uilding	: Main		
	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
Jioup	nom Typo	Location	Quantity	COM	Kank	Recommend	Comments



						Replacement	
Corridor						·	
	Ceiling - Plaster/Drywall	1st Floor	4,433	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	6	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	2	EΑ	7	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	2	EΑ	7	6-10 years	
	Floor - Terrazzo	1st Floor	400	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	593	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	4,096	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	18	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	5	EΑ	7	10+ years	zamagou moo
	Lighting - Wall Mounted	1st Floor	4	ĒΑ	7	10+ years	
	Stairs - Terrazzo	1st Floor	40	LF	7	10+ years	
	Student Lockers - One Tier	1st Floor	229	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,166	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	4,765	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	17	SF	5	1-2 years	Cracked tiles
	Ceiling - Plaster/Drywall	2nd Floor	3,740	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	36	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	2	ĒΑ	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EΑ	7	6-10 years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EΑ	7	6-10 years	
	Floor - Terrazzo	2nd Floor	29	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	4,049	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	. 8	SF	5	1-2 years	Broken tiles
	Lighting - Pendent/Surface	2nd Floor	48	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	5	1-2 years	Missing covers
	Stairs - Terrazzo	2nd Floor	80	LF	7	10+ years	C
	Student Lockers - One Tier	2nd Floor	214	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	3,356	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	3,636	SF	7	10+ years	
						•	
Safety							
,	Camera Viewing Station	Entire Building	2	EΑ	7	10+ years	
	Camera Viewing Station	Entire Building	2	EA	5	0-1 year	Camera program not working at
	· ·	C				·	station
	Security Cameras	Entire Building	12	EA	7	6-10 years	
	Security Cameras	Entire Building	4	EA	5	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	NE Stair down to basement	97	SF	7	10+ years	
	Floor - Concrete	NE Stair down to basement	97	SF	7	10+ years	
	Handrails	NE Stair down to basement	38	LF	7	10+ years	
	Lighting - Pendent/Surface	NE Stair down to basement	1	EA	7	10+ years	
	Lighting - Wall Mounted	NE Stair down to basement	2	EA	7	6-10 years	



					Replacement	
Stairs - Concrete	NE Stair down to basement	76	LF	7	10+ years	
Walls - Masonry	NE Stair down to basement	657	SF	7	10+ years	
Ceiling - Plaster/Drywall	North East	389	SF	6	10+ years	
Ceiling - Plaster/Drywall	North East	10	SF	4	0-1 year	Water damage
Floor - Terrazzo	North East	173	SF	7	10+ years	
Handrails	North East	58	LF	7	10+ years	
Lighting - Pendent/Surface	North East	2	EΑ	7	10+ years	
Lighting - Wall Mounted	North East	2	EA	7	10+ years	
Stairs - Terrazzo	North East	132	LF	7	10+ years	
Walls - Plaster/Drywall	North East	733	SF	7	10+ years	
Walls - Structural Glazed Tile	North East	489	SF	7	10+ years	
Ceiling - Plaster/Drywall	North West	378	SF	7	10+ years	
Ceiling - Plaster/Drywall	North West	20	SF	4	0-1 year	Water damage
Floor - Terrazzo	North West	127	SF	7	10+ years	
Handrails	North West	62	LF	7	10+ years	
Lighting - Pendent/Surface	North West	2	EA	7	10+ years	
Lighting - Wall Mounted	North West	2	EA	7	10+ years	
Stairs - Terrazzo	North West	150	LF	7	10+ years	
Walls - Plaster/Drywall	North West	733	SF	7	10+ years	
Walls - Structural Glazed Tile	North West	489	SF	7	10+ years	
Ceiling - Plaster/Drywall	South West	398	SF	7	10+ years	
Floor - Terrazzo	South West	127	SF	7	10+ years	
Handrails	South West	62	LF	7	10+ years	
Lighting - Pendent/Surface	South West	2	EΑ	7	10+ years	
Lighting - Wall Mounted	South West	2	EΑ	7	10+ years	
Stairs - Terrazzo	South West	150	LF	7	10+ years	
Walls - Plaster/Drywall	South West	733	SF	7	10+ years	
Walls - Structural Glazed Tile	South West	489	SF	7	10+ years	



Category : Exterior			В						
				Recommend					
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
ntrance									
	Exterior Doors - Exterior Steel Door	#3 - NW	6	EA	4	0-1 year	Don't lock properly. Corroded		
	Exterior Doors - Transom Lite	#3 - NW	6	EA	6	10+ years	,		
	Exterior Stairs - Concrete	#3 - NW	75	LF	5	10+ years			
	Exterior Stairs - Stone	#3 - NW	18	LF	5	6-10 years			
	Exterior Doors - Exterior Steel Door	#4 - SW	2	EA	4	0-1 year	Don't lock properly		
	Exterior Doors - Side lite	#4 - SW	2	EA	6	10+ years	,		
	Exterior Doors - Transom Lite	#4 - SW	4	EA	6	10+ years			
	Exterior Stairs - Concrete	#4 - SW	108	LF	6	10+ years			
	Ramp Handrail - Steel_Ramp Handrail	#4 - SW	210	LF	6	10+ years			
	Ramps - Concrete	#4 - SW	100	LF	6	10+ years			
	Stair Handrail - Steel_Stair Handrail	#4 - SW	30	LF	6	10+ years			
	Exterior Doors - Exterior Steel Door	#4.5 - NW	1	EA	6	10+ years			
	Exterior Doors - Transom Lite	#4.5 - NW	1	EΑ	5	6-10 years			
	Exterior Stairs - Concrete	#4.5 - NW	18	LF	5	6-10 years			
	Exterior Stairs - Stone	#4.5 - NW	3	LF	6	10+ years			
	Stair Handrail - Steel_Stair Handrail	#4.5 - NW	12	LF	4	0-1 year	Missing/loose		
	Entrance Control - Audio and Video	#5 - NW	1	EA	6	6-10 years	Changed to match current observations		
	Exterior Doors - Exterior Steel Door	#5 - NW	1	EA	6	10+ years	observations		
	Exterior Doors - Side lite	#5 - NW	1	EA	6	10+ years			
	Exterior Stairs - Concrete	#5 - NW	32	LF	7	10+ years			
	Ramp Handrail - Steel_Ramp Handrail	#5 - NW	80	LF	7	10+ years			
	Ramps - Concrete	#5 - NW	40	LF	7	10+ years			
	Stair Handrail - Steel_Stair Handrail	#5 - NW	30	LF	7	10+ years			
	Stall Harlardin Steel_Stall Harlardin	#O 1444	30		•	101 years			
oundatio									
	Foundation - Concrete	Entire Building	711	LF	7	10+ years			
	Superstructure - Concrete	Entire Building	34,406	SF	7	10+ years			
	Superstructure - Concrete	Entire Building	10	SF	5	1-2 years	Wall cracking in the lunch room causing the attached board to fall.		
ighting									
-	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	6	10+ years			
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	4	0-1 year	The lights heads are new but the		
		Ç				·	hardware never replaced and not attached to the roof		
	Exterior Lighting - Wall Mounted	Entire Building	6	EA	7	10+ years	Newly replaced		
oof Sys	stem.								
	Coping - Metal	Low NW roof	42	LF	6	10+ years	Changed to match current observations		

Campus Name: Gillespie Page : 24 of 41 Assessment Date: 03/04/2024



Catego	ry : Exterior		В	uilding	: Additi	on	<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Interior Downspouts	Low NW roof	25	LF	4	1-2 years	Smaller drain, no strainer
	Roof - Asphalt Gravel Ballast	Low NW roof	356	SF	4	1-2 years	Soft spots/bubbling/cracking throughout
	Roof Structure - Concrete	Low NW roof	356	SF	7	10+ years	
	Coping - Metal	Low SE roof	42	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low SE roof	16	LF	5	6-10 years	
	Roof - Asphalt Gravel Ballast	Low SE roof	434	SF	4	1-2 years	Soft spots/bubbling/cracking throughout
	Roof Structure - Concrete	Low SE roof	434	SF	7	10+ years	
	Coping - Metal	Low SW roof	40	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low SW roof	25	LF	4	0-1 year	Covered with asphalt
	Roof - Asphalt Gravel Ballast	Low SW roof	323	SF	4	1-2 years	Soft spots/bubbling/cracking throughout
	Roof Structure - Concrete	Low SW roof	323	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	2	EA	5	10+ years	
	Chimney - Metal Flue	Main Roof	32	LF	6	10+ years	
	Coping - Metal	Main Roof	687	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	112	LF	5	2-5 years	
	Roof - Asphalt Gravel Ballast	Main Roof	19,931	SF	4	1-2 years	Soft spots/bubbling/cracking throughout
	Roof Hatch - Metal	Main Roof	1	EA	5	6-10 years	
	Roof Structure - Concrete	Main Roof	19,931	SF	7	10+ years	
_Walls							
	Canopy - Concrete/ Stucco	Entire Building	1,613	SF	6	10+ years	
	Canopy - Concrete/ Stucco	Entire Building	45	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	13,608	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	100	SF	5	1-2 years	Large cracking/Wall separation between the main and addition buildings
	Exterior Walls - Brick	Entire Building	305	SF	4	1-2 years	Deteriorating/cracking
	Exterior Walls - Precast Panel Wall	Entire Building	225	SF	6	10+ years	
Windows							
	Curtain wall - Insulated Panel	Entire Building	1,180	SF	6	6-10 years	
	Curtain wall - Louver	Entire Building	42	SF	6	6-10 years	
	Guard - Guards perforated	Entire Building	1,720	SF	6	10+ years	
	Lintels - Steel	Entire Building	120	LF	5	10+ years	
	Windows - Decorative	Entire Building	450	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,920	SF	6	6-10 years	

Campus Name: Gillespie Page : 25 of 41 Assessment Date: 03/04/2024



Catego	ry : Electrical		В	uilding	: Additi	on	
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Emergency A/C Power - Corridors and Stairs	1st Floor	7,561	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	1st Floor	1,500	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	25	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	1	EA	6	0-1 year	Broken
	Exit Signs - Multipurpose Room	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	12	EA	7	6-10 years	
	Emergency Battery Packs - Multipurpose Room	Entire Building	3	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	1	EA	7	6-10 years	
	Security System - CCTV	Entire Building	30,600	SF	6	6-10 years	
	Security System - CCTV	Entire Building	30,600	SF	3	0-1 year	Most cameras are missing in many locations
	Security System - Intrusion Detection	Entire Building	30,600	SF	5	6-10 years	In need of upgrade. A lot of broken of the wall.
Main Se							
	PA System	1st Floor	30,600	SF	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	30,600	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	30,600	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Hand	lling Systems						
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - Less than 6000 cfm	2nd Floor	1	EA	6	6-10 years	



Catego	ry : Mechanical		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Air Intake	2nd Floor	1	EΑ	6	6-10 years	
	Indoor Return Fans- Centrifugal Squirrel	Mechanical Room	1	EA	6	6-10 years	
	Cage - 5000 - 10000 CFM					·	
Heating I	Devices						
	Wall Heater - Electric	Entire Building	6	EA	2	0-1 year	Not working
	Wall Heater - Electric	Entire Building	3	EA	2	0-1 year	Not working
	Fin Tube - Steam	Entire Building	10	LF	5	6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building	14	EA	6	6-10 years	
	Unit Heater - Steam	Kitchen	1	EA	6	6-10 years	
Mechani	cal Plumbing						
	Condensate-Steel or Galvanized	Entire Building	1,200	LF	6	6-10 years	
Tempera	ture Control						
	Hybrid Pneumatic/DDC System	Entire Building	1	SF	6	6-10 years	
	Pneumatic System	Entire Building	30,600	SF	6	6-10 years	Served from Main building. Runs in concert with 2 compressors.
	Thermostats - Pneumatic	Entire Building	30	EA	5	0-1 year	Thermostats are broken or missing Do not work cannot maintain prope pressure leaking air.
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted-Steam Heating w/ DX Cooling Coil & Remote Mounted Compressors	Entire Building	18	EA	5	0-1 year	Univents do not work properly. No proper working damper controls on most units.
	Unit Ventilators- Floor Mounted-Steam Heating w/ DX Cooling Coil & Remote Mounted Compressors	Entire Building	1	EA	2	0-1 year	Room 214
Ventilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Roof and Kitchen	1	EA	6	6-10 years	Kitchen area
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof and Kitchen	1	EA	6	6-10 years	Operational, per engineer
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof and Kitchen	4	EA	6	6-10 years	
	Roof Mounted Duct Work	Roof and Kitchen	10	LF	6	6-10 years	
	Roof Mounted Duct Work	Roof and Kitchen	6	LF	5	6-10 years	
	Type I Exhaust Hood- Kitchen	Roof and Kitchen	1	EA	2	0-1 year	No fire suppression system

Campus Name: Gillespie Page : 27 of 41 Assessment Date: 03/04/2024



Catego	ry : Plumbing		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	30,600	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	30,600	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	30,600	SF	6	6-10 years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	30,600	SF	6	6-10 years	
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	30,600	SF	6	6-10 years	
	(Risers)	F 4 B 4 B	00.000	0=		0.40	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	30,600	SF	6	6-10 years	
	(from Risers to Fixtures)	Father Building	00.000	0.	0	0.40	
	Sanitary Piping	Entire Building	30,600	SF	6	6-10 years	
	Storm Piping	Entire Building	30,600	SF	6	6-10 years	
	Vent Piping	Entire Building	30,600	SF	6	6-10 years	

Category: Room **Building: Addition**

itegory .	1100111	Ballallig : Addition					
						Recommend	
up Ite	em - Type	Location	Quantity	UOM	Rank	Replacement	Comments
nistrativ	ve Suites/Offices						
C	eiling - Plaster/Drywall	1st Floor Teacher's lunch room	433	SF	6	10+ years	
	oors - Wood Doors inclu hw	1st Floor Teacher's lunch room	2	EA	6	10+ years	
FI	oor - Tile	1st Floor Teacher's lunch room	428	SF	6	6-10 years	
FI	oor - Tile	1st Floor Teacher's lunch room	5	SF	5	0-1 year	Damaged tiles
Li	ghting - Pendent/Surface	1st Floor Teacher's lunch room	6	EA	7	6-10 years	•
	ower Distribution	1st Floor Teacher's lunch room	8	EA	7	10+ years	
W	alls - Concrete Block	1st Floor Teacher's lunch room	754	SF	6	10+ years	
C	eiling - Plaster/Drywall	215 Women's Teacher's Room	320	SF	6	10+ years	
D	oors - Wood Doors inclu hw	215 Women's Teacher's Room	1	EΑ	6	10+ years	
FI	oor - Tile	215 Women's Teacher's Room	300	SF	6	6-10 years	
FI	oor - Tile	215 Women's Teacher's Room	20	SF	4	0-1 year	Damaged floor
Li	ghting - Pendent/Surface	215 Women's Teacher's Room	4	EA	6	6-10 years	
Po	ower Distribution	215 Women's Teacher's Room	6	EA	7	10+ years	
W	alls - Concrete Block	215 Women's Teacher's Room	696	SF	7	10+ years	
C	eiling - Plaster/Drywall	2nd- Room 208 Technology	335	SF	6	10+ years	
		Coordinator					
D	oors - Wood Doors inclu hw	2nd- Room 208 Technology Coordinator	1	EA	6	10+ years	
FI	oor - Tile	2nd- Room 208 Technology	335	SF	6	6-10 years	
		Coordinator					
Li	ghting - Pendent/Surface	2nd- Room 208 Technology Coordinator	10	EA	7	6-10 years	
Po	ower Distribution	2nd- Room 208 Technology Coordinator	4	EA	6	10+ years	
St	torage/ Closet	2nd- Room 208 Technology	7	SF	7	10+ years	Locked

Campus Name: Gillespie Page : 28 of 41 Assessment Date: 03/04/2024



Category : Room			Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
		Coordinator							
	Walls - Concrete Block	2nd- Room 208 Technology	514	SF	6	10+ years			
		Coordinator							
	Walls - Plaster/Drywall	2nd- Room 208 Technology	163	SF	6	10+ years			
		Coordinator							
	Ceiling - Plaster/Drywall	Book Room	368	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Book Room	1	EA	6	10+ years			
	Floor - Tile	Book Room	348	SF	6	6-10 years			
	Floor - Tile	Book Room	20	SF	4	0-1 year	Missing and damaged tiles		
	Lighting - Pendent/Surface	Book Room	8	EA	7	6-10 years			
	Power Distribution	Book Room	4	EA	6	10+ years			
	Walls - Concrete Block	Book Room	729	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Kitchen Office	62	SF	6	2-5 years	Peeling paint		
	Doors - Wood Doors inclu hw	Kitchen Office	1	EA	6	10+ years			
	Floor - Tile	Kitchen Office	57	SF	6	6-10 years			
	Floor - Tile	Kitchen Office	5	SF	4	0-1 year	Damaged tiles		
	Lighting - Pendent/Surface	Kitchen Office	1	EA	7	6-10 years			
	Power Distribution	Kitchen Office	4	EA	6	10+ years			
	Walls - Concrete Block	Kitchen Office	244	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Lunchroom/ Gym Office	177	SF	6	10+ years			
	Doors - Side-lite	Lunchroom/ Gym Office	6	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Lunchroom/ Gym Office	1	EA	6	10+ years			
	Floor - Tile	Lunchroom/ Gym Office	177	SF	6	6-10 years			
	Lighting - Pendent/Surface	Lunchroom/ Gym Office	2	EA	7	6-10 years			
	Power Distribution	Lunchroom/ Gym Office	4	EA	6	10+ years			
	Walls - Concrete Block	Lunchroom/ Gym Office	421	SF	6	10+ years			
	AC Unit	Men's Teacher's Lounge	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	Men's Teacher's Lounge	320	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Men's Teacher's Lounge	1	EA	6	10+ years			
	Floor - Tile	Men's Teacher's Lounge	320	SF	6	6-10 years			
	Lighting - Pendent/Surface	Men's Teacher's Lounge	4	EA	7	6-10 years			
	Power Distribution	Men's Teacher's Lounge	6	EA	6	10+ years			
	Walls - Concrete Block	Men's Teacher's Lounge	696	SF	6	10+ years			
ymnas	ia								
-	Ceiling - Plaster/Drywall	1st Floor	3,787	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	4	ĒΑ	7	10+ years			
	Floor - Tile	1st Floor	3,787	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor	15	ĒΑ	7	6-10 years			
	Walls - Concrete Block	1st Floor	2,137	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	60	SF	6	1-2 years	Mortar crack		
	Walls - Structural Glazed Tile	1st Floor	2,253	SF	7	10+ years			
	3.00.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.0.	. 21.1.00.	_,_00	- .	•	,			
itchen									

Campus Name: Gillespie Page : 29 of 41 Assessment Date: 03/04/2024



Catego	ry : Room	-	Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	1st Floor	640	SF	7	10+ years		
	Doors - Transom Window	1st Floor	3	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile Quarry	1st Floor	640	SF	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years		
	Serving Line	1st Floor	20	LF	7	10+ years		
	Storage/ Closet	1st Floor	98	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	1,189	SF	7	10+ years		
Library								
•	AC Unit	110	2	EA	7	6-10 years		
	Casework	110	34	LF	7	10+ years		
	Ceiling - Plaster/Drywall	110	1,160	SF	6	10+ years		
	Doors - Wood Doors inclu hw	110	2	ĒΑ	6	10+ years		
	Floor - Carpet	110	1,205	SF	6	6-10 years		
	Floor - Carpet	110	5	SF	5	0-1 year	Damaged carpet	
	Lighting - Pendent/Surface	110	18	EA	7	6-10 years	Damagoa carpot	
	Storage/ Closet	110	66	SF	7	10+ years		
	Walls - Concrete Block	110	1,207	SF	7	10+ years		
	Walls - Plaster/Drywall	110	842	SF	7	10+ years		
	walls - Flaster/Drywall	110	042	31	,	10+ years		
_MDF_ID								
	Doors - Wood Doors inclu hw	2nd- Inside Room 208	1	EA	6	10+ years		
	Finishes	2nd- Inside Room 208	80	SF	7	10+ years		
	Window AC Unit	2nd- Inside Room 208	1	EA	7	6-10 years		
_Mechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	40	SF	7	6-10 years		
	Storage Room	1st Floor	223	SF	7	10+ years		
	Janitor's Closet	2nd Floor	156	SF	7	6-10 years		
	Mechanical/ Service Rooms	2nd Floor	278	SF	7	10+ years		
_Restroor	n							
	Accessories	1st Floor	254	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	254	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	2-5 years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	254	SF	6	6-10 years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Lavatory	1st Floor	3	EA	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	5	EA	6	6-10 years		
	Partitions	1st Floor	2	EA	4	0-10 years 0-1 year	Damaged partition	
	Urinals	1st Floor	4	EA	6	10+ years	Damagea partition	
	Ciliais	13111001	4	LA	J	TOT YEARS		



Calego	ry : Room		Building : Addition							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Structural Glazed Tile	1st Floor	684	SF	6	10+ years				
	Water Closet	1st Floor	2	EA	6	10+ years				
	Accessories	1st Floor	254	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor	254	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years				
	Floor - Tile Ceramic/ Porcelain	1st Floor	254	SF	6	6-10 years				
	Floor Drain	1st Floor	1	EA	7	10+ years				
	Lavatory	1st Floor	3	EA	7	10+ years				
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years				
	Partitions	1st Floor	5	EA	7	10+ years				
	Partitions	1st Floor	1	EA	4	0-1 year	Missing door			
	Walls - Structural Glazed Tile	1st Floor	684	SF	6	10+ years	ŭ			
	Water Closet	1st Floor	6	EA	6	10+ years				
	Accessories	215 Women Teacher's Lounge	60	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	215 Women Teacher's Lounge	60	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	215 Women Teacher's Lounge	1	ĒΑ	6	6-10 years				
	Floor - Tile	215 Women Teacher's Lounge	60	SF	6	6-10 years				
	Lavatory	215 Women Teacher's Lounge	2	ĒΑ	6	10+ years				
	Lighting - Pendent/Surface	215 Women Teacher's Lounge	1	EΑ	7	6-10 years	Qty adjusted			
	Lighting - Wall Mounted	215 Women Teacher's Lounge	1	EΑ	6	6-10 years	aty adjusted			
	Partitions	215 Women Teacher's Lounge	1	EA	7	10+ years				
	Walls - Concrete Block	215 Women Teacher's Lounge	255	SF	7	10+ years				
	Water Closet	215 Women Teacher's Lounge	1	EA	7	10+ years				
	Accessories	2nd Floor	254	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor	254	SF	7	10+ years	Restroom is not currently in use			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	4	0-1 year	Door damaged beyond repair			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	254	SF	6	6-10 years	boor damaged beyond repair			
	Floor Drain	2nd Floor	1	EA	7	10+ years				
	Lavatory	2nd Floor	2	EA	7	10+ years				
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years				
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Missing cover			
	Partitions	2nd Floor	2	EA	4	1-2 years	Bent frames			
	Urinals	2nd Floor	4	EA	6	10+ years	Dent names			
	Walls - Structural Glazed Tile	2nd Floor	684	SF	7	10+ years				
	Water Closet	2nd Floor	2	EA	7	10+ years				
	Accessories	2nd Floor	254	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor	254 254	SF	6	10+ years				
	Doors - Hardware	2nd Floor	254	EA	6	1-2 years	Missing handle			
	Doors - Hardware Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	2	EA	7	10+ years	wissing nativite			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	254	SF	7	6-10 years				
	Floor Drain	2nd Floor	25 4 1	SF EA	7	10+ years				
				EA EA	7					
	Lavatory	2nd Floor	3			10+ years				
	Lighting - Pendent/Surface	2nd Floor	2 6	EA EA	6 7	6-10 years				
	Partitions	2nd Floor	б	EA	,	10+ years				

Campus Name: Gillespie Page : 31 of 41 Assessment Date: 03/04/2024



Category: Room				Building : Addition						
						Recommend				
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Structural Glazed Tile	2nd Floor	684	SF	7	10+ years				
	Water Closet	2nd Floor	4	EA	7	10+ years				
	Water Closet	2nd Floor	1	EA	6	1-2 years	Out of order			
	Water Closet	2nd Floor	1	EA	6	1-2 years	Out of order			
	Accessories	Kitchen Office Toilet	28	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Kitchen Office Toilet	22	SF	6	10+ years				
	Ceiling - Plaster/Drywall	Kitchen Office Toilet	6	SF	5	0-1 year	Water damage			
	Doors - Hardware	Kitchen Office Toilet	1	EA	6	1-2 years	Loose door knob			
	Doors - Wood Doors inclu hw	Kitchen Office Toilet	1	EΑ	7	10+ years				
	Floor - Tile	Kitchen Office Toilet	28	SF	6	6-10 years				
	Lavatory	Kitchen Office Toilet	1	EA	6	10+ years				
	Lighting - Pendent/Surface	Kitchen Office Toilet	1	EA	7	6-10 years				
	Walls - Concrete Block	Kitchen Office Toilet	168	SF	6	10+ years				
	Water Closet	Kitchen Office Toilet	1	EA	6	10+ years				
	Accessories	Men's Teacher's Room	96	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Men's Teacher's Room	96	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Men's Teacher's Room	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	Men's Teacher's Room	96	SF	7	10+ years				
	Lavatory	Men's Teacher's Room	1	EA	7	10+ years				
	Lighting - Pendent/Surface	Men's Teacher's Room	1	EA	7	6-10 years				
	Lighting - Wall Mounted	Men's Teacher's Room	1	EA	7	6-10 years				
	Partitions	Men's Teacher's Room	1	EA	7	10+ years				
	Walls - Concrete Block	Men's Teacher's Room	320	SF	7	10+ years				
	Water Closet	Men's Teacher's Room	1	EA	7	10+ years				
	Accessories	Women's teacher restroom	56	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	Women's teacher restroom	70	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	Women's teacher restroom	1	EA	7	10+ years				
	Floor - Tile	Women's teacher restroom	70	SF	7	6-10 years				
	Lavatory	Women's teacher restroom	1	EA	7	10+ years				
	Lighting - Chandelier, Incandescent	Women's teacher restroom	1	EA	7	6-10 years				
	Partitions	Women's teacher restroom	1	EA	7	10+ years				
	Walls - Concrete Block	Women's teacher restroom	560	SF	7	10+ years				
	Water Closet	Women's teacher restroom	1	EA	7	6-10 years				

Category : Classroom **Building: Addition**

					Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroom #114 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall	1st Floor	704	SF	7	10+ years	
Ceiling - Plaster/Drywall	1st Floor	16	SF	6	6-10 years	
Chalk Board	1st Floor	20	LF	4	2-5 years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Floor - Tile	1st Floor	720	SF	6	6-10 years	



Catego	ry : Classroom		В	uilding	: Additi			
					Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years		
	Storage/ Closet	1st Floor	20	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	828	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	7	SF	6	1-2 years	Cracking at mortar	
						•	· ·	
lassroo	om #116 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	695	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	25	SF	5	1-2 years	Water damage	
	Chalk Board	1st Floor	20	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	720	SF	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years		
	Storage/ Closet	1st Floor	20	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	835	SF	7	10+ years		
	Walls - Collete block	13(1100)	000	OI.	,	10+ years		
lassroo	om #117 (Store Room)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years		
	Chalk Board	1st Floor	30	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	720	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	13	ĒΑ	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years		
	Storage/ Closet	1st Floor	20	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	836	SF	7	10+ years		
		1301 1001	000	Oi	,	101 years		
Classroo	om #118 (Other Instructional Use)							
	Ceiling - Plaster/Drywall	1st Floor	1,062	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years		
	Floor - Carpet	1st Floor	1,092	SF	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	24	EΑ	7	6-10 years		
	Walls - Concrete Block	1st Floor	1,032	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	1,002	SF	5	0-1 year	Window sill damaged	
	Walls - Collete block	13(1100)	ı	OI.	3	0-1 year	willdow sill damaged	
lassroo	om #119 (Store Room)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years		
	Chalk Board	1st Floor	40	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	720	SF	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years		
				EA		•	Missing sovers	
	Lighting - Pendent/Surface	1st Floor	9	EA	5	1-2 years	Missing covers	



Catego	Category : Classroom		В	on	3301 G Glate GTNEET, GHICAGO, IE 60013		
curege	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	835	SF	7	10+ years	
Classro	om #120 (Poquilor Closeroom)						
Classio	om #120 (Regular Classroom)	4-4-51	2	ΓΛ	7	C 40	
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	2	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,092	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,092	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,030	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #209 (Science)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	53	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	972	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	Water damage
	Floor - Tile	2nd Floor	997	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor		EA	7	6-10 years	
	Lighting - Pendent/Sunace		20				
	Walls - Concrete Block	2nd Floor	1,230	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
_Classro	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	715	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	0-1 year	Water damage
	Doors - Hardware	2nd Floor	1	ĒΑ	6	1-2 years	Metal damage at base
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	720	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	835	SF	7	10+ years	
Classra	om #212 (Regular Classroom)						
CidooiU	AC Units	2nd Floor	4	Ε^	7	6 10 2000	
			1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	5
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	5	0-1 year	Damaged hinge
	Floor - Tile	2nd Floor	720	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	835	SF	7	10+ years	

Campus Name: Gillespie Page : 34 of 41 Assessment Date: 03/04/2024



Catego	ry : Classroom		В	uilding	: Additi		
				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
assroo	m #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	720	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	829	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	3	SF	6	1-2 years	Cracked blocks
	Walls - Coliciete Block	ZHU FIOOI	3	SI	O	1-2 years	Clacked blocks
assroo	m #216 (Vacant)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	710	SF	6	6-10 years	
	Floor - Tile	2nd Floor	10	SF	4	0-1 year	Missing and broken tiles
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	Wildeling and broken theo
	Lighting - Pendent/Surface	2nd Floor	13	EA	6	6-10 years	
	Storage/ Closet	2nd Floor 2nd Floor		SF	7	•	
	Walls - Concrete Block	2nd Floor 2nd Floor	20	SF SF	7	10+ years	
			835			10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
assroo	m #217 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Hardware	2nd Floor	1	EA	6	0-1 year	Loose hardware
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	20000 Haraware
	Floor - Tile	2nd Floor	715	SF	6	6-10 years	
	Floor - Tile	2nd Floor	5	SF	5	1-2 years	Cracks
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	Clacks
			15				
	Lighting - Pendent/Surface	2nd Floor	•	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	835	SF	7	10+ years	
assroo	m #218 (Store Room)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	44	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,092	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1,002	EA	6	10+ years	
				SF	0	. o . youro	



Catego	ry : Classroom		B	uildina	: Additi		
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	23	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Missing cover
	Walls - Concrete Block	2nd Floor	974	SF	7	10+ years	
	Work Sink	2nd Floor	2	EA	7	10+ years	
Naceroo	m #219 (Regular Classroom)						
Jiassiuu	AC Units	2nd Floor	1	EA	7	6 10 years	
				SF		6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	712		7	10+ years	\\/_t_=
	Ceiling - Plaster/Drywall	2nd Floor	8	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	_ 1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	710	SF	6	6-10 years	
	Floor - Tile	2nd Floor	10	SF	4	0-1 year	Cracks
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	835	SF	7	10+ years	
Classroo	m #220 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	22	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	1,088	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	4	SF	5	0-1 year	Loose tiles
	Chalk Board	2nd Floor	20	LF	4	2-5 years	20000 11100
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,082	SF	6	6-10 years	
	Floor - Tile	2nd Floor	10	SF	4	<u>-</u>	Missing and broken tiles
				EA	7	0-1 year	Missing and broken tiles
	Lighting - Pendent/Surface	2nd Floor	21			6-10 years	Minaton
	Lighting - Pendent/Surface	2nd Floor	3	EA	5	1-2 years	Missing covers
	Walls - Concrete Block	2nd Floor	974	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Catego	ry : Interior		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor	nem - Type	Location	Quantity	OON	Kank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	3,021	SF	7	10+ years	
	Ceiling - Splined	1st Floor	851	SF	7	10+ years	
	Doors - Side-lite	1st Floor	39	SF	7	10+ years	
	Doors - Store Front	1st Floor	4	EA	7	10+ years	
	Doors - Transom Window	1st Floor	45	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	1	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
				SF	7	-	
	Floor - Terrazzo	1st Floor	1.015	OF.	,	10+ years	
		1st Floor 1st Floor	1,015 265	SF SF	6	10+ years 6-10 years	



Catego	ry : Interior		В	uilding	: Additi	on	
_				_	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	37	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	122	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,915	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,584	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,223	SF	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	6-10 years	
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	5	0-1 year	Fountain spraying water
	Floor - Tile/Sheet	2nd Floor	3,223	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	27	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	134	EA	6	10+ years	
	Student Lockers - One Tier	2nd Floor	1	EA	5	1-2 years	Door missing
	Student Lockers - One Tier	2nd Floor	18	EA	5	1-2 years	Bent lockers & panels
	Walls - Plaster/Drywall	2nd Floor	1,697	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	3,326	SF	7	10+ years	
Safety							
,	Metal Detector	1st Floor	2	EA	7	6-10 years	
	Security Cameras	1st Floor	5	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North	205	SF	7	10+ years	
	Floor - Terrazzo	North	106	SF	7	10+ years	
	Handrails	North	62	LF	7	10+ years	
	Lighting - Pendent/Surface	North	1	EA	7	6-10 years	
	Stairs - Terrazzo	North	100	LF	7	10+ years	
	Walls - Plaster/Drywall	North	327	SF	7	10+ years	
	Walls - Structural Glazed Tile	North	491	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South	299	SF	6	10+ years	
	Floor - Terrazzo	South	271	SF	7	10+ years	
	Handrails	South	47	LF	7	10+ years	
	Handrails	South	6	LF	4	0-1 year	Missing rail
	Lighting - Pendent/Surface	South	2	EA	7	6-10 years	-
	Stairs - Terrazzo	South	100	LF	7	10+ years	
	Walls - Plaster/Drywall	South	382	SF	7	10+ years	
	Walls - Structural Glazed Tile	South	553	SF	7	10+ years	



Category : Site Building : Site

Category : Site							
	N T	l continu	0	HOM	Danila	Recommend	0
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ivil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	3	EΑ	5	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	2	EΑ	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	7	EA	6	10+ years	
encing							
	Fencing - Chain Link	Entire Site	1,332	LF	5	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	40	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	483	LF	4	1-2 years	Corroded
	Fencing - New Standard Ornamental	Entire Site	6	LF	4	1-2 years	Broken
andsca	pe						
	Benches	Entire Site	2	EA	5	10+ years	
	Landscape - Grass	Entire Site	32,377	SF	6	10+ years	
	Parkway trees	Entire Site	19	EA	6	10+ years	
	Parkway trees	Entire Site	1	EA	4	1-2 years	Missing
	Planting Beds/ Area	Entire Site	2,704	SF	6	10+ years	ŭ
	Play Area - Hardscape- Asphalt	Entire Site	12,374	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	5,168	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	350	SF	5	0-1 year	Cracking. Trees root damage
	Retaining Wall - Concrete	Entire Site	192	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	140	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	310	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	20	SF	5	1-2 years	Cracking
	Retaining Wall - Concrete	Entire Site	40	SF	4	1-2 years	Cracking
	Trash Receptacles	Entire Site	3	EA	6	10+ years	Ordoning
arking	Lot						
y	Surface - Asphalt	Parking Lot- East	23,450	SF	6	10+ years	
	Surface - Asphalt	Parking Lot- East	1,200	SF	5	0-1 year	Cracking/potholes
	Surface - Concrete	Parking Lot- East	4,785	SF	7	10+ years	31
	Surface - Asphalt	SE parking lot	2,138	SF	6	10+ years	
aygrou	und						
, 5	Equipment - School Age 5-12	SE site	1	EA	6	6-10 years	
	Surface - Poured Surface	SE site	2,500	SF	6	6-10 years	
	Equipment - Pre K 3-5	SW site	_,	EΑ	5	10+ years	Seesaw is not secured to the floo
	Surface - Poured Surface	SW site	2,500	SF	6	6-10 years	
idewall	SS.						
		Entire Site	521	LF	6	10+ years	

Campus Name: Gillespie Page : 38 of 41 Assessment Date: 03/04/2024



Catego	ry : Site	В	uilding				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Internal Walks	Entire Site	80	LF	4	1-2 years	Cracking/uneven
	Sidewalks - Perimeter Sidewalks	Entire Site	200	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	17,351	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	200	SF	5	1-2 years	Upheaving/cracking
Signage							
0 0	Flag Pole - Flag Pole	Site West and South	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/	Site West and South	1	EA	6	10+ years	
	LED						
	Monument - Building Mounted Cut Letter	Site West and South	3	EA	6	10+ years	
	Sign					-	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Gillespie Page: 39 of 41 Assessment Date: 03/04/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main			110	1100000	(0.)	7	700		
Counseling Room	Regular Classroom	2nd Floor	252	252	715	168	55	N	Υ
Kindergarten	Pre School	1st Floor	102	102	828	203	14	Y	Y
Kindergarten	Regular Classroom	1st Floor	154	154	1,058	252	83	N	Y
Kindergarten	Regular Classroom	1st Floor	155	155	684	168	55	N	Y
Kindergarten	Regular Classroom	1st Floor	157	157	704	168	55	N	Υ
Office	Regular Classroom	1st Floor	103	103	713	174	12	Y	N
Regular Classroom	Regular Classroom	1st Floor	105	105	713	174	12	Y	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	713	174	12	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	713	174	12	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	713	174	12	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	713	174	12	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	713	174	12	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	713	174	12	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	253	253	704	168	55	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	254	254	690	168	55	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	255	255	675	168	55	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	256	256	714	168	55	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	257	257	712	168	55	N	Υ
Store Room	Regular Classroom	1st Floor	101	101	713	174	12	Υ	N
Store Room	Regular Classroom	1st Floor	104	104	713	174	12	Υ	Υ
Store Room	Regular Classroom	1st Floor	106	106	713	174	12	Υ	N
Store Room	Regular Classroom	1st Floor	107	107	713	174	12	Υ	N
Store Room	Regular Classroom	1st Floor	153	153	704	168	55	N	Υ
Store Room	Regular Classroom	1st Floor	156	156	714	168	55	N	Υ
Store Room	Regular Classroom	2nd Floor	201	201	713	174	87	N	N
Store Room	Regular Classroom	2nd Floor	203	203	713	174	12	Υ	Υ
Building : Addition									
Computer Lab	Regular Classroom	2nd Floor	220	220	1,092	236	22	Υ	N
Other Instructional Use	Regular Classroom	1st Floor	118	118	1,092	238	22	Υ	Y
Regular Classroom	Regular Classroom	1st Floor	114	114	720	173	16	Υ	Y
Regular Classroom	Regular Classroom	1st Floor	116	116	720	173	16	Υ	Y
Regular Classroom	Regular Classroom	1st Floor	120	120	1,092	238	22	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	720	173	16	Υ	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	720	173	16	N	Y
Regular Classroom	Regular Classroom	2nd Floor	214	214	720	173	16	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	217	217	720	173	16	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	219	219	720	173	16	Υ	Y

Campus Name: Gillespie Page: 40 of 41 Assessment Date: 03/04/2024



Classroom Summary

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Science	Regular Classroom	2nd Floor	209	209	997	225	65	Υ	N
Store Room	Art Room	2nd Floor	218	218	1,092	236	22	Υ	N
Store Room	Regular Classroom	1st Floor	117	117	720	173	16	Υ	Υ
Store Room	Regular Classroom	1st Floor	119	119	720	120	52	N	N
Vacant	Regular Classroom	2nd Floor	216	216	720	173	22	Y	N

Page : 41 of 41 Campus Name: Gillespie Assessment Date: 03/04/2024