

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <http://www.cps.edu/facilityassessment>.

| Campus Summary | | | |
|---------------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1978 | 3 | 60,718 |
| Campus Total | | | 60,718 |

Category : Exterior

Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------|---------------------------------------|----------|----------|-----|------|-----------------------|--|
| Entrance | | | | | | | |
| | Entrance Control - Audio and Video | 1 | 1 | EA | 7 | 6-10 years | |
| | Exterior Doors - Side lite | 1 | 4 | EA | 6 | 10+ years | Quantity changed to match current observations |
| | Exterior Doors - Store Front | 1 | 4 | EA | 5 | 6-10 years | |
| | Exterior Doors - Transom Lite | 1 | 6 | EA | 7 | 10+ years | |
| | Power Door Operator and Controls | 1 | 2 | EA | 7 | 6-10 years | Quantity changed to match current observations |
| | Exterior Doors - Store Front | 2 | 2 | EA | 6 | 6-10 years | |
| | Exterior Doors - Transom Lite | 2 | 2 | EA | 6 | 10+ years | |
| | Ramp Handrail - Steel_Ramp Handrail | 2 | 64 | LF | 6 | 10+ years | |
| | Ramps - Concrete | 2 | 20 | LF | 6 | 10+ years | |
| | Ramps - Concrete | 2 | 12 | LF | 5 | 0-1 year | Cracking/chipping |
| | Entrance Control - Audio and Video | 3 | 1 | EA | 6 | 2-5 years | |
| | Exterior Doors - Side lite | 3 | 3 | EA | 6 | 6-10 years | |
| | Exterior Doors - Store Front | 3 | 2 | EA | 5 | 6-10 years | |
| | Exterior Doors - Transom Lite | 3 | 2 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 3 | 45 | LF | 6 | 10+ years | |
| | Power Door Operator and Controls | 3 | 1 | EA | 7 | 2-5 years | |
| | Ramp Handrail - Steel_Ramp Handrail | 3 | 96 | LF | 6 | 10+ years | |
| | Ramps - Concrete | 3 | 48 | LF | 6 | 10+ years | |
| | Stair Handrail - Steel_Stair Handrail | 3 | 12 | LF | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 4 | 2 | EA | 6 | 6-10 years | |
| | Exterior Doors - Transom Lite | 4 | 1 | EA | 6 | 6-10 years | |
| | Exterior Stairs - Concrete | 4 | 30 | LF | 6 | 10+ years | |

Category : Exterior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------------------|---|-----------------|----------|-----|------|-----------------------|---|
| | Exterior Doors - Store Front | 5 | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | 6 | 2 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 7 | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 7 | 38 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 8 | 2 | EA | 7 | 10+ years | Newly replaced |
| Foundation | | | | | | | |
| | Foundation - Concrete | Entire Building | 910 | LF | 7 | 10+ years | |
| | Superstructure - Steel | Entire Building | 59,150 | SF | 7 | 10+ years | |
| Lighting | | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 15 | EA | 6 | 6-10 years | |
| | Exterior Lighting - Wall Mounted | Entire Building | 23 | EA | 6 | 6-10 years | |
| Roof System | | | | | | | |
| | Access Ladder - Metal | 1 | 1 | EA | 7 | 10+ years | |
| | Coping - Stone | 1 | 159 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | 1 | 32 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | 1 | 159 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | 1 | 4,900 | SF | 4 | 1-2 years | Cracking/bubbling/open seems throughout. |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 1 | 4,900 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | 2 | 1 | EA | 7 | 10+ years | |
| | Coping - Metal | 2 | 95 | LF | 6 | 6-10 years | Added to match current observations |
| | Coping - Stone | 2 | 253 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | 2 | 87 | LF | 7 | 10+ years | |
| | Parapet - 16" - 30" Height | 2 | 163 | LF | 6 | 10+ years | |
| | Parapet - Parapet > 30" | 2 | 90 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | 2 | 6,500 | SF | 4 | 1-2 years | Cracking/bubbling/ open seems throughout. |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 2 | 6,500 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | 3 | 1 | EA | 7 | 10+ years | |
| | Coping - Stone | 3 | 652 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | 3 | 240 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | 3 | 652 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | 3 | 15,484 | SF | 4 | 1-2 years | Cracking/bubbling/open seems throughout. |
| | Roof Hatch - Metal | 3 | 1 | EA | 7 | 10+ years | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 3 | 15,484 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | 4 | 1 | EA | 7 | 10+ years | |

Category : Exterior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---|----------|----------|-----|------|-----------------------|--|
| | Coping - Stone | 4 | 141 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | 4 | 58 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | 4 | 141 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | 4 | 1,705 | SF | 4 | 1-2 years | Cracking/bubbling/open seems throughout. |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | 4 | 1,705 | SF | 7 | 10+ years | |

Walls

| | | | | | | | |
|--|------------------------|-----------------|--------|----|---|-----------|----------------------|
| | Exterior Walls - Brick | Entire Building | 33,000 | SF | 7 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 550 | SF | 4 | 1-2 years | Cracking/open joints |

Windows

| | | | | | | | |
|--|---|-----------------|-------|----|---|------------|--|
| | Guard - Guards perforated | Entire Building | 850 | SF | 6 | 6-10 years | |
| | Lintels - Steel | Entire Building | 395 | LF | 5 | 6-10 years | |
| | Windows - Casement Aluminum Double-pane | Entire Building | 330 | SF | 7 | 10+ years | |
| | Windows - Louver | Entire Building | 144 | SF | 5 | 2-5 years | |
| | Windows - Sash Aluminum Double-pane | Entire Building | 1,790 | SF | 7 | 6-10 years | |

Category : Electrical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------------|---|-----------------|----------|-----|------|-----------------------|--|
| Emergency System | | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 2 | EA | 6 | 6-10 years | No visible asset tag |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | 2-5 years | No visible asset tag |
| | Exit Signs - Auditorium | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 12 | EA | 6 | 6-10 years | |
| | Exit Signs - Gym | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Exit Signs - Lunchroom | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Security System - CCTV | Entire Building | 59,150 | SF | 4 | 2-5 years | Only camera working is at the front door |
| | Security System - Intrusion Detection | Entire Building | 59,150 | SF | 5 | 2-5 years | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 6 | EA | 6 | 6-10 years | |
| | Emergency A/C Power - Auditorium and Aisle Lighting | Entire Building | 2,500 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 8,788 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Gym | Entire Building | 4,000 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 1,814 | SF | 6 | 10+ years | |
| | Emergency A/C Power - Students Toilets | Entire Building | 396 | SF | 6 | 10+ years | |
| | Emergency Generator- Outdoor- Diesel - | Site - East | 1 | EA | 6 | 10+ years | |

Category : Electrical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---------------------------|--|-----------------|----------|-----|------|-----------------------|--|
| | 151 - 200 KW | | | | | | |
| <u>Main Service</u> | | | | | | | |
| | Main Electrical Service - 2000 A 277/480/3PH | Electrical Room | 1 | EA | 6 | 10+ years | |
| | Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | 6-10 years | No asset tag visible |
| | PA System | Entire Building | 59,159 | SF | 6 | 6-10 years | No visible asset tag. No speakers visible in hallways or classrooms, most likely in ceiling. |
| <u>Power Distribution</u> | | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 6 | EA | 6 | 6-10 years | Some electrical panels do not have visible asset tags |
| | Lighting and Power Panels - Above 100 A | Entire Building | 11 | EA | 6 | 6-10 years | Some electrical panels do not have visible asset tags |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Main Distribution Panels - Less than 400 amp | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 6 | 6-10 years | No visible asset tag |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 6 | 6-10 years | No visible asset tag |

Category : Fire Protection
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------|--------------------------|-----------------|----------|-----|------|-----------------------|-----------------------|
| <u>Fire Alarm</u> | | | | | | | |
| | Fire ALarm Anunciator | Entire Building | 1 | EA | 7 | 6-10 years | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Fire Alarm Strobe Lights | Entire Building | 59,150 | SF | 6 | 6-10 years | |
| | Fire Alarm_System | Entire Building | 59,150 | SF | 6 | 6-10 years | No visible asset tags |

Category : Mechanical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------------|-----------------------------|-------------|----------|-----|------|-----------------------|---|
| <u>Air Conditioning</u> | | | | | | | |
| | Cooling Tower - Closed Cell | Boiler Room | 1 | EA | 5 | 6-10 years | Per engineer, chiller in good working condition |
| | Glycol Feed | Boiler Room | 1 | EA | 5 | 6-10 years | No asset tag visible |

Air Handling Systems

Category : Mechanical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------------------------|---|-----------------|----------|-----|------|-----------------------|--|
| | Roof Top Unit-Single Zone-Roof Mounted-Electric and DX Cooling with Self Contained Compressor - 5 - 10 tons | Roof | 1 | EA | 6 | 6-10 years | |
| | Roof Top Unit-Single Zone-Roof Mounted-Electric and DX Cooling with Self Contained Compressor - 5 - 10 tons | Roof | 1 | EA | 6 | 6-10 years | |
| | Roof Top Unit-Single Zone-Roof Mounted-Electric and DX Cooling with Self Contained Compressor - 5 - 10 tons | Roof | 1 | EA | 6 | 6-10 years | |
| | Roof Top Unit-Single Zone-Roof Mounted-Electric and DX Cooling with Self Contained Compressor - 5 - 10 tons | Roof | 1 | EA | 6 | 6-10 years | |
| | Roof Top Unit-Single Zone-Roof Mounted-Electric and DX Cooling with Self Contained Compressor - 5 - 10 tons | Roof | 1 | EA | 6 | 6-10 years | |
| | Roof Top Unit-Single Zone-Roof Mounted-Electric and DX Cooling with Self Contained Compressor - 5 - 10 tons | Roof | 1 | EA | 6 | 6-10 years | |
| | Roof Top Unit-Single Zone-Roof Mounted-Electric and DX Cooling with Self Contained Compressor - 5 - 10 tons | Roof | 1 | EA | 5 | 6-10 years | Bad motor on this unit. Work order in for repair. |
| Boiler Systems | | | | | | | |
| | Boiler Auxiliary- Electric- Hot Water Boiler - 1001 - 2000 MBH | Boiler Room | 1 | EA | 6 | 6-10 years | Auxiliary appear to be in good working condition upon observation |
| | Chemical Pot Feeder | Boiler Room | 1 | EA | 5 | 6-10 years | No visible asset tag |
| | Combustion Dampers | Boiler Room | 4 | EA | 5 | 6-10 years | |
| | Electric- Hot Water Boiler - 1001 - 2000 MBH | Boiler Room | 1 | EA | 6 | 6-10 years | Per engineer, boilers in good operating condition |
| Heating Devices | | | | | | | |
| | Cabinet Heaters - With Electric Coil | Entire Building | 7 | EA | 6 | 6-10 years | No asset tag visible |
| | PTAC - Electric Heating and Self Contained Cooling | Entire Building | 3 | EA | 6 | 6-10 years | Principal's office, assistant, principal office, engineers office. |
| | Unit Heater - Electric | Entire Building | 3 | EA | 6 | 6-10 years | |
| Mechanical Plumbing | | | | | | | |
| | Hot Water Pump - 10 - 20 HP | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump - 10 - 20 HP | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Condenser Pump - Less than 10 | Boiler Room | 1 | EA | 6 | 6-10 years | Per engineer pump in good working condition. No asset tag visible |
| | Hydronic Supply and Return - Steel | Entire Building | 300 | LF | 6 | 6-10 years | |

Category : Mechanical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------------------------|---|-----------------|----------|-----|------|-----------------------|--|
| <u>Temperature Control</u> | | | | | | | |
| | Electric Controls | Entire Building | 59,150 | SF | 6 | 6-10 years | |
| | Electric Thermostat | Entire Building | 4 | EA | 6 | 6-10 years | |
| | Electric Thermostat | Entire Building | 49 | EA | 5 | 2-5 years | Electric thermostats are in hallways and main office auditorium, gym lunch room, lunch room kitchen |
| <u>Unit Ventilation</u> | | | | | | | |
| | Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water | Entire Building | 45 | EA | 6 | 6-10 years | Some units are tagged, some units are not |
| <u>Ventilation</u> | | | | | | | |
| | Exhaust Fans- Indoor - Less than 500 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 1 | EA | 5 | 2-5 years | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 10 | EA | 5 | 6-10 years | A few have bad motors. Work order in for it to be repaired. Some are decommissioned, and non-operable. Missing cover |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 1 | EA | 4 | 1-2 years | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Entire Building | 5 | EA | 6 | 6-10 years | |
| | Type I Exhaust Hood- Kitchen | Entire Building | 1 | EA | 6 | 10+ years | No asset tag visible |
| | Type II Exhaust Hood- Warming Kitchen | Entire Building | 1 | EA | 6 | 10+ years | No asset tag visible |

Category : Plumbing
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|------------------|---|-----------------|----------|-----|------|-----------------------|---|
| <u>Hot Water</u> | | | | | | | |
| | Electric Heater - 20 - 50 KW | Entire Building | 1 | EA | 6 | 6-10 years | |
| <u>Piping</u> | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 59,160 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 59,160 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 59,160 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 59,160 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 59,160 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 59,160 | SF | 6 | 6-10 years | No leaking reported. In good condition per observation, most likely repaired. |

Category : Plumbing
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-----------------|-----------------|----------|-----|------|-----------------------|----------|
| | Sanitary Piping | Entire Building | 59,160 | SF | 6 | 6-10 years | |
| | Storm Piping | Entire Building | 59,160 | SF | 6 | 6-10 years | |
| | Vent Piping | Entire Building | 59,160 | SF | 6 | 6-10 years | |

Pumps

| | | | | | | |
|--------------------------------------|-----------|---|----|---|------------|-----------------------------|
| Pumps - Domestic Booster Pump-Duplex | 1st Floor | 1 | EA | 5 | 6-10 years | Closet in engineers office |
| Pumps - Sump-Simplex | 1st Floor | 1 | EA | 6 | 6-10 years | Pump located under elevator |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------------------------------------|-----------------------------|-----------|----------|-----|------|-----------------------|---------------------|
| Administrative Suites/Offices | | | | | | | |
| | Ceiling - Lay-in | 116 | 46 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 116 | 12 | SF | 4 | 0-1 year | Water damaged |
| | Doors - Wood Doors inclu hw | 116 | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 116 | 58 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 116 | 1 | EA | 7 | 6-10 years | |
| | Power Distribution | 116 | 4 | EA | 7 | 10+ years | |
| | Storage/ Closet | 116 | 40 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 116 | 210 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 125 | 219 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 125 | 8 | SF | 4 | 0-1 year | Water damaged tiles |
| | Doors - Wood Doors inclu hw | 125 | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 125 | 227 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 125 | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 125 | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 125 | 498 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 136 | 80 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 136 | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 136 | 80 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 136 | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 136 | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 136 | 324 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 139 | 268 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 139 | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 139 | 268 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 139 | 6 | EA | 7 | 6-10 years | |
| | Power Distribution | 139 | 8 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 139 | 528 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 882 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 15 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 1st Floor | 882 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 11 | EA | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-----------------------------|----------------------------|----------|-----|------|-----------------------|--------------|
| | Lighting - Lay-in | 1st Floor | 4 | EA | 6 | 6-10 years | |
| | Power Distribution | 1st Floor | 22 | EA | 7 | 10+ years | |
| | Storage/ Closet | 1st Floor | 9 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,700 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor - Faculty Lounge | 160 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor - Faculty Lounge | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor - Faculty Lounge | 160 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor - Faculty Lounge | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 1st Floor - Faculty Lounge | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor - Faculty Lounge | 242 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor - Faculty Lounge | 221 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | Kitchen Manager | 52 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Kitchen Manager | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | Kitchen Manager | 52 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Kitchen Manager | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | Kitchen Manager | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Kitchen Manager | 200 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Office A | 62 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Office A | 4 | SF | 4 | 0-1 year | Water damage |
| | Floor - Carpet | Office A | 66 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | Office A | 1 | EA | 7 | 6-10 years | |
| | Power Distribution | Office A | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Office A | 295 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Office B | 84 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Office B | 4 | SF | 5 | 1-2 years | Broken tile |
| | Doors - Wood Doors inclu hw | Office B | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Office B | 88 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Office B | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | Office B | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Office B | 322 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Office C | 88 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Office C | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Office C | 88 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | Office C | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | Office C | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Office C | 322 | SF | 7 | 10+ years | |

Auditorium & Theater

| | | | | | |
|-----------------------------|---------------------------------|-------|----|---|------------|
| Ceiling - Lay-in | KIVA - Enter on 1st + 2nd floor | 3,160 | SF | 7 | 10+ years |
| Doors - Transom Window | KIVA - Enter on 1st + 2nd floor | 28 | SF | 7 | 10+ years |
| Doors - Wood Doors inclu hw | KIVA - Enter on 1st + 2nd floor | 4 | EA | 7 | 10+ years |
| Floor - Carpet | KIVA - Enter on 1st + 2nd floor | 2,700 | SF | 6 | 6-10 years |
| Lighting - Lay-in | KIVA - Enter on 1st + 2nd floor | 53 | EA | 6 | 10+ years |
| Sound System | KIVA - Enter on 1st + 2nd floor | 1 | EA | 7 | 10+ years |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------------------------------------|-----------------------------|---------------------------------|----------|-----|------|-----------------------|-------------------------|
| | Stage | KIVA - Enter on 1st + 2nd floor | 460 | SF | 7 | 10+ years | |
| | Stage Lift | KIVA - Enter on 1st + 2nd floor | 1 | EA | 7 | 10+ years | |
| | Stage Lighting System | KIVA - Enter on 1st + 2nd floor | 1 | EA | 7 | 10+ years | |
| | Stage-Stairs - Tile | KIVA - Enter on 1st + 2nd floor | 36 | LF | 7 | 10+ years | |
| | Stairs - Tile | KIVA - Enter on 1st + 2nd floor | 112 | LF | 7 | 10+ years | |
| | Storage/ Closet | KIVA - Enter on 1st + 2nd floor | 250 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | KIVA - Enter on 1st + 2nd floor | 2,335 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | KIVA - Enter on 1st + 2nd floor | 240 | SF | 7 | 10+ years | |
| Gymnasias | | | | | | | |
| | Ceiling - Exposed | 1st Floor | 4,000 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 28 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 6 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 4,000 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 28 | EA | 7 | 6-10 years | Lighting count adjusted |
| | Lighting - Pendent/Surface | 1st Floor | 20 | EA | 5 | 1-2 years | Lights not working |
| | Scoreboards | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Sound System | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 60 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 5,370 | SF | 6 | 10+ years | |
| Kitchen | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 956 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 4 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | 1st Floor | 956 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 27 | EA | 7 | 6-10 years | |
| | Serving Line | 1st Floor | 23 | LF | 7 | 10+ years | |
| | Storage/ Closet | 1st Floor | 205 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,400 | SF | 7 | 10+ years | |
| Library | | | | | | | |
| | Casework | 2nd Floor | 135 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 2,328 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 72 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 14 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 2,400 | SF | 6 | 2-5 years | |
| | Lighting - Lay-in | 2nd Floor | 47 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 2,160 | SF | 7 | 10+ years | |
| Lunch & Multipurpose Room | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,814 | SF | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---------------------------|-----------------------------|-----------------------------|----------|-----|------|-----------------------|----------------------------|
| | Floor - Tile | 1st Floor | 1,814 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 25 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 1,528 | SF | 7 | 10+ years | |
| <hr/> | | | | | | | |
| MDF_IDF | | | | | | | |
| | Doors - Wood Doors inclu hw | 314 | 1 | EA | 7 | 10+ years | Some missing ceiling tiles |
| | Finishes | 314 | 100 | SF | 5 | 6-10 years | |
| | Other Cooling Unit | 314 | 1 | EA | 7 | 6-10 years | |
| <hr/> | | | | | | | |
| Mechanical/ Service Rooms | | | | | | | |
| | Janitor's Closet | 1st Floor | 76 | SF | 5 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 236 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 450 | SF | 7 | 10+ years | |
| | Vaults | 1st Floor | 400 | SF | 7 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 28 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 75 | SF | 7 | 10+ years | |
| | Janitor's Closet | 3rd Floor | 28 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 30 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 800 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 30 | SF | 7 | 10+ years | |
| | Storage Room | 3rd Floor | 75 | SF | 7 | 10+ years | |
| | Storage Room | 3rd Floor | 600 | SF | 7 | 10+ years | |
| | Janitor's Closet | Loading Dock/Receiving Area | 9 | SF | 7 | 10+ years | |
| | Loading Docks | Loading Dock/Receiving Area | 190 | SF | 7 | 10+ years | |
| | Storage Room | Loading Dock/Receiving Area | 76 | SF | 7 | 10+ years | |
| <hr/> | | | | | | | |
| Restroom | | | | | | | |
| | Accessories | 140 | 12 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 140 | 12 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 140 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | 140 | 12 | SF | 7 | 10+ years | |
| | Lighting - Wall Mounted | 140 | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 140 | 135 | SF | 7 | 10+ years | |
| | Water Closet | 140 | 1 | EA | 7 | 10+ years | |
| | Accessories | 141 | 12 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 141 | 12 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 141 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | 141 | 12 | SF | 7 | 10+ years | |
| | Lighting - Wall Mounted | 141 | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 141 | 135 | SF | 7 | 10+ years | |
| | Water Closet | 141 | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor | 154 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 154 | SF | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-----------------------------|------------------------|----------|-----|------|-----------------------|---------------------------------|
| | Floor - Tile Quarry | 1st Floor | 154 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 4 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Urinals | 1st Floor | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 407 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor | 154 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 154 | SF | 7 | 10+ years | |
| | Floor - Tile Quarry | 1st Floor | 154 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 4 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 405 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor | 4 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor | 154 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 154 | SF | 7 | 10+ years | |
| | Floor - Tile Quarry | 2nd Floor | 154 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 4 | EA | 7 | 10+ years | |
| | Partitions | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Urinals | 2nd Floor | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 405 | SF | 7 | 2-5 years | Paint needed but good condition |
| | Water Closet | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor | 154 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor | 154 | SF | 7 | 10+ years | |
| | Floor - Tile Quarry | 2nd Floor | 154 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 4 | EA | 7 | 6-10 years | |
| | Partitions | 2nd Floor | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 405 | SF | 7 | 2-5 years | Good condition needs painting |
| | Water Closet | 2nd Floor | 4 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor - Accessible | 37 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor - Accessible | 37 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor - Accessible | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | 2nd Floor - Accessible | 37 | SF | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-----------------------------|------------------------|----------|-----|------|-----------------------|-------------------------------|
| | Floor Drain | 2nd Floor - Accessible | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd Floor - Accessible | 1 | EA | 7 | 10+ years | |
| | Lighting - Wall Mounted | 2nd Floor - Accessible | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor - Accessible | 189 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor - Accessible | 1 | EA | 7 | 10+ years | |
| | Accessories | 2nd Floor - Unisex | 65 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd Floor - Unisex | 65 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor - Unisex | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | 2nd Floor - Unisex | 65 | SF | 6 | 10+ years | |
| | Lavatory | 2nd Floor - Unisex | 1 | EA | 7 | 10+ years | |
| | Lighting - Wall Mounted | 2nd Floor - Unisex | 1 | EA | 7 | 10+ years | |
| | Partitions | 2nd Floor - Unisex | 1 | EA | 7 | 6-10 years | |
| | Urinals | 2nd Floor - Unisex | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor - Unisex | 216 | SF | 7 | 10+ years | |
| | Water Closet | 2nd Floor - Unisex | 1 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor | 154 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 154 | SF | 7 | 10+ years | |
| | Floor - Tile Quarry | 3rd Floor | 154 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 4 | EA | 7 | 10+ years | |
| | Partitions | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Urinals | 3rd Floor | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 407 | SF | 6 | 10+ years | Good condition needs painting |
| | Water Closet | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Accessories | 3rd Floor | 154 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd Floor | 154 | SF | 7 | 10+ years | |
| | Floor - Tile Quarry | 3rd Floor | 154 | SF | 7 | 10+ years | |
| | Floor Drain | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 3rd Floor | 2 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 4 | EA | 7 | 10+ years | |
| | Partitions | 3rd Floor | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 405 | SF | 7 | 10+ years | |
| | Water Closet | 3rd Floor | 4 | EA | 7 | 10+ years | |
| | Accessories | Main Office | 23 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Main Office | 23 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Main Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | Main Office | 23 | SF | 7 | 6-10 years | |
| | Lavatory | Main Office | 1 | EA | 7 | 10+ years | |
| | Lighting - Wall Mounted | Main Office | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Main Office | 150 | SF | 7 | 10+ years | |
| | Water Closet | Main Office | 1 | EA | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---------------------------------|--------------------------|----------|-----|------|-----------------------|--------------------------|
| | Accessories | Principal's Office | 30 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Principal's Office | 30 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Principal's Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | Principal's Office | 30 | SF | 7 | 10+ years | |
| | Lavatory | Principal's Office | 1 | EA | 7 | 10+ years | |
| | Lighting - Wall Mounted | Principal's Office | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | Principal's Office | 112 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Principal's Office | 32 | SF | 7 | 10+ years | |
| | Water Closet | Principal's Office | 1 | EA | 7 | 10+ years | |
| | Accessories | Receiving Dock - Men's | 64 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Receiving Dock - Men's | 64 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Receiving Dock - Men's | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Receiving Dock - Men's | 60 | SF | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Receiving Dock - Men's | 4 | SF | 5 | 1-2 years | Chipped tiles near drain |
| | Floor Drain | Receiving Dock - Men's | 1 | EA | 7 | 10+ years | |
| | Lavatory | Receiving Dock - Men's | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Receiving Dock - Men's | 1 | EA | 7 | 10+ years | |
| | Lighting - Wall Mounted | Receiving Dock - Men's | 1 | EA | 7 | 6-10 years | |
| | Partitions | Receiving Dock - Men's | 1 | EA | 7 | 10+ years | |
| | Showers | Receiving Dock - Men's | 1 | EA | 7 | 10+ years | |
| | Student Lockers - One Tier | Receiving Dock - Men's | 4 | EA | 7 | 10+ years | |
| | Urinals | Receiving Dock - Men's | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Receiving Dock - Men's | 200 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Receiving Dock - Men's | 78 | SF | 7 | 10+ years | |
| | Water Closet | Receiving Dock - Men's | 1 | EA | 7 | 10+ years | |
| | Accessories | Receiving Dock - Women's | 62 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Receiving Dock - Women's | 62 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Receiving Dock - Women's | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | Receiving Dock - Women's | 62 | SF | 7 | 10+ years | |
| | Floor Drain | Receiving Dock - Women's | 1 | EA | 7 | 10+ years | |
| | Lavatory | Receiving Dock - Women's | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Receiving Dock - Women's | 1 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | Receiving Dock - Women's | 1 | EA | 7 | 10+ years | |
| | Partitions | Receiving Dock - Women's | 1 | EA | 7 | 10+ years | |
| | Showers | Receiving Dock - Women's | 1 | EA | 7 | 10+ years | |
| | Student Lockers - One Tier | Receiving Dock - Women's | 3 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Receiving Dock - Women's | 226 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Receiving Dock - Women's | 78 | SF | 6 | 10+ years | |
| | Water Closet | Receiving Dock - Women's | 1 | EA | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---------------------------------|-------------|----------|----------|-----|------|-----------------------|----------|
| Classroom #140/141 (Pre School) | | | | | | | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------------------------------------|-----------------------------|-----------|----------|-----|------|-----------------------|--------------|
| | Casework | 1st Floor | 60 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 2,190 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 2,190 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 38 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 1,600 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st Floor | 200 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |
| Classroom #144 (Kindergarten) | | | | | | | |
| | Casework | 1st Floor | 21 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 852 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 852 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 952 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classroom #145 (Kindergarten) | | | | | | | |
| | Casework | 1st Floor | 21 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 844 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 852 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 952 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classroom #146 (Kindergarten) | | | | | | | |
| | Casework | 1st Floor | 21 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 865 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 10 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 1st Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 875 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 18 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 970 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|----------------|
| Classroom #147 (Kindergarten) | | | | | | | |
| | Casework | 1st Floor | 23 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 928 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 928 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 1,000 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classroom #148 (Store Room) | | | | | | | |
| | Casework | 1st Floor | 26 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 863 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 12 | SF | 4 | 0-1 year | Water damaged |
| | Chalk Board | 1st Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 20 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 875 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 19 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 950 | SF | 6 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 10 | SF | 5 | 1-2 years | Cmu seperating |
| | Work Sink | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Classroom #151 (Regular Classroom) | | | | | | | |
| | Casework | 1st Floor | 27 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 539 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 10 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 1st Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 549 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 10 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 765 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classroom #214 (Office) | | | | | | | |
| | Casework | 2nd Floor | 11 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 360 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 5 | SF | 5 | 1-2 years | Water damage |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 7 | SF | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|------------------|
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 365 | SF | 5 | 2-5 years | |
| | Lighting - Lay-in | 2nd Floor | 11 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 35 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 670 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #215 (Faculty Lounge) | | | | | | | |
| | Casework | 2nd Floor | 20 | LF | 7 | 6-10 years | |
| | Casework | 2nd Floor | 8 | LF | 4 | 1-2 years | Damaged cabinets |
| | Ceiling - Lay-in | 2nd Floor | 652 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 652 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 645 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 300 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 3 | EA | 7 | 10+ years | |
| Classroom #216 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 24 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 546 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 4 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 2nd Floor | 8 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 550 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 15 | SF | 7 | 10+ years | Blocked |
| | Walls - Concrete Block | 2nd Floor | 530 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 290 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 10 | SF | 5 | 1-2 years | Damaged wall |
| Classroom #217 (Other Instructional Use) | | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 760 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 20 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 780 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 9 | EA | 6 | 6-10 years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|------------------------------------|-----------------------------|-----------|----------|-----|------|-----------------------|---|
| | Lighting - Lay-in | 2nd Floor | 9 | EA | 5 | 1-2 years | Half of lighting not turning on when switch engaged |
| | Marker Board | 2nd Floor | 18 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 907 | SF | 7 | 10+ years | |
| Classroom #218 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 18 | LF | 7 | 10+ years | Damaged tiles Crack in exterior corner |
| | Ceiling - Lay-in | 2nd Floor | 800 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 790 | SF | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 10 | SF | 5 | 1-2 years | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 884 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 16 | SF | 4 | 1-2 years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Classroom #219 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 12 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 800 | SF | 7 | 10+ years | |
| | Chalk Board | 2nd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 800 | SF | 6 | 2-5 years | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 916 | SF | 7 | 10+ years | |
| Classroom #220 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 15 | LF | 7 | 10+ years | Water damage |
| | Ceiling - Lay-in | 2nd Floor | 795 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 5 | SF | 4 | 0-1 year | |
| | Chalk Board | 2nd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 800 | SF | 6 | 2-5 years | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 925 | SF | 7 | 10+ years | |
| Classroom #221 (Regular Classroom) | | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 768 | SF | 7 | 10+ years | Water damage |
| | Ceiling - Lay-in | 2nd Floor | 12 | SF | 4 | 0-1 year | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|--------------|
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 763 | SF | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 17 | SF | 4 | 0-1 year | Broken tiles |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 12 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 900 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 266 | SF | 7 | 10+ years | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #221B (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 14 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 528 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 523 | SF | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 5 | SF | 5 | 1-2 years | Broken tiles |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 540 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 234 | SF | 7 | 10+ years | |
| Classroom #224 (Science Lab Level 3) | | | | | | | |
| | Casework | 2nd Floor | 52 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 920 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 8 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 2nd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Eye Wash Station | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | Floor - Tile | 2nd Floor | 928 | SF | 6 | 6-10 years | |
| | Gas Line | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 18 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 66 | SF | 7 | 10+ years | Locked |
| | Walls - Concrete Block | 2nd Floor | 1,000 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 3 | EA | 7 | 6-10 years | |
| Classroom #226 (Other Instructional Use) | | | | | | | |
| | Casework | 2nd Floor | 10 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 1,087 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 8 | SF | 5 | 1-2 years | Broken tiles |
| | Ceiling - Lay-in | 2nd Floor | 4 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|--------------|
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 525 | SF | 7 | 6-10 years | |
| | Floor - Tile | 2nd Floor | 570 | SF | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 4 | SF | 5 | 1-2 years | Broken |
| | Lighting - Lay-in | 2nd Floor | 16 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 6 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 12 | SF | 7 | 10+ years | Locked |
| | Walls - Concrete Block | 2nd Floor | 1,216 | SF | 7 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #314 (Office) | | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 700 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 7 | SF | 4 | 1-2 years | Water damage |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 707 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 6 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 900 | SF | 7 | 10+ years | |
| Classroom #316 (Music Room) | | | | | | | |
| | Casework | 3rd Floor | 21 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 867 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 8 | SF | 4 | 0-1 year | Water damage |
| | Doors - Side-lite | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 690 | SF | 7 | 6-10 years | |
| | Floor - Tile | 3rd Floor | 185 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 18 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 986 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #317 (Regular Classroom) | | | | | | | |
| | Casework | 3rd Floor | 21 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 852 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 670 | SF | 7 | 6-10 years | |
| | Floor - Tile | 3rd Floor | 182 | SF | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|--------------|
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 952 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #318 (Regular Classroom) | | | | | | | |
| | Casework | 3rd Floor | 15 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 524 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 5 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 529 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 48 | SF | 7 | 10+ years | Locked |
| | Walls - Concrete Block | 3rd Floor | 790 | SF | 7 | 10+ years | |
| Classroom #320 (Regular Classroom) | | | | | | | |
| | Casework | 3rd Floor | 31 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 960 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 2 | SF | 5 | 0-1 year | Missing tile |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 662 | SF | 7 | 6-10 years | |
| | Floor - Tile | 3rd Floor | 300 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,160 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #321 (Regular Classroom) | | | | | | | |
| | Casework | 3rd Floor | 26 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 848 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 4 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 852 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 4 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 952 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|---------------------------|
| Classroom #322 (Regular Classroom) | | | | | | | |
| | Casework | 3rd Floor | 21 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 844 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 8 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 670 | SF | 7 | 6-10 years | |
| | Floor - Tile | 3rd Floor | 182 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 952 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #323 (Regular Classroom) | | | | | | | |
| | Casework | 3rd Floor | 21 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 848 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 4 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 670 | SF | 7 | 6-10 years | |
| | Floor - Tile | 3rd Floor | 182 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 952 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #324 (Store Room) | | | | | | | |
| | Casework | 3rd Floor | 21 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 844 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 8 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 842 | SF | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 10 | SF | 4 | 0-1 year | Missing and damaged tiles |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 6 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 952 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #325 (Other Instructional Use) | | | | | | | |
| | Casework | 3rd Floor | 12 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 553 | SF | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-----------------------------|-----------|----------|-----|------|-----------------------|--------------|
| | Ceiling - Lay-in | 3rd Floor | 3 | SF | 4 | 0-1 year | Water damage |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 435 | SF | 6 | 6-10 years | Ripped |
| | Floor - Carpet | 3rd Floor | 5 | SF | 4 | 1-2 years | |
| | Floor - Tile | 3rd Floor | 116 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 780 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |

Classroom #326 (Regular Classroom)

| | | | | | | | |
|--|-----------------------------|-----------|-------|----|---|------------|--|
| | Casework | 3rd Floor | 22 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 928 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 20 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 928 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 20 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,000 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |

Classroom #328 (Regular Classroom)

| | | | | | | | |
|--|-----------------------------|-----------|-----|----|---|------------|--|
| | Casework | 3rd Floor | 24 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 875 | SF | 7 | 10+ years | |
| | Chalk Board | 3rd Floor | 18 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 735 | SF | 7 | 6-10 years | |
| | Floor - Tile | 3rd Floor | 140 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 19 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 970 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |

Classroom #330 (Store Room)

| | | | | | | | |
|--|-----------------------------|-----------|-----|----|---|------------|--|
| | Ceiling - Exposed | 3rd Floor | 140 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 28 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 140 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd Floor | 4 | EA | 7 | 6-10 years | |
| | Walls - Metal Panel | 3rd Floor | 340 | SF | 7 | 10+ years | |

Category : Interior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend | Comments |
|-------|-------------|----------|----------|-----|------|-----------|----------|
|-------|-------------|----------|----------|-----|------|-----------|----------|

Replacement
Corridor

| | | | | | | |
|--------------------------------------|-----------|-------|----|---|------------|---------------|
| Ceiling - Lay-in | 1st Floor | 3,912 | SF | 7 | 10+ years | Water damage |
| Ceiling - Lay-in | 1st Floor | 4 | SF | 4 | 0-1 year | |
| Doors - Side-lite | 1st Floor | 60 | SF | 7 | 10+ years | |
| Doors - Transom Window | 1st Floor | 30 | SF | 7 | 10+ years | Damaged tiles |
| Doors - Wood Doors include hw | 1st Floor | 9 | EA | 7 | 10+ years | |
| Drinking Fountains - Single Fountain | 1st Floor | 2 | EA | 7 | 6-10 years | |
| Floor - Tile/Sheet | 1st Floor | 3,911 | SF | 7 | 10+ years | |
| Floor - Tile/Sheet | 1st Floor | 5 | SF | 4 | 1-2 years | |
| Lighting - Lay-in | 1st Floor | 46 | EA | 6 | 6-10 years | Water damage |
| Student Lockers - Two Tiers | 1st Floor | 24 | EA | 7 | 10+ years | |
| Walls - Concrete Block | 1st Floor | 4,599 | SF | 6 | 10+ years | |
| Ceiling - Lay-in | 2nd Floor | 2,107 | SF | 7 | 10+ years | |
| Ceiling - Lay-in | 2nd Floor | 10 | SF | 4 | 0-1 year | |
| Doors - Steel Doors incl hw | 2nd Floor | 3 | EA | 7 | 10+ years | |
| Doors - Transom Window | 2nd Floor | 20 | SF | 7 | 10+ years | |
| Drinking Fountains - Single Fountain | 2nd Floor | 2 | EA | 7 | 10+ years | |
| Floor - Tile/Sheet | 2nd Floor | 2,117 | SF | 7 | 10+ years | |
| Lighting - Lay-in | 2nd Floor | 20 | EA | 7 | 6-10 years | |
| Walls - Concrete Block | 2nd Floor | 3,087 | SF | 7 | 10+ years | |
| Ceiling - Lay-in | 3rd Floor | 1,924 | SF | 7 | 10+ years | |
| Doors - Transom Window | 3rd Floor | 60 | SF | 7 | 10+ years | |
| Doors - Wood Doors include hw | 3rd Floor | 3 | EA | 7 | 10+ years | |
| Drinking Fountains - Single Fountain | 3rd Floor | 2 | EA | 7 | 10+ years | |
| Floor - Tile/Sheet | 3rd Floor | 1,924 | SF | 7 | 10+ years | |
| Lighting - Lay-in | 3rd Floor | 17 | EA | 7 | 10+ years | |
| Walls - Concrete Block | 3rd Floor | 2,900 | SF | 7 | 10+ years | |

Safety

| | | | | | | |
|------------------------|-----------------|---|----|---|------------|---|
| Camera Viewing Station | Entire Building | 1 | EA | 7 | 6-10 years | Exterior parking lot camera are old and record onto outdated system |
| Security Cameras | Entire Building | 1 | EA | 5 | 2-5 years | |
| Security Cameras | Entire Building | 3 | EA | 4 | 2-5 years | |

Stairs

| | | | | | | |
|---------------------------------|------------|-------|----|---|------------|--------------|
| Ceiling - Plaster/Drywall | North | 370 | SF | 7 | 10+ years | Large cracks |
| Floor - Tile Ceramic/ Porcelain | North | 285 | SF | 7 | 6-10 years | |
| Handrails | North | 100 | LF | 7 | 10+ years | |
| Lighting - Lay-in | North | 8 | EA | 6 | 6-10 years | |
| Lighting - Wall Mounted | North | 4 | EA | 7 | 6-10 years | |
| Stairs - Tile | North | 198 | LF | 7 | 6-10 years | |
| Walls - Concrete Block | North | 1,925 | SF | 7 | 10+ years | |
| Ceiling - Plaster/Drywall | South East | 440 | SF | 7 | 10+ years | |
| Ceiling - Plaster/Drywall | South East | 8 | SF | 4 | 1-2 years | |
| Floor - Tile Ceramic/ Porcelain | South East | 346 | SF | 7 | 6-10 years | |
| Handrails | South East | 100 | LF | 7 | 10+ years | |

| | | | | | | Replacement | |
|---------------------------------|------------|-------|----|---|------------|-------------|--|
| Lighting - Lay-in | South East | 8 | EA | 7 | 6-10 years | | |
| Lighting - Wall Mounted | South East | 4 | EA | 7 | 6-10 years | | |
| Stairs - Tile | South East | 198 | LF | 7 | 10+ years | | |
| Walls - Concrete Block | South East | 1,925 | SF | 7 | 10+ years | | |
| Ceiling - Plaster/Drywall | South West | 330 | SF | 7 | 10+ years | | |
| Ceiling - Plaster/Drywall | South West | 5 | SF | 4 | 1-2 years | Large crack | |
| Floor - Tile Ceramic/ Porcelain | South West | 200 | SF | 7 | 6-10 years | | |
| Handrails | South West | 100 | LF | 7 | 10+ years | | |
| Lighting - Lay-in | South West | 6 | EA | 7 | 6-10 years | | |
| Lighting - Wall Mounted | South West | 4 | EA | 7 | 6-10 years | | |
| Stairs - Tile | South West | 198 | LF | 7 | 6-10 years | | |
| Walls - Concrete Block | South West | 1,890 | SF | 7 | 10+ years | | |
| Vertical Conveyance | | | | | | | |
| Elevator - Hydraulic Elevator | South | 1 | EA | 6 | 6-10 years | | |

Category : Site
Building : Site

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------------|-----------------------------------|---------------|----------|-----|------|-----------------------|---|
| <u>Civil/Drainage</u> | | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 4 | EA | 7 | 10+ years | Changed to match current observations |
| | Civil/ Drainage - Catch Basin | Entire Site | 1 | EA | 3 | 0-1 year | Collapsing |
| | Civil/ Drainage - Site Manhole | Entire Site | 8 | EA | 7 | 10+ years | |
| <u>Fencing</u> | | | | | | | |
| | Fencing - Chain Link | Entire Site | 186 | LF | 6 | 6-10 years | |
| | Fencing - Guard Rail | Entire Site | 216 | LF | 7 | 10+ years | |
| | Fencing - Guard Rail | Entire Site | 107 | LF | 6 | 6-10 years | |
| | Fencing - New Standard Ornamental | Entire Site | 796 | LF | 7 | 10+ years | |
| <u>Landscape</u> | | | | | | | |
| | Benches | Entire Site | 4 | EA | 7 | 10+ years | New |
| | Landscape - Grass | Entire Site | 3,630 | SF | 6 | 2-5 years | |
| | Landscape - Hardscape- Concrete | Entire Site | 6,555 | SF | 6 | 2-5 years | |
| | Landscape - Hardscape- Concrete | Entire Site | 1,475 | SF | 6 | 2-5 years | |
| | Landscape - Hardscape- Concrete | Entire Site | 1,640 | SF | 5 | 1-2 years | Cracking/potholes. Quantity changed to match current observations |
| | Landscape - Hardscape- Pavers | Entire Site | 1,130 | SF | 6 | 10+ years | |
| | Lighting - Pole Mounted | Entire Site | 1 | EA | 6 | 6-10 years | Added to match current observations |
| | Parkway trees | Entire Site | 2 | EA | 7 | 10+ years | |
| | Planting Beds/ Area | Entire Site | 450 | SF | 7 | 10+ years | |
| | Play Area - Hardscape- Asphalt | Entire Site | 8,530 | SF | 7 | 10+ years | Newly replaced |
| | Trash Receptacles | Entire Site | 4 | EA | 7 | 6-10 years | |
| <u>Parking Lot</u> | | | | | | | |
| | Concrete Curbs | Entire Site | 390 | LF | 6 | 2-5 years | |
| | Lighting - Pole Mounted | Entire Site | 2 | EA | 6 | 6-10 years | Added to match current observations |
| | Surface - Asphalt | Entire Site | 1,748 | SF | 6 | 2-5 years | Cracking throughout |
| | Surface - Asphalt | Entire Site | 4,300 | SF | 6 | 2-5 years | Cracking throughout |
| | Surface - Concrete | Entire Site | 852 | SF | 7 | 10+ years | Newly added |
| | Surface - Concrete | Entire Site | 470 | SF | 5 | 1-2 years | Cracking/sinking |
| | Trash Enclosure - Chain Links | Entire Site | 1,012 | SF | 7 | 10+ years | Newly added |
| <u>Playground</u> | | | | | | | |
| | Equipment - Pre K 3-5 | Main Entrance | 1 | EA | 7 | 6-10 years | |
| | Surface - Poured Surface | Main Entrance | 840 | SF | 7 | 6-10 years | |
| | Equipment - Combo 3-12 | West | 1 | EA | 7 | 10+ years | Brand new. |
| | Surface - Poured Surface | West | 2,415 | SF | 7 | 10+ years | Brand new. |

Category : Site
Building : Site

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|------------------|--|-------------|----------|-----|------|-----------------------|----------|
| Sidewalks | | | | | | | |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 7,425 | SF | 6 | 10+ years | |
| Signage | | | | | | | |
| | Flag Pole - Building Mounted Flag Pole | Entire Site | 1 | EA | 7 | 10+ years | |
| | Marquee - Building Mounted Back Lighted w/ LED | Entire Site | 1 | EA | 7 | 6-10 years | |
| | Monument - Building Mounted Cut Letter Sign | Entire Site | 1 | EA | 7 | 10+ years | |

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Glazed Window Area | Operable Window Area | Window Stop | Smart-Board |
|-------------------------|-------------------------|---------------|-------------|------------------------|-----------|--------------------|----------------------|-------------|-------------|
| Building : Main | | | | | | | | | |
| Faculty Lounge | Regular Classroom | 2nd Floor | 215 | 215 | 652 | 25 | 0 | N | Y |
| Kindergarten | Kindergarten | 1st Floor | 144 | 144 | 852 | 60 | 7 | N | Y |
| Kindergarten | Regular Classroom | 1st Floor | 145 | 145 | 852 | 60 | 7 | N | Y |
| Kindergarten | Regular Classroom | 1st Floor | 146 | 146 | 875 | 60 | 7 | N | Y |
| Kindergarten | Regular Classroom | 1st Floor | 147 | 147 | 928 | 60 | 7 | N | Y |
| Music Room | Regular Classroom | 3rd Floor | 316 | 316 | 875 | 35 | 7 | N | Y |
| Office | Other Instructional Use | 2nd Floor | 214 | 214 | 365 | 50 | 0 | N | N |
| Office | Other Instructional Use | 3rd Floor | 314 | 314 | 707 | 35 | 7 | N | Y |
| Other Instructional Use | Faculty Lounge | 2nd Floor | 226 | 226 | 1,099 | 60 | 7 | N | N |
| Other Instructional Use | Regular Classroom | 2nd Floor | 217 | 217 | 780 | 60 | 7 | N | Y |
| Other Instructional Use | Regular Classroom | 3rd Floor | 325 | 325 | 556 | 35 | 7 | N | Y |
| Pre School | Pre School | 1st Floor | 140/141 | 140 | 2,190 | 100 | 0 | N | Y |
| Regular Classroom | Computer Lab | 2nd Floor | 221 | 221 | 780 | 60 | 7 | N | Y |
| Regular Classroom | Kindergarten | 1st Floor | 151 | 151 | 549 | 35 | 7 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 216 | 216 | 550 | 35 | 7 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 218 | 218 | 800 | 60 | 7 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 219 | 219 | 800 | 60 | 7 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 220 | 220 | 800 | 60 | 7 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 221B | - | 528 | 35 | 7 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 317 | 317 | 852 | 60 | 7 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 318 | 318 | 529 | 60 | 7 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 320 | 320 | 962 | 95 | 14 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 321 | 321 | 852 | 60 | 5 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 322 | 322 | 852 | 60 | 7 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 323 | 323 | 852 | 60 | 7 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 326 | 326 | 928 | 60 | 7 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 328 | 328 | 875 | 60 | 7 | N | Y |
| Science Lab Level 3 | Science Lab Level 3 | 2nd Floor | 224 | 224 | 928 | 60 | 7 | N | Y |
| Store Room | Other Instructional Use | 3rd Floor | 330 | - | 140 | 42 | 0 | N | N |
| Store Room | Regular Classroom | 1st Floor | 148 | 148 | 875 | 60 | 7 | N | Y |
| Store Room | Regular Classroom | 3rd Floor | 324 | 324 | 852 | 60 | 7 | N | N |