



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1903	3	74,643
Campus Total			74,643

Category : Exterior Building : Main

	y Laterier			anamg		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance						<u>.</u>	
	Entrance Control - Audio and Video	1 Main S	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	1 Main S	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	1 Main S	2	EΑ	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	1 Main S	90	LF	7	10+ years	Newly added
	Ramps - Concrete	1 Main S	45	LF	7	10+ years	Newly added
	Exterior Doors - Exterior Wood Door	2 W	4	EΑ	6	10+ years	·
	Exterior Doors - Transom Lite	2 W	2	EΑ	7	10+ years	
	Exterior Stairs - Concrete	2 W	12	LF	5	6-10 years	
	Exterior Doors - Exterior Wood Door	3 W	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	3 W	12	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	4 N	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	4 N	1	EΑ	6	10+ years	
	Exterior Stairs - Stone	4 N	3	LF	5	6-10 years	
	Exterior Doors - Exterior Steel Door	4.5 N	2	EΑ	4	1-2 years	Corroded
	Exterior Doors - Exterior Wood Door	5 E	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	5 E	4	LF	5	6-10 years	Changed to match current observations
	Entrance Control - Audio	6 E	1	EΑ	6	6-10 years	
	Exterior Doors - Exterior Wood Door	6 E	4	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	6 E	2	EA	6	10+ years	
	Exterior Stairs - Concrete	6 E	16	LF	5	1-2 years	Cracking/deteriorating
	Exterior Doors - Exterior Steel Door	7-Light courts	1	EA	6	10+ years	-
	Exterior Stairs - Concrete	7-Light courts	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	8 - Light court	1	EA	6	6-10 years	



Catego	ry : Exterior		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Exterior Stairs - Concrete	8 - Light court	3	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	Northeast Fire Escape	3	EA	6	10+ years		
	Exterior Doors - Transom Lite	Northeast Fire Escape	3	EA	6	6-10 years	Added to match current observations	
	Exterior Stairs - Concrete	Northeast Fire Escape	15	LF	7	10+ years		
	Exterior Doors - Exterior Steel Door	Northwest Fire Escape	2	EA	6	6-10 years		
	Exterior Doors - Transom Lite	Northwest Fire Escape	2	EA	6	6-10 years	Added to match current observations	
	Exterior Doors - Transom Lite	Northwest Fire Escape	1	EA	4	0-1 year	Cracking glass	
	Exterior Stairs - Concrete	Northwest Fire Escape	10	LF	5	1-2 years	Cracking	
Fire Esc	ape							
	Exterior Doors - Exterior Steel Door	Façade- NE	3	EA	6	10+ years		
	Fire Escape	Façade- NE	110	LF	6	10+ years		
	Paints	Façade- NE	110	LF	5	2-5 years		
	Exterior Doors - Exterior Steel Door	Facade- NW	2	ĒΑ	7	6-10 years		
	Fire Escape	Façade- NW	117	LF	6	10+ years		
	Paints	Façade- NW	117	LF	5	2-5 years		
Foundat	ion							
T Odridat	Foundation - Masonry	Entire Building	629	LF	6	10+ years		
	Superstructure - Heavy Timber	Entire Building	71,844	SF	7	10+ years		
	Superstructure - Steel with Clay Tile Arch	Entire Building	2,799	SF	7	10+ years		
	Superstructure Steel with Stay The Aton	Entire Dallaling	2,100	O.	'	101 years		
Lighting								
Lighting	Exterior Lighting - Wall Mounted	Entire Building	14	EA	6	6-10 years		
Roof Sys	stem							
rtoor oy.	Chimney - Brick Chimney- Stainless Steel	Low	50	LF	6	10+ years		
	Liner	2011	00		J	101 youro		
	Chimney - Brick Chimney- Stainless Steel	Low	5	LF	4	0-1 year	Cracking	
	Liner	LOW	9		7	o i yeai	Oracking	
	Chimney - Metal Flue	Low	20	LF	6	10+ years		
	Coping - Clay Tile	Low	219	LF	6	6-10 years		
	Downspouts - Exterior Downspouts	Low	100	LF	5	6-10 years		
	Parapet - 16" - 30" Height	Low	219	LF	6	10+ years		
	Roof - Modified Bitumen	Low	2,799	SF	6	6-10 years		
	Roof Structure - Steel with Clay Tile Arch	Low	2,799	SF	7			
			,			10+ years	Not accured from the ten	
	Access Ladder - Metal	Main	1	EΑ	5	1-2 years	Not secured from the top	
	Access Ladder - Metal	Main	•	EΑ	4	0-1 year	Not secured to the wall/not stable	
	Access Ladder - Wood	Main	1	EA	4	0-1 year	Falling apart	
	Chimney - Metal Flue	Main	10	LF	6	6-10 years		
	Coping - Stone	Main	140	LF	7	10+ years		
	Downspouts - Exterior Downspouts	Main	1,235	LF	6	6-10 years		
	Parapet - 16" - 30" Height	Main	140	LF	7	10+ years		



Catego	ory : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Asphalt Shingle	Main	10,017	SF	5	2-5 years	
	Roof - Modified Bitumen	Main	7,370	SF	4	1-2 years	Cracking throughout
	Roof Hatch - Metal	Main	2	EA	3	0-1 year	Falling apart/not sealed
	Roof Structure - Heavy Timber	Main	17,387	SF	6	10+ years	
Walls							
	Cornice - Masonry Projecting Limestone	Entire Building	78	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	24,142	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	1,700	SF	4	1-2 years	Open joints/cracking
	Exterior Walls - Brick	Entire Building	100	SF	3	0-1 year	Bucked bricks over the fire escape door
	Exterior Walls - Stone-Cut	Entire Building	7,109	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	200	SF	5	10+ years	
Window	S						
	Guard - Guards perforated	Entire Building	2,021	SF	6	10+ years	
	Lintels - Brick	Entire Building	11	LF	7	10+ years	
	Lintels - Steel	Entire Building	571	LF	7	10+ years	
	Lintels - Steel	Entire Building	5	LF	4	•	Corroded/bending by the fire escape
	Linters - Steel	Entire building	5		4	0-1 year	door
	Lintels - Stone	Entire Building	343	LF	6	10+ years	
	Windows - Decorative	Entire Building	80	SF	6	6-10 years	
	Windows - Louver	Entire Building	64	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	7,816	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System	Location	Quantity	00	rtanit	rtopiacomont	Commonto
-merge	Automatic Transfer Switch	Electrical Room	1	EA	7	10+ years	
	Security System - Intrusion Detection	Entire Building	71,844	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	71,044	EA	7	6-10 years	
	Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs	Entire Building	26	EA	6		
	Exit Signs - Compositions and Stalls					6-10 years	
	Exit Signs - Gym	Entire Building	7	EΑ	7	10+ years	
	Exit Signs - Lunchroom	Entire Building	2	EΑ	7	10+ years	
	Exit Signs - Lunchroom	Entire Building	2	EΑ	7	10+ years	
		Entire Building	1	EΑ	6	6-10 years	
	Exit Signs - Lunchroom				7	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	35	EA	-	-	
	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym	Entire Building	6	EA	7	10+ years	
	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Lunchrooms	Entire Building Entire Building	6 2	EA EA	7	-	
	Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym	Entire Building	6	EA	7	10+ years	



	ry : Electrical		R	uilding	Main		
Jaiogo	i y . Liecti icai		O O	ununig	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
лоир	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	7	10+ years	Comments
	Emergency A/C Power - Corridors and	Entire Building	10.710	SF	6	6-10 years	
	Stairs	Zittiro Dallallig	10,110	О.	Ü	o lo youlo	
	Emergency A/C Power - Gym	Entire Building	5,771	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,110	SF	7	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,934	SF	7	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	1,934	SF	7	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,255	SF	6	6-10 years	
lain Ser	rvice						
	Main Electrical Service - 1200 A	Basement	1	EA	7	10+ years	
	120/240/3PH		•		•	, , , , , , , , , , , , , , , , , , , ,	
	Independent Electrical Service for	Electrical Room	1	EA	7	10+ years	
	emergency power					,	
	PA System	Entire Building	71,844	SF	4	6-10 years	Repaired. System in good working
							condition.
ower D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	6-10 years	In proper working condition
	Lighting and Power Panels - Above 100 A	Entire Building	16	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	4	6-10 years	In proper working condition
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	2-5 years	
	amp						
atego	ry : Fire Protection		В	uilding	: Main		
atego	ry : Fire Protection		В	uilding	: Main	Recommend	
_	ry : Fire Protection Item - Type	Location	B Quantity	uilding UOM	: Main Rank	Recommend Replacement	Comments
roup	Item - Type	Location		_			Comments
roup	Item - Type	Location Basement		_		Replacement	Comments
iroup	Item - Type		Quantity	UOM	Rank		Comments
roup	Item - Type m Fire Alarm Panel	Basement	Quantity 1	UOM	Rank 6	Replacement 6-10 years	Comments
roup	Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights	Basement Basement	Quantity 1 74,643	UOM EA SF	Rank 6 6	6-10 years 6-10 years	Comments In good working condition
Group Fire Aları	Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System	Basement Basement Basement	Quantity 1 74,643 74,643	UOM EA SF SF	Rank 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	
Froup ire Aları	Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller	Basement Basement Basement Basement	Quantity 1 74,643 74,643	EA SF SF EA	Rank 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	In good working condition
Froup ire Aları	Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller	Basement Basement Basement	Quantity 1 74,643 74,643 1	UOM EA SF SF	6 6 6 4	6-10 years 6-10 years 6-10 years 6-10 years	
iroup ire Alari	Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller	Basement Basement Basement Basement	Quantity 1 74,643 74,643 1	EA SF SF EA	6 6 6 4	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	In good working condition
Group ire Alari d'ump Ro	Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller com Assembly Fire Pump - 25-50 hp	Basement Basement Basement Basement Basement Entire Building	Quantity 1 74,643 74,643 1 1	UOM EA SF SF EA EA	6 6 6 4 4 5	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	In good working condition In proper working condition.
Group ire Alari d'ump Ro	Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller Doom Assembly Fire Pump - 25-50 hp	Basement Basement Basement Basement Basement	Quantity 1 74,643 74,643 1	EA SF EA SF SF	6 6 6 4	6-10 years 6-10 years 6-10 years 6-10 years 2-5 years	In good working condition
Group Fire Alari	Item - Type m Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System Fire Pump Controller com Assembly Fire Pump - 25-50 hp T System Dry Sprinkler System	Basement Basement Basement Basement Basement Entire Building	Quantity 1 74,643 74,643 1 1	UOM EA SF SF EA EA	6 6 6 4 4 5	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 2-5 years	In good working condition In proper working condition.



Category : Mechanical			В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone-	Basement	1	EA	5	6-10 years	
	Steam Coils - Greater than 35000 cfm	2400	·	`	•	o lo youlo	
	Air Intake	Basement	2	EA	6	6-10 years	
	Auxiliaries - Greater than 35000 cfm	Basement	1	EΑ	5	2-5 years	
	Return Duct Work - Masonry and Ducts-	Basement	100	LF	6	6-10 years	
	Missing or Existing Shaft	2400		- -	· ·	o lo youlo	
	Zone Dampers	Basement	38	EA	6	6-10 years	
		2400		`	·	0 .0 ,00.0	
Boiler Sy	stems						
	Boiler Auxiliary- Scotch Marine- Steam Low	Basement	2	EA	5	6-10 years	
	Pressure Boiler - 76 - 100 HP					•	
	Chemical Feed System	Basement	1	EA	6	6-10 years	
	Combustion Dampers	Basement	2	EΑ	6	6-10 years	
	Condensate Pump	Basement	1	EA	3	0-1 year	Condensate pump leaking. In need of
	•					•	repair, or replacement.
	Feed Water Pumps and Tank	Basement	1	EΑ	6	6-10 years	' '
	Non Condensing- Fire Tube- Scotch Marine-	Basement	1	EΑ	5	6-10 years	
	Steam- Low Pressure Boiler - 76 - 100 HP					,	
	Non Condensing- Fire Tube- Scotch Marine-	Basement	1	EA	5	0-1 year	Boiler 1, not in use due to need for
	Steam- Low Pressure Boiler - 76 - 100 HP					,	gas valve replacement.
	Piping - Condensate Pipe- Steel	Basement	200	LF	5	6-10 years	3
	Piping - Steam Pipe- Steel	Basement	200	LF	5	6-10 years	
	Steam Traps	Basement	12	EA	5	6-10 years	
Heating I	Devices						
- rouning i	Wall Heater - Electric	Basement	3	EA	5	6-10 years	
	Fin Tube - Steam	Basement	100	LF	6	6-10 years	Engineer, not aware of any other
	Till Tube Glean	Basement	100		O	o to years	units. Non-seen per observation.
	Unit Heater - Gas	Boiler Room	2	EA	5	2-5 years	units. Non seen per observation.
	Child Houlds Gdo	Bollot Room	_	_/\	O	2 0 youro	
Tempera	ture Control						
	Pneumatic System	Entire Building	74,643	SF	7	6-10 years	
	Thermostats - Pneumatic	Entire Building	37	EA	6	6-10 years	
	Thermostats - Pneumatic	Entire Building	1	EA	5	6-10 years	Thermostats repaired since last
		Ğ				•	assessment. In good working
							condition.
Ventilatio		E # B # P	-			0.40	N
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	No, asset sticker present
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	2	EA	7	10+ years	
	CFM						
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	3	0-1 year	Unit in disrepair, in need of

Campus Name: Hamilton Page : 5 of 24 Assessment Date: 11/20/2023



Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	CFM	F # B ##			_	0.40	replacement.
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	5	6-10 years	
Catago	n, Dlumbina		-	uildina	. Main		
Catego	ry : Plumbing		<u></u>	Building	: wam	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Basement	1	EA	7	6-10 years	
		2000	·		•	0 .0 ,00.0	
Piping							
- 1 5	Domestic Piping-Hot Water Return Lines	Entire Building	74,643	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	74,643	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	74,643	SF	6	6-10 years	
	Fixtures	3	,			,	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	74,643	SF	6	6-10 years	
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply	Entire Building	74,643	SF	6	6-10 years	
	(Risers)	Entire Building	74,043	SF	O	0-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	74,643	SF	6	6-10 years	
	(from Risers to Fixtures)	g	,	-	-	,	
	Sanitary Piping	Entire Building	74,643	SF	6	6-10 years	
	Storm Piping	Entire Building	74,643	SF	6	6-10 years	
	Vent Piping	Entire Building	74,643	SF	6	6-10 years	
Catago	ru . Boom		-	uildina	. Main		
Calego	ry : Room			Building	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	rative Suites/Offices	Location	Qualitity	CON	Italik	Replacement	Comments
Administ	AC Unit	105 - Faculty Lounge	1	EA	5	6-10 years	
	Ceiling - Exposed	105 - Faculty Lounge	614	SF	6	10+ years	
	Doors - Transom Window	105 - Faculty Lounge	8	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	105 - Faculty Lounge	2	EA	6	6-10 years	
	Floor - Wood	105 - Faculty Lounge	614	SF	6	10+ years	
	Lighting - Chandelier, Incandescent	105 - Faculty Lounge	3	EA	6	1-2 years	Relamp
	Lighting - Pendent/Surface	105 - Faculty Lounge	3	EΑ	7	6-10 years	rtolamp
	Power Distribution	105 - Faculty Lounge	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	105 - Faculty Lounge	1,178	SF	6	10+ years	
	Work Sink	105 - Faculty Lounge	1,170	EA	7	10+ years	
	AC Unit	105 Main office	1	EA	7	6-10 years	
	Ceiling - Lay-in	105 Main office	510	SF	7	10+ years	
	Doors - Transom Window	105 Main office	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105 Main office	1	EA	6	10+ years	
	Floor - Wood	105 Main office	510	SF	6	10+ years	
						•	
0	Name: Hamilton		Page : 6 of 24				Assessment Date: 11/20/2023

Assessment Date: 11/20/2023 Campus Name: Hamilton Page : 6 of 24



Catego	ry : Room		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	105 Main office	6	EA	7	6-10 years	
	Power Distribution	105 Main office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	105 Main office	950	SF	7	10+ years	
	AC Unit	Engineer's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Office	392	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	Engineer's Office	392	SF	7	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	4	EA	5	1-2 years	Missing cover
	Power Distribution	Engineer's Office	8	EA	6	10+ years	· ·
	Storage/ Closet	Engineer's Office	36	SF	5	10+ years	
	Walls - Concrete Block	Engineer's Office	224	SF	6	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	224	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Kitchen Office	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Office	1	EA	6	10+ years	
	Floor - Tile	Kitchen Office	60	SF	6	10+ years	
	Lighting - Pendent/Surface	Kitchen Office	1	EA	7	6-10 years	
	Power Distribution	Kitchen Office	2	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	Kitchen Office	260	SF	6	10+ years	
	vano i lactor/Brywan	Tatorion Onioo	200	0.	O	101 youro	
Gymnas	ia						
,	Ceiling - Plaster/Drywall	3rd Flr. Gym	5,721	SF	6	2-5 years	
	Ceiling - Plaster/Drywall	3rd Flr. Gym	50	SF	5	1-2 years	Peeling paint
	Doors - Side-lite	3rd Flr. Gym	50	SF	7	10+ years	r coming paint
	Doors - Transom Window	3rd Flr. Gym	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Flr. Gym	4	EA	6	10+ years	
	Floor - Sport Flooring	3rd Flr. Gym	5,771	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Fir. Gym	24	EA	7	10+ years	
	Lighting - Wall Mounted	3rd Fir. Gym	10	EA	7	10+ years	
	Scoreboards	3rd Fir. Gym	10	EA	7	10+ years	
	Sound System	3rd Fir. Gym	1	EA	7	6-10 years	
	Stage	3rd Fir. Gym	1,386	SF	6	10+ years	
	Stage Curtain	3rd Fir. Gym	10	EA	7	6-10 years	
	Stage Curtain Stage Lighting System	3rd Fir. Gym	10	EA	7	6-10 years	
	Stage-Stairs - Wood	3rd Fir. Gym	12	LF	7		
						10+ years	Cracked naint
	Storage/ Closet	3rd Flr. Gym	210	SF	5	1-2 years	Cracked paint
	Storage/ Closet	3rd Flr. Gym	210	SF	5	1-2 years	Cracked paint
	Walls - Plaster/Drywall	3rd Flr. Gym	6,338	SF SF	6	10+ years	Cracked rejet
	Walls - Plaster/Drywall	3rd Flr. Gym	25	SF	5	1-2 years	Cracked paint
Vitaba:							
Kitchen	Ceiling - Plaster/Drywall	Bsmt. / Kitchen	15	SF	7	6-10 years	Ceiling painted
	Ceiling - Plaster/Drywall	Bsmt. / Kitchen	865	SF	6	10+ years	Centry painted
	Doors - Wood Doors inclu hw			SF EA			
		Bsmt. / Kitchen	3		6	10+ years	
	Floor - Tile	Bsmt. / Kitchen	842	SF	6	10+ years	

Page: 7 of 24 Campus Name: Hamilton Assessment Date: 11/20/2023



	ry : Room			uilding	. IVIAIII				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	Bsmt. / Kitchen	15	EA	7	6-10 years			
	Lighting - Pendent/Surface	Bsmt. / Kitchen	3	EA	6	6-10 years			
	Walls - Plaster/Drywall	Bsmt. / Kitchen	1,142	SF	6	10+ years			
Library									
Library	AC Unit	106 library	2	EA	5	6-10 years			
	Casework	106 library	95	LF	6	6-10 years			
	Ceiling - Lay-in	106 library	1,260	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	106 library	2	EA	6	10+ years			
	Floor - Wood	106 library	1,260	SF	6	10+ years			
	Lighting - Pendent/Surface	106 library	21	EA	7	6-10 years			
	Lighting - Pendent/Surface	106 library	1	EA	5	1-2 years	Missing cover		
	Storage/ Closet	106 library	175	SF	7	10+ years	imeening eeven		
	Walls - Plaster/Drywall	106 library	1,562	SF	6	10+ years			
Lunch & I	Multipurpose Room								
LUNCITO	Ceiling - Exposed	Basement Lunchroom	1,108	SF	6	10+ years			
	Doors - Steel Doors incl hw	Basement Lunchroom	1	EA	7	10+ years			
	Floor - Tile	Basement Lunchroom	1,150	SF	6	10+ years			
	Lighting - Pendent/Surface	Basement Lunchroom	31	EA	7	6-10 years			
	Lighting - Pendent/Surface	Basement Lunchroom	4	EΑ	6	6-10 years			
	Serving Line	Basement Lunchroom	16	LF	6	10+ years			
	Walls - Masonry	Basement Lunchroom	1,060	SF	6	10+ years			
	Walls - Plaster/Drywall	Basement Lunchroom	253	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Boy's Playroom	1,934	SF	6	10+ years			
	Floor - Epoxy/ Painted	Boy's Playroom	1,934	SF	7	10+ years			
	Lighting - Pendent/Surface	Boy's Playroom	18	ĒΑ	7	6-10 years			
	Walls - Masonry	Boy's Playroom	655	SF	6	10+ years			
	Walls - Plaster/Drywall	Boy's Playroom	184	SF	6	10+ years			
	Walls - Vinyl Coated Gypsum Panel	Boy's Playroom	920	SF	6	10+ years			
	Ceiling - Exposed	Boy's Playroom #2	880	SF	6	10+ years			
	Floor - Epoxy/ Painted	Boy's Playroom #2	880	SF	7	10+ years			
	Lighting - Pendent/Surface	Boy's Playroom #2	18	EA	7	6-10 years			
	Walls - Masonry	Boy's Playroom #2	571	SF	6	10+ years			
	Walls - Plaster/Drywall	Boy's Playroom #2	571	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Girl's Playroom	1,934	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Girl's Playroom	1,954	EA	6	10+ years			
	Floor - Epoxy/ Painted	Girl's Playroom	1,934	SF	7	10+ years			
	Lighting - Pendent/Surface	Girl's Playroom	1,934	EA	6	6-10 years			
	Walls - Concrete Block	Girl's Playroom	184	SF	6	10+ years			
	Walls - Masonry	Girl's Playroom	20	SF	6	1-2 years	Cracked masonry		
	Walls - Masonry	Girl's Playroom	655	SF	6	10+ years	Oracico masoni y		
	Walls - Metal Panel	Girl's Playroom	920	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Staff lunchroom basement	220	SF	7	10+ years	No occupancy signage		
	Coming - Flaster/Drywall	Stail Idilottiootti basettietit	220	Ji	,	10+ years	140 occupation signage		



Catego	ry : Room		В	uilding	: Main		•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Staff lunchroom basement	220	SF	7	10+ years	
	Lighting - Pendent/Surface	Staff lunchroom basement	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Staff lunchroom basement	3	EΑ	6	6-10 years	
	Power Distribution	Staff lunchroom basement	2	EΑ	7	10+ years	
	Student Lockers - Two Tier	Staff lunchroom basement	8	EΑ	7	6-10 years	
	Walls - Concrete Block	Staff lunchroom basement	440	SF	7	10+ years	
_MDF_ID	F						
	Doors - Steel Doors incl hw	2nd Flr. MDF/IDF	1	EA	6	10+ years	
	Finishes	2nd Flr. MDF/IDF	125	SF	5	2-5 years	
	Other Cooling Unit	2nd Flr. MDF/IDF	1	EA	7	6-10 years	
	Window AC Unit	2nd Flr. MDF/IDF	1	EA	4	0-1 year	Not functioning
_Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	16	SF	5	10+ years	
	Janitor's Closet	1st Floor	16	SF	5	10+ years	
	Janitor's Closet	2nd Floor	16	SF	7	10+ years	
	Janitor's Closet	2nd Floor	16	SF	7	10+ years	
	Janitor's Closet	3rd Floor	12	SF	7	10+ years	
	Janitor's Closet	3rd Floor	12	SF	7	10+ years	
	Storage Room	3rd Floor	182	SF	5	1-2 years	Cracks at walls and ceiling
	Storage Room	3rd Floor	182	SF	5	1-2 years	Cracks and water damage at walls and ceiling
	Air Intake Plenums	Basement	250	SF	5	10+ years	and coming
	Air Tunnel	Basement	880	SF	5	10+ years	
	Boiler Room	Basement	1,440	SF	5	10+ years	
	Coal Room	Basement	840	SF	5	10+ years	
	Janitor's Closet	Basement	198	SF	5	1-2 years	Repair,repaint
	Mechanical/ Service Rooms	Basement	910	SF	5	1-2 years	Repair and repaint
	Mechanical/ Service Rooms	Basement	80	SF	5	1-2 years	Repair and repaint
	Storage Room	Basement	189	SF	7	10+ years	Repair and repairit
	Storage Room	Basement	196	SF	5	1-2 years	Repair and repaint
	Storage Room	Basement	335	SF	5	1-2 years	Cracked masonry and peeling paint
Б							
_Restroo		404 la sista				0.40	
	Accessories	101 Inside	66	SF	7	6-10 years	
	Ceiling - Exposed	101 Inside	66	SF	6	10+ years	
	Doors - Wood Doors inclu hw	101 Inside	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	101 Inside	66	SF	7	10+ years	
	Floor Drain	101 Inside	1	EA	7	10+ years	
	Lavatory	101 Inside	1	EA	7	10+ years	
	Lighting - Pendent/Surface	101 Inside	1	EA	7	10+ years	
	Walls - Plaster/Drywall	101 Inside	200	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Tile Ceramic/ Porcelain	101 Inside	220	SF	7	10+ years	
	Water Closet	101 Inside	1	EA	6	10+ years	
	Accessories	105 Toilet	76	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	105 Toilet	76	SF	6	10+ years	
	Doors - Wood Doors inclu hw	105 Toilet	1	EA	6	10+ years	
	Floor - Tile	105 Toilet	5	SF	5	1-2 years	Broken tiles
	Floor - Tile Ceramic/ Porcelain	105 Toilet	71	SF	7	10+ years	
	Lavatory	105 Toilet	1	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	105 Toilet	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	105 Toilet	450	SF	6	10+ years	
	Water Closet	105 Toilet	1	EA	6	10+ years	
	Accessories	1st flr. unisex	38	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st flr. unisex	38	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr. unisex	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr. unisex	38	SF	6	10+ years	
	Hand Dryer	1st flr. unisex	1	ĒΑ	7	6-10 years	
	Lavatory	1st flr. unisex	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st flr. unisex	1	EA	7	6-10 years	
	Partitions	1st flr. unisex	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st flr. unisex	220	SF	6	10+ years	
	Water Closet	1st flr. unisex	1	EΑ	6	10+ years	
	Accessories	2nd Floor Staff	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Staff	28	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Staff	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Staff	28	SF	6	10+ years	
	Floor Drain	2nd Floor Staff	1	EA	7	6-10 years	
	Lavatory	2nd Floor Staff	1	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor Staff	1	EΑ	5	1-2 years	Cover is broken
	Walls - Plaster/Drywall	2nd Floor Staff	230	SF	6	10+ years	COVOL IO DIGITALI
	Water Closet	2nd Floor Staff	1	EA	7	6-10 years	Good condition
	Accessories	2nd Flr. Girls	251	SF	7	6-10 years	Cood containen
	Ceiling - Plaster/Drywall	2nd Flr. Girls	251	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Flr. Girls	251	SF	6	10+ years	
	Floor Drain	2nd Flr. Girls	1	EA	7	10+ years	
	Hand Dryer	2nd Flr. Girls	2	EΑ	7	6-10 years	
	Lavatory	2nd Flr. Girls	1	EΑ	7	6-10 years	Good condition
	Lighting - Pendent/Surface	2nd Flr. Girls	5	EΑ	7	6-10 years	Good condition
	Lighting - Pendent/Surface	2nd Fir. Girls	1	EA	6	0-10 years 0-1 year	Relamp
	Partitions	2nd Fir. Girls	5	EA	7	6-10 years	Notarip
	Walls - Plaster/Drywall	2nd Flr. Girls	725	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Flr. Girls	5	SF	5	1-2 years	Cracks/ damage
	Water Closet	2nd Flr. Girls	5	EA	7	6-10 years	Good condition
	Accessories	2nd flr. Boys	251	SF	7	6-10 years	Cood condition
	Ceiling - Plaster/Drywall	2nd flr. Boys	251	SF	6	10+ years	
	James Francisco Prywan	2.13 20,0	201	٥.	3	. o. youro	

Campus Name: Hamilton Page : 10 of 24 Assessment Date: 11/20/2023



Catego	ry : Room		В	uilding	: Main		. 5 .
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	2nd flr. Boys	251	SF	6	10+ years	
	Floor Drain	2nd flr. Boys	1	EA	7	10+ years	
	Hand Dryer	2nd flr. Boys	2	EA	7	6-10 years	
	Lavatory	2nd flr. Boys	1	EA	7	6-10 years	Good condition
	Lighting - Pendent/Surface	2nd flr. Boys	6	EA	7	6-10 years	
	Partitions	2nd flr. Boys	2	EA	7	6-10 years	
	Urinals	2nd flr. Boys	5	EA	7	6-10 years	Good condition
	Walls - Plaster/Drywall	2nd flr. Boys	522	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd flr. Boys	208	SF	6	10+ years	
	Water Closet	2nd flr. Boys	2	EA	7	6-10 years	Good condition
	Accessories	Basement By engineer's office	76	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement By engineer's office	76	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement By engineer's office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement By engineer's office	76	SF	7	10+ years	
	Hand Dryer	Basement By engineer's office	1	EA	7	6-10 years	
	Lavatory	Basement By engineer's office	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement By engineer's office	1	EA	7	6-10 years	
	Partitions	Basement By engineer's office	1	EA	7	10+ years	
	Urinals	Basement By engineer's office	1	EA	6	10+ years	
	Walls - Concrete Block	Basement By engineer's office	281	SF	7	10+ years	
	Water Closet	Basement By engineer's office	1	EA	6	10+ years	
	Accessories	Basement Toilet inside staff lunchroom	76	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement Toilet inside staff lunchroom	76	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement Toilet inside staff lunchroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement Toilet inside staff lunchroom	74	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement Toilet inside staff lunchroom	1	SF	4	1-2 years	Missing tiles
	Floor Drain	Basement Toilet inside staff lunchroom	1	EA	7	10+ years	
	Hand Dryer	Basement Toilet inside staff lunchroom	1	EA	7	6-10 years	
	Lavatory	Basement Toilet inside staff lunchroom	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement Toilet inside staff lunchroom	1	EA	6	6-10 years	
	Partitions	Basement Toilet inside staff lunchroom	2	EA	7	6-10 years	
	Urinals	Basement Toilet inside staff lunchroom	1	EA	7	10+ years	
	Walls - Concrete Block	Basement Toilet inside staff	281	SF	6	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		lunchroom					
	Water Closet	Basement Toilet inside staff	2	EA	6	10+ years	
		lunchroom					
	Accessories	Boiler Room	38	SF	5	6-10 years	
	Ceiling - Exposed	Boiler Room	60	SF	5	1-2 years	Peeling paint and water damage
	Doors - Wood Doors inclu hw	Boiler Room	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boiler Room	60	SF	6	10+ years	
	Lavatory	Boiler Room	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Boiler Room	1	EA	6	6-10 years	
	Showers	Boiler Room	1	EA	5	1-2 years	Missing showethead
	Walls - Masonry	Boiler Room	337	SF	6	0-1 year	Peeling paint
	Walls - Plaster/Drywall	Boiler Room	48	SF	6	1-2 years	Hole in wall
	Walls - Vinyl Coated Gypsum Panel	Boiler Room	96	SF	7	10+ years	
	Water Closet	Boiler Room	1	EA	6	10+ years	
	Accessories	Bsmt. Boys	396	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Bsmt. Boys	396	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Bsmt. Boys	396	SF	6	10+ years	
	Floor Drain	Bsmt. Boys	2	EA	7	10+ years	
	Hand Dryer	Bsmt. Boys	2	EA	7	6-10 years	
	Lavatory	Bsmt. Boys	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Bsmt. Boys	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	Bsmt. Boys	2	EA	6	6-10 years	
	Partitions	Bsmt. Boys	3	EA	7	6-10 years	
	Urinals	Bsmt. Boys	10	EA	6	6-10 years	
	Walls - Concrete Block	Bsmt. Boys	628	SF	6	10+ years	
	Water Closet	Bsmt. Boys	3	EA	6	10+ years	
	Accessories	Bsmt. Girls	396	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Bsmt. Girls	396	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Bsmt. Girls	396	SF	6	10+ years	
	Floor Drain	Bsmt. Girls	2	EA	7	10+ years	
	Hand Dryer	Bsmt, Girls	2	EA	5	6-10 years	
	Lavatory	Bsmt. Girls	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Bsmt, Girls	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	Bsmt, Girls	2	EA	6	6-10 years	
	Partitions	Bsmt. Girls	12	ĒΑ	7	6-10 years	
	Walls - Concrete Block	Bsmt. Girls	623	SF	6	10+ years	
	Walls - Structural Glazed Tile	Bsmt. Girls	5	SF	4	1-2 years	Missing tiles
	Water Closet	Bsmt. Girls	12	EA	6	10+ years	··· ·9 ····
					•	,	
atego	ry : Classroom		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	om #008 (Dance Room)	2004.1011	Quantity		Rain	Nopidocinicit	CO.MIIOINO
<u> </u>	Casework	Basement	15	LF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Basement	1,127	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Wood	Basement	1,127	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	31	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement	3	EA	5	1-2 years	Missing covers
	Marker Board	Basement	12	LF	6	6-10 years	•
	Storage/ Closet	Basement	75	SF	5	10+ years	
	Wall Mirrors	Basement	15	SF	7	10+ years	
	Walls - Masonry	Basement	1,040	SF	6	10+ years	
	Weight/ Fitness Room Floor Matting	Basement	900	SF	6	10+ years	
Classroo	om #101 (Kindergarten)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Splined	1st Floor	871	SF	6	10+ years	
	Doors - Transom Window	1st Floor	4	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	·	SF	6		
			871			10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	36	LF	6	6-10 years	
	Storage/ Closet	1st Floor	150	SF	7	10+ years	
	Storage/ Closet	1st Floor	125	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	6-10 years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	4	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	ĒΑ	5	1-2 years	Missing cover
	Marker Board	1st Floor	36	LF	6	6-10 years	gg
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	10+ years	
Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	6-10 years	
	•	1st Floor		SF		•	
	Doors - Transom Window		4		6	10+ years	

Campus Name: Hamilton Page : 13 of 24 Assessment Date: 11/20/2023



	Catego	ry : Classroom		В	uilding	: Main		
Doors - Wood Doors inclu hw							Recommend	
Floor - Wood	Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Lighting - Pendent/Surface		Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Lighting - Pendent/Surface 1st Floor 1		Floor - Wood	1st Floor	871	SF	6	10+ years	
Lighting - Pendent/Surface 1st Floor 1		Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
Marker Board		Lighting - Pendent/Surface	1st Floor		EA	5		Missing cover
Storage/ Closet		Marker Board	1st Floor	36	LF	6		· ·
Classroom#104_Principals (Office)		Storage/ Closet	1st Floor	120	SF	5	•	
AC Units								
AC Units	Classroo	om #104 Principal's (Office)						
Ceiling - Lay-in			1st Floor	1	EA	5	6-10 years	
Doors - Transom Window								
Doors - Wood Doors inclu hw						_		
Floor - Wood							•	
Lighting - Pendent/Surface						-		
Lighting - Pendent/Surface						-	-	
Marker Board								Missing cover
Storage Closet 1st Floor 120 SF 5 10+ years							•	Wilsoling Cover
Classroom #107 (Regular Classroom)							•	
AC Units								
AC Units		wane i lactor, 21, wan	10(1)001	1,110	0.	Ü	0 10 90010	
Ceiling - Lay-in	Classroo		=					
Ceiling - Lay-in 1st Floor 24 SF 5 1-2 years Damaged tiles Doors - Transom Window 1st Floor 28 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Wood 1st Floor 13 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Lighting - Pendent/Surface 1st Floor 1 EA 5 6-10 years Lighting - Pendent/Surface 1st Floor 120 SF 5 10+ years Storage/ Closet 1st Floor 1,336 SF 6 10+ years Walls - Plaster/Drywall 1st Floor 1,336 SF 6 10+ years Ceiling - Lay-in 1st Floor 871 SF 6 6-10 years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 6-10 years Lighting - Pendent/Surface 1st Floor 13 EA								
Doors - Transom Window								
Doors - Wood Doors inclu hw 1st Floor 1								Damaged tiles
Floor - Wood								
Lighting - Pendent/Surface 1st Floor 13 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Missing cover Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years Walls - Plaster/Drywall 1st Floor 1,336 SF 6 10+ years Classroom #108 (Regular Classroom) AC Units 1st Floor 1 EA 5 6-10 years Ceiling - Lay-in 1st Floor 871 SF 6 6-10 years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Wood 1st Floor 871 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 13 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Missing cover Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years				· · · · · · · · · · · · · · · · · · ·			•	
Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Missing cover Missing cover Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years Walls - Plaster/Drywall 1st Floor 1,336 SF 6 10+ years 10+ years Classroom #108 (Regular Classroom) 1 EA 5 6-10 years 6-10 years Ceiling - Lay-in 1st Floor 2 1 EA 6 6-10 years 1 EA 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years 1 EA 6 10+ years Floor - Wood 1st Floor 371 SF 6 10+ years 10+ years Lighting - Pendent/Surface 1st Floor 1 EA 7 6-10 years 1 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 36 LF 6 6-10 years 1 EA 5 1-2 years Missing cover Marker Board 1st Floor 36 LF 6 6-10 years 5 10+ years Storage/ Closet 1st Floor 120 SF 5 10+ years								
Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years Walls - Plaster/Drywall 1st Floor 1,336 SF 6 10+ years Classroom #108 (Regular Classroom) AC Units 1st Floor 1 EA 5 6-10 years Ceiling - Lay-in 1st Floor 871 SF 6 6-10 years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Wood 1st Floor 871 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 13 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Missing cover Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years				13				
Storage/ Closet 1st Floor 120 SF 5 10+ years Walls - Plaster/Drywall 1st Floor 1,336 SF 6 10+ years Classroom #108 (Regular Classroom) AC Units 1st Floor 1 EA 5 6-10 years Ceiling - Lay-in 1st Floor 871 SF 6 6-10 years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Wood 1st Floor 871 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 13 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Missing cover Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years								Missing cover
Walls - Plaster/Drywall 1st Floor 1,336 SF 6 10+ years Classroom #108 (Regular Classroom) AC Units 1st Floor 1 EA 5 6-10 years Ceiling - Lay-in 1st Floor 871 SF 6 6-10 years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Wood 1st Floor 871 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 13 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Missing cover Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years						-	6-10 years	
Classroom #108 (Regular Classroom) AC Units						5		
AC Units 1st Floor 1 EA 5 6-10 years Ceiling - Lay-in 1st Floor 871 SF 6 6-10 years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Wood 1st Floor 871 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 13 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Missing cover Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years		Walls - Plaster/Drywall	1st Floor	1,336	SF	6	10+ years	
Ceiling - Lay-in 1st Floor 871 SF 6 6-10 years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Wood 1st Floor 871 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 13 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Missing cover Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years	Classroo	om #108 (Regular Classroom)						
Ceiling - Lay-in 1st Floor 871 SF 6 6-10 years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Wood 1st Floor 871 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 13 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Missing cover Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years		AC Units	1st Floor	1	EA	5	6-10 years	
Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Wood 1st Floor 871 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 13 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Missing cover Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years		Ceiling - Lay-in		871			6-10 years	
Floor - Wood 1st Floor 871 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 13 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Missing cover Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years		Doors - Wood Doors inclu hw					•	
Lighting - Pendent/Surface 1st Floor 13 EA 7 6-10 years Lighting - Pendent/Surface 1st Floor 1 EA 5 1-2 years Missing cover Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years				871			,	
Lighting - Pendent/Surface1st Floor1 EA5 1-2 yearsMissing coverMarker Board1st Floor36 LF6 6-10 yearsStorage/ Closet1st Floor120 SF5 10+ years		Lighting - Pendent/Surface	1st Floor			7	,	
Marker Board 1st Floor 36 LF 6 6-10 years Storage/ Closet 1st Floor 120 SF 5 10+ years								Missing cover
Storage/ Closet 1st Floor 120 SF 5 10+ years						-		9
						-		
1,212 01 0 101 yourd							-	
			.555.	1,212	σ.	ŭ	,	

Campus Name: Hamilton Page : 14 of 24 Assessment Date: 11/20/2023



Jategor	y : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroo	m #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	6	6-10 years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Missing cover
	Marker Board	1st Floor	24	LF	6	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	10+ years	
	Work Sink	1st Floor	· 1	EA	5	6-10 years	
						•	
lassroo	m #110 (Regular Classroom)						
	AC Units	1st Floor	1	EA	5	6-10 years	
	Ceiling - Lay-in	1st Floor	871	SF	7	10+ years	
	Doors - Transom Window	1st Floor	4	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	1-2 years	Missing cover and relamp
	Marker Board	1st Floor	36	LF	6	6-10 years	·
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,272	SF	6	10+ years	
	m #201 (Regular Classroom)						
lassioo	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor 2nd Floor	871	SF	6		
	Doors - Wood Doors inclu hw				_	10+ years	
		2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	36	LF	6	6-10 years	AA7 4 1 2 2 20
	Storage/ Closet	2nd Floor	175	SF	5	1-2 years	Water damage at ceiling
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years	
lassroo	m #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	871	SF	6	10+ years	



Category : Classroom		В	uilding	: Main				
	_					Recommend		
	ı - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	ting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years		
	ker Board	2nd Floor	75	LF	6	6-10 years		
	age/ Closet	2nd Floor	175	SF	7	10+ years		
Wall	ls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years		
Classroom #20	03 (Regular Classroom)							
AC I	Units	2nd Floor	1	EA	7	6-10 years		
Ceili	ing - Lay-in	2nd Floor	861	SF	6	10+ years		
Ceili	ing - Lay-in	2nd Floor	10	SF	4	1-2 years	Water damage	
	rs - Transom Window	2nd Floor	9	SF	6	10+ years	ŭ	
Doo	rs - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
Floo	or - Wood	2nd Floor	871	SF	6	10+ years		
	ting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	Good condition	
	ker Board	2nd Floor	75	LF	7	6-10 years		
	age/ Closet	2nd Floor	175	SF	5	1-2 years	Water damage at ceiling	
	ls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years	Trater damage at coming	
Classroom #20	04 (Science)							
	Units	2nd Floor	2	EA	7	6-10 years		
	ing - Lay-in	2nd Floor	1,161	SF	6	10+ years		
	ing - Lay-in	2nd Floor	10	SF	4	0-1 year	Water damage	
	rs - Transom Window	2nd Floor	42	SF	6	10+ years	water damage	
	rs - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years		
	or - Wood	2nd Floor	1,171	SF	6	10+ years		
	ting - Pendent/Surface	2nd Floor	19	EA	7	6-10 years		
	ting - Pendent/Surface	2nd Floor	19	EA	5	1-2 years	Missing cover	
	ker Board	2nd Floor 2nd Floor	62	LF	6	6-10 years	wissing cover	
		2nd Floor	175	SF	7			
	age/ Closet					10+ years		
vvaii	ls - Plaster/Drywall	2nd Floor	1,682	SF	6	10+ years		
	05 (Regular Classroom)							
	Units	2nd Floor	1	EA	7	6-10 years		
	ing - Lay-in	2nd Floor	852	SF	6	10+ years		
	ing - Lay-in	2nd Floor	8	SF	5	1-2 years	Cracked tile	
Doo	rs - Transom Window	2nd Floor	35	SF	6	10+ years		
Doo	rs - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years		
	or - Wood	2nd Floor	860	SF	6	10+ years		
Ligh	ting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years		
	ker Board	2nd Floor	50	LF	7	6-10 years		
Stor	age/ Closet	2nd Floor	175	SF	5	1-2 years	Water damage at ceiling	
	ls - Plaster/Drywall	2nd Floor	1,336	SF	6	10+ years	5 5	
Classroom #20	06 (Regular Classroom)							

Campus Name: Hamilton Page : 16 of 24 Assessment Date: 11/20/2023



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	607	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	607	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	5	1-2 years	Water damage at ceiling
	Walls - Plaster/Drywall	2nd Floor	1,149	SF	6	10+ years	Traio. damage at coming
assroo	m #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	852	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	6	10+ years	
				SF	-	•	
	Floor - Wood	2nd Floor	860		6	10+ years	O a a di a a a diti a a
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	Good condition
	Marker Board	2nd Floor	36	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	5	1-2 years	Damaged at walls and ceiling
	Walls - Plaster/Drywall	2nd Floor	1,326	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Cracks in wall
assroo	m #208 (Other Instructional Use)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	789	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	82	SF	5	0-1 year	Water damage
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	3
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	75	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor		SF	6	,	
			1,264	SF SF		10+ years	Crosks
	Walls - Plaster/Drywall	2nd Floor	8	SF	5	1-2 years	Cracks
assroo	m #209 (Regular Classroom)	01 51				0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	847	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	24	SF	5	1-2 years	Water damage
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Boold Halloom William						



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	5	1-2 years	Water damage at ceiling
	Walls - Plaster/Drywall	2nd Floor	1,250	SF	6	10+ years	3 3
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	1-2 years	Water damage
assroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	855	SF	6	10+ years	
		2nd Floor	16	SF	5		Water demons
	Ceiling - Lay-in				-	1-2 years	Water damage
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	75	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	5	1-2 years	Damaged wall and ceiling (water
	oneral gar one con			-	•	,	damage and bulging tiles at ceiling
	Walls - Plaster/Drywall	2nd Floor	1,257	SF	6	10+ years	aamago ana baiging moo at comin
	Walls - Plaster/Drywall	2nd Floor	15	SF	5	1-2 years	Cracks in wall
assroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	775	SF	6	10+ years	
		3rd Floor	96	SF			Water demage in closet and
	Ceiling - Lay-in	310 F1001	90		4	0-1 year	Water damage in closet and classroom ceiling
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	Good condition
	Marker Board	3rd Floor	40	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	5	10+ years	Ceiling damage
	Walls - Plaster/Drywall		20	SF	6		Celling damage
		3rd Floor		SF SF		2-5 years	
	Walls - Plaster/Drywall	3rd Floor	1,252	51	6	10+ years	
	#222 (4 : D)						
assroo	om #302 (Art Room)			_ ^	7	6-10 years	
assroc	AC Units	3rd Floor	1	EA		,	
assroo	AC Units Ceiling - Lay-in	3rd Floor	1 781	SF	6	10+ years	
assroc	AC Units Ceiling - Lay-in					10+ years	Missing tile
assroc	AC Units Ceiling - Lay-in Ceiling - Lay-in	3rd Floor 3rd Floor	781 10	SF	6 5	10+ years 0-1 year	Missing tile Water damage
assroc	AC Units Ceiling - Lay-in	3rd Floor	781	SF SF	6	10+ years	

Campus Name: Hamilton Page : 18 of 24 Assessment Date: 11/20/2023



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	Lights in good condition
	Marker Board	3rd Floor	58	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	5	1-2 years	Water damage at ceiling
	Walls - Plaster/Drywall	3rd Floor	1,262	SF	6	10+ years	5
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Water damage
lassroc	om #303 (Music Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	871	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
				SF	5	•	Cracking at corners
	Storage/ Closet	3rd Floor	175	SF SF		1-2 years	
	Walls - Plaster/Drywall	3rd Floor	25	SF SF	6	1-2 years	Peeling paint
	Walls - Plaster/Drywall	3rd Floor	1,247	SF	6	10+ years	
assroc	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	845	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	10	SF	5	1-2 years	Missing tile
	Ceiling - Lay-in	3rd Floor	16	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	5	1-2 years	Damage at walls and ceiling
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	6	2-5 years	Damage at wane and coming
lassroc	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	847	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	24	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	vvater damage
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	•	
		3rd Floor		SF		10+ years	
	Floor - Wood		871		6	10+ years	Cood condition
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	Good condition
	Marker Board	3rd Floor	28	LF	6	6-10 years	5
	Storage/ Closet	3rd Floor	175	SF	5	1-2 years	Damage at walls and ceiling
	Walls - Plaster/Drywall	3rd Floor	1,257	SF	6	10+ years	

Campus Name: Hamilton Page : 19 of 24 Assessment Date: 11/20/2023



Alexander Hamilton Elementary School

	Schools					100	50 W Cornelia AVENUE, Chicago, IL 60657
Catego	ry : Classroom		Ві	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	15	SF	5	1-2 years	Cracks in wall
Classroo	om #310 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	851	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	20	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Wood	3rd Floor	871	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EΑ	7	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	175	SF	5	1-2 years	Damaged walls
	Walls - Plaster/Drywall	3rd Floor	1,272	SF	6	10+ years	-
Catego	ry : Interior		Ві	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
orridor	nem Type	Location	Quantity	OOM	Rank	Replacement	Comments
OTTIGOT	Ceiling - Lay-in	1st Floor	2,824	SF	6	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Asphalt Floor	1st Floor	2,735	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	34	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	5,744	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	2,710	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	10	SF	4	1-2 years	Water damage
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	9
	Floor - Asphalt Floor	2nd Floor	2,720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	26	EA	7	6-10 years	Good condition
	Student Lockers - Two Tiers	2nd Floor	19	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4,576	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,364	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	36	SF	5	1-2 years	Water damage
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	G
	Floor - Asphalt Floor	3rd Floor	1,400	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years	Lights in good condition
	Student Lockers - Two Tiers	3rd Floor	75	EA	6	10+ years	3
	Walls - Plaster/Drywall	3rd Floor	2,699	SF	6	10+ years	
	Ceiling - Exposed	Basement	900	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	1	EA	6	10+ years	
	Doors - Wood Doors include hw	Basement	2	EA	6	10+ years	
	Drinking Fountains - Single Fountain	Basement	9	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	880	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	10	SF	4	1-2 years	Peeling epoxy
	Lighting - Pendent/Surface	Basement	8	EA	7	6-10 years	3 . ,

Page : 20 of 24 Campus Name: Hamilton Assessment Date: 11/20/2023



Category : Interior		В	uilding	: Main			
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs - Concrete Stairs	Basement	12	LF	6	10+ years	
	Walls - Concrete Block	Basement	240	SF	6	10+ years	
	Walls - Masonry	Basement	160	SF	6	10+ years	
	Walls - Masonry	Basement	100	SF	5	1-2 years	Cracking
Safety							
,	Camera Viewing Station	1st Floor	1	EA	4	6-10 years	Poor visibility
	Security Cameras	1st Floor	1	EA	7	6-10 years	No interior cameras
Stairs							
	Ceiling - Lay-in	East stairs	100	SF	7	6-10 years	
	Ceiling - Lay-in	East stairs	328	SF	6	10+ years	Only lay in ceiling observed
	Ceiling - Lay-in	East stairs	22	SF	5	0-1 year	Water damage and loose tile
	Floor - Asphalt	East stairs	675	SF	5	2-5 years	Cracks forming throughout floor
	Handrails	East stairs	270	LF	7	10+ years	5 5
	Lighting - Chandelier, Incandescent	East stairs	6	EA	7	6-10 years	Good condition
	Lighting - Pendent/Surface	East stairs	3	EA	7	6-10 years	Good condition
	Stairs - Asphalt	East stairs	504	LF	6	10+ years	
	Walls - Plaster/Drywall	East stairs	3,270	SF	6	6-10 years	
	Walls - Plaster/Drywall	East stairs	30	SF	5	1-2 years	Paint cracking Quantity changed to match observed
	Ceiling - Lay-in	South	328	SF	6	10+ years	
	Ceiling - Lay-in	South	8	SF	5	1-2 years	Water damage
	Floor - Asphalt	South	84	SF	6	10+ years	ŭ
	Handrails	South	72	LF	7	10+ years	
	Lighting - Chandelier, Incandescent	South	1	EΑ	6	1-2 years	Relamp
	Stairs - Asphalt	South	216	LF	6	10+ years	•
	Walls - Plaster/Drywall	South	140	SF	6	10+ years	
	Ceiling - Lay-in	West stairs	414	SF	6	10+ years	
	Ceiling - Lay-in	West stairs	36	SF	5	1-2 years	Water damage
	Floor - Asphalt	West stairs	675	SF	5	2-5 years	Cracks forming in floor
	Handrails	West stairs	270	LF	7	10+ years	•
	Lighting - Chandelier, Incandescent	West stairs	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	West stairs	3	EA	7	6-10 years	
	Stairs - Asphalt	West stairs	404	LF	6	10+ years	
	Stairs - Asphalt	West stairs	100	LF	5	1-2 years	Cracked and chipped nosing
	Walls - Plaster/Drywall	West stairs	3,200	SF	6	10+ years	0
	Walls - Plaster/Drywall	West stairs	200	SF	5	1-2 years	Paint cracking
Vertical	Conveyance						
	Wheelchair Lift - Platform Lift	NA	1	EA	7	10+ years	





Category: Site **Building: Site**

Catego	ry : Site		В	ullaing	: Site		
_			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	•						
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	6	1-2 years	Added to match current observation
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	4	1-2 years	patch concrete Patch cracked concrete
_							
encing	Fencing - Chain Link	Entire Site	379	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	667	LF	6	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	250	LF	6	6-10 years	
andsca	pe Benches	Entire Site	4	EA	7	10+ years	Quantity changed to match current
	Bollollog	Littiro otto	•		•	101 youro	observations
	Landscape - Hardscape- Asphalt	Entire Site	1,337	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	400	SF	5	1-2 years	Quantity changed to match current
							observations Cracking/sinking
		-			_		concrete in the courtyards
	Landscape - Hardscape- Pavers	Entire Site	8,750	SF	6	10+ years	Quantity changed to match current observations
	Landscape - Mulch	Entire Site	3,834	SF	6	6-10 years	Converted into mulch and pavers
	Parkway trees	Entire Site	, 1	EA	6	10+ years	•
	Planting Beds/ Area	Entire Site	5,127	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	5,522	SF	4	1-2 years	Large cracking throughout
	Play Area - Synthetic Turf	Entire Site	4,080	SF	6	6-10 years	
	Retaining Wall - Masonry	Entire Site	201	SF	6	10+ years	
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
Parking	Lot						
9	Surface - Asphalt	North	17,465	SF	5	1-2 years	Large cracking/potholes throughout
	Surface - Concrete	North	1,500	SF	7	10+ years	
	Trash Enclosure - Chain Links	North	898	SF	7	10+ years	
	Trash Enclosure - Chain Links	North	160	SF	4	1-2 years	The fence frame is broken
Playgrou	ınd						
70	Equipment - School Age 5-12	NE	1	EA	7	10+ years	
	Surface - Poured Surface	NE	1,188	SF	7	6-10 years	
	Surface - Poured Surface	North	1,800	SF	7	6-10 years	
	Equipment - Pre K 3-5	South east	1	EA	6	6-10 years	
	Surface - Poured Surface	South east	1,800	SF	4	1-2 years	Torn throughout
O:ala=!!	_						
Sidewall	AS						



Category : Site							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	12,006	SF	7	10+ years	
Signage							
	Flag Pole - Flag Pole	Site SE	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Site SE	1	EΑ	6	6-10 years	
	Monument - Building Mounted Cut Letter	Site SE	1	EA	7	10+ years	
	Sign						

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Hamilton Page: 23 of 24 Assessment Date: 11/20/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-			
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board			
Building : Main												
Art Room	Regular Classroom	3rd Floor	302	302	871	118	80	N	Υ			
Dance Room	Regular Classroom	Basement	800	008	1,127	88	35	N	N			
Kindergarten	Regular Classroom	1st Floor	101	101	871	189	94	N	N			
Music Room	Regular Classroom	3rd Floor	303	303	871	177	80	N	Υ			
Office	Regular Classroom	1st Floor	104	104	607	80	40	N	N			
			Principal's									
Other Instructional Use	Regular Classroom	2nd Floor	208	208	871	177	80	N	N			
Regular Classroom	Multi Purpose Room	2nd Floor	206	206	607	80	40	N	N			
Regular Classroom	Regular Classroom	1st Floor	102	102	871	118	80	N	Υ			
Regular Classroom	Regular Classroom	1st Floor	103	103	871	177	80	N	Υ			
Regular Classroom	Regular Classroom	1st Floor	107	107	860	118	64	N	N			
Regular Classroom	Regular Classroom	1st Floor	108	108	871	177	80	N	Υ			
Regular Classroom	Regular Classroom	1st Floor	109	109	871	118	80	N	N			
Regular Classroom	Regular Classroom	1st Floor	110	110	871	177	80	N	Υ			
Regular Classroom	Regular Classroom	2nd Floor	201	201	871	189	94	N	Y			
Regular Classroom	Regular Classroom	2nd Floor	202	202	871	118	80	N	Υ			
Regular Classroom	Regular Classroom	2nd Floor	203	203	871	177	80	N	Υ			
Regular Classroom	Regular Classroom	2nd Floor	205	205	860	118	64	N	N			
Regular Classroom	Regular Classroom	2nd Floor	207	207	860	118	64	N	Υ			
Regular Classroom	Regular Classroom	2nd Floor	209	209	871	118	80	N	Υ			
Regular Classroom	Regular Classroom	2nd Floor	210	210	871	177	80	N	Y			
Regular Classroom	Regular Classroom	3rd Floor	301	301	871	150	60	N	Y			
Regular Classroom	Regular Classroom	3rd Floor	308	308	871	177	80	N	Y			
Regular Classroom	Regular Classroom	3rd Floor	309	309	871	118	80	N	Υ			
Regular Classroom	Regular Classroom	3rd Floor	310	310	871	177	80	N	Υ			
Science	Regular Classroom	2nd Floor	204	204	1,171	120	60	N	Υ			