

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1930	2	12,582
Addition 1	1940	2	15,537
Addition 2	1955	2	6,162
Campus Total			34,281

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	9						
	Entrance Control - Audio and Video	1 - Main Entrance	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	1 - Main Entrance	2	EΑ	6	10+ years	
	Exterior Stairs - Concrete	1 - Main Entrance	88	LF	6	10+ years	
	Exterior Stairs - Stone	1 - Main Entrance	7	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	1 - Main Entrance	64	LF	7	10+ years	
	Exterior Doors - Exterior Wood Door	6 - Roof	2	EΑ	4	0-1 year	Warped, broken glass
	Exterior Doors - Transom Lite	6 - Roof	1	EΑ	6	10+ years	
	Exterior Doors - Exterior Steel Door	7 - Fire Escape	1	EA	4	0-1 year	Deteriorated, corroded, doesn't close
	Exterior Doors - Transom Lite	7 - Fire Escape	1	EA	6	10+ years	
_Fire Esc	ape						
	Exterior Doors - Exterior Steel Door	North Façade	1	EA	4	0-1 year	Corroded, doesn't close
	Fire Escape	North Façade	5	LF	5	2-5 years	Obstructed, corroded
	Paints	North Façade	28	LF	3	0-1 year	Corroded, peeling
	Swing Stairs	North Façade	23	EA	3	0-1 year	Obstructed, corroded
_Foundat	ion						
	Foundation - Concrete	Entire Building	360	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	12,582	SF	7	10+ years	
_Lighting_							

Campus Name: Harte Page : 1 of 29 Assessment Date: 11/16/2023





Catego	ry : Exterior		В	uilding	: Main		
_						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Parapet or Roof Mounted	East Façade	2	EA	6	6-10 years	
oof Cur	tom						
oof Sys	Access Ladder - Metal	Λ	4	ГΛ	7	10	
		A	1	EA LF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	A	42	LF	6	10+ years	
	Coping - Terra Cotta	A	189	LF	7	10+ years	
	Parapet - 16" - 30" Height	A	149	LF	6	10+ years	
	Roof - Modified Bitumen	A	3,000	SF	7	10+ years	
	Roof - Modified Bitumen	A	865	SF	6	6-10 years	
						•	
	Roof Hatch - Metal	A	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Α _	3,865	SF	7	10+ years	
	Coping - Terra Cotta	B - Lower East	44	LF	6	10+ years	
	Parapet - Parapet > 30"	B - Lower East	44	LF	6	10+ years	
	Roof - Modified Bitumen	B - Lower East	121	SF	5	2-5 years	Patches throughout
	Roof Structure - Steel with Clay Tile Arch	B - Lower East	121	SF	7	10+ years	-
	Coping - Terra Cotta	С	38	LF	6	10+ years	
	Parapet - Parapet > 30"	C	38	LF	6	10+ years	
	Roof - Modified Bitumen	C	88	SF	6	6-10 years	Concrete paver sealed
	Roof Structure - Steel with Clay Tile Arch	C	88	SF	7	-	Concrete paver sealed
	Roof Structure - Steel with Clay Tile Arch	C	00	SF	/	10+ years	
Valls							
	Canopy - Concrete/ Stucco	Entire Building	80	SF	7	10+ years	
	Cornice - Terra Cotta	Entire Building	250	LF	7	10+ years	
	Exterior Walls - Brick	Entire Building	9,826	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	504	SF	5	2-5 years	
		•				•	
/indows	Guard - Guards perforated	Entire Building	211	SF	6	10+ years	
		<u> </u>		SF			
	Guard - Guards wire guard	Entire Building	27		6	10+ years	
	Lintels - Steel	Entire Building	19	LF	7	10+ years	
	Lintels - Terra Cotta	Entire Building	100	LF	7	10+ years	
	Windows - Insulated Panel	Entire Building	131	SF	6	10+ years	
	Windows - Sash Lexan/ Glass Double-pane	Entire Building	734	SF	6	10+ years	
atego	ry : Electrical		В	uilding	: Main		
<b>\</b>	Ham Time	Laatian	0	11014	De!	Recommend	Commonto
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger		Entire Duilding	40.504			0.40	
	Security System - CCTV	Entire Building	12,581	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	12,581	SF	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	3,757	SF	6	6-10 years	





	ry : Electrical		R	uilding	· Main		1556 E 5611 STREET, Chicago, IL 60657
Catego	i y . Liectricai		<u> </u>	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
o.oup	Emergency Battery Packs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	3	EA	5	6-10 years	
_Main Ser	vice						
	PA System	Entire Building	34,281	SF	5	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Entire Building	10.500	EA	7	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	12,582	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	12,582	SF	7	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Cond							
7111 00110	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	2	0-1 year	Not working at all
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	2	0-1 year	Not working at all
		Roof Roof	1	EA EA	2 2	0-1 year 0-1 year	Not working at all  Not working at all
Air Hand	Condensing Unit- Roof Mounted - Less than 5 tons Condensing Unit- Roof Mounted - Less than 5 tons		·			-	•
_Air Hand	Condensing Unit- Roof Mounted - Less than 5 tons Condensing Unit- Roof Mounted - Less than 5 tons  ling Systems Air Handling Unit- Built Up- Multi Zone- Hot Water and Chilled Water Coils - 15001 -		·			-	•
_Air Hand	Condensing Unit- Roof Mounted - Less than 5 tons Condensing Unit- Roof Mounted - Less than 5 tons  ling Systems Air Handling Unit- Built Up- Multi Zone- Hot Water and Chilled Water Coils - 15001 - 25000 cfm	Roof  Entire Building	1	EA	5	0-1 year 6-10 years	•
_Air Hand	Condensing Unit- Roof Mounted - Less than 5 tons Condensing Unit- Roof Mounted - Less than 5 tons  ling Systems Air Handling Unit- Built Up- Multi Zone- Hot Water and Chilled Water Coils - 15001 - 25000 cfm Air Intake Return Duct Work - Indoor- Vertical Shaft	Roof	1	EA	2	0-1 year	•
_Air Hand	Condensing Unit- Roof Mounted - Less than 5 tons Condensing Unit- Roof Mounted - Less than 5 tons  ling Systems Air Handling Unit- Built Up- Multi Zone- Hot Water and Chilled Water Coils - 15001 - 25000 cfm Air Intake Return Duct Work - Indoor- Vertical Shaft and Ducts	Roof  Entire Building  Entire Building Entire Building	1 1 40	EA EA LF	5 6 6	0-1 years 6-10 years 10+ years 10+ years	•
_Air Hand	Condensing Unit- Roof Mounted - Less than 5 tons Condensing Unit- Roof Mounted - Less than 5 tons  ling Systems Air Handling Unit- Built Up- Multi Zone- Hot Water and Chilled Water Coils - 15001 - 25000 cfm Air Intake Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers	Roof  Entire Building  Entire Building Entire Building Entire Building	1 1	EA EA LF EA	5 6 6	0-1 years 6-10 years 10+ years 10+ years 10+ years	•
_Air Hand	Condensing Unit- Roof Mounted - Less than 5 tons Condensing Unit- Roof Mounted - Less than 5 tons  ling Systems Air Handling Unit- Built Up- Multi Zone- Hot Water and Chilled Water Coils - 15001 - 25000 cfm Air Intake Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers Fan Coil Unit- Celing Mounted - Electric	Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 1 1 40 21	EA EA LF EA EA	5 6 6 6 5	0-1 years 6-10 years 10+ years 10+ years 10+ years 6-10 years	•
_Air Hand	Condensing Unit- Roof Mounted - Less than 5 tons Condensing Unit- Roof Mounted - Less than 5 tons  ling Systems Air Handling Unit- Built Up- Multi Zone- Hot Water and Chilled Water Coils - 15001 - 25000 cfm Air Intake Return Duct Work - Indoor- Vertical Shaft and Ducts Zone Dampers	Roof  Entire Building  Entire Building Entire Building Entire Building	1 1 1 40 21 1	EA EA LF EA	5 6 6	0-1 years 6-10 years 10+ years 10+ years 10+ years	•

Campus Name: Harte Page : 3 of 29 Assessment Date: 11/16/2023






Catego	Category : Mechanical		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Outdoor Return Fans- Air Handling Unit Type - 10001 - 20000 CFM	Roof	1	EA	6	6-10 years	
_Heating_	Devices						
	Wall Heater - Electric	Basement	2	EA	6	2-5 years	
_Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	6-10 years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	6-10 years	
_Tempera	ature Control						
	DDC System	Entire Building	12,582	SF	6	6-10 years	
	Electric Thermostat	Entire Building	3	EA	5	6-10 years	
	Thermostats - DDC	Entire Building	21	EA	6	6-10 years	
_Ventilatio	on						
	Roof Mounted Duct Work	Roof	15	LF	5	6-10 years	

Category : Plumbing **Building: Main** 

	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Basement	1	EA	5	6-10 years	
_Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	12,582	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	12,582	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	12,582	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	12,582	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	12,582	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	12,582	SF	6	6-10 years	Galvanized piping
	Sanitary Piping	Entire Building	12,582	SF	5	6-10 years	
	Storm Piping	Entire Building	12,582	SF	5	6-10 years	
	Vent Piping	Entire Building	12,582	SF	5	6-10 years	







**Building: Main** Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement **Comments** Administrative Suites/Offices 1 EΑ 7 AC Unit 1st Floor - Main Office 6-10 years Rank changed to update/correct to match current observation SF Ceiling - Plaster/Drywall 1st Floor - Main Office 468 10+ years Doors - Transom Window SF 7 10+ years 1st Floor - Main Office Doors - Wood Doors inclu hw 2 FΑ 7 1st Floor - Main Office 10+ years Floor - Tile 438 SF 6 10+ years 1st Floor - Main Office SF Floor - Tile 1st Floor - Main Office 30 5 1-2 years Broken floor tiles EΑ 7 Lighting - Pendent/Surface 1st Floor - Main Office 12 6-10 years Power Distribution 1st Floor - Main Office 8 EΑ 7 10+ years Storage/ Closet SF 1st Floor - Main Office 126 7 10+ years Walls - Plaster/Drywall 1st Floor - Main Office 1,139 SF 7 10+ years Ceiling - Exposed Basement - Custodial SF 7 104 10+ years Doors - Steel Doors incl hw Basement - Custodial EΑ 7 10+ years 1 Floor - Tile SF Basement - Custodial 104 6 10+ years Lighting - Pendent/Surface Basement - Custodial FΑ 7 6-10 years 1 Power Distribution Basement - Custodial 4 FΑ 7 10+ years SF Storage/ Closet Basement - Custodial 10 5 6-10 years SF Walls - Plaster/Drywall Basement - Custodial 456 6 10+ years Walls - Plaster/Drywall Basement - Custodial SF 6 10+ years 54 Walls - Plaster/Drywall SF Basement - Custodial 10 4 1-2 years Damaged wood and plaster walls Work SInk Basement - Custodial 1 EΑ 7 10+ years SF Ceiling - Exposed Basement Engineer's Office 112 7 10+ years Doors - Steel Doors incl hw Basement Engineer's Office EΑ 7 1 10+ years Floor - Concrete Epoxy/ Painted Basement Engineer's Office 112 SF 7 10+ years Lighting - Pendent/Surface Basement Engineer's Office 2 EΑ 7 10+ years 7 Power Distribution Basement Engineer's Office 4 EΑ 10+ years Walls - Concrete Block Basement Engineer's Office SF 7 158 10+ years SF Walls - Masonry Basement Engineer's Office 392 7 10+ years EΑ AC Unit Principals Office 1 7 6-10 years Ceiling - Plaster/Drywall Principals Office 147 SF 7 10+ years Ceiling - Plaster/Drywall SF Principals Office 8 10+ years 6 Doors - Transom Window SF Principals Office 9 7 10+ years Doors - Wood Doors inclu hw Principals Office 1 EΑ 7 10+ years Floor - Tile Principals Office 155 SF 7 10+ years EΑ 7 Lighting - Pendent/Surface Principals Office 3 6-10 years Power Distribution Principals Office 4 FΑ 7 10+ years Walls - Plaster/Drywall SF 7 **Principals Office** 578 10+ years Lunch & Multipurpose Room Ceiling - Exposed Basement SF 282 7 10+ years Doors - Wood Doors inclu hw Basement EΑ 7 10+ years 2 SF Floor - Tile Basement 282 7 10+ years Lighting - Pendent/Surface Basement 5 EΑ 7 10+ years





Category:	: Room		В	uilding	: Main		
outegoly !			_	<u>.</u>		Recommend	
Group Ite	em - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	/alls - Concrete Block	Basement	340	SF	7	10+ years	
W	/alls - Masonry	Basement	340	SF	7	10+ years	
MDF IDF							
	oors - Steel Doors incl hw	Basement	1	EA	7	10+ years	
	inishes	Basement	118	SF	7	10+ years	
	/indow AC Unit	Basement	110	EA	7	6-10 years	
VV	Wildow Ac Chil	Dasement	'	LA	,	0-10 years	
Mechanical/	Service Rooms						
St	torage Room	2nd Floor	14	SF	7	10+ years	
Bo	oiler Room	Basement	586	SF	7	10+ years	
Me	lechanical/ Service Rooms	Basement	130	SF	7	10+ years	
St	torage Room	Basement	759	SF	7	10+ years	
	torage Room	Basement	294	SF	5	1-2 years	Missing floor tiles
Prep Room							
	eiling - Plaster/Drywall	2nd Floor	92	SF	7	10+ years	
	eiling - Plaster/Drywall	2nd Floor	6	SF	4	0-1 year	Damaged
	oors - Side-lite	2nd Floor	30	SF	7	10+ years	Damagod
	oors - Transom Window	2nd Floor	36	SF	7	10+ years	
	oors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	loor - Carpet	2nd Floor	88	SF	7	6-10 years	
	loor - Carpet	2nd Floor	10	SF	4	0-1 year	Damaged
	ighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	zamagoa
\/\	/alls - Plaster/Drywall	2nd Floor	290	SF	7	10+ years	
	/ork Sink	2nd Floor	2	EA	, 7	10+ years	
Restroom						•	
	ccessories	103A	17	SF	7	6-10 years	
	eiling - Plaster/Drywall	103A	17	SF	7	10+ years	
	oors - Wood Doors inclu hw	103A	1	EA	7	10+ years	
	loor - Tile	103A	17	SF	6	10+ years	
	avatory	103A	1	EA	7	10+ years	
	ighting - Pendent/Surface	103A	1	EA	7	6-10 years	
\/\	/alls - Plaster/Drywall	103A 103A	127	SF	6	10+ years	
	/ater Closet	103A	127	EA	7	10+ years	
	ccessories	2nd Floor - Prep Room	18	SF	7	6-10 years	
	eiling - Plaster/Drywall	2nd Floor - Prep Room	18	SF	7	10+ years	
חי	oors - Wood Doors inclu hw	2nd Floor - Prep Room	10	EA	7	10+ years	
	loor - Tile	2nd Floor - Prep Room	18	SF	4	1-2 years	Worn and cracked throughout
	ighting - Pendent/Surface	2nd Floor - Prep Room	10	EA	7	6-10 years	Wom and cracked tilloughout
	/alls - Plaster/Drywall	2nd Floor - Prep Room	155	SF	, 5	1-2 years	Damaged
V V							Damaged
	/ater Closet	2nd Floor - Prep Room	1	EA	7	10+ years	





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	Basement Boys	410	SF	7	6-10 years	
	Ceiling - Lay-in	Basement Boys	366	SF	7	10+ years	
	Ceiling - Lay-in	Basement Boys	8	SF	5	1-2 years	Damaged
	Ceiling - Lay-in	Basement Boys	36	SF	4	1-2 years	Damaged
	Doors - Wood Doors inclu hw	Basement Boys	1	EA	7	10+ years	
	Floor - Tile/Sheet	Basement Boys	410	SF	7	10+ years	
	Floor Drain	Basement Boys	2	EA	7	10+ years	
	Hand Dryer	Basement Boys	2	EA	7	6-10 years	
	Lavatory	Basement Boys	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement Boys	8	EA	7	10+ years	
	Partitions	Basement Boys	4	EA	7	10+ years	
	Urinals	Basement Boys	7	EA	7	10+ years	
	Walls - Concrete Block	Basement Boys	130	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement Boys	520	SF	7	10+ years	
	Water Closet	Basement Boys	4	EA	7	10+ years	
	Accessories	Basement Girls	410	SF	7	6-10 years	
	Ceiling - Lay-in	Basement Girls	410	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement Girls	1	EA	7	10+ years	
	Floor - Terrazzo	Basement Girls	410	SF	7	10+ years	
	Floor Drain	Basement Girls	1	EA	7	10+ years	
	Hand Dryer	Basement Girls	2	EA	7	6-10 years	
	Lavatory	Basement Girls	3	EA	7	10+ years	
	Lighting - Lay-in	Basement Girls	7	EA	7	6-10 years	
	Lighting - Pendent/Surface	Basement Girls	1	EA	7	6-10 years	
	Partitions	Basement Girls	9	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement Girls	648	SF	7	10+ years	
	Water Closet	Basement Girls	9	EA	7	10+ years	
	Accessories	Main Office	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	1	EA	7	10+ years	
	Floor - Tile	Main Office	28	SF	6	10+ years	
	Lavatory	Main Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Main Office	1	EA	7	6-10 years	
	Partitions	Main Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Main Office	169	SF	7	10+ years	
	Water Closet	Main Office	2	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #003 (Other Instructional Use)						
	Ceiling - Exposed	Basement	380	SF	6	10+ years	
	Doors - Transom Window	Basement	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	





Catego	ry : Classroom		В	uilding	: Main		1330 E 30th OTNEET, Onleage, le 00037
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Floor - Tile	Basement	376	SF	6	10+ years	
	Floor - Tile	Basement	4	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	Basement	6	EA	7	6-10 years	Ç
	Walls - Plaster/Drywall	Basement	873	SF	5	10+ years	
	Work Sink	Basement	1	EA	7	10+ years	
Classroo	om #004 (Office)						
<u> </u>	Ceiling - Plaster/Drywall	Basement	832	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	7	10+ years	
	Floor - Tile	Basement	832	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	15	EA	7	10+ years	
	Walls - Masonry	Basement	1,240	SF	7	10+ years	
	Work Sink	Basement	1,240	EA	7	10+ years	
	WORKSHIK	Dasement	1	LA	,	10+ years	
_Classroo	om #103 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	816	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	816	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years	
	Marker Board	1st Floor	25	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,321	SF	7	10+ years	
_Classroo	om #105 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	801	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	801	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,286	SF	7	10+ years	
Classroo	om #107 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	803	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
			Ŭ	<u> </u>	•	,	





Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Wood	1st Floor	803	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	11	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EΑ	5	1-2 years	Broken fixture cover
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Storage/ Closet	1st Floor	22	SF	5	1-2 years	Peeling paint falling to the floor
	Walls - Plaster/Drywall	1st Floor	1,321	SF	7	10+ years	Tooming paint raining to the hoof
Classroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	806	SF	6	10+ years	
				SF			Damagad
	Ceiling - Plaster/Drywall Doors - Transom Window	2nd Floor	10	SF SF	4 7	0-1 year	Damaged
		2nd Floor	9			10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	813	SF	7	10+ years	
	Floor - Wood	2nd Floor	3	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,275	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	25	SF	4	0-1 year	Damaged
Classroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	810	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	810	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	5	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,328	SF	7	10+ years	
Classroc	om #205 (Computer Lab)						
	AC Units	2nd Floor	3	EΑ	7	6-10 years	
	Casework	2nd Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	799	SF	5	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood Books including	2nd Floor	799	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
		2nd Floor	12	SF	7		
	Storage/ Closet	ZIIU FIUUI	11	SF	1	10+ years	








Catego	ry : Classroom	·	В	uilding	: Main	·	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,165	SF	5	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroo	om #207 (Science Classroom)						
	Casework	2nd Floor	3	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	766	SF	7	10+ years	
	Chalk Board	2nd Floor	15	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EΑ	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Wood	2nd Floor	761	SF	6	10+ years	
	Floor - Wood	2nd Floor	5	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	6-10 years	
	Storage/ Closet	2nd Floor	59	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,250	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	50	SF	5	0-1 year	Damaged
	Work Sink	2nd Floor	1	EΑ	7	2-5 years	•

Category : Interior **Building: Main** 

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor - North	770	SF	6	10+ years	
	Floor - Terrazzo	1st Floor - North	111	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor - North	659	SF	7	10+ years	
	Lighting - Wall Mounted	1st Floor - North	17	EA	7	6-10 years	
	Stairs - Terrazzo	1st Floor - North	30	LF	6	10+ years	
	Student Lockers - One Tier	1st Floor - North	13	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - North	1,947	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - South	286	SF	6	10+ years	
	Doors - Side-lite	1st Floor - South	28	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor - South	2	EA	6	10+ years	
	Doors - Transom Window	1st Floor - South	24	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor - South	2	EA	6	10+ years	
	Floor - Terrazzo	1st Floor - South	152	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor - South	134	SF	7	10+ years	
	Lighting - Wall Mounted	1st Floor - South	4	EA	7	6-10 years	
	Stairs - Terrazzo	1st Floor - South	30	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - South	726	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor - South	227	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - North	700	SF	6	10+ years	
	Doors - Side-lite	2nd Floor - North	22	SF	6	10+ years	
	Doors - Transom Window	2nd Floor - North	18	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Floor - North	2	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor - North	700	SF	4	1-2 years	Cracked and worn throughout

Campus Name: Harte Page : 10 of 29 Assessment Date: 11/16/2023





Catego	ry : Interior		В	uilding	: Main	<del>g</del> :	
22.090	. ,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Lighting - Pendent/Surface	2nd Floor - North	4	EA	7	6-10 years	
	Lighting - Wall Mounted	2nd Floor - North	5	EA	7	6-10 years	
	Stairs - Terrazzo	2nd Floor - North	36	LF	7	10+ years	
	Student Lockers - Two Tiers	2nd Floor - North	18	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - North	1,566	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - South	264	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor - South	159	SF	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor - South	100	SF	4	0-1 year	Cracked and worn throughout
	Lighting - Wall Mounted	2nd Floor - South	3	EA	7	6-10 years	•
	Student Lockers - Two Tiers	2nd Floor - South	34	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - South	600	SF	6	10+ years	
	Ceiling - Exposed	Basement	1,810	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement	2	EA	6	10+ years	
	Drinking Fountains - Single Fountain	Basement	1	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	Basement	2	EA	7	6-10 years	
	Floor - Tile/Sheet	Basement	1,810	SF	7	10+ years	
	Lighting - Wall Mounted	Basement	29	EA	7	6-10 years	
	Walls - Masonry	Basement	1,954	SF	6	10+ years	
Safety							
-	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	6	EA	7	6-10 years	
	Security Cameras	Entire Building	10	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North	152	SF	6	10+ years	
	Floor - Terrazzo	North	25	SF	6	10+ years	
	Handrails	North	20	LF	5	6-10 years	
	Lighting - Pendent/Surface	North	1	EA	6	10+ years	
	Stairs - Terrazzo	North	104	LF	6	10+ years	
	Walls - Plaster/Drywall	North	303	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	152	SF	6	10+ years	
	Floor - Terrazzo	South	25	SF	6	10+ years	
	Handrails	South	20	LF	5	6-10 years	
	Lighting - Pendent/Surface	South	1	EA	6	6-10 years	
	Stairs - Terrazzo	South	104	LF	6	10+ years	
	Walls - Plaster/Drywall	South	303	SF	6		




Category : Exterior			В	uilding	: Additio	on 1	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	2 - South	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	2 - South	2	EA	5	2-5 years	
	Exterior Doors - Transom Lite	2 - South	- 1	EΑ	6	6-10 years	
	Exterior Stairs - Stone	2 - South	7	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	5 - North	2	ĒΑ	6	6-10 years	
	Exterior Doors - Transom Lite	5 - North	1	ΕA	4	1-2 years	Damaged, deteriorated frame
	Exterior Stairs - Stone	5 - North	7	LF	5	2-5 years	
Foundati	ion						
	Foundation - Concrete	Entire Building	247	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	15,537	SF	7	10+ years	
ighting							
5 _ 5	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	6	6-10 years	
Roof Sys							
	Coping - Terra Cotta	D - South	99	LF	6	10+ years	
	Downspouts - Interior Downspouts	D - South	38	LF	6	10+ years	
	Parapet - 16" - 30" Height	D - South	99	LF	6	10+ years	
	Roof - Modified Bitumen	D - South	2,158	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	D - South	2,158	SF	7	10+ years	
	Access Ladder - Metal	E - West	1	EA	7	10+ years	
	Coping - Terra Cotta	E - West	95	LF	6	10+ years	
	Downspouts - Interior Downspouts	E - West	28	LF	6	6-10 years	
	Parapet - 16" - 30" Height	E - West	51	LF	6	10+ years	
	Parapet - Parapet > 30"	E - West	44	LF	6	10+ years	
	Roof - Modified Bitumen	E - West	2,059	SF	5	2-5 years	
	Roof Hatch - Metal	E - West	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	E - West	2,059	SF	7	10+ years	
	Access Ladder - Metal	F - North	1	EA	7	10+ years	
	Access Ladder - Wood	F - North	1	EA	7	10+ years	
	Coping - Terra Cotta	F - North	53	LF	6	10+ years	
	Downspouts - Interior Downspouts	F - North	38	LF	6	10+ years	
	Parapet - 16" - 30" Height	F - North	53	LF	6	10+ years	
	Roof - Modified Bitumen	F - North	1,162	SF	5	2-5 years	
	Roof Hatch - Metal	F - North	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	F - North	1,162	SF	7	10+ years	
Walls							
	Cornice - Terra Cotta	Entire Building	30	LF	6	10+ years	

Campus Name: Harte Page : 12 of 29 Assessment Date: 11/16/2023



Category : Exterior			В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	4,992	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	300	SF	3	0-1 year	Issuing bricks, displaced, bowing wa
	Exterior Walls - Terra Cotta	Entire Building	232	SF	6	10+ years	
Nindow:							
viridow.	Guard - Guards wire guard	Entire Building	261	SF	6	10+ years	
	Lintels - Steel	Entire Building	72	LF	7	10+ years	
	Windows - Insulated Panel	Entire Building	36	SF	6	•	
						10+ years	
	Windows - Louver Windows - Sash Lexan	Entire Building Entire Building	4 732	SF SF	7 5	10+ years 2-5 years	Discolored
	Williauws - Sasii Lexaii	Little Building	132	SF	3	2-5 years	Discolored
Catego	ry : Electrical		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System	Location	Quantity	COM	Rank	Replacement	Comments
	Emergency A/C Power - Gym	1st Floor	2,844	SF	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	18	EA	6	10+ years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	1	ΕA	5	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	17	EΑ	5	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	5	6-10 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	5	6-10 years	
	Security System - CCTV	Entire Building		SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	15,537 15,537	SF	5		
	Automatic Transfer Switch	Mechanical Room	15,557	EA	6	6-10 years 6-10 years	
	Automatic Transfer Switch	Woonamoar Room	·		Ū	o ro youro	
Main Se						0.40	
	Main Electrical Service - 2001 to 3000 A 120/240/3PH	Basement	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Basement	1	EA	6	10+ years	
	PA System	Entire Building	15,537	SF	5	6-10 years	
ower D	Distribution						
	Lighting and Power Panels - 100 A	Basement	2	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Basement	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Basement	8	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Basement	2	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Basement	1	EA	7	10+ years	

Campus Name: Harte Page: 13 of 29 Assessment Date: 11/16/2023



	SCHOOIS						1556 E 56th STREET, Chicago, IL 60637			
Catego	ry : Electrical		В	uilding	: Additi	on 1				
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Catama	w Fina Brataction		В	به ما المالي	. A al al:4:	1				
Catego	ry : Fire Protection	Building : Addition 1								
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Commonts			
•		Location	Quantity	OOW	Nalik	Replacement	Comments			
Fire Alar		Fating Desilations	45 507	0.5		0.40				
	Fire Alarm System	Entire Building Entire Building	15,537 15,537	SF SF	6 6	6-10 years 6-10 years				
	Fire Alarm_System	Entire Building	10,007	SF	O	0-10 years				
Catego	ry : Mechanical		В	uildina	: Additi	on 1				
Outogo	i y : iliconamoui			unung	. Additi	Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Air Hand	lling Systems		•			•				
7 111 1 101 10	Air Handling Unit- Built Up- Multi Zone- Hot	Basement	1	EA	6	6-10 years				
	Water Coils - 15001 - 25000 cfm		·		_	5 15 J 5 5 11 5				
	Air Intake	Basement	1	EA	5	6-10 years				
	Auxiliaries - 15001 - 25000 cfm	Basement	1	EA	6	6-10 years				
	Return Duct Work - Indoor- Vertical Shaft	Basement	40	LF	6	6-10 years				
	and Ducts	_			_					
	Zone Dampers	Basement	18	EΑ	6	6-10 years				
	Outdoor Return Fans- Air Handling Unit	Roof	1	EA	5	6-10 years				
	Type - 10001 - 20000 CFM									
Boiler S	vetome									
Doller Sy	Boiler Auxiliary- Non Condensing Hot Water	Boiler Room	2	EA	6	6-10 years				
	- 2001 - 3000 MBH	Doller Room	2	LA	U	0-10 years				
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years				
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years				
	Glycol Feed System	Boiler Room	1	EA	5	6-10 years				
	Non Condensing- Water Tube- Flexible	Boiler Room	1	EA	6	6-10 years				
	Tube- Force Draft- Hot Water Boiler - 2001									
	- 3000 MBH	5 " 5				0.40				
	Non Condensing- Water Tube- Flexible	Boiler Room	1	EA	6	6-10 years				
	Tube- Force Draft- Hot Water Boiler - 2001 - 3000 MBH									
	Water Fill System	Boiler Room	1	EA	6	6-10 years				
	Water i iii Oysterii	Bollet Room	'	LA	U	0-10 years				
Heating	Devices									
. ioaiiig	Unit Heater - Electric	Boiler Room	1	EA	5	6-10 years				
		= =	•	-/ \	Ŭ	o .o youro				
Mechani	cal Plumbing									
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years				
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years				
	·					•				





Pumps - Sump-Simplex

							1330 E 30til OTKEET, Officago, IE 00037
Catego	ry : Mechanical		В	uilding	: Additi	on 1	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hot Water Pump - Less than 10	Boiler Room	1	EΑ	6	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	200	LF	6	6-10 years	
Tempera	ature Control						
	DDC System	Entire Building	15,537	SF	6	6-10 years	
	Thermostats - DDC	Entire Building	18	EA	6	6-10 years	
Ventilati	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Roof Mounted Duct Work	Entire Building	10	LF	5	6-10 years	
Catego	ry : Plumbing		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping	**		•			•	
	Domestic Piping-Hot Water Return Lines	Entire Building	15,537	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	15,537	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	15,537	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	15,537	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	15,537	SF	6	10+ years	
	Sanitary Piping	Entire Building	15,537	SF	6	10+ years	
	Storm Piping	Entire Building	15,537	SF	6	10+ years	
	Vent Piping	Entire Building	15,537	SF	6	10+ years	
Pumps							

Category : Classroom **Building: Addition 1** 

Boiler Room

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #001 (Art Room)						
	Ceiling - Exposed	Basement	730	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EΑ	7	10+ years	
	Floor - Tile	Basement	726	SF	6	6-10 years	
	Floor - Tile	Basement	4	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	Basement	15	EA	7	6-10 years	-
	Walls - Masonry	Basement	1,068	SF	7	10+ years	
	Work Sink	Basement	1	EA	4	1-2 years	Damaged

1

EΑ

5

6-10 years





Category : Classroom			В	uilding	: Additi	on 1	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #002 (Counseling Room)						
	Ceiling - Exposed	Basement	375	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	ĒΑ	7	10+ years	
	Floor - Tile	Basement	375	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	9	EΑ	7	6-10 years	
	Walls - Masonry	Basement	580	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	193	SF	6	10+ years	
	Trans Tractor/21/Trans	Bassment	.00	O.	Ŭ	io. youro	
Classroc	om #101 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	784	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	784	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,312	SF	7	10+ years	
Naceroo	om #102 (Kindergarten)						
JIASSIUC	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	784	SF	7		
	Chalk Board	1st Floor	20	LF	4	10+ years	
	Doors - Transom Window			SF		2-5 years	
		1st Floor	9		7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Wood	1st Floor	784	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,269	SF	7	10+ years	
laseroo	om #106 (Regular Classroom)						
عاد معادلات	AC Units	1st Floor	3	EA	7	6-10 years	
	Casework	1st Floor	4	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	801	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood Doors inclu riw	1st Floor	801	SF	7	-	
						10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	32	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	



Category : Classroom			Building : Addition 1					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Plaster/Drywall	1st Floor	1,183	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Damaged plaster wall next to door	
_Classroo	om #201 (Regular Classroom)							
	AC Units	2nd Floor	3	EA	7	6-10 years		
	Casework	2nd Floor	4	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	773	SF	6	10+ years		
	Chalk Board	2nd Floor	20	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Wood	2nd Floor	773	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years		
	Storage/ Closet	2nd Floor	9	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,312	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	0-1 year	Damaged	
Classroo	om #202 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	4	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	788	SF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	10+ years		
	Chalk Board	2nd Floor	20	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	10+ years		
	Floor - Wood	2nd Floor	793	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years		
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	9	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	1,312	SF	7	10+ years		
_Classroo	om #206 (Regular Classroom)							
	AC Units	2nd Floor	3	EA	7	6-10 years		
	Casework	2nd Floor	21	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	801	SF	6	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Wood	2nd Floor	798	SF	6	10+ years		
	Floor - Wood	2nd Floor	3	SF	4	0-1 year	Damaged	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	-3	
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	9	SF	5	2-5 years		
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	7	10+ years		





Catego	ry : Room		В	uilding	on 1		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Gymnasi	a						
,	Ceiling - Plaster/Drywall	1st Floor	1,880	SF	7	10+ years	
	Doors - Transom Window	1st Floor	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	7	10+ years	
	Floor - Wood	1st Floor	1,880	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	6	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	232	SF	7	10+ years	
	Stage Curtain	1st Floor	10	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Asphalt	1st Floor	34	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	730	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,121	SF	7	10+ years	
Kitchen							
	Ceiling - Plaster/Drywall	Basement	578	SF	7	10+ years	
	Doors - Steel Doors incl hw	Basement	2	ĒΑ	7	10+ years	
	Floor - Tile	Basement	523	SF	7	10+ years	
	Floor - Tile	Basement	50	SF	4	1-2 years	Broken floor tiles
	Lighting - Pendent/Surface	Basement	5	ĒΑ	7	6-10 years	
	Serving Line	Basement	12	LF	7	10+ years	
	Walls - Concrete Block	Basement	484	SF	7	10+ years	
	Walls - Masonry	Basement	484	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	120	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement	48	SF	7	10+ years	
unch &	Multipurpose Room						
_uncn x	Ceiling - Lay-in	Basement	1,056	SF	7	10+ years	
	Floor - Tile	Basement	1,056	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	12	EA	7	10+ years	
	Walls - Masonry	Basement	682	SF	7	10+ years	
	Walls - Masorily	basement	002	Si	,	10+ years	
/lechani	cal/ Service Rooms						
	Janitor's Closet	2nd Floor	61	SF	7	10+ years	
	Boiler Room	Basement	800	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	700	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	200	SF	7	10+ years	
	Storage Room	Basement	418	SF	7	10+ years	
Catego	ry : Interior		В	uildina	: Additio	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							





Catego	ry : Interior		В	uilding	: Additi	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor South	681	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor South	2	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor South	2	EA	6	10+ years	
	Floor - Terrazzo	1st Floor South	182	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor South	469	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor South	30	SF	4	1-2 years	Broken and cracked floor tiles
	Lighting - Wall Mounted	1st Floor South	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor South	1,841	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor South	270	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor West	700	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor West	1	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor West	2	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor West	700	SF	7	10+ years	
	Lighting - Wall Mounted	1st Floor West	16	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor West	1,771	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor South	661	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor South	4	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor South	661	SF	7	10+ years	
	Lighting - Wall Mounted	2nd Floor South	9	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor South	17	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor South	1,470	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor West	705	SF	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor West	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor West	705	SF	4	0-1 year	Cracking, worn throughout
	Lighting - Wall Mounted	2nd Floor West	16	EA	7	6-10 years	
	Student Lockers - Two Tiers	2nd Floor West	51	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor West	1,151	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North Stairs Corridor	178	SF	7	10+ years	
	Doors - Steel Doors incl hw	North Stairs Corridor	2	EA	7	10+ years	
	Floor - Terrazzo	North Stairs Corridor	178	SF	7	10+ years	
	Lighting - Wall Mounted	North Stairs Corridor	3	EA	7	6-10 years	
	Stairs - Terrazzo	North Stairs Corridor	26	LF	7	10+ years	
	Walls - Plaster/Drywall	North Stairs Corridor	435	SF	7	10+ years	
	Walls - Structural Glazed Tile	North Stairs Corridor	135	SF	7	10+ years	
<u>Stairs</u>	0.11.					10	
	Ceiling - Plaster/Drywall	North	177	SF	7	10+ years	
	Floor - Epoxy/ Painted	North	67	SF	7	10+ years	
	Floor - Terrazzo	North	188	SF	7	10+ years	
	Floor - Tile/Sheet	North	144	SF	7	10+ years	
	Handrails	North	123	LF	7	10+ years	
	Lighting - Pendent/Surface	North	2	EA	7	6-10 years	
	Lighting - Wall Mounted	North	6	EA	7	6-10 years	
	Stairs - Terrazzo	North	223	LF	7	10+ years	

Campus Name: Harte Page: 19 of 29 Assessment Date: 11/16/2023



Catego	ry : Interior	В	Building : Addition 1						
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	North	2,008	SF	7	10+ years			
	Ceiling - Plaster/Drywall	South	223	SF	7	10+ years			
	Floor - Epoxy/ Painted	South	77	SF	7	10+ years			
	Floor - Terrazzo	South	117	SF	7	10+ years			
	Floor - Tile/Sheet	South	65	SF	7	10+ years			
	Handrails	South	127	LF	7	10+ years			
	Lighting - Pendent/Surface	South	2	EA	7	6-10 years			
	Lighting - Wall Mounted	South	5	EA	7	6-10 years			
	Stairs - Terrazzo	South	221	LF	7	10+ years			
	Walls - Plaster/Drywall	South	1,881	SF	6	10+ years			

Campus Name: Harte Page : 20 of 29 Assessment Date: 11/16/2023



Catego	ry : Exterior	Building : Addition 2							
0	Name Tama	Laartian	0	LIOM	D I-	Recommend	0		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Entrance		2	4		4	0.4	Description and according		
	Exterior Doors - Exterior Wood Door Exterior Stairs - Stone	3	1	EA LF	4 7	0-1 year 10+ years	Door falling apart, warped, peeling		
	Entrance Control - Audio and Video	4	3 1	EA	6	6-10 years			
	Exterior Doors - Exterior Steel Door	4	2	EA	6	10+ years			
	Extend Book Extend Glod Book	•	_	_/ \	Ū	To Fyddio			
_Foundat	on								
	Foundation - Concrete	Entire Building	243	LF	7	10+ years			
	Superstructure - Concrete	Entire Building	6,162	SF	7	10+ years			
	·	· ·				•			
_Lighting									
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	3	EA	6	6-10 years			
_Roof Sys	stem								
	Access Ladder - Metal	G	2	EA	7	10+ years			
	Coping - Stone	G	198	LF	6	10+ years			
	Downspouts - Exterior Downspouts	G	30	LF	6	10+ years			
	Parapet - 16" - 30" Height	G	198	LF	6	10+ years			
	Roof - Modified Bitumen	G	2,581	SF	6	6-10 years			
	Roof - Modified Bitumen	G	500	SF	4	0-1 year	Leak		
	Roof Hatch - Metal	G	1	EA	7	10+ years			
	Roof Structure - Steel with Clay Tile Arch	G	3,081	SF	7	10+ years			
_Walls									
	Canopy - Metal	Entire Building	60	SF	6	10+ years			
	Exterior Walls - Brick	Entire Building	5,073	SF	6	10+ years			
_Windows						10			
	Lintels - Steel	Entire Building	129	LF	7	10+ years			
	Windows - Insulated Panel	Entire Building	324	SF SF	6	10+ years	Discolared		
	Windows - Sash Lexan/ Glass Double-pane	Entire Building	642	SF	5	10+ years	Discolored		
Catego	ry : Electrical		Building : Addition 2						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
	ncy System		•			•			
	Exit Signs - Corridors and Stairs	Entire Building	2	EA	5	6-10 years			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	1	EA	6	6-10 years			
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years			
	Emergency A/C Power - Corridors and	Entire Building	980	SF	6	10+ years			

Campus Name: Harte Page : 21 of 29 Assessment Date: 11/16/2023





XIII.	Schools						1556 E 56th STREET, Chicago, IL 60637
Catego	ry : Electrical		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs Contains COTV	Fatin Building	0.400	0.5	0	0.40	
	Security System - CCTV Security System - Intrusion Detection	Entire Building Entire Building	6,162 6,162	SF SF	6 6	6-10 years 6-10 years	
	Security System - Intrusion Detection	Entire Building	0,102	SF	0	6-10 years	
Main Se	rvice						
	PA System	Entire Building	6,162	SF	5	6-10 years	
D D	teach cates						
Power D	istribution	Fating Duilding	4		7	10	
	Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building	1	EA EA	7 7	10+ years	
	Lighting and Fower Fallets - Above 100 A	Entire Building	ı	EA	,	10+ years	
Catego	ry : Fire Protection		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	6,162	SF	6	10+ years	
	Fire Alarm_System	Entire Building	6,162	SF	7	10+ years	
Catego	ry : Mechanical		В	uildina	: Additi	on 2	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	cal Plumbing						
	Hydronic Supply and Return - Steel	Entire Building	200	LF	6	10+ years	
		•				•	
Tempera	ature Control						
	DDC System	Entire Building	6,162	SF	6	6-10 years	All tie in together
	Thermostats - DDC	Entire Building	7	EA	6	6-10 years	
Ventilation							
	Exhaust Fans- Roof Mounted - Less than	Roof	1	EA	6	6-10 years	
	500 CFM						
Catego	ry : Plumbing		В	uildina	: Additi	on 2	
Guiogo	. y . r iumomy			anamg			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping			•				
1 -5 -	Domestic Piping-Hot Water Return Lines	Entire Building	6,162	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	6,162	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to	Entire Building	6,162	SF	6	10+ years	
	Fixtures	-	•			•	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	6,162	SF	6	10+ years	

Campus Name: Harte Page : 22 of 29 Assessment Date: 11/16/2023





Category : Plumbing		В	uilding	: Additi			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	6,162	SF	6	10+ years	
	(Risers)				_		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	6,162	SF	6	10+ years	
	(from Risers to Fixtures)	E 4 B 4 B	0.400	0=	•	4.0	
	Sanitary Piping	Entire Building	6,162	SF	6	10+ years	
	Storm Piping	Entire Building	6,162	SF	6	10+ years	
	Vent Piping	Entire Building	6,162	SF	6	10+ years	
Catego	ry : Room		В	uilding	: Additi	on 2	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	1st Floor - Adjustment Room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Adjustment Room	268	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Adjustment Room	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Adjustment Room	268	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Adjustment Room	6	EA	7	6-10 years	
	Power Distribution	1st Floor - Adjustment Room	8	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Adjustment Room	633	SF	7	10+ years	
	AC Unit	2nd Floor - Teachers Lounge	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Teachers Lounge	245	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Teachers Lounge	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor - Teachers Lounge	243	SF	6	10+ years	
	Floor - Tile	2nd Floor - Teachers Lounge	2	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor - Teachers Lounge	3	EA	7	6-10 years	Damagoa
	Power Distribution	2nd Floor - Teachers Lounge	4	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Teachers Lounge	845	SF	7	10+ years	
	Walls Tlastel/Diywall	Zha i looi - reachers Lourige	040	O.	,	101 years	
Library							
	AC Unit	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	120	LF	7	10+ years	
	Ceiling - Splined	2nd Floor	910	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	835	SF	7	6-10 years	
	Floor - Tile	2nd Floor	75	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	25	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	950	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4	SF	4	1-2 years	Spalling, crumbling
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	12	SF	5	1-2 years	Paint is peeling and falling to the floo
		Janitor's closet 2nd floor	12	SF	7	10+ years	to pooming and raining to the hoo
	Janitor's Closet	Jannoi e Cioeti viia nooi					

Campus Name: Harte Page : 23 of 29 Assessment Date: 11/16/2023





Category: Room		В	uilding	: Additi	on 2		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
stroor	n						
	Accessories	109A	19	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	109A	19	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109A	1	EΑ	7	10+ years	
	Floor - Tile	109A	19	SF	6	10+ years	
	Lighting - Pendent/Surface	109A	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	109A	160	SF	7	10+ years	
	Water Closet	109A	1	EA	7	10+ years	
	Accessories	1st Floor - Next to 108	50	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Next to 108	42	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Next to 108	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Next to 108	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor - Next to 108	50	SF	7	10+ years	
	Lavatory	1st Floor - Next to 108	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Next to 108	1	EΑ	7	6-10 years	
	Partitions	1st Floor - Next to 108	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Next to 108	219	SF	7	10+ years	
	Water Closet	1st Floor - Next to 108	1	EA	7	10+ years	
	Accessories	1st Floor - Next to 109	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Next to 109	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Next to 109	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Next to 109	35	SF	6	10+ years	
		1st Floor - Next to 109	1	EA	7	10+ years	
	Lavatory Lighting - Pendent/Surface	1st Floor - Next to 109	1	EA	7		
	Walls - Plaster/Drywall		•	SF	7	6-10 years	
	Water Closet	1st Floor - Next to 109	168	Sr EA	7	10+ years	
		1st Floor - Next to 109	1	SF		10+ years	
	Accessories	2nd Floor	32		7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	32	SF	7	10+ years	
	Lavatory	2nd Floor	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EΑ	7	6-10 years	
	Partitions	2nd Floor	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	166	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	2nd Floor - Teachers Lounge	28	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Teachers Lounge	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Teachers Lounge	1	EA	7	10+ years	_
	Floor - Tile	2nd Floor - Teachers Lounge	28	SF	4	1-2 years	Damaged
	Lavatory	2nd Floor - Teachers Lounge	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor - Teachers Lounge	1	EA	7	6-10 years	
	Partitions	2nd Floor - Teachers Lounge	1	EA	7	10+ years	







Category : Room			В	uilding	: Additi	on 2	1000 E GOLLI GIRCET, GILLOUGE, IE GOOGF
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Walls - Plaster/Drywall	2nd Floor - Teachers Lounge	148	SF	5	10+ years	
	Water Closet	2nd Floor - Teachers Lounge	1	EA	7	10+ years	
		·				•	
Catego	ry : Classroom		В	uilding	: Additi	on 2	
			0	11014	D	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	848	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	848	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Student Lockers - One Tier	1st Floor	10	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	963	SF	6	10+ years	
Classro	om #109 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	848	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	848	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,151	SF	7	10+ years	
	Work Sink	1st Floor	1,131	EA	7	10+ years	
	WOIR SIIR	15t F1001	ı	LA	,	10+ years	
Classro	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	848	SF	7	10+ years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	844	SF	7	10+ years	
	Floor - Tile	2nd Floor	4	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	•
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,143	SF	5	10+ years	
	,		,		-	,	



Category : Interior			В	uilding	on 2		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	350	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	345	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	5	SF	4	1-2 years	Missing floor tiles
	Lighting - Wall Mounted	1st Floor	10	EA	7	6-10 years	•
	Walls - Plaster/Drywall	1st Floor	879	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	364	SF	5	10+ years	
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	364	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	20	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	620	SF	5	10+ years	
Stairs							
	Ceiling - Plaster/Drywall	East	226	SF	6	10+ years	
	Floor - Terrazzo	East	202	SF	6	10+ years	
	Handrails	East	51	LF	7	10+ years	
	Lighting - Pendent/Surface	East	2	EA	6	6-10 years	
	Stairs - Terrazzo	East	85	LF	6	10+ years	
	Walls - Plaster/Drywall	East	1,075	SF	6	10+ years	
	Walls - Structural Glazed Tile	East	147	SF	5	10+ years	





Category : Site **Building: Site** 

Jaiego	ry . Site		Building . Site							
						Recommend				
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
ivil/Dra	inage									
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	7	10+ years				
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	6	1-2 years	Blocked, north and south			
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	7	10+ years	Blocked, Horar and South			
	Olviii Brainage Olic Marinole	Entire Oite	O	L/\	,	101 years				
encing										
	Fencing - Chain Link	Entire Site	105	LF	5	6-10 years	Removed for sidewalk repair			
	Fencing - Chain Link	Entire Site	275	LF	4	0-1 year	Missing parts, damaged, uneven			
	Fencing - New Standard Ornamental	Entire Site	110	LF	7	10+ years				
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	70	LF	7	10+ years				
andaaa										
andsca	Landscape - Hardscape- Concrete	East	755	SF	7	10+ years				
	Parkway trees	East	1	EA	7	10+ years				
	Planting Beds/ Area	East	125	SF	6	10+ years				
		East	4,564	SF	7	10+ years				
	Play Area - Hardscape- Asphalt			EA	7 7					
	Trash Receptacles	East	3	EA	/	10+ years				
arking	Lot									
	Concrete Curbs	Parking Lot- North	200	LF	7	10+ years				
	Pavers	Parking Lot- North	380	SF	7	10+ years				
	Trash Enclosure - Chain Links	Parking Lot- North	78	SF	6	6-10 years				
Playgrou	ind									
iay groc	Equipment - Pre K 3-5	North	1	EA	7	10+ years				
	Surface - Poured Surface	North	2,433	SF	6	2-5 years				
	Equipment - Combo 3-12	South	_,	ĒΑ	7	10+ years				
	Surface - Poured Surface	South	2,457	SF	7	10+ years				
			_,	О.	•	,				
idewalk										
	Sidewalks - Internal Walks	South	250	LF	7	10+ years				
	Sidewalks - Perimeter Sidewalks	South	3,078	SF	7	10+ years				
Signage										
<del>J</del>	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years				
	Marquee - Building Mounted Back Lighted	Entire Site	1	EA	5	2-5 years				
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	5	2-5 years	No power			
			·		-	,	- 1			



### **Bret Harte Elementary School**

1556 E 56th STREET, Chicago, IL 60637

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Harte Page : 28 of 29 Assessment Date: 11/16/2023





Classroom Summary

Classroom Summary				T	ı				
				Floor Plan		Glazed	Operable	100	
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	· · · · · · · · · · · · · · · · · · ·			1	i .	+		1	1
Computer Lab	Regular Classroom	2nd Floor	205	203	810	150	75	Y	Υ
Kindergarten	Regular Classroom	1st Floor	105	103	810	150	75	Y	Υ
Office	Regular Classroom	Basement	004	004	832	36	36		
Other Instructional Use	Faculty Lounge	Basement	003	003	380	24	24	N	Υ
Pre School	Pre School	1st Floor	103	101	825	150	75	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	107	104	803	150	75	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	201	816	150	75	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	202	810	150	75	Y	Υ
Science Classroom	Regular Classroom	2nd Floor	207	204	766	120	60	Υ	Υ
		•						-	
Building : Addition 1									
Art Room	Library	Basement	001	Bsmt.	730	18	18	N	N
				Library					
Counseling Room	Library	Basement	002	N/A	375	12	12	N	N
Kindergarten	Regular Classroom	1st Floor	102	114	784	150	75	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	101	115	784	150	75	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	106	110	801	150	75	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	208	773	150	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	208	793	150	75	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	204	801	150	75	N	Υ
		•	-	•	•	•		•	•
Building : Addition 2									
Kindergarten	Kindergarten	1st Floor	109	111	848	180	90	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	108	110	848	180	90	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	212	848	180	90	Y	Υ