

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|------------------------------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1975 | 3 | 186,327 |
| Linked Addition-Athletic Building | 1975 | 1 | 52,621 |
| Linked Addition-Fine Arts Building | 1975 | 1 | 27,456 |
| Campus Total | | | 266,404 |

| Catego | ry : Exterior | B | uilding | | | | |
|----------|---|-------------------------|----------|-----|------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Entrance | | | | | | | |
| | Exterior Doors - Exterior FRP Door | #1- SE- Main | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #1- SE- Main | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #1- SE- Main | 1 | EA | 6 | 10+ years | |
| | Entrance Control - Audio and Video | #2- SW | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior FRP Door | #2- SW | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #2- SW | 4 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #2- SW | 1 | EA | 6 | 10+ years | |
| | Power Door Operator and Controls | #2- SW | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Overhead Rolling/ Garage | #22- Basement Dock Door | 2 | EA | 6 | 10+ years | |
| | Door | | | | | | |
| | Exterior Doors - Exterior Steel Door | #23- Basement Dock Door | 1 | EA | 6 | 10+ years | |
| | Entrance Control - Audio and Video | #3- NE | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior FRP Door | #3- NE | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #3- NE | 4 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #3- NE | 1 | EA | 6 | 10+ years | |
| | Power Door Operator and Controls | #3- NE | 1 | EA | 7 | 6-10 years | |
| | Exterior Doors - Exterior FRP Door | #4- NW | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #4- NW | 4 | EA | 6 | 6-10 years | |
| | Exterior Doors - Transom Lite | #4- NW | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #9- SW- Exit (Rm 115) | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Side lite | #9- SW- Exit (Rm 115) | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #9- SW- Exit (Rm 115) | 1 | EA | 6 | 10+ years | |



| Catego | ry : Exterior | | В | uilding | : Main | | | | |
|----------|--|-----------------|----------|----------|--------|-------------|--|--|--|
| _ | | | | _ | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| - | | | | | | | | | |
| Foundat | on Foundation - Concrete | Entire Building | 1,551 | LF | 7 | 10+ years | | | |
| | Foundation - Concrete | Entire Building | 5 | LF | 5 | 1-2 years | Spalling , exposed rebar | | |
| | Superstructure - Concrete | Entire Building | 186,037 | SF | 7 | 10+ years | Spannig, exposed rebai | | |
| | Superstructure - Concrete | Entire Building | 100,037 | 55 | / | TO+ years | | | |
| Lighting | | | | | | | | | |
| | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 12 | EA | 7 | 10+ years | New | | |
| Roof Sys | stem | | | | | | | | |
| | Coping - Metal | Main Roof | 972 | LF | 7 | 10+ years | Replaced | | |
| | Downspouts - Interior Downspouts | Main Roof | 660 | LF | 6 | 10+ years | | | |
| | Parapet - 16" - 30" Height | Main Roof | 972 | LF | 7 | 10+ years | Repaired | | |
| | Roof - Modified Bitumen | Main Roof | 58,002 | SF | 7 | 10+ years | Replaced | | |
| | Roof Hatch - Metal | Main Roof | 2 | ĒΑ | 7 | 6-10 years | Assessed based on current condition | | |
| | Roof Structure - Concrete | Main Roof | 58,002 | SF | 7 | 10+ years | | | |
| Walls | | | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 25,883 | SF | 6 | 10+ years | | | |
| Windows | | | | | | | | | |
| vindow. | Curtain wall - Glazed Double Pane | Entire Building | 4,229 | SF | 5 | 10+ years | Single glazed | | |
| | Curtain wall - Louver | Entire Building | 50 | SF | 7 | 10+ years | | | |
| | Curtain wall - Windows | Entire Building | 17,898 | SF | 5 | 6-10 years | Single glazed | | |
| | Lintels - Steel | Entire Building | 26 | LF | 6 | 10+ years | | | |
| Catego | ry : Electrical | | в | uilding | · Main | | | | |
| outogo | | | | anang | · main | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| Emerger | ncy System | | | | | | | | |
| | Emergency Battery Packs - Lunchrooms | 3rd Floor | 4 | EA | 6 | 6-10 years | Two each in the Beta and Gamma lunchrooms. | | |
| | Automatic Transfer Switch | Basement | 1 | EA | 7 | 10+ years | ATS-1 | | |
| | Automatic Transfer Switch | Basement | 1 | EA | 7 | 10+ years | ATS-2 | | |
| | Emergency Generator- Indoor- Natural Gas - 101 - 150 KW | Basement | 1 | EA | 7 | 10+ years | Serves Main and Fine Arts Addition | | |
| | Exit Signs - Corridors and Stairs | Entire Building | 35 | EA | 6 | 6-10 years | | | |
| | Exit Signs - Lunchroom | Entire Building | 4 | EA | 7 | 6-10 years | Two each in the Beta and Gamma lunchrooms. | | |
| | Exit Signs - Multipurpose Room | Entire Building | n | E۸ | 7 | 6-10 years | | | |
| | | | 196 227 | EA SF | 6 | 6-10 years | Also Library (Room 220). | | |
| | Security System - CCTV | Entire Building | 186,327 | | - | 6-10 years | | | |
| | Security System - Intrusion Detection | Entire Building | 186,327 | SF | 5 | 6-10 years | | | |



Category : Electrical Building : Main Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Group Main Service Independent Electrical Service for Basement 1 ΕA 6 6-10 years emergency power Main Electrical Service - 1200 A Basement EA 7 Electrical room 1 6-10 years 120/208/3PH PA System Entire Building SF 6 6-10 years 186.327 Serves the entire school. Main Electrical Service - 1200 A Garage 1 FΑ 6 6-10 years 277/480/3PH Main Electrical Service - 2001 to 3000 A Garage 2 EΑ 6 6-10 years 277/480/3PH Power Distribution Lighting and Power Panels - 100 A Entire Building 1 EΑ 7 Located in 1st floor electrical room. 10+ vears Lighting and Power Panels - 100 A Entire Building 2 ΕA 7 10+ years Location changed for clarification. Lighting and Power Panels - 100 A Entire Building 1 ΕA 7 10+ years Located in Room 110A. Lighting and Power Panels - 100 A 7 ΕA 7 10+ years Entire Building Lighting and Power Panels - 100 A 7 ΕA 7 10+ years Entire Building Entire Building Lighting and Power Panels - 100 A FΑ 7 1 10+ years Lighting and Power Panels - 100 A 1 FΑ 0-1 year Opening in the inside cover plate Entire Building 4 exposes live conductors and terminals presenting a live front condition. Lighting and Power Panels - 100 A Entire Building 1 EΑ 4 0-1 year Located in 1st floor electrical room. Open fuse receptacles expose live conductors presenting a live front condition. ΕA 7 Located in the TV studio control Lighting and Power Panels - Above 100 A Entire Building 1 10+ years room. Lighting and Power Panels - Above 100 A Entire Building 1 FΑ 7 10+ years 1st floor 5 Lighting and Power Panels - Above 100 A Entire Building ΕA 7 10+ years 7 Lighting and Power Panels - Above 100 A Entire Building 6 EΑ 10+ years Located in the basement kitchen. Lighting and Power Panels - Above 100 A 9 ΕA Entire Building 6 10+ years One each located in the Beta and Gamma kitchens. Lighting and Power Panels - Above 100 A Entire Building 1 ΕA 6 10+ vears Located inside the MDF Room. Main Distribution Panels - 400 - 600 amp FΑ 6 Located in the TV studio control Entire Building 1 6-10 years room. Main Distribution Panels - 400 - 600 amp Entire Building FΑ 6 6-10 years 1 Main Distribution Panels - Greater than 600 ΕA 7 Entire Building 1 10+ years amp Main Distribution Panels - Greater than 600 ΕA 6 Located in the first floor electrical Entire Building 1 6-10 years amp room. Main Distribution Panels - Greater than 600 Entire Building 3 EΑ 6 6-10 years Located in the basement kitchen. amp



Building : Main Category : Electrical Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Main Distribution Panels - Less than 400 Entire Building FΑ 6 6-10 years Located in a mechanical closet 1 between the elevator and the first amp floor electrical room. Main Distribution Panels - Less than 400 2 Entire Building EA 6 6-10 years amp Main Distribution Panels - Less than 400 Entire Building 3 EΑ 6 6-10 years Located in the first floor electrical amp room. Transformers - 277/480 - 120/208 Entire Building 4 ΕA 6 6-10 years Transformers - 277/480 - 120/208 Entire Building 1 ΕA 6 6-10 years Located in the first floor electrical room. Lighting and Power Panels - 100 A 2 ΕA 7 Located in custodian mens locker Entire Building 6-10 years room. ΕA Lighting and Power Panels - 100 A Entire Building 1 4 0-1 year Located in custodian mens locker room. Open fuse receptacles expose live conductors presenting a live front condition. ΕA Lighting and Power Panels - Above 100 A Entire Building 1 6 6-10 years Located in Mechanical Room. Unit is fully operational but happened to be involved in a maintenance project on the day of assessment. Main Distribution Panels - 400 - 600 amp 2 EΑ 7 Located in the basement electrical Entire Building 10+ years room. Main Distribution Panels - 400 - 600 amp Entire Building EA 7 10+ years Located in mechanical room. 1 Main Distribution Panels - Greater than 600 Entire Building 1 FΑ 7 10+ years Located in mechanical room. One amp switch associated with a circuit involved in a project on the day of assessment and is safely lockedout/tagged-out in full compliance with Code. Main Distribution Panels - Greater than 600 1 ΕA 7 Located in the basement electrical Entire Building 10+ years amp room. Main Distribution Panels - Greater than 600 FΑ 6 Motor control center. Located in Entire Building 1 6-10 years amp mechanical room. Main Distribution Panels - Less than 400 FΑ 7 Entire Building 1 10+ years Located in the basement electrical amp room. Transformers - 277/480 - 120/208 Entire Building 3 EΑ 7 10+ years Located in the basement electrical room.

| Catego | Category : Fire Protection | | | uilding | : Main | | |
|-----------|--|------------------------------------|--------------|----------|--------|--------------------------|----------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Fire Alar | m | | | | | | |
| | Fire Alarm Panel Fire Alarm Strobe Lights | Entire Building Entire Building | 1 186,327 | EA SF | 7 6 | 6-10 years 10+ years | |



| GroupItem - TypeLocationQuantityUOMRankRepFire Alarm_SystemEntire Building186,327SF710Fire Pump ControllerEntire Building1EA66 | |
|--|--|
| GroupItem - TypeLocationQuantityUOMRankRepFire Alarm_SystemEntire Building186,327SF710Fire Pump ControllerEntire Building1EA66 | |
| Fire Pump Controller Entire Building 1 EA 6 6- | commend placement Comments |
| | 0+ years -10 years |
| _Pump Room Assembly | |
| | I-2 years Pump and fittings are considerably corroded and shows signs of deterioration and past leakage. Pump seals actively leaking at the time of assessment. |
| Jockey Pump Basement 1 EA 5 6- | -10 years Piping has considerable corrosion. |
| Sprinkler System | |
| | 2-5 years |
| | -10 years |
| Wet Sprinkler System Entire Building 186,327 SF 6 6- | -10 years Pump Room located in basement. System is fully operational and passes inspection but piping and fittings show considerable signs of corrosion. |
| Category : Mechanical Building : Main | |
| | commend placement Comments |

| Gro | oup Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
|-----|--|----------|----------|-----|------|-------------|---|
| Air | Conditioning | | | | | | |
| | Condensing Unit- Ground Mounted - Less than 5 tons | Basement | 1 | EA | 6 | 6-10 years | Component of a ductless split system serving the Elevator Machine Room. Item Type changed to match current observations and per review with Building Engineer. Unit installed such that the dataplate was not accessible at the time of assessment. |
| | Condensing Unit- Ground Mounted - Less than 5 tons | Basement | 1 | EA | 6 | 6-10 years | Component of a ductless split system serving the MDF Room. Item Type changed to match current observations and per review with Building Engineer. Unit installed such that the dataplate was not accessible at the time of assessment. |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 5 | 2-5 years | CU-1. Component of a ductless split system serving the TV Studio Control Room. |

Air Handling Systems



Percy L Julian High School 10330 S Elizabeth STREET, Chicago, IL 60643

| Catego | ry : Mechanical | | Building : Main | | | 10330 3 Elizabeth 31 KEE I, Chicago, iE 00043 | | | |
|--------|---|----------|-----------------|-----|------|---|---|--|--|
| | · , · ································ | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM | Basement | 1 | EA | 6 | 6-10 years | Quantity changed as total has been divided/aggregated. Dataplate inaccessible due to ceiling- suspended location. | | |
| | Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM | Basement | 1 | EA | 6 | 6-10 years | Formerly served an area that has been repurposed and this unit is not needed. Fully operational per review with Building Engineer but no longer in service. | | |
| | Make Up Air Unit- Indoor Mounted- Electric Coil - 10,001 - 20,000 cfm | Basement | 1 | EA | 7 | 10+ years | MUA-1. Installed in 2022. Serves Main to provide heat for rooms and hallways in the basement. No CPS Asset Tag present. | | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 6-10 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer. | | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. | | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. | | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. | | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. | | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer. | | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | First and sixth digits of CPS Asset Tag are obliterated. QR code not able to be scanned. Unit only has one operational air conditioning circuit and has exceeded its EUL. | | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self | Roof | 1 | EA | 4 | 2-5 years | Unit only has one operational air conditioning circuit and has exceeded | | |



Percy L Julian High School 10330 S Elizabeth STREET, Chicago, IL 60643

| Catego | ry : Mechanical | | В | uilding | : Main | | |
|---------|--|----------|----------|---------|--------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Contained Compressor - 46 - 60 tons Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | its EUL. Unit only has one operational air conditioning circuit and has exceeded its EUL. Rank adjusted based on current observations and per review with Building Engineer. |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 6-10 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer. |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 6-10 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer. |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 6-10 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer. |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. |
| Gas Boo | ster | | | | | | |
| | Gas Booster | Garage | 2 | EA | 5 | 6-10 years | |
| Heating | Devices | | | | | | |
| | Fin Tube - Electric | Basement | 4 | LF | 6 | 6-10 years | Located in custodian womens locker room. |
| | Duct Heater - Electric | Basement | 2 | | 6 | 6-10 years | Based on review with Building |



Percy L Julian High School 10330 S Elizabeth STREET, Chicago, IL 60643

| Catego | ry : Mechanical | | В | | | | |
|------------|--|-----------------|----------|-----|------|-------------|--|
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments Engineer, repairs were completed since last assessment and the duct heaters are fully operational. Rank, Reason and Priority Rep changed to match current observations. |
| | Unit Heater - Electric | Basement | 2 | EA | 6 | 6-10 years | maich current observations. |
| Mechani | cal Plumbing | | | | | | |
| | Hydronic Supply and Return - Steel | Entire Building | 500 | LF | 6 | 6-10 years | |
| Tempera | ature Control | | | | | | |
| • | Electric Thermostat | Entire Building | 2 | EA | 6 | 6-10 years | Case is damaged. |
| | Electric Thermostat | Entire Building | 1 | EA | 6 | 6-10 years | Controls the ductless split system in the MDF Room. |
| | Pneumatic System | Entire Building | 186,327 | SF | 6 | 6-10 years | Serves Main, Fine Arts Addition, and Athletic Addition. |
| | Pneumatic System | Entire Building | 186,327 | SF | 3 | 0-1 year | Not in service. Replaced with a new system in 1996 and abandoned in place. |
| | Thermostats - Pneumatic | Entire Building | 100 | EA | 5 | 6-10 years | |
| Ventilatio | on | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Entire Building | 1 | EA | 3 | 0-1 year | Unit is inoperable. |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 1 | EA | 6 | 10+ years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 3 | EA | 6 | 10+ years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Entire Building | 2 | EA | 6 | 10+ years | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 1 | EA | 6 | 10+ years | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 3 | EA | 5 | 2-5 years | Units are operational but are not in service. Vintage equipment that has exceeded its EUL. |
| | Exhaust Fans- Roof Mounted - Greater than 8000 CFM | Entire Building | 1 | EA | 6 | 10+ years | |
| | Exhaust Fans- Roof Mounted - Less than 500 CFM | Entire Building | 1 | EA | 6 | 10+ years | |



| ry : Mechanical | | В | uilding | : Main | | |
|---------------------------------------|--|---|---|---|---|--|
| - | | | | | Recommend | |
| Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Roof Mounted Duct Work | Entire Building | 40 | LF | 6 | 6-10 years | 26 |
| Type I Exhaust Hood- Kitchen | Entire Building | 2 | EA | 6 | 6-10 years | |
| Type I Exhaust Hood- Kitchen | Entire Building | 2 | EA | 6 | 6-10 years | |
| Type II Exhaust Hood- Warming Kitchen | Entire Building | 2 | EA | 6 | 6-10 years | |
| ry : Plumbing | В | uilding | : Main | | | |
| | | | - | | Recommend | |
| Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| 9r | | | | | | |
| Electric Heater - Greater than 50 KW | Basement | 2 | EA | 6 | 6-10 years | Neither water heater shows any signs of leaks at the time of assessment; repairs made since last assessment although the units are nineteen years old and show signs of age-related degradation. |
| | Item - Type Roof Mounted Duct Work Type I Exhaust Hood- Kitchen Type I Exhaust Hood- Kitchen Type II Exhaust Hood- Warming Kitchen Ty : Plumbing Item - Type | Item - Type Location Roof Mounted Duct Work Entire Building Type I Exhaust Hood- Kitchen Entire Building Type I Exhaust Hood- Kitchen Entire Building Type II Exhaust Hood- Warming Kitchen Entire Building Type II Exhaust Hood- Warming Kitchen Entire Building Type II Exhaust Hood- Warming Kitchen Entire Building | Item - Type Location Quantity Roof Mounted Duct Work Entire Building 40 Type I Exhaust Hood- Kitchen Entire Building 2 Type I Exhaust Hood- Kitchen Entire Building 2 Type I Exhaust Hood- Kitchen Entire Building 2 Type II Exhaust Hood- Warming Kitchen Entire Building 2 ry : Plumbing B Item - Type Location | Item - TypeLocationQuantityUOMRoof Mounted Duct WorkEntire Building40LFType I Exhaust Hood- KitchenEntire Building2EAType I Exhaust Hood- KitchenEntire Building2EAType II Exhaust Hood- Warming KitchenEntire BuildingUOMType II Exhaust Hood- Warming KitchenEntire BuildingUOM | Item - TypeLocationQuantityUOMRankRoof Mounted Duct WorkEntire Building40LF6Type I Exhaust Hood- KitchenEntire Building2EA6Type I Exhaust Hood- KitchenEntire Building2EA6Type II Exhaust Hood- Warming KitchenEntire Building2EA6Type II Exhaust Hood- Warming KitchenEntire Building2EA6Type II Exhaust Hood- Warming KitchenEntire BuildingBuilding : MainItem - TypeLocationQuantityUOMRankerErErErErEr | Item - TypeLocationQuantityUOMRankRecommendRoof Mounted Duct WorkEntire Building40LF66-10 yearsType I Exhaust Hood- KitchenEntire Building2EA66-10 yearsType I Exhaust Hood- KitchenEntire Building2EA66-10 yearsType II Exhaust Hood- Warming KitchenEntire Building2YearKanneKanneType II Exhaust Hood |

| Piping | | | | | | | |
|--------|--|-----------------|---------|----|---|-----------|---|
| | Domestic Piping-Hot Water Return Lines | Entire Building | 186,327 | SF | 4 | 2-5 years | Galvanized material over 40 years old with notable corrosion and some pipe clamps. |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 186,327 | SF | 4 | 2-5 years | Galvanized material over 40 years old with notable corrosion and some pipe clamps. |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 186,327 | SF | 4 | 2-5 years | Galvanized material over 40 years old with notable corrosion and some pipe clamps. |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 186,327 | SF | 4 | 2-5 years | Galvanized material over 40 years old with notable corrosion and some pipe clamps. |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 186,327 | SF | 4 | 2-5 years | Galvanized material over 40 years old with notable corrosion and some pipe clamps. |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 186,327 | SF | 4 | 2-5 years | Galvanized material over 40 years old with notable corrosion and some pipe clamps. |
| | Sanitary Piping | Entire Building | 186,327 | SF | 4 | 2-5 years | Galvanized material over 40 years old. Notable corrosion reported by building engineer. |
| | Storm Piping | Entire Building | 186,327 | SF | 4 | 2-5 years | Galvanized material over 40 years old. Notable corrosion reported by building engineer. |
| | Vent Piping | Entire Building | 186,327 | SF | 4 | 2-5 years | Galvanized material over 40 years old. Notable corrosion reported by building engineer. |



place.

Category : Plumbing Building : Main Recommend Quantity UOM Rank **Replacement** Comments Item - Type Location Group Pumps Pumps - Domestic Booster Pump-Duplex 10+ years Basement 1 ΕA 6 Pumps - Ejector-Duplex Basement ΕA 6 10+ years 1 Pumps - Sump-Duplex Basement 1 ΕA 6 10+ years At some point, a motor was replaced and the previous motor abandoned in

| Catego | ry : Room | | B | uilding | : Main | | |
|--|---|--------------------------------------|----------|---------|------------|--------------------------|-----------------------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | trative Suites/Offices | | | •••• | | | |
| | Ceiling - Lay-in | 104C Art Storage | 250 | SF | 6 | 2.5.0000 | |
| | Doors - Steel Doors incl hw | 104C Art Storage | 250 | EA | 6 6 | 2-5 years 6-10 years | |
| | Floor - Tile | 104C Art Storage | 250 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 104C Art Storage | 250 | EA | 7 | 6-10 years | |
| | | | 3 | EA | 6 | | Notworking |
| | Lighting - Lay-in Power Distribution | 104C Art Storage 104C Art Storage | з 6 | EA | 6 7 | 1-2 years | Not working |
| | Walls - Metal Panel | | 560 | SF | 7 | 10+ years | |
| | | 104C Art Storage | | SF | - | 10+ years | |
| | Ceiling - Lay-in | 109 B Accounting | 266 | | 6 | 6-10 years | Demonstration of any also d |
| | Ceiling - Lay-in | 109 B Accounting | 8 | SF | 5 | 1-2 years | Damaged and cracked |
| Doors - Steel Doors incl hw 109 B Accounting | | 3 | EA | 7 | 10+ years | | |
| Doors - Store Front 109 B Accounting | | 2 | EA | 7 | 10+ years | | |
| Floor - Carpet 109 B Accounting | | 274 | SF | 6 | 6-10 years | | |
| | Lighting - Lay-in | 109 B Accounting | 3 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 109 B Accounting | 1 | EA | 6 | 1-2 years | Not working |
| | Power Distribution | 109 B Accounting | 2 | EA | 7 | 6-10 years | |
| | Walls - Metal Panel | 109 B Accounting | 400 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 109A Store | 400 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 109A Store | 3 | EA | 6 | 6-10 years | |
| | Doors - Store Front | 109A Store | 3 | EA | 7 | 10+ years | |
| | Floor - Carpet | 109A Store | 400 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 109A Store | 4 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 109A Store | 1 | EA | 6 | 1-2 years | Not working |
| | Power Distribution | 109A Store | 6 | EA | 7 | 10+ years | |
| | Walls - Metal Panel | 109A Store | 800 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 110A Assistant Principal Conference | 707 | SF | 7 | 6-10 years | |
| | | Room | | | | | |
| | Ceiling - Lay-in | 110A Assistant Principal Conference | 16 | SF | 5 | 1-2 years | Missing and damaged |
| | | Room | | | | | |
| | Doors - Steel Doors incl hw | 110A Assistant Principal Conference | 1 | EA | 7 | 10+ years | |
| | | Room | | | | | |
| | Doors - Store Front | 110A Assistant Principal Conference | 1 | EA | 7 | 10+ years | |
| | | Room | | | | | |



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Floor - Tile SF 110A Assistant Principal Conference 723 6 10+ vears Room Lighting - Lay-in 110A Assistant Principal Conference 22 FΑ 7 6-10 years Room Lighting - Lay-in **110A Assistant Principal Conference** 5 EA 6 1-2 years Not working Room Walls - Concrete Block **110A Assistant Principal Conference** 1,025 SF 7 10+ years Room Ceiling - Lay-in 1st- 105- tech room 1,493 SF 4 24sf of water damaged tiles, others 1-2 years aged. Doors - Side-lite 49 SF 7 1st-105- tech room 10+ vears Doors - Steel Doors incl hw 1st-105-tech room 1 EΑ 7 10+ years Floor - Tile 1,493 SF 6 10+ years 1st- 105- tech room 7 Lighting - Lay-in 1st-105-tech room 30 EA 6-10 years **Power Distribution** 66 ΕA 7 1st-105-tech room 10+ years SF 7 Walls - Concrete Block 1st-105- tech room 798 10+ years SF 7 Walls - Metal Panel 1st-105- tech room 798 10+ years Work SInk 1st- 105- tech room 1 EΑ 7 10+ years SF Ceiling - Lay-in 1st-114B Office 286 6 10+ vears Doors - Side-lite SF 1st-114B Office 79 7 10+ years Doors - Steel Doors incl hw 1st-114B Office 1 ΕA 7 10+ years SF 7 10+ years Doors - Transom Window 1st-114B Office 240 SF 1st-114B Office 7 Floor - Tile/Sheet 286 10+ years Lighting - Lay-in 1st-114B Office 6 FΑ 5 1-2 years Lights did not turn on 8 ΕA 7 Power Distribution 1st-114B Office 10+ years SF Walls - Concrete Block 1st-114B Office 535 7 10+ vears SF Walls - Metal Panel 1st-114B Office 147 7 10+ years 1st- File Room (former Asst 153 SF 6 6-10 years Ceiling - Lay-in Principal) Doors - Side-lite 1st- File Room (former Asst 11 SF 7 6-10 years Principal) Doors - Steel Doors incl hw 1st- File Room (former Asst ΕA 7 1 6-10 years Principal) Doors - Transom Window 1st- File Room (former Asst SF 7 10 6-10 years Principal) Floor - Carpet 1st- File Room (former Asst SF 153 6 6-10 years Principal) 1st- File Room (former Asst Lighting - Lay-in 2 EΑ 7 6-10 years Principal) Lighting - Lay-in 1st- File Room (former Asst 1 EΑ 6 1-2 years Not working Principal) 1st- File Room (former Asst Power Distribution FΑ 7 4 10+ years Principal) Walls - Metal Panel 1st- File Room (former Asst 505 SF 7 10+ years



Building : Main Category : Room Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Group Principal) SF Ceiling - Lav-in 1st- Mail Room 193 6 10+ vears Doors - Steel Doors incl hw 1st- Mail Room 2 FΑ 7 10+ years Floor - Tile/Sheet SF 7 1st- Mail Room 193 10+ years Lighting - Lay-in 1st- Mail Room 4 EΑ 7 6-10 years 1st- Mail Room 8 7 Power Distribution EΑ 10+ years Walls - Metal Panel 590 SF 7 10+ years 1st- Mail Room SF Ceiling - Lay-in 1st-Main Office 1.050 6 6-10 years Doors - Side-lite 1st-Main Office 219 SF 7 10+ years Doors - Steel Doors incl hw 1st-Main Office 2 ΕA 7 10+ vears Doors - Transom Window 1st-Main Office 11 SF 7 10+ vears Floor - Tile 1st-Main Office 1.050 SF 7 10+ years Lighting - Lay-in ΕA 7 6-10 years 1st-Main Office 19 ΕA 7 Power Distribution 1st-Main Office 6 10+ years SF 7 Walls - Metal Panel 1st-Main Office 985 10+ years 1st- Main Office Conference Room SF Ceiling - Lay-in 510 6 6-10 years SF 7 Floor - Tile/Sheet 1st- Main Office Conference Room 510 10+ vears Lighting - Lay-in 1st- Main Office Conference Room 11 ΕA 7 6-10 years Power Distribution 1st- Main Office Conference Room 14 EΑ 7 10+ vears Walls - Metal Panel 1st- Main Office Conference Room 905 SF 7 10+ years Work SInk 1st- Main Office Conference Room 1 ΕA 7 10+ years Ceiling - Lay-in 1st-Office inside 117 SF 209 6 6-10 years Doors - Steel Doors incl hw 7 1st-Office inside 117 1 EA 10+ years SF Floor - Tile 1st-Office inside 117 209 6 10+ years Lighting - Lay-in ΕA 7 1st-Office inside 117 6 6-10 years Power Distribution 1st-Office inside 117 8 EΑ 7 10+ vears SF Walls - Concrete Block 1st-Office inside 117 580 7 10+ years SF 7 6-10 years Ceiling - Lay-in 1st-Police Office 111A on plan 8 SF Ceiling - Lay-in 1st-Police Office 111A on plan 330 6 6-10 years Doors - Side-lite 1st-Police Office 111A on plan 9 SF 7 10+ years 2 Doors - Steel Doors incl hw 1st-Police Office 111A on plan ΕA 7 10+ vears Doors - Transom Window 1st-Police Office 111A on plan 7 SF 7 10+ vears SF 7 10+ years Floor - Tile 1st-Police Office 111A on plan 338 1st-Police Office 111A on plan FΑ 7 6-10 years Lighting - Lay-in 11 Power Distribution 7 1st-Police Office 111A on plan 12 EΑ 10+ years SF 7 Walls - Concrete Block 1st-Police Office 111A on plan 465 10+ years SF Ceiling - Lay-in 1st-Principal Office 307 6 2-5 years Doors - Steel Doors incl hw 7 1st-Principal Office EA 10+ years 1 Floor - Tile/Sheet 1st- Principal Office 307 SF 7 10+ years Lighting - Lav-in 1st-Principal Office 7 EΑ 7 6-10 vears Power Distribution 1st- Principal Office 12 EΑ 7 10+ years SF 7 Storage/ Closet 1st-Principal Office 35 10+ vears Walls - Metal Panel 1st-Principal Office 705 SF 7 10+ years SF Ceiling - Lay-in 1st- Principal's Conference Room 171 6 6-10 years



Category : Room

Group

Recommend Item - Type Location Quantity UOM Rank Replacement Comments Doors - Steel Doors incl hw 1st- Principal's Conference Room 2 EΑ 10+ vears 7 Doors - Transom Window SF 7 1st- Principal's Conference Room 10 10+ vears Floor - Carpet 1st- Principal's Conference Room 171 SF 6 6-10 years 2 ΕA 7 Lighting - Lay-in 1st- Principal's Conference Room 6-10 years Lighting - Lay-in 1st- Principal's Conference Room 1 EA 6 1-2 years Not working 7 Power Distribution 1st- Principal's Conference Room 10 EΑ 10+ years Walls - Metal Panel 1st- Principal's Conference Room SF 7 10+ years 530 SF Ceiling - Lay-in 1st- Principal's Secretary 153 6 6-10 years Doors - Side-lite 1st- Principal's Secretary 11 SF 7 10+ years Doors - Steel Doors incl hw 1st- Principal's Secretary FΑ 7 10+ vears 1 Doors - Transom Window 1st- Principal's Secretary 10 SF 7 10+ vears Floor - Carpet 1st- Principal's Secretary 153 SF 6 6-10 years 1st- Principal's Secretary 3 ΕA 7 6-10 years Lighting - Lay-in ΕA 7 Power Distribution 1st- Principal's Secretary 4 10+ years SF 7 Walls - Metal Panel 1st- Principal's Secretary 505 10+ years 1st- Programming Office/Storage SF Ceiling - Lay-in 130 6 6-10 years 108G Doors - Steel Doors incl hw 1st- Programming Office/Storage 1 FΑ 6 10+ years 108G Floor - Carpet 1st- Programming Office/Storage 130 SF 7 6-10 years 108G Lighting - Lay-in 1st- Programming Office/Storage 4 EA 7 2-5 years Does not work 108G Power Distribution 1st- Programming Office/Storage FΑ 6 10+ years 4 108G 1st- Programming Office/Storage Walls - Metal Panel 485 SF 7 10+ years 108G Ceiling - Lay-in 1st- Rm 105A- Counselor Office SF 144 6 6-10 years Doors - Steel Doors incl hw 7 1st- Rm 105A- Counselor Office 1 EΑ 10+ years Floor - Tile 1st- Rm 105A- Counselor Office 144 SF 6 10+ years Lighting - Lay-in 1st- Rm 105A- Counselor Office 2 FΑ 7 6-10 years Lighting - Lav-in 1st- Rm 105A- Counselor Office 1 EΑ 6 1-2 vears Not working 7 Power Distribution 1st- Rm 105A- Counselor Office 4 FΑ 10+ years Walls - Metal Panel 1st- Rm 105A- Counselor Office 490 SF 7 10+ years SF Ceiling - Lay-in 1st- Rm 107B Counselors Office 141 6 6-10 years SF 7 Doors - Side-lite 1st- Rm 107B Counselors Office 20 10+ years Doors - Steel Doors incl hw 1st- Rm 107B Counselors Office 1 EA 7 10+ years 1st- Rm 107B Counselors Office SF Floor - Tile/Sheet 141 7 10+ years Lighting - Lay-in 1st- Rm 107B Counselors Office 2 ΕA 7 6-10 years Lighting - Lay-in 1st- Rm 107B Counselors Office 1 ΕA 6 1-2 vears Not working Power Distribution 1st- Rm 107B Counselors Office 4 FΑ 7 10+ years 1st- Rm 107B Counselors Office SF 7 Walls - Concrete Block 144 10+ vears Walls - Masonry 1st- Rm 107B Counselors Office 99 SF 7 10+ years SF 7 Walls - Metal Panel 1st- Rm 107B Counselors Office 223 10+ years

Building : Main



| Catego | ry : Room | | R | uilding | • Main | | 30 S Elizabeth STREET, Chicago, IL 60643 |
|--------|-----------------------------|---|----------|------------|--------|--------------------|--|
| Calego | | | D | unung | . Mani | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | 1st- Rm 108 Call Center program | 290 | SF | 6 | 6-10 years | |
| | | Office | | | | - | |
| | Doors - Side-lite | 1st- Rm 108 Call Center program | 15 | SF | 7 | 10+ years | |
| | | Office | | | | | |
| | Doors - Steel Doors incl hw | 1st- Rm 108 Call Center program | 1 | EA | 7 | 10+ years | |
| | | Office | | | | | |
| | Doors - Transom Window | 1st- Rm 108 Call Center program | 18 | SF | 7 | 10+ years | |
| | | Office | | 05 | - | 40 | |
| | Floor - Tile | 1st- Rm 108 Call Center program | 290 | SF | 7 | 10+ years | |
| | Linkting Low in | Office | 0 | | 7 | 0.10 | |
| | Lighting - Lay-in | 1st- Rm 108 Call Center program Office | 6 | EA | 7 | 6-10 years | |
| | Power Distribution | 1st- Rm 108 Call Center program | 6 | EA | 7 | 10+ years | |
| | | Office | 0 | LA | 1 | TOT years | |
| | Walls - Concrete Block | 1st- Rm 108 Call Center program | 342 | SF | 7 | 10+ years | |
| | | Office | 542 | 01 | ' | Tor years | |
| | Walls - Metal Panel | 1st- Rm 108 Call Center program | 343 | SF | 7 | 10+ years | |
| | | Office | | - | | · , · · · · | |
| | Ceiling - Lay-in | 1st- Rm 108- Office B Operations | 229 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st- Rm 108- Office B Operations | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st- Rm 108- Office B Operations | 229 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st- Rm 108- Office B Operations | 5 | EA | 7 | 6-10 years | |
| | Power Distribution | 1st- Rm 108- Office B Operations | 6 | EA | 7 | 10+ years | |
| | Walls - Metal Panel | 1st- Rm 108- Office B Operations | 605 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st- Rm 108- Office C .storage | 110 | SF | 5 | 1-2 years | Ceiling in overall poor shape |
| | Doors - Steel Doors incl hw | 1st- Rm 108- Office C .storage | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st- Rm 108- Office C .storage | 110 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st- Rm 108- Office C .storage | 1 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st- Rm 108- Office C .storage | 1 | EA | 6 | 1-2 years | Not working |
| | Power Distribution | 1st- Rm 108- Office C .storage | 4 | EA | 7 | 10+ years | |
| | Walls - Metal Panel | 1st- Rm 108- Office C .storage | 400 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st- Rm 108-Office A Administrative | 217 | SF | 6 | 6-10 years | |
| | | Support | | | | | |
| | Doors - Steel Doors incl hw | 1st- Rm 108-Office A Administrative | 1 | EA | 7 | 6-10 years | |
| | | Support | | ~- | _ | | |
| | Floor - Tile/Sheet | 1st- Rm 108-Office A Administrative | 217 | SF | 7 | 10+ years | |
| | | Support | | | _ | | |
| | Lighting - Lay-in | 1st- Rm 108-Office A Administrative | 4 | EA | 7 | 6-10 years | |
| | | Support | 0 | Ξ. | - | 40 | |
| | Power Distribution | 1st- Rm 108-Office A Administrative | 8 | EA | 7 | 10+ years | |
| | Store so / Closet | Support | 400 | 0- | - | 10 | |
| | Storage/ Closet | 1st- Rm 108-Office A Administrative | 192 | SF | 7 | 10+ years | |
| | Walla Matal Danal | Support | 500 | <u>с</u> г | 7 | 10, 1000 | |
| | Walls - Metal Panel | 1st- Rm 108-Office A Administrative | 590 | SF | 7 | 10+ years | |
| | | | | | | | |



| Catego | ry : Room | | R | uilding | : Main | | |
|--------|-----------------------------|-----------------------------------|----------|----------|--------|-------------------------|----------------------|
| outogo | | | | unung | . mann | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Croup | | Support | quantity | 00111 | mann | Ropidoomon | Commente |
| | Ceiling - Lay-in | 1st- Rm 122 Attendance Office | 877 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | 1st- Rm 122 Attendance Office | 270 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st- Rm 122 Attendance Office | 1 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 1st- Rm 122 Attendance Office | 6 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st- Rm 122 Attendance Office | 875 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st- Rm 122 Attendance Office | 2 | SF | 4 | 1-2 years | Chipped tile corners |
| | Lighting - Lay-in | 1st- Rm 122 Attendance Office | 18 | EA | 7 | 6-10 years | Ompped me comers |
| | Power Distribution | 1st- Rm 122 Attendance Office | 36 | EA | 7 | 10+ years | |
| | Storage/ Closet | 1st- Rm 122 Attendance Office | 51 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st- Rm 122 Attendance Office | 580 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st- Rm 122 Attendance Office | 290 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st- Rm 125 Counselor Office | 145 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | 1st- Rm 125 Counselor Office | 93 | SF | | 10+ years | |
| | Doors - Steel Doors incl hw | 1st- Rm 125 Counselor Office | 93 | EA | 6 | , | |
| | Floor - Carpet | 1st- Rm 125 Counselor Office | 145 | SF | 6 6 | 10+ years 6-10 years | |
| | | 1st- Rm 125 Counselor Office | - | EA | 7 | | |
| | Lighting - Lay-in | 1st- Rm 125 Counselor Office | 3 4 | EA | 6 | 6-10 years | |
| | Power Distribution | | | SF | | 10+ years | |
| | Walls - Metal Panel | 1st- Rm 125 Counselor Office | 490 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st- Security Office | 155 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 1st- Security Office | 9 | | 7 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st- Security Office | 1 | EA | 6 | 6-10 years | |
| | Doors - Transom Window | 1st- Security Office | 6 | SF SF | 7 | 6-10 years | |
| | Floor - Tile | 1st- Security Office | 155 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 1st- Security Office | 6 | | 7 | 6-10 years | |
| | Power Distribution | 1st- Security Office | 18 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st- Security Office | 357 | SF SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st- Security Office (across from | 86 | SF | 6 | 0-1 year | No access |
| | | 1005) could not access | | 0- | _ | | |
| | Ceiling - Lay-in | 1st- Security Office (across from | 8 | SF | 5 | 1-2 years | Stained and damaged |
| | | 1005) could not access | | | • | 4.0 | |
| | Doors - Steel Doors incl hw | 1st- Security Office (across from | 1 | EA | 6 | 10+ years | |
| | | 1005) could not access | | ~- | - | | |
| | Floor - Carpet | 1st- Security Office (across from | 94 | SF | 6 | 6-10 years | |
| | | 1005) could not access | _ | | _ | | |
| | Lighting - Lay-in | 1st- Security Office (across from | 2 | EA | 6 | 6-10 years | |
| | | 1005) could not access | | | | | |
| | Power Distribution | 1st- Security Office (across from | 4 | EA | 6 | 10+ years | |
| | | 1005) could not access | | | | | |
| | Walls - Metal Panel | 1st- Security Office (across from | 385 | SF | 7 | 10+ years | |
| | | 1005) could not access | | | | | |
| | Ceiling - Lay-in | 1st-Assistant principal 110 | 225 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st-Assistant principal 110 | 1 | EA | 7 | 10+ years | |
| | Doors - Store Front | 1st-Assistant principal 110 | 5 | EA | 7 | 10+ years | |
| | | | | | | | |



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|---|--|------------|----------|--------|-------------------------|----------------------|
| | | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Tile | 1st-Assistant principal 110 | 225 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st-Assistant principal 110 | 12 | EA | 7 | 6-10 years | |
| | Power Distribution | 1st-Assistant principal 110 | 8 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st-Assistant principal 110 | 242 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 235L conference room inside library | 440 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 235L conference room inside library | 210 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 235L conference room inside library | 2 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 235L conference room inside library | 60 | SF | 7 | 10+ years | |
| | Floor - Tile | 235L conference room inside library | 440 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 235L conference room inside library | 9 | EA | 7 | 6-10 years | |
| | Power Distribution | 235L conference room inside library | 5 | EA SF | 7 | 10+ years | |
| | Walls - Metal Panel | 235L conference room inside library 2nd - 201C Counselor's Office | 440 152 | SF | 7 6 | 10+ years | |
| | Ceiling - Lay-in | | - | SF | - | 10+ years | |
| | Doors - Side-lite | 2nd - 201C Counselor's Office | 10 | | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 2nd - 201C Counselor's Office | 1 30 | EA SF | 6 6 | 10+ years | |
| | Doors - Transom Window | 2nd - 201C Counselor's Office | | SF | 6 | 10+ years | |
| | Floor - Carpet | 2nd - 201C Counselor's Office 2nd - 201C Counselor's Office | 152 | EA | 6 6 | 6-10 years | |
| | Lighting - Lay-in Power Distribution | 2nd - 201C Counselor's Office | 3 2 | | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd - 201C Counselor's Office | ے 148 | EA SF | 6 6 | 10+ years | |
| | Walls - Metal Panel | 2nd - 201C Counselor's Office | 356 | SF | 6 | 10+ years | |
| | | 2nd - 2010 Counselor's Office | 356 137 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in Doors - Side-lite | 2nd - 201D Counselor's Office | | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd - 201D Counselor's Office | 10 1 | EA | 6 6 | 10+ years | |
| | Doors - Transom Window | 2nd - 201D Counselor's Office | 30 | SF | 6 | 10+ years | |
| | Floor - Carpet | 2nd - 201D Counselor's Office | 137 | SF | 6 | 10+ years 6-10 years | |
| | Lighting - Lay-in | 2nd - 201D Counselor's Office | 3 | EA | 6 | 1-2 years | Light switch missing |
| | Power Distribution | 2nd - 201D Counselor's Office | 2 | EA | 6 | 10+ years | Light Switch missing |
| | Walls - Concrete Block | 2nd - 201D Counselor's Office | 148 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd - 201D Counselor's Office | 356 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd - 201E Office | 207 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 2nd - 201E Office | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd - 201E Office | 10 | EA | 6 | 6-10 years | |
| | Doors - Transom Window | 2nd - 201E Office | 40 | SF | 6 | 10+ years | |
| | Floor - Carpet | 2nd - 201E Office | 207 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd - 201E Office | 4 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd - 201E Office | 4 | EA | 6 | 1-2 years | Not working |
| | Power Distribution | 2nd - 201E Office | 4 | EA | 6 | 6-10 years | Not working |
| | Walls - Concrete Block | 2nd - 201E Office | 138 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd - 201E Office | 138 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd - 201E Office | 304 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd - 222 Periodical Rm inside | 304 301 | SF | 6 | 10+ years | |
| | Centry - Lay-III | Library | 301 | 36 | 0 | IUT years | |
| | Doors - Side-lite | 2nd - 222 Periodical Rm inside | 72 | SF | 6 | 6-10 years | |



| Cotoro | nu - Deem | | P | uilding | Main | 100 | |
|--------|-----------------------------|--|----------------|------------|--------|---|-----------------|
| Catego | ry : Room | | В | uilding | : Main | | |
| | No. 10 T 10 | | O U U U | | | Recommend | 0 |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | Library | | | | 0.40 | |
| | Doors - Steel Doors incl hw | 2nd - 222 Periodical Rm inside | 2 | EA | 6 | 6-10 years | |
| | | Library | 10 | 0- | | 0.40 | |
| | Doors - Transom Window | 2nd - 222 Periodical Rm inside | 40 | SF | 6 | 6-10 years | |
| | | Library | | 0- | | | |
| | Floor - Carpet | 2nd - 222 Periodical Rm inside | 301 | SF | 4 | 1-2 years | Stains and torn |
| | | Library | 0 | - ^ | 0 | 0.40 | |
| | Lighting - Lay-in | 2nd - 222 Periodical Rm inside | 6 | EA | 6 | 6-10 years | |
| | | | | - ^ | 0 | 40 | |
| | Power Distribution | 2nd - 222 Periodical Rm inside | 24 | EA | 6 | 10+ years | |
| | Walls Matel Danal | Library | 500 | 05 | ~ | 10 | |
| | Walls - Metal Panel | 2nd - 222 Periodical Rm inside | 593 | SF | 6 | 10+ years | |
| | | Library | 400 | 05 | ~ | 6.40 | |
| | Ceiling - Lay-in | 2nd - 235A Student info process rm | 436 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | inside Library 2nd - 235A Student info process rm | 101 | SF | 6 | 10 | |
| | Doors - Side-lite | • | 101 | эг | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | inside Library | 2 | EA | 6 | 10 | |
| | Doors - Steer Doors Inci nw | 2nd - 235A Student info process rm | 2 | EA | 6 | 10+ years | |
| | Doors - Transom Window | inside Library 2nd - 235A Student info process rm | 120 | SF | 6 | 10 | |
| | | • | 120 | ЪГ | 6 | 10+ years | |
| | Floor - Tile/Sheet | inside Library 2nd - 235A Student info process rm | 436 | SF | 7 | 6 10 10000 | |
| | FIOU - The/Sheet | inside Library | 430 | ЪГ | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd - 235A Student info process rm | 9 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | inside Library | 9 | LA | 0 | 0-10 years | |
| | Power Distribution | 2nd - 235A Student info process rm | 18 | EA | 6 | 10+ years | |
| | | inside Library | 10 | LA | 0 | IUT years | |
| | Walls - Metal Panel | 2nd - 235A Student info process rm | 679 | SF | 7 | 10+ years | |
| | | inside Library | 0/0 | 01 | ' | Tor years | |
| | Ceiling - Lay-in | 2nd - 235D Seminar Room inside | 771 | SF | 6 | 6-10 years | |
| | | Library | 771 | 01 | 0 | | |
| | Doors - Side-lite | 2nd - 235D Seminar Room inside | 352 | SF | 6 | 10+ years | |
| | | Library | 002 | 01 | Ū | ior youro | |
| | Doors - Steel Doors incl hw | 2nd - 235D Seminar Room inside | 1 | EA | 6 | 10+ years | |
| | | Library | | 273 | Ū | ior youro | |
| | Doors - Transom Window | 2nd - 235D Seminar Room inside | 10 | SF | 6 | 10+ years | |
| | | Library | 10 | 01 | Ū | ior youro | |
| | Floor - Carpet | 2nd - 235D Seminar Room inside | 771 | SF | 6 | 6-10 years | |
| | | Library | | 01 | Ū | e re jeare | |
| | Lighting - Lay-in | 2nd - 235D Seminar Room inside | 15 | EA | 7 | 6-10 years | |
| | gg, | Library | | _/ ` | • | 0 10 900.0 | |
| | Power Distribution | 2nd - 235D Seminar Room inside | 71 | EA | 7 | 10+ years | |
| | | Library | | | • | , | |
| | Walls - Concrete Block | 2nd - 235D Seminar Room inside | 205 | SF | 7 | 10+ years | |
| | | | | | • | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | |



Building : Main Category : Room Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Librarv 2nd - 235D Seminar Room inside SF Walls - Metal Panel 304 7 10+ years Library 2nd - 260 Office SF Ceiling - Lay-in 416 6 6-10 years Doors - Side-lite 2nd - 260 Office 74 SF 6 10+ years Doors - Steel Doors incl hw 2nd - 260 Office 1 EΑ 6 10+ years Doors - Transom Window 30 SF 6 10+ years 2nd - 260 Office 2nd - 260 Office SF Floor - Tile 416 6 6-10 years Lighting - Lay-in 2nd - 260 Office 9 ΕA 7 6-10 years Power Distribution 2nd - 260 Office 4 EΑ 6 10+ years Walls - Metal Panel 2nd - 260 Office 580 SF 7 10+ vears Ceiling - Lay-in 2nd - Conference room 235L 418 SF 6 6-10 years Doors - Steel Doors incl hw 2nd - Conference room 235L 2 ΕA 6 10+ years SF 6 Floor - Carpet 2nd - Conference room 235L 418 6-10 years ΕA 7 6-10 years Lighting - Lay-in 2nd - Conference room 235L 9 Power Distribution 27 2nd - Conference room 235L FΑ 6 6-10 years SF 7 Walls - Metal Panel 2nd - Conference room 235L 433 10+ vears SF Walls - Metal Panel 2nd - Conference room 235L 433 7 10+ years SF 2nd - Librarian Office - IDF area 423 6 6-10 years Ceiling - Lay-in 235P/235N Doors - Steel Doors incl hw 2nd - Librarian Office - IDF area 2 ΕA 6 10+ years 235P/235N 2nd - Librarian Office - IDF area Doors - Transom Window 50 SF 6 10+ years 235P/235N Floor - Carpet 2nd - Librarian Office - IDF area SF 423 6 6-10 years 235P/235N 2nd - Librarian Office - IDF area Lighting - Lay-in 9 EA 7 6-10 years 235P/235N **Power Distribution** 2nd - Librarian Office - IDF area 12 ΕA 6 10+ years 235P/235N SF Walls - Concrete Block 2nd - Librarian Office - IDF area 146 7 10+ years 235P/235N SF Walls - Metal Panel 2nd - Librarian Office - IDF area 288 7 10+ years 235P/235N 2nd - Librarian Office - IDF area Walls - Metal Panel 708 SF 7 10+ years 235P/235N Ceiling - Lay-in 2nd - Office 221A inside 221 98 SF 6 10+ years Doors - Steel Doors incl hw 2nd - Office 221A inside 221 EΑ 6 10+ years 1 Doors - Transom Window 2nd - Office 221A inside 221 125 SF 7 10+ years SF Floor - Tile/Sheet 2nd - Office 221A inside 221 98 7 10+ vears Lighting - Lay-in 2nd - Office 221A inside 221 3 ΕA 6 6-10 years 2 FΑ 6 Power Distribution 2nd - Office 221A inside 221 10+ vears Walls - Metal Panel 2nd - Office 221A inside 221 270 SF 6 10+ years SF Ceiling - Lay-in 2nd - Office 221B inside 221 101 6 10+ years



| Category : Room | | | Building : Main | | | | | |
|-----------------|------------------------------|--------------------------------|-----------------|---------|--------|-------------|-------------------------------------|--|
| ealege | | | _ | anang i | . main | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Doors - Side-lite | 2nd - Office 221B inside 221 | 100 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | 2nd - Office 221B inside 221 | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile | 2nd - Office 221B inside 221 | 101 | SF | 6 | 10+ years | | |
| | Lighting - Lay-in | 2nd - Office 221B inside 221 | 2 | EA | 6 | 6-10 years | | |
| | Power Distribution | 2nd - Office 221B inside 221 | 4 | EA | 6 | 6-10 years | | |
| | Walls - Concrete Block | 2nd - Office 221B inside 221 | 103 | SF | 6 | 10+ years | | |
| | Walls - Metal Panel | 2nd - Office 221B inside 221 | 98 | SF | 6 | 10+ years | | |
| | Ceiling - Lay-in | 2nd - Office 235E Listening Rm | 291 | SF | 6 | 10+ years | | |
| | | inside Library | 201 | 01 | 0 | lor youro | | |
| | Doors - Side-lite | 2nd - Office 235E Listening Rm | 176 | SF | 6 | 10+ years | | |
| | Doors - Olde-lite | inside Library | 170 | 01 | 0 | TOF years | | |
| | Doors - Steel Doors incl hw | 2nd - Office 235E Listening Rm | 1 | EA | 6 | 10+ years | | |
| | Doors - Steel Doors Inci nw | 5 | 1 | LA | 0 | IUT years | | |
| | | inside Library | 40 | 05 | ~ | 10 | | |
| | Doors - Transom Window | 2nd - Office 235E Listening Rm | 10 | SF | 6 | 10+ years | | |
| | | inside Library | 004 | 05 | • | 0.40 | | |
| | Floor - Carpet | 2nd - Office 235E Listening Rm | 291 | SF | 6 | 6-10 years | | |
| | | inside Library | | | _ | | | |
| | Lighting - Lay-in | 2nd - Office 235E Listening Rm | 4 | EA | 6 | 2-5 years | | |
| | | inside Library | | | | | | |
| | Lighting - Lay-in | 2nd - Office 235E Listening Rm | 2 | EA | 5 | 1-2 years | Not working, switch may be fused in | |
| | | inside Library | | | | | the on position | |
| | Power Distribution | 2nd - Office 235E Listening Rm | 3 | EA | 7 | 10+ years | | |
| | | inside Library | | | | | | |
| | Power Distribution | 2nd - Office 235E Listening Rm | 11 | EA | 6 | 10+ years | | |
| | | inside Library | | | | | | |
| | Walls - Metal Panel | 2nd - Office 235E Listening Rm | 523 | SF | 6 | 10+ years | | |
| | | inside Library | | | | - | | |
| | Ceiling - Lay-in | 2nd - Office inside 214 | 91 | SF | 6 | 6-10 years | | |
| | Doors - Side-lite | 2nd - Office inside 214 | 120 | SF | 6 | 6-10 years | | |
| | Doors - Steel Doors incl hw | 2nd - Office inside 214 | 1 | EA | 6 | 6-10 years | | |
| | Doors - Transom Window | 2nd - Office inside 214 | 40 | SF | 6 | 6-10 years | | |
| | Floor - Carpet | 2nd - Office inside 214 | 91 | SF | 4 | 1-2 years | Stained and damaged carpet | |
| | Lighting - Lay-in | 2nd - Office inside 214 | 2 | EA | 7 | 6-10 years | | |
| | Power Distribution | 2nd - Office inside 214 | 2 | EA | 7 | 10+ years | | |
| | Walls - Metal Panel | 2nd - Office inside 214 | 235 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | 2nd - Small Conference inside | 159 | SF | 6 | 2-5 years | | |
| | | Library | 100 | 01 | 0 | 2 0 yours | | |
| | Doors - Steel Doors incl hw | 2nd - Small Conference inside | 1 | EA | 6 | 10+ years | | |
| | Doors - Steer Doors inci niw | Library | I | LA | 0 | IUT years | | |
| | Doors - Transom Window | 2nd - Small Conference inside | 100 | SF | 7 | 6-10 years | | |
| | | | 100 | ЪГ | 1 | 0-10 years | | |
| | Elect Corpet | Library | 450 | сг | Λ | 1.0 10000 | Cornet steined and rises | |
| | Floor - Carpet | 2nd - Small Conference inside | 159 | SF | 4 | 1-2 years | Carpet stained and ripped | |
| | Lighting Low in | Library | <u>^</u> | | 7 | 6 10 | | |
| | Lighting - Lay-in | 2nd - Small Conference inside | 2 | EA | 7 | 6-10 years | | |



| Catego | ry : Room | | В | uilding | : Main | | SU S Elizabelli STREET, Chicago, ie 00045 |
|--------|---------------------------------------|----------------------------------|----------|---------|--------|-------------|---|
| Galogo | | | | anang | . mani | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | , , , , , , , , , , , , , , , , , , , | Library | | | | • | |
| | Walls - Concrete Block | 2nd - Small Conference inside | 100 | SF | 7 | 10+ years | |
| | | Library | | | | | |
| | Walls - Metal Panel | 2nd - Small Conference inside | 400 | SF | 7 | 10+ years | |
| | | Library | | | | | |
| | Ceiling - Lay-in | 2nd - library workroom 235M | 885 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd - library workroom 235M | 2 | EA | 6 | 10+ years | |
| | Floor - Carpet | 2nd - library workroom 235M | 885 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd - library workroom 235M | 18 | EA | 7 | 6-10 years | |
| | Power Distribution | 2nd - library workroom 235M | 14 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 2nd - library workroom 235M | 298 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 2nd - library workroom 235M | 891 | SF | 7 | 10+ years | |
| | Work SInk | 2nd - library workroom 235M | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 316B instrument room inside | 94 | SF | 5 | 1-2 years | Tiles missing throughout |
| | 6 9 | classroom 316 | | | | , | 5 5 |
| | Doors - Steel Doors incl hw | 316B instrument room inside | 1 | EA | 7 | 10+ years | |
| | | classroom 316 | | | | - , | |
| | Doors - Transom Window | 316B instrument room inside | 20 | SF | 7 | 10+ years | |
| | | classroom 316 | _0 | 0. | • | ie geale | |
| | Floor - Tile | 316B instrument room inside | 94 | SF | 6 | 6-10 years | |
| | | classroom 316 | 0.1 | 0. | Ũ | o ro youro | |
| | Lighting - Lay-in | 316B instrument room inside | 4 | EA | 7 | 6-10 years | |
| | | classroom 316 | 7 | | ' | 0-10 years | |
| | Power Distribution | 316B instrument room inside | 1 | EA | 7 | 10+ years | |
| | | classroom 316 | 1 | LA | ' | TUT years | |
| | Walls - Concrete Block | 316B instrument room inside | 150 | SF | 7 | 10 | |
| | Walls - Concrete Diock | classroom 316 | 150 | ЪГ | 1 | 10+ years | |
| | Walls Matel Danal | | 220 | 05 | 7 | 10 | |
| | Walls - Metal Panel | 316B instrument room inside | 330 | SF | 7 | 10+ years | |
| | | classroom 316 | 100 | 05 | _ | 4.0 | |
| | Ceiling - Lay-in | 319B science office | 188 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 319B science office | 1 | EA | 6 | 10+ years | |
| | Doors - Store Front | 319B science office | 3 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 319B science office | 188 | SF | 5 | 2-5 years | |
| | Lighting - Lay-in | 319B science office | 8 | EA | 7 | 6-10 years | |
| | Power Distribution | 319B science office | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 319B science office | 194 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 319B science office | 393 | SF | 7 | 10+ years | |
| | Work SInk | 319B science office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 3rd - 301A Assistant Prin Office | 157 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd - 301A Assistant Prin Office | 175 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd - 301A Assistant Prin Office | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd - 301A Assistant Prin Office | 50 | SF | 6 | 10+ years | |
| | Floor - Carpet | 3rd - 301A Assistant Prin Office | 157 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd - 301A Assistant Prin Office | 3 | EA | 6 | 6-10 years | |
| | | | 5 | | 0 | o io youro | |



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Power Distribution 3rd - 301A Assistant Prin Office 4 EΑ 10+ vears 6 250 SF 6 Walls - Metal Panel 3rd - 301A Assistant Prin Office 10+ years Ceiling - Lay-in 3rd - 301B Faculty Prep Rm 298 SF 6 10+ years Doors - Side-lite SF 6 3rd - 301B Faculty Prep Rm 10 6-10 years Doors - Steel Doors incl hw 3rd - 301B Faculty Prep Rm 1 EA 6 10+ years SF Doors - Transom Window 3rd - 301B Faculty Prep Rm 20 6 10+ years Floor - Carpet 3rd - 301B Faculty Prep Rm 298 SF 6 6-10 years Lighting - Lay-in 3rd - 301B Faculty Prep Rm 6 ΕA 6 6-10 years Power Distribution 3rd - 301B Faculty Prep Rm 2 ΕA 6 10+ years SF Walls - Concrete Block 3rd - 301B Faculty Prep Rm 203 6 10+ years SF Walls - Metal Panel 3rd - 301B Faculty Prep Rm 580 6 10+ vears Ceiling - Lay-in 3rd - 301C Counselor's Office 157 SF 6 10+ years Doors - Side-lite 3rd - 301C Counselor's Office SF 6 10 10+ years 6 Doors - Steel Doors incl hw 3rd - 301C Counselor's Office 1 EA 10+ years 30 SF Doors - Transom Window 3rd - 301C Counselor's Office 6 10+ years SF 6 Floor - Carpet 3rd - 301C Counselor's Office 157 6-10 years ΕA Lighting - Lay-in 3rd - 301C Counselor's Office 3 6 6-10 years Power Distribution 3rd - 301C Counselor's Office 2 ΕA 6 10+ years 45 SF Walls - Concrete Block 3rd - 301C Counselor's Office 6 10+ vears SF Walls - Metal Panel 3rd - 301C Counselor's Office 359 6 10+ years Ceiling - Lay-in 3rd - 301D Counselor's Office 139 SF 6 10+ years SF 6 10+ years Doors - Side-lite 3rd - 301D Counselor's Office 10 6 Doors - Steel Doors incl hw 3rd - 301D Counselor's Office 1 EA 10+ years SF Doors - Transom Window 3rd - 301D Counselor's Office 10 6 10+ years Floor - Carpet 3rd - 301D Counselor's Office 139 SF 6 6-10 years Lighting - Lay-in 3rd - 301D Counselor's Office 3 EΑ 6 6-10 years 2 Power Distribution 3rd - 301D Counselor's Office EA 6 10+ years Walls - Concrete Block 3rd - 301D Counselor's Office 27 SF 6 10+ years SF Walls - Metal Panel 3rd - 301D Counselor's Office 154 6 10+ years Walls - Metal Panel 3rd - 301D Counselor's Office 244 SF 6 10+ years Glass store front walls SF Ceiling - Lay-in 3rd - 301E Office 32 7 10+ vears SF Ceiling - Lav-in 3rd - 301E Office 172 6 10+ vears Doors - Side-lite SF 3rd - 301E Office 6 10+ years 10 Doors - Steel Doors incl hw 3rd - 301E Office FA 6 10+ years 1 SF Doors - Transom Window 3rd - 301E Office 34 6 10+ years SF 6 Floor - Carpet 3rd - 301E Office 204 6-10 years Lighting - Lay-in 3rd - 301E Office 5 EΑ 6 1-2 years Lights did not turn on Power Distribution 2 3rd - 301E Office EA 6 10+ years Walls - Concrete Block 3rd - 301E Office 140 SF 6 10+ years SF 7 Walls - Metal Panel 3rd - 301E Office 225 10+ vears Glass store front walls SF Walls - Metal Panel 3rd - 301E Office 430 6 10+ years SF 3rd - 319-B teacher work area 252 6 6-10 years Ceiling - Lay-in labeled 317A on print Doors - Side-lite 3rd - 319-B teacher work area 98 SF 6 10+ years



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|-----------------------------|------------------------------------|----------|---------|--------|-------------|-----------------------|
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | labeled 317A on print | | | | | |
| | Doors - Steel Doors incl hw | 3rd - 319-B teacher work area | 1 | EA | 6 | 10+ years | |
| | | labeled 317A on print | | | | | |
| | Doors - Transom Window | 3rd - 319-B teacher work area | 30 | SF | 6 | 10+ years | |
| | | labeled 317A on print | | | | | |
| | Floor - Carpet | 3rd - 319-B teacher work area | 252 | SF | 6 | 6-10 years | |
| | | labeled 317A on print | | | | | |
| | Lighting - Lay-in | 3rd - 319-B teacher work area | 5 | EA | 7 | 6-10 years | |
| | | labeled 317A on print | | | | | |
| | Power Distribution | 3rd - 319-B teacher work area | 4 | EA | 6 | 10+ years | |
| | | labeled 317A on print | | | | | |
| | Walls - Metal Panel | 3rd - 319-B teacher work area | 338 | SF | 7 | 10+ years | |
| | | labeled 317A on print | | | | | |
| | Ceiling - Lay-in | 3rd - 319D science prep room | 188 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 3rd - 319D science prep room | 1 | EA | 6 | 6-10 years | |
| | Doors - Transom Window | 3rd - 319D science prep room | 30 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | 3rd - 319D science prep room | 188 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd - 319D science prep room | 8 | EA | 7 | 6-10 years | |
| | Power Distribution | 3rd - 319D science prep room | 4 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 3rd - 319D science prep room | 194 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd - 319D science prep room | 393 | SF | 7 | 10+ years | |
| | Work SInk | 3rd - 319D science prep room | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 3rd - 321 Special Education Office | 288 | SF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 3rd - 321 Special Education Office | 16 | SF | 5 | 1-2 years | Missing tiles |
| | Doors - Side-lite | 3rd - 321 Special Education Office | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd - 321 Special Education Office | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd - 321 Special Education Office | 10 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd - 321 Special Education Office | 296 | SF | 7 | 6-10 years | |
| | Floor - Tile/Sheet | 3rd - 321 Special Education Office | 8 | SF | 5 | 1-2 years | Rust stained on floor |
| | Lighting - Lay-in | 3rd - 321 Special Education Office | 6 | EA | 7 | 6-10 years | |
| | Power Distribution | 3rd - 321 Special Education Office | 4 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 3rd - 321 Special Education Office | 148 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd - 321 Special Education Office | 565 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd - 331A | 149 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd - 331A | 8 | SF | 5 | 1-2 years | Missing tiles |
| | Doors - Side-lite | 3rd - 331A | 175 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 3rd - 331A | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd - 331A | 50 | SF | 6 | 10+ years | |
| | Floor - Carpet | 3rd - 331A | 157 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd - 331A | 3 | EA | 6 | 6-10 years | |
| | Power Distribution | 3rd - 331A | 1 | EA | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd - 331A | 250 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd - 331B Teacher's Lounge | 302 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | 3rd - 331B Teacher's Lounge | 10 | SF | 6 | 10+ years | |



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|-----------------------------|-----------------------------------|----------|---------|--------|-------------|--------------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Steel Doors incl hw | 3rd - 331B Teacher's Lounge | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd - 331B Teacher's Lounge | 18 | SF | 6 | 10+ years | |
| | Floor - Carpet | 3rd - 331B Teacher's Lounge | 302 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd - 331B Teacher's Lounge | 6 | EA | 7 | 6-10 years | |
| | Power Distribution | 3rd - 331B Teacher's Lounge | 10 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 3rd - 331B Teacher's Lounge | 205 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd - 331B Teacher's Lounge | 507 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd - 331C Counselor's Office | 157 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | 3rd - 331C Counselor's Office | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd - 331C Counselor's Office | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd - 331C Counselor's Office | 26 | SF | 6 | 10+ years | |
| | Floor - Carpet | 3rd - 331C Counselor's Office | 157 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd - 331C Counselor's Office | 3 | EA | 7 | 6-10 years | |
| | Power Distribution | 3rd - 331C Counselor's Office | 6 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 3rd - 331C Counselor's Office | 148 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd - 331C Counselor's Office | 361 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd - 331D Counselor's Office | 138 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | 3rd - 331D Counselor's Office | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd - 331D Counselor's Office | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd - 331D Counselor's Office | 10 | SF | 6 | 10+ years | |
| | Floor - Carpet | 3rd - 331D Counselor's Office | 138 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd - 331D Counselor's Office | 3 | EA | 7 | 6-10 years | |
| | Power Distribution | 3rd - 331D Counselor's Office | 2 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 3rd - 331D Counselor's Office | 153 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd - 331D Counselor's Office | 340 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd - 331E Conference Room | 205 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | 3rd - 331E Conference Room | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd - 331E Conference Room | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd - 331E Conference Room | 10 | SF | 6 | 10+ years | |
| | Floor - Carpet | 3rd - 331E Conference Room | 205 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd - 331E Conference Room | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 3rd - 331E Conference Room | 2 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 3rd - 331E Conference Room | 140 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd - 331E Conference Room | 439 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd - Faculty inside 314E | 187 | SF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 3rd - Faculty inside 314E | 8 | SF | 5 | 1-2 years | Missing tile |
| | Doors - Steel Doors incl hw | 3rd - Faculty inside 314E | 2 | EA | 6 | 10+ years | 5 |
| | Floor - Tile/Sheet | 3rd - Faculty inside 314E | 195 | SF | 5 | 2-5 years | |
| | Lighting - Lay-in | 3rd - Faculty inside 314E | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 3rd - Faculty inside 314E | 6 | EA | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd - Faculty inside 314E | 599 | SF | 6 | 10+ years | |
| | Work SInk | 3rd - Faculty inside 314E | 2 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | 3rd - Instrument Room inside 314A | 93 | SF | 6 | 10+ years | |
| | | | | | | | |



| Catego | ry : Room | | B | uilding | : Main | | |
|--------|-----------------------------|-----------------------------------|----------|---------|--------|-------------|----------|
| Ū | • | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Steel Doors incl hw | 3rd - Instrument Room inside 314A | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd - Instrument Room inside 314A | 21 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd - Instrument Room inside 314A | 93 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd - Instrument Room inside 314A | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 3rd - Instrument Room inside 314A | 2 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 3rd - Instrument Room inside 314A | 98 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd - Instrument Room inside 314A | 292 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd - Project Room inside 314F | 207 | SF | 7 | 6-10 years | |
| | Doors - Steel Doors incl hw | 3rd - Project Room inside 314F | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd - Project Room inside 314F | 21 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd - Project Room inside 314F | 207 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd - Project Room inside 314F | 8 | EA | 7 | 6-10 years | |
| | Power Distribution | 3rd - Project Room inside 314F | 6 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd - Project Room inside 314F | 198 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd - Project Room inside 314F | 408 | SF | 7 | 10+ years | |
| | Work SInk | 3rd - Project Room inside 314F | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Lay-in | Assistant principal office 201A | 136 | SF | 7 | 10+ years | |
| | Doors - Side-lite | Assistant principal office 201A | 40 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | Assistant principal office 201A | 1 | EA | 7 | 10+ years | |
| | Doors - Transom Window | Assistant principal office 201A | 180 | SF | 7 | 10+ years | |
| | Floor - Carpet | Assistant principal office 201A | 136 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | Assistant principal office 201A | 3 | EA | 7 | 6-10 years | |
| | Power Distribution | Assistant principal office 201A | 3 | EA | 7 | 10+ years | |
| | Walls - Metal Panel | Assistant principal office 201A | 250 | SF | 7 | 10+ years | |
| | Ceiling - Splined | Basement - Custodian Women | 71 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Basement - Custodian Women | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | Basement - Custodian Women | 71 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | Basement - Custodian Women | 2 | EA | 6 | 6-10 years | |
| | Power Distribution | Basement - Custodian Women | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Basement - Custodian Women | 269 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | Basement - Engineer / fire alarm | 150 | SF | 6 | 10+ years | |
| | | suite | | | | | |
| | Doors - Side-lite | Basement - Engineer / fire alarm | 10 | SF | 7 | 10+ years | |
| | | suite | | | | | |
| | Doors - Steel Doors incl hw | Basement - Engineer / fire alarm | 2 | EA | 7 | 10+ years | |
| | | suite | | | | | |
| | Floor - Tile | Basement - Engineer / fire alarm | 150 | SF | 6 | 10+ years | |
| | | suite | | | | | |
| | Lighting - Lay-in | Basement - Engineer / fire alarm | 3 | EA | 6 | 6-10 years | |
| | | suite | | | | | |
| | Power Distribution | Basement - Engineer / fire alarm | 6 | EA | 7 | 10+ years | |
| | | suite | | | | - | |
| | | | | | | | |
| | Walls - Concrete Block | Basement - Engineer / fire alarm | 421 | SF | 6 | 10+ years | |



| Catego | ry : Room | | В | uilding | : Main | | |
|---------|---------------------------------|-------------------------------------|----------|---------|--------|-------------|---------------|
| | | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Plaster/Drywall | Basement - Engineer Office | 256 | SF | 7 | 10+ years | |
| | Doors - Side-lite | Basement - Engineer Office | 10 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | Basement - Engineer Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Basement - Engineer Office | 256 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | Basement - Engineer Office | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | Basement - Engineer Office | 10 | EA | 7 | 10+ years | |
| | Storage/ Closet | Basement - Engineer Office | 90 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Basement - Engineer Office | 362 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Basement - Engineer Office | 174 | SF | 7 | 10+ years | |
| | Ceiling - Splined | Basement - inside kitchen | 158 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Basement - inside kitchen | 1 | EA | 7 | 6-10 years | |
| | Doors - Store Front | Basement - inside kitchen | 1 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | Basement - inside kitchen | 158 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Basement - inside kitchen | 3 | EA | 6 | 6-10 years | |
| | Power Distribution | Basement - inside kitchen | 4 | EA | 7 | 6-10 years | |
| | Walls - Metal Panel | Basement - inside kitchen | 100 | SF | 7 | 10+ years | |
| | Walls - Structural Glazed Tile | Basement - inside kitchen | 204 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | Faculty work room 201B | 285 | SF | 7 | 10+ years | |
| | Doors - Side-lite | Faculty work room 201B | 18 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | Faculty work room 201B | 1 | EA | 7 | 10+ years | |
| | Doors - Transom Window | Faculty work room 201B | 26 | SF | 7 | 10+ years | |
| | Floor - Carpet | Faculty work room 201B | 285 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | Faculty work room 201B | 6 | EA | 6 | 6-10 years | |
| | Power Distribution | Faculty work room 201B | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Faculty work room 201B | 90 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | Faculty work room 201B | 550 | SF | 7 | 10+ years | |
| | | | | | | | |
| Clinic | | | | | | | |
| | Ceiling - Lay-in | 1st- Rm 114 Medical lab next to 113 | 640 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st- Rm 114 Medical lab next to 113 | 2 | EA | 6 | 6-10 years | |
| | Floor - Tile/Sheet | 1st- Rm 114 Medical lab next to 113 | 640 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st- Rm 114 Medical lab next to 113 | 12 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 1st- Rm 114 Medical lab next to 113 | 50 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st- Rm 114 Medical lab next to 113 | 705 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st- Rm 114 Medical lab next to 113 | 300 | SF | 7 | 10+ years | |
| Kitohon | | | | | | | |
| Kitchen | Ceiling - Splined | Basement | 2,899 | SF | 6 | 6-10 years | |
| | Ceiling - Splined | Basement | 500 | SF | 5 | 1-2 years | Missing tails |
| | Doors - Steel Doors incl hw | Basement | 4 | EA | 6 | 6-10 years | |
| | Floor - Terrazzo | Basement | 3,399 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Basement | 69 | EA | 7 | 6-10 years | |
| | Storage/ Closet | Basement | 109 | SF | 7 | 10+ years | |
| | Storage/ Closet | Basement | 250 | SF | 7 | 10+ years | |
| | | | 200 | | | youro | |



| Catego | ry : Room | | R | uilding | : Main | | |
|----------|--|----------------------------|----------|---------|--------|-------------|---------------|
| Suicyo | | | | anang | · man | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| oroup | Storage/ Closet | Basement | 356 | SF | 7 | 10+ years | Commente |
| | Walls - Tile Ceramic/ Porcelain | Basement | 4,252 | SF | 7 | 10+ years | |
| | | Bacomon | 1,202 | 0. | • | ier yeare | |
| ibrary | | | | | | | |
| , | Casework | 2nd - 235 | 227 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 2nd - 235 | 5,193 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 2nd - 235 | 10 | SF | 6 | 10+ years | |
| | Doors - Store Front | 2nd - 235 | 3 | EA | 6 | 10+ years | |
| | Doors - Store Front | 2nd - 235 | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | 2nd - 235 | 2,645 | SF | 6 | 6-10 years | |
| | Floor - Tile/Sheet | 2nd - 235 | 2,548 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd - 235 | 210 | ĒA | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd - 235 | 8 | EA | 6 | 1-2 years | Not working |
| | Storage/ Closet | 2nd - 235 | 2,224 | SF | 7 | 6-10 years | |
| | Storage/ Closet | 2nd - 235 | 25 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd - 235 | 1,481 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 2nd - 235 | 1,670 | SF | 7 | 10+ years | |
| | | | .,010 | • | | ie geale | |
| _ocker/S | Shower Room | | | | | | |
| | Accessories | Basement - Custodian Men | 292 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Basement - Custodian Men | 90 | SF | 6 | 10+ years | |
| | Ceiling - Splined (Moister Resistance) | Basement - Custodian Men | 172 | SF | 6 | 6-10 years | |
| | Ceiling - Splined (Moister Resistance) | Basement - Custodian Men | 30 | SF | 4 | 0-1 year | Missing tiles |
| | Doors - Steel Doors incl hw | Basement - Custodian Men | 1 | ĒA | 7 | 10+ years | 3 |
| | Doors - Steel Doors incl hw | Basement - Custodian Men | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | Basement - Custodian Men | 292 | SF | 7 | 10+ years | |
| | Floor Drain | Basement - Custodian Men | | ĒA | 7 | 10+ years | |
| | Lavatory | Basement - Custodian Men | 1 | EA | 6 | 2-5 years | |
| | Lighting - Lay-in | Basement - Custodian Men | 11 | EA | 7 | 6-10 years | |
| | Partitions | Basement - Custodian Men | 1 | EA | 5 | 6-10 years | |
| | Showers | Basement - Custodian Men | 1 | EA | 5 | 2-5 years | |
| | Student Lockers - One Tier | Basement - Custodian Men | 29 | EA | 7 | 10+ years | |
| | Urinals | Basement - Custodian Men | 1 | EA | 6 | 2-5 years | |
| | Walls - Concrete Block | Basement - Custodian Men | 930 | SF | 7 | 10+ years | |
| | Water Closet | Basement - Custodian Men | 930 1 | EA | 6 | 2-5 years | |
| | Accessories | Basement - Custodian Women | 144 | SF | 7 | 6-10 years | |
| | Ceiling - Splined (Moister Resistance) | Basement - Custodian Women | 144 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | Basement - Custodian Women | 2 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | Basement - Custodian Women | 2 144 | SF | 7 | 10+ years | |
| | Floor Drain | Basement - Custodian Women | 144 | EA | 7 | | |
| | | | • | EA | 6 | 10+ years | |
| | Lavatory | Basement - Custodian Women | 1 | | - | 10+ years | |
| | Lighting - Lay-in | Basement - Custodian Women | 2 | EA | 7 | 6-10 years | |
| | Partitions | Basement - Custodian Women | 1 | EA | 7 | 10+ years | |
| | Showers | Basement - Custodian Women | 1 | EA | 7 | 6-10 years | |



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|--|--|----------|------------|--------|-------------|----------|
| j | , | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Student Lockers - One Tier | Basement - Custodian Women | 7 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Basement - Custodian Women | 537 | SF | 7 | 10+ years | |
| | Water Closet | Basement - Custodian Women | 1 | EA | 6 | 10+ years | |
| | Accessories | Basement - Men Staff Locker - used | 126 | SF | 7 | 6-10 years | |
| | | as storage | | | | - | |
| | Ceiling - Plaster/Drywall | Basement - Men Staff Locker - used | 126 | SF | 6 | 10+ years | |
| | | as storage | | | | | |
| | Ceiling - Splined (Moister Resistance) | Basement - Men Staff Locker - used | 187 | SF | 6 | 6-10 years | |
| | | as storage | | | | | |
| | Doors - Steel Doors incl hw | Basement - Men Staff Locker - used | 2 | EA | 6 | 6-10 years | |
| | | as storage | | | | | |
| | Floor - Terrazzo | Basement - Men Staff Locker - used | 126 | SF | 7 | 10+ years | |
| | | as storage | | | | | |
| | Floor - Tile/Sheet | Basement - Men Staff Locker - used | 187 | SF | 7 | 6-10 years | |
| | | as storage | | | | | |
| | Floor Drain | Basement - Men Staff Locker - used | 1 | EA | 7 | 10+ years | |
| | | as storage | | | | | |
| | Lavatory | Basement - Men Staff Locker - used | 2 | EA | 6 | 6-10 years | |
| | | as storage | _ | | _ | | |
| | Lighting - Lay-in | Basement - Men Staff Locker - used | 8 | EA | 7 | 6-10 years | |
| | | as storage | | | _ | | |
| | Partitions | Basement - Men Staff Locker - used | 1 | EA | 7 | 6-10 years | |
| | 0 | as storage | | F A | - | 0.40 | |
| | Showers | Basement - Men Staff Locker - used | 1 | EA | 7 | 6-10 years | |
| | Otodaat Laskana – Osa Tian | as storage | 40 | | 7 | 10 | |
| | Student Lockers - One Tier | Basement - Men Staff Locker - used | 12 | EA | 7 | 10+ years | |
| | Urinals | as storage Basement - Men Staff Locker - used | 1 | EA | 6 | 6-10 years | |
| | UTITIAIS | as storage | I | EA | 0 | 0-10 years | |
| | Walls - Concrete Block | Basement - Men Staff Locker - used | 437 | SF | 7 | 10+ years | |
| | | as storage | 437 | ЪГ | 1 | 10+ years | |
| | Water Closet | Basement - Men Staff Locker - used | 1 | EA | 6 | 6-10 years | |
| | Water Closet | as storage | 1 | LA | 0 | 0-10 years | |
| | Accessories | Basement - Women Staff Locker | 474 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Basement - Women Staff Locker | 129 | SF | 6 | 10+ years | |
| | Ceiling - Splined (Moister Resistance) | Basement - Women Staff Locker | 345 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | Basement - Women Staff Locker | 2 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | Basement - Women Staff Locker | 474 | SF | 7 | 10+ years | |
| | Floor Drain | Basement - Women Staff Locker | 1 | EA | 7 | 10+ years | |
| | Lavatory | Basement - Women Staff Locker | 2 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | Basement - Women Staff Locker | 12 | EA | 7 | 6-10 years | |
| | Partitions | Basement - Women Staff Locker | 1 | EA | 7 | 10+ years | |
| | Showers | Basement - Women Staff Locker | 1 | EA | 5 | 6-10 years | |
| | Student Lockers - One Tier | Basement - Women Staff Locker | 21 | EA | 7 | 10+ years | |
| | | | - 1 | _/ ` | • | | |



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Basement - Women Staff Locker Walls - Concrete Block 1.097 SF 10+ years 7 Water Closet Basement - Women Staff Locker 2 ΕA 6 10+ years Lunch & Multipurpose Room Ceiling - Lay-in 1st- Rm 104 Genesis Cafe 905 SF 6 6-10 years SF Ceiling - Lay-in 1st- Rm 104 Genesis Cafe 32 1-2 years Water damaged 4 Doors - Side-lite 1st- Rm 104 Genesis Cafe 6 SF 7 10+ years 2 Doors - Steel Doors incl hw 1st- Rm 104 Genesis Cafe FΑ 7 10+ years SF Floor - Tile Ceramic/ Porcelain 1st- Rm 104 Genesis Cafe 937 7 10+ vears Lighting - Lay-in 1st- Rm 104 Genesis Cafe 38 EA 7 6-10 years LF Market Board 1st- Rm 104 Genesis Cafe 12 7 6-10 years Walls - Concrete Block 1st- Rm 104 Genesis Cafe 240 SF 7 10+ years Walls - Metal Panel 1st- Rm 104 Genesis Cafe SF 7 1.016 10+ years SF Walls - Metal Panel 1st- Rm 104 Genesis Cafe 240 7 10+ years SF 7 Ceiling - Plaster/Drvwall 3rd - Beta Commons 20 10+ vears Ceiling - Plaster/Drywall 3rd - Beta Commons 2.796 SF 6 6-10 years Doors - Steel Doors incl hw 3rd - Beta Commons 1 FΑ 6 10+ years Doors - Store Front 3rd - Beta Commons 2 FA 6 10+ years SF Doors - Transom Window 3rd - Beta Commons 32 6 10+ years Floor - Tile/Sheet 3rd - Beta Commons 2,816 SF 7 6-10 years Lighting - Lav-in 3rd - Beta Commons 57 ΕA 7 6-10 years Walls - Concrete Block 3rd - Beta Commons 587 SF 7 10+ vears SF Walls - Metal Panel 3rd - Beta Commons 442 7 10+ vears SF Ceiling - Lav-in 3rd - Beta Serving Area 772 6 6-10 years Doors - Steel Doors incl hw 3rd - Beta Serving Area 2 EA 6 10+ years Floor - Terrazzo 3rd - Beta Serving Area 772 SF 6 10+ years 7 Lighting - Lay-in 3rd - Beta Serving Area 28 FA 6-10 years 5 Lighting - Lay-in 3rd - Beta Serving Area EΑ 6 1-2 years May not be operational 40 LF Serving Line 3rd - Beta Serving Area 6 10+ years SF Walls - Tile Ceramic/ Porcelain 3rd - Beta Serving Area 1.325 7 10+ years SF Ceiling - Lay-in 3rd - Gamma Commons 401 6 10+ years SF Ceiling - Plaster/Drvwall 3rd - Gamma Commons 2.897 6 10+ vears Doors - Steel Doors incl hw 3rd - Gamma Commons EA 6 10+ years 1 Doors - Store Front 3rd - Gamma Commons 2 ΕA 6 10+ years Doors - Transom Window 3rd - Gamma Commons 68 SF 6 10+ years SF 7 Floor - Tile/Sheet 3rd - Gamma Commons 3.298 6-10 years Lighting - Lay-in 3rd - Gamma Commons 53 FΑ 7 6-10 years FΑ Lighting - Lay-in 3rd - Gamma Commons 9 6 2-5 years Not operational SF Walls - Concrete Block 3rd - Gamma Commons 747 7 10+ vears SF Walls - Metal Panel 7 10+ years 3rd - Gamma Commons 899 SF 6-10 years Ceiling - Splined 3rd - Gamma Serving area 770 6 Doors - Steel Doors incl hw 3rd - Gamma Serving area 3 EΑ 6 10+ years Floor - Terrazzo 3rd - Gamma Serving area 770 SF 6 10+ years 7 Lighting - Lay-in 3rd - Gamma Serving area 33 EA 6-10 years



| Category : Room | | | В | uilding | : Main | | |
|-----------------|---------------------------------|--------------------------|----------|---------|--------|-------------|--------------------|
| | , | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| - | Serving Line | 3rd - Gamma Serving area | 40 | LF | 7 | 6-10 years | |
| | Walls - Tile Ceramic/ Porcelain | 3rd - Gamma Serving area | 1,325 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd - Teachers Cafeteria | 420 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 3rd - Teachers Cafeteria | 1 | EA | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd - Teachers Cafeteria | 1 | EA | 4 | 1-2 years | Removed from frame |
| | Doors - Store Front | 3rd - Teachers Cafeteria | 44 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 3rd - Teachers Cafeteria | 825 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 3rd - Teachers Cafeteria | 420 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd - Teachers Cafeteria | 9 | EA | 7 | 6-10 years | |
| | Walls - Metal Panel | 3rd - Teachers Cafeteria | 80 | SF | 7 | 10+ years | |
| MDF ID | F | | | | | | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Finishes | 1st Floor | 113 | SF | 7 | 6-10 years | |
| | Other Cooling Unit | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Mechani | cal/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 54 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 276 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 154 | SF | 7 | 10+ years | |
| | Vaults | 1st Floor | 104 | SF | 7 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 56 | SF | 7 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 35 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 126 | SF | 7 | 10+ years | |
| | Storage Room | 2nd Floor | 663 | SF | 7 | 10+ years | |
| | Janitor's Closet | 3rd Floor | 52 | SF | 7 | 10+ vears | |
| | Janitor's Closet | 3rd Floor | 52 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 35 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 3rd Floor | 202 | SF | 7 | 10+ years | |
| | Storage Room | 3rd Floor | 711 | SF | 7 | 10+ years | |
| | Boiler Room | Basement | 902 | SF | 7 | 10+ years | |
| | Janitor's Closet | Basement | 27 | SF | 7 | 10+ years | |
| | Loading Docks | Basement | 418 | SF | 7 | 10+ years | |
| | Loading Docks | Basement | 2,000 | SF | 7 | 10+ years | |
| | Loading Docks | Basement | 9,286 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | Basement | 535 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | Basement | 577 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | Basement | 804 | SF | 7 | 10+ years | |
| | Storage Room | Basement | 2,804 | SF | 7 | 10+ years | |
| Prep Ro | om | | | | | | |
| | Casework | 319C | 10 | LF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 319C | 220 | SF | 7 | 10+ years | |



| Category : Room | | | B | uilding | : Main | | |
|-----------------|---------------------------------|------------------------|----------|---------|--------|-------------|-------------------------------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Steel Doors incl hw | 319C | 1 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 319C | 32 | SF | 7 | 10+ years | |
| | Floor - Tile | 319C | 220 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 319C | 8 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 319C | 110 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 319C | 240 | SF | 7 | 10+ years | |
| | Work Sink | 319C | 1 | EA | 7 | 10+ years | |
| | Casework | Inside classroom 240 | 14 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | Inside classroom 240 | 198 | SF | 4 | 1-2 years | Damaged missing ceiling tiles |
| | Doors - Wood Doors inclu hw | Inside classroom 240 | 1 | EA | 7 | 10+ years | Damagoa meenig comig nee |
| | Floor - Terrazzo | Inside classroom 240 | 198 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | Inside classroom 240 | 130 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | Inside classroom 240 | 9 | EA | 4 | 1-2 years | Not working |
| | Walls - Plaster/Drywall | Inside classroom 240 | 270 | SF | 6 | 10+ years | Not working |
| | 2 | | | SF | - | | |
| | Walls - Tile Ceramic/ Porcelain | Inside classroom 240 | 300 | | 6 | 10+ years | Out at use |
| | Work Sink | Inside classroom 240 | 1 | EA | 4 | 1-2 years | Out of use |
| | Casework | Inside science lab 242 | 50 | LF | 7 | 6-10 years | |
| | Ceiling - Lay-in | Inside science lab 242 | 417 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Inside science lab 242 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | Inside science lab 242 | 417 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | Inside science lab 242 | 3 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | Inside science lab 242 | 660 | SF | 7 | 10+ years | |
| | Work Sink | Inside science lab 242 | 2 | EA | 7 | 6-10 years | |
| Destruction | | | | | | | |
| Restroo | | | 0.15 | | _ | | |
| | Accessories | 1st Floor | 345 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 345 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 345 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Hand Dryer | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 8 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor | 6 | EA | 7 | 6-10 years | |
| | Walls - Masonry | 1st Floor | 525 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor | 285 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor | 6 | ĒA | 7 | 6-10 years | |
| | Accessories | 1st Floor | 345 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 345 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 345 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Hand Dryer | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | • | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Lavatory | | | | | , | |
| | Lighting - Lay-in | 1st Floor | 8 | EA | 7 | 6-10 years | |



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Partitions 1st Floor 3 ΕA 6-10 vears 7 3 ΕA 7 Urinals 1st Floor 6-10 years Walls - Masonry 1st Floor 525 SF 7 10+ years Walls - Tile Ceramic/ Porcelain SF 7 1st Floor 285 10+ years Water Closet 1st Floor 3 EΑ 7 6-10 years SF Accessories 1st- Main Office Suite- next to 28 7 6-10 years Principal SF Ceiling - Plaster/Drywall 1st- Main Office Suite- next to 28 6 10+ years Principal Doors - Steel Doors incl hw 1st- Main Office Suite- next to FΑ 1 6 6-10 years Principal Floor - Terrazzo 1st- Main Office Suite- next to 28 SF 6 10+ years Principal Lavatory 1st- Main Office Suite- next to 1 EΑ 6 6-10 years Principal 1st- Main Office Suite- next to FΑ Lighting - Lay-in 1 6 6-10 years Principal Walls - Metal Panel 1st- Main Office Suite- next to 204 SF 6 10+ years Principal 1st- Main Office Suite- next to Walls - Metal Panel 6 SF 6 10+ years Principal Water Closet 1st- Main Office Suite- next to 1 EΑ 6 6-10 years Principal 1st- Men's Staff inside Boy's RR SF Accessories 26 7 6-10 years Ceiling - Plaster/Drywall 1st- Men's Staff inside Boy's RR 26 SF 5 2-5 years Doors - Steel Doors incl hw 1st- Men's Staff inside Boy's RR 1 ΕA 6 6-10 vears SF Floor - Terrazzo 1st- Men's Staff inside Boy's RR 26 6 10+ years 1st- Men's Staff inside Boy's RR ΕA 6 6-10 years Lavatory 1 Lighting - Lay-in 1st- Men's Staff inside Boy's RR 1 EΑ 6 6-10 years Walls - Masonry 1st- Men's Staff inside Boy's RR 80 SF 6 10+ years SF Walls - Plaster/Drvwall 1st- Men's Staff inside Boy's RR 80 6 10+ vears Water Closet 1st- Men's Staff inside Boy's RR 1 EΑ 6 6-10 vears SF 7 **1st- Principals Toilet** 28 6-10 years Accessories Ceiling - Plaster/Drywall 1st- Principals Toilet 28 SF 6 10+ years Doors - Steel Doors incl hw 1st- Principals Toilet 1 EA 6 6-10 years Floor - Terrazzo SF 6 1st- Principals Toilet 28 10+ years Lavatory 1st- Principals Toilet 1 EΑ 6 6-10 years Lighting - Lay-in **1st- Principals Toilet** 1 EA 6 6-10 years Walls - Plaster/Drywall 1st- Principals Toilet 8 SF 6 10+ years SF Walls - Plaster/Drvwall 1st- Principals Toilet 210 6 10+ vears Water Closet 1st- Principals Toilet ΕA 6 6-10 years 1 1st- Rm 108- Unisex #1 25 SF 7 Accessories 6-10 years Ceiling - Plaster/Drywall 1st- Rm 108- Unisex #1 25 SF 7 10+ years Doors - Steel Doors incl hw ΕA 1st- Rm 108- Unisex #1 1 7 10+ years



| Category : Room | | | Building : Main | | | | | | |
|-----------------|-----------------------------|-------------------------------------|-----------------|-----|------|-------------|---------------------------------|--|--|
| | | | | | | Recommend | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| • | Floor - Terrazzo | 1st- Rm 108- Unisex #1 | 25 | SF | 7 | 10+ years | | | |
| | Lavatory | 1st- Rm 108- Unisex #1 | 1 | EA | 7 | 6-10 years | | | |
| | Lighting - Lay-in | 1st- Rm 108- Unisex #1 | 1 | EA | 7 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 1st- Rm 108- Unisex #1 | 155 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | 1st- Rm 108- Unisex #1 | 5 | SF | 7 | 10+ years | | | |
| | Water Closet | 1st- Rm 108- Unisex #1 | 1 | EA | 7 | 6-10 years | | | |
| | Accessories | 1st- Rm 108- Unisex #2 | 25 | SF | 7 | 2-5 years | | | |
| | Ceiling - Plaster/Drywall | 1st- Rm 108- Unisex #2 | 25 | SF | 6 | 10+ years | | | |
| | Doors - Steel Doors incl hw | 1st- Rm 108- Unisex #2 | 1 | EA | 6 | 6-10 years | | | |
| | Floor - Terrazzo | 1st- Rm 108- Unisex #2 | 25 | SF | 6 | 10+ years | | | |
| | Lavatory | 1st- Rm 108- Unisex #2 | 1 | EA | 6 | 6-10 years | | | |
| | Lighting - Lay-in | 1st- Rm 108- Unisex #2 | 1 | EA | 6 | 6-10 years | | | |
| | Walls - Plaster/Drywall | 1st- Rm 108- Unisex #2 | 160 | SF | 6 | 10+ years | | | |
| | Water Closet | 1st- Rm 108- Unisex #2 | 1 | EA | 6 | 6-10 years | | | |
| | Accessories | 1st- Staff Restroom across from | 30 | SF | 7 | 6-10 years | | | |
| | | Rm1005 | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st- Staff Restroom across from | 30 | SF | 7 | 10+ years | | | |
| | · · | Rm1005 | | | | - | | | |
| | Doors - Steel Doors incl hw | 1st- Staff Restroom across from | 1 | EA | 4 | 1-2 years | Door damaged and wouldn't close | | |
| | | Rm1005 | | | | 2 | C C | | |
| | Floor - Terrazzo | 1st- Staff Restroom across from | 30 | SF | 7 | 10+ years | | | |
| | | Rm1005 | | | | , , | | | |
| | Lavatory | 1st- Staff Restroom across from | 1 | EA | 7 | 10+ years | | | |
| | - | Rm1005 | | | | , | | | |
| | Lighting - Lay-in | 1st- Staff Restroom across from | 1 | EA | 7 | 6-10 years | | | |
| | | Rm1005 | | | | | | | |
| | Walls - Plaster/Drywall | 1st- Staff Restroom across from | 200 | SF | 7 | 10+ years | | | |
| | - | Rm1005 | | | | - | | | |
| | Water Closet | 1st- Staff Restroom across from | 1 | EA | 7 | 10+ years | | | |
| | | Rm1005 | | | | , , | | | |
| | Accessories | 1st- Unisex Staff RR#2- across from | 30 | SF | 7 | 6-10 years | | | |
| | | Rm1005 | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st- Unisex Staff RR#2- across from | 30 | SF | 7 | 10+ years | | | |
| | 5 | Rm1005 | | | | , | | | |
| | Doors - Steel Doors incl hw | 1st- Unisex Staff RR#2- across from | 1 | EA | 6 | 6-10 years | | | |
| | | Rm1005 | | | | , | | | |
| | Floor - Terrazzo | 1st- Unisex Staff RR#2- across from | 30 | SF | 7 | 10+ years | | | |
| | | Rm1005 | | - | | - , | | | |
| | Lavatory | 1st- Unisex Staff RR#2- across from | 1 | EA | 7 | 6-10 years | | | |
| | , | Rm1005 | | | | , | | | |
| | Lighting - Lay-in | 1st- Unisex Staff RR#2- across from | 1 | EA | 7 | 10+ years | | | |
| | 5 5 5 5 | Rm1005 | | | | · | | | |
| | Walls - Plaster/Drywall | 1st- Unisex Staff RR#2- across from | 200 | SF | 7 | 10+ years | | | |
| | | Rm1005 | | | | , | | | |
| | | | | | | | | | |



| Category : Room | | | Building : Main | | | | |
|-----------------|-----------------------------|---|-----------------|-----|------|-------------|---|
| | ., | | _ | | | Recommend | |
| iroup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Water Closet | 1st- Unisex Staff RR#2- across from | 1 | EA | 7 | 6-10 years | |
| | | Rm1005 | | | _ | | |
| | Accessories | 1st- Women's staff RR inside Girl's RR | 26 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st- Women's staff RR inside Girl's RR | 26 | SF | 4 | 1-2 years | Water damage on ceiling |
| | Doors - Steel Doors incl hw | 1st- Women's staff RR inside Girl's RR | 1 | EA | 6 | 10+ years | |
| | Floor - Terrazzo | 1st- Women's staff RR inside Girl's RR | 26 | SF | 6 | 10+ years | |
| | Lavatory | 1st- Women's staff RR inside Girl's RR | 1 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 1st- Women's staff RR inside Girl's RR | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st- Women's staff RR inside Girl's RR | 80 | SF | 6 | 10+ years | |
| | Walls - Masonry | 1st- Women's staff RR inside Girl's RR | 80 | SF | 6 | 10+ years | |
| | Water Closet | 1st- Women's staff RR inside Girl's RR | 1 | EA | 6 | 6-10 years | |
| | Accessories | 1st- by 001 Unisex Staff RR | 39 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st- by 001 Unisex Staff RR | 39 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st- by 001 Unisex Staff RR | 1 | EA | 6 | 1-2 years | Door broken could not open into restroom |
| | Floor - Terrazzo | 1st- by 001 Unisex Staff RR | 39 | SF | 7 | 10+ years | |
| | Lavatory | 1st- by 001 Unisex Staff RR | 1 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 1st- by 001 Unisex Staff RR | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st- by 001 Unisex Staff RR | 62 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st- by 001 Unisex Staff RR | 142 | SF | 7 | 10+ years | |
| | Water Closet | 1st- by 001 Unisex Staff RR | 1 | EA | 7 | 10+ years | |
| | Accessories | 2nd - Men staff west | 23 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd - Men staff west | 23 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd - Men staff west | 1 | EA | 6 | 10+ years | |
| | Floor - Terrazzo | 2nd - Men staff west | 23 | SF | 6 | 10+ years | |
| | Lavatory | 2nd - Men staff west | 1 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd - Men staff west | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd - Men staff west | 157 | SF | 6 | 10+ years | |
| | Water Closet | 2nd - Men staff west | 1 | EA | 6 | 6-10 years | |
| | Accessories | 2nd - Mens East | 334 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd - Mens East | 334 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | 2nd - Mens East | 334 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd - Mens East | | EA | 7 | • | |
| | | 2nd - Mens East 2nd - Mens East | 1 | | | 6-10 years | |
| | Hand Dryer | | - | EA | 7 | 6-10 years | |
| | Lavatory | 2nd - Mens East | 2 | EA | 7 | 6-10 years | |



| Category : Room | | | В | uilding | : Main | | | |
|-----------------|---------------------------------|--|----------|----------|--------|------------------------|----------|--|
| | , | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Lavatory | 2nd - Mens East | 1 | EA | 7 | 6-10 years | | |
| | Lighting - Lay-in | 2nd - Mens East | 8 | EA | 7 | 6-10 years | | |
| | Partitions | 2nd - Mens East | 4 | EA | 7 | 10+ years | | |
| | Urinals | 2nd - Mens East | 3 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | 2nd - Mens East | 174 | SF | 7 | 10+ years | | |
| | Walls - Tile Ceramic/ Porcelain | 2nd - Mens East | 553 | SF | 7 | 10+ years | | |
| | Water Closet | 2nd - Mens East | 4 | EA | 7 | 6-10 years | | |
| | Accessories | 2nd - Mens West | 334 | SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | 2nd - Mens West | 334 | SF | 6 | 10+ years | | |
| | Floor - Terrazzo | 2nd - Mens West | 334 | SF | 6 | 10+ years | | |
| | Floor Drain | 2nd - Mens West | 1 | ĒA | 7 | 10+ years | | |
| | Hand Dryer | 2nd - Mens West | 1 | EA | 7 | 6-10 years | | |
| | Lavatory | 2nd - Mens West | 3 | EA | 7 | 6-10 years | | |
| | Lighting - Lay-in | 2nd - Mens West | 8 | EA | 7 | 6-10 years | | |
| | Partitions | 2nd - Mens West | 5 | EA | 7 | 6-10 years | | |
| | Urinals | 2nd - Mens West | 3 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | 2nd - Mens West | 173 | SF | 7 | 10+ years | | |
| | Walls - Tile Ceramic/ Porcelain | 2nd - Mens West | 555 | SF | 7 | 10+ years | | |
| | Water Closet | 2nd - Mens West | 5 | EA | 7 | 6-10 years | | |
| | Accessories | 2nd - Mens staff east | 24 | SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | 2nd - Mens staff east | 24 | SF | 6 | 10+ years | | |
| | Doors - Steel Doors incl hw | 2nd - Mens staff east | 1 | EA | 6 | 10+ years | | |
| | Floor - Terrazzo | 2nd - Mens staff east | 24 | SF | 7 | 10+ years | | |
| | Lavatory | 2nd - Mens staff east | 1 | EA | 7 | 6-10 years | | |
| | Lighting - Lay-in | 2nd - Mens staff east | 1 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | 2nd - Mens staff east | 157 | SF | 7 | 10+ years | | |
| | Water Closet | 2nd - Mens staff east | 107 | EA | 7 | 6-10 years | | |
| | Accessories | 2nd - Unisex by 210 | 47 | SF | 7 | 10+ years | | |
| | Ceiling - Plaster/Drywall | 2nd - Unisex by 210 2nd - Unisex by 210 | 47 | SF | 6 | 10+ years | | |
| | Doors - Steel Doors incl hw | 2nd - Unisex by 210 2nd - Unisex by 210 | 47 | EA | 6 | 10+ years | | |
| | Floor - Tile/Sheet | 2nd - Unisex by 210 2nd - Unisex by 210 | 47 | SF | 7 | 6-10 years | | |
| | Floor Drain | 2nd - Unisex by 210 | | EA | 7 | 10+ years | | |
| | Hand Dryer | 2nd - Unisex by 210 2nd - Unisex by 210 | 1 | EA | 7 | 6-10 years | | |
| | Lavatory | 2nd - Unisex by 210 2nd - Unisex by 210 | 1 | EA | 7 | 6-10 years | | |
| | Lighting - Lay-in | 2nd - Unisex by 210 2nd - Unisex by 210 | 1 | EA | 7 | 6-10 years | | |
| | Walls - Plaster/Drywall | 2nd - Unisex by 210 2nd - Unisex by 210 | 249 | SF | 7 | 10+ years | | |
| | Water Closet | 2nd - Unisex by 210 2nd - Unisex by 210 | 249 | EA | 7 | 6-10 years | | |
| | Accessories | | 106 | SF | 7 | • | | |
| | Ceiling - Plaster/Drywall | 2nd - Unisex by 211 | 106 | SF | 6 | 10+ years | | |
| | Doors - Steel Doors incl hw | 2nd - Unisex by 211 2nd - Unisex by 211 | 108 | EA | 6 | 10+ years 10+ years | | |
| | Floor - Tile | | | SF | - | • | | |
| | | 2nd - Unisex by 211 | 106 | EA | 6 | 6-10 years | | |
| | Floor Drain | 2nd - Unisex by 211 | 1 | EA EA | 7 | 10+ years | | |
| | Hand Dryer | 2nd - Unisex by 211 | 1 | EA | 7 7 | 6-10 years | | |
| | Lavatory | 2nd - Unisex by 211 | 1 | EA | 1 | 6-10 years | | |
| | | | | | | | | |



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|---------------------------------|-------------------------|----------|---------|--------|-------------|----------|
| Ū | • | | | Ŭ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 2nd - Unisex by 211 | 2 | EA | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 2nd - Unisex by 211 | 398 | SF | 7 | 10+ years | |
| | Water Closet | 2nd - Unisex by 211 | 1 | EA | 7 | 6-10 years | |
| | Accessories | 2nd - Women staff east | 24 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd - Women staff east | 24 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd - Women staff east | 1 | EA | 6 | 10+ years | |
| | Floor - Terrazzo | 2nd - Women staff east | 24 | SF | 6 | 10+ years | |
| | Lavatory | 2nd - Women staff east | 1 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd - Women staff east | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd - Women staff east | 157 | SF | 6 | 10+ years | |
| | Water Closet | 2nd - Women staff east | 1 | EA | 6 | 6-10 years | |
| | Accessories | 2nd - Women staff west | 24 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd - Women staff west | 24 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd - Women staff west | 1 | EA | 6 | 10+ years | |
| | Floor - Terrazzo | 2nd - Women staff west | 24 | SF | 6 | 10+ years | |
| | Lavatory | 2nd - Women staff west | 1 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd - Women staff west | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd - Women staff west | 157 | SF | 6 | 10+ years | |
| | Water Closet | 2nd - Women staff west | 1 | EA | 6 | 6-10 years | |
| | Accessories | 2nd - Women's East Side | 334 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd - Women's East Side | 334 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | 2nd - Women's East Side | 47 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 2nd - Women's East Side | 287 | SF | 7 | 10+ years | |
| | Floor Drain | 2nd - Women's East Side | 1 | EA | 7 | 6-10 years | |
| | Hand Dryer | 2nd - Women's East Side | 1 | EA | 5 | 2-5 years | |
| | Lavatory | 2nd - Women's East Side | 3 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd - Women's East Side | 8 | EA | 6 | 6-10 years | |
| | Partitions | 2nd - Women's East Side | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd - Women's East Side | 173 | SF | 6 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 2nd - Women's East Side | 556 | SF | 6 | 10+ years | |
| | Water Closet | 2nd - Women's East Side | 4 | EA | 6 | 6-10 years | |
| | Accessories | 2nd - Women's West Side | 334 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 2nd - Women's West Side | 334 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | 2nd - Women's West Side | 334 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd - Women's West Side | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 2nd - Women's West Side | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 2nd - Women's West Side | 3 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd - Women's West Side | 8 | EA | 7 | 6-10 years | |
| | Partitions | 2nd - Women's West Side | 5 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd - Women's West Side | 173 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 2nd - Women's West Side | 556 | SF | 6 | 10+ years | |
| | Water Closet | 2nd - Women's West Side | 5 | EA | 7 | 6-10 years | |
| | Accessories | 3rd - Men's East Side | 332 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd - Men's East Side | 332 | SF | 6 | 10+ years | |



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments 332 Floor - Terrazzo 3rd - Men's East Side SF 6 10+ vears Floor Drain 3rd - Men's East Side ΕA 7 1 10+ years Hand Drver 3rd - Men's East Side 1 FΑ 7 6-10 years 3 ΕA 7 Lavatory 3rd - Men's East Side 6-10 years 8 Lighting - Lay-in 3rd - Men's East Side EΑ 7 6-10 years 7 Partitions 3rd - Men's East Side 4 EΑ 10+ years 3rd - Men's East Side 3 ΕA 7 6-10 years Urinals SF Walls - Concrete Block 3rd - Men's East Side 173 7 10+ years SF Walls - Tile Ceramic/ Porcelain 3rd - Men's East Side 553 7 10+ vears Water Closet 3rd - Men's East Side 4 FΑ 7 6-10 years Accessories 3rd - Men's West Side 287 SF 7 6-10 years Ceiling - Plaster/Drywall 3rd - Men's West Side 287 SF 6 10+ years Floor - Terrazzo 3rd - Men's West Side 287 SF 6 10+ years 7 Floor Drain 3rd - Men's West Side 1 EA 6-10 years Hand Dryer 7 3rd - Men's West Side 1 EΑ 6-10 years 3 FΑ 7 Lavatory 3rd - Men's West Side 6-10 years 8 Lighting - Lay-in 3rd - Men's West Side EΑ 7 6-10 years Partitions 3rd - Men's West Side 5 EΑ 7 6-10 years 3 Urinals 3rd - Men's West Side ΕA 7 6-10 years Walls - Concrete Block 3rd - Men's West Side 176 SF 7 10+ years Walls - Tile Ceramic/ Porcelain 3rd - Men's West Side 555 SF 7 10+ years 5 7 Water Closet 3rd - Men's West Side EΑ 6-10 years SF 7 Accessories 3rd - Mens inside 310 30 6-10 years SF Ceiling - Plaster/Drywall 3rd - Mens inside 310 30 6 10+ years Doors - Steel Doors incl hw ΕA 6 3rd - Mens inside 310 1 10+ years SF Floor - Terrazzo 3rd - Mens inside 310 30 7 6-10 years 3rd - Mens inside 310 EA 6 6-10 years Lavatory 1 Lighting - Pendent/Surface ΕA 7 6-10 years 3rd - Mens inside 310 1 Walls - Metal Panel SF 3rd - Mens inside 310 179 7 10+ years Water Closet 3rd - Mens inside 310 ΕA 7 6-10 years 1 SF Accessories 3rd - Staff Unisex in Mens east 24 7 6-10 years corridor Ceiling - Plaster/Drywall SF 3rd - Staff Unisex in Mens east 24 6 10+ years corridor Doors - Steel Doors incl hw 3rd - Staff Unisex in Mens east 1 EA 6 10+ years corridor Floor - Terrazzo 3rd - Staff Unisex in Mens east 24 SF 6 10+ years corridor Lavatory 3rd - Staff Unisex in Mens east 1 FΑ 4 1-2 years Sink and faucet leaking corridor Lighting - Lay-in 3rd - Staff Unisex in Mens east FΑ 6 6-10 years 1 corridor Walls - Concrete Block 3rd - Staff Unisex in Mens east 157 SF 6 10+ years corridor



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments 6-10 years Water Closet 3rd - Staff Unisex in Mens east FΑ 6 1 corridor Accessories 3rd - Staff in men's west bath 24 SF 7 6-10 years corridor Ceiling - Plaster/Drywall 3rd - Staff in men's west bath 24 SF 6 10+ years corridor Doors - Steel Doors incl hw 3rd - Staff in men's west bath ΕA 1 6 10+ years corridor Floor - Terrazzo 3rd - Staff in men's west bath 24 SF 6 10+ years corridor 3rd - Staff in men's west bath 1 ΕA 6 Lavatory 6-10 years corridor 3rd - Staff in men's west bath 7 Lighting - Lay-in 1 EΑ 10+ years corridor Walls - Concrete Block 3rd - Staff in men's west bath 158 SF 6 10+ years corridor Water Closet 3rd - Staff in men's west bath 1 ΕA 6 2-5 years corridor SF Accessories 3rd - Unisex in women's east 23 7 6-10 years corridor Ceiling - Plaster/Drywall 3rd - Unisex in women's east 23 SF 6 10+ years corridor Doors - Steel Doors incl hw 3rd - Unisex in women's east 1 EA 6 10+ years corridor Floor - Terrazzo SF 3rd - Unisex in women's east 23 6 10+ years corridor 3rd - Unisex in women's east EΑ 7 6-10 years Lavatory 1 corridor Lighting - Lay-in 3rd - Unisex in women's east 1 ΕA 7 6-10 years corridor SF Walls - Concrete Block 3rd - Unisex in women's east 157 7 10+ years corridor Water Closet FΑ 7 3rd - Unisex in women's east 1 6-10 years corridor Accessories 3rd - Unisex inside 322 38 SF 5 6-10 years Ceiling - Plaster/Drywall 38 SF 6 3rd - Unisex inside 322 10+ years Doors - Steel Doors incl hw 3rd - Unisex inside 322 1 EΑ 6 10+ years Floor - Terrazzo 38 SF 6 6-10 years 3rd - Unisex inside 322 Lavatory 3rd - Unisex inside 322 1 EΑ 5 1-2 years Leaking at faucet Lighting - Pendent/Surface 3rd - Unisex inside 322 1 ΕA 6 6-10 vears Walls - Metal Panel 3rd - Unisex inside 322 180 SF 6 10+ years Water Closet FΑ 6 6-10 vears 3rd - Unisex inside 322 1 Accessories 3rd - Unisex inside 322 30 SF 7 6-10 years SF Ceiling - Plaster/Drywall 3rd - Unisex inside 322 30 6 10+ years



| Catego | ry : Room | | В | uilding | : Main | | | |
|--------|---------------------------------|---|----------|------------|----------|-------------|--------------------|--|
| e | ., | | _ | ·········· | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Doors - Steel Doors incl hw | 3rd - Unisex inside 322 | 1 | EA | 6 | 10+ years | | |
| | Floor - Terrazzo | 3rd - Unisex inside 322 | 30 | SF | 7 | 10+ years | | |
| | Lavatory | 3rd - Unisex inside 322 | 1 | ĒA | 5 | 1-2 years | Leaking at handles | |
| | Lighting - Pendent/Surface | 3rd - Unisex inside 322 | 1 | EA | 6 | 6-10 years | Loaking at handloo | |
| | Walls - Metal Panel | 3rd - Unisex inside 322 | 179 | SF | 6 | 10+ years | | |
| | Water Closet | 3rd - Unisex inside 322 | 1 | EA | 6 | 6-10 years | | |
| | Accessories | 3rd - Unisex inside 322 3rd - Unisex inside women's west | 49 | SF | 7 | 6-10 years | | |
| | Accessories | corridor | +3 | 51 | 1 | 0-10 years | | |
| | Ceiling - Plaster/Drywall | | 49 | SF | 6 | 101 years | | |
| | Celling - Flastel/Drywall | 3rd - Unisex inside women's west | 49 | SF | 0 | 10+ years | | |
| | Deere Steel Deere include | corridor | 4 | Γ Λ | <u>^</u> | 10 | | |
| | Doors - Steel Doors incl hw | 3rd - Unisex inside women's west | 1 | EA | 6 | 10+ years | | |
| | | corridor | | 0- | • | 4.0 | | |
| | Floor - Terrazzo | 3rd - Unisex inside women's west | 49 | SF | 6 | 10+ years | | |
| | | corridor | | | | | | |
| | Lavatory | 3rd - Unisex inside women's west | 1 | EA | 7 | 6-10 years | | |
| | | corridor | | | | | | |
| | Lighting - Lay-in | 3rd - Unisex inside women's west | 1 | EA | 7 | 6-10 years | | |
| | | corridor | | | | | | |
| | Walls - Concrete Block | 3rd - Unisex inside women's west | 157 | SF | 7 | 10+ years | | |
| | | corridor | | | | - | | |
| | Water Closet | 3rd - Unisex inside women's west | 1 | EA | 7 | 6-10 years | | |
| | | corridor | | | | | | |
| | Accessories | 3rd - Women East Side | 334 | SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | 3rd - Women East Side | 334 | SF | 6 | 10+ years | | |
| | Floor - Tile/Sheet | 3rd - Women East Side | 334 | SF | 7 | 10+ years | | |
| | Floor Drain | 3rd - Women East Side | 1 | EA | 7 | 6-10 years | | |
| | Hand Dryer | 3rd - Women East Side | 1 | EA | 7 | 2-5 years | | |
| | Lavatory | 3rd - Women East Side | 3 | EA | 6 | 6-10 years | | |
| | Lighting - Lay-in | 3rd - Women East Side | 8 | EA | 6 | 6-10 years | | |
| | Partitions | 3rd - Women East Side | 4 | EA | 7 | - | | |
| | Walls - Concrete Block | 3rd - Women East Side | 173 | SF | 6 | 10+ years | | |
| | | | 556 | SF | | 10+ years | | |
| | Walls - Tile Ceramic/ Porcelain | 3rd - Women East Side | | | 6 | 10+ years | | |
| | Water Closet | 3rd - Women East Side | 4 | EA | 6 | 6-10 years | | |
| | Accessories | 3rd - Women West Side | 334 | SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | 3rd - Women West Side | 334 | SF | 6 | 10+ years | | |
| | Floor - Terrazzo | 3rd - Women West Side | 334 | SF | 6 | 6-10 years | | |
| | Floor Drain | 3rd - Women West Side | 1 | EA | 7 | 6-10 years | | |
| | Hand Dryer | 3rd - Women West Side | 1 | EA | 7 | 6-10 years | | |
| | Lavatory | 3rd - Women West Side | 3 | EA | 7 | 6-10 years | | |
| | Lighting - Lay-in | 3rd - Women West Side | 8 | EA | 7 | 6-10 years | | |
| | Partitions | 3rd - Women West Side | 5 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | 3rd - Women West Side | 173 | SF | 7 | 10+ years | | |
| | Walls - Tile Ceramic/ Porcelain | 3rd - Women West Side | 556 | SF | 6 | 10+ years | | |
| | Water Closet | 3rd - Women West Side | 5 | EA | 7 | 6-10 years | | |
| | | | - | | | j ' | | |



| Catego | ry : Room | | Building : Main | | | | | |
|--------|-----------------------------|------------------------------------|-----------------|-----|------|-------------|-------------------------|--|
| | | | | _ | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Accessories | 3rd - Women inside 310 | 30 | SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | 3rd - Women inside 310 | 30 | SF | 6 | 10+ years | | |
| | Doors - Steel Doors incl hw | 3rd - Women inside 310 | 1 | EA | 6 | 10+ years | | |
| | Floor - Terrazzo | 3rd - Women inside 310 | 30 | SF | 7 | 6-10 years | | |
| | Lavatory | 3rd - Women inside 310 | 1 | EA | 7 | 6-10 years | | |
| | Lighting - Lay-in | 3rd - Women inside 310 | 1 | EA | 7 | 6-10 years | | |
| | Walls - Metal Panel | 3rd - Women inside 310 | 179 | SF | 7 | 10+ years | | |
| | Water Closet | 3rd - Women inside 310 | 1 | EA | 7 | 6-10 years | | |
| | Accessories | Basement - Unisex | 28 | SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | Basement - Unisex | 28 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | Basement - Unisex | 1 | EA | 7 | 10+ years | | |
| | Floor - Terrazzo | Basement - Unisex | 28 | SF | 7 | 10+ years | | |
| | Lavatory | Basement - Unisex | 1 | EA | 7 | 10+ years | | |
| | Lighting - Lay-in | Basement - Unisex | 1 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | Basement - Unisex | 168 | SF | 7 | 10+ years | | |
| | Water Closet | Basement - Unisex | 1 | EA | 7 | 6-10 years | | |
| | Accessories | Basement - inside Engineers Office | 78 | SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | Basement - inside Engineers Office | 78 | SF | 6 | 10+ years | | |
| | Doors - Steel Doors incl hw | Basement - inside Engineers Office | 2 | EA | 6 | 6-10 years | | |
| | Floor - Terrazzo | Basement - inside Engineers Office | 78 | SF | 6 | 10+ years | | |
| | Floor Drain | Basement - inside Engineers Office | 1 | EA | 7 | 6-10 years | | |
| | Lavatory | Basement - inside Engineers Office | 1 | EA | 6 | 6-10 years | | |
| | Lighting - Lay-in | Basement - inside Engineers Office | 1 | EA | 7 | 6-10 years | | |
| | Partitions | Basement - inside Engineers Office | 1 | EA | 7 | 6-10 years | | |
| | Showers | Basement - inside Engineers Office | 1 | EA | 5 | 1-2 years | Replace missing fixture | |
| | Urinals | Basement - inside Engineers Office | 1 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | Basement - inside Engineers Office | 292 | SF | 7 | 10+ years | | |
| | Water Closet | Basement - inside Engineers Office | 1 | EA | 7 | 6-10 years | | |

| Category | : | Classroom |
|----------|---|-----------|
|----------|---|-----------|

Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------|-----------------------------|-----------|----------|-----|------|--------------------------|---------------|
| Classroo | m #100 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 673 | SF | 7 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 673 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | |
| | Walls - Plaster/Drywall | 1st Floor | 810 | SF | 7 | 10+ years | |
| Classroo | m #1004 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 770 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 8 | SF | 5 | 1-2 years | Peeling paint |



| | | | P | uildina | Mair | 103. | 30 S Elizabeth STREET, Chicago, IL 60643 |
|----------|-----------------------------|-----------|---------------|---------|-----------|---------------------------|--|
| Catego | ry : Classroom | | В | uilding | : wain | Decommond | |
| Group | Item - Type | Location | Quantity | UOM | Bank | Recommend | Comments |
| Group | Doors - Steel Doors incl hw | 1st Floor | Quantity 1 | EA | Rank 6 | Replacement 6-10 years | Comments |
| | Floor - Tile | 1st Floor | 778 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 13 | | 6 | 6-10 years | |
| | Walls - Metal Panel | 1st Floor | 490 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 610 | SF | 7 | 10+ years | |
| Classroo | m #1005 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 570 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 18 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 6 | 2-5 years | |
| | Doors - Store Front | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 22 | SF | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 570 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 11 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 6 | 6-10 years | |
| | Walls - Metal Panel | 1st Floor | 985 | SF | 7 | 10+ years | |
| Classroo | m #101A (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 673 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 673 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 18 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 280 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 758 | SF | 7 | 10+ years | |
| Classroo | m #101B (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 785 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 785 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 15 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 16 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 562 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 563 | SF | 7 | 10+ years | |
| Classroo | m #103 (Laboratory/Shop) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,300 | SF | 7 | 6-10 years | |
| | Doors - Side-lite | 1st Floor | 62 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,300 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 35 | EA | 7 | 6-10 years | |
| | Walls - Metal Panel | 1st Floor | 1,823 | SF | 7 | 10+ years | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|---------|-----------------------------|-----------|----------|---------|--------|-------------|---------------|
| Ŭ | | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | | | | | | |
| lassroc | m #106 (Science) | | | | | | |
| | Casework | 1st Floor | 25 | LF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 1,170 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Eye Wash Station | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Floor - Tile | 1st Floor | 1,170 | SF | 7 | 10+ years | |
| | Gas Line | 1st Floor | 3 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 47 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 6 | 6-10 years | |
| | Science Lab Fume Hood | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Science Lab Shower | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 480 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 1,385 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 11 | EA | 7 | 6-10 years | |
| | | 13(1100) | | | ' | o io years | |
| lassroc | m #107A (Office) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 475 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 6 | LF | 4 | 2-5 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 475 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 20 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 395 | SF | 7 | 10+ years | |
| | Walls - Masonry | 1st Floor | 246 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st Floor | 246 | SF | 7 | 10+ years | |
| | | | 240 | 01 | , | for years | |
| lassroo | m #112 (Special Program) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 394 | SF | 6 | 10+ years | |
| | Ceiling - Splined | 1st Floor | 1,011 | SF | 6 | 10+ years | |
| | Ceiling - Splined | 1st Floor | 100 | SF | 4 | 1-2 years | Missing tiles |
| | Doors - Steel Doors incl hw | 1st Floor | 3 | EA | 6 | 10+ years | - |
| | Floor - Tile | 1st Floor | 1,505 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 2,498 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 398 | SF | 6 | 10+ years | |
| | " | | | | | | |
| lassroo | m #113 (Special Program) | | | | - | 0.40 | |
| | Casework | 1st Floor | 6 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 1,498 | SF | 7 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,498 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 13 | EA | 7 | 6-10 years | |



| Catego | ory : Classroom | | R | uilding | : Main | | 30 S Elizabeth STREET, Chicago, IL 60643 |
|----------|------------------------------------|-----------|----------|---------|--------|-------------|--|
| ouloge | | | | unung | . mann | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Pendent/Surface | 1st Floor | 11 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 1 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 610 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st Floor | 490 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 490 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | -30 | EA | 7 | 6-10 years | |
| | Work On K | 13(1100) | 2 | L/\ | , | o ro years | |
| Classroo | om #114A (Other Instructional Use) | | | | | | |
| | Casework | 1st Floor | 6 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 1,477 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 3 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 6 | SF | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,477 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 44 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 138 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 770 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st Floor | 770 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 160 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | WOR SINK | ISt FIOOI | 2 | EA | 1 | 0-10 years | |
| Classroo | om #115A (Office) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 850 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 50 | SF | 5 | 1-2 years | Replace tiles |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 36 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 6 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,214 | SF | 7 | 10+ years | |
| | | 13(1100) | 1,214 | 01 | ' | 10+ years | |
| Classroo | om #115B (Other Instructional Use) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 900 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 3 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 900 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 33 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 598 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 598 | SF | 7 | 10+ years | |
| | | | | | | | |
| Classroo | om #116A (Music Room) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 780 | SF | 7 | 10+ years | |
| | | | | | | | |



| atego | ry : Classroom | | В | uilding | | | |
|---------|------------------------------|-----------|----------|---------|------|-------------|--------------|
| | | | | | | Recommend | |
| iroup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Side-lite | 1st Floor | 36 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 7 | SF | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 780 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 33 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 160 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 580 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st Floor | 298 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 298 | SF | 7 | 10+ years | |
| lassroo | om #116B (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 650 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 4 | SF | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 650 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 27 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 160 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 12 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 600 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st Floor | 278 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 278 | SF | 7 | 10+ years | |
| | | | 210 | 0. | | ior youro | |
| assroc | om #117 (Special Program) | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,429 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 4 | EA | 6 | 6-10 years | |
| | Doors - Transom Window | 1st Floor | 3 | SF | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 1,429 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 53 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 1st Floor | 1 | EA | 6 | 0-1 year | Replace bulb |
| | Marker Board | 1st Floor | 12 | LF | 7 | 6-10 years | - |
| | Walls - Concrete Block | 1st Floor | 1,340 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st Floor | 220 | SF | 7 | 10+ years | |
| assroo | om #118 (Art Room) | | | | | | |
| | Casework | 1st Floor | 63 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 870 | SF | 6 | 6-10 years | |
| | Chalk Board | 1st Floor | 6 | LF | 4 | 2-5 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | | | | | | | |



| Catego | ry : Classroom | | B | uilding | : Main | | 30 S Elizabeth STREET, Chicago, IL 60643 |
|----------|-----------------------------|------------|----------|------------|--------|---|--|
| oulogo | | | | anang | · main | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Tile | 1st Floor | 870 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 6 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 49 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 902 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st Floor | 289 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 200 | EA | 7 | 6-10 years | |
| | | | E. | 2/1 | | e re yeare | |
| Classroo | om #119 (Regular Classroom) | | | | | | |
| | Casework | 1st Floor | 35 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor | 778 | SF | 6 | 6-10 years | |
| | Chalk Board | 1st Floor | 5 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 34 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 778 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 15 | EA | 7 | 6-10 years | |
| | Marker Board | 1st Floor | 5 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 42 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 870 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 1st Floor | 250 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 250 | EA | 7 | 6-10 years | |
| | WORKSIIK | TST FIOOI | 2 | LA | 1 | 0-10 years | |
| Classroo | om #120 (Store Room) | | | | | | |
| | Casework | 1st Floor | 48 | LF | 6 | 6-10 years | Unable to assess due to storage in |
| | | | | | | , | the room. Assessed per previous |
| | | | | | | | vear. |
| | Ceiling - Lay-in | 1st Floor | 778 | SF | 7 | 6-10 years | Unable to assess due to storage in |
| | | | | | - | - · · · · · · · · | the room. Assessed per previous |
| | | | | | | | year. |
| | Chalk Board | 1st Floor | 6 | LF | 4 | 2-5 years | Unable to assess due to storage in |
| | Shall Board | 13(1100) | 8 | L 1 | - | 2 0 yours | the room. Assessed per previous |
| | | | | | | | vear. |
| | Doors - Side-lite | 1st Floor | 45 | SF | 7 | 10+ years | Unable to assess due to storage in |
| | Doors - Side-lite | 13(1100) | 45 | 01 | ' | TOT years | the room. Assessed per previous |
| | | | | | | | • • |
| | Doors - Steel Doors incl hw | 1 at Elear | 1 | EA | 7 | 10, , , , , , , , , , , , , , , , , , , | year. |
| | Doors - Steel Doors Inclinw | 1st Floor | 1 | EA | 1 | 10+ years | Unable to assess due to storage in |
| | | | | | | | the room. Assessed per previous |
| | | | 45 | 05 | - | 10 | year. |
| | Doors - Transom Window | 1st Floor | 15 | SF | 7 | 10+ years | Unable to assess due to storage in |
| | | | | | | | the room. Assessed per previous |
| | | | | e – | _ | | year. |
| | Floor - Tile | 1st Floor | 778 | SF | 7 | 10+ years | Unable to assess due to storage in |
| | | | | | | | the room. Assessed per previous |
| | | | | | | | year. |
| | | | | | | | - |



Percy L Julian High School 10330 S Elizabeth STREET, Chicago, IL 60643

| 5 |
|---|
| assess due to storage in Assessed per previous |
| assess due to storage in Assessed per previous |
| assess due to storage in Assessed per previous |
| assess due to storage in Assessed per previous |
| assess due to storage in Assessed per previous |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| zing on side light |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments LF Marker Board 2nd Floor 9 6 6-10 years Walls - Concrete Block 2nd Floor 219 SF 6 10+ years Walls - Metal Panel 2nd Floor 560 SF 6 10+ years Classroom #204 (Regular Classroom) Ceiling - Lay-in 2nd Floor SF 6 759 10+ vears Doors - Side-lite 2nd Floor 10 SF 6 10+ years 2nd Floor Doors - Steel Doors incl hw 1 EΑ 6 10+ years SF Doors - Transom Window 2nd Floor 50 6 10+ years SF Floor - Tile/Sheet 2nd Floor 753 7 10+ years Floor - Tile/Sheet 2nd Floor SF 1-2 years 6 4 Rust damaged tiles Lighting - Lay-in 2nd Floor 15 ΕA 6 6-10 years Marker Board 2nd Floor 10 LF 6 6-10 years SF Walls - Concrete Block 2nd Floor 93 6 10+ years Walls - Metal Panel 2nd Floor 874 SF 6 10+ years Classroom #205 (Regular Classroom) Ceiling - Lav-in 2nd Floor 757 SF 6 10+ years Doors - Side-lite 2nd Floor SF 10 6 10+ years Doors - Steel Doors incl hw 2nd Floor FΑ 6 10+ years 1 SF Doors - Transom Window 2nd Floor 42 6 10+ years SF 7 Floor - Tile/Sheet 2nd Floor 757 10+ years Lighting - Lay-in 2nd Floor 14 EΑ 6 6-10 years Marker Board 2nd Floor 10 LF 6 6-10 years Walls - Concrete Block 2nd Floor 45 SF 6 10+ years Walls - Metal Panel 2nd Floor SF 965 6 10+ years Classroom #206 (Regular Classroom) Ceiling - Lay-in 2nd Floor 759 SF 6 10+ years Doors - Side-lite 2nd Floor SF 10 6 10+ years Doors - Steel Doors incl hw ΕA 6 2nd Floor 10+ years 1 SF Doors - Transom Window 2nd Floor 42 6 10+ years Floor - Tile/Sheet 2nd Floor 759 SF 7 10+ years Lighting - Lay-in 2nd Floor 14 EΑ 6 6-10 years LF Marker Board 2nd Floor 10 6 6-10 years SF Walls - Concrete Block 2nd Floor 88 6 10+ vears Walls - Metal Panel SF 2nd Floor 869 6 10+ years Classroom #207 (Regular Classroom) Ceiling - Lav-in 2nd Floor SF 759 6 10+ vears SF Doors - Side-lite 2nd Floor 10 6 10+ years Doors - Steel Doors incl hw 2nd Floor ΕA 6 10+ years 1 Doors - Transom Window SF 2nd Floor 42 6 10+ years



| Catego | ry : Classroom | | В | uilding | : Main | | 30 S Elizabeth STREET, Chicago, IL 60643 |
|----------|----------------------------------|-----------|----------|---------|--------|-------------|--|
| J | , | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| • | Floor - Tile/Sheet | 2nd Floor | 759 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 88 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 863 | SF | 6 | 10+ years | |
| 0 | | | | | | | |
| Classroo | om #208 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 757 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 757 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 88 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 863 | SF | 6 | 10+ years | |
| Classroo | om #209 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 757 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 42 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 757 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 88 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 875 | SF | 6 | 10+ years | |
| | | | | | | | |
| Classroo | om #210/211 (Multi Purpose Room) | | 00.4 | | | | |
| | Ceiling - Lay-in | 2nd Floor | 624 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 196 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 20 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 624 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 10 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 190 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 510 | SF | 6 | 10+ years | |
| Classroo | om #212 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 455 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | ĒA | 6 | 10+ years | |



| GroupItem - TypeLocationQuantityUOMRankReplayingDoors - Transom Window3rd Floor20SF610-Floor - Tile/Sheet3rd Floor455SF710-Lighting - Lay-in3rd Floor9EA66-1Marker Board3rd Floor14LF66-1Walls - Concrete Block3rd Floor52SF610-Walls - Metal Panel3rd Floor52SF610-Classroom #213 (Regular Classroom)Classroom #213 (Regular Classroom)ClassroomClassroomA floorA floorA floorA floor <td colspa<="" th=""><th><pre>pmmend acement Comments + years 0 years 0 years + years + years + years + years + years + years + years 0 years + years +</pre></th></td> | <th><pre>pmmend acement Comments + years 0 years 0 years + years + years + years + years + years + years + years 0 years + years +</pre></th> | <pre>pmmend acement Comments + years 0 years 0 years + years + years + years + years + years + years + years 0 years + years +</pre> |
|--|---|--|
| Doors - Transom Window3rd Floor20SF610-Floor - Tile/Sheet3rd Floor455SF710-Lighting - Lay-in3rd Floor9EA66-11Marker Board3rd Floor14LF66-11Walls - Concrete Block3rd Floor52SF610-Walls - Metal Panel3rd Floor52SF610-Classroom #213 (Regular Classroom)Classroom #213 (Regular Classroom)ClassroomClassroomDoors - Steel Doors incl hw2nd Floor439SF610LF6AMarker Board2nd Floor439SF610LF610LFA6AAAAAA< | + years + years 0 years 0 years + years + years + years + years + years 0 years 0 years 0 years + years | |
| Floor - Tile/Sheet3rd Floor455SF710-Lighting - Lay-in3rd Floor9EA66-11Marker Board3rd Floor14LF66-11Walls - Concrete Block3rd Floor52SF610-Walls - Metal Panel3rd Floor770SF610-Classroom #213 (Regular Classroom)Ceiling - Lay-in2nd Floor439SF610-Doors - Steel Doors incl hw2nd Floor1EA610-Floor - Tile/Sheet2nd Floor439SF710-Lighting - Lay-in2nd Floor8EA66-11Marker Board2nd Floor10LF66-11Walls - Metal Panel2nd Floor10LF66-11Warker Board2nd Floor10LF66-11Walls - Metal Panel2nd Floor10LF66-11Work Sink2nd Floor1EA76-11 | + years 0 years 0 years + years + years + years + years + years 0 years 0 years + years + years | |
| Lighting - Lay-in3rd Floor9EA66-10Marker Board3rd Floor14LF66-10Walls - Concrete Block3rd Floor52SF610Walls - Metal Panel3rd Floor770SF610Classroom/Classroom #213 (Regular Classroom)Ceiling - Lay-in2nd Floor439SF610Doors - Steel Doors incl hw2nd Floor1EA610Floor - Tile/Sheet2nd Floor439SF710Lighting - Lay-in2nd Floor8EA66-11Marker Board2nd Floor8EA66-11Walls - Metal Panel2nd Floor10LF66-11Walls - Metal Panel2nd Floor10LF66-11Work Sink2nd Floor1EA76-11 | 0 years 0 years + years + years + years + years + years 0 years 0 years + years + years | |
| Marker Board3rd Floor14LF66-10Walls - Concrete Block3rd Floor52SF610-Walls - Metal Panel3rd Floor770SF610-Classroom #213 (Regular Classroom)Ceiling - Lay-in2nd Floor439SF610-Doors - Steel Doors incl hw2nd Floor1EA610-Floor - Tile/Sheet2nd Floor439SF710-Lighting - Lay-in2nd Floor8EA66-11Marker Board2nd Floor10LF66-11Walls - Metal Panel2nd Floor10LF66-11Walls - Metal Panel2nd Floor10LF66-11Work Sink2nd Floor1EA76-11 | 0 years + years + years + years + years + years 0 years 0 years + years | |
| Walls - Concrete Block3rd Floor52SF610-Walls - Metal Panel3rd Floor770SF610-Classroom #213 (Regular Classroom)Ceiling - Lay-in2nd Floor439SF610-Doors - Steel Doors incl hw2nd Floor1EA610-Floor - Tile/Sheet2nd Floor439SF710-Lighting - Lay-in2nd Floor8EA66-11Marker Board2nd Floor10LF66-11Walls - Metal Panel2nd Floor894SF610-Work Sink2nd Floor1EA76-11 | + years + years + years + years + years 0 years 0 years + years | |
| Walls - Metal Panel3rd Floor770SF610-Classroom #213 (Regular Classroom)Ceiling - Lay-in2nd Floor439SF610-Doors - Steel Doors incl hw2nd Floor1EA610-Floor - Tile/Sheet2nd Floor439SF710-Lighting - Lay-in2nd Floor8EA66-11Marker Board2nd Floor10LF66-11Walls - Metal Panel2nd Floor894SF610-Work Sink2nd Floor1EA76-11 | + years + years + years + years 0 years 0 years + years + years | |
| Classroom #213 (Regular Classroom)Ceiling - Lay-in2nd Floor439SF610-Doors - Steel Doors incl hw2nd Floor1EA610-Floor - Tile/Sheet2nd Floor439SF710-Lighting - Lay-in2nd Floor8EA66-11Marker Board2nd Floor10LF66-11Walls - Metal Panel2nd Floor894SF610-Work Sink2nd Floor1EA76-11 | + years + years + years 0 years 0 years + years | |
| Ceiling - Lay-in2nd Floor439SF610-Doors - Steel Doors incl hw2nd Floor1EA610-Floor - Tile/Sheet2nd Floor439SF710-Lighting - Lay-in2nd Floor8EA66-11Marker Board2nd Floor10LF66-11Walls - Metal Panel2nd Floor894SF610-Work Sink2nd Floor1EA76-11 | + years + years 0 years 0 years + years | |
| Doors - Steel Doors incl hw2nd Floor1EA610-Floor - Tile/Sheet2nd Floor439SF710-Lighting - Lay-in2nd Floor8EA66-1Marker Board2nd Floor10LF66-1Walls - Metal Panel2nd Floor894SF610-Work Sink2nd Floor1EA76-1 | + years + years 0 years 0 years + years | |
| Doors - Steel Doors incl hw2nd Floor1EA610-Floor - Tile/Sheet2nd Floor439SF710-Lighting - Lay-in2nd Floor8EA66-1Marker Board2nd Floor10LF66-1Walls - Metal Panel2nd Floor894SF610-Work Sink2nd Floor1EA76-1 | + years + years 0 years 0 years + years | |
| Floor - Tile/Sheet2nd Floor439SF710-Lighting - Lay-in2nd Floor8EA66-10Marker Board2nd Floor10LF66-10Walls - Metal Panel2nd Floor894SF610-Work Sink2nd Floor1EA76-10 | + years 0 years 0 years + years | |
| Lighting - Lay-in2nd Floor8EA66-10Marker Board2nd Floor10LF66-10Walls - Metal Panel2nd Floor894SF610-10Work Sink2nd Floor1EA76-10 | 0 years 0 years + years | |
| Marker Board2nd Floor10LF66-10Walls - Metal Panel2nd Floor894SF610-Work Sink2nd Floor1EA76-10 | 0 years + years | |
| Walls - Metal Panel2nd Floor894SF610-Work Sink2nd Floor1EA76-1 | + years | |
| Work Sink2nd Floor1EA76-10 | 5 | |
| Classroom #214 (Computer Lab) | 0 years | |
| | | |
| | 5 years | |
| | + years | |
| | 0 years | |
| | 0 years | |
| | + years | |
| | + years | |
| Classroom #215 (Computer Lab) | | |
| | 5 years | |
| | + years | |
| | + years | |
| | + years | |
| | 0 years | |
| | 0 years | |
| | + years | |
| | + years | |
| | 0 years | |
| Classroom #216 (Regular Classroom) | | |
| | + years | |
| | 5 years | |
| | + years | |
| Doors - Steel Doors incl hw 2nd Floor 1 EA 6 10- | | |



| Catego | ry : Classroom | | R | uilding | • Main | | 30 S Elizabeth STREET, Chicago, IL 60643 |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|--|
| Jacyo | | | | anung | . mant | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| 0.000 | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 441 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 9 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 11 | LF | 6 | 6-10 years | |
| | Walls - Metal Panel | 2nd Floor | 892 | SF | 6 | 10+ years | |
| Classroo | om #217 (Computer Lab) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,360 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 1,360 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 2 | EA | 6 | 1-2 years | Not working |
| | Lighting - Lay-in | 2nd Floor | 28 | EA | 6 | 6-10 years | 5 |
| | Storage/ Closet | 2nd Floor | 133 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 540 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 792 | SF | 6 | 10+ years | |
| Classroo | om #218 (Computer Lab) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,257 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 1,257 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 24 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 9 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 113 | SF | 5 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 409 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 845 | SF | 6 | 10+ years | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | 2-5 years | |
| Classroo | om #219 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 902 | SF | 6 | 2-5 years | |
| | Doors - Steel Doors incl hw | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 902 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 17 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 1 | EA | 6 | 1-2 years | Light out in storage closet |
| | Marker Board | 2nd Floor | 15 | LF | 6 | 6-10 years | - |
| | Storage/ Closet | 2nd Floor | 110 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 2 | SF | 6 | 1-2 years | Cracks in block |
| | Walls - Concrete Block | 2nd Floor | 110 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 1,026 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 5 | 1-2 years | No water, may have been drained for repair |

Classroom #220 (Computer Lab)



| Catego | ry : Classroom | | R | uilding | : Main | | 30 S Elizabeth STREET, Chicago, IL 60 |
|---------|------------------------------|-----------|----------|---------|--------|-------------|---------------------------------------|
| Jaicgo | | | | unung | . mani | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | 2nd Floor | 754 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 10 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 754 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 15 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 112 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 810 | SF | 6 | 10+ years | |
| | Wireless System | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| lassroo | m #221 (Computer Lab) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,168 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | ĒA | 6 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 1,168 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 23 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 71 | SF | 5 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 481 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 853 | SF | 6 | 10+ years | |
| lassroo | m #240 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,276 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 14 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 20 | SF | 6 | 10+ years | |
| | Doors - Store Front | 2nd Floor | 2 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 2nd Floor | 92 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 1,276 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | · 1 | EA | 6 | 1-2 years | Not working |
| | Lighting - Lay-in | 2nd Floor | 25 | EA | 6 | 6-10 years | 3 |
| | Marker Board | 2nd Floor | 14 | LF | 6 | 6-10 years | |
| | Walls - Metal Panel | 2nd Floor | 741 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 436 | SF | 5 | 1-2 years | Wall need patch and paint repair |
| assroo | m #242 (Science Lab Level 1) | | | | | | |
| | Casework | 2nd Floor | 73 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 2nd Floor | 1,329 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Eye Wash Station | 2nd Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile/Sheet | 2nd Floor | 1,329 | SF | 7 | 10+ years | |
| | Gas Line | 2nd Floor | 7 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 9 | LF | 6 | 6-10 years | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|---------------|
| | , | | | J | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| - | Science Lab Fume Hood | 2nd Floor | 1 | EA | 6 | 2-5 years | |
| | Science Lab Shower | 2nd Floor | 1 | EA | 7 | 2-5 years | |
| | Walls - Plaster/Drywall | 2nd Floor | 1,055 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 10 | ĒA | 7 | 6-10 years | |
| Classroo | m #302 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 500 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 253 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | ĒA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 34 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 746 | SF | 7 | 6-10 years | |
| | Floor - Tile/Sheet | 3rd Floor | 7 | SF | 4 | 1-2 years | Damaged tiles |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 6-10 years | Damagea mee |
| | Marker Board | 3rd Floor | 10 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 88 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 865 | SF | 6 | 10+ years | |
| | | | 000 | 01 | 0 | TOF years | |
| Classroo | m #303 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 795 | SF | 7 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 5 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 795 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 16 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 14 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 205 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 557 | SF | 6 | 10+ years | |
| Classroo | m #304 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 757 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | ĒA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 50 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 757 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 15 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 12 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 88 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 866 | SF | 6 | 10+ years | |
| Classroo | m #305 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 753 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 10 | SF | 6 | 10+ years | |



| | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|--------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 753 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 14 | ĒA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 88 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 865 | SF | 6 | 10+ years | |
| Classroc | om #306 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 755 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 755 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 88 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 859 | SF | 6 | 10+ years | |
| | | | | | | , | |
| Classroc | om #307 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 8 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 745 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 752 | SF | 7 | 6-10 years | |
| | Floor - Tile/Sheet | 3rd Floor | 1 | SF | 4 | 1-2 years | Damaged tile |
| | Lighting - Lay-in | 3rd Floor | 14 | EA | 7 | 6-10 years | 0 |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 88 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 863 | SF | 6 | 10+ years | |
| Classroc | om #308 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 755 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 755 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 6 | 6-10 years | |
| | | | | | | | |
| | Walls - Concrete Block | 3rd Floor | 88 | SF | 6 | 10+ years | |



| y : Classroom Item - Type | | | uilding | | | |
|---------------------------------|---|---|--|---|--|---|
| Item - Type | | | | | Recommend | |
| | Location | Quantity | UOM | Rank | Replacement | Comments |
| m #309 (Regular Classroom) | | | | | | |
| Ceiling - Lay-in | 3rd Floor | 8 | SF | 7 | 10+ years | |
| Ceiling - Lay-in | 3rd Floor | 745 | SF | 6 | 10+ years | |
| | 3rd Floor | 10 | | 6 | | |
| Doors - Steel Doors incl hw | 3rd Floor | 1 | | 6 | | |
| Doors - Transom Window | 3rd Floor | 42 | | 6 | | |
| Floor - Tile/Sheet | 3rd Floor | | | 5 | | |
| | | 14 | EA | | | |
| | | 10 | LF | | | |
| | | | | | • | |
| Walls - Metal Panel | 3rd Floor | 858 | SF | 6 | 10+ years | |
| m #310. 311 (Special Education) | | | | | | |
| Casework | 3rd Floor | 12 | LF | 4 | 1-2 years | Cabinets in deteriorating condition |
| | | | | | | |
| Doors - Steel Doors incl hw | | | | | - | |
| | | | | | | |
| | | | | | , | |
| | | | | | • | |
| | | | | | | |
| | | | | | | |
| | | | | - | | |
| Work Sink | 3rd Floor | 1 | ËA | 4 | 1-2 years | Not operational |
| m #312 (Regular Classroom) | | | | | | |
| | 3rd Floor | 391 | SF | 6 | 10+ vears | |
| | | | | | | Missing tile |
| | | | | | | ineenig ne |
| | | - | | | | |
| | | | | | | |
| | | | | | | |
| | | | | - | • | |
| Walls - Metal Panel | 3rd Floor | 424 | SF | 6 | 10+ years | |
| m #313 (Science) | | | | | | |
| | 3rd Floor | 602 | SF | 6 | 10+ vears | |
| | | | | | • | |
| | | | | | , | |
| | | | | | | |
| | | | | | | |
| | | | | - | | |
| Walls - Metal Panel | 3rd Floor | 305 | SF | 6 | 10+ years | |
| Work Sink | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile/Sheet Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Metal Panel m #310, 311 (Special Education) Casework Ceiling - Lay-in Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile/Sheet Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Metal Panel Work Sink m #312 (Regular Classroom) Ceiling - Lay-in Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Concrete Block Walls - Steel Doors incl hw Floor - Tile/Sheet Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Metal Panel m #313 (Science) Ceiling - Lay-in Doors - Steel Doors incl hw Floor - Tile/Sheet Lighting - Lay-in Marker Board Walls - Concrete Block Walls - Metal Panel | Doors - Side-lite3rd FloorDoors - Steel Doors incl hw3rd FloorFloor - Tile/Sheet3rd FloorFloor - Tile/Sheet3rd FloorWalls - Concrete Block3rd FloorWalls - Metal Panel3rd Floorm#310, 311 (Special Education)3rd FloorCasework3rd FloorCasework3rd FloorDoors - Transom Window3rd Floorm#310, 311 (Special Education)3rd FloorCasework3rd FloorCasework3rd FloorDoors - Steel Doors incl hw3rd FloorDoors - Tile/Sheet3rd FloorLighting - Lay-in3rd FloorMarker Board3rd FloorWalls - Concrete Block3rd FloorWalls - Concrete Block3rd FloorWalls - Concrete Block3rd FloorWalls - Concrete Block3rd FloorWalls - Metal Panel3rd FloorWalls - Metal Panel3rd FloorWork Sink3rd FloorMarker Board3rd FloorWalls - Concrete Block3rd FloorMarker Board3rd Floor | Doors - Side-life 3rd Floor 10 Doors - Steel Doors incl hw 3rd Floor 1 Doors - Transom Window 3rd Floor 42 Floor - Tile/Sheet 3rd Floor 753 Lighting - Lay-in 3rd Floor 14 Marker Board 3rd Floor 10 Walls - Concrete Block 3rd Floor 88 m #310, 311 (Special Education) 7 7 Casework 3rd Floor 12 Ceiling - Lay-in 3rd Floor 12 Coors - Transom Window 3rd Floor 12 Doors - Steel Doors incl hw 3rd Floor 12 Doors - Transom Window 3rd Floor 14 Jighting - Lay-in 3rd Floor 17 Marker Board 3rd Floor 6 Walls - Concrete Block 3rd Floor 16 Walls - Metal Panel 3rd Floor 17 Walls - Metal Panel 3rd Floor 16 Doors - Steel Doors incl hw 3rd Floor 16 Doors - Steel Doors incl hw 3rd Floor | Doors - Side-lite 3rd Floor 10 SF Doors - Steel Doors incl hw 3rd Floor 1 EA Doors - Tile/Sheet 3rd Floor 42 SF Lighting - Lay-in 3rd Floor 14 EA Warker Board 3rd Floor 10 LF Walls - Concrete Block 3rd Floor 10 LF Walls - Metal Panel 3rd Floor 88 SF m#310, 311 (Special Education) C 2 LF Ceiling - Lay-in 3rd Floor 12 LF Ceiling - Lay-in 3rd Floor 2 EA Doors - Steel Doors incl hw 3rd Floor 2 EA Doors - Transom Window 3rd Floor 2 EA Doors - Transom Window 3rd Floor 4 SF Doors - Transom Window 3rd Floor 17 EA Marker Board 3rd Floor 17 EA Marker Board 3rd Floor 17 EA Marker Board 3rd Floor 187 </td <td>Doors - Side-lite 3rd Floor 10 SF 6 Doors - Steel Doors incl hw 3rd Floor 1 EA 6 Doors - Transom Window 3rd Floor 753 SF 5 Lighting - Lay-in 3rd Floor 14 EA 6 Walts - Concrete Block 3rd Floor 10 LF 6 Walts - Metal Panel 3rd Floor 12 LF 4 Casework 3rd Floor 2 EA 6 Doors - Steel Doors incl hw 3rd Floor 2 EA 6 Doors - Steel Doors incl hw 3rd Floor 2 EA 6 Doors - Transom Window 3rd Floor 17 EA 6 Doors - Transom Window 3rd Floor 17 EA 6 Walts - Concrete Block 3rd Floor 17 EA 6 Walts - Concrete Block 3rd Floor 187 SF 6 Walts - Concrete Block 3rd Floor 187 SF 6 Walts</td> <td>Doors - Side-life 3rd Floor 10 SF 6 6-10 years Doors - Steel Doors incl hw 3rd Floor 42 SF 6 6-10 years Floor - TiarSom Window 3rd Floor 42 SF 6 6-10 years Floor - TiarSom Window 3rd Floor 42 SF 6 6-10 years Marker Board 3rd Floor 14 EA 6 6-10 years Marker Board 3rd Floor 10 LF 6 6-10 years Walls - Concrete Block 3rd Floor 12 LF 4 1-2 years m#310.311 (Special Education) 2 EA 6 10+ years Doors - Steel Doors inch w 3rd Floor 2 EA 10+ years Doors - Transom Window 3rd Floor 12 LF 4 1-2 years Doors - Steel Doors inch w 3rd Floor 12 LF 4 1-2 years Marker Board 3rd Floor 16 F 6 10+ years Vark Sink</td> | Doors - Side-lite 3rd Floor 10 SF 6 Doors - Steel Doors incl hw 3rd Floor 1 EA 6 Doors - Transom Window 3rd Floor 753 SF 5 Lighting - Lay-in 3rd Floor 14 EA 6 Walts - Concrete Block 3rd Floor 10 LF 6 Walts - Metal Panel 3rd Floor 12 LF 4 Casework 3rd Floor 2 EA 6 Doors - Steel Doors incl hw 3rd Floor 2 EA 6 Doors - Steel Doors incl hw 3rd Floor 2 EA 6 Doors - Transom Window 3rd Floor 17 EA 6 Doors - Transom Window 3rd Floor 17 EA 6 Walts - Concrete Block 3rd Floor 17 EA 6 Walts - Concrete Block 3rd Floor 187 SF 6 Walts - Concrete Block 3rd Floor 187 SF 6 Walts | Doors - Side-life 3rd Floor 10 SF 6 6-10 years Doors - Steel Doors incl hw 3rd Floor 42 SF 6 6-10 years Floor - TiarSom Window 3rd Floor 42 SF 6 6-10 years Floor - TiarSom Window 3rd Floor 42 SF 6 6-10 years Marker Board 3rd Floor 14 EA 6 6-10 years Marker Board 3rd Floor 10 LF 6 6-10 years Walls - Concrete Block 3rd Floor 12 LF 4 1-2 years m#310.311 (Special Education) 2 EA 6 10+ years Doors - Steel Doors inch w 3rd Floor 2 EA 10+ years Doors - Transom Window 3rd Floor 12 LF 4 1-2 years Doors - Steel Doors inch w 3rd Floor 12 LF 4 1-2 years Marker Board 3rd Floor 16 F 6 10+ years Vark Sink |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Neeeroo | om #314A (Science) | | | | | | |
| 1455100 | Casework | 3rd Floor | 76 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 3rd Floor | 1,209 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 2 | EA | 6 | 10+ years | |
| | Eye Wash Station | 3rd Floor | 2 | EA | 6 | 6-10 years | |
| | Floor - Tile/Sheet | 3rd Floor | | SF | 7 | | |
| | | | 1,209 | | - | 10+ years | |
| | Gas Line | 3rd Floor | 4 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 47 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 6 | LF | 6 | 6-10 years | |
| | Science Lab Fume Hood | 3rd Floor | 1 | EA | 6 | 2-5 years | |
| | Science Lab Shower | 3rd Floor | 1 | EA | 5 | 6-10 years | |
| | Storage/ Closet | 3rd Floor | 359 | SF | 5 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 539 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 608 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 4 | EA | 5 | 6-10 years | |
| | | | | | | | |
| lassroc | m #315 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 485 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 76 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 485 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 10 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 444 | SF | 6 | 2-5 years | |
| | Walls - Metal Panel | 3rd Floor | 444 | SF | 6 | 2-5 years | |
| | | | | 01 | 0 | 2-5 years | |
| Classroo | om #316 (Science) | | | | | | |
| | Casework | 3rd Floor | 76 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 3rd Floor | 1,200 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 2 | EA | 6 | 10+ years | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile/Sheet | 3rd Floor | 1,200 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 48 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 20 | LF | 7 | 10+ years | |
| | Science Lab Fume Hood | 3rd Floor | 20 | EA | 6 | 6-10 years | |
| | | | • | | | | |
| | Science Lab Shower | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 472 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 792 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 5 | EA | 7 | 6-10 years | |

_Classroom #317 (Regular Classroom)



| Catego | ry : Classroom | | B | uilding | : Main | | |
|----------|-------------------------------|-----------|------------|---------|--------|-------------|-----------------------|
| Ŭ | · | | | Ŭ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Lay-in | 3rd Floor | 473 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 8 | SF | 5 | 1-2 years | Missing tiles |
| | Doors - Steel Doors incl hw | 3rd Floor | 2 | EA | 6 | 10+ years | • |
| | Floor - Tile/Sheet | 3rd Floor | 481 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 9 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 20 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 626 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 290 | SF | 6 | 10+ years | |
| Classroo | om #318 (Science) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 594 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 8 | SF | 5 | 1-2 years | Missing tile |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 602 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 38 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 843 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 2 | EA | 5 | 6-10 years | |
| Classroo | om #319 (Science Lab Level 3) | | | | | | |
| | Casework | 3rd Floor | 92 | LF | 6 | 6-10 years | |
| | Ceiling - Lay-in | 3rd Floor | 1,209 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | , 1 | ĒA | 6 | 10+ years | |
| | Eye Wash Station | 3rd Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile/Sheet | 3rd Floor | 1,209 | SF | 7 | 10+ years | |
| | Gas Line | 3rd Floor | , 1 | EA | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 48 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 6 | LF | 6 | 6-10 years | |
| | Science Lab Fume Hood | 3rd Floor | 1 | EA | 6 | 2-5 years | |
| | Science Lab Shower | 3rd Floor | 1 | EA | 7 | 2-5 years | |
| | Walls - Concrete Block | 3rd Floor | 392 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 712 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 2 | EA | 5 | 6-10 years | |
| Classroo | om #320 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 428 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 420 | SF | 4 | 0-1 year | Missing Tile |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 8 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 436 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 430 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 298 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 298 590 | SF | 6 | | |
| | | 3rd Floor | 590 | SF | 6 4 | 10+ years | Missing base to fleer |
| | Walls - Metal Panel | 310 F100f | 1 | 35 | 4 | 1-2 years | Missing base to floor |



Category : Classroom

Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Classroom #322 (Special Education) Casework 3rd Floor 11 LF 4 1-2 years Cabinets damaged and losing integrity 3rd Floor 523 SF 6 Ceiling - Lav-in 10+ years Doors - Steel Doors incl hw FΑ 3rd Floor 6 10+ years 1 Floor - Tile/Sheet 3rd Floor 523 SF 5 2-5 years Lighting - Lay-in 3rd Floor 11 EΑ 6 6-10 years LF Marker Board 3rd Floor 9 6 6-10 years SF Walls - Concrete Block 3rd Floor 145 6 10+ years Walls - Metal Panel SF 6 3rd Floor 465 10+ years Work Sink 3rd Floor 1 EA 5 2-5 years Classroom #323 (Regular Classroom) Ceiling - Lay-in 3rd Floor SF 752 6 10+ years Doors - Side-lite 3rd Floor 10 SF 6 10+ years Doors - Steel Doors incl hw 6 3rd Floor 1 EA 10+ years Doors - Transom Window 42 SF 6 3rd Floor 10+ years SF Floor - Tile 3rd Floor 752 6 10+ years Lighting - Lay-in 3rd Floor 15 FΑ 6 6-10 years Marker Board LF 3rd Floor 10 6 6-10 years SF Walls - Concrete Block 3rd Floor 87 6 10+ years SF Walls - Metal Panel 3rd Floor 862 6 10+ years Classroom #324 (Regular Classroom) SF Ceiling - Lay-in 3rd Floor 749 6 10+ years Ceiling - Lay-in 3rd Floor SF 8 5 1-2 vears Missing tile Doors - Side-lite SF 3rd Floor 10 6 10+ years Doors - Steel Doors incl hw 3rd Floor 1 ΕA 6 10+ years Doors - Transom Window 42 SF 6 3rd Floor 10+ years SF 7 10+ years Floor - Tile/Sheet 3rd Floor 757 Lighting - Lay-in 3rd Floor 14 EΑ 6 6-10 years Marker Board 3rd Floor 10 LF 6 6-10 years SF Walls - Concrete Block 3rd Floor 88 6 10+ years SF Walls - Metal Panel 3rd Floor 867 6 10+ years Classroom #325 (Regular Classroom) SF Ceiling - Lay-in 3rd Floor 757 6 10+ vears Doors - Side-lite 3rd Floor SF 6 10+ years 10 Doors - Steel Doors incl hw 3rd Floor ΕA 1 6 10+ vears SF Doors - Transom Window 3rd Floor 42 6 10+ years Floor - Tile/Sheet 3rd Floor 757 SF 7 10+ years Lighting - Lay-in 3rd Floor 15 EA 6 6-10 years

Building : Main



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|-----------------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Marker Board | 3rd Floor | 10 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 88 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 862 | SF | 6 | 10+ years | |
| | | | | | | | |
| Classroo | om #326 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 757 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 757 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 88 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 869 | SF | 6 | 10+ years | |
| | | | | | | | |
| Classroo | om #327 (Regular Classroom) | | 750 | 05 | • | 40 | |
| | Ceiling - Lay-in | 3rd Floor | 753 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 753 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 88 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 855 | SF | 6 | 10+ years | |
| Classroo | om #328 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 755 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 42 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 755 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 88 | SF | 6 | 10+ years | |
| | | | | SF | | • | |
| | Walls - Metal Panel | 3rd Floor | 862 | 55 | 6 | 10+ years | |
| Classroo | om #329 (Regular Classroom) | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 770 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 8 | SF | 5 | 1-2 years | Missing tile |
| | Doors - Side-lite | 3rd Floor | 10 | SF | 4 | 1-2 years | Damaged glazing |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | ĒA | 6 | 10+ years | 00 |
| | Doors - Transom Window | 3rd Floor | 10 | SF | 6 | 10+ years | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|-----------------|---|--|---|--|---|---|---------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Tile | 3rd Floor | 778 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 15 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 15 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 212 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 564 | SF | 6 | 10+ years | |
| Classroo | m #330 (Regular Classroom) | | | | | | |
| 0.000.00 | Ceiling - Lay-in | 3rd Floor | 742 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 8 | SF | 5 | 1-2 years | Missing tile, may be from repair work |
| | | | | | | | above ceiling |
| | Doors - Side-lite | 3rd Floor | 10 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 34 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 747 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 3 | SF | 4 | 1-2 years | Broken tiles |
| | Lighting - Lay-in | 3rd Floor | 15 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 88 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 832 | SF | 6 | 10+ years | |
| | | | | | | | Datab and paint domaged wells |
| | Walls - Plaster/Drywall | 3rd Floor | 30 | SF | 6 | 1-2 years | Patch and paint damaged walls |
| Catego | Walls - Plaster/Drywall ry : Interior | 3rd Floor | | | - | 1-2 years | Patch and paint damaged wans |
| Catego | · | 3rd Floor | | S⊦ uilding | - | Recommend | Paten and paint damaged waits |
| Catego Group | · | 3rd Floor Location | | | - | · | Comments |
| Group | ry : Interior | | В | uilding | : Main | Recommend | · |
| | ry : Interior Item - Type | Location | B Quantity | uilding UOM | : Main Rank | Recommend Replacement | · |
| Group | ry : Interior Item - Type Ceiling - Lay-in | Location 1st Floor | B Quantity 7,378 | uilding UOM SF | : Main Rank 7 | Recommend Replacement | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall | Location 1st Floor 1st Floor | B Quantity 7,378 1,160 | UOM SF SF | : Main Rank 7 7 | Recommend Replacement 10+ years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined | Location 1st Floor 1st Floor 1st Floor 1st Floor | B Quantity 7,378 1,160 11,379 | uilding UOM SF SF SF | : Main Rank 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite | Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor | B Quantity 7,378 1,160 11,379 544 | UOM SF SF SF SF SF SF | : Main Rank 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Store Front | Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor | B Quantity 7,378 1,160 11,379 544 17 | UOM SF SF SF SF SF EA | : Main Rank 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Store Front Doors - Transom Window | Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor | B Quantity 7,378 1,160 11,379 544 17 180 | UOM SF SF SF SF EA SF SF | * Main Rank 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain | Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor | B Quantity 7,378 1,160 11,379 544 17 180 7 | UOM SF SF SF SF EA SF EA SF EA | * Main Rank 7 7 7 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Side-lite Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo | Location 1st Floor 1st Floor | B Quantity 7,378 1,160 11,379 544 17 180 7 20,597 | UOM SF SF SF SF EA SF EA SF EA SF | * Main Rank 7 7 7 7 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Side-lite Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in | Location 1st Floor 1st Floor | B Quantity 7,378 1,160 11,379 544 17 180 7 20,597 415 | UOM SF SF SF SF EA SF EA SF EA SF EA | * Main Rank 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier | Location 1st Floor 1st Floor | B Quantity 7,378 1,160 11,379 544 17 180 7 20,597 415 106 | UOM UOM SF SF SF EA SF EA SF EA SF EA EA EA | * Main Rank 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Student Lockers - Two Tiers | Location 1st Floor 1st Floor | B Quantity 7,378 1,160 11,379 544 17 180 7 20,597 415 106 320 | UOM SF SF SF EA SF EA SF EA SF EA EA EA EA | : Main Rank 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Student Lockers - Two Tiers Walls - Masonry | Location 1st Floor 1st Floor | B Quantity 7,378 1,160 11,379 544 17 180 7 20,597 415 106 320 8,364 | UOM SF SF SF EA SF EA SF EA SF EA SF EA SF EA SF SF | : Main Rank 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Student Lockers - Two Tiers Walls - Masonry Walls - Metal Panel | Location 1st Floor 1st Floor | B Quantity 7,378 1,160 11,379 544 17 180 7 20,597 415 106 320 8,364 5,372 | UOM UOM SF SF SF EA SF EA SF EA SF EA SF EA SF SF SF | : Main Rank 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Student Lockers - Two Tiers Walls - Masonry Walls - Metal Panel Walls - Plaster/Drywall | Location 1st Floor 1st Floor | B Quantity 7,378 1,160 11,379 544 17 180 7 20,597 415 106 320 8,364 5,372 9,076 | UOM UOM SF SF SF EA SF EA SF EA SF EA SF SF SF SF | : Main Rank 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Student Lockers - Two Tiers Walls - Masonry Walls - Metal Panel Walls - Plaster/Drywall Ceiling - Lay-in | Location 1st Floor 1st Floor 2nd Floor | B Quantity 7,378 1,160 11,379 544 17 180 7 20,597 415 106 320 8,364 5,372 9,076 8,572 | UOM UOM SF SF SF EA SF EA SF EA SF EA SF SF SF SF SF | : Main Rank 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Student Lockers - Two Tiers Walls - Masonry Walls - Metal Panel Walls - Plaster/Drywall Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall | Location 1st Floor 1st Floor 2nd Floor 2nd Floor | B Quantity 7,378 1,160 11,379 544 17 180 7 20,597 415 106 320 8,364 5,372 9,076 8,572 1,348 | UOM UOM SF SF SF SF EA SF EA SF EA SF EA SF SF SF SF SF | : Main Rank 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Student Lockers - One Tier Student Lockers - Two Tiers Walls - Masonry Walls - Metal Panel Walls - Plaster/Drywall Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall Doors - Side-lite | Location 1st Floor 1st Floor 2nd Floor 2nd Floor 2nd Floor | B Quantity 7,378 1,160 11,379 544 17 180 7 20,597 415 106 320 8,364 5,372 9,076 8,572 9,076 8,572 1,348 148 | UOM SF SF SF SF EA SF EA SF EA SF EA SF SF SF SF SF SF | : Main Rank 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years | |
| Group | ry : Interior Item - Type Ceiling - Lay-in Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Store Front Doors - Transom Window Drinking Fountains - Single Fountain Floor - Terrazzo Lighting - Lay-in Student Lockers - One Tier Student Lockers - Two Tiers Walls - Masonry Walls - Metal Panel Walls - Plaster/Drywall Ceiling - Lay-in Ceiling - Lay-in Ceiling - Plaster/Drywall | Location 1st Floor 1st Floor 2nd Floor 2nd Floor | B Quantity 7,378 1,160 11,379 544 17 180 7 20,597 415 106 320 8,364 5,372 9,076 8,572 1,348 | UOM UOM SF SF SF SF EA SF EA SF EA SF EA SF SF SF SF SF | : Main Rank 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 | Recommend Replacement 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 10+ years | |



| Catego | ry : Interior | | В | uilding | : Main | | |
|--------|--------------------------------------|-----------|----------|---------|--------|-------------|-------------------------|
| | | | _ | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Drinking Fountains - Double Fountain | 2nd Floor | 1 | EA | 5 | 1-2 years | Not working |
| | Drinking Fountains - Single Fountain | 2nd Floor | 5 | EA | 7 | 6-10 years | - |
| | Floor - Terrazzo | 2nd Floor | 728 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 9,192 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 1 | EA | 6 | 1-2 years | Not working |
| | Lighting - Lay-in | 2nd Floor | 315 | EA | 6 | 6-10 years | - |
| | Student Lockers - One Tier | 2nd Floor | 349 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 1,982 | SF | 6 | 10+ years | |
| | Walls - Masonry | 2nd Floor | 360 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 6,862 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 200 | SF | 6 | 2-5 years | Patch and paint |
| | Ceiling - Lay-in | 3rd Floor | 11,418 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 16 | SF | 5 | 1-2 years | Missing/ damaged tiles |
| | Ceiling - Plaster/Drywall | 3rd Floor | 1,143 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 3rd Floor | 168 | SF | 6 | 10+ years | |
| | Doors - Store Front | 3rd Floor | 8 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 3rd Floor | 72 | SF | 6 | 10+ years | |
| | Drinking Fountains - Single Fountain | 3rd Floor | 3 | EA | 7 | 6-10 years | |
| | Drinking Fountains - Single Fountain | 3rd Floor | 5 | EA | 5 | 1-2 years | Not operating properly |
| | Floor - Terrazzo | 3rd Floor | 728 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 11,833 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 3rd Floor | 284 | EA | 6 | 6-10 years | |
| | Student Lockers - One Tier | 3rd Floor | 510 | EA | 6 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 2,351 | SF | 6 | 10+ years | |
| | Walls - Masonry | 3rd Floor | 350 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 10,400 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 800 | SF | 6 | 10+ years | |
| | Ceiling - Exposed | Basement | 1,770 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | Basement | 750 | SF | 6 | 10+ years | |
| | Ceiling - Splined | Basement | 957 | SF | 4 | 1-2 years | Missing tile throughout |
| | Doors - Steel Doors incl hw | Basement | 7 | EA | 6 | 6-10 years | |
| | Drinking Fountains - Single Fountain | Basement | 1 | EA | 7 | 2-5 years | |
| | Floor - Terrazzo | Basement | 1,050 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | Basement | 2,615 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Basement | 49 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | Basement | 5,046 | SF | 7 | 10+ years | |
| | Walls - Masonry | Basement | 1,883 | SF | 7 | 10+ years | |
| | | | | | | | |
| Safety | | | | | | | |
| | Camera Viewing Station | 1st Floor | 4 | EA | 7 | 6-10 years | |
| | Metal Detector | 1st Floor | 3 | EA | 7 | 6-10 years | |
| | Security Cameras | 1st Floor | 3 | EA | 7 | 6-10 years | |
| | Security Cameras | 1st Floor | 29 | EA | 7 | 6-10 years | |
| | | | | | | | |



| ategoi | ry : Interior | | В | uilding | : Main | | |
|---------|-------------------------------|--------------------------------|----------|---------|--------|-------------|-------------------------------|
| _ | - | | | _ | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| tairs | | | | | | | |
| | Floor - Terrazzo | Center stair - 1st to Basement | 86 | SF | 7 | 10+ years | |
| | Handrails | Center stair - 1st to Basement | 77 | LF | 7 | 10+ years | |
| | Stairs - Terrazzo | Center stair - 1st to Basement | 24 | LF | 7 | 10+ years | |
| | Walls - Masonry | Center stair - 1st to Basement | 118 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | North East | 424 | SF | 6 | 10+ years | |
| | Floor - Terrazzo | North East | 184 | SF | 6 | 10+ years | |
| | Handrails | North East | 117 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | North East | 6 | EA | 6 | 6-10 years | |
| | Stairs - Terrazzo | North East | 48 | LF | 6 | 10+ years | |
| | Walls - Masonry | North East | 844 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | North East | 388 | SF | 6 | 10+ years | Glass store front windows |
| | Ceiling - Plaster/Drywall | North West | 20 | SF | 7 | 10+ years | Water Damaged peeling paint |
| | Ceiling - Plaster/Drywall | North West | 404 | SF | 6 | 10+ years | Water Damaged pooling paint |
| | Floor - Terrazzo | North West | 184 | SF | 6 | 10+ years | |
| | Handrails | North West | 117 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | North West | 6 | EA | 6 | 6-10 years | |
| | Stairs - Terrazzo | North West | 48 | LA | 6 | 10+ years | |
| | Walls - Masonry | North West | 844 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | North West | 60 | SF | 4 | 1-2 years | Water demograd and pooling po |
| | Walls - Tile | North West | 388 | SF | 4 6 | 10+ years | Water damaged and peeling pa |
| | | | 20 | SF | 7 | | Water demogra |
| | Ceiling - Plaster/Drywall | South East | | SF | | 10+ years | Water damage |
| | Ceiling - Plaster/Drywall | South East | 300 | | 6 | 10+ years | |
| | Floor - Terrazzo | South East | 320 | SF | 6 | 10+ years | |
| | Handrails | South East | 205 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | South East | 8 | EA | 6 | 6-10 years | |
| | Stairs - Terrazzo | South East | 96 | LF | 6 | 10+ years | |
| | Walls - Masonry | South East | 1,400 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | South East | 50 | SF | 4 | 1-2 years | Water damage |
| | Ceiling - Plaster/Drywall | South West | 200 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | South West | 40 | SF | 5 | 1-2 years | Peeling paint |
| | Floor - Terrazzo | South West | 240 | SF | 6 | 10+ years | |
| | Handrails | South West | 157 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | South West | 6 | EA | 6 | 6-10 years | |
| | Stairs - Terrazzo | South West | 72 | LF | 6 | 10+ years | |
| | Walls - Masonry | South West | 1,050 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | South West | 50 | SF | 4 | 1-2 years | Water damage and peeling pain |
| tical (| Conveyance | | | | | | |
| | Elevator - Hydraulic Elevator | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Elevator - Hydraulic Elevator | 1st Floor | 1 | EA | 6 | 6-10 years | |



Category : Exterior Building : Linked Addition-Athletic Building Recommend Location **Replacement** Comments Item - Type Quantity UOM Group Rank Entrance 2 FΑ 7 Exterior Doors - Exterior Steel Door #12- NW 10+ years Exterior Doors - Exterior FRP Door 2 FΑ #13- NW 6 10+ years Exterior Doors - Transom Lite #13- NW 1 EΑ 6 10+ years Exterior Doors - Exterior FRP Door #14- NW 2 ΕA 6 10+ years Exterior Doors - Transom Lite #14- NW 1 EΑ 6 10+ years Exterior Doors - Exterior FRP Door #15- NE 2 EA 6 10+ years #15- NE Exterior Doors - Transom Lite 1 ΕA 6 10+ years Exterior Doors - Exterior FRP Door #16- NE 2 ΕA 6 10+ vears Exterior Doors - Transom Lite #16- NE 1 FΑ 6 10+ years FΑ Entrance Control - Audio and Video #17- E 1 5 6-10 vears 2 Exterior Doors - Exterior FRP Door #17- E EΑ 6 10+ years Power Door Operator and Controls 7 #17- E 1 EΑ 6-10 years Exterior Doors - Exterior Steel Door #18-SE 2 ΕA 6 10+ years Exterior Doors - Transom Lite #18-SE 1 EΑ 6 10+ years Exterior Doors - Exterior Steel Door #19- SW 2 FΑ 6 10+ years Exterior Doors - Transom Lite #19- SW 1 FΑ 6 10+ years Exterior Doors - Exterior FRP Door #20-W 2 ΕA 6 10+ vears Exterior Doors - Exterior Steel Door #21-SW 1 FΑ 6 10+ years Foundation Foundation - Concrete Entire Building 745 LF 7 10+ vears SF Superstructure - Steel Entire Building 52.621 7 10+ years Lighting Exterior Lighting - Wall Mounted 7 ΕA Entire Building 6 6-10 years Roof System Low W roof ΕA 7 Access Ladder - Metal 1 10+ years Coping - Metal Low W roof 294 LF 7 10+ years Relocated assets from Main LF Coping - Metal Low W roof 307 6 10+ years LF Downspouts - Interior Downspouts 36 7 Low W roof 10+ years LF **Downspouts - Interior Downspouts** 36 Low W roof 6 10+ years Relocated assets from Main Parapet - 16" - 30" Height 307 LF 7 Low W roof 6-10 years LF Parapet - Parapet < 16" Height Low W roof 294 7 10+ years Relocated assets from Main Roof - Modified Bitumen SF Low W roof 3.340 7 10+ vears SF Roof - Modified Bitumen Low W roof 1,974 7 10+ years Roof Structure - Steel / Metal Deck/ Low W roof SF 7 3.340 10+ years Concrete Topping Roof Structure - Steel / Metal Deck/ Low W roof 1.974 SF 7 10+ years Concrete Topping Coping - Metal LF 7 Main Roof 800 10+ years



| | ry : Exterior | | D | uilding | ·Linkoo | Addition-Ath | 30 S Elizabeth STREET, Chicago, IL 60643 |
|----------|---|------------------------------------|-------------|----------|----------|-------------------------|---|
| Jaleyo | | | D | unung | . Linked | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Downspouts - Interior Downspouts | Main Roof | 296 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | Main Roof | 100 | LF | 6 | 10+ years | |
| | Parapet - Parapet < 16" Height | Main Roof | 700 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Main Roof | 39,921 | SF | 7 | 10+ years | |
| | Roof Hatch - Metal | Main Roof | 2 | EA | 7 | 10+ years | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Main Roof | 39,921 | SF | 7 | 10+ years | |
| Walls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 20,112 | SF | 7 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 302 | SF | 5 | 1-2 years | Loose mortar, open joints, efflorescence |
| Windows | | | | | | | |
| | Curtain wall - Glazed Single Pane Lintels - Steel | Entire Building Entire Building | 7,956 36 | SF LF | 5 6 | 6-10 years 10+ years | Single pane |
| Catego | ry : Electrical | | В | uilding | : Linkec | Addition-Ath | letic Building |
| C | Home Time | Leastion | Quentitu | | Dault | Recommend | Commente |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Emerger | icy System | | | = . | | 0.40 | |
| | Automatic Transfer Switch | Basement | 2 | EA | 7 | 6-10 years | Location changed for clarification. |
| | Exit Signs - Corridors and Stairs | Entire Building | 4 | EA EA | 6 6 | 6-10 years | Evit Signa have been upgraded since |
| | Exit Signs - Gym | Entire Building | | | - | 6-10 years | Exit Signs have been upgraded since last assessment. Rank, Reason and Priority Rep adjusted to account for contemporary LED illumination and based on current observations. |
| | Exit Signs - Pool | Entire Building | 4 | EA | 6 | 6-10 years | Exit Signs have been upgraded since last assessment. Rank, Reason and Priority Rep adjusted to account for contemporary LED illumination and based on current observations. |
| | Security System - CCTV | Entire Building | 52,621 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 52,621 | SF | 5 | 6-10 years | |
| | Emergency Generator- Indoor- Natural Gas - Below 60 KW | Generator Room | 1 | EA | 7 | 10+ years | |
| | Emergency Battery Packs - Gym | Gym | 5 | EA | 6 | 6-10 years | Quantity changed as total has been divided/aggregated. |
| | Emergency Battery Packs - Gym | Gym | 1 | EA | 4 | 0-1 year | Electrical compartment cover is missing; live parts are exposed. |

Main Service



| Category : Electrical | | | | Building : Linked Addition-Athletic Building | | | | | | |
|-----------------------|---|-----------------|----------|--|----------|---------------|--|--|--|--|
| | | | | | | Recommend | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |
| | Main Electrical Service - 2000 A 277/480/3PH | Basement | 1 | EA | 6 | 6-10 years | | | | |
| | PA System | Entire Building | 52,621 | SF | 6 | 6-10 years | Served by Main | | | |
| Power D | istribution | | | | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 3 | EA | 7 | 10+ years | Located in electrical closet. | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 6 | 10+ years | Located in maintenance closet. | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 6 | 6-10 years | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 6 | 6-10 years | Located in electrical closet. Quanti changed as total has been divided/aggregated. | | | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 7 | 10+ years | Located in electrical closet. | | | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 7 | 10+ years | | | | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 6 | 10+ years | Located in Weight Room | | | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 2 | EA | 7 | 10+ years | · | | | |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 6 | 6-10 years | Location changed for clarification. | | | |
| | Main Distribution Panels - Greater than 600 amp | Entire Building | 2 | EA | 6 | 6-10 years | Location changed for clarification. | | | |
| | Main Distribution Panels - Less than 400 amp | Entire Building | 1 | EA | 7 | 10+ years | Located in electrical closet. | | | |
| | Main Distribution Panels - Less than 400 amp | Entire Building | 3 | EA | 7 | 10+ years | | | | |
| | Main Distribution Panels - Less than 400 amp | Entire Building | 2 | EA | 7 | 6-10 years | | | | |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 6 | 10+ years | | | | |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 6 | 10+ years | Located in electrical closet. | | | |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 5 | 6-10 years | Quantity changed as total has been divided/aggregated. Location changed for clarification. | | | |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 5 | 6-10 years | | | | |
| Catego | ry : Fire Protection | | B | uilding | : Linked | Addition-Athl | etic Building | | | |
| | | | | | | Recommend | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |

Fire Alarm Panel

Fire Alarm Strobe Lights Fire Alarm_System ΕA

SF

SF

1

52,561 52,561 6

7

7

6-10 years

10+ years

10+ years

Entire Building

Entire Building

Entire Building

No CPS Asset Tag present. Installed

in a closet in an office space inside

the gym.



Category : Mechanical **Building : Linked Addition-Athletic Building** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Air Handling Systems Indoor Return Fans- Centrifugal Inline -ΕA Basement 1 6 6-10 years 5000 - 10000 CFM ΕA Roof Top Unit-Single Zone-Roof Mounted-Lower Roof 1 5 2-5 years Gas Heating and DX Cooling Coil - 11 - 20 tons Roof Top Unit-Multi Zone-Roof Mounted-Roof FΑ 6 Unit is also referenced as S-24. 1 6-10 vears Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons Roof Top Unit-Multi Zone-Roof Mounted-Roof 1 EΑ 4 2-5 years Unit only has one operational air Gas Heating and DX Cooling w/ Self conditioning circuit and has exceeded Contained Compressor - 46 - 60 tons its EUL. Roof Top Unit-Multi Zone-Roof Mounted-Roof 1 ΕA 4 2-5 years Unit only has one operational air Gas Heating and DX Cooling w/ Self conditioning circuit and has exceeded Contained Compressor - 46 - 60 tons its EUL. Roof Top Unit-Multi Zone-Roof Mounted-Roof EΑ Unit only has one operational air 1 4 2-5 years Gas Heating and DX Cooling w/ Self conditioning circuit and has exceeded Contained Compressor - 46 - 60 tons its EUL. Roof Top Unit-Multi Zone-Roof Mounted-Roof 1 EΑ 4 2-5 years Unit only has one operational air Gas Heating and DX Cooling w/ Self conditioning circuit and has exceeded Contained Compressor - 46 - 60 tons its EUL. Roof Top Unit-Multi Zone-Roof Mounted-Roof 1 ΕA 4 2-5 vears Unit only has one operational air Gas Heating and DX Cooling w/ Self conditioning circuit and has exceeded Contained Compressor - 46 - 60 tons its EUL. Rank adjusted based on current observations and per review with Building Engineer. Unit is also referenced as S-27. Roof Top Unit-Multi Zone-Roof Mounted-Roof 1 ΕA 6 6-10 years Gas Heating and DX Cooling w/ Self Contained Compressor - Greater than 60 tons Boiler Systems Boiler Auxiliary- Condensing Hot Water -1 ΕA Basement 6 6-10 years Less than 500 HP Condensing- Hot Water Boiler - Less than Basement 1 ΕA 6 10+ vears 500 MBH Piping - Dual Temperature Pipes- Copper LF 100 6 Basement 10+ vears Heating Devices Fin Tube - Hot Water 1st Floor 300 LF 6 6-10 years 2 ΕA 5 Cabinet Heaters - With Hot Water Coil 1st Floor 2-5 years Mechanical Plumbing



10330 S Elizabeth STREET, Chicago, IL 60643 **Building : Linked Addition-Athletic Building Category : Mechanical** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Hydronic Supply and Return - Copper LF Associated with the hot water boiler Entire Building 100 6 10+ years serving the pool area fin tube heating. Temperature Control **Electric Thermostat** Entire Building ΕA 6 6-10 years 1 Pneumatic System 52.621 SF Entire Building 6 6-10 years Temperature control for this building is accomplished via the pneumatic system located in Main. ΕA Thermostats - Pneumatic Entire Building 17 6 6-10 years Ventilation Exhaust Fans- Indoor - 500 - 1500 CFM Entire Building 2 ΕA 6 6-10 years Dataplates not visible. Exhaust Fans- Indoor - 500 - 1500 CFM Entire Building 1 ΕA 6 6-10 years Serves the Electrical Room. Dataplate not visible. Exhaust Fans- Roof Mounted - 1501 - 8000 Entire Building 1 ΕA 7 10+ years CFM Exhaust Fans- Roof Mounted - 1501 - 8000 ΕA Entire Building 3 5 2-5 years CFM LF 6 Roof Mounted Duct Work 15 Lineal footage confirmed by physical Entire Building 6-10 years measurement at the time of assessment. **Category : Plumbing Building : Linked Addition-Athletic Building** Recommend

| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
|----------|--|-----------------|----------|-----|------|-------------|--|
| Hot Wate | er | | | | | | |
| | Gas Heater - 300001 - 600000 BTU/HR | Basement | 2 | EA | 6 | 6-10 years | Units date to 2017 |
| | Hot Water Storage Tank_Gas - 501 - 1000 Gallons | Basement | 1 | EA | 6 | 6-10 years | Well-maintained older unit with minimal insulation damage. |
| Piping | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 52,621 | SF | 4 | 2-5 years | Domestic water supplied from Main. Galvanized material over 40 years old with notable corrosion and some pipe clamps. |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 52,621 | SF | 4 | 2-5 years | Domestic water supplied from Main. Galvanized material over 40 years old with notable corrosion and some pipe clamps. |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 52,621 | SF | 4 | 2-5 years | Domestic water supplied from Main. Galvanized material over 40 years old with notable corrosion and some pipe clamps. |



Percy L Julian High School 10330 S Elizabeth STREET, Chicago, IL 60643

| Category : Plumbing | | | | Building : Linked Addition-Athletic Building | | | | | | |
|---------------------|---|----------------------|----------|--|----------|--------------------------|--|--|--|--|
| j- | ., | | | | | Recommend | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 52,621 | SF | 4 | 2-5 years | Domestic water supplied from Main. Galvanized material over 40 years old with notable corrosion and some pipe clamps. | | | |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 52,621 | SF | 4 | 2-5 years | Domestic water supplied from Main. Galvanized material over 40 years old with notable corrosion and some pipe clamps. | | | |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 52,621 | SF | 4 | 2-5 years | Domestic water supplied from Main. Galvanized material over 40 years old with notable corrosion and some pipe clamps. | | | |
| | Sanitary Piping | Entire Building | 52,621 | SF | 4 | 2-5 years | Galvanized material over 40 years old. Notable corrosion reported by building engineer. | | | |
| | Storm Piping | Entire Building | 52,621 | SF | 4 | 2-5 years | Galvanized material over 40 years old. Notable corrosion reported by building engineer. | | | |
| | Vent Piping | Entire Building | 52,621 | SF | 4 | 2-5 years | Galvanized material over 40 years old. Notable corrosion reported by building engineer. | | | |
| Pool Sys | stems | | | | | | | | | |
| | Pool Drain Piping | Basement | 200 | LF | 6 | 6-10 years | | | | |
| | Pool Filtration System including Pump | Basement | 1 | EA | 4 | 2-5 years | Pump and filtration system leak free at the time of assessment with signs of previous leak repairs. Considerable age-related corrosion. | | | |
| | Pool Hot Water Heater - Gas Fired | Basement | 1 | EA | 6 | 6-10 years | | | | |
| | Pool Supply and Return Piping | Basement | 200 | LF | 4 | 2-5 years | Galvanized piping over 40 years old; leak free at the time of assessment with signs of previous leak repairs. Considerable age-related corrosion. | | | |
| Pumps | | | | | | | | | | |
| | Pumps - Ejector-Duplex Pumps - Sump-Duplex | Basement Basement | 1 1 | EA EA | 6 6 | 6-10 years 6-10 years | | | | |
| Catego | ry : Room | | в | uilding | · Linkor | d Addition-Ath | etic Building | | | |
| Juleyo | | | | anang | | Recommend | | | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |
| Administ | trative Suites/Offices | | | | | | | | | |
| | Ceiling - Plaster/Drywall | 420 Coach's Office | 94 | SF | 5 | 1-2 years | Paint is peeling | | | |



| Cataga | | | D | uilding | Linkor | | so S Elizabeth STREET, Chicago, IL 60643 |
|--------|--|-------------------------|----------|----------|----------|--------------|--|
| Catego | ry : Room | | В | unaing | : LINKed | Addition-Ath | letic Building |
| 0 | Hanna Tama | Leveller | 0 | | Daula | Recommend | 0 |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Steel Doors incl hw | 420 Coach's Office | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile Ceramic/ Porcelain | 420 Coach's Office | 94 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 420 Coach's Office | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 420 Coach's Office | 2 | EA | 7 | 10+ years | |
| | Storage/ Closet | 420 Coach's Office | 28 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 420 Coach's Office | 319 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 421 Coach's Office | 74 | SF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 421 Coach's Office | 20 | SF | 5 | 0-1 year | Peeling paint |
| | Doors - Steel Doors incl hw | 421 Coach's Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 421 Coach's Office | 94 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 421 Coach's Office | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 421 Coach's Office | 2 | EA | 7 | 6-10 years | |
| | Storage/ Closet | 421 Coach's Office | 28 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 421 Coach's Office | 319 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 423 | 137 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 423 | 1 | ĒA | 7 | 10+ years | |
| | Floor - Terrazzo | 423 | 137 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 423 | 3 | ĒA | 7 | 6-10 years | |
| | Power Distribution | 423 | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 423 | 431 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 431 women's locker room | 126 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 431 women's locker room | 1 | EA | 7 | 10+ years | |
| | Doors - Transom Window | 431 women's locker room | 30 | SF | 7 | 10+ years | |
| | Floor - Epoxy/ Painted | 431 women's locker room | 128 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 431 women's locker room | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 431 women's locker room | 4 | EA | 7 | 10+ years | |
| | Storage/ Closet | 431 women's locker room | 12 | SF | 7 | 10+ years | |
| | | 431 women's locker room | | SF | 7 | | |
| | Walls - Concrete Block | | 308 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 440 | 74 | | | 10+ years | |
| | Ceiling - Plaster/Drywall Doors - Side-lite | 440 | 20 | SF SF | 6 | 2-5 years | |
| | | 440 | 16 | | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 440 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 440 | 94 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 440 | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 440 | 2 | EA | 7 | 10+ years | |
| | Storage/ Closet | 440 | 28 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 440 | 319 | SF | 7 | 10+ years | |
| | Ceiling - Splined | Men's Gym Office 404 | 71 | SF | 6 | 6-10 years | |
| | Ceiling - Splined | Men's Gym Office 404 | 30 | SF | 4 | 0-1 year | Replace tiles and grid. |
| | Doors - Side-lite | Men's Gym Office 404 | 11 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Men's Gym Office 404 | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | Men's Gym Office 404 | 101 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | Men's Gym Office 404 | 1 | EA | 7 | 6-10 years | |
| | Power Distribution | Men's Gym Office 404 | 4 | EA | 7 | 10+ years | |
| | | | | | | • | |



| Catego | ry : Room | | Building : Linked Addition-Athletic Building | | | | | |
|--------|-----------------------------|---------------------------------|--|-----|------|-------------|---------------------|--|
| Ĩ | | | | | | Recommend | - | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Walls - Concrete Block | Men's Gym Office 404 | 314 | SF | 7 | 10+ years | | |
| | Ceiling - Plaster/Drywall | Training room men's locker room | 244 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | Training room men's locker room | 2 | EA | 6 | 2-5 years | | |
| | Floor - Epoxy/ Painted | Training room men's locker room | 244 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | Training room men's locker room | 6 | EA | 7 | 6-10 years | | |
| | Power Distribution | Training room men's locker room | 6 | EA | 6 | 6-10 years | | |
| | Walls - Concrete Block | Training room men's locker room | 480 | SF | 7 | 10+ years | | |
| | Ceiling - Lay-in | Weight Room Office 400B | 168 | SF | 6 | 6-10 years | | |
| | Ceiling - Lay-in | Weight Room Office 400B | 24 | SF | 5 | 1-2 years | Water damaged tiles | |
| | Doors - Steel Doors incl hw | Weight Room Office 400B | 1 | EA | 6 | 2-5 years | | |
| | Floor - Tile | Weight Room Office 400B | 192 | SF | 6 | 10+ years | | |
| | Lighting - Pendent/Surface | Weight Room Office 400B | 4 | EA | 6 | 6-10 years | | |
| | Power Distribution | Weight Room Office 400B | 2 | EA | 7 | 10+ years | | |
| | Walls - Concrete Block | Weight Room Office 400B | 129 | SF | 6 | 10+ years | | |
| | Walls - Plaster/Drywall | Weight Room Office 400B | 323 | SF | 6 | 10+ years | | |
| | Ceiling - Splined | Women's Gym Office I | 94 | SF | 7 | 6-10 years | | |
| | Doors - Side-lite | Women's Gym Office I | 11 | SF | 7 | 6-10 years | | |
| | Doors - Steel Doors incl hw | Women's Gym Office I | 1 | EA | 6 | 6-10 years | | |
| | Floor - Tile | Women's Gym Office I | 94 | SF | 6 | 10+ years | | |
| | Lighting - Lay-in | Women's Gym Office I | 2 | EA | 6 | 2-5 years | | |
| | Power Distribution | Women's Gym Office I | 2 | EA | 7 | 10+ years | | |
| | Walls - Concrete Block | Women's Gym Office I | 311 | SF | 6 | 10+ years | | |
| | Ceiling - Splined | Women's Gym Office II | 94 | SF | 6 | 6-10 years | | |
| | Doors - Side-lite | Women's Gym Office II | 11 | SF | 6 | 10+ years | | |
| | Doors - Steel Doors incl hw | Women's Gym Office II | 1 | EA | 6 | 6-10 years | | |
| | Floor - Tile | Women's Gym Office II | 94 | SF | 6 | 10+ years | | |
| | Lighting - Lay-in | Women's Gym Office II | 2 | EA | 7 | 6-10 years | | |
| | Power Distribution | Women's Gym Office II | 22 | EA | 6 | 10+ years | | |
| | Walls - Concrete Block | Women's Gym Office II | 311 | SF | 7 | 10+ years | | |
| Svmnas | ia | | | | | | | |
| 5 | Bleacher Seating | Large Gym 400 | 1,008 | EA | 7 | 6-10 years | | |
| | Ceiling - Exposed | Large Gym 400 | 11,946 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | Large Gym 400 | 6 | EA | 6 | 6-10 years | | |
| | Floor - Wood | Large Gym 400 | 11,946 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | Large Gym 400 | 35 | EA | 7 | 6-10 years | | |
| | Scoreboards | Large Gym 400 | 2 | EA | 7 | 6-10 years | | |
| | Sound System | Large Gym 400 | 1 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | Large Gym 400 | 6,700 | SF | 7 | 10+ years | | |
| | Ceiling - Exposed | Small Gym 401 | 8,090 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | Small Gym 401 | 6 | EA | 6 | 6-10 years | | |
| | Floor - Wood | Small Gym 401 | 8,090 | SF | 7 | 10+ years | | |
| | Lighting - Pendent/Surface | Small Gym 401 | 25 | EA | 7 | 6-10 years | | |
| | Storage/ Closet | Small Gym 401 | 423 | SF | 7 | 10+ years | | |



| Category : Room Building : Linked Addition-Athletic Building | | | | | | | |
|--|---|------------------|-----------|---------|----------|------------------------|------------------------|
| Catego | ry : Room | | В | uilding | : Linked | | letic Building |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Walls - Concrete Block | Small Gym 401 | 5,300 | SF | 7 | 10+ years | |
| | Ceiling - Exposed | Weight Room 400A | 2,403 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Weight Room 400A | 2 | EA | 6 | 6-10 years | |
| | Floor - Sport Flooring | Weight Room 400A | 2,403 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Weight Room 400A | 12 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Weight Room 400A | 446 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Weight Room 400A | 1,896 | SF | 7 | 10+ years | |
| Locker/S | Shower Room | | | | | | |
| | Accessories | 1M | 237 | SF | 7 | 6-10 years | |
| | Benches, ped mounted | 1M | 7 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1M | 237 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1M | 207 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 1M | 10 | SF | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1M | 227 | SF | 7 | 10+ years | |
| | Floor Drain | 1M | 2 | EA | 7 | 10+ years | |
| | Hand Dryer | 1M | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1M | 2 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | 1M | 6 | EA | 7 | 6-10 years | |
| | Partitions | 1M | 1 | EA | 4 | 1-2 years | Missing partition door |
| | Showers | 1M | 1 | EA | 4 5 | 0-1 year | Replace fixtures |
| | Student Lockers - One Tier | 1M | 3 | EA | 7 | 10+ years | Replace lixiules |
| | Urinals | 1M | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1M | 587 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1M | 92 | SF | 7 | 10+ years | |
| | Water Closet | 1M | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor | 237 | SF | 7 | 6-10 years | |
| | Benches, ped mounted | 1st Floor | 7 | LF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 237 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 201 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 1st Floor | 10 | SF | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 227 | SF | 7 | 10+ years | |
| | Floor Drain | 1st Floor | 227 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 6 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Showers | 1st Floor | 2 | EA | 7 | | |
| | Student Lockers - One Tier | 1st Floor | 3 | EA | 7 | 10+ years 10+ years | |
| | Walls - Concrete Block | 1st Floor | 587 | SF | 7 | - | |
| | Walls - Concrete Block Walls - Tile Ceramic/ Porcelain | 1st Floor | 587 92 | SF | 7 | 10+ years | |
| | Walls - The Ceramic/ Porcelain Water Closet | 1st Floor | 92 | EA | 7 | 10+ years | |
| | | | 132 | SF | 7 | 10+ years | |
| | Accessories | 431 | | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 431 | 132 | 25 | 1 | 10+ years | |



| Category : Room | | | | Building : Linked Addition-Athletic Building | | | | | |
|-----------------|--|------------------------------|----------|--|------|-------------|----------------------|--|--|
| j- | · · · · · · · · · · · · · · · · · · · | | _ | | | Recommend | J | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Doors - Steel Doors incl hw | 431 | 1 | EA | 7 | 10+ years | | | |
| | Floor - Epoxy/ Painted | 431 | 132 | SF | 7 | 10+ years | | | |
| | Floor Drain | 431 | 4 | ĒA | 7 | 10+ years | | | |
| | Lavatory | 431 | 2 | EA | 6 | 10+ years | | | |
| | Lighting - Metal Halide/ High Pressure | 431 | 2 | EA | 7 | 6-10 years | | | |
| | Sodium | | | | | , | | | |
| | Partitions | 431 | 1 | EA | 7 | 10+ years | | | |
| | Showers | 431 | 3 | EA | 7 | 6-10 years | | | |
| | Walls - Concrete Block | 431 | 308 | SF | 7 | 10+ years | | | |
| | Water Closet | 431 | 1 | EA | 7 | 10+ years | | | |
| | Accessories | Basement | 4,229 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | Basement | 4,229 | SF | 7 | 6-10 years | | | |
| | Doors - Steel Doors incl hw | Basement | 2 | EA | 7 | 10+ years | | | |
| | Floor - Terrazzo | Basement | 3,746 | SF | 7 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | Basement | 483 | SF | 6 | 10+ years | | | |
| | Floor Drain | Basement | 30 | EA | 7 | 10+ years | | | |
| | Floor Drain | Basement | 2 | EA | 4 | 0-1 year | Missing drain covers | | |
| | Hand Dryer | Basement | 4 | EA | 7 | 6-10 years | 5 | | |
| | Lavatory | Basement | 2 | EA | 7 | 6-10 years | | | |
| | Lighting - Lay-in | Basement | 41 | EA | 7 | 6-10 years | | | |
| | Partitions | Basement | 3 | EA | 7 | 10+ years | | | |
| | Showers | Basement | 28 | EA | 7 | 10+ years | | | |
| | Storage/ Closet | Basement | 45 | SF | 7 | 10+ years | | | |
| | Student Lockers - Three Tiers | Basement | 486 | ĒA | 7 | 10+ years | | | |
| | Urinals | Basement | 3 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | Basement | 3,767 | SF | 7 | 10+ years | | | |
| | Walls - Tile Ceramic/ Porcelain | Basement | 384 | SF | 7 | 10+ years | | | |
| | Water Closet | Basement | 3 | EA | 7 | 10+ years | | | |
| | Accessories | Basement Women's Locker Room | 3,001 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | Basement Women's Locker Room | 3,001 | SF | 7 | 6-10 years | | | |
| | Doors - Steel Doors incl hw | Basement Women's Locker Room | 2 | EA | 6 | 6-10 years | | | |
| | Floor - Concrete | Basement Women's Locker Room | 3,001 | SF | 7 | 10+ years | | | |
| | Floor Drain | Basement Women's Locker Room | 30 | EA | 7 | 10+ years | | | |
| | Hand Dryer | Basement Women's Locker Room | 11 | EA | 7 | 10+ years | | | |
| | Lavatory | Basement Women's Locker Room | 5 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | Basement Women's Locker Room | 22 | EA | 7 | 6-10 years | | | |
| | Partitions | Basement Women's Locker Room | 7 | EA | 7 | 10+ years | | | |
| | Showers | Basement Women's Locker Room | 18 | EA | 7 | 10+ years | | | |
| | Storage/ Closet | Basement Women's Locker Room | 32 | SF | 7 | 10+ years | | | |
| | Student Lockers - Three Tiers | Basement Women's Locker Room | 996 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | Basement Women's Locker Room | 3,495 | SF | 7 | 10+ years | | | |
| | Walls - Masonry | Basement Women's Locker Room | 200 | SF | 7 | 2-5 years | | | |
| | Walls - Plaster/Drywall | Basement Women's Locker Room | 1 | SF | 7 | 10+ years | | | |
| | Walls - Plaster/Drywall | Basement Women's Locker Room | 60 | SF | 7 | 10+ years | | | |



| Category : Room | | | | Building : Linked Addition-Athletic Building | | | | | | |
|-----------------|---------------------------------|------------------------------|----------|--|------|-------------|----------|--|--|--|
| | | | | Recommend | | | | | | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | | |
| • | Water Closet | Basement Women's Locker Room | 7 | EA | 7 | 10+ years | | | | |
| | Accessories | Home Team Room | 729 | SF | 7 | 6-10 years | | | | |
| | Ceiling - Plaster/Drywall | Home Team Room | 729 | SF | 7 | 10+ years | | | | |
| | Doors - Steel Doors incl hw | Home Team Room | 2 | EA | 6 | 6-10 years | | | | |
| | Floor - Terrazzo | Home Team Room | 84 | SF | 7 | 10+ years | | | | |
| | Floor - Tile Ceramic/ Porcelain | Home Team Room | 79 | SF | 7 | 10+ years | | | | |
| | Floor - Tile/Sheet | Home Team Room | 566 | SF | 7 | 10+ years | | | | |
| | Floor Drain | Home Team Room | 1 | EA | 7 | 10+ years | | | | |
| | Floor Drain | Home Team Room | 2 | EA | 7 | 10+ years | | | | |
| | Hand Dryer | Home Team Room | 1 | EA | 7 | 6-10 years | | | | |
| | Lavatory | Home Team Room | 1 | EA | 7 | 10+ years | | | | |
| | Lighting - Lay-in | Home Team Room | 7 | EA | 7 | 6-10 years | | | | |
| | Showers | Home Team Room | 6 | EA | 7 | 10+ years | | | | |
| | Storage/ Closet | Home Team Room | 103 | SF | 7 | 10+ years | | | | |
| | Student Lockers - One Tier | Home Team Room | 24 | EA | 7 | 10+ years | | | | |
| | Urinals | Home Team Room | 1 | EA | 7 | 10+ years | | | | |
| | Walls - Concrete Block | Home Team Room | 1,325 | SF | 7 | 10+ years | | | | |
| | Water Closet | Home Team Room | 1 | EA | 7 | 10+ years | | | | |
| | Accessories | Visiting team room basement | 50 | SF | 7 | 6-10 years | | | | |
| | Ceiling - Plaster/Drywall | Visiting team room basement | 681 | SF | 7 | 10+ years | | | | |
| | Doors - Steel Doors incl hw | Visiting team room basement | 1 | EA | 6 | 6-10 years | | | | |
| | Floor - Concrete | Visiting team room basement | 491 | SF | 7 | 10+ years | | | | |
| | Floor - Tile Ceramic/ Porcelain | Visiting team room basement | 180 | SF | 6 | 10+ years | | | | |
| | Floor Drain | Visiting team room basement | 3 | EA | 7 | 10+ years | | | | |
| | Hand Dryer | Visiting team room basement | 1 | EA | 7 | 6-10 years | | | | |
| | Lavatory | Visiting team room basement | 1 | EA | 7 | 10+ years | | | | |
| | Lighting - Lay-in | Visiting team room basement | 11 | EA | 7 | 6-10 years | | | | |
| | Partitions | Visiting team room basement | 1 | EA | 7 | 10+ years | | | | |
| | Showers | Visiting team room basement | 9 | EA | 7 | 10+ years | | | | |
| | Student Lockers - One Tier | Visiting team room basement | 25 | EA | 7 | 10+ years | | | | |
| | Student Lockers - One Tier | Visiting team room basement | 5 | EA | 5 | 1-2 years | Damaged | | | |
| | Urinals | Visiting team room basement | 1 | EA | 7 | 10+ years | - | | | |
| | Walls - Concrete Block | Visiting team room basement | 800 | SF | 7 | 10+ years | | | | |
| | Walls - Masonry | Visiting team room basement | 440 | SF | 7 | 10+ years | | | | |
| | Water Closet | Visiting team room basement | 1 | EA | 7 | 10+ years | | | | |
| | | | | | | | | | | |
| echan | ical/ Service Rooms | 4 · · = | | 6- | _ | | | | | |
| | Janitor's Closet | 1st Floor | 70 | SF | 7 | 10+ years | | | | |
| | Mechanical/ Service Rooms | 1st Floor | 268 | SF | 7 | 10+ years | | | | |
| | Mechanical/ Service Rooms | 1st Floor | 72 | SF | 7 | 10+ years | | | | |
| | Vaults | 1st Floor | 22 | SF | 7 | 10+ years | | | | |
| | Air Intake Plenums | Basement | 197 | SF | 7 | 10+ years | | | | |
| | Janitor's Closet | Basement | 45 | SF | 7 | 10+ years | | | | |
| | Mechanical/ Service Rooms | Basement | 7,780 | SF | 7 | 10+ years | | | | |



| Category : Room | | | В | Building : Linked Addition-Athletic Building | | | | | |
|-----------------|---------------------------------|------------------------------|----------|--|------|-------------|----------------|--|--|
| | | Recommend | | | | | | | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | | |
| | Mechanical/ Service Rooms | Basement | 100 | SF | 7 | 10+ years | | | |
| | Storage Room | Basement | 603 | SF | 7 | 10+ years | | | |
| | Vaults | Basement | 338 | SF | 7 | 10+ years | | | |
| | | | | | | • | | | |
| 001 & N | latatorium | | | | | | | | |
| | Accessories | 1st Floor | 12,515 | SF | 7 | 6-10 years | | | |
| | Bleachers Seating/Plank Seating | 1st Floor | 408 | EA | 7 | 10+ years | | | |
| | Ceiling - Exposed | 1st Floor | 6,980 | SF | 7 | 10+ years | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 6,200 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | 1st Floor | 6 | EA | 7 | 10+ years | | | |
| | Floor - Concrete | 1st Floor | 3,200 | SF | 7 | 10+ years | | | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 4,585 | SF | 7 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor | 4,000 | EA | 7 | 6-10 years | | | |
| | Lighting - Pendent/Surface | 1st Floor | 24 | EA | 7 | 6-10 years | | | |
| | Pool Basin | 1st Floor | 4,730 | SF | 7 | 10+ years | | | |
| | | | | SF | 7 | • | | | |
| | Pool Deck | 1st Floor | 4,585 | | | 10+ years | | | |
| | Pool Deck Drains | 1st Floor | 38 | EA | 7 | 10+ years | | | |
| | Storage/ Closet | 1st Floor | 456 | SF | 7 | 10+ years | | | |
| | Walls - Concrete Block | 1st Floor | 6,200 | SF | 6 | 10+ years | | | |
| | | | | | | | | | |
| estroor | | 4 f i a a a a a a a b | 440 | 05 | 7 | 0.40 | | | |
| | Accessories | 1flr mens west | 118 | SF | 7 | 6-10 years | | | |
| | Ceiling - Plaster/Drywall | 1flr mens west | 118 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | 1flr mens west | 1 | EA | 7 | 10+ years | | | |
| | Floor - Terrazzo | 1flr mens west | 118 | SF | 7 | 10+ years | | | |
| | Floor Drain | 1flr mens west | 1 | EA | 7 | 10+ years | | | |
| | Hand Dryer | 1flr mens west | 1 | EA | 7 | 6-10 years | | | |
| | Lavatory | 1flr mens west | 3 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | 1flr mens west | 6 | EA | 7 | 6-10 years | | | |
| | Partitions | 1flr mens west | 1 | EA | 7 | 10+ years | | | |
| | Urinals | 1flr mens west | 1 | EA | 7 | 10+ years | | | |
| | Walls - Concrete Block | 1flr mens west | 437 | SF | 7 | 10+ years | | | |
| | Water Closet | 1flr mens west | 1 | EA | 7 | 10+ years | | | |
| | Accessories | 1st Floor Men's | 123 | SF | 5 | 1-2 years | Replace mirror | | |
| | Ceiling - Plaster/Drywall | 1st Floor Men's | 123 | SF | 7 | 10+ years | | | |
| | Doors - Steel Doors incl hw | 1st Floor Men's | 1 | EA | 6 | 6-10 years | | | |
| | Floor - Terrazzo | 1st Floor Men's | 123 | SF | 7 | 10+ years | | | |
| | Floor Drain | 1st Floor Men's | 1 | EA | 7 | 10+ years | | | |
| | Hand Dryer | 1st Floor Men's | 1 | EA | 7 | 10+ years | | | |
| | Lavatory | 1st Floor Men's | 3 | EA | 7 | 10+ years | | | |
| | Lighting - Lay-in | 1st Floor Men's | 5 | EA | 7 | 6-10 years | | | |
| | Partitions | 1st Floor Men's | 1 | EA | 7 | 6-10 years | | | |
| | Urinals | 1st Floor Men's | 2 | EA | 7 | 10+ years | | | |
| | Unnais | | | | | | | | |



| Catago | | | P | بناطنهم | Linkor | | atio Building |
|--------|---------------------------------|--|---------------|----------|----------|--------------------------|--------------------------|
| Catego | ry : Room | | В | unaing | : Linked | Addition-Ath | letic Building |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Group | Water Closet | 1st Floor Men's | Quantity 1 | EA | 7 | 10+ years | Comments |
| | Accessories | 1st Floor West women's | 123 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor West women's | 123 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor West women's | 123 | EA | 7 | | |
| | Floor - Terrazzo | 1st Floor West women's | 123 | SF | 7 | 10+ years | |
| | | | | | | 10+ years | |
| | Floor Drain | 1st Floor West women's | 1 | EA EA | 7 7 | 10+ years | |
| | Hand Dryer | 1st Floor West women's 1st Floor West women's | 1 | EA | 7 | 6-10 years | |
| | Lavatory | | 3 5 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor West women's | | | | 6-10 years | |
| | Partitions | 1st Floor West women's | 2 | EA SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor West women's | 446 | | 7 | 10+ years | |
| | Water Closet | 1st Floor West women's | 2 | EA | 7 | 10+ years | |
| | Accessories | 1st east womens | 135 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st east womens | 135 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st east womens | 1 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 1st east womens | 135 | SF | 7 | 10+ years | |
| | Floor Drain | 1st east womens | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st east womens | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st east womens | 3 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 1st east womens | 6 | EA | 6 | 6-10 years | |
| | Partitions | 1st east womens | 3 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st east womens | 500 | SF | 7 | 10+ years | |
| | Water Closet | 1st east womens | 3 | EA | 7 | 10+ years | |
| | Accessories | 420 | 51 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 420 | 51 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 420 | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile Ceramic/ Porcelain | 420 | 51 | SF | 7 | 10+ years | |
| | Floor Drain | 420 | 1 | EA | 7 | 10+ years | |
| | Lavatory | 420 | 1 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 420 | 1 | EA | 6 | 6-10 years | |
| | Showers | 420 | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 420 | 242 | SF | 7 | 10+ years | |
| | Water Closet | 420 | 1 | EA | 7 | 10+ years | |
| | Accessories | 421 | 51 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 421 | 51 | SF | 6 | 0-1 year | Peeling paint |
| | Doors - Steel Doors incl hw | 421 | 1 | EA | 6 | 0-1 year | Replace missing doorknob |
| | Floor - Tile Ceramic/ Porcelain | 421 | 51 | SF | 6 | 10+ years | |
| | Lavatory | 421 | 1 | EA | 4 | 1-2 years | Replace fixture |
| | Lighting - Lay-in | 421 | 1 | EA | 7 | 6-10 years | |
| | Showers | 421 | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 421 | 242 | SF | 7 | 10+ years | |
| | Water Closet | 421 | 1 | EA | 7 | 10+ years | |
| | Accessories | 423 | 115 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 423 | 115 | SF | 7 | 10+ years | |



| Catego | ry : Room | | B | uildina | : Linked | Addition-Ath | etic Building |
|--------|--|-----------------------|----------|----------|----------|------------------------|----------------------------------|
| Julogo | ., | | | anang | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Steel Doors incl hw | 423 | 1 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 423 | 115 | SF | 6 | 10+ years | |
| | Floor Drain | 423 | 3 | EA | 7 | 10+ years | |
| | Hand Dryer | 423 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 423 | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 423 | 2 | EA | 7 | 6-10 years | |
| | Partitions | 423 | 1 | EA | 7 | 10+ years | |
| | Showers | 423 | 2 | EA | 5 | 2-5 years | |
| | Student Lockers - One Tier | 423 | 6 | EA | 6 | 6-10 years | |
| | Urinals | 423 | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 423 | 423 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 423 | 1 | SF | 7 | 10+ years | |
| | Water Closet | 423 | 1 | EA | 7 | 10+ years | |
| | Accessories | 440 | 54 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 440 | 54 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 440 | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 440 | 54 | SF | 6 | 10+ years | |
| | Floor Drain | 440 | 1 | EA | 7 | 10+ years | Demonad |
| | Lavatory | 440 | 1 | EA EA | 5 6 | 0-1 year | Damaged |
| | Lighting - Lay-in | 440 440 | 1 | EA | 6 5 | 6-10 years | Daplage shower bood |
| | Showers Walls - Concrete Block | 440 440 | 242 | SF | 5 7 | 0-1 year | Replace shower head |
| | Walls - Concrete Block Water Closet | 440 | 242 | EA | 7 | 10+ years | |
| | | Men's Gym Office | 37 | SF | 7 | 10+ years | |
| | Accessories Ceiling - Plaster/Drywall | Men's Gym Office | 37 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | Men's Gym Office | 37 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Men's Gym Office | 37 | SF | 5 | 10+ years 1-2 years | Poplaco tilos |
| | Floor Drain | Men's Gym Office | 37 1 | EA | 7 | 10+ years | Replace tiles |
| | Lavatory | Men's Gym Office | 1 | EA | 6 | 1-2 years | Rust on sink |
| | Lighting - Lay-in | Men's Gym Office | 1 | EA | 6 | 6-10 years | Rust off Sink |
| | Walls - Concrete Block | Men's Gym Office | 202 | SF | 7 | 10+ years | |
| | Water Closet | Men's Gym Office | 1 | EA | 7 | 10+ years | |
| | Accessories | Women's Gym Office I | 38 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Women's Gym Office I | 38 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Women's Gym Office I | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Women's Gym Office I | 8 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | Women's Gym Office I | 30 | SF | 4 | 0-1 year | Replace damaged or missing tiles |
| | Lavatory | Women's Gym Office I | 1 | EA | 5 | 1-2 years | Replace fixture |
| | Lighting - Lay-in | Women's Gym Office I | 1 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | Women's Gym Office I | 202 | SF | 7 | 10+ years | |
| | Water Closet | Women's Gym Office I | 1 | EA | 7 | 10+ years | |
| | Accessories | Women's Gym Office II | 38 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | Women's Gym Office II | 38 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Women's Gym Office II | 1 | EA | 6 | 6-10 years | |
| | | Women's Cym Omoe II | 1 | | 0 | o io youis | |



| Catego | ry : Room | 10330 S Elizabeth STREET, Chicago, IL 6064 Building : Linked Addition-Athletic Building | | | | | | |
|----------|--|--|--------------|----------|----------|--------------------------|---------------|--|
| Jaleyo | | | D | unung | . Linket | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| oroup | Floor - Tile | Women's Gym Office II | 38 | SF | 6 | 10+ years | Comments | |
| | Lavatory | Women's Gym Office II | 1 | EA | 6 | 6-10 years | | |
| | | | | | | • | | |
| | Lighting - Lay-in | Women's Gym Office II | 1 | EA | 6 | 6-10 years | | |
| | Walls - Concrete Block | Women's Gym Office II | 202 | SF | 6 | 10+ years | | |
| | Water Closet | Women's Gym Office II | 1 | EA | 6 | 6-10 years | | |
| Catego | ry : Classroom | | В | uilding | : Linked | Addition-Ath | etic Building | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments | |
| | om #428 (Regular Classroom) | Location | Quantity | | Nank | Replacement | Comments | |
| Classioo | | | 0.17 | 05 | • | 10 | | |
| | Ceiling - Lay-in | 1st Floor | 317 | SF | 6 | 10+ years | | |
| | Chalk Board | 1st Floor | 18 | LF | 4 | 2-5 years | | |
| | Doors - Side-lite | 1st Floor | 11 | SF | 6 | 10+ years | | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 6 | 10+ years | | |
| | Floor - Tile | 1st Floor | 317 | SF | 6 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 9 | EA | 7 | 6-10 years | | |
| | Walls - Concrete Block | 1st Floor | 1,552 | SF | 6 | 10+ years | | |
| Classroo | om #432 (Regular Classroom) | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 320 | SF | 7 | 10+ years | | |
| | Chalk Board | 1st Floor | 12 | LF | 4 | 2-5 years | | |
| | Doors - Side-lite | 1st Floor | 11 | SF | 7 | 10+ years | | |
| | Doors - Steel Doors incl hw | 1st Floor | 3 | EA | 6 | 6-10 years | | |
| | | | - | | | | | |
| | Floor - Weight/ Fitness Room Floor Matting | 1st Floor | 320 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 9 | EA | 7 | 6-10 years | | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | | |
| | Walls - Concrete Block | 1st Floor | 1,556 | SF | 7 | 10+ years | | |
| Catego | ry : Interior | | В | uilding | : Linked | d Addition-Ath | etic Building | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments | |
| Corridor | | Location | Quantity | 001 | Marik | Replacement | Comments | |
| | Ceiling - Lay-in | 1st Floor | 3,557 | SF | 7 | 6-10 years | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 1,381 | SF | 7 | 10+ years | | |
| | Doors - Store Front | 1st Floor | 1,000 | EA | 7 | 10+ years | | |
| | Drinking Fountains - Double Fountain | 1st Floor | 1,000 | EA | 7 | 6-10 years | | |
| | | | ∡ | | | | | |
| | Drinking Fountains - Single Fountain | 1st Floor | 1 | EA | 7 | 6-10 years | | |
| | Floor - Terrazzo | 1st Floor | 4,938 | SF | 7 | 10+ years | | |
| | Lighting - Lay-in | 1st Floor | 18 | EA | 7 | 6-10 years | | |
| | Lighting - Pendent/Surface | 1st Floor | 33 | EA | 7 | 6-10 years | | |
| | | | | | _ | | | |
| | Walls - Masonry | 1st Floor | 9,759 | SF | 7 | 10+ years | | |
| | | 1st Floor Basement Tunnel to Main | 9,759 745 | SF SF | 7 7 | 10+ years 10+ years | | |



| Catego | ry : Interior | В | uilding | : Linked | d Addition-Athl | etic Building | |
|--------|--------------------------------|-------------------------|----------|----------|-----------------|---------------|------------------------|
| - | | | | - | | Recommend | - |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Ceiling - Plaster/Drywall | Basement Tunnel to Main | 931 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Basement Tunnel to Main | 4 | EA | 6 | 6-10 years | |
| | Floor - Terrazzo | Basement Tunnel to Main | 845 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | Basement Tunnel to Main | 931 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Basement Tunnel to Main | 15 | EA | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | Basement Tunnel to Main | 24 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | Basement Tunnel to Main | 1,801 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | Basement Tunnel to Main | 505 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | Basement Tunnel to Main | 2,026 | SF | 6 | 10+ years | |
| Safety | | | | | | | |
| | Security Cameras | Entire building | 2 | EA | 7 | 6-10 years | |
| | Security Cameras | Entire building | 10 | EA | 7 | 6-10 years | |
| Stairs | | | | | | | |
| | Ceiling - Plaster/Drywall | Mezzanine East to Roof | 333 | SF | 6 | 1-2 years | Paint peeling |
| | Floor - Terrazzo | Mezzanine East to Roof | 195 | SF | 7 | 10+ years | |
| | Handrails | Mezzanine East to Roof | 112 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | Mezzanine East to Roof | 8 | EA | 7 | 6-10 years | |
| | Stairs - Terrazzo | Mezzanine East to Roof | 65 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | Mezzanine East to Roof | 1,991 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Mezzanine West | 225 | SF | 7 | 10+ years | |
| | Ceiling - Plaster/Drywall | Mezzanine West | 100 | SF | 6 | 0-1 year | Peeling paint |
| | Floor - Terrazzo | Mezzanine West | 195 | SF | 7 | 10+ years | |
| | Handrails | Mezzanine West | 112 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | Mezzanine West | 8 | EA | 7 | 6-10 years | |
| | Stairs - Terrazzo | Mezzanine West | 65 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | Mezzanine West | 1,911 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Mezzanine West | 20 | SF | 4 | 0-1 year | Water damage extensive |
| | Ceiling - Plaster/Drywall | Women's Locker Room | 333 | SF | 7 | 10+ years | |
| | Floor - Epoxy/ Painted | Women's Locker Room | 95 | SF | 7 | 10+ years | |
| | Handrails | Women's Locker Room | 50 | LF | 7 | 10+ years | |
| | Lighting - Lay-in | Women's Locker Room | 6 | EA | 7 | 6-10 years | |
| | Stairs - Concrete | Women's Locker Room | 30 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | Women's Locker Room | 1,164 | SF | 7 | 10+ years | |



| ategor | y : Exterior | | В | uilding | : Linkec | Addition-Fine | Arts Building |
|----------|--|-----------------|-----------|---------|----------|---------------|---|
| | Hama Tama | Leastlen | Owentitue | | Daula | Recommend | 0 |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| ntrance | | | | | | | |
| | Exterior Doors - Exterior Steel Door | #10- SW | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | #11- NW | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #5- W | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #5- W | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | #6- NE | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #7- NE | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | #8- W | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | #8- W | 1 | EA | 6 | 10+ years | |
| oundatio | 22 | | | | | | |
| Junualio | Foundation - Concrete | Entire Building | 657 | LF | 7 | 10+ years | |
| | Superstructure - Steel | Entire Building | 27,456 | SF | 7 | 10+ years | |
| | | | , | | | , | |
| ghting | Exterior Lighting - Parapet or Roof Mounted | Entire Building | 5 | EA | 7 | 10+ years | New |
| | Extendi Lighting - Larapet of Roof Mounted | Little Building | 5 | LA | ' | 10+ years | New |
| oof Sys | | | | | | | |
| | Coping - Metal | Link roof | 64 | LF | 7 | 10+ years | |
| | Downspouts - Interior Downspouts | Link roof | 12 | LF | 6 | 10+ years | |
| | Roof - Modified Bitumen | Link roof | 1,001 | SF | 7 | 10+ years | Replaced |
| | Roof Structure - Steel / Metal Deck/ | Link roof | 1,001 | SF | 7 | 10+ years | • |
| | Concrete Topping | | | | | • | |
| | Coping - Metal | Main Roof | 640 | LF | 7 | 10+ years | New |
| | Downspouts - Interior Downspouts | Main Roof | 333 | LF | 6 | 10+ years | |
| | Parapet - 16" - 30" Height | Main Roof | 640 | LF | 7 | 10+ years | Repaired |
| | Roof - Modified Bitumen | Main Roof | 25,225 | SF | 7 | 10+ years | Replaced. Leak noted in enginee survey is under initial warranty. Roofing company is onsite to investigate |
| | Roof Hatch - Metal | Main Roof | 1 | EA | 7 | 10+ years | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Main Roof | 25,225 | SF | 7 | 10+ years | |
| /alls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 21,107 | SF | 7 | 10+ years | |
| | Exterior Walls - Brick | Entire Building | 170 | SF | 4 | 0-1 year | Open joints |
| indows | | | | | | | |
| | Curtain wall - Glazed Single Pane | Entire Building | 3,632 | SF | 5 | 6-10 years | Single glazed |
| | Lintels - Steel | Entire Building | 18 | LF | 5 | 10+ years | |



| Catego | ry : Exterior | | В | uilding | : Linked | Addition-Fine | Arts Building |
|----------|---|------------------------------------|----------|----------|----------|--------------------------|--|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Catego | ry : Electrical | | В | uilding | : Linked | Addition-Fine | Arts Building |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| merger | ncy System | | | | | | |
| | Exit Signs - Auditoium Exit Signs - Corridors and Stairs | Entire Building Entire Building | 6 7 | EA EA | 6 6 | 6-10 years 6-10 years | Exit Signs have been upgraded sinclast assessment. Rank, Reason and Priority Rep adjusted to account for contemporary LED illumination and based on current observations. |
| | Security System - CCTV | Entire Building | 27,456 | SF | 6 | 6-10 years | |
| | Security System - Intrusion Detection | Entire Building | 27,456 | SF | 5 | 6-10 years | |
| Aain Sei | | | | | | | |
| | Main Electrical Service - 1200 A 120/208/3PH | Electrical Room | 1 | EA | 6 | 6-10 years | Location changed for clarification. Item Type changed to match current observations and per review with Building Engineer. |
| | PA System | Entire Building | 27,456 | SF | 6 | 6-10 years | Served by Main |
| Power D | istribution | | | | | | |
| | Lighting and Power Panels - 100 A | 1st Floor | 1 | EA | 4 | 0-1 year | Location changed for clarification. Quantity changed based on current observations. Rank, Reason and Priority Rep changed due to open fuse receptacles which expose live conductors presenting a live front condition. |
| | Lighting and Power Panels - Above 100 A | 1st Floor | 1 | EA | 7 | 10+ years | Location changed for clarification. |
| | Lighting and Power Panels - Above 100 A | 1st Floor | 3 | EA | 7 | 6-10 years | Location changed for clarification. Quantity changed as total has been divided/aggregated. |
| | Lighting and Power Panels - Above 100 A | 1st Floor | 1 | EA | 6 | 10+ years | Located in the control room. Missin a directory. |
| | Lighting and Power Panels - Above 100 A | 1st Floor | 1 | EA | 4 | 0-1 year | Location changed for clarification. Panel in the midst of installation at the time of assessment. Missing cover assembly exposes live conductors presenting a live front condition. |
| | Lighting and Power Panels - Above 100 A | 1st Floor | 1 | EA | 4 | 0-1 year | Location changed for clarification. |



Percy L Julian High School 10330 S Elizabeth STREET, Chicago, IL 60643

| Catego | ry : Electrical | | В | uilding | : Linked | | Arts Building |
|-----------|---|------------------------------------|------------------|----------|----------|--------------------------|--|
| - | | | | - | | Recommend | - |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Main Distribution Panels - Greater than 600 amp | 1st Floor | 1 | EA | 6 | 6-10 years | conductors presenting a live front condition. One switch associated with a circuit involved in a project on the day of assessment and is safely locked- out/tagged-out in full compliance with Code. |
| | Main Distribution Panels - Greater than 600 amp | 1st Floor | 1 | EA | 6 | 6-10 years | Location changed for clarification. Quantity changed as total has been divided/aggregated. |
| | Main Distribution Panels - Greater than 600 amp | 1st Floor | 1 | EA | 4 | 0-1 year | Missing cover plates expose live terminals presenting a live front condition. |
| | Main Distribution Panels - Less than 400 amp | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Main Distribution Panels - Less than 400 amp | 1st Floor | 1 | EA | 6 | 6-10 years | Location changed for clarification. Based on current observations the panel is missing a directory; Rank adjusted as panel is not labeled. |
| | Transformers - 277/480 - 120/208 Transformers - 277/480 - 120/208 | 1st Floor 1st Floor | 1 1 | EA EA | 6 6 | 10+ years 6-10 years | Location changed for clarification. Location changed for clarification. |
| Catego | ry : Fire Protection | | В | uilding | : Linked | Addition-Fine | Arts Building |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Fire Alar | | Location | Quantity | 00111 | Kank | Replacement | ooninients |
| | Fire Alarm Strobe Lights Fire Alarm_System | Entire Building Entire Building | 27,456 27,456 | SF SF | 7 7 | 10+ years 10+ years | |
| Sprinkle | System | | | | | | |
| | Sprinkler Heads Sprinkler Piping | Entire Building Entire Building | 27,456 27,456 | SF SF | 7 6 | 6-10 years 6-10 years | |
| | Wet Sprinkler System | Entire Building | 27,456 | SF | 6 | 6-10 years | Installed in a dedicated closet space located backstage left. |
| Catego | ry : Mechanical | | В | uilding | : Linked | Addition-Fine | Arts Building |
| | - | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Air Hand | lling Systems | _ / | | | | | |
| | Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | Unit only has one operational air conditioning circuit and has exceeded its EUL. |
| | Roof Top Unit-Multi Zone-Roof Mounted- | Roof | 1 | EA | 4 | 2-5 years | Unit only has one operational air |



Percy L Julian High School 10330 S Elizabeth STREET, Chicago, IL 60643

| Catego | ry : Mechanical | В | Building : Linked Addition-Fine Arts Building | | | | | |
|------------|--|-----------------|---|-----|------|-------------|---|--|
| | | | | | | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments | |
| | Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons Roof Top Unit-Multi Zone-Roof Mounted- Gas Heating and DX Cooling w/ Self Contained Compressor - 46 - 60 tons | Roof | 1 | EA | 4 | 2-5 years | conditioning circuit and has exceeded its EUL. Unit only has one operational air conditioning circuit and has exceeded its EUL. | |
| | Roof Top Unit-Single Zone-Roof Mounted- Gas Heating and DX Cooling Coil - 11 - 20 tons | Roof | 1 | EA | 5 | 2-5 years | Dataplate no longer present. | |
| Heating | Devices | | | | | | | |
| | Fin Tube - Electric | 1st Floor | 30 | LF | 7 | 10+ years | | |
| Tempera | ature Control | | | | | | | |
| · | Pneumatic System | Entire Building | 27,456 | SF | 5 | 6-10 years | Temperature control for this building is accomplished via the pneumatic system located in Main. | |
| | Thermostats - Pneumatic | Entire Building | 18 | EA | 5 | 6-10 years | System located in Main. | |
| Ventilatio | on | | | | | | | |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 CFM | Roof | 1 | EA | 7 | 6-10 years | Replaced with new equipment since last assessment. Rank adjusted based on current observations. | |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Roof | 1 | EA | 7 | 6-10 years | Replaced with new equipment since last assessment. Rank adjusted based on current observations. | |

Category : Plumbing

Building : Linked Addition-Fine Arts Building

| Group Piping | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------|---|-----------------|----------|-----|------|--------------------------|--|
| - 1 - 3 | Domestic Piping-Hot Water Return Lines | Entire Building | 27,456 | SF | 4 | 2-5 years | Domestic water supplied from Main. Galvanized material over 40 years old with notable corrosion and some pipe clamps. |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 27,456 | SF | 4 | 2-5 years | Domestic water supplied from Main. Galvanized material over 40 years old with notable corrosion and some pipe clamps. |
| | Sanitary Piping | Entire Building | 27,456 | SF | 4 | 2-5 years | Galvanized material over 40 years old. Notable corrosion reported by building engineer. |
| | Storm Piping | Entire Building | 27,456 | SF | 4 | 2-5 years | Galvanized material over 40 years old with notable corrosion throughout |



Percy L Julian High School

| | ory : Plumbing | | В | uilding | : Linked | | Arts Building |
|-----------|--|--|---|--|--|---|---|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Jioup | Vent Piping | Entire Building | 27,456 | SF | 4 | 2-5 years | much of the building. Roof drain piping in north area of the building experiencing an active leak at the time of assessment. Galvanized material over 40 years old. Notable corrosion reported by building engineer. |
| Pumps | | | | | | | |
| | Pumps - Sump-Simplex Pumps - Sump-Simplex | Entire Building Entire Building | 1 | EA EA | 6 | 6-10 years 6-10 years | Located at the bottom of the elevato pit. The pump with its dataplate and CPS Asset Tag were not accessible at the time of assessment. Body of pump embossed with mfr. name and a number but otherwise n dataplate present. |
| Catego | ory : Room | | В | uilding | : Linked | Addition-Fine | Arts Building |
| | - | | | Ŭ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Adminis | trative Suites/Offices | | | | | | |
| | Ceiling - Lay-in | 1st- Boy's Dressing Room | 228 | SF | 7 | 6-10 years | |
| | Doors - Steel Doors incl hw | 1st- Boy's Dressing Room | | EA | 7 | 6-10 years | |
| | | | | | | | |
| | | | 1 228 | | | • | |
| | Floor - Tile | 1st- Boy's Dressing Room | 228 | SF | 7 | 10+ years | |
| | Floor - Tile Lighting - Lay-in | 1st- Boy's Dressing Room 1st- Boy's Dressing Room | 228 8 | SF EA | 7 6 | 10+ years 6-10 years | |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room | 228 8 496 | SF EA SF | 7 6 7 | 10+ years 6-10 years 10+ years | Missing or damaged tiles |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room | 228 8 496 198 | SF EA SF SF | 7 6 7 5 | 10+ years 6-10 years 10+ years 0-1 year | Missing or damaged tiles |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room 1st- Girl's Dressing Room | 228 8 496 198 1 | SF EA SF SF EA | 7 6 7 5 7 | 10+ years 6-10 years 10+ years 0-1 year 10+ years | Missing or damaged tiles |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room 1st- Girl's Dressing Room 1st- Girl's Dressing Room | 228 8 496 198 1 9 | SF EA SF EA SF | 7 6 7 5 7 7 | 10+ years 6-10 years 10+ years 0-1 year 10+ years 10+ years | Missing or damaged tiles |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room 1st- Girl's Dressing Room 1st- Girl's Dressing Room 1st- Girl's Dressing Room | 228 8 496 198 1 9 198 | SF EA SF EA SF SF | 7 6 7 5 7 6 | 10+ years 6-10 years 10+ years 0-1 year 10+ years 10+ years 10+ years | Missing or damaged tiles |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Lay-in | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room 1st- Girl's Dressing Room 1st- Girl's Dressing Room 1st- Girl's Dressing Room | 228 8 496 198 1 9 198 7 | SF EA SF EA SF EA EA | 7 6 7 5 7 7 6 6 | 10+ years 6-10 years 10+ years 0-1 year 10+ years 10+ years 10+ years 6-10 years | Missing or damaged tiles |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Lay-in Walls - Concrete Block | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room | 228 8 496 198 1 9 198 7 456 | SF EA SF EA SF EA SF SF | 7 6 7 5 7 6 6 7 | 10+ years 6-10 years 10+ years 0-1 year 10+ years 10+ years 6-10 years 10+ years | Missing or damaged tiles |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Plaster/Drywall | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room 1st- Make-Up Room | 228 8 496 198 1 9 198 7 456 247 | SF SF SF SF SF SF SF SF | 7 6 7 5 7 6 6 7 7 | 10+ years 6-10 years 10+ years 0-1 year 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years | Missing or damaged tiles |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room 1st- Make-Up Room 1st- Make-Up Room | 228 8 496 198 1 9 198 7 456 247 2 | SF SFA SFA SFA SFA SFA SFA SFA | 7 6 7 5 7 6 6 7 7 7 | 10+ years 6-10 years 0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years | Missing or damaged tiles |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room | 228 8 496 198 1 9 198 7 456 247 2 247 | SF SFA SFA SFA SFA SFA SF SFA SF | 7 6 7 5 7 6 6 7 7 7 7 | 10+ years 6-10 years 0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years | Missing or damaged tiles |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room | 228 8 496 198 1 9 198 7 456 247 2 247 10 | SFAFFAFFAFFA SFAFFAFFAFFA SFAFFAFFA SFAFFAFFA | 7 6 7 5 7 6 6 7 7 7 6 | 10+ years 6-10 years 0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years | Missing or damaged tiles |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Lighting - Wall Mounted | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room | 228 8 496 198 1 9 198 7 456 247 2 247 10 19 | SFAFFAFFAFFAFA SESFAFFAFFAF ESFAFFAFFAF EA | 7 6 7 5 7 6 6 7 7 6 6 | 10+ years 6-10 years 0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years | Missing or damaged tiles |
| | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room | 228 8 496 198 1 9 198 7 456 247 2 247 10 | SFAFFAFFAFFA SFAFFAFFAFFA SFAFFAFFA SFAFFAFFA | 7 6 7 5 7 6 6 7 7 7 6 | 10+ years 6-10 years 0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years | Missing or damaged tiles |
| Auditoriu | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Lighting - Lay-in Lighting - Wall Mounted Walls - Concrete Block Work Sink | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room | 228 8 496 198 1 9 198 7 456 247 2 247 10 19 552 | SFAFFAFFAFAAF SFAFFAFFAFAAF SFAFFAFFAFAAF | 7 6 7 5 7 6 6 7 7 6 6 7 | 10+ years 6-10 years 0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years | |
| uditoriu | Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Splined Doors - Steel Doors incl hw Doors - Transom Window Floor - Tile Lighting - Lay-in Walls - Concrete Block Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Lay-in Lighting - Wall Mounted Walls - Concrete Block | 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Boy's Dressing Room 1st- Girl's Dressing Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room 1st- Make-Up Room | 228 8 496 198 1 9 198 7 456 247 2 247 10 19 552 | SFAFFAFFAFAAF SFAFFAFFAFAAF SFAFFAFFAFAAF | 7 6 7 5 7 6 6 7 7 6 6 7 | 10+ years 6-10 years 0-1 year 10+ years 10+ years 10+ years 6-10 years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years | |



| Catego | ry : Room | | В | uilding | : Linked | Addition-Fine | e Arts Building |
|----------------|--------------------------------|---------------------------------|------------|----------|----------|---------------|----------------------------------|
| - | • | | | _ | | Recommend | U |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Steel Doors incl hw | 1st Floor | 6 | EA | 7 | 10+ years | |
| | Floor - Carpet | 1st Floor | 7,073 | SF | 7 | 6-10 years | |
| | Floor - Wood | 1st Floor | 2,733 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 47 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | 1st Floor | 6 | EA | 7 | 6-10 years | |
| | Main Floor Seating | 1st Floor | 798 | EA | 7 | 6-10 years | |
| | Sound System | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Stage | 1st Floor | 2,733 | SF | 7 | 10+ years | |
| | Stage Curtain | 1st Floor | 2,700 | EA | 7 | 10+ years | |
| | Stage Lighting System | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Stage-Stairs - Wood | 1st Floor | 14 | LA | 7 | 10+ years | |
| | Stairs - Wood Stairs - Wood | 1st Floor | 50 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | | SF | 7 | | |
| | | | 5,248 | SF | | 10+ years | |
| | Walls - Masonry | 1st Floor | 7,966 | SF | 7 | 10+ years | |
| | Ceiling - Exposed | Backstage area (Rm 172A on map) | 150 | SF | 7 | 10+ years | Missing any ustan stain ad tiles |
| | Ceiling - Lay-in | Backstage area (Rm 172A on map) | 40 | | 4 | 1-2 years | Missing or water stained tiles. |
| | Ceiling - Splined | Backstage area (Rm 172A on map) | 798 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | Backstage area (Rm 172A on map) | 2 | EA | 7 | 10+ years | |
| | Floor - Concrete | Backstage area (Rm 172A on map) | 875 | SF | 7 | 10+ years | |
| | Floor - Terrazzo | Backstage area (Rm 172A on map) | 113 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Backstage area (Rm 172A on map) | 16 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | Backstage area (Rm 172A on map) | 6 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | Backstage area (Rm 172A on map) | 1 | EA | 6 | 6-10 years | |
| | Stage Lift | Backstage area (Rm 172A on map) | 1 | EA | 7 | 6-10 years | |
| | Stairs - Terrazzo | Backstage area (Rm 172A on map) | 69 | LF | 7 | 10+ years | |
| | Storage/ Closet | Backstage area (Rm 172A on map) | 61 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Backstage area (Rm 172A on map) | 6 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Backstage area (Rm 172A on map) | 4,026 | SF | 7 | 10+ years | |
| | Ceiling - Splined | Projection Room for Auditorium | 426 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Projection Room for Auditorium | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | Projection Room for Auditorium | 426 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | Projection Room for Auditorium | 7 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | Projection Room for Auditorium | 1,500 | SF | 6 | 10+ years | |
| <u>lechani</u> | cal/ Service Rooms | | | | | | |
| | Janitor's Closet | 1st Floor | 25 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 479 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 82 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | Basement | 474 | SF | 7 | 10+ years | |
| | Storage Room | Basement | 48 | SF | 7 | 10+ years | |
| | | | .0 | | • | .e. jouro | |
| Restroor | | 1et Doule | 050 | | 7 | 6.10 | |
| | Accessories | 1st- Boy's 1st- Boy's | 256 256 | SF SF | 7 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | ISI- DUY S | 200 | 35 | (| 10+ years | |



| Catego | ry : Room | | В | uildina | : Linked | d Addition-Fine | e Arts Building |
|--------|---------------------------------|-----------------------------------|----------|---------|----------|-----------------|-----------------|
| | • | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| - | Doors - Steel Doors incl hw | 1st- Boy's | 1 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 1st- Boy's | 256 | SF | 7 | 10+ years | |
| | Floor Drain | 1st- Boy's | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st- Boy's | 2 | EA | 7 | 6-10 years | |
| | Lavatory | 1st- Boy's | 3 | EA | 6 | 6-10 years | |
| | Lighting - Lay-in | 1st- Boy's | 12 | EA | 7 | 6-10 years | |
| | Partitions | 1st- Boy's | 4 | EA | 7 | 10+ years | |
| | Urinals | 1st- Boy's | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st- Boy's | 260 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st- Boy's | 260 | SF | 7 | 10+ years | |
| | Water Closet | 1st- Boy's | 4 | EA | 7 | 10+ years | |
| | Accessories | 1st- Boy's (inside Boy's Dressing | 101 | SF | 7 | 6-10 years | |
| | | Room) | | | | | |
| | Ceiling - Plaster/Drywall | 1st- Boy's (inside Boy's Dressing | 101 | SF | 7 | 10+ years | |
| | | Room) | | | | | |
| | Doors - Wood Doors inclu hw | 1st- Boy's (inside Boy's Dressing | 1 | EA | 7 | 10+ years | |
| | | Room) | | | | | |
| | Floor - Terrazzo | 1st- Boy's (inside Boy's Dressing | 101 | SF | 7 | 10+ years | |
| | | Room) | | | | | |
| | Floor Drain | 1st- Boy's (inside Boy's Dressing | 2 | EA | 7 | 10+ years | |
| | | Room) | | | | | |
| | Hand Dryer | 1st- Boy's (inside Boy's Dressing | 1 | EA | 7 | 6-10 years | |
| | | Room) | | | | | |
| | Lavatory | 1st- Boy's (inside Boy's Dressing | 1 | EA | 7 | 10+ years | |
| | | Room) | | | | | |
| | Lighting - Lay-in | 1st- Boy's (inside Boy's Dressing | 3 | EA | 6 | 6-10 years | |
| | | Room) | | | | | |
| | Partitions | 1st- Boy's (inside Boy's Dressing | 1 | EA | 5 | 10+ years | |
| | | Room) | | | | | |
| | Showers | 1st- Boy's (inside Boy's Dressing | 1 | EA | 5 | 10+ years | |
| | | Room) | | | | | |
| | Walls - Concrete Block | 1st- Boy's (inside Boy's Dressing | 324 | SF | 7 | 10+ years | |
| | | Room) | | | | | |
| | Walls - Tile Ceramic/ Porcelain | 1st- Boy's (inside Boy's Dressing | 72 | SF | 7 | 10+ years | |
| | | Room) | | | | | |
| | Water Closet | 1st- Boy's (inside Boy's Dressing | 1 | EA | 7 | 6-10 years | |
| | | Room) | | | | | |
| | Accessories | 1st- Girl's | 225 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st- Girl's | 225 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st- Girl's | 1 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 1st- Girl's | 225 | SF | 7 | 10+ years | |
| | Floor Drain | 1st- Girl's | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st- Girl's | 2 | EA | 7 | 6-10 years | |
| | | | | | | | |



| Catego | ry : Room | Building : Linked Addition-Fine Arts Building | | | | | |
|--------|---------------------------------|---|----------|-----|------|-------------|----------|
| | | | | J | | Recommend | 5 |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Lay-in | 1st- Girl's | 12 | EA | 7 | 6-10 years | |
| | Lighting - Wall Mounted | 1st- Girl's | 1 | EA | 7 | 6-10 years | |
| | Partitions | 1st- Girl's | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st- Girl's | 156 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st- Girl's | 388 | SF | 7 | 10+ years | |
| | Water Closet | 1st- Girl's | 4 | EA | 7 | 10+ years | |
| | Accessories | 1st- Girl's (inside Girl's Dressing | 101 | SF | 7 | 6-10 years | |
| | | Room) | | | | | |
| | Ceiling - Plaster/Drywall | 1st- Girl's (inside Girl's Dressing Room) | 101 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st- Girl's (inside Girl's Dressing Room) | 1 | EA | 7 | 10+ years | |
| | Floor - Terrazzo | 1st- Girl's (inside Girl's Dressing Room) | 101 | SF | 7 | 10+ years | |
| | Floor Drain | 1st- Girl's (inside Girl's Dressing Room) | 2 | EA | 7 | 10+ years | |
| | Hand Dryer | 1st- Girl's (inside Girl's Dressing Room) | 1 | EA | 7 | 10+ years | |
| | Lavatory | 1st- Girl's (inside Girl's Dressing Room) | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 1st- Girl's (inside Girl's Dressing Room) | 3 | EA | 6 | 6-10 years | |
| | Partitions | 1st- Girl's (inside Girl's Dressing Room) | 1 | EA | 7 | 10+ years | |
| | Showers | 1st- Girl's (inside Girl's Dressing Room) | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st- Girl's (inside Girl's Dressing Room) | 324 | SF | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st- Girl's (inside Girl's Dressing Room) | 72 | SF | 7 | 10+ years | |
| | Water Closet | 1st- Girl's (inside Girl's Dressing Room) | 1 | EA | 7 | 10+ years | |

Category : Classroom

Building : Linked Addition-Fine Arts Building

| Group Item - | Туре | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------------|---|-----------|----------|-----|------|--------------------------|----------|
| Classroom #150 | (Store Room) | | | | | | |
| Ceiling | ⊢ - Lay-in | 1st Floor | 714 | SF | 7 | 10+ years | |
| Chalk I | Board | 1st Floor | 10 | LF | 4 | 2-5 years | |
| Doors | Steel Doors incl hw | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Doors | - Transom Window | 1st Floor | 4 | SF | 7 | 6-10 years | |
| Floor - | Carpet | 1st Floor | 714 | SF | 6 | 6-10 years | |
| Lightin | g - Lay-in | 1st Floor | 20 | EA | 7 | 6-10 years | |
| Marker | Board | 1st Floor | 12 | LF | 7 | 6-10 years | |



Building : Linked Addition-Fine Arts Building Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments SF Walls - Concrete Block 1st Floor 2.580 7 10+ vears Classroom #151 (Music Room) 1st Floor 1,206 SF 7 Ceiling - Splined 10+ years Doors - Steel Doors incl hw ΕA 7 10+ years 1st Floor 2 Floor - Concrete SF 7 1st Floor 1.206 10+ years Lighting - Lay-in 1st Floor 39 FΑ 7 10+ years 20 LF Marker Board 1st Floor 6 6-10 years SF 7 Walls - Concrete Block 1st Floor 1.782 10+ years SF Walls - Plaster/Drywall 1st Floor 570 7 10+ years Classroom #152 (Music Room) SF Ceiling - Splined 1st Floor 1.206 6 10+ years Doors - Steel Doors incl hw 1st Floor ΕA 7 10+ vears 1 SF Floor - Concrete 1st Floor 1,206 7 10+ years Lighting - Lay-in 1st Floor 39 ΕA 7 10+ years Marker Board 20 LF 6-10 years 1st Floor 6 SF 7 Walls - Concrete Block 1st Floor 1.782 10+ years SF 570 7 Walls - Plaster/Drywall 1st Floor 10+ years Classroom #160 (Store Room) Ceiling - Lay-in SF 7 1st Floor 726 6-10 years Ceiling - Lay-in 1st Floor 30 SF 5 1-2 years Messing or water stained tiles. 7 Doors - Steel Doors incl hw 1st Floor 2 ΕA 10+ years SF Doors - Transom Window 1st Floor 12 7 10+ years SF Floor - Tile 1st Floor 756 7 10+ years ΕA Lighting - Lav-in 1st Floor 20 6 6-10 vears Lighting - Wall Mounted 1st Floor 1 ΕA 6 6-10 vears Marker Board 1st Floor 12 LF 7 6-10 years Storage/ Closet SF 7 1st Floor 308 6-10 years Walls - Concrete Block SF 7 2,640 10+ years 1st Floor Classroom #165 (Special Program) Ceiling - Lay-in 1st Floor SF 7 480 10+ years Chalk Board LF 1st Floor 6 4 2-5 years Doors - Steel Doors incl hw 1st Floor ΕA 7 1 10+ years SF Doors - Transom Window 1st Floor 6 7 10+ years SF Floor - Carpet 1st Floor 480 6 6-10 years Lighting - Lay-in 1st Floor ΕA 7 6-10 years 10 Marker Board LF 7 1st Floor 12 6-10 years Walls - Concrete Block 1st Floor 2.124 SF 7 10+ years



Building : Linked Addition-Fine Arts Building Category : Interior Recommend Quantity Group Item - Type Location UOM Rank **Replacement** Comments Corridor Ceiling - Plaster/Drywall 214 SF 6 1st Floor 10+ years Ceiling - Splined 1st Floor 3,527 SF 6 6-10 years Ceiling - Splined 500 SF 3 0-1 year 1st Floor Water stained or missing Doors - Side-lite SF 7 10+ years 1st Floor 112 Doors - Store Front FΑ 7 1st Floor 10+ years 4 Doors - Transom Window 1st Floor 36 SF 7 10+ years Drinking Fountains - Single Fountain 1st Floor 4 FΑ 7 6-10 years SF Floor - Terrazzo 1st Floor 4.241 7 10+ years Lighting - Lay-in 1st Floor 90 EΑ 6 6-10 years Walls - Masonry 5,766 SF 7 1st Floor 10+ years Ceiling - Exposed Basement 408 SF 7 10+ years Doors - Steel Doors incl hw Basement ΕA 7 1 10+ years SF Floor - Concrete Basement 408 7 10+ years Lighting - Pendent/Surface ΕA 6-10 years Basement 6 7 Walls - Concrete Block Basement 1.209 SF 7 10+ years Safety Metal Detector 1 FΑ 7 Entire building 6-10 years Security Cameras Entire building 10 FΑ 7 6-10 years Security Cameras ΕA Entire building 2 7 6-10 years Stairs Ceiling - Plaster/Drywall Basement 194 SF 7 10+ years Floor - Concrete SF Basement 16 7 10+ years LF Handrails 30 7 10+ years Basement Lighting - Pendent/Surface 3 ΕA Basement 6 6-10 vears Stairs - Concrete LF Basement 4 7 10+ years Stairs - Concrete Basement 11 LF 7 10+ years Walls - Concrete Block 385 SF 7 Basement 10+ years Vertical Convevance Elevator - Elevator- Machine Roomless 1st Floor 1 FΑ 7 10+ years 1st Floor ΕA 7 Wheelchair Lift - Platform Lift 1 6-10 years



Category : Site Building : Site Recommend Location Item - Type Quantity UOM Replacement **Comments** Group Rank Athletic SF Surface - Asphalt South 26.870 4 Cracking and vegetation throughout 0-1 year ΕA Liahtina South 4 1-2 vears Not working 4 Surface - Natural 56,310 SF Not maintained South 4 0-1 year Surface - Asphalt South 12,816 SF 4 0-1 year Cracking and vegetation throughout Civil/Drainage Civil/ Drainage - Catch Basin Entire Site 16 ΕA 6 10+ years Civil/ Drainage - Site Drain Entire Site ΕA 6 6-10 years 1 Civil/ Drainage - Site Manhole ΕA Entire Site 14 6 10+ years Fencina Fencing - Chain Link Entire Site 2,463 LF 6 10+ years LF Fencing - Chain Link **Entire Site** 50 5 0-1 vear Broken, falling down LF Fencing - Guard Rail Entire Site 379 6 10+ years LF Entire Site 6 Fencing - Wood Fencing w/ Steel Frame 353 10+ years Fencing - Wood Fencing w/ Steel Frame Entire Site 50 LF 5 0-1 year Broken sections Landscape SF Landscape - Grass Entire Site 56.310 6 6-10 years Landscape - Hardscape- Concrete Entire Site 5,660 SF 6 10+ years Landscape - Hardscape- Concrete Entire Site 30,216 SF 6 10+ years SF Landscape - Hardscape- Concrete Entire Site 3,300 5 1-2 years Extensive ponding over underground tunnel SF Landscape - Hardscape- Pavers **Entire Site** 900 6 10+ years Lighting - Pole Mounted **Entire Site** 17 ΕA 6 6-10 years Parkway trees Entire Site 40 FΑ 6 6-10 vears Parkway trees Entire Site 2 ΕA 4 1-2 vears Missina SF 6 Planting Beds/ Area Entire Site 15.972 10+ years Retaining Wall - Concrete Entire Site 535 SF 6 10+ years Parking Lot LF Interior Plantings Parking Lot- East 60 6 6-10 years Lighting - Pole Mounted Parking Lot- East 4 FΑ 6 6-10 years Pavers Parking Lot- East 1,200 SF 6 10+ years SF Surface - Concrete Parking Lot- East 29,081 5 10+ years Not designed as a parking lot. No striping, settling, no proper curb cuts or driveways Concrete Curbs Parking Lot- West 2.355 LF 6 10+ vears LF Interior Plantings Parking Lot- West 45 6 6-10 years Lighting - Pole Mounted Parking Lot- West 2 ΕA 6 6-10 vears Surface - Asphalt SF Parking Lot- West 29,750 6 10+ years



Building : Site Category : Site Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments 17,430 SF 10+ years Raveling, alligator cracking, pot holes Surface - Asphalt Parking Lot- West 5 throughout Surface - Concrete Parking Lot- West 9.178 SF 6 10+ years ΕA 6 Trash Compactor Parking Lot- West 1 6-10 years Sidewalks Sidewalks - Internal Walks Entire Site 1.025 LF 6 10+ years LF Sidewalks - Internal Walks Entire Site 50 5 1-2 years Cracks, spalling, sunken SF 7 Sidewalks - Perimeter Sidewalks Entire Site 18.761 10+ years New SF Sidewalks - Perimeter Sidewalks Entire Site 50 4 0-1 year Cracked, spalling Signage Flag Pole - Flag Pole ΕA Entire Site 2 6 10+ years Marquee - Free Standing Back lighted w/ **Entire Site** 1 EΑ 6 10+ years LED Monument - Building Mounted Cut Letter **Entire Site** 1 ΕA 6 10+ years Sign 2 Monument - Building Mounted Cut Letter Entire Site EA 6 10+ years Sign

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

| | | _ | Room | Floor Plan Room | Area | Glazed Window | Operable Window | Window | Smart- |
|--|--|------------------------|---------|--------------------|-------|------------------|--------------------|--------|--------|
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |
| Building : Main | | | 140 | 110 | 070 | 400 | | | |
| Art Room | Art Room | 1st Floor | 118 | 118 | 870 | 168 | 0 | N | N |
| Computer Lab | Computer Lab | 2nd Floor | 214 | 214 | 811 | 192 | 0 | N | N |
| Computer Lab | Computer Lab | 2nd Floor | 217 | 219 | 1,360 | 252 | 0 | N | Y |
| Computer Lab | Computer Lab | 2nd Floor | 218 | 218 | 1,257 | 186 | 0 | N | Y |
| Computer Lab | Computer Lab | 2nd Floor | 220 | 220 | 754 | 186 | 0 | N | N |
| Computer Lab | Computer Lab | 2nd Floor | 221 | 221 | 1,168 | 372 | 0 | N | N |
| Computer Lab | Regular Classroom | 1st Floor | 121 | 121 | 1,214 | 0 | 0 | N | N |
| Computer Lab | Regular Classroom | 2nd Floor | 215 | 214 | 751 | 160 | 0 | N | N |
| Laboratory/Shop | Laboratory/Shop | 1st Floor | 103 | 103 | 1,300 | 348 | 0 | N | Y |
| Multi Purpose Room | Regular Classroom | 2nd Floor | 210/211 | 210/211 | 624 | 320 | 0 | N | N |
| Music Room | Computer Lab | 1st Floor | 116A | 116 | 780 | 214 | 0 | N | N |
| Office | Computer Lab | 1st Floor | 115A | 115A | 900 | 426 | 0 | N | N |
| Office | Science | 1st Floor | 107A | 107A | 475 | 0 | 0 | N | N |
| Other Instructional Use | Computer Lab | 1st Floor | 115B | 115B | 900 | 33 | 0 | N | N |
| Other Instructional Use | Other Instructional Use | 1st Floor | 114A | 114 | 1,477 | 0 | 0 | N | N |
| Regular Classroom | Laboratory/Shop | 1st Floor | 116B | 116 | 650 | 212 | 0 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 100 | 001 | 673 | 196 | 0 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 1004 | 004 | 778 | 140 | 0 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 1005 | 102B | 570 | 0 | 0 | N | N |
| Regular Classroom | Regular Classroom | 1st Floor | 101A | 002 | 673 | 168 | 0 | N | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 101B | 003 | 785 | 389 | 0 | N | Ν |
| Regular Classroom | Regular Classroom | 1st Floor | 119 | 119 | 778 | 308 | 0 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 755 | 155 | 0 | N | Ν |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 771 | 341 | 0 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 204 | 204 | 759 | 155 | 0 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 757 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 759 | 160 | 0 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | 207 | 759 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 757 | 160 | 0 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 757 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 213 | 213 | 439 | 0 | 0 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 216 | 216 | 441 | 0 | 0 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 219 | 210 | 902 | 186 | 0 | N | N |
| Regular Classroom | Regular Classroom | 2nd Floor | 240 | 240 | 1,276 | 189 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 240 | 240 | 455 | 96 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 302 | 302 | 753 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 303 | 303 | 795 | 352 | 0 | N | N |
| Regular Classroom Regular Classroom | Regular Classroom Regular Classroom | 3rd Floor 3rd Floor | 303 | 303 | 795 | 352 160 | 0 | N N | N N |
| Regular Classroom | Regular Classroom | 310 F1001 | 304 | 304 | /5/ | 160 | U | IN | IN |



Classroom Summary

| 10330 S Elizabeth STREET, Chicago, IL 60643 | | | | | | | | |
|---|------|------------------|--------------------|--------|--------|--|--|--|
| Floor Plan Room | Area | Glazed Window | Operable Window | Window | Smart- | | | |

| Current Usage | Intended Usage | Room Location | Room Number | Room Number | Area (SF) | Window Area | Window Area | Window Stop | Smart- Board |
|-----------------------------|--------------------|---------------|----------------|----------------|--------------|----------------|----------------|----------------|-----------------|
| Regular Classroom | Regular Classroom | 3rd Floor | 305 | 305 | 753 | 160 | 0 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 306 | 306 | 755 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 307 | 307 | 753 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 308 | 308 | 755 | 160 | 0 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 309 | 309 | 753 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 312 | 312 | 407 | 0 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 320 | 320 | 436 | 0 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 323 | 323 | 752 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 324 | 324 | 757 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 325 | 325 | 757 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 326 | 326 | 757 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 327 | 327 | 753 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 328 | 328 | 755 | 160 | 0 | N | N |
| Regular Classroom | Regular Classroom | 3rd Floor | 329 | 329 | 778 | 352 | 0 | N | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 330 | 330 | 750 | 160 | 0 | N | N |
| Regular Classroom | Science | 3rd Floor | 315 | 315 | 485 | 0 | 0 | N | N |
| Regular Classroom | Science | 3rd Floor | 317 | 317 | 481 | 0 | 0 | N | N |
| Science | Science | 1st Floor | 106 | 106 | 1,170 | 168 | 0 | N | N |
| Science | Science | 3rd Floor | 313 | 313 | 602 | 128 | 0 | N | N |
| Science | Science | 3rd Floor | 314A | 314 | 1,209 | 256 | 0 | N | N |
| Science | Science | 3rd Floor | 316 | 316 | 1,200 | 256 | 0 | N | Y |
| Science | Science | 3rd Floor | 318 | 318 | 602 | 128 | 0 | N | N |
| Science Lab Level 1 | Science | 2nd Floor | 242 | 242 | 1,329 | 267 | 0 | N | Y |
| Science Lab Level 3 | Science | 3rd Floor | 319 | 319 | 1,209 | 320 | 0 | N | N |
| Special Education | Special Education | 3rd Floor | 310, 311 | 310, 311 | 944 | 416 | 1 | N | N |
| Special Education | Special Education | 3rd Floor | 322 | 322 | 523 | 320 | 0 | N | N |
| Special Program | Special Program | 1st Floor | 112 | 112 | 1,505 | 0 | 0 | N | N |
| Special Program | Special Program | 1st Floor | 113 | 113 | 1,498 | 348 | 0 | N | N |
| Special Program | Special Program | 1st Floor | 117 | 117 | 1,429 | 0 | 0 | N | N |
| Store Room | Art Room | 1st Floor | 120 | 120 | 778 | 168 | 0 | N | N |
| Building : Linked Addition- | Fine Arts Building | | | | | | | | |
| Music Room | Music Room | 1st Floor | 151 | 151 | 1,206 | 0 | 0 | N | N |
| Music Room | Music Room | 1st Floor | 152 | 152 | 1,206 | 0 | 0 | N | N |
| Special Program | Regular Classroom | 1st Floor | 165 | | 480 | 234 | 0 | N | Y |
| Store Room | Music Room | 1st Floor | 150 | 150 | 714 | 234 | 0 | N | N |
| Store Room | Regular Classroom | 1st Floor | 160 | 153 | 756 | 0 | 0 | N | Ν |
| Building : Linked Addition- | | | | | | | | | |
| Regular Classroom | Regular Classroom | 1st Floor | 428 | 428 | 317 | 781 | 0 | N | Y |
| Regular Classroom | Regular Classroom | 1st Floor | 432 | 432 | 320 | 780 | 0 | N | N |



Classroom Summary

| | | | | Floor Plan | | Glazed | Operable | | |
|---------------|----------------|---------------|--------|------------|------|--------|----------|--------|--------|
| | | | Room | Room | Area | Window | Window | Window | Smart- |
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |