

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1918	3	98,284
Addition	1928	3	89,800
Campus Total			188,084

Category : Exterior			В	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	3						
	Entrance Control - Audio and Video	#1 - N	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#1 - N	2	EA	5	6-10 years	
	Exterior Doors - Transom Lite	#1 - N	4	EA	6	10+ years	
	Exterior Stairs - Concrete	#1 - N	150	LF	7	10+ years	
	Power Door Operator and Controls	#1 - N	2	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	#1 - N	65	LF	6	10+ years	
	Ramps - Concrete	#1 - N	50	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1 - N	30	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#2 - N	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2 - N	4	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 - N	72	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#3 - N	2	EA	5	6-10 years	
	Exterior Doors - Transom Lite	#3 - N	4	EA	6	10+ years	
	Exterior Stairs - Concrete	#3 - N	66	LF	6	10+ years	
	Exterior Stairs - Concrete	#3 - N	6	LF	5	1-2 years	Cracking /chipping
	Exterior Doors - Exterior FRP Door	#4 - N	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 - N	4	EA	6	10+ years	
	Exterior Stairs - Concrete	#4 - N	72	LF	6	10+ years	
	Entrance Control - Audio and Video	#8 - W	1	EA	6	6-10 years	
	Exterior Doors - Exterior FRP Door	#8 - W	3	EA	6	6-10 years	
	Exterior Doors - Side lite	#8 - W	1	EA	5	6-10 years	
	Exterior Doors - Transom Lite	#8 - W	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#8 - W	60	LF	6	10+ years	



Catogo	ry : Exterior		P	uilding	· Main		4343 W Wrightwood, Chicago, IL 6063
Calego	ry. Exterior		D	unung	. พลาก	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Power Door Operator and Controls	#8 - W	Quantity 1	EA	7	6-10 years	Comments
	Ramp Handrail - Steel_Ramp Handrail	#8 - W	65	LF	6	10+ years	
	Ramps - Concrete	#8 - W	36	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#8 - W	15	LF	6		
	Exterior Doors - Exterior Wood Door	Roof Door	15	EA	4	10+ years	Changed to match ourrent
	Exterior Doors - Exterior wood Door	ROOI DOOI	I	EA	4	0-1 year	Changed to match current
							observations Deteriorating.
Foundat	ion						
	Foundation - Concrete	Entire Building	702	LF	6	10+ years	
	Foundation - Concrete	Entire Building	60	LF	5	0-1 year	Deteriorating/exposed rebar
	Superstructure - Steel with Clay Tile Arch	Entire Building	98,284	SF	7	10+ years	
		-				-	
ighting	Exterior Lighting - Wall Mounted	Entire Building	8	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	8 7	EA	6	6-10 years	
	Exterior Lighting - Wair Mounted	Entite Building	1	LA	0	0-10 years	
Roof Sys							
	Downspouts - Interior Downspouts	1 - Main Roof	114	LF	6	10+ years	
	Roof - Metal	1 - Main Roof	360	SF	4	0-1 year	Rusted
	Roof - Modified Bitumen	1 - Main Roof	7,998	SF	4	1-2 years	Cracking/bubbling/soft spots
	Roof Structure - Steel with Clay Tile Arch	1 - Main Roof	8,358	SF	7	10+ years	
	Access Ladder - Metal	2 - North High Roof	1	EA	7	10+ years	
	Coping - Metal	2 - North High Roof	236	LF	5	2-5 years	Rusted
	Downspouts - Exterior Downspouts	2 - North High Roof	26	LF	6	10+ years	
	Parapet - 16" - 30" Height	2 - North High Roof	236	LF	6	10+ years	
	Roof - Modified Bitumen	2 - North High Roof	7,473	SF	4	1-2 years	Cracking/bubbling/soft spots.
	Roof Hatch - Metal	2 - North High Roof	1	EA	3	0-1 year	Not in use. No ladder
	Roof Structure - Steel with Clay Tile Arch	2 - North High Roof	7,473	SF	7	10+ years	
	Access Ladder - Metal	3 - West High Roof	1	EA	7	10+ years	Newly replaced
	Coping - Stone	3 - West High Roof	420	LF	6	10+ years	
	Downspouts - Exterior Downspouts	3 - West High Roof	40	LF	6	10+ years	Corrected quantity
	Downspouts - Exterior Downspouts	3 - West High Roof	12	LF	4	0-1 year	Disconnect
	Downspoute - Interior Downspoute	3 - West High Roof	14	LF	6	10+ years	
	Parapet - 16" - 30" Height	3 - West High Roof	350	LF	5	0-1 year	Crumbling
	Parapet - Parapet > 30"	3 - West High Roof	70	LF	5	0-1 year	Crumbling
	Roof - Modified Bitumen	3 - West High Roof	9,134	SF	4	1-2 years	Cracking/bubbling/soft spots
	Roof Structure - Steel with Clay Tile Arch	3 - West High Roof	9,134	SF	7	10+ years	oraciang/babbing/son spots
	Access Ladder - Metal	4 - East High Roof	9,134	EA	7	10+ years	Newly replaced
	Coping - Stone	4 - East High Roof	420		6	10+ years	reading replaced
			420 24	LF	6		
	Downspouts - Interior Downspouts	4 - East High Roof		LF		10+ years	Crumbling
	Parapet - 16" - 30" Height	4 - East High Roof	350	LF	5	0-1 year	Crumbling
	Parapet - Parapet > 30"	4 - East High Roof	70		5	0-1 year	Crumbling
	Roof - Modified Bitumen	4 - East High Roof	9,134	SF	4	1-2 years	Spalling/displaced.



	ry : Exterior		P	uilding	· Main		4343 W Wrightwood, Chicago, IL 60
Jaleyo	ry. Exterior		В	unung	. พลาก	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
loup	Roof Structure - Steel with Clay Tile Arch	4 - East High Roof	9,134	SF	7	10+ years	Comments
	Chimney - Metal Flue	5 - Low Roof	12	LF	6	10+ years	
	Coping - Clay Tile	5 - Low Roof	24	LF	5	0-1 year	Displaced/cracking. Changed to match current observations
	Downspouts - Exterior Downspouts	5 - Low Roof	68	LF	5	6-10 years	materi current observations
	Parapet - 16" - 30" Height	5 - Low Roof	24	LF	6	10+ years	Quantity changed to match current
	ralapet - 10 - 30 rieight	3 - Eow 1(00)	27		0	TO+ years	observations
	Roof - Modified Bitumen	5 - Low Roof	1,446	SF	4	1-2 years	Cracking/bubbling/soft spots.
	Roof Structure - Steel with Clay Tile Arch	5 - Low Roof	1,446	SF	7	10+ years	
	·····		.,	•		, see years	
/alls							
	Cornice - Masonry Projecting Limestone	Entire Building	592	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	244	LF	6	6-10 years	
	Exterior Walls - Brick	Entire Building	22,084	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	10,243	SF	5	6-10 years	
	Exterior Walls - Brick	Entire Building	300	SF	4	0-1 year	Cracking/open joints
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	2,130	SF	5	1-2 years	Corroded
	Exterior Walls - Stone-Cast	Entire Building	6,520	SF	6	10+ years	
Vindows	Guard - Guards wire guard	Entire Building	2,916	SF	6	10+ years	
	Lintels - Steel	Entire Building	1,339	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	1,685	SF	4	1-2 years	Cracking
	Windows - Sash Aluminum	Entire Building	12,558	SF	4 5	2-5 years	Single temepered glass windows
	Windows - Sash Aluminum	Entire Building	12,556	эг	5	2-5 years	Single tempered glass windows
atego	ry : Electrical		В	uilding	: Main		
						Recommend	•
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System Automatic Transfer Switch	Electrical Room	3	EA	7	6-10 years	
	Automatic Transfer Switch	Electrical Room	1	EA	2		Non-operational. Water damage.
						0-1 year	Quotes out for repair.
	Security System - CCTV	Entire Building	98,284	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	98,284	SF	6	6-10 years	
		Entire Building	10	EA	6	6-10 years	
	Exit Signs - Auditoium						
	Exit Signs - Corridors and Stairs	Entire Building	15	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs Exit Signs - Lunchroom	Entire Building Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building					
	Exit Signs - Corridors and Stairs Exit Signs - Lunchroom Emergency A/C Power - Corridors and	Entire Building Entire Building	4	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs Exit Signs - Lunchroom Emergency A/C Power - Corridors and Stairs	Entire Building Entire Building Entire Building	4 10,529	EA SF	6 6	6-10 years 6-10 years	



Catego	ry : Electrical		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas - 101 - 150 KW		_				
/lain Sei	Nice						
	Main Electrical Service - 1200 A	Electrical Room	1	EA	7	6 10 1000	
		Electrical Room	1	EA	1	6-10 years	
	120/240/3PH	Floatrical Boom	4		7	6 10 1000	
	Main Electrical Service - 2000 A	Electrical Room	1	EA	7	6-10 years	
	120/240/3PH	Electrical Decar	4	Γ.	7	0.40	
	Independent Electrical Service for	Electrical Room	1	EA	7	6-10 years	
	emergency power		00.004	05	•	0.40	
	PA System	Entire Building	98,284	SF	6	6-10 years	
20war D	stribution						
	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	4	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Could not access
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	6-10 years	Could Hot access
	Lighting and Power Panels - Above 100 A	Entire Building	11	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	,	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp		1		-	6-10 years	
		Entire Building	3	EA	7	6-10 years	
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	6	6-10 years	
	amp Main Distribution Danala - Orgatan than 600	Fating Duilding	0	Γ.	0	0.40	
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	6	6-10 years	
	amp				•	0.40	
	Transformers - 120/240 - 120/208	Entire Building	2	EA	6	6-10 years	
	Transformers - 277/480 - 120/240	Entire Building	1	EA	6	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar						-	
	Fire ALarm Anunciator	Boiler Room	1	EA	7	6-10 years	
	Fire Alarm Panel	Boiler Room	1	EA	7	6-10 years	
	Fire Alarm Strobe Lights	Boiler Room	98,284	SF	6	6-10 years	
	Fire Alarm_System	Boiler Room	98,284	SF	6	6-10 years	
	·				-	,	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	itioning						
Ir Cond							
Ir Cond	Condensing Unit- Roof Mounted - Less	Main Roof	1	EA	2	0-1 year	Inoperable. Decommissioned build



Kelvyn Park High School 4343 W Wrightwood, Chicago, IL 60639

Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Condensing Unit- Roof Mounted - Less than 5 tons	Main Roof	1	EA	2	0-1 year	Daikin fan coil unit. Inoperable. Decommissioned building is cooled through window units and Daikin fan coil unit.
Air Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU-2 - Auditorium, main office, East and west
	Air Intake	Mechanical Room	1	EA	4	0-1 year	Air intake, take has to be manually operated to open and close, actuator bed, damper, fin rusted
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	6-10 years	· • ·
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	6-10 years	
	Zone Dampers	Mechanical Room	14	EA	6	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 15000 - 30000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU-1 - East & West
	Air Intake	Mechanical Room	1	EA	5	6-10 years	
	Auxiliaries - 15000 - 30000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	300	LF	6	6-10 years	
	Zone Dampers	Mechanical Room	41	EA	6	6-10 years	
	Roof Top Unit-Single Zone-Roof Mounted- Electric and Chilled Water Coils - 11 - 20 tons	Roof	1	EA	7	10+ years	2021 install
Boiler Sv	vstems						
,	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	2-5 years	Air is pulled in from the ceiling and into the combustion system via floor vents
	Condensate Pump	Boiler Room	1	EA	7	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	4	1-2 years	Tank and pumps are not leaking, but show signs of corrosion on shell
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Greater than 300 HP	Boiler Room	1	EA	6	6-10 years	-
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Greater than 300 HP	Boiler Room	1	EA	6	6-10 years	



Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Piping - Condensate Pipe- Steel	Boiler Room	300	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	300	LF	6	10+ years	
	Steam Traps	Boiler Room	70	EA	6	6-10 years	
	Steam Traps	Boiler Room	20	EA	6	6-10 years	
Heating	Devices						
	Radiators - Steam	Entire Building	7	EA	6	6-10 years	
	Radiators - Steam	Entire Building	3	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	14	EA	7	6-10 years	
	Wall Heater - Electric	Entire Building	1	EA	7	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years	
Tempera	ature Control						
	Electric Thermostat	Entire Building	2	EA	7	6-10 years	
	Hybrid Pneumatic/DDC System	Entire Building	98,224	SF	6	6-10 years	Pneumatic system is operational, but not in use. Decommissioned.
	Thermostats - DDC	Entire Building	55	EA	6	6-10 years	Temperature sensors, recessed into the wall
Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	2	EA	6	6-10 years	

Catego	Category : Plumbing				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water Return Lines	Entire Building	98,284	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	98,284	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	98,284	SF	6	6-10 years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	98,284	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	98,284	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	98,284	SF	6	6-10 years	
	Sanitary Piping	Entire Building	98,284	SF	6	6-10 years	
	Storm Piping	Entire Building	98,284	SF	6	6-10 years	



Category : Plumbing Building : Main Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Vent Piping Entire Building 98.284 SF 6 6-10 years Pumps Pumps - Domestic Booster Pump-Simplex ΕA 6 Basement 1 6-10 years Pumps - Sump-Simplex ΕA 6 6-10 years **Basement** 1 Category : Room Building : Main Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Administrative Suites/Offices SF Ceiling - Plaster/Drywall 104 269 6 10+ years SF Ceiling - Plaster/Drywall 104 10 4 0-1 year Damaged ceiling Doors - Wood Doors inclu hw 104 1 EΑ 7 10+ years Floor - Tile 104 279 SF 6 10+ years Lighting - Pendent/Surface 104 4 EΑ 7 10+ years **Power Distribution** 10 ΕA 7 104 10+ years Storage/ Closet 104 SF 5 10+ years 118 Walls - Plaster/Drvwall 616 SF 6 104 10+ years AC Unit 112 ROTC Office 1 FΑ 4 0-1 year Out of order SF 6 Ceiling - Lay-in 167 10+ years 112 ROTC Office SF 7 Floor - Tile 112 ROTC Office 167 10+ vears Lighting - Lay-in 112 ROTC Office 5 EΑ 7 6-10 years Lighting - Lay-in 112 ROTC Office 1 ΕA 6 6-10 years **Power Distribution** 112 ROTC Office 6 EΑ 6 10+ years 220 SF 7 Reassessed and recalculated Walls - Masonry 112 ROTC Office 10+ vears SF Walls - Plaster/Drywall 220 7 10+ years Reassessed and recalculated 112 ROTC Office AC Unit 112A Nurse's Office ΕA 7 6-10 vears 1 AC Unit 112A Nurse's Office 1 FΑ 4 0-1 year Not working Ceiling - Lay-in SF 112A Nurse's Office 290 6 10+ years SF Ceiling - Plaster/Drywall 112A Nurse's Office 74 6 10+ years Doors - Transom Window SF 7 112A Nurse's Office 9 10+ years Doors - Wood Doors inclu hw 112A Nurse's Office 1 ΕA 7 10+ years SF Floor - Tile Ceramic/ Porcelain 112A Nurse's Office 364 7 10+ years Lighting - Lay-in 112A Nurse's Office 5 ΕA 7 10+ years Lighting - Lay-in 112A Nurse's Office 1 FΑ 6 6-10 years Lighting - Pendent/Surface 112A Nurse's Office 2 ΕA 7 10+ vears Power Distribution 7 112A Nurse's Office 16 EΑ 10+ years Storage/ Closet 22 SF 5 10+ years 112A Nurse's Office 7 112A Nurse's Office SF Walls - Plaster/Drywall 10 10+ years Walls painted Walls - Plaster/Drywall SF 112A Nurse's Office 871 6 10+ years SF Walls - Structural Glazed Tile 112A Nurse's Office 211 6 10+ years SF Ceiling - Plaster/Drvwall 112B 69 6 10+ years SF Doors - Side-lite 112B 18 7 10+ years

Doors - Steel Doors incl hw

EΑ

1

7

10+ years

112B



Catego	ry : Room		D	uilding	·Main		4343 W Wilgittwood, Chicago, IL 60639
Calego			D	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Floor - Terrazzo	112B	12	SF	7	10+ years	
	Floor - Tile	112B	57	SF	6	10+ years	
	Lighting - Pendent/Surface	112B	2	EA	7	6-10 years	
	Power Distribution	112B	8	EA	7	10+ years	
	Walls - Plaster/Drywall	112B	79	SF	6	10+ years	
	Ceiling - Splined	199 ROTC Training Center	2,293	SF	6	10+ years	
	Doors - Wood Doors inclu hw	199 ROTC Training Center	_,•	EA	6	10+ years	
	Floor - Tile	199 ROTC Training Center	2,293	SF	7	10+ years	
	Lighting - Pendent/Surface	199 ROTC Training Center	35	EA	7	6-10 years	
	Lighting - Pendent/Surface	199 ROTC Training Center	3	EA	6	6-10 years	
	Power Distribution	199 ROTC Training Center	14	EA	6	10+ years	
	Walls - Plaster/Drywall	199 ROTC Training Center	2,636	SF	7	10+ years	
	AC Unit	201A Office	[′] 1	EA	7	6-10 years	
	Ceiling - Lay-in	201A Office	110	SF	6	10+ years	
	Doors - Wood Doors inclu hw	201A Office	1	EA	7	10+ years	
	Floor - Tile	201A Office	110	SF	7	10+ years	
	Lighting - Lay-in	201A Office	4	EA	7	6-10 years	
	Power Distribution	201A Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	201A Office	350	SF	6	10+ years	
	AC Unit	201C Assistant Principal	1	EA	7	6-10 years	
	Ceiling - Lay-in	201C Assistant Principal	240	SF	6	10+ years	
	Doors - Wood Doors inclu hw	201C Assistant Principal	2	EA	7	10+ years	
	Floor - Wood	201C Assistant Principal	240	SF	6	10+ years	
	Lighting - Lay-in	201C Assistant Principal	3	EA	7	6-10 years	
	Lighting - Lay-in	201C Assistant Principal	1	EA	5	1-2 years	Missing cover
	Power Distribution	201C Assistant Principal	1	EA	7	10+ years	-
	Walls - Plaster/Drywall	201C Assistant Principal	380	SF	6	10+ years	
	Ceiling - Plaster/Drywall	312	468	SF	6	10+ years	
	Doors - Wood Doors inclu hw	312	1	EA	7	10+ years	
	Floor - Tile	312	468	SF	6	10+ years	
	Lighting - Pendent/Surface	312	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	312	2	EA	5	1-2 years	Missing or loose covers
	Power Distribution	312	6	EA	7	10+ years	
	Storage/ Closet	312	44	SF	5	1-2 years	Drywall cracks and broken overhead glass
	Walls - Plaster/Drywall	312	535	SF	6	10+ years	ylass
	AC Unit	398 Intervention	1	EA	7	6-10 years	
	Ceiling - Lay-in	398 Intervention	838	SF	6	10+ years	
	Doors - Transom Window	398 Intervention	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	398 Intervention	1	EA	7	10+ years	
	Floor - Tile	398 Intervention	830	SF	6	10+ years	
	Floor - Tile	398 Intervention	8	SF	5	1-2 years	Damaged
	Lighting - Lay-in	398 Intervention	15	ĒA	7	6-10 years	0
	Power Distribution	398 Intervention	12	EA	7	10+ years	
						-	



Category : Room			Building : Main							
caloge				anang	- main	Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
-	Storage/ Closet	398 Intervention	38	SF	5	1-2 years	Drywall cracks and damaged door			
	Walls - Plaster/Drywall	398 Intervention	991	SF	6	10+ years				
	AC Unit	Faculty Lounge 211	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	Faculty Lounge 211	760	SF	6	10+ years				
	Doors - Transom Window	Faculty Lounge 211	9	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Faculty Lounge 211	1	EA	6	10+ years				
	Floor - Tile	Faculty Lounge 211	760	SF	6	10+ years				
	Lighting - Lay-in	Faculty Lounge 211	12	EA	7	6-10 years				
	Power Distribution	Faculty Lounge 211	12	EA	6	10+ years				
	Walls - Plaster/Drywall	Faculty Lounge 211	886	SF	6	10+ years				
	Walls - Plaster/Drywall	Faculty Lounge 211	5	SF	5	1-2 years	Drywall cracks			
	AC Unit	Principal office 203	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	Principal office 203	450	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Principal office 203	2	EA	7	10+ years				
	Floor - Wood	Principal office 203	450	SF	6	10+ years				
	Lighting - Pendent/Surface	Principal office 203	4	EA	7	6-10 years				
	Power Distribution	Principal office 203	1	EA	7	10+ years				
	Storage/ Closet	Principal office 203	12	SF	7	10+ years				
	Walls - Plaster/Drywall	Principal office 203	540	SF	6	10+ years				
	AC Unit	Rm 113 Tech Storage	2	EA	7	6-10 years	Moved from storage rooms			
	Ceiling - Plaster/Drywall	Rm 113 Tech Storage	557	SF	7	10+ years	Moved from storage rooms			
	Doors - Transom Window	Rm 113 Tech Storage	1	SF	7	10+ years	Moved from storage rooms			
	Doors - Wood Doors inclu hw	Rm 113 Tech Storage	1	EA	7	10+ years	Moved from storage rooms			
	Floor - Wood	Rm 113 Tech Storage	557	SF	7	10+ years	Moved from storage rooms			
	Lighting - Pendent/Surface	Rm 113 Tech Storage	4	EA	7	10+ years	Moved from storage rooms			
	Power Distribution	Rm 113 Tech Storage	8	EA	7	10+ years	Moved from storage rooms			
	Walls - Plaster/Drywall	Rm 113 Tech Storage	780	SF	7	10+ years	Moved from storage rooms			
	AC Unit	Room 201 Main Office	2	EA	7	6-10 years				
	Ceiling - Lay-in	Room 201 Main Office	340	SF	7	10+ years				
	Ceiling - Plaster/Drywall	Room 201 Main Office	848	SF	6	10+ years				
	Doors - Transom Window	Room 201 Main Office	10	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Room 201 Main Office	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Room 201 Main Office	223	SF	6	10+ years				
	Floor - Wood	Room 201 Main Office	965	SF	6	10+ years				
	Lighting - Lay-in	Room 201 Main Office	8	EA	7	6-10 years				
	Lighting - Pendent/Surface	Room 201 Main Office	10	EA	7	6-10 years				
	Power Distribution	Room 201 Main Office	4	EA	7	10+ years				
	Storage/ Closet	Room 201 Main Office	75	SF	7	10+ years				
	Walls - Plaster/Drywall	Room 201 Main Office	2,104	SF	6	10+ years				
	AC Unit	Room 205 Counselor	2	EA	7	6-10 years				
	Ceiling - Lay-in	Room 205 Counselor	754	SF	6	10+ years				
	Ceiling - Lay-in	Room 205 Counselor	6	SF	4	0-1 year	Buckled tile			
	Doors - Transom Window	Room 205 Counselor	9	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Room 205 Counselor	1	EA	7	10+ years				



Catego	ry : Room		В	uilding	: Main		
				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Room 205 Counselor	750	SF	6	10+ years	
	Floor - Tile	Room 205 Counselor	10	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	Room 205 Counselor	18	EA	7	6-10 years	
	Storage/ Closet	Room 205 Counselor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 205 Counselor	1,283	SF	6	10+ years	
	Walls - Plaster/Drywall	Room 205 Counselor	10	SF	5	1-2 years	Damaged drywall
	AC Unit	Room 209 Counselor	1	EA	7	6-10 years	5
	Ceiling - Lay-in	Room 209 Counselor	381	SF	7	10+ years	
	Doors - Transom Window	Room 209 Counselor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 209 Counselor	1	ĒA	7	10+ years	
	Floor - Carpet	Room 209 Counselor	381	SF	6	6-10 years	
	Lighting - Pendent/Surface	Room 209 Counselor	8	EA	7	6-10 years	
	Lighting - Pendent/Surface	Room 209 Counselor	1	EA	5	1-2 years	Missing cover
	Power Distribution	Room 209 Counselor	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 209 Counselor	644	SF	6	10+ years	
	Walls - Plaster/Drywall	Room 209 Counselor	2	SF	5	1-2 years	Damaged drywall
	AC Unit	Room 209A Counselor	2	EA	7	6-10 years	Damaged drywall
		Room 209A Counselor		SF	6	10+ years	
	Ceiling - Lay-in		370	SF			
	Doors - Transom Window	Room 209A Counselor	6		7	10+ years	
	Doors - Wood Doors inclu hw	Room 209A Counselor	1	EA	6	10+ years	
	Floor - Carpet	Room 209A Counselor	370	SF	6	6-10 years	
	Lighting - Lay-in	Room 209A Counselor	6	EA	7	6-10 years	
	Storage/ Closet	Room 209A Counselor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 209A Counselor	998	SF	6	10+ years	
Auditoriu	ım & Theater						
	Balcony Seating	1st Floor	450	EA	7	10+ years	No occupancy signage
	Ceiling - Plaster/Drywall	1st Floor	3,025	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years	
	Floor - Tile	1st Floor	2,865	SF	6	6-10 years	
	Floor - Tile	1st Floor	80	SF	4	0-1 year	Damaged tiles
	Lighting - Lay-in	1st Floor	60	EA	6	6-10 years	
	Main Floor Seating	1st Floor	600	ĒA	7	10+ years	
	Sound System	1st Floor	5	EA	7	10+ years	
	Stage	1st Floor	750	SF	7	10+ years	
	Stage Curtain	1st Floor	9	EA	7	10+ years	
	Stage Lighting System	1st Floor	25	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	23	LF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,650	SF	6	10+ years	
Kitchan							
Kitchen_	Ceiling - Exposed	room 212D	922	SF	6	10+ years	
<u>Kitchen</u>	Ceiling - Exposed Doors - Transom Window	room 212D room 212D	922 6	SF SF	6 7	10+ years 10+ years	



	_		_				4545 W Wilginwood, Chicago, IL 00039
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	room 212D	922	SF	6	10+ years	
	Lighting - Pendent/Surface	room 212D	24	EA	7	6-10 years	
	Storage/ Closet	room 212D	154	SF	7	10+ years	
	Walls - Structural Glazed Tile	room 212D	1,060	SF	6	10+ years	
Library							
	AC Unit	1st Floor	2	EA	7	6-10 years	Room under renovation
	Casework	1st Floor	180	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2,114	SF	6	10+ years	
	Doors - Transom Window	1st Floor	2,114	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Carpet	1st Floor	1,057	SF	6	6-10 years	
	•			SF		,	
	Floor - Tile Ceramic/ Porcelain	1st Floor	1,057		6	10+ years	
	Lighting - Pendent/Surface	1st Floor	31	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	6	6-10 years	
	Storage/ Closet	1st Floor	250	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,431	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	2nd Floor	4,573	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	60	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years	
	Floor - Tile	2nd Floor	4,633	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	58	EA	7	6-10 years	
	Serving Line	2nd Floor	30	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	459	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	3,995	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,331	SF	6	10+ years	
MDF ID	F						
	Doors - Wood Doors inclu hw	113A MDF located in Rm 113	1	EA	6	10+ years	
	Finishes	113A MDF located in Rm 113	258	SF	5	10+ years	
	Other Cooling Unit	113A MDF located in Rm 113	230	EA	7	6-10 years	
		TISA MDF localed in Kin 113	I	LA	'	0-10 years	
Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	10	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	200	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	1,016	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	75	SF	7	10+ years	
	Storage Room	1st Floor	25	SF	7	10+ years	
	Janitor's Closet	2nd Floor	12	SF	7	10+ years	
	Janitor's Closet	2nd Floor	12	SF	7	10+ years	
	Janitor's Closet	2nd Floor	12	SF	7	10+ years	
					-	. ,	



Catego	ry : Room		B	uilding	: Main		
J	-			5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Janitor's Closet	2nd Floor	14	SF	7	10+ years	
	Janitor's Closet	3rd Floor	13	SF	7	10+ years	
	Janitor's Closet	3rd Floor	13	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	80	SF	7	10+ years	
	Storage Room	3rd Floor	120	SF	7	10+ years	Relamp light
	Air Tunnel	Basement	9,000	SF	7	10+ years	
	Auditorium Plenums	Basement	3,025	SF	7	10+ years	
	Boiler Room	Basement	3,815	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	15,536	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	1,190	SF	7	10+ years	
	Storage Room	Basement	3,434	SF	5	10+ years	
Restroor	n						
	Accessories	1st Floor - Men next to office 112B	215	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Men next to office 112B	215	SF	6	10+ years	
	Doors - Transom Window	1st Floor - Men next to office 112B	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Men next to office 112B	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Men next to office 112B	209	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Men next to office 112B	6	SF	4	0-1 year	Cracking
	Floor Drain	1st Floor - Men next to office 112B	1	EA	7	10+ years	
	Lavatory	1st Floor - Men next to office 112B	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Men next to office 112B	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor - Men next to office 112B	2	EA	5	1-2 years	Missing covers
	Partitions	1st Floor - Men next to office 112B	2	EA	5	6-10 years	
	Urinals	1st Floor - Men next to office 112B	2	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - Men next to office 112B	101	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Men next to office 112B	954	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - Men next to office 112B	5	SF	5	1-2 years	Cracking
	Water Closet	1st Floor - Men next to office 112B	2	EA	7	10+ years	
	Accessories	2nd Floor	339	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	334	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	339	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Urinals	2nd Floor	5	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	195	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	195	SF	6	10+ years	
	Water Closet	2nd Floor	2	EA	7	10+ years	



Catego	ry : Room		B	uilding	· Main		4343 W Wrightwood, Chicago, IL 60639
Calego	ry . Room			unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oreup	Accessories	3rd Floor	339	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	339	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	339	SF	5	1-2 years	Missing finish throughout
	Floor Drain	3rd Floor	1	ĒA	7	10+ years	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years	
	Lavatory	3rd Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	6-10 years	
	Partitions	3rd Floor	2	EA	7	10+ years	
	Urinals	3rd Floor	5	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	492	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	482	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	4	1-2 years	Drywall cracks
	Water Closet	3rd Floor	2	EA	7	10+ years	-
	Accessories	3rd Floor - next to 304	292	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor - next to 304	292	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor - next to 304	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor - next to 304	292	SF	6	10+ years	
	Floor Drain	3rd Floor - next to 304	1	EA	7	10+ years	
	Lavatory	3rd Floor - next to 304	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor - next to 304	4	EA	7	6-10 years	
	Partitions	3rd Floor - next to 304	6	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor - next to 304	52	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor - next to 304	409	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor - next to 304	10	SF	5	1-2 years	Water damage
	Walls - Structural Glazed Tile	3rd Floor - next to 304	225	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor - next to 304	255	SF	7	10+ years	
	Water Closet	3rd Floor - next to 304	6	EA	7	10+ years	
	Accessories	Boiler Room	81	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Boiler Room	81	SF	6	2-5 years	Peeling paint
	Doors - Wood Doors inclu hw	Boiler Room	1	EA	7	10+ years	
	Floor - Tile	Boiler Room	81	SF	6	10+ years	
	Floor Drain	Boiler Room	1	EA	7	10+ years	
	Lavatory	Boiler Room	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Boiler Room	1	EA	5	1-2 years	Missing cover
	Partitions	Boiler Room	2	EA	7	6-10 years	
	Showers	Boiler Room	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Boiler Room	220	SF	6	2-5 years	
	Water Closet	Boiler Room	1	EA	6	6-10 years	
	Accessories	Near Auditorium - All Gender	185	SF	7	6-10 years	
	Ceiling - Exposed	Near Auditorium - All Gender	185	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Near Auditorium - All Gender	1	EA	7	10+ years	
	Floor - Tile	Near Auditorium - All Gender	185	SF	6	10+ years	
	Hand Dryer	Near Auditorium - All Gender	1	EA	4	1-2 years	Not working



Catego	ry : Room		В	uilding	: Main		
0	, ,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	Near Auditorium - All Gender	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Near Auditorium - All Gender	2	EA	7	10+ years	
	Partitions	Near Auditorium - All Gender	1	EA	5	10+ years	
	Walls - Concrete Block	Near Auditorium - All Gender	54	SF	6	10+ years	
	Walls - Plaster/Drywall	Near Auditorium - All Gender	500	SF	6	10+ years	
	Water Closet	Near Auditorium - All Gender	1	EA	7	10+ years	
	Accessories	Near Auditorium - Men	185	SF	7	6-10 years	
	Ceiling - Exposed	Near Auditorium - Men	185	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Near Auditorium - Men	1	EA	7	10+ years	
	Floor - Tile	Near Auditorium - Men	183	SF	6	10+ years	
	Floor - Tile	Near Auditorium - Men	2	SF	4	0-1 year	Damaged tiles
	Hand Dryer	Near Auditorium - Men	1	EA	7	10+ years	
	Lavatory	Near Auditorium - Men	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Near Auditorium - Men	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	Near Auditorium - Men	1	EA	6	6-10 years	
	Partitions	Near Auditorium - Men	1	EA	5	10+ years	
	Urinals	Near Auditorium - Men	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Near Auditorium - Men	549	SF	6	6-10 years	
	Water Closet	Near Auditorium - Men	1	EA	7	10+ years	
	Accessories	Unisex Restroom in main office	5	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Unisex Restroom in main office	120	SF	6	10+ years	
	Doors - Transom Window	Unisex Restroom in main office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Unisex Restroom in main office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Unisex Restroom in main office	120	SF	6	10+ years	
	Lavatory	Unisex Restroom in main office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Unisex Restroom in main office	1	EA	7	6-10 years	
	Partitions	Unisex Restroom in main office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Unisex Restroom in main office	240	SF	6	10+ years	
	Water Closet	Unisex Restroom in main office	1	EA	7	10+ years	
	Accessories	Women's restroom next to 206	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Women's restroom next to 206	250	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Women's restroom next to 206	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Women's restroom next to 206	250	SF	6	10+ years	
	Floor Drain	Women's restroom next to 206	1	EA	7	10+ years	
	Hand Dryer	Women's restroom next to 206	2	EA	7	6-10 years	
	Lavatory	Women's restroom next to 206	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Women's restroom next to 206	4	EA	7	6-10 years	
	Partitions	Women's restroom next to 206	6	EA	7	10+ years	
	Walls - Concrete Block	Women's restroom next to 206	290	SF	6	10+ years	
	Walls - Plaster/Drywall	Women's restroom next to 206	430	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Women's restroom next to 206	350	SF	6	10+ years	
	Water Closet	Women's restroom next to 206	6	EA	7	10+ years	



Catego	ry : Classroom		В				
	-			Recommend			
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroo	m #099 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	760	SF	6	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	6	6-10 years	
	Storage/ Closet	1st Floor	14	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,380	SF	7	10+ years	
						-	
lassroo	m #101 (Office)			F ^	-	0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	610	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	610	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	4	EA	6	6-10 years	
	Storage/ Closet	1st Floor	10	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	760	SF	6	10+ years	
lassroo	m #103 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	525	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	525	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	6	6-10 years	
	Storage/ Closet	1st Floor	43	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,096	SF	6	10+ years	
lassroo	m #105 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	485	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	-03	EA	7	10+ years	
	Floor - Tile	1st Floor	475	SF	6	10+ years	
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	7	EA	4 7	6-10 years	Damayeu lies
	Marker Board	1st Floor	12		7	6-10 years	
	WAINEI DUAIU	151 1001	12	LF	1	o-ro years	



	Schools						4343 W Wrightwood, Chicago, IL 606
Catego	ry : Classroom		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,099	SF	6	10+ years	
Classroo	om #107 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	485	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	485	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	25	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,099	SF	6	10+ years	
Classroo	om #108 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	764	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	7	10+ years	
	Floor - Wood	1st Floor	764	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	52	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	878	SF	6	10+ years	
Classroo	om #109 (Other Instructional Use)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	525	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	495	SF	6	10+ years	
	Floor - Tile	1st Floor	30	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	Damagou noo
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	25	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,099	SF	6	10+ years	
Jacerov	om #110 (Regular Classroom)						
21033100	AC Units	1st Floor	1	EA	7	6-10 years	
		1st Floor	760	EA SF			
	Ceiling - Plaster/Drywall Chalk Board	1st Floor	760	SF LF	6 4	10+ years	
	Doors - Wood Doors inclu hw			EA		2-5 years	
		1st Floor	1		6	10+ years	
	Floor - Wood	1st Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Storage/ Closet	1st Floor	18	SF	7	10+ years	



: Classroom tem - Type Walls - Plaster/Drywall #111 (Office) AC Units Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall	Location 1st Floor 1st Floor	B Quantity 891 1 525 1 525 4 4 4 30 18 1,029	UOM SF EA SF EA SF EA EA EA LF SF	Rank 6 5 6 7 6 7 6	Recommend Replacement10+ years6-10 years10+ years10+ years10+ years10+ years10+ years6-10 years	Comments
Walls - Plaster/Drywall #111 (Office) AC Units Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor	891 1 525 1 525 4 4 4 30 18	SF EA SF EA EA EA LF	6 5 6 7 6 7 6	6-10 years 10+ years 6-10 years 10+ years 10+ years 10+ years	Comments
Walls - Plaster/Drywall #111 (Office) AC Units Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor	891 1 525 1 525 4 4 4 30 18	SF EA SF EA EA EA LF	6 5 6 7 6 7 6	10+ years 6-10 years 10+ years 10+ years 10+ years	Comments
#111 (Office) AC Units Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 525 1 525 4 4 30 18	EA SF EA EA EA LF	5 6 7 6 7 6	6-10 years 10+ years 10+ years 10+ years	
AC Units Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	525 1 525 4 4 30 18	SF EA SF EA EA LF	6 7 6 7 6	10+ years 10+ years 10+ years	
AC Units Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	525 1 525 4 4 30 18	SF EA SF EA EA LF	6 7 6 7 6	10+ years 10+ years 10+ years	
Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	525 1 525 4 4 30 18	SF EA SF EA EA LF	6 7 6 7 6	10+ years 10+ years 10+ years	
Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	1 525 4 4 30 18	EA SF EA EA LF	7 6 7 6	10+ years 10+ years	
Floor - Tile Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	525 4 4 30 18	SF EA EA LF	6 7 6	10+ years	
Lighting - Pendent/Surface Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor	4 4 30 18	EA EA LF	7 6	6-10 years	
Lighting - Pendent/Surface Marker Board Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor	4 30 18	EA LF	6	0-10 years	
Marker Board Storage/ Closet Walls - Plaster/Drywall	1st Floor 1st Floor	30 18	LF	-	6-10 years	
Storage/ Closet Walls - Plaster/Drywall	1st Floor	18		7	6-10 years	
Walls - Plaster/Drywall				7	10+ years	
-	ISt Floor	1.079	SF	-		
		1,320	SF	6	10+ years	
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	32		7	10+ years	
Ceiling - Lay-in	2nd Floor	744	SF	6	10+ years	
Ceiling - Lay-in	2nd Floor	6	SF	5	0-1 year	Broken
Ceiling - Lay-in	2nd Floor	10	SF	4	1-2 years	Water damage
Doors - Transom Window	2nd Floor	9	SF	7		0
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7		
Floor - Wood	2nd Floor	760	SF	6	•	
Lighting - Lav-in	2nd Floor	10	ĒA	7		
	2nd Floor		EA	5		Missing covers
			LF	-		
					•	Locked
Walls - Plaster/Drywall	2nd Floor	891	SF	6	10+ years	
			F A	7	0.40	
		-				
Celling - Plaster/Drywall						
					•	
				-		
Storage/ Closet						Blocked
	2nd Floor	881		6		
Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Water damage
#204 (Regular Classroom)_						
	2nd Floor	1	FA	7	6-10 years	
	Casework Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Ceiling - Lay-in Coors - Transom Window Doors - Wood Doors inclu hw Coors - Wood Coors - Wood Coors - Lay-in Marker Board Coorage/ Closet Valls - Plaster/Drywall #202 (Regular Classroom) CC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Cloor - Wood Coors - Wood Coors - Wood Coors - Wood Coors - Pendent/Surface Marker Board Corage/ Closet Valls - Plaster/Drywall	AC Units 2nd Floor Casework 2nd Floor Ceiling - Lay-in 2nd Floor Ceiling - Lay-in 2nd Floor Ceiling - Lay-in 2nd Floor Coors - Transom Window 2nd Floor Coors - Transom Window 2nd Floor Coors - Wood Doors inclu hw 2nd Floor Coors - Wood 2nd Floor Coors - Wood 2nd Floor Ighting - Lay-in 2nd Floor Aarker Board 2nd Floor Aarker Board 2nd Floor Korage/ Closet 2nd Floor Valls - Plaster/Drywall 2nd Floor Coors - Transom Window 2nd Floor Coors - Wood Doors inclu hw 2nd Floor Coors - Wood Doors inclu hw 2nd Floor </td <td>AC Units2nd Floor1Casework2nd Floor32Seiling - Lay-in2nd Floor744Seiling - Lay-in2nd Floor6Seiling - Lay-in2nd Floor10Doors - Transom Window2nd Floor10Doors - Transom Window2nd Floor10Doors - Wood Doors inclu hw2nd Floor1Noor - Wood2nd Floor10ighting - Lay-in2nd Floor10ighting - Lay-in2nd Floor10ighting - Lay-in2nd Floor2Aarker Board2nd Floor2Arker Board2nd Floor32Storage/ Closet2nd Floor6Valls - Plaster/Drywall2nd Floor6Valls - Plaster/Drywall2nd Floor1Cors - Transom Window2nd Floor1Seiling - Plaster/Drywall2nd Floor1Cors - Wood Doors inclu hw2nd Floor1Cors - Wood Doors inclu hw2nd Floor1Cors - Wood Doors inclu hw2nd Floor1Cors - Wood2nd Floor1Cors - Wood2nd Floor1Arker Board2nd Floor14Arker Board2nd Floor32Storage/ Closet2nd Floor32Storage/ Closet2nd Floor32Storage/ Closet2nd Floor32Storage/ Closet2nd Floor32Storage/ Closet2nd Floor381Valls - Plaster/Drywall2nd Floor381<t< td=""><td>AC Units2nd Floor1EACasework2nd Floor32LFCeiling - Lay-in2nd Floor744SFCeiling - Lay-in2nd Floor6SFCors - Transom Window2nd Floor10SFDoors - Transom Window2nd Floor9SFDoors - Wood Doors inclu hw2nd Floor1EAIdor - Wood2nd Floor10EAighting - Lay-in2nd Floor10EAighting - Lay-in2nd Floor10EAighting - Lay-in2nd Floor2EAAarker Board2nd Floor32LFStorage/ Closet2nd Floor32LFValls - Plaster/Drywall2nd Floor6SFValls - Plaster/Drywall2nd Floor1EACors - Wood Doors inclu hw2nd Floor18LFScasework2nd Floor18LFScasework2nd Floor18LFScasework2nd Floor12SFDoors - Transom Window2nd Floor12SFDoors - Transom Window2nd Floor12SFDoors - Transom Window2nd Floor12SFDoors - Vood2nd Floor14EAAarker Board2nd Floor14EAScasework2nd Floor14EAScasework2nd Floor14EAScore - Wood Doors inclu hw2nd Floor14EAStorage/ Closet2nd Floo</td><td>AC Units 2nd Floor 1 EA 7 Casework 2nd Floor 32 LF 7 Ceiling - Lay-in 2nd Floor 744 SF 6 Seiling - Lay-in 2nd Floor 6 SF 5 Seiling - Lay-in 2nd Floor 10 SF 4 Doors - Transom Window 2nd Floor 9 SF 7 Doors - Transom Window 2nd Floor 1 EA 7 Doors - Transom Window 2nd Floor 1 EA 7 Doors - Transom Window 2nd Floor 1 EA 7 Doors - Wood 2nd Floor 10 EA 7 Ighting - Lay-in 2nd Floor 10 EA 7 Storage/ Closet 2nd Floor 32 LF 7 Valls - Plaster/Drywall 2nd Floor 32 LF 7 Cu Units 2nd Floor 1 EA 7 Casework 2nd Floor 1 EA 7 Casework 2nd Floor 18 LF 7</td><td>C Units 2nd Floor 1 EA 7 6-10 years Jasework 2nd Floor 32 LF 7 10+ years Jasework 2nd Floor 6 SF 6 10+ years Seiling - Lay-in 2nd Floor 6 SF 5 0-1 year Seiling - Lay-in 2nd Floor 10 SF 4 1-2 years Joors - Transom Window 2nd Floor 10 SF 4 1-2 years Joors - Wood Doors inclu hw 2nd Floor 1 EA 7 10+ years Joors - Wood 2nd Floor 1 EA 7 10+ years Joors - Wood 2nd Floor 10 EA 7 6-10 years Ighting - Lay-in 2nd Floor 10 EA 7 6-10 years Ighting - Lay-in 2nd Floor 32 LF 7 6-10 years Ighting - Lay-in 2nd Floor 32 LF 7 6-10 years Ighting - Lay-in 2nd Floor 32 LF 7 6-10 years Ighting - Plas</td></t<></td>	AC Units2nd Floor1Casework2nd Floor32Seiling - Lay-in2nd Floor744Seiling - Lay-in2nd Floor6Seiling - Lay-in2nd Floor10Doors - Transom Window2nd Floor10Doors - Transom Window2nd Floor10Doors - Wood Doors inclu hw2nd Floor1Noor - Wood2nd Floor10ighting - Lay-in2nd Floor10ighting - Lay-in2nd Floor10ighting - Lay-in2nd Floor2Aarker Board2nd Floor2Arker Board2nd Floor32Storage/ Closet2nd Floor6Valls - Plaster/Drywall2nd Floor6Valls - Plaster/Drywall2nd Floor1Cors - Transom Window2nd Floor1Seiling - Plaster/Drywall2nd Floor1Cors - Wood Doors inclu hw2nd Floor1Cors - Wood Doors inclu hw2nd Floor1Cors - Wood Doors inclu hw2nd Floor1Cors - Wood2nd Floor1Cors - Wood2nd Floor1Arker Board2nd Floor14Arker Board2nd Floor32Storage/ Closet2nd Floor32Storage/ Closet2nd Floor32Storage/ Closet2nd Floor32Storage/ Closet2nd Floor32Storage/ Closet2nd Floor381Valls - Plaster/Drywall2nd Floor381 <t< td=""><td>AC Units2nd Floor1EACasework2nd Floor32LFCeiling - Lay-in2nd Floor744SFCeiling - Lay-in2nd Floor6SFCors - Transom Window2nd Floor10SFDoors - Transom Window2nd Floor9SFDoors - Wood Doors inclu hw2nd Floor1EAIdor - Wood2nd Floor10EAighting - Lay-in2nd Floor10EAighting - Lay-in2nd Floor10EAighting - Lay-in2nd Floor2EAAarker Board2nd Floor32LFStorage/ Closet2nd Floor32LFValls - Plaster/Drywall2nd Floor6SFValls - Plaster/Drywall2nd Floor1EACors - Wood Doors inclu hw2nd Floor18LFScasework2nd Floor18LFScasework2nd Floor18LFScasework2nd Floor12SFDoors - Transom Window2nd Floor12SFDoors - Transom Window2nd Floor12SFDoors - Transom Window2nd Floor12SFDoors - Vood2nd Floor14EAAarker Board2nd Floor14EAScasework2nd Floor14EAScasework2nd Floor14EAScore - Wood Doors inclu hw2nd Floor14EAStorage/ Closet2nd Floo</td><td>AC Units 2nd Floor 1 EA 7 Casework 2nd Floor 32 LF 7 Ceiling - Lay-in 2nd Floor 744 SF 6 Seiling - Lay-in 2nd Floor 6 SF 5 Seiling - Lay-in 2nd Floor 10 SF 4 Doors - Transom Window 2nd Floor 9 SF 7 Doors - Transom Window 2nd Floor 1 EA 7 Doors - Transom Window 2nd Floor 1 EA 7 Doors - Transom Window 2nd Floor 1 EA 7 Doors - Wood 2nd Floor 10 EA 7 Ighting - Lay-in 2nd Floor 10 EA 7 Storage/ Closet 2nd Floor 32 LF 7 Valls - Plaster/Drywall 2nd Floor 32 LF 7 Cu Units 2nd Floor 1 EA 7 Casework 2nd Floor 1 EA 7 Casework 2nd Floor 18 LF 7</td><td>C Units 2nd Floor 1 EA 7 6-10 years Jasework 2nd Floor 32 LF 7 10+ years Jasework 2nd Floor 6 SF 6 10+ years Seiling - Lay-in 2nd Floor 6 SF 5 0-1 year Seiling - Lay-in 2nd Floor 10 SF 4 1-2 years Joors - Transom Window 2nd Floor 10 SF 4 1-2 years Joors - Wood Doors inclu hw 2nd Floor 1 EA 7 10+ years Joors - Wood 2nd Floor 1 EA 7 10+ years Joors - Wood 2nd Floor 10 EA 7 6-10 years Ighting - Lay-in 2nd Floor 10 EA 7 6-10 years Ighting - Lay-in 2nd Floor 32 LF 7 6-10 years Ighting - Lay-in 2nd Floor 32 LF 7 6-10 years Ighting - Lay-in 2nd Floor 32 LF 7 6-10 years Ighting - Plas</td></t<>	AC Units2nd Floor1EACasework2nd Floor32LFCeiling - Lay-in2nd Floor744SFCeiling - Lay-in2nd Floor6SFCors - Transom Window2nd Floor10SFDoors - Transom Window2nd Floor9SFDoors - Wood Doors inclu hw2nd Floor1EAIdor - Wood2nd Floor10EAighting - Lay-in2nd Floor10EAighting - Lay-in2nd Floor10EAighting - Lay-in2nd Floor2EAAarker Board2nd Floor32LFStorage/ Closet2nd Floor32LFValls - Plaster/Drywall2nd Floor6SFValls - Plaster/Drywall2nd Floor1EACors - Wood Doors inclu hw2nd Floor18LFScasework2nd Floor18LFScasework2nd Floor18LFScasework2nd Floor12SFDoors - Transom Window2nd Floor12SFDoors - Transom Window2nd Floor12SFDoors - Transom Window2nd Floor12SFDoors - Vood2nd Floor14EAAarker Board2nd Floor14EAScasework2nd Floor14EAScasework2nd Floor14EAScore - Wood Doors inclu hw2nd Floor14EAStorage/ Closet2nd Floo	AC Units 2nd Floor 1 EA 7 Casework 2nd Floor 32 LF 7 Ceiling - Lay-in 2nd Floor 744 SF 6 Seiling - Lay-in 2nd Floor 6 SF 5 Seiling - Lay-in 2nd Floor 10 SF 4 Doors - Transom Window 2nd Floor 9 SF 7 Doors - Transom Window 2nd Floor 1 EA 7 Doors - Transom Window 2nd Floor 1 EA 7 Doors - Transom Window 2nd Floor 1 EA 7 Doors - Wood 2nd Floor 10 EA 7 Ighting - Lay-in 2nd Floor 10 EA 7 Storage/ Closet 2nd Floor 32 LF 7 Valls - Plaster/Drywall 2nd Floor 32 LF 7 Cu Units 2nd Floor 1 EA 7 Casework 2nd Floor 1 EA 7 Casework 2nd Floor 18 LF 7	C Units 2nd Floor 1 EA 7 6-10 years Jasework 2nd Floor 32 LF 7 10+ years Jasework 2nd Floor 6 SF 6 10+ years Seiling - Lay-in 2nd Floor 6 SF 5 0-1 year Seiling - Lay-in 2nd Floor 10 SF 4 1-2 years Joors - Transom Window 2nd Floor 10 SF 4 1-2 years Joors - Wood Doors inclu hw 2nd Floor 1 EA 7 10+ years Joors - Wood 2nd Floor 1 EA 7 10+ years Joors - Wood 2nd Floor 10 EA 7 6-10 years Ighting - Lay-in 2nd Floor 10 EA 7 6-10 years Ighting - Lay-in 2nd Floor 32 LF 7 6-10 years Ighting - Lay-in 2nd Floor 32 LF 7 6-10 years Ighting - Lay-in 2nd Floor 32 LF 7 6-10 years Ighting - Plas



Catego	ry : Classroom		В	uilding	: Main		4343 W Wightwood, Chicago, iL 60639
Jacyo				ananig			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	760	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	891	SF	6	10+ years	
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	760	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	2nd Floor	891	SF	6	10+ years	
Classroo	m #207 (Office)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	760	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	760	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	2nd Floor	1,373	SF	6	10+ years	
Classroo	m #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	760	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	760	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒA	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	891	SF	6	10+ years	
	,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,					-)	
lassroo	m #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	755	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	3
	Floor - Wood	2nd Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	2nd Floor	891	SF	6	10+ years	Looked
	Walls Thastel/Drywall	21011001	001	01	0	for years	
lassroo	m #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	415	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	413	SF	6	10+ years	
	Floor - Tile	2nd Floor	2	SF	4	0-1 year	Chipping
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,006	SF	6	10+ years	
lassroo	m #300 (Special Education)						
1000100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	584	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	6	SF	4	0-1 year	Buckled
	Chalk Board	3rd Floor	22	LF	4	2-5 years	Duckied
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	4		
	Floor - Tile	3rd Floor	590	SF	6	10+ years	
						10+ years	
	Lighting - Lay-in	3rd Floor	7	EA	7	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	625	SF	6	10+ years	D
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Drywall damage
lassroo	m #301 (Regular Classroom)						
	AC Units	4th Floor	2	EA	7	6-10 years	
	Casework	4th Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	760	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		4343 W Wrightwood, Chicago, IL 60639
oulego				unung	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.00p	Doors - Transom Window	4th Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	ĒA	7	10+ years	
	Floor - Wood	4th Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	4th Floor	14	ĒA	7	6-10 years	
	Marker Board	4th Floor	24	LF	7	6-10 years	
	Storage/ Closet	4th Floor	102	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	1,317	SF	6	10+ years	
	Wireless System	4th Floor	· 1	EA	7	6-10 years	
	Work Sink	4th Floor	1	EA	7	6-10 years	
Classroo	om #302 (Office)						
21000100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	254	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	6	SF	4	0-1 year	Buckled
	Chalk Board	3rd Floor	6	LF	4	2-5 years	Duomou
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	260	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	6	EA	7	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	12	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	295	SF	6	10+ years	
Classroo	om #303 (Regular Classroom)						
01033100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	6	10+ years	
	Chalk Board	3rd Floor	23	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	- <u>-</u> 1	EA	7	10+ years	
	Floor - Tile	3rd Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,293	SF	6	10+ years	
	Work Sink	3rd Floor	1,200	EA	7	10+ years	
Classroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	740	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	2	SF	4	0-1 year	Water damage
	Ceiling - Lay-in	3rd Floor	18	SF	4	0-1 year	Buckling
	Chalk Board	3rd Floor	38	LF	4	2-5 years	



Catego	ry : Classroom		P	uilding	·Main		4343 W Wrightwood, Chicago, IL 60639
Caleyo	1 y . 01033100111		В	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Sidup	Doors - Wood Doors inclu hw	3rd Floor	Quantity 1	EA	7	10+ years	Common to
	Floor - Tile	3rd Floor	760	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	6	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	872	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	5	1-2 years	Stopped up
	Work On K			L/(0		
Classroo	m #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	73	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,293	SF	6	10+ years	
Classroo	m #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	6	10+ years	
	Chalk Board	3rd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	58	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	3rd Floor	872	SF	6	10+ years	
Classroo	m #307 (Regular Classroom)						
_0/255100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6		7	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	760	SF	6	10+ years	
	Chalk Board	3rd Floor	780	LF	6 4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	4 7		
				EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1			10+ years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	98	SF	7	10+ years	



Catego	ory : Classroom		В				
-						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	1,293	SF	6	10+ years	
lassroo	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	6	10+ years	
	Chalk Board	3rd Floor	32	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	12	EA	7	10+ years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
					7		
	Lighting - Pendent/Surface	3rd Floor	14	EA LF	-	6-10 years	
	Marker Board	3rd Floor	18		6	6-10 years	
	Storage/ Closet	3rd Floor	58	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	872	SF	6	10+ years	
lassroo	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	30	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	98	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,293	SF	6	10+ years	
lacero	om #310 (Regular Classroom)						
123310	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	6	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	13	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	58	SF	7	10+ years	
		3rd Floor		SF			
	Walls - Plaster/Drywall		867	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	55	5	1-2 years	Drywall damage

Classroom #311 (Regular Classroom)



Catego	ry : Classroom		В	uilding	: Main		10 10 17 111g.111000, 01100g0, 1 <u>2</u> 00000
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	67	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,289	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4	SF	5	0-1 year	Drywall cracks
Classroo	om #312A (Store Room)						
	Casework	3rd Floor	14	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	598	SF	6	10+ years	
	Chalk Board	3rd Floor	9	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	598	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	9	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	5	1-2 years	Missing covers
	Marker Board	3rd Floor	14	LF	7	6-10 years	-
	Walls - Plaster/Drywall	3rd Floor	630	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	5	1-2 years	Faucet broken
Catego	ry : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	9,365	SF	6	10+ years	
			0,000		-		

Ceiling - Plaster/Drywall	1st Floor	9,365	SF	6	10+ years	
Doors - Wood Doors include hw	1st Floor	4	EA	6	10+ years	
Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	10+ years	
Drinking Fountains - Single Water Cooler	1st Floor	1	EA	4	0-1 year	Damaged fixture also making noise
Floor - Terrazzo	1st Floor	975	SF	7	10+ years	c c
Floor - Terrazzo	1st Floor	25	SF	5	1-2 years	Cracked terrazzo
Floor - Tile/Sheet	1st Floor	8,285	SF	7	10+ years	
Floor - Tile/Sheet	1st Floor	80	SF	4	0-1 year	Damaged tiles
Lighting - Pendent/Surface	1st Floor	60	EA	7	6-10 years	C C
Lighting - Pendent/Surface	1st Floor	2	EA	6	6-10 years	
Student Lockers - One Tier	1st Floor	448	EA	6	10+ years	
Walls - Plaster/Drywall	1st Floor	6	SF	6	1-2 years	Damaged wall base
Walls - Plaster/Drywall	1st Floor	10,764	SF	6	10+ years	C C
Ceiling - Plaster/Drywall	2nd Floor	9,345	SF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	20	SF	4	0-1 year	Water damage
Drinking Fountains - Single Water Cooler	2nd Floor	6	EA	7	10+ vears	-
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Plaster/Drywall Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall	Ceiling - Plaster/Drywall1st FloorDoors - Wood Doors include hw1st FloorDrinking Fountains - Single Water Cooler1st FloorDrinking Fountains - Single Water Cooler1st FloorPrinking Fountains - Single Water Cooler1st FloorFloor - Terrazzo1st FloorFloor - Terrazzo1st FloorFloor - Tile/Sheet1st FloorFloor - Tile/Sheet1st FloorLighting - Pendent/Surface1st FloorLighting - Pendent/Surface1st FloorStudent Lockers - One Tier1st FloorWalls - Plaster/Drywall1st FloorWalls - Plaster/Drywall2nd FloorCeiling - Plaster/Drywall2nd FloorCeiling - Plaster/Drywall2nd Floor	Ceiling - Plaster/Drywall1st Floor9,365Doors - Wood Doors include hw1st Floor4Drinking Fountains - Single Water Cooler1st Floor3Drinking Fountains - Single Water Cooler1st Floor1Floor - Terrazzo1st Floor975Floor - Terrazzo1st Floor25Floor - Tile/Sheet1st Floor8,285Floor - Tile/Sheet1st Floor80Lighting - Pendent/Surface1st Floor60Lighting - Pendent/Surface1st Floor2Student Lockers - One Tier1st Floor448Walls - Plaster/Drywall1st Floor6Walls - Plaster/Drywall1st Floor9,345Ceiling - Plaster/Drywall2nd Floor9,345Ceiling - Plaster/Drywall2nd Floor20	Ceiling - Plaster/Drywall1st Floor9,365SFDoors - Wood Doors include hw1st Floor4EADrinking Fountains - Single Water Cooler1st Floor3EADrinking Fountains - Single Water Cooler1st Floor1EAFloor - Terrazzo1st Floor975SFFloor - Terrazzo1st Floor25SFFloor - Terrazzo1st Floor25SFFloor - Tile/Sheet1st Floor80SFLighting - Pendent/Surface1st Floor60EALighting - Pendent/Surface1st Floor2EAStudent Lockers - One Tier1st Floor448EAWalls - Plaster/Drywall1st Floor6SFWalls - Plaster/Drywall1st Floor6SFCeiling - Plaster/Drywall2nd Floor9,345SFCeiling - Plaster/Drywall2nd Floor9,345SFCeiling - Plaster/Drywall2nd Floor20SF	Ceiling - Plaster/Drywall1st Floor9,365SF6Doors - Wood Doors include hw1st Floor4EA6Drinking Fountains - Single Water Cooler1st Floor3EA7Drinking Fountains - Single Water Cooler1st Floor1EA4Floor - Terrazzo1st Floor975SF7Floor - Terrazzo1st Floor25SF5Floor - Tile/Sheet1st Floor80SF4Lighting - Pendent/Surface1st Floor60EA7Lighting - Pendent/Surface1st Floor2EA6Student Lockers - One Tier1st Floor448EA6Walls - Plaster/Drywall1st Floor6SF6Walls - Plaster/Drywall1st Floor10,764SF6Ceiling - Plaster/Drywall2nd Floor20SF4	Ceiling - Plaster/Drywall1st Floor9,365SF610+ yearsDoors - Wood Doors include hw1st Floor4EA610+ yearsDrinking Fountains - Single Water Cooler1st Floor3EA710+ yearsDrinking Fountains - Single Water Cooler1st Floor1EA40-1 yearFloor - Terrazzo1st Floor975SF710+ yearsFloor - Terrazzo1st Floor25SF51-2 yearsFloor - Terrazzo1st Floor25SF710+ yearsFloor - Terrazzo1st Floor8,285SF710+ yearsFloor - Tile/Sheet1st Floor80SF40-1 yearLighting - Pendent/Surface1st Floor60EA76-10 yearsLighting - Pendent/Surface1st Floor2EA610+ yearsStudent Lockers - One Tier1st Floor448EA610+ yearsWalls - Plaster/Drywall1st Floor6SF61-2 yearsWalls - Plaster/Drywall1st Floor10,764SF610+ yearsCeiling - Plaster/Drywall2nd Floor20SF40-1 yearCeiling - Plaster/Drywall2nd Floor20SF40-1 year



Catego	ry : Interior		В	uilding			
Ŭ	•			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	2nd Floor	1,040	SF	7	10+ years	Not previously assessed
	Floor - Tile/Sheet	2nd Floor	8,285	SF	7	10+ years	Divided out terrazzo quantity
	Floor - Tile/Sheet	2nd Floor	40	SF	4	0-1 year	Cracks
	Lighting - Pendent/Surface	2nd Floor	62	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	448	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10,755	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	15	SF	4	0-1 year	Water damage
	Ceiling - Plaster/Drywall	3rd Floor	9,355	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	4	0-1 year	Water damage
	Drinking Fountains - Single Water Cooler	3rd Floor	6	EA	5	1-2 years	All fountains are damaged Qty
	Drinking i buntains - Bingle Water bobler	314 1 1001	0	LA	5	1-2 years	updated
	Floor - Terrazzo	3rd Floor	1,040	SF	7	10+ years	Not previously assessed
	Floor - Tile/Sheet	3rd Floor	8,285	SF	7	10+ years	Divided out terrazzo quantity
	Floor - Tile/Sheet	3rd Floor		SF	4		
			40	EA		1-2 years	Cracks
	Lighting - Pendent/Surface	3rd Floor	62		7	6-10 years	
	Student Lockers - One Tier	3rd Floor	448	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10,740	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	30	SF	4	0-1 year	Water damage
Safety							
	Camera Viewing Station	Entire Building	2	EA	7	6-10 years	
	Metal Detector	Entire Building	2	EA	7	6-10 years	
	Security Cameras	Entire Building	20	EA	7	6-10 years	20 interior cameras (28 total)
	Security Cameras	Entire Building	8	EA	7	6-10 years	8 exterior cameras
Stairs							
	Ceiling - Plaster/Drywall	Northeast	1,154	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Northeast	10	SF	5	1-2 years	Water damage
	Floor - Asphalt	Northeast	1,144	SF	6	10+ years	
	Floor - Asphalt	Northeast	20	SF	5	1-2 years	Damaged
	Handrails	Northeast	270	LF	7	10+ years	C C
	Lighting - Pendent/Surface	Northeast	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	Northeast	2	EA	6	6-10 years	
	Stairs - Asphalt	Northeast	480	LF	6	10+ years	
	Walls - Plaster/Drywall	Northeast	1,371	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Northwest	1,144	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Northwest	20	SF	5	1-2 years	Water damage
	Floor - Asphalt	Northwest	1,144	SF	7	10+ years	rrater damage
	Floor - Asphalt	Northwest	20	SF	5	1-2 years	Damaged
	Handrails	Northwest	270	LF	7	10+ years	Danagou
	Lighting - Pendent/Surface	Northwest	270	EA	7	6-10 years	
			-				
	Lighting - Pendent/Surface	Northwest	2	EA	6	6-10 years	
	Stairs - Asphalt	Northwest	480	LF	6	10+ years	
	Walls - Plaster/Drywall	Northwest	1,371	SF	6	10+ years	



					4343 W Wilghtwood, Chicago, iL 00039
Category : Interior		Building	: Main		
Group Item - Type	Location	Quantity UOM	Rank	Recommend Replacement	Comments
Group Rem - Type	Location	Quantity OOM	Nalik	Replacement	Comments
Vertical Conveyance					
Elevator - Hydraulic Elevator	Entire Building	1 EA	5	10+ years	



Category : Exterior Building : Addition Recommend Location Item - Type Quantity UOM Replacement Comments Group Rank Entrance #10 - S FΑ Exterior Doors - Exterior FRP Door 1 6 10+ years #11 - S FΑ 6 Entrance Control - Audio and Video 1 6-10 years #11 - S 2 Exterior Doors - Exterior FRP Door EΑ 6 10+ years Exterior Doors - Transom Lite #11 - S 2 ΕA 6 10+ years 1 F Ramps - Concrete #11 - S 8 6 10+ years Exterior Doors - Exterior FRP Door 3 ΕA #5 - E 6 10+ years #5 - E 2 Exterior Doors - Transom Lite EΑ 6 10+ years Exterior Stairs - Concrete #5 - E 79 LF 5 1-2 vears Cracking/chipping LF Exterior Stairs - Stone #5 - E 56 5 6-10 years #6 - S FΑ 6 Entrance Control - Audio and Video 6-10 vears 1 2 Exterior Doors - Exterior FRP Door #6 - S EΑ 6 10+ years Exterior Doors - Transom Lite #6 - S 6 EΑ 10+ years 1 **Exterior Stairs - Concrete** #6 - S 20 LF 6 10+ years ΕA Power Door Operator and Controls #6 - S 2 7 10+ years Ramp Handrail - Steel_Ramp Handrail #6 - S 65 LF 6 10+ years LF Ramps - Concrete #6 - S 40 6 10+ years Stair Handrail - Steel Stair Handrail #6 - S 12 LF 6 10+ vears Exterior Doors - Exterior Steel Door #6.1 - Basement W 1 FΑ 4 1-2 years Deteriorating frame **Exterior Stairs - Concrete** #6.1 - Basement W 120 LF 5 10+ years LF 6 10+ years Stair Handrail - Steel Stair Handrail #6.1 - Basement W 24 Exterior Doors - Exterior FRP Door #7 - W 3 ΕA 5 1-2 years Heavy corrosion on door frame 3 6 Exterior Doors - Transom Lite #7 - W FΑ 10+ years 49 LF Exterior Stairs - Concrete #7 - W 4 0-1 vear Cracking/spalling LF Exterior Stairs - Wood #7 - W 56 6 6-10 years Replaced with wood ΕA Exterior Doors - Exterior FRP Door #9 - S 4 5 6-10 years Exterior Doors - Transom Lite #9 - S 2 ΕA 6 10+ years #9 - S 36 LF Exterior Stairs - Concrete 6 10+ years Exterior Doors - Exterior Steel Door #9.1 - S 2 EΑ 4 1-2 years Corroded 4 LF 5 6-10 years Ramps - Concrete #9.1 - S Foundation Foundation - Concrete Entire Building 1,006 LF 7 10+ years LF Foundation - Concrete Entire Building 15 6 6-10 years SF 7 Superstructure - Metal Deck/ Concrete Entire Building 3.448 10+ years Topping SF Superstructure - Steel with Clay Tile Arch 86,352 7 Entire Building 10+ years Lighting Exterior Lighting - Parapet or Roof Mounted Entire Building 4 EΑ 7 10+ years Exterior Lighting - Wall Mounted Entire Building 14 EΑ 7 10+ years Exterior Lighting - Wall Mounted **Entire Building** 8 EΑ 6 10+ years



Catego	ry : Exterior		В	uilding	on		
_	-			_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Roof Sys	stem						
	Access Ladder - Wood	6 - Main Roof	1	EA	3	0-1 year	Homemade not secured
	Chimney - Brick Chimney- Concrete/ Mortar Liner	6 - Main Roof	42	LF	6	10+ years	
	Coping - Stone	6 - Main Roof	1,091	LF	6	10+ years	
	Downspouts - Interior Downspouts	6 - Main Roof	380	LF	5	2-5 years	
	Parapet - Parapet > 30"	6 - Main Roof	1,091	LF	5	10+ years	
	Roof - Modified Bitumen	6 - Main Roof	28,696	SF	4	1-2 years	Cracking/bubbling/soft spots
	Roof Hatch - Metal	6 - Main Roof	3	EA	3	0-1 year	Not in use.
	Roof Structure - Steel with Clay Tile Arch	6 - Main Roof	28,696	SF	7	10+ years	
	Access Ladder - Metal	7 - South Low Roof	1	EA	4	0-1 year	Not secured
	Coping - Stone	7 - South Low Roof	61	LF	6	10+ years	
	Downspouts - Interior Downspouts	7 - South Low Roof	78	LF	6	10+ years	
	Parapet - 16" - 30" Height	7 - South Low Roof	61	LF	6	10+ years	
	Roof - Modified Bitumen	7 - South Low Roof	1,724	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	7 - South Low Roof	1,724	SF	7	10+ years	
Valls							
	Cheek-Wall - Concrete	Entire Building	85	SF	6	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	879	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	27,059	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	2,050	SF	4	1-2 years	Efflorescence, cracks, open join
	Exterior Walls - Stone-Cast	Entire Building	5,534	SF	6	10+ years	
	Exterior Walls - Stucco	Entire Building	2,025	SF	6	10+ years	
Nindows							
	Guard - Guards wire guard	Entire Building	2,598	SF	6	10+ years	
	Lintels - Steel	Entire Building	1,193	LF	6	10+ years	
	Skylite - Lexan	Entire Building	156	SF	5	1-2 years	Cracking
	Windows - Louver	Entire Building	12	SF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	10,585	SF	5	2-5 years	Single temepered glass window
atego	ry : Electrical		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
mergen	icy System						
0	Security System - CCTV	Entire Building	89,800	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	89,800	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	12	ĒA	6	6-10 years	
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	
	Exit Signs - Pool	5		EA	6	6-10 years	



Catego	ry : Electrical		B	uilding	: Additi	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	8,163	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,126	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	9,477	SF	6	6-10 years	
Main Se	vice						
	PA System	Entire Building	89,800	SF	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	6	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	6	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	6-10 years	
		Entire Ballang	I	LA	,	0-10 years	
Catego	ry : Fire Protection		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Commonts
-		Location	Quantity		INDIIN	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	89,800	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	89,800	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Additi	on	
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	itioning						
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	2	0-1 year	Not use. Decommissioned building is cooled through window, shakers, and Dakin have rooftop mounted fan coil unit.
Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Steam	Entire Building	1	EA	6	6-10 years	Units are located in ceilings underneath tiles
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU-3 - SW Wing



Catego	ry : Mechanical		B	uilding	: Additi	on	
	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Air Intake	Mechanical Room	1	EA	3	0-1 year	Actuators need to be manually, opened and closed. Louvers, not existent, dampers, badly rusted.
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	6	6-10 years	· · · · · · · · · · · · · · · · · · ·
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	7	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU-4 - Lockerooms, swimming poo
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	5	6-10 years	
	Zone Dampers	Mechanical Room	5	EA	7	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU-5 - Gym
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	6	6-10 years	
	Zone Dampers	Mechanical Room	6	EA	6	6-10 years	
Heating	Devices						
	Radiators - Steam	Entire Building	3	EA	6	6-10 years	
	Radiators - Steam	Entire Building	4	EA	6	6-10 years	
	Radiators - Steam	Entire Building	1	EA	3	1-2 years	Behind grate, very rusty. Not used.
	Wall Heater - Electric	Entire Building	5	EA	6	6-10 years	
Tempera	ature Control						
•	Electric Thermostat	Entire Building	3	EA	7	10+ years	
	Hybrid Pneumatic/DDC System	Entire Building	89,800	SF	6	6-10 years	Pneumatic system is operational, but not in use. Decommissioned.
	Thermostats - DDC	Entire Building	39	EA	6	6-10 years	
Jnit Ver							
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	4	EA	2	0-1 year	Old dilapidated, non-operational. Per engineer may be original to the building.
Ventilati	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	



Kelvyn Park High School 4343 W Wrightwood, Chicago, IL 60639

Catego	ry : Mechanical		P	uilding	· Additi	on	
Caleyo	y . WECHAIIICAI		D	unung	. Adulti	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Group	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	Quantity	EA	6	2-5 years	Comments
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	Not operable, not in use.
		Entire Building	1	EA		6-10 years	Not operable, not in use.
	Exhaust Fans- Indoor - Less than 500 CFM		1	EA	6 6		Some runting on popula
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	T	EA	0	6-10 years	Some rusting on panels
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	6-10 years	
	Roof Mounted Duct Work	Entire Building	15	LF	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	
	Type II Exhaust 1000- Warning Ritchen	Entitle Building	I	LA	0	0-10 years	
Catego	ry : Plumbing		В	uilding	: Additi		
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
	Hot Water Storage Tank_Gas - Greater than	Boiler Room	1	EA	6	6-10 years	
	1000 Gallons						
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	89,800	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	89,800	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	89,800	SF	6	6-10 years	
	Fixtures						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	89,800	SF	6	6-10 years	
	(Horizontal Lines)	C				2	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	89,800	SF	6	6-10 years	
	(Risers)	C				2	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	89,800	SF	6	6-10 years	
	(from Risers to Fixtures)	5	-,			,	
	Sanitary Piping	Entire Building	89,800	SF	6	6-10 years	
	Storm Piping	Entire Building	89,800	SF	6	6-10 years	
	Vent Piping	Entire Building	89,800	SF	6	6-10 years	
		5	·				
Pool Sys	tems						
	Pool Drain Piping	Pool area	100	LF	6	6-10 years	
	Pool Filtration System including Pump	Pool area	1	EA	6	6-10 years	
	Pool Hot Water Heater - Gas Fired	Pool area	1	EA	3	0-1 year	Heater for pool not operational. Work
						,	order in for repair.
	Pool Supply and Return Piping	Pool area	300	LF	6	6-10 years	·
	· · ·						



Kelvyn Park High School 4343 W Wrightwood, Chicago, IL 60639

Catego	ry : Plumbing	Building : Addition					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Pumps							
	Pumps - Ejector-Duplex	Basement	1	EA	6	6-10 years	Pump in pit
	Pumps - Ejector-Duplex	Basement	1	EA	6	6-10 years	
	Pumps - Ejector-Duplex	Basement	1	EA	6	6-10 years	

Catego	Category : Room				: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	ative Suites/Offices						
	AC Unit	123 Year Book	1	EA	7	6-10 years	Moved from Main
	Ceiling - Lay-in	123 Year Book	210	SF	6	10+ years	Moved from Main
	Ceiling - Plaster/Drywall	123 Year Book	98	SF	6	10+ years	Moved from Main
	Doors - Transom Window	123 Year Book	9	SF	7	10+ years	Moved from Main
	Doors - Wood Doors inclu hw	123 Year Book	1	EA	7	10+ years	Moved from Main
	Floor - Tile	123 Year Book	200	SF	6	10+ years	Moved from Main
	Floor - Tile	123 Year Book	108	SF	5	1-2 years	Damaged tiles Moved from Main
	Lighting - Lay-in	123 Year Book	7	EA	7	6-10 years	Moved from Main
	Power Distribution	123 Year Book	12	EA	7	10+ years	Moved from Main
	Storage/ Closet	123 Year Book	60	SF	7	10+ years	Moved from Main
	Walls - Plaster/Drywall	123 Year Book	756	SF	6	10+ years	Moved from Main
	Walls - Plaster/Drywall	123 Year Book	2	SF	5	1-2 years	Hole in wall Moved from Main
	Ceiling - Plaster/Drywall	214B PE Office	70	SF	6	10+ years	
	Ceiling - Plaster/Drywall	214B PE Office	10	SF	4	1-2 years	Drywall cracks
	Doors - Wood Doors inclu hw	214B PE Office	2	EA	7	10+ years	
	Floor - Wood	214B PE Office	80	SF	6	10+ years	
	Lighting - Pendent/Surface	214B PE Office	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	214B PE Office	326	SF	6	10+ years	
	Walls - Plaster/Drywall	214B PE Office	10	SF	4	1-2 years	Drywall cracks
	Ceiling - Plaster/Drywall	218A PE Office	75	SF	6	10+ years	,
	Ceiling - Plaster/Drywall	218A PE Office	5	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	218A PE Office	2	EA	7	10+ years	5
	Floor - Wood	218A PE Office	80	SF	6	10+ years	
	Lighting - Pendent/Surface	218A PE Office	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	218A PE Office	330	SF	6	10+ years	
	Walls - Plaster/Drywall	218A PE Office	6	SF	5	1-2 years	Water damage
	AC Unit	219 Office	1	EA	7	6-10 years	Moved from Main
	Ceiling - Plaster/Drywall	219 Office	205	SF	6	10+ years	Moved from Main
	Doors - Transom Window	219 Office	9	SF	7	10+ years	Moved from Main
	Doors - Wood Doors inclu hw	219 Office	1	EA	7	10+ years	Moved from Main
	Floor - Carpet	219 Office	205	SF	6	6-10 years	Moved from Main
	Lighting - Pendent/Surface	219 Office	2	EA	7	6-10 years	Moved from Main
	Power Distribution	219 Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	219 Office	490	SF	6	10+ years	Moved from Main



atego	ry : Room		B	uilding	: Additie		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Unit	316A	1	EA	5	0-1 year	Not functioning
	Ceiling - Lay-in	316A	141	SF	6	10+ years	
	Ceiling - Lay-in	316A	8	SF	5	0-1 year	Missing tiles
	Ceiling - Lay-in	316A	24	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	316A	1	EA	7	10+ years	
	Floor - Tile	316A	173	SF	6	10+ years	
	Lighting - Lay-in	316A	2	EA	7	6-10 years	
	Power Distribution	316A	18	EA	7	10+ years	
	Walls - Plaster/Drywall	316A	491	SF	6	10+ years	
	Ceiling - Lay-in	Boiler Room Engineer	102	SF	7	10+ years	Moved from Main
	Ceiling - Lay-in	Boiler Room Engineer	24	SF	5	1-2 years	Missing tiles Moved from Main
	Doors - Wood Doors inclu hw	Boiler Room Engineer	1	EA	7	10+ years	Moved from Main
	Floor - Concrete	Boiler Room Engineer	128	SF	7	10+ years	Moved from Main
	Lighting - Pendent/Surface	Boiler Room Engineer	1	EA	7	6-10 years	Moved from Main
	Power Distribution	Boiler Room Engineer	4	EA	7	10+ years	Moved from Main
	Walls - Plaster/Drywall	Boiler Room Engineer	337	SF	7	10+ years	Moved from Main
	Ceiling - Plaster/Drywall	Kitchen Manager's Office	62	SF	7	10+ years	Moved from Main
	Ceiling - Plaster/Drywall	Kitchen Manager's Office	8	SF	4	0-1 year	Hole Moved from Main
	Doors - Wood Doors inclu hw	Kitchen Manager's Office	1	EA	6	10+ years	Moved from Main
	Floor - Tile	Kitchen Manager's Office	70	SF	6	10+ years	Moved from Main
	Lighting - Pendent/Surface	Kitchen Manager's Office	1	EA	7	6-10 years	Moved from Main
	Power Distribution	Kitchen Manager's Office	2	EA	7	10+ years	Moved from Main
	Walls - Masonry	Kitchen Manager's Office	42	SF	7	10+ years	Moved from Main
	Walls - Plaster/Drywall	Kitchen Manager's Office	42	SF	6	10+ years	Moved from Main
/mnas	ia						
	Bleacher Seating	Room 214	175	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Room 214	4,724	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 214	30	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	Room 214	4	EA	6	10+ years	0
	Floor - Wood	Room 214	4,754	SF	7	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	Room 214	20	ĒA	7	6-10 years	
	Scoreboards	Room 214	1	EA	7	6-10 years	
	Storage/ Closet	Room 214	80	SF	7	10+ years	Locked
	Walls - Structural Glazed Tile	Room 214	5,467	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 218, Girl's Gym	4,703	SF	6	10+ years	Max occupancy sign not posted
	Ceiling - Plaster/Drywall	Room 218, Girl's Gym	20	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	Room 218, Girl's Gym	20	EA	7	10+ years	
	Floor - Wood	Room 218, Girl's Gym	4,723	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	Room 218, Girl's Gym	-,, 23	EA	7	6-10 years	



Group

Kitchen

Category : Room

Item - Type

Floor - Tile

Serving Line

Ceiling - Splined

Doors - Transom Window

Doors - Wood Doors inclu hw

Lighting - Pendent/Surface

Kelvyn Park High School

4343 W Wrightwood, Chicago, IL 60639 **Building : Addition** Recommend Location Quantity UOM Rank Replacement Comments Servery 4,250 SF 6 10+ years Moved from Main, corrected quantity 10+ years Servery 18 SF 7 Servery 10+ years 2 ΕA 7 10+ years Servery 4,250 SF 6 Moved from Main, corrected quantity 25 ΕA 7 6-10 years Moved from Main Servery Servery 60 LF 7 10+ years Moved from Main Serverv 240 SE 7 10 + vearsMoved from Main antity

	Serving Line	Servery	00	LF	'	10+ years	
	Storage/ Closet	Servery	240	SF	7	10+ years	Moved from Main
	Walls - Metal Panel	Servery	900	SF	7	10+ years	Moved from Main, corrected quar
Locker	/Shower Room						
	Accessories	1st Floor Female Locker Room 116	3,310	SF	5	6-10 years	
	Benches, ped mounted	1st Floor Female Locker Room 116	128	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Female Locker Room 116	3,310	SF	6	10+ years	
	Doors - Side-lite	1st Floor Female Locker Room 116	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Female Locker Room 116	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Female Locker Room 116	3,210	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Female Locker Room 116	100	SF	5	1-2 years	Cracked tiles
	Floor Drain	1st Floor Female Locker Room 116	8	EA	7	6-10 years	
	Hand Dryer	1st Floor Female Locker Room 116	3	EA	7	6-10 years	
	Lavatory	1st Floor Female Locker Room 116	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor Female Locker Room 116	43	EA	5	1-2 years	Missing covers
	Partitions	1st Floor Female Locker Room 116	28	EA	7	10+ years	
	Partitions	1st Floor Female Locker Room 116	3	EA	5	6-10 years	
	Showers	1st Floor Female Locker Room 116	28	EA	5	6-10 years	
	Student Lockers - Two Tier	1st Floor Female Locker Room 116	515	EA	6	6-10 years	
	Student Lockers - Two Tier	1st Floor Female Locker Room 116	11	EA	5	1-2 years	Missing doors
	Walls - Concrete Block	1st Floor Female Locker Room 116	500	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor Female Locker Room 116	3,306	SF	6	10+ years	
	Water Closet	1st Floor Female Locker Room 116	3	EA	6	10+ years	
	Accessories	1st Floor Male Locker Room 114	2,790	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Male Locker Room 114	2,750	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Male Locker Room 114	20	SF	5	1-2 years	Water damage
	Doors - Steel Doors incl hw	1st Floor Male Locker Room 114	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor Male Locker Room 114	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Male Locker Room 114	2	EA	6	10+ years	
	Floor - Sport Flooring	1st Floor Male Locker Room 114	840	SF	5	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Male Locker Room 114	1,950	SF	6	10+ years	
	Floor Drain	1st Floor Male Locker Room 114	2	EA	7	10+ years	
	Lavatory	1st Floor Male Locker Room 114	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor Male Locker Room 114	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor Male Locker Room 114	12	EA	5	1-2 years	Missing cover
	Partitions	1st Floor Male Locker Room 114	2	EA	5	6-10 years	
	Showers	1st Floor Male Locker Room 114	9	EA	5	6-10 years	



Categor	ry : Room		В	uilding	: Additi			
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Student Lockers - One Tier	1st Floor Male Locker Room 114	160	EA	7	10+ years		
	Urinals	1st Floor Male Locker Room 114	3	EA	7	10+ years		
	Walls - Concrete Block	1st Floor Male Locker Room 114	220	SF	7	10+ years		
	Walls - Masonry	1st Floor Male Locker Room 114	3,620	SF	6	10+ years		
	Walls - Structural Glazed Tile	1st Floor Male Locker Room 114	256	SF	6	10+ years		
	Water Closet	1st Floor Male Locker Room 114	2	EA	6	10+ years		
	Accessories	In Kitchen	205	SF	7	6-10 years	Moved from Main	
	Ceiling - Plaster/Drywall	In Kitchen	185	SF	7	10+ years	Moved from Main	
	Ceiling - Plaster/Drywall	In Kitchen	20	SF	5	10+ years	Water damage Moved from Main	
	Doors - Wood Doors inclu hw	In Kitchen	3	EA	7	10+ years	Moved from Main	
	Floor - Tile/Sheet	In Kitchen	202	SF	7	6-10 years	Moved from Main	
	Floor - Tile/Sheet	In Kitchen	3	SF	4	0-1 year	Missing tiles Moved from Main	
	Lavatory	In Kitchen	1	EA	7	10+ years	Moved from Main	
	Lighting - Pendent/Surface	In Kitchen	4	EA	7	10+ years	Moved from Main	
	Partitions	In Kitchen	1	EA	7	10+ years	Moved from Main	
	Student Lockers - One Tier	In Kitchen	13	EA	6	10+ years	Moved from Main	
	Walls - Plaster/Drywall	In Kitchen	326	SF	7	10+ years	Moved from Main	
	Walls - Plaster/Drywall	In Kitchen	10	SF	5	10+ years	Peeling paint Moved from Main	
	Water Closet	In Kitchen	1	EA	7	6-10 years	Moved from Main	
	Accessories	Unisex locker room	290	SF	7	6-10 years		
	Benches, ped mounted	Unisex locker room	6	LF	7	10+ years		
	Ceiling - Plaster/Drywall	Unisex locker room	290	SF	7	10+ years		
	Doors - Steel Doors incl hw	Unisex locker room	1	EA	7	10+ years		
	Doors - Wood Doors inclu hw	Unisex locker room	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Unisex locker room	290	SF	7	10+ years		
	Floor Drain	Unisex locker room	2	EA	7	10+ years		
	Hand Dryer	Unisex locker room	1	EA	7	6-10 years		
	Lavatory	Unisex locker room	1	EA	7	10+ years		
	Lighting - Pendent/Surface	Unisex locker room	4	EA	7	10+ years		
	Showers	Unisex locker room	1	EA	7	10+ years		
	Student Lockers - One Tier	Unisex locker room	4	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	Unisex locker room	520	SF	7	10+ years		
	Water Closet	Unisex locker room	1	EA	7	10+ years		
<i>Nechanic</i>	cal/ Service Rooms							
	Janitor's Closet	1st Floor	15	SF	5	10+ years		
	Storage Room	1st Floor	105	SF	7	10+ years		
	Storage Room	1st Floor	250	SF	7	10+ years	Moved from Main	
	Vaults	1st Floor	30	SF	7	10+ years	Moved from Main	
	Janitor's Closet	2nd Floor	12	SF	7	10+ years		
	Storage Room	2nd Floor	158	SF	5	10+ years	Peeling paint Moved from Main	
	Janitor's Closet	3rd Floor	50	SF	5	10+ years	5 - 5	
	Janitor's Closet	3rd Floor	13	SF	5	10+ years		
	Air Tunnel	Basement	1,354	SF	7	10+ years		
		Basemont	1,004	0	'	ioi youio		



Category : Room			В	uilding			
Ŭ						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Crawl Space - Unfinished	Basement	4,543	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	3,658	SF	5	10+ years	
	Storage Room	Basement	750	SF	5	10+ years	
	Storage Room	Basement	123	SF	5	10+ years	
Pool & N	latatorium						
	Bleachers Seating/Plank Seating	1st Floor	2	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3,550	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	ĒA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	2,022	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	_,。	SF	5	1-2 years	Cracking
	Lighting - Pendent/Surface	1st Floor	35	EA	7	6-10 years	Cracinity
	Pool Basin	1st Floor	1,500	SF	7	10+ years	
	Pool Deck	1st Floor	50	SF	7	10+ years	
	Pool Deck Drains	1st Floor	8	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,300	SF	6	10+ years	
			0,000	0.	Ũ	ior youro	
Prep Ro							
	Casework	125A	10	LF	6	10+ years	Moved from Main
	Ceiling - Plaster/Drywall	125A	135	SF	6	10+ years	Moved from Main
	Doors - Wood Doors inclu hw	125A	1	EA	7	10+ years	Moved from Main
	Floor - Tile	125A	135	SF	7	10+ years	Moved from Main
	Lighting - Pendent/Surface	125A	3	EA	6	10+ years	Moved from Main
	Walls - Plaster/Drywall	125A	520	SF	7	10+ years	Moved from Main
	Work Sink	125A	1	EA	5	6-10 years	Moved from Main
	Casework	221	14	LF	6	10+ years	Moved from Addition
	Ceiling - Plaster/Drywall	221	88	SF	6	10+ years	Moved from Addition
	Doors - Wood Doors inclu hw	221	1	EA	7	10+ years	Moved from Addition
	Floor - Tile	221	88	SF	6	10+ years	Moved from Addition
	Lighting - Pendent/Surface	221	2	EA	7	6-10 years	Moved from Addition
	Walls - Plaster/Drywall	221	342	SF	7	10+ years	Moved from Addition
	Casework	225	14	LF	6	10+ years	Moved from Addition
	Ceiling - Plaster/Drywall	225	88	SF	6	10+ years	Peeling paint, Moved from Addition
	Doors - Wood Doors inclu hw	225	1	EA	7	10+ years	Moved from Addition
	Floor - Tile	225	88	SF	6	10+ years	Moved from Addition
	Lighting - Pendent/Surface	225	2	EA	6	6-10 years	Moved from Addition
	Walls - Plaster/Drywall	225	332	SF	6	10+ years	Moved from Addition
	Walls - Plaster/Drywall	225	10	SF	5	10+ years	Cracks, Moved from Addition
	Work Sink	225	1	EA	5	1-2 years	Not functional
	Casework	In 115	30	LF	6	10+ years	Missing drawer Moved from Main
	Ceiling - Plaster/Drywall	In 115	105	SF	6	10+ years	Moved from Main
	Doors - Wood Doors inclu hw	In 115	103	EA	7	10+ years	Moved from Main
	Floor - Tile/Sheet	In 115 In 115	105	SF	7	10+ years	Moved from Main
	Lighting - Pendent/Surface	In 115	2	EA	7	6-10 years	Moved from Main
	Lighting - I chucht/Sullace	111113	2	ĽA	1	U-TU years	



Category : Room Building : Addition							4343 W Wrightwood, Chicago, IL 60639
Catego		В	unung	. Auditi	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Walls - Plaster/Drywall	In 115	320	SF	6	10+ years	Moved from Main
	Work Sink	In 115	1	EA	5	1-2 years	Sink covered over Moved from Main
	Casework	In 229	4	LF	7	10+ years	Moved from Main
	Ceiling - Lay-in	In 229	295	SF	7	10+ years	Moved from Main
	Doors - Wood Doors inclu hw	In 229	200	EA	7	10+ years	Moved from Main
	Floor - Tile	In 229	295	SF	6	10+ years	Moved from Main
	Lighting - Lay-in	In 229	6	EA	7	6-10 years	Moved from Main
	Walls - Plaster/Drywall	In 229	634	SF	6	10+ years	Moved from Main
	Work Sink	In 229	1	EA	7	10+ years	Moved from Main
				_/ \	•	let yeare	
Restroor	n						
	Accessories	1st Floor Women 117D	212	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Women 117D	204	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Women 117D	8	SF	4	0-1 year	Holes in ceiling
	Doors - Wood Doors inclu hw	1st Floor Women 117D	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Women 117D	212	SF	6	10+ years	
	Hand Dryer	1st Floor Women 117D	2	EA	7	6-10 years	
	Lavatory	1st Floor Women 117D	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Women 117D	3	EA	7	6-10 years	
	Partitions	1st Floor Women 117D	4	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Women 117D	468	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor Women 117D	2	SF	4	0-1 year	Damaged wall
	Water Closet	1st Floor Women 117D	4	EA	6	10+ years	
	Accessories	3rd Floor - Women	283	SF	7	6-10 years	Moved from Main
	Ceiling - Plaster/Drywall	3rd Floor - Women	283	SF	6	10+ years	Moved from Main
	Doors - Transom Window	3rd Floor - Women	18	SF	7	10+ years	Moved from Main
	Doors - Wood Doors inclu hw	3rd Floor - Women	2	EA	7	10+ years	Moved from Main
	Floor - Tile Ceramic/ Porcelain	3rd Floor - Women	280	SF	7	10+ years	Moved from Main
	Floor - Tile Ceramic/ Porcelain	3rd Floor - Women	3	SF	5	1-2 years	Missing/Damaged Moved from Main
	Floor Drain	3rd Floor - Women	1	EA	7	10+ years	Moved from Main
	Lavatory	3rd Floor - Women	2	EA	7	10+ years	Moved from Main
	Lighting - Pendent/Surface	3rd Floor - Women	3	EA	7	10+ years	Moved from Main
	Partitions	3rd Floor - Women	3	EA	5	10+ years	Moved from Main
	Walls - Plaster/Drywall	3rd Floor - Women	115	SF	6	10+ years	Moved from Main
	Walls - Plaster/Drywall	3rd Floor - Women	5	SF	5	10+ years	Cracks, Moved from Main
	Walls - Structural Glazed Tile	3rd Floor - Women	120	SF	7	10+ years	Moved from Main
	Water Closet	3rd Floor - Women	2	EA	7	10+ years	Moved from Main
	Water Closet	3rd Floor - Women	1	EA	4	0-1 year	Out of order Moved from Main
	Accessories	3rd Floor Unisex	105	SF	7	6-10 years	Moved from Main
	Ceiling - Plaster/Drywall	3rd Floor Unisex	105	SF	6	10+ years	Moved from Main
	Doors - Wood Doors inclu hw	3rd Floor Unisex	1	EA	7	10+ years	Moved from Main
	Floor - Tile Ceramic/ Porcelain	3rd Floor Unisex	105	SF	7	10+ years	Moved from Main
	Floor Drain	3rd Floor Unisex	1	EA	7	10+ years	Moved from Main
	Hand Dryer	3rd Floor Unisex	1	EA	7	6-10 years	Moved from Main



Catago			P	Building : Addition				
Catego	ry : Room		В	ullaing	: Additio			
0	Items Trune	Leasting	Overstites		Denl	Recommend	Commente	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments Mayor d from Main	
	Lavatory	3rd Floor Unisex	1	EA	7	10+ years	Moved from Main	
	Lighting - Pendent/Surface	3rd Floor Unisex	1	EA	7	10+ years	Moved from Main	
	Walls - Tile Ceramic/ Porcelain	3rd Floor Unisex	345	SF	7	10+ years	Moved from Main	
	Water Closet	3rd Floor Unisex	1	EA	7	10+ years	Moved from Main	
	Accessories	3rd Floor next to 319 - used as storage	292	SF	5	6-10 years	Moved from Main	
	Ceiling - Plaster/Drywall	3rd Floor next to 319 - used as storage	292	SF	6	10+ years	Moved from Main	
	Doors - Transom Window	3rd Floor next to 319 - used as storage	36	SF	7	10+ years	Moved from Main	
	Doors - Wood Doors inclu hw	3rd Floor next to 319 - used as storage	3	EA	7	10+ years	Moved from Main	
	Floor - Tile Ceramic/ Porcelain	3rd Floor next to 319 - used as storage	292	SF	7	10+ years	Moved from Main	
	Floor Drain	3rd Floor next to 319 - used as storage	1	EA	7	10+ years	Moved from Main	
	Hand Dryer	3rd Floor next to 319 - used as storage	2	EA	5	6-10 years	Moved from Main	
	Lavatory	3rd Floor next to 319 - used as storage	2	EA	6	6-10 years	Moved from Main	
	Lighting - Pendent/Surface	3rd Floor next to 319 - used as storage	5	EA	5	2-5 years	Moved from Main	
	Partitions	3rd Floor next to 319 - used as storage	6	EA	7	10+ years	Moved from Main	
	Walls - Plaster/Drywall	3rd Floor next to 319 - used as storage	477	SF	6	10+ years	Moved from Main	
	Walls - Structural Glazed Tile	3rd Floor next to 319 - used as storage	477	SF	7	10+ years	Moved from Main	
	Water Closet	3rd Floor next to 319 - used as storage	6	EA	6	6-10 years	Moved from Main	
	Accessories	Next to 117	680	SF	7	6-10 years	Moved from Main	
	Ceiling - Plaster/Drywall	Next to 117	680	SF	7	10+ years	Moved from Main	
	Doors - Wood Doors inclu hw	Next to 117	1	EA	7	10+ years	Moved from Main	
	Floor - Tile Ceramic/ Porcelain	Next to 117	675	SF	7	10+ years	Moved from Main	
	Floor - Tile Ceramic/ Porcelain	Next to 117	5	SF	5	1-2 years	Missing tiles throughout, Moved from	
						-	Main	
	Floor Drain	Next to 117	1	EA	7	10+ years	Moved from Main	
	Hand Dryer	Next to 117	2	EA	7	6-10 years	Moved from Main	
	Lavatory	Next to 117	3	EA	7	10+ years	Moved from Main	
	Lavatory	Next to 117	1	EA	4	0-1 year	Missing Moved from Main	
	Lighting - Pendent/Surface	Next to 117	4	EA	7	6-10 years	Moved from Main	
	Partitions	Next to 117	3	EA	7	10+ years	Moved from Main	
	Urinals	Next to 117	8	EA	7	10+ years	Moved from Main	
	Walls - Concrete Block	Next to 117	600	SF	7	10+ years	Moved from Main	



Kelvyn Park High School 4343 W Wrightwood, Chicago, IL 60639

Categor	Category : Room			Building : Addition					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Masonry	Next to 117	120	SF	7	10+ years	Moved from Main		
	Water Closet	Next to 117	3	EA	7	10+ years	Moved from Main		

Category : Classroom

Category : Classroom			В	Building : Addition					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #115 (Science Classroom)								
	AC Units	1st Floor	2	EA	7	6-10 years	Moved from Main		
	Casework	1st Floor	31	LF	7	10+ years	Moved from Main		
	Casework	1st Floor	5	LF	6	1-2 years	Moved from Main, Missing drawers		
	Ceiling - Plaster/Drywall	1st Floor	1,010	SF	7	10+ years	Moved from Main		
	Chalk Board	1st Floor	12	LF	4	2-5 years	Moved from Main		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	Moved from Main		
	Eye Wash Station	1st Floor	1	EA	7	10+ years	Moved from Main		
	Floor - Tile	1st Floor	1,010	SF	7	10+ years	Moved from Main		
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	Moved from Main		
	Marker Board	1st Floor	12	LF	7	6-10 years	Moved from Main		
	Science Lab Shower	1st Floor	1	EA	7	10+ years	Moved from Main		
	Storage/ Closet	1st Floor	98	SF	7	10+ years	Moved from Main		
	Walls - Plaster/Drywall	1st Floor	1,269	SF	7	10+ years	Moved from Main		
	Work Sink	1st Floor	2	EA	7	10+ years	Moved from Main		
	Work Sink	1st Floor	1	EA	4	0-1 year	Moved from Main, Damaged sink		
Classroo	m #117 (Office)								
01222100	AC Units	1st Floor	1	EA	7	6-10 years	Moved from Main		
	Ceiling - Lay-in	1st Floor	380	SF	6	10+ years	Moved from Main		
	Chalk Board	1st Floor	4	LF	4	2-5 years	Moved from Main		
	Doors - Transom Window	1st Floor	4 9	SF	4 7	10+ years	Moved from Main		
	Doors - Wood Doors inclu hw	1st Floor	9	EA	7	10+ years	Moved from Main		
	Floor - Tile	1st Floor	380	SF	6	10+ years	Moved from Main		
	Lighting - Lay-in	1st Floor	500	EA	7	6-10 years	Moved from Main		
	Marker Board	1st Floor	6	LF	7	•	Moved from Main		
	Walls - Plaster/Drywall	1st Floor	903	SF	6	6-10 years 10+ years	Moved from Main		
		13(1100)	903	51	0	TOF years			
Classroo	m #119 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years	Moved from Main		
	Ceiling - Lay-in	1st Floor	760	SF	6	10+ years	Moved from Main		
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	Moved from Main		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	Moved from Main		
	Floor - Tile	1st Floor	750	SF	6	10+ years	Moved from Main		
	Floor - Tile	1st Floor	10	SF	5	1-2 years	Damaged tiles, Moved from Main		
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	Moved from Main		
	Marker Board	1st Floor	30	LF	7	6-10 years	Moved from Main		



Catego	ry : Classroom	В	Building : Addition					
U			J		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-	Storage/ Closet	1st Floor	12	SF	7	10+ years	Moved from Main	
	Walls - Plaster/Drywall	1st Floor	1,269	SF	6	10+ years	Moved from Main	
lassroc	om #121 (Store Room)							
	AC Units	1st Floor	1	EA	7	6-10 years	Moved from Main	
	Casework	1st Floor	8	LF	7	6-10 years	Moved from Main	
	Casework	1st Floor	2	LF	6	6-10 years	Missing drawer Moved from Main	
	Ceiling - Plaster/Drywall	1st Floor	628	SF	6	10+ years	Moved from Main	
	Chalk Board	1st Floor	24	LF	4	2-5 years	Moved from Main	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	Moved from Main	
	Eye Wash Station	1st Floor	1	EA	7	10+ years	Moved from Main	
	Floor - Tile	1st Floor	628	SF	7	10+ years	Moved from Main	
	Gas Line	1st Floor	2	EA	7	6-10 years		
	Lighting - Lay-in	1st Floor	2	EA	7	6-10 years	Moved from Main	
	Lighting - Lay-in	1st Floor	1	EA	5	0-1 year	Damaged fixture	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	Moved from Main	
	Marker Board	1st Floor	16	LF	7	6-10 years	Moved from Main	
	Science Lab Shower	1st Floor	1	EA	7	10+ years	Moved from Main	
	Walls - Plaster/Drywall	1st Floor	1,298	SF	7	10+ years	Moved from Main	
	Work Sink	1st Floor	1	EA	7	10+ years	Moved from Main	
lassroo	om #125 (Science Lab Level 3)							
	AC Units	1st Floor	2	EA	7	6-10 years	Moved from Main	
	Casework	1st Floor	60	LF	7	10+ years	Moved from Main	
	Ceiling - Lay-in	1st Floor	1,010	SF	7	10+ years	Moved from Main	
	Chalk Board	1st Floor	12	LF	4	2-5 years	Moved from Main	
	Doors - Wood Doors inclu hw	1st Floor	- <u>-</u> 1	EA	7	10+ years	Moved from Main	
	Eye Wash Station	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	1,010	SF	7	10+ years	Moved from Main	
	Gas Line	1st Floor	6	EA	7	10+ years	Moved from Main	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	Moved from Main	
	Marker Board	1st Floor	16	LF	7	6-10 years	Moved from Main	
	Science Lab Shower	1st Floor	1	EA	7	10+ years	Moved from Main	
	Storage/ Closet	1st Floor	46	SF	7	10+ years	Moved from Main	
	Walls - Plaster/Drywall	1st Floor	1,233	SF	7	10+ years	Moved from Main	
	Work Sink	1st Floor	5	EA	7	10+ years	Moved from Main	
lassroc	m #127 (Faculty Lounge)							
	AC Units	1st Floor	1	EA	7	6-10 years	Moved from Main	
	Casework	1st Floor	26	LF	7	10+ years	Moved from Main	
		1st Floor	405	SF	6	10+ years	Moved from Main	
	Celling - Lav-in							
	Ceiling - Lay-in Ceiling - Lay-in	1st Floor	17	SF	5	1-2 years	Water damage.Moved from Main	



Kelvyn Park High School 4343 W Wrightwood, Chicago, IL 60639

atego	ry : Classroom		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	Moved from Main
	Floor - Tile	1st Floor	422	SF	6	10+ years	Moved from Main
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	Moved from Main
	Walls - Plaster/Drywall	1st Floor	664	SF	7	10+ years	Moved from Main
lassroc	om #129 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	Moved from Main
	Ceiling - Plaster/Drywall	2nd Floor	682	SF	6	10+ years	Moved from Main
	Chalk Board	2nd Floor	24	LF	4	2-5 years	Moved from Main
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	Moved from Main
	Floor - Tile	2nd Floor	677	SF	6	10+ years	Moved from Main
	Floor - Tile	2nd Floor	5	SF	5	0-1 year	Damaged tiles Moved from Main
	Lighting - Lay-in	2nd Floor	14	EA	6	6-10 years	Moved from Main
	Storage/ Closet	2nd Floor	24	SF	7	10+ years	Moved from Main
	Walls - Plaster/Drywall	2nd Floor	1,269	SF	6	10+ years	Moved from Main
assroc	om #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	Moved from Main
	Ceiling - Plaster/Drywall	2nd Floor	560	SF	6	10+ years	Moved from Main
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	Moved from Main
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	Moved from Main
	Floor - Tile	2nd Floor	560	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒA	7	6-10 years	Moved from Main
	Marker Board	2nd Floor	12	LF	7	6-10 years	Moved from Main
	Storage/ Closet	2nd Floor	55	SF	7	10+ years	Moved from Main
	Walls - Plaster/Drywall	2nd Floor	1,483	SF	7	10+ years	Moved from Main
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	10+ years	Minor cracks Moved from Main
assroc	om #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	586	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	598	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	5	1-2 years	Missing cover
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	630	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	

Classroom #220 (Regular Classroom)



Category : Classroom				uilding	: Additio		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	594	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	598	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	8	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	Locked
	Walls - Plaster/Drywall	2nd Floor	630	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
lassroo	m #221 (Science Lab Level 3)						
	AC Units	2nd Floor	2	EA	7	6-10 years	Moved from Main
	Casework	2nd Floor	53	LF	7	10+ years	Moved from Main
	Ceiling - Plaster/Drywall	2nd Floor	1,010	SF	7	10+ years	Moved from Main
	Chalk Board	2nd Floor	. 9	LF	4	2-5 years	Moved from Main
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	Moved from Main
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	Moved from Main
	Floor - Tile	2nd Floor	1,010	SF	7	10+ years	Moved from Main
	Gas Line	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	Moved from Main
	Marker Board	2nd Floor	12	LF	7	6-10 years	Moved from Main
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	Moved from Main
	Storage/ Closet	2nd Floor	16	SF	7	10+ years	Moved from Main
	Walls - Plaster/Drywall	2nd Floor	1,500	SF	6	10+ years	Moved from Main
	Work Sink	2nd Floor	1,000	EA	5	1-2 years	Not draining Moved from Main
assroo	m #223 (Science Lab Level 2)						
	AC Units	2nd Floor	2	EA	7	6-10 years	Moved from Main
	Casework	2nd Floor	74	LF	7	10+ years	Moved from Main
	Ceiling - Lay-in	2nd Floor	1,010	SF	7	10+ years	Moved from Main
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	Moved from Main
	Floor - Tile	2nd Floor	1,010	SF	6	10+ years	Moved from Main
	Gas Line	2nd Floor	9	EA	7	6-10 years	Moved from Main
	Lighting - Lay-in	2nd Floor	17	EA	7	10+ years	Moved from Main
	Science Lab Fume Hood	2nd Floor	1	EA	7	10+ years	Moved from Main
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	Moved from Main
	Walls - Plaster/Drywall	2nd Floor	1,111	SF	6	10+ years	Moved from Main
	Work Sink	2nd Floor	4	EA	7	10+ years	Moved from Main
assroo	m #225 (Science Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	Moved from Main
		2nd Floor	53	LF	7	10+ years	



atego	ry : Classroom		В	uilding	: Additie		
	-			_		Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	1,010	SF	7	10+ years	Moved from Main
	Chalk Board	2nd Floor	9	LF	4	2-5 years	Moved from Main
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	Moved from Main
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	Moved from Main
	Floor - Tile	2nd Floor	1,010	SF	6	10+ years	Moved from Main
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	Moved from Main
	Marker Board	2nd Floor	12	LF	7	6-10 years	Moved from Main
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	Moved from Main
	Storage/ Closet	2nd Floor	32	SF	7	10+ years	Moved from Main
	Walls - Plaster/Drywall	2nd Floor	1,485	SF	6	10+ years	Moved from Main
	Work Sink	2nd Floor	1	EA	7	10+ years	Moved from Main
assroo	m #229 (Science Lab Level 1)						
	AC Units	2nd Floor	1	EA	7	10+ years	Moved from Main
	Casework	2nd Floor	53	LF	7	10+ years	Moved from Main
	Ceiling - Plaster/Drywall	2nd Floor	1,010	SF	7	10+ years	Moved from Main
	Doors - Wood Doors inclu hw	2nd Floor	· 1	EA	7	10+ years	Moved from Main
	Eye Wash Station	2nd Floor	1	EA	7	10+ years	Moved from Main
	Floor - Tile	2nd Floor	1,010	SF	7	10+ years	Moved from Main
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	Moved from Main
	Marker Board	2nd Floor	12	LF	7	6-10 years	Moved from Main
	Science Lab Shower	2nd Floor	1	EA	7	10+ years	Moved from Main
	Storage/ Closet	2nd Floor	80	SF	7	10+ years	Moved from Main
	Walls - Plaster/Drywall	2nd Floor	1,485	SF	7	10+ years	Moved from Main
	Work Sink	2nd Floor	3	ËA	7	10+ years	Moved from Main
assroo	m #313 (Band Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	Moved from Main
	Casework	3rd Floor	3	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	2,088	SF	7	10+ years	Moved from Main
	Doors - Wood Doors inclu hw	3rd Floor	2,000	EA	7	10+ years	Moved from Main
	Floor - Tile	3rd Floor	2,088	SF	7	10+ years	Moved from Main
	Instrument Storage Casework	3rd Floor	44	LF	7	10+ years	Moved from Main
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	Moved from Main
	Storage/ Closet	3rd Floor	150	SF	5	10+ years	Peeling paint Moved from Main
	Walls - Plaster/Drywall	3rd Floor	1,586	SF	7	10+ years	Moved from Main
	Work Sink	3rd Floor	1,000	EA	7	10+ years	Moved from Main
	Work Sink	514 1 1001	'	LA	,	TOF years	Moved from Main
assroc	m #315 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	Moved from Main
	Casework	3rd Floor	8	LF	7	10+ years	Moved from Main
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	7	10+ years	Moved from Main
	Chalk Board	3rd Floor	5	LF	4	2-5 years	Moved from Main



<u> </u>				ب نامانه م	· ^ d d :+:	.	4343 W Wrightwood, Chicago, IL 60639
Catego	ry : Classroom			unaing	: Additi		
Crown	Hom Turne	Location	Quantity	UOM	Donk	Recommend	Commente
Group	Item - Type Doors - Transom Window	3rd Floor	Quantity	SF	Rank 7	Replacement 10+ years	Comments Moved from Main
	Doors - Wood Doors inclu hw	3rd Floor	18 2	EA	7		Moved from Main
				SF		10+ years	
	Floor - Wood	3rd Floor	760		7	10+ years	Moved from Main
	Lighting - Pendent/Surface	3rd Floor	14	EA LF	7	6-10 years	Moved from Main
	Marker Board Walls - Plaster/Drywall	3rd Floor 3rd Floor	36 1,293	SF	7 7	6-10 years 10+ years	Moved from Main Moved from Main
Classro	om #316 (Computer Lab)						
01233100	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	580	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Missing tile
	Ceiling - Lay-in	3rd Floor	10	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years	Water damage
	Floor - Tile	3rd Floor	598	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	667	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	20	SF	4	0-1 year	Water damage
	Wireless System	3rd Floor	1	EA	7	6-10 years	Water damage
	om #318 (Multi Purpose Room) AC Units Casework Ceiling - Lay-in Ceiling - Lay-in Doors - Wood Doors inclu hw	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	1 15 589 9 1	EA LF SF EA	7 7 6 4 7	6-10 years 10+ years 10+ years 0-1 year 10+ years	Water damage
	Floor - Tile	3rd Floor	598	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	15	EA	7 7	6-10 years	
	Marker Board Walls - Plaster/Drywall	3rd Floor 3rd Floor	8 687	LF SF	6	6-10 years 10+ years	
	Wireless System	3rd Floor	1	EA	7	6-10 years	
		310 1001	1	EA	/	0-10 years	
Classroo	om #319 (Regular Classroom)			F ^	7	0.40	Maria di fuana Maria
	AC Units	3rd Floor	1	EA	7	6-10 years	Moved from Main
	Casework	3rd Floor	8	LF	7	10+ years	Moved from Main
	Ceiling - Plaster/Drywall	3rd Floor	760	SF	7	10+ years	Moved from Main
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	Moved from Main
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	Moved from Main
	Floor - Tile	3rd Floor	760	SF	6	10+ years	Moved from Main
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	Moved from Main
	Marker Board	3rd Floor	16	LF	7	6-10 years	Moved from Main
	Walls - Plaster/Drywall	3rd Floor	960	SF	7	10+ years	Moved from Main Recalculated



Group

Category : Classroom

Kelvyn Park High School 4343 W Wrightwood, Chicago, IL 60639

Recommend Item - Type Location Quantity UOM Rank Replacement Comments quantity SF 6 Walls - Plaster/Drvwall 3rd Floor 10 10+ years Peeling paint. Moved from Main Classroom #321 (Regular Classroom) AC Units 3rd Floor 1 7 Moved from Main EA 6-10 years 3rd Floor 8 LF 7 Casework 10+ years Moved from Main Ceiling - Plaster/Drvwall 3rd Floor 760 SF 7 10+ years Moved from Main SF Ceiling - Plaster/Drywall 3rd Floor 10 5 10+ years Minor water damage, peeling paint, Moved from Main Chalk Board LF 3rd Floor 7 4 2-5 years Moved from Main Doors - Steel Doors incl hw 2 ΕA Moved from Main 3rd Floor 7 10+ years Doors - Transom Window 3rd Floor 12 SF 7 10+ years Moved from Main Floor - Wood 3rd Floor SF 7 10+ vears Moved from Main 760 Lighting - Pendent/Surface 3rd Floor 14 FΑ 7 6-10 years Moved from Main Marker Board 3rd Floor LF 7 24 6-10 years Moved from Main Walls - Plaster/Drywall 3rd Floor 1.293 SF 6 10+ years Moved from Main Classroom #323 (Art Room) AC Units 3rd Floor 1 FΑ 7 Moved from Main 6-10 years Casework 3rd Floor 22 LF 7 10+ years Moved from Main SF Ceiling - Plaster/Drywall 3rd Floor 890 6 10+ years Moved from Main Doors - Transom Window SF 7 3rd Floor 9 10+ vears Moved from Main 2 Doors - Wood Doors inclu hw 3rd Floor EΑ 7 10+ years Moved from Main Floor - Tile 885 SF 7 3rd Floor 10+ years Moved from Main Floor - Tile 3rd Floor 5 SF 5 1-2 years Damaged tile Moved from Main Lighting - Pendent/Surface 3rd Floor 24 ΕA 7 6-10 years Moved from Main LF Marker Board 3rd Floor 16 7 6-10 years Moved from Main 1,373 SF Moved from Main Walls - Plaster/Drvwall 3rd Floor 6 10+ years Work Sink 3rd Floor FΑ 7 10+ vears 1 Classroom #325 (Art Room) AC Units 7 3rd Floor 1 EΑ 6-10 years Moved from Main Casework 3rd Floor 22 LF 6 10+ years Moved from Main SF Ceiling - Plaster/Drywall 3rd Floor 890 6 10+ years Moved from Main SF 7 Doors - Transom Window 3rd Floor 18 10+ years Moved from Main Doors - Wood Doors inclu hw 3rd Floor 2 EΑ 7 10+ vears Moved from Main SF Floor - Wood 3rd Floor 890 7 10+ years Moved from Main Lighting - Pendent/Surface 3rd Floor 16 ΕA 7 6-10 years Moved from Main Marker Board 3rd Floor LF 7 6-10 years Moved from Main 10 Walls - Plaster/Drywall 3rd Floor 1,273 SF 6 10+ years Moved from Main Work Sink FΑ 7 3rd Floor 10+ years Moved from Main 1 Classroom #327 (Regular Classroom)

Building : Addition



Catego	y : Classroom		В	Building : Addition					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	AC Units	3rd Floor	2	EA	7	6-10 years	Moved from Main		
	Casework	3rd Floor	32	LF	6	10+ years	Moved from Main		
	Ceiling - Plaster/Drywall	3rd Floor	850	SF	6	10+ years	Moved from Main		
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	Moved from Main		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	Moved from Main		
	Floor - Tile	3rd Floor	850	SF	6	10+ years	Moved from Main		
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	Moved from Main		
	Marker Board	3rd Floor	20	LF	7	6-10 years	Moved from Main		
	Walls - Plaster/Drywall	3rd Floor	1,273	SF	6	10+ years	Moved from Main		
	Work Sink	3rd Floor	1	EA	7	10+ years	Moved from Main		
lassroo	m #329 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years	Moved from Main		
	Casework	3rd Floor	34	LF	6	10+ years	Moved from Main		
	Ceiling - Plaster/Drywall	3rd Floor	840	SF	6	10+ years	Moved from Main		
	Chalk Board	3rd Floor	6	LF	4	2-5 years	Moved from Main		
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	Moved from Main		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	Moved from Main		
	Floor - Wood	3rd Floor	840	SF	7	10+ years	Moved from Main		
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	Moved from Main		
	Marker Board	3rd Floor	10	LF	7	6-10 years	Moved from Main		
	Walls - Plaster/Drywall	3rd Floor	1,273	SF	6	10+ years	Moved from Main		
atego	y : Interior		В	uilding	: Additi	on			
						Recommend			
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
orridor									
	Ceiling - Plaster/Drywall	1st Floor	3,962	SF	6	10+ years			
	Doors - Wood Doors include hw	1st Floor	12	EA	7	10+ years			
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	6-10 years			
	Drinking Fountains - Single Fountain	1st Floor	1	EA	5	1-2 years	Damaged fountain		

Difficing Foundains - Single Foundain			EA	1	0-10 years	
Drinking Fountains - Single Fountain	1st Floor	1	EA	5	1-2 years	Damaged fountain
Floor - Terrazzo	1st Floor	200	SF	5	0-1 year	Cracking
Floor - Tile/Sheet	1st Floor	3,702	SF	5	10+ years	-
Floor - Tile/Sheet	1st Floor	60	SF	4	1-2 years	Cracking tile
Lighting - Pendent/Surface	1st Floor	33	EA	7	6-10 years	-
Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
Student Lockers - One Tier	1st Floor	289	EA	6	10+ years	
Walls - Masonry	1st Floor	1,200	SF	7	10+ years	Not previously assessed
Walls - Plaster/Drywall	1st Floor	3,475	SF	6	10+ years	Divided out masonry quantity
Ceiling - Plaster/Drywall	2nd Floor	3,962	SF	6	10+ years	
Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
Floor - Terrazzo	2nd Floor	396	SF	6	10+ years	
Floor - Tile/Sheet	2nd Floor	3,962	SF	7	10+ years	
Lighting - Pendent/Surface	2nd Floor	34	EA	7	6-10 years	



Catego	ry : Interior	R	uilding	4343 W Wrightwood, Chicago, IL 60639					
Ualcyu			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
ereap	Student Lockers - One Tier	2nd Floor	289	EA	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	4,675	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	3,942	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	4	0-1 year	Water damage		
	Drinking Fountains - Single Fountain	3rd Floor	20	EA	5	1-2 years	Damaged units		
	Floor - Terrazzo	3rd Floor	396	SF	7	10+ years	Damaged units		
	Floor - Tile/Sheet	3rd Floor	3,962	SF	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	24	EA	7	6-10 years			
	Student Lockers - One Tier	3rd Floor	289	EA	6	10+ years			
					6	•			
	Walls - Plaster/Drywall	3rd Floor	4,675	SF	0	10+ years			
Safety									
	Metal Detector	Entire Building	1	EA	7	6-10 years			
	Security Cameras	Entire Building	5	EA	7	6-10 years			
	Security Cameras	Entire Building	6	EA	7	6-10 years			
Stairs									
	Ceiling - Plaster/Drywall	North East	1,154	SF	6	10+ years			
	Ceiling - Plaster/Drywall	North East	10	SF	4	0-1 year	Water damage		
	Floor - Terrazzo	North East	1,164	SF	6	10+ years			
	Handrails	North East	270	LF	7	10+ years			
	Lighting - Pendent/Surface	North East	6	EA	7	6-10 years			
	Stairs - Terrazzo	North East	360	LF	6	10+ years			
	Walls - Plaster/Drywall	North East	1,371	SF	6	10+ years			
	Ceiling - Plaster/Drywall	North West	1,164	SF	6	10+ years			
	Floor - Terrazzo	North West	1,144	SF	6	10+ years			
	Floor - Terrazzo	North West	20	SF	4	0-1 year	Damaged		
	Handrails	North West	270	LF	7	10+ years	2 aage a		
	Lighting - Pendent/Surface	North West	6	EA	7	6-10 years			
	Stairs - Terrazzo	North West	360	LF	6	10+ years			
	Walls - Plaster/Drywall	North West	1,371	SF	6	10+ years			
	Ceiling - Plaster/Drywall	South	1,159	SF	6	10+ years			
	Ceiling - Plaster/Drywall	South	5	SF	4	0-1 year	Water damage		
	Floor - Terrazzo	South	1,164	SF	7	10+ years	Water damage		
	Handrails	South	270	LF	7	10+ years			
	Lighting - Pendent/Surface	South	4	EA	7	6-10 years	Qty updated		
	Stairs - Terrazzo	South	360	LF	6	-	ary upuareu		
			1,361	SF	6	10+ years			
	Walls - Plaster/Drywall	South	1,361	SF	ю 4	10+ years	Drawall cracks		
	Walls - Plaster/Drywall	South	-			1-2 years	Drywall cracks		
	Ceiling - Plaster/Drywall	South East	1,114	SF	6	10+ years	Weter demogra		
	Ceiling - Plaster/Drywall	South East	50	SF	5	0-1 year	Water damage		
	Floor - Terrazzo	South East	1,164	SF	7	10+ years			
	Handrails	South East	270	LF	7	10+ years			
	Lighting - Pendent/Surface	South East	6	EA	7	6-10 years			



Kelvyn Park High School 4343 W Wrightwood, Chicago, IL 60639

Building : Addition Category : Interior Recommend Location Group Item - Type Quantity UOM Rank Comments Replacement Stairs - Terrazzo South East 10+ years 480 LF 6 Walls - Plaster/Drywall South East 1,361 SF 7 10+ years Walls - Plaster/Drywall SF 0-1 year Water damage South East 10 4



Category : Site			В	uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Civil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	7	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	9	EA	6	10+ years	
			Ũ	L/\	0	Tor youro	
Fencing							
	Fencing - Chain Link	Entire Site	70	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	70	LF	5	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	1,456	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	5	LF	5	1-2 years	Quantity changed to match current
							observations. Bending
Landsca	pe						
	Benches	Entire Site	3	EA	6	10+ years	
	Landscape - Grass	Entire Site	19,205	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	6,512	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	7,855	SF	6	10+ years	
	Parkway trees	Entire Site	28	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	15,050	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	150	SF	5	10+ years	
	Trash Receptacles	Entire Site	5	EA	6	10+ years	
	Walking Path - Hardscape- Pavers	Entire Site	650	SF	6	10+ years	
Parking I	ot						
0	Surface - Asphalt	South Courtyard	20,500	SF	5	2-5 years	
	Surface - Asphalt	South Courtyard	30,000	SF	4	0-1 year	Cracking/potholes
	Trash Compactor	South Courtyard	1	EA	7	10+ years	31
Sidewalk	S						
	Sidewalks - Internal Walks	Entire Site	65	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	9,565	SF	6	10+ years	
Signage							
990	Flag Pole - Flag Pole	NW Courtyard	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/	NW Courtyard	1	EA	6	10+ years	Changed to match current observations
	Monument - Building Mounted Cut Letter Sign	NW Courtyard	3	EA	7	10+ years	Quantity changed to match current observations



4343 W Wrightwood, Chicago, IL 60639

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main				1	1	1	I		
Art Room	Art Room	3rd Floor	323 - in Additi	323	890	272	96	Y	Y
Art Room	Regular Classroom	3rd Floor	325 - in Additi	321	890	238	84	Y	Y
Band Room	Band Room	3rd Floor	313 - in additi	313	2,088	114	54		Y
Music Room	Choral Room	3rd Floor	314 -NA	314	1,044	216	32		
Office	Other Instructional Use	1st Floor	111	107	525	136	48	Y	N
Office	Other Instructional Use	1st Floor	117 in Addition	117	380	102	36	Ŷ	Y
Office	Regular Classroom	1st Floor	099	099	760	170	60	Y	Ν
Office	Regular Classroom	1st Floor	101	101	610	136	48	Y	Y
Office	Regular Classroom	1st Floor	103	103	525	136	48	Y	Y
Office	Regular Classroom	1st Floor	105	105	485	136	48	Y	Y
Office	Regular Classroom	1st Floor	107	105	485	136	48	Y	Y
Office	Regular Classroom	2nd Floor	207	203	760	204	72	Y	Y
Office	Special Education	3rd Floor	302	302	260	38	18	Y	N
Other Instructional Use	Regular Classroom	1st Floor	109	105	525	136	48	Y	N
Other Instructional Use	Regular Classroom	1st Floor	127 - in additi	115	422	102	36	N	Y
Regular Classroom	Computer Lab	4th Floor	301	301	760	170	60	Y	Y
Regular Classroom	Other Instructional Use	2nd Floor	213	209	415	102	36	N	Y
Regular Classroom	Regular Classroom	1st Floor	108	108	764	114	54	Y	
Regular Classroom	Regular Classroom	1st Floor	110	110	760	114	54	Y	Y
Regular Classroom	Regular Classroom	1st Floor	119 - in additi	113	760	204	72	N	Y
Regular Classroom	Regular Classroom	1st Floor	129 - in additi	119	682	204	72	N	Y
Regular Classroom	Regular Classroom	2nd Floor	200	200	760	95	45	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	760	114	54	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	760	114	54	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	760	114	54	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	760	114	63	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	760	95	45	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	215 - in additi	209	560	170	60	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	303	303	760	204	72	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	304	304	760	114	54	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	305	305	760	204	72	Y	Y



Classroom Summary Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	3rd Floor	306	306	760	114	54	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	307	307	760	204	72	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	760	114	54	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	309	309	760	204	72	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	310	310	760	95	45	N	Y
Regular Classroom	Regular Classroom	3rd Floor	311	311	760	204	72	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	315 - in additi	315	760	204	72	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	319 - in additi	319	760	204	54	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	321 - in Additi	321	760	204	72	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	327 - in Additi	327	850	238	84	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	329 - in Additi	329	840	238	84	Y	Y
Science Classroom	Science Classroom	1st Floor	115 in Addition	109	1,010	204	72	Y	Y
Science Classroom	Science Lab Level 1	1st Floor	125 - in additi	117	1,010	306	108	Y	Y
Science Lab Level 1	Regular Classroom	2nd Floor	229 - in additi	227	1,010	272	96	Y	Y
Science Lab Level 1	Science Lab Level 1	2nd Floor	223 - in additi	213	1,010	238	84	Y	Y
Science Lab Level 3	Science Classroom	2nd Floor	221 - in additi	211	1,010	306	108	Y	Y
Science Lab Level 3	Science Classroom	2nd Floor	225 - in additi	215	1,010	272	96	Y	Y
Science Lab Level 3	Science Lab Level 3	2nd Floor	227 - same as 2	217	1,010	272	96	N	Y
Special Education	Special Education	3rd Floor	300	300	590	76	36	Y	Y
Store Room	Regular Classroom	3rd Floor	312A	312A	598	61	9	N	Y
Vacant	Science Lab Level 3	1st Floor	121 - in additi	111	628	170	60	Y	N
Building : Addition									
Art Room	Art Room	3rd Floor	323	323	890	272	96	Y	Y
Art Room	Regular Classroom	3rd Floor	325	321	890	238	84	Y	N
Band Room	Band Room	3rd Floor	313	313/314	2,088	114	54	1	Y
Computer Lab	Regular Classroom	3rd Floor	316	316	598	76	3	Y	Y
Faculty Lounge	Regular Classroom	1st Floor	127	115	422	102	36		Ý
Multi Purpose Room	Computer Lab	3rd Floor	318	318	598	66	3	Y	Ý



Classroom Summary									
Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Office	Other Instructional Use	1st Floor	117	117	380	102	36	Y	
Regular Classroom	Computer Lab	2nd Floor	216	216	598	66	33	N	Y
Regular Classroom	Computer Lab	2nd Floor	220	220	598	66	33	N	Y
Regular Classroom	Regular Classroom	1st Floor	119	113	760	204	72		
Regular Classroom	Regular Classroom	2nd Floor	129	119	682	204	72		Y
Regular Classroom	Regular Classroom	2nd Floor	215	209	560	170	60	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	315	315	760	204	72	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	319	319	760	204	54	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	321	321	760	204	72	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	327	327	850	238	84	Y	Y
Regular Classroom	Regular Classroom	3rd Floor	329	329	840	238	84	Y	Y
Science Classroom	Science Classroom	1st Floor	115	109	1,010	204	72	Y	Y
Science Classroom	Science Classroom	2nd Floor	225	215	1,010	272	96	Y	Y
Science Lab Level 1	Regular Classroom	2nd Floor	229	227	1,010	272	96	Y	Y
Science Lab Level 2	Science Lab Level 1	2nd Floor	223	213	1,010	238	84	Y	Y
Science Lab Level 3	Science Classroom	1st Floor	125	117	1,010	306	108	Y	Y
Science Lab Level 3	Science Classroom	2nd Floor	221	211	1,010	306	108	Y	Y
Store Room	Science Lab Level 3	1st Floor	121	111	628	170	60	Y	