

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main-Academic_Unit B	1969	4	105,996
Addition-Lunchroom_Unit D	1969	2	36,736
Branch @ Old Canter	1913	3	41,382
Linked Addition-Arts_Unit A	1969	4	63,520
Linked Addition-Athletic Building_Unit C	1969	4	66,180
Campus Total			313,814

Category : Exterior Building : Main-Academic_Unit B

		1	0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance							
	Exterior Doors - Exterior Steel Door	RAD - E	1	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	RAD - E	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	RAD - N	2	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	RAD - N	6	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	RAD - NE	2	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	RAD - NW	2	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	RAD - NW	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	RAD - SE	2	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	RAD - SE	6	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	RAD - SW	2	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	RAD - SW	6	LF	7	10+ years	
_Foundati	on						
	Foundation - Concrete	Entire Building	785	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	105,996	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	4	0-1 year	Missing, damaged



Catego	ry : Exterior		В	uilding	: Main-A	Academic_Unit	В
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oof Sys	etem						
.cor cy.	Access Ladder - Metal	A	2	EA	7	10+ years	
	Access Ladder - Wood	Ā	1	EA	4	0-1 year	Unstable, broken, unsafe
	Chimney - Metal Flue	A	10	LF	6	10+ years	Olistable, blokeli, ulisale
		Ä	382	LF		•	
	Coping - Metal			LF	6 6	10+ years	
	Downspouts - Interior Downspouts	A	420			10+ years	
	Parapet - Parapet < 16" Height	A	382	LF	6	10+ years	
	Roof - Modified Bitumen	A	7,520	SF	6	10+ years	B 111
	Roof - Modified Bitumen	Α	1,000	SF	4	1-2 years	Bubbling, cracks, worn
	Roof Hatch - Metal	Α	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Α	8,520	SF	7	10+ years	
	Concrete Topping	_					
	Access Ladder - Wood	В	1	EA	4	0-1 year	Ustable, broken, unsafe
	Coping - Metal	В	919	LF	6	10+ years	
	Parapet - Parapet < 16" Height	В	919	LF	6	10+ years	
	Roof - Modified Bitumen	В	7,072	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	В	7,072	SF	7	10+ years	
	Coping - Metal	C - Lower Center	770	LF	6	10 Lyoars	
		C - Lower Center C - Lower Center	270	LF	6 5	10+ years	Mara carradad aquara
	Downspouts - Interior Downspouts					2-5 years	Worn, corroded covers
	Parapet - Parapet < 16" Height	C - Lower Center	770	LF	6	10+ years	
	Roof - Modified Bitumen	C - Lower Center	15,000	SF	6	6-10 years	
	Roof - Modified Bitumen	C - Lower Center	6,132	SF	4	1-2 years	Soft spots, plant growth, bubbling
	Roof Structure - Steel / Metal Deck/ Concrete Topping	C - Lower Center	21,132	SF	7	10+ years	
/alls							
ans	Exterior Walls - Brick	Entire Building	12,080	SF	6	10+ years	
	Exterior Walls - Concrete Block	Entire Building	8,368	SF	6	10+ years	
indows							
HIUUWS	Guard - Guards perforated	Entire Building	640	SF	6	10+ years	
	Lintels - Concrete			LF		•	
		Entire Building	1,056		6	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	6,400	SF	6	10+ years	
	pane	Entine Duildie ::	4.004	0.5	^	40	
	Windows - Louver	Entire Building	1,024	SF	6	10+ years	
atego	ry : Electrical		В	uilding	: Main-A	Academic_Unit	В
	_				_	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
-	Emergency A/C Power - Corridors and	Entire Building	19,826	SF	6	6-10 years	
		0	. 5,020	•	•	3 .0 ,00.0	



atego	ry : Electrical		В	Building : Main-Academic_Unit B					
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Stairs	E B	4	0.5	•	0.40			
	Emergency A/C Power - Students Toilets	Entire Building	1,530	SF	6	6-10 years			
	Exit Signs - Corridors and Stairs	Entire Building	24	EA	5	6-10 years			
	Security System - CCTV	Entire Building	105,996	SF	6	6-10 years			
	Security System - Intrusion Detection	Entire Building	105,996	SF	6	6-10 years			
lain Sei	vice								
	PA System	Entire Building	105,996	SF	6	6-10 years	Serves Bldgs. A, B, C and D.		
	Main Electrical Service - 1600 A	Mechanical Room	100,000	EA	6	10+ years	Location changed for clarification.		
	120/208/3PH	Wednamear Noom		LA	U	10+ years	Location changed for clarification.		
	Main Electrical Service - 2001 to 3000 A	Mechanical Room	1	EA	6	10+ years	Location changed for clarification.		
	277/480/3PH					,	S		
	Main Electrical Service - 800 A and	Mechanical Room	1	EA	6	10+ years			
	277/480/3PH								
ower D	istribution								
	Lighting and Power Panels - 100 A	Entire Building	11	EA	7	10+ years	Quantity changed as total has bee		
							divided/aggregated.		
	Lighting and Power Panels - Above 100 A	Entire Building	22	EA	7	10+ years	Quantity changed as total has bee		
							divided/aggregated.		
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slot exposes live		
							conductors presenting a live front		
							condition.		
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	10+ years	Location changed for clarification.		
							Quantity changed as total has bee		
							divided/aggregated.		
	Transformers - 277/480 - 120/208	Entire Building	5	EA	6	10+ years	Quantity changed as total has bee		
		·				•	divided/aggregated.		
atego	ry : Fire Protection		В	uildina	: Main-A	Academic_Unit	В		
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
re Alar	m								
	Fire ALarm Anunciator	Entire Building	1	EA	6	10+ years	No CPS Asset Tag present.		
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	No CPS Asset Tag present		
	Fire Alarm Strobe Lights	Entire Building	105,996	SF	6	10+ years	5 .		
	Fire Alarm_System	Entire Building	105,996	SF	6	10+ years			
_4	w. Maskaviasl		.				. D		
atego	ry : Mechanical		В	ullaing	: wain-A	Academic_Unit Recommend	: B		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	· ·		quantity	00111	Marin	. topiasomont			
r Cond									
ir Cond	Chiller-Water Cooled- Absorber - 201 - 300	Mechanical Room	1	EA	2	0-1 year	Based on current observations and		

Campus Name: Kenwood HS Page : 3 of 115 Assessment Date: 07/08/2024



Group	Item - Type tons	Location	0			Recommend		
Group		Location						
	IONS		Quantity	UOM	Rank	Replacement	Comments	
							per review with Building Engineer, chiller is nonfunctional and out of service. Replaced by centrifugal chiller, rendering the absorber chiller obsolete. Rank, Reason and Priority Rep changed to note that the equipment has been abandoned in place. Location changed for clarification.	
	Chemical Pot Feeder	Mechanical Room	1	EA	5	6-10 years		
	Chiller-Water Cooled- Cetrifugal - 201-300 tons	Mechanical Room	1	EA	6	6-10 years	Serves Bldgs. A, B and D.	
	Cooling Tower - Open Cell	Mechanical Room	1	EA	6	6-10 years		
	Cooling Tower - Open Cell	Mechanical Room	1	EA	6	6-10 years		
	Pipes - Chilled Water Pipe- Steel	Mechanical Room	400	LF	6	6-10 years		
Air Hand	ling Systems							
	Indoor Return Fans- Centrifugal Squirrel Cage - 10001 - 20000 CFM	Mechanical Room	4	EA	5	6-10 years	Associated with AHU-4, -5, -6 and -7. Location changed for clarification.	
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils and Chilled Water Coils - 20001-30000 cfm	Mechanical Room - AHU-4	1	EA	6	6-10 years	AHU-4	
	Air Intake	Mechanical Room - AHU-4	1	EA	6	6-10 years		
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils and Chilled Water Coils - 20001-30000 cfm	Mechanical Room - AHU-5	1	EA	6	6-10 years	AHU-5	
	Air Intake	Mechanical Room - AHU-5	1	EA	6	6-10 years		
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils and Chilled Water Coils - 12001-20000 cfm	Mechanical Room - AHU-6	1	EA	6	6-10 years	AHU-6	
	Air Intake	Mechanical Room - AHU-6	1	EA	6	6-10 years		
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils and Chilled Water Coils - 20001-30000 cfm	Mechanical Room - AHU-7	1	EA	6	6-10 years	AHU-7	
	Air Intake	Mechanical Room - AHU-7	1	EA	6	6-10 years		
	VAV Box	VAV Boxes - Entire Building	79	EA	6	10+ years	Quantity changed as total has been divided/aggregated. Located above suspended ceiling grids or in mechanical closets throughout the building. Location changed for clarification.	
Boiler Sy								
	Boiler Auxiliary- Scotch Marine- Steam Low	Mechanical Room	2	EA	5	6-10 years	B-1 and B-2, serve Bldgs. A, B, C and	



Catego	ry : Mechanical		В	uilding	: Main-A	\cademic_Unit	B
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pressure Boiler - 201 - 300 HP						 D. In the midst of seasonal maintenance protocol at the time of assessment. Location changed for clarification.
	Chemical Feed System	Mechanical Room	1	EA	6	6-10 years	Location changed for clarification.
	Combustion Dampers	Mechanical Room	2	EA	7	6-10 years	Location changed for clarification. Rank changed based on current observations and per review with Building Engineer that the combustion dampers are subject to a maintenance program such that they are always fully operational.
	Condensate Pump	Mechanical Room	1	EA	5	10+ years	Location changed for clarification. No CPS Asset Tag present.
	Condensate Pump	Mechanical Room	1	EA	5	10+ years	Location changed for clarification. No CPS Asset Tag present.
	Feed Water Pumps and Tank	Mechanical Room	1	EA	6	10+ years	Location changed for clarification.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Mechanical Room	1	EA	5	6-10 years	B-2. Serves Bldgs. A, B, C and D. In the midst of seasonal maintenance protocol at the time of assessment. Location changed for clarification.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Mechanical Room	1	EA	5	6-10 years	B-1. Serves Bldgs. A, B, C and D. In the midst of seasonal maintenance protocol at the time of assessment. Location changed for clarification.
	Piping - Condensate Pipe- Steel	Mechanical Room	450	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Mechanical Room	450	LF	6	10+ years	
	Steam Traps	Mechanical Room	45	EA	7	6-10 years	Quantity changed as total has been divided/aggregated. Rank adjusted as all steam traps have been upgraded since previous assessment.
Heating	Devices						
J	Wall Heater - Electric	Entire Building	16	EA	6	6-10 years	Quantity changed as total has been divided/aggregated
	Unit Heater - Steam	Mechanical Room	4	EA	4	2-5 years	Location changed for clarification. Vintage units that have reached end of anticipated service life.
_Mechani	cal Plumbing						
	Chilled Water Pump - 21 - 50 HP	Mechanical Room	1	EA	7	10+ years	P-4
	Chilled Water Pump - 21 - 50 HP Condenser Pump - Greater than 50 HP	Mechanical Room Mechanical Room	1 2	EA EA	7 7	10+ years 10+ years	P-3, no CPS Asset Tag present. CWP-1 and CWP-2. Item Type changed to match current



Catego	ry : Mechanical		В	uilding	: Main-	Academic_Unit	: B
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							observations.
Tompor	ature Control						
<u>rempera</u>		Finting Divilation	405,000		7	10	
	DDC System	Entire Building	105,996	SF	7	10+ years	
	Electric Thermostat Electric Thermostat	Entire Building	4	EA EA	6	6-10 years	
		Entire Building	70	EA EA	6 7	6-10 years	
	Thermostats - DDC	Entire Building	79	EA	7	10+ years	
_Ventilation	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	3	EA	6	6-10 years	Location changed for clarification. Quantity changed to match current observations.
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	Location changed for clarification.
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	3	EA	6	6-10 years	Quantity changed to match current observations. Location changed for clarification.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	4	2-5 years	Damaged and deteriorated with the appearance consistent with equipment that has reached the end of its anticipated service life.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	4	2-5 years	Damaged and deteriorated with the appearance consistent with equipment that has reached the end of its anticipated service life.
	Roof Mounted Duct Work	Entire Building	30	LF	4	2-5 years	Deteriorated and damaged with an appearance consistent with material that has reached the end of its anticipated service life.

Category : Plumbing Building : Main-Academic_Unit B

Group Piping	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
. •	Domestic Piping-Hot Water Return Lines	Entire Building	105,996	SF	6	10+ years	Domestic hot and cold water supplied by Bldg. C.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	105,996	SF	6	10+ years	Domestic hot and cold water supplied by Bldg. C.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	105,996	SF	6	10+ years	Domestic hot and cold water supplied by Bldg. C.



Catego	ry : Plumbing		Building : Main-Academic_Unit B					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	105,996	SF	6	10+ years	Domestic hot and cold water supplied by Bldg. C.	
	Sanitary Piping	Entire Building	105,996	SF	6	10+ years		
	Storm Piping	Entire Building	105,996	SF	6	10+ years		
	Vent Piping	Entire Building	105,996	SF	6	10+ years		
Pumps								
•	Pumps - Sump-Simplex	Other	1	EA	5	6-10 years	Elevator pit sump pump. Not accessible at the time of assessment. No CPS Asset Tag available. Condition verified by Building Engineer. Location changed for clarification.	

Category: Room Building: Main-Academic_Unit B

Juloge	19.1100111		Ballating : Main Addacting_office B					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
dminis	trative Suites/Offices		•					
	Ceiling - Lay-in	100 Guidance Office	203	SF	7	10+ years		
	Doors - Side-lite	100 Guidance Office	45	SF	7	10+ years		
	Doors - Store Front	100 Guidance Office	1	ĒΑ	7	10+ years		
	Doors - Transom Window	100 Guidance Office	4	SF	7	10+ years		
	Floor - Wood	100 Guidance Office	203	SF	7	10+ years		
	Lighting - Lay-in	100 Guidance Office	4	ĒΑ	7	6-10 years		
	Power Distribution	100 Guidance Office	4	EA	7	10+ years		
	Walls - Concrete Block	100 Guidance Office	276	SF	7	10+ years		
	Ceiling - Lay-in	100A Conference Room	250	SF	7	10+ years		
	Doors - Wood Doors inclu hw	100A Conference Room	1	EA	7	10+ years		
	Floor - Wood	100A Conference Room	250	SF	6	6-10 years		
	Lighting - Lay-in	100A Conference Room	6	EA	7	6-10 years		
	Power Distribution	100A Conference Room	10	EA	7	10+ years		
	Walls - Concrete Block	100A Conference Room	396	SF	7	10+ years		
	Ceiling - Lay-in	100B	98	SF	7	10+ years		
	Doors - Wood Doors inclu hw	100B	1	EΑ	7	10+ years		
	Floor - Carpet	100B	98	SF	7	10+ years		
	Lighting - Lay-in	100B	2	EA	7	10+ years		
	Power Distribution	100B	8	EA	7	10+ years		
	Walls - Concrete Block	100B	180	SF	7	10+ years		
	Ceiling - Lay-in	100C Office	68	SF	7	10+ years		
	Doors - Wood Doors inclu hw	100C Office	1	EA	7	10+ years		
	Floor - Wood	100C Office	68	SF	7	10+ years		
	Lighting - Lay-in	100C Office	1	EA	7	6-10 years		
	Power Distribution	100C Office	6	EA	7	10+ years		
	Walls - Concrete Block	100C Office	242	SF	7	10+ years		



Category : Room			В	Building : Main-Academic_Unit B					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Splined	100D Office	156	SF	7	10+ years			
	Doors - Wood Doors inclu hw	100D Office	1	EA	7	10+ years			
	Floor - Wood	100D Office	156	SF	7	10+ years			
	Lighting - Lay-in	100D Office	2	EA	7	6-10 years			
	Power Distribution	100D Office	8	EA	7	10+ years			
	Walls - Concrete Block	100D Office	312	SF	7	10+ years			
	Ceiling - Splined	100E Office	77	SF	7	10+ years			
	Ceiling - Splined	100E Office	10	SF	5	1-2 years	Tiles appear loose		
	Doors - Wood Doors inclu hw	100E Office	1	EA	7	10+ years			
	Floor - Wood	100E Office	87	SF	7	10+ years			
	Lighting - Lay-in	100E Office	1	EA	7	6-10 years			
	Power Distribution	100E Office	6	EA	7	10+ years			
	Walls - Concrete Block	100E Office	217	SF	7	10+ years			
	Walls - Masonry	100E Office	54	SF	7	10+ years			
	Ceiling - Splined	100G Office	84	SF	7	10+ years			
	Doors - Wood Doors inclu hw	100G Office	1	EA	7	10+ years			
	Floor - Wood	100G Office	84	SF	7	10+ years			
	Lighting - Lay-in	100G Office	1	EA	7	6-10 years			
	Power Distribution	100G Office	6	EA	7	10+ years			
	Walls - Concrete Block	100G Office	209	SF	7	10+ years			
	Ceiling - Splined	100H Office	85	SF	7	10+ years			
	Doors - Wood Doors inclu hw	100H Office	1	EA	7	10+ years			
	Floor - Wood	100H Office	85	SF	7	10+ years			
	Lighting - Lay-in	100H Office	1	EA	7	6-10 years			
	Power Distribution	100H Office	6	EA	7	10+ years			
	Walls - Concrete Block	100H Office	213	SF	7	10+ years			
	Ceiling - Splined	100K Office	85	SF	6	10+ years			
	Doors - Wood Doors inclu hw	100K Office	1	EA	7	10+ years			
	Floor - Carpet	100K Office	85	SF	7	6-10 years			
	Lighting - Lay-in	100K Office	1	EΑ	7	6-10 years			
	Power Distribution	100K Office	6	EA SF	7	10+ years			
	Walls - Concrete Block	100K Office	213	SF SF	7	10+ years			
	Ceiling - Lay-in	100M Office	99		7	10+ years			
	Doors - Wood Doors inclu hw Floor - Wood	100M Office	1 99	EA SF	7	10+ years			
		100M Office		SF EA	7 7	10+ years			
	Lighting - Lay-in Power Distribution	100M Office 100M Office	1 4	EA EA	7 7	6-10 years			
	Walls - Concrete Block	100M Office	225	SF	7	10+ years 10+ years			
	Ceiling - Lay-in	100N Office	225 71	SF SF	7 7	10+ years 10+ years			
	Doors - Wood Doors inclu hw	100N Office	1	SF EA	7 7	10+ years 10+ years			
	Floor - Carpet	100N Office	71	SF	7 7	6-10 years			
	Lighting - Lay-in	100N Office	1	EA	7	6-10 years			
	Power Distribution	100N Office	6	EA	7 7	10+ years			
	Walls - Concrete Block	100N Office	242	SF	7	10+ years			
	VValia - Colloiete Diock	10014 Office	242	OI.	,	TOT years			



Category : Room			Building : Main-Academic_Unit B						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	100Q Office	325	SF	7	10+ years			
	Doors - Wood Doors inclu hw	100Q Office	2	EA	7	10+ years			
	Floor - Carpet	100Q Office	234	SF	7	6-10 years			
	Floor - Wood	100Q Office	91	SF	7	10+ years			
	Lighting - Lay-in	100Q Office	6	EA	7	6-10 years			
	Power Distribution	100Q Office	12	EA	7	10+ years			
	Walls - Concrete Block	100Q Office	725	SF	7	10+ years			
	Ceiling - Lay-in	101 Main Office	300	SF	7	10+ years			
	Ceiling - Splined	101 Main Office	732	SF	7	10+ years			
	Doors - Steel Doors incl hw	101 Main Office	1	EA	7	10+ years			
	Doors - Store Front	101 Main Office	1	EA	7	10+ years			
	Doors - Transom Window	101 Main Office	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	101 Main Office	4	EA	7	10+ years			
	Floor - Wood	101 Main Office	1,032	SF	7	10+ years			
	Lighting - Lay-in	101 Main Office	14	EΑ	7	6-10 years			
	Lighting - Lay-in	101 Main Office	1	EA	6	6-10 years			
	Power Distribution	101 Main Office	30	EA	7	10+ years			
	Storage/ Closet	101 Main Office	190	SF	5	10+ years	Missing ceiling tiles		
	Walls - Concrete Block	101 Main Office	290	SF	7	10+ years			
	Walls - Concrete Block	101 Main Office	660	SF	7	10+ years			
	Ceiling - Splined	101C Kitchenette	58	SF	5	1-2 years	Tile removed		
	Doors - Wood Doors inclu hw	101C Kitchenette	1	EA	7	10+ years			
	Floor - Wood	101C Kitchenette	58	SF	7	10+ years			
	Lighting - Lay-in	101C Kitchenette	1	EA	7	6-10 years			
	Power Distribution	101C Kitchenette	4	EA	7	10+ years			
	Walls - Concrete Block	101C Kitchenette	166	SF	7	10+ years			
	Walls - Masonry	101C Kitchenette	62	SF	7	10+ years			
	Work SInk	101C Kitchenette	1	EA	7	6-10 years			
	Ceiling - Splined	101D Assistant Principal's Office	209	SF	7	10+ years			
	Doors - Wood Doors inclu hw	101D Assistant Principal's Office	1	EA	7	10+ years			
	Floor - Carpet	101D Assistant Principal's Office	209	SF	7	6-10 years			
	Lighting - Lay-in	101D Assistant Principal's Office	4	EA	7	6-10 years			
	Power Distribution	101D Assistant Principal's Office	4	EA	7	10+ years			
	Walls - Concrete Block	101D Assistant Principal's Office	508	SF	7	10+ years			
	Ceiling - Splined	101F Assistant Principal's Office	209	SF	7	10+ years			
	Doors - Wood Doors inclu hw	101F Assistant Principal's Office	1	EA	7	10+ years			
	Floor - Carpet	101F Assistant Principal's Office	209	SF	7	6-10 years			
	Lighting - Lay-in	101F Assistant Principal's Office	4	EΑ	7	6-10 years			
	Power Distribution	101F Assistant Principal's Office	4	EA	7	10+ years			
	Walls - Concrete Block	101F Assistant Principal's Office	508	SF	7	10+ years			
	Ceiling - Splined	101K North Office	214	SF	7	10+ years			
	Doors - Wood Doors inclu hw	101K North Office	1	EA	7	10+ years			
	Floor - Carpet	101K North Office	214	SF	7	6-10 years			
	Lighting - Lay-in	101K North Office	3	EA	7	6-10 years			



Category : Room		Building : Main-Academic_Unit B					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	101K North Office	1	EA	6	6-10 years	Not working
	Power Distribution	101K North Office	6	EA	7	10+ years	
	Walls - Concrete Block	101K North Office	508	SF	7	10+ years	
	Ceiling - Splined	101K South Office	208	SF	7	10+ years	
	Doors - Wood Doors inclu hw	101K South Office	2	EA	7	10+ years	
	Floor - Carpet	101K South Office	208	SF	7	6-10 years	
	Lighting - Lay-in	101K South Office	4	EA	7	6-10 years	
	Power Distribution	101K South Office	6	EA	7	10+ years	
	Walls - Concrete Block	101K South Office	508	SF	7	10+ years	
	Ceiling - Splined	101L Assistant Principal's Office	198	SF	7	10+ years	
	Doors - Wood Doors inclu hw	101L Assistant Principal's Office	1	EA	7	10+ years	
	Floor - Carpet	101L Assistant Principal's Office	198	SF	7	6-10 years	
	Lighting - Lay-in	101L Assistant Principal's Office	4	EA	7	6-10 years	
	Power Distribution	101L Assistant Principal's Office	4	EA	7	10+ years	
	Storage/ Closet	101L Assistant Principal's Office	16	SF	7	10+ years	
	Walls - Concrete Block	101L Assistant Principal's Office	402	SF	7	10+ years	
	Ceiling - Lay-in	101N Treasury Office	114	SF	7	10+ years	
	Doors - Steel Doors incl hw	101N Treasury Office	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	101N Treasury Office	1	EA	7	10+ years	
	Floor - Wood	101N Treasury Office	114	SF	7	10+ years	
	Lighting - Lay-in	101N Treasury Office	2	EA	7	6-10 years	
	Power Distribution	101N Treasury Office	6	EA	7	10+ years	
	Walls - Concrete Block	101N Treasury Office	280	SF	7	10+ years	
	Ceiling - Lay-in	101P Office	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	101P Office	1	EA	7	10+ years	
	Floor - Carpet	101P Office	120	SF	7	6-10 years	
	Lighting - Lay-in	101P Office	2	EA	7	6-10 years	
	Power Distribution	101P Office	6	EA	7	10+ years	
	Walls - Concrete Block	101P Office	366	SF	7	10+ years	
	Ceiling - Lay-in	101Q Conference Room	216	SF	7	10+ years	
	Doors - Steel Doors incl hw	101Q Conference Room	1	ĒΑ	7	10+ years	
	Doors - Wood Doors inclu hw	101Q Conference Room	1	EΑ	7	10+ years	
	Floor - Carpet	101Q Conference Room	216	SF	7	6-10 years	
	Lighting - Lay-in	101Q Conference Room	4	ĒΑ	7	6-10 years	
	Power Distribution	101Q Conference Room	5	ĒΑ	7	10+ years	
	Walls - Concrete Block	101Q Conference Room	430	SF	7	10+ years	
	Ceiling - Lay-in	101R	80	SF	7	10+ years	
	Ceiling - Lay-in	101R	16	SF	5	1-2 years	Missing/ damaged tile
	Doors - Wood Doors inclu hw	101R	2	EA	7	10+ years	esg, damaged the
	Floor - Wood	101R	96	SF	7	10+ years	
	Lighting - Lay-in	101R	1	EA	7	10+ years	
	Power Distribution	101R	4	EA	7	10+ years	
	Walls - Concrete Block	101R	180	SF	7	10+ years	
	Ceiling - Lay-in	111 Attendance Office	836	SF	7	10+ years	
		TTT Autoridation Office	550	٥.	•	. o . youro	

Campus Name: Kenwood HS Page : 10 of 115 Assessment Date: 07/08/2024



Category : Room		В	Building : Main-Academic_Unit B					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	111 Attendance Office	24	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	111 Attendance Office	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	111 Attendance Office	3	EA	7	10+ years		
	Floor - Tile	111 Attendance Office	860	SF	7	10+ years		
	Lighting - Lay-in	111 Attendance Office	15	EA	7	6-10 years		
	Lighting - Lay-in	111 Attendance Office	1	EA	6	6-10 years	Not working	
	Power Distribution	111 Attendance Office	14	EA	7	10+ years		
	Walls - Concrete Block	111 Attendance Office	760	SF	7	10+ years		
	Walls - Metal Panel	111 Attendance Office	290	SF	7	10+ years		
	Ceiling - Lay-in	112 English Office	372	SF	7	10+ years		
	Doors - Transom Window	112 English Office	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	112 English Office	1	EA	7	10+ years		
	Floor - Tile	112 English Office	372	SF	7	10+ years		
	Lighting - Lay-in	112 English Office	6	EA	7	6-10 years		
	Lighting - Lay-in	112 English Office	1	EA	6	6-10 years	Not working	
	Power Distribution	112 English Office	14	EA	7	10+ years		
	Walls - Concrete Block	112 English Office	658	SF	7	10+ years		
	Ceiling - Lay-in	113 English Office	348	SF	7	10+ years		
	Ceiling - Lay-in	113 English Office	24	SF	4	1-2 years	Damaged tile	
	Doors - Transom Window	113 English Office	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	113 English Office	3	EA	7	10+ years		
	Floor - Tile	113 English Office	372	SF	7	10+ years		
	Lighting - Lay-in	113 English Office	7	EΑ	7	6-10 years		
	Power Distribution	113 English Office	30	EA	7	10+ years		
	Storage/ Closet	113 English Office	240	SF	7	10+ years		
	Walls - Concrete Block	113 English Office	610	SF	7	10+ years		
	Ceiling - Lay-in	113B	81	SF	7	10+ years		
	Doors - Wood Doors inclu hw	113B	1	EΑ	7	10+ years		
	Floor - Tile	113B	81	SF	7	10+ years		
	Lighting - Lay-in	113B	2	EA	7	10+ years		
	Power Distribution	113B	2	EΑ	7	10+ years		
	Walls - Concrete Block	113B	180	SF	7	10+ years		
	Ceiling - Lay-in	121A Office	124	SF	7	10+ years		
	Ceiling - Lay-in	121A Office	6	SF	5	1-2 years	Damaged tile	
	Doors - Side-lite	121A Office	40	SF	7	10+ years	· ·	
	Doors - Wood Doors inclu hw	121A Office	1	EA	7	10+ years		
	Floor - Tile	121A Office	130	SF	7	10+ years		
	Lighting - Lay-in	121A Office	2	EA	7	6-10 years		
	Power Distribution	121A Office	4	EA	7	10+ years		
	Walls - Concrete Block	121A Office	380	SF	7	10+ years		
	Ceiling - Splined	121B Office	130	SF	7	10+ years		
	Doors - Side-lite	121B Office	40	SF	7	10+ years		
	Doors - Wood Doors inclu hw	121B Office	1	ĒΑ	7	10+ years		
	Floor - Tile	121B Office	130	SF	7	10+ years		
	-			-		- ,		



Category : Room		B	Building : Main-Academic_Unit B				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	121B Office	2	EA	7	6-10 years	
	Power Distribution	121B Office	4	EA	7	10+ years	
	Walls - Concrete Block	121B Office	350	SF	7	10+ years	
	Ceiling - Splined	121C Copy Center	180	SF	7	10+ years	
	Doors - Side-lite	121C Copy Center	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	121C Copy Center	3	EA	7	10+ years	
	Floor - Tile	121C Copy Center	180	SF	7	10+ years	
	Lighting - Pendent/Surface	121C Copy Center	2	EA	7	6-10 years	
	Power Distribution	121C Copy Center	2	EA	7	10+ years	
	Storage/ Closet	121C Copy Center	60	SF	7	10+ years	
	Walls - Concrete Block	121C Copy Center	400	SF	7	10+ years	
	Ceiling - Lay-in	123A Office	80	SF	7	10+ years	
	Doors - Side-lite	123A Office	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	123A Office	1	EA	7	10+ years	
	Floor - Tile	123A Office	80	SF	7	10+ years	
	Lighting - Lay-in	123A Office	2	EA	7	6-10 years	
	Power Distribution	123A Office	8	EA	7	10+ years	
	Walls - Concrete Block	123A Office	300	SF	7	10+ years	
	Ceiling - Lay-in	160A Magazine Room	230	SF	7	10+ years	
	Doors - Side-lite	160A Magazine Room	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	160A Magazine Room	1	EA	7	10+ years	
	Floor - Carpet	160A Magazine Room	230	SF	7	6-10 years	
	Lighting - Lay-in	160A Magazine Room	4	EA	7	6-10 years	
	Power Distribution	160A Magazine Room	6	EA	7	10+ years	
	Walls - Concrete Block	160A Magazine Room	460	SF	7	10+ years	
	Ceiling - Lay-in	160B Librarian Office	110	SF	6	10+ years	
	Doors - Wood Doors inclu hw	160B Librarian Office	2	EA	6	10+ years	
	Floor - Carpet	160B Librarian Office	110	SF	6	6-10 years	
	Lighting - Lay-in	160B Librarian Office	1	EΑ	6	6-10 years	
	Power Distribution	160B Librarian Office	8	EA	7	10+ years	
	Walls - Concrete Block	160B Librarian Office	220	SF SF	6	10+ years	
	Ceiling - Lay-in	160C Work Room	300	SF SF	7	10+ years	Democrad sailing
	Ceiling - Lay-in	160C Work Room	40		4	1-2 years	Damaged ceiling
	Doors - Wood Doors inclu hw	160C Work Room	2	EA SF	7 7	10+ years	
	Floor - Tile	160C Work Room	340	SF EA		10+ years	
	Lighting - Lay-in	160C Work Room 160C Work Room	5 1	EA EA	7 6	6-10 years	Not working
	Lighting - Lay-in Power Distribution	160C Work Room	12	EA	7	2-5 years	Not working
	Walls - Concrete Block	160C Work Room	680	SF	7	10+ years	
	Work Sink		1	EA		10+ years	
		160C Work Room 160D Conference Room	340	SF	7 7	10+ years	
	Ceiling - Lay-in Doors - Side-lite	160D Conference Room	340 48	SF SF	7	10+ years 10+ years	
	Doors - Side-life Doors - Wood Doors inclu hw	160D Conference Room	40 1	EA	7	10+ years 10+ years	
	Floor - Carpet	160D Conference Room	340	SF	6	6-10 years	
	i looi - Gaipet	TOOD COMEIGNED KOOM	340	JI.	Ü	0-10 years	

Campus Name: Kenwood HS Page : 12 of 115 Assessment Date: 07/08/2024



Category : Room		Building : Main-Academic_Unit B						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	160D Conference Room	6	EA	7	10+ years		
	Power Distribution	160D Conference Room	4	EA	7	10+ years		
	Walls - Concrete Block	160D Conference Room	520	SF	7	10+ years		
	Ceiling - Lay-in	212 Social Studies Office	656	SF	7	10+ years		
	Ceiling - Lay-in	212 Social Studies Office	8	SF	5	1-2 years	Damaged tile	
	Doors - Transom Window	212 Social Studies Office	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	212 Social Studies Office	2	EA	7	10+ years		
	Floor - Tile	212 Social Studies Office	664	SF	7	10+ years		
	Lighting - Lay-in	212 Social Studies Office	14	EA	7	6-10 years		
	Lighting - Lay-in	212 Social Studies Office	1	EΑ	6	2-5 years		
	Power Distribution	212 Social Studies Office	32	EA	7	10+ years		
	Walls - Concrete Block	212 Social Studies Office	830	SF	7	10+ years		
	Work SInk	212 Social Studies Office	1	EA	7	10+ years		
	Ceiling - Lay-in	213 Listening/Viewing Room (in Media Center)	400	SF	7	10+ years		
	Doors - Side-lite	213 Listening/Viewing Room (in Media Center)	48	SF	7	10+ years		
	Doors - Wood Doors inclu hw	213 Listening/Viewing Room (in Media Center)	1	EA	7	10+ years		
	Floor - Carpet	213 Listening/Viewing Room (in	400	SF	7	6-10 years		
	Lighting - Lay-in	Media Center) 213 Listening/Viewing Room (in Media Center)	6	EA	7	6-10 years		
	Power Distribution	213 Listening/Viewing Room (in Media Center)	10	EA	7	10+ years		
	Walls - Concrete Block	213 Listening/Viewing Room (in Media Center)	588	SF	7	10+ years		
	Ceiling - Lay-in	214 World Language Office	442	SF	7	10+ years		
	Ceiling - Lay-in	214 World Language Office	16	SF	5	1-2 years	Damaged tile	
	Doors - Transom Window	214 World Language Office	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	214 World Language Office	3	EA	7	10+ years		
	Floor - Tile	214 World Language Office	458	SF	7	10+ years		
	Lighting - Lay-in	214 World Language Office	7	EA	7	6-10 years		
	Lighting - Lay-in	214 World Language Office	3	EA	6	6-10 years	Not working	
	Power Distribution	214 World Language Office	10	EA	7	10+ years		
	Walls - Concrete Block	214 World Language Office	630	SF	7	10+ years		
	Work SInk	214 World Language Office	1	EA	7	10+ years		
	Ceiling - Lay-in	214A Office (between 214 and 212)	166	SF	7	10+ years		
	Floor - Tile	214A Office (between 214 and 212)	166	SF EA	7	10+ years		
	Lighting - Lay-in Power Distribution	214A Office (between 214 and 212)	4 6	EA EA	7 7	6-10 years		
	Storage/ Closet	214A Office (between 214 and 212) 214A Office (between 214 and 212)	16	SF	7	10+ years 10+ years		
	Walls - Concrete Block	214A Office (between 214 and 212)	390	SF	7	10+ years		
	Ceiling - Lay-in	245 Dean's Office (formerly Women	128	SF	6	10+ years		
		• •				•		

Campus Name: Kenwood HS Page: 13 of 115 Assessment Date: 07/08/2024



Catego	ry : Room		Building : Main-Academic_Unit B					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Calling Lawin	Faculty Restroom)	40	C.E.	_	1.0.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Minaina/ dama and tila	
	Ceiling - Lay-in	245 Dean's Office (formerly Women Faculty Restroom)	16	SF	5	1-2 years	Missing/ damaged tile	
	Doors - Wood Doors inclu hw	245 Dean's Office (formerly Women	1	EA	6	10+ years		
	Doore Wood Doore more m	Faculty Restroom)		_, 、	Ü	io. youro		
	Floor - Tile	245 Dean's Office (formerly Women	144	SF	7	10+ years		
		Faculty Restroom)						
	Lighting - Lay-in	245 Dean's Office (formerly Women	2	EA	7	6-10 years		
	Power Distribution	Faculty Restroom) 245 Dean's Office (formerly Women	4	EA	7	10		
	Power distribution	Faculty Restroom)	4	EA	7	10+ years		
	Walls - Concrete Block	245 Dean's Office (formerly Women	440	SF	7	10+ years		
		Faculty Restroom)			•	, , , , , , , , , , , , , , , , , , , ,		
	Ceiling - Lay-in	253A Meeting Room (in Media	330	SF	7	10+ years		
		Center)						
	Doors - Wood Doors inclu hw	253A Meeting Room (in Media	1	EA	7	10+ years		
	Floor - Carpet	Center) 253A Meeting Room (in Media	330	SF	7	6-10 years		
	Floor - Carpet	Center)	330	SF	,	0-10 years		
	Lighting - Lay-in	253A Meeting Room (in Media	4	EA	7	6-10 years		
		Center)				,		
	Lighting - Lay-in	253A Meeting Room (in Media	2	EA	6	6-10 years	Not working	
		Center)			_			
	Power Distribution	253A Meeting Room (in Media	4	EA	7	10+ years		
	Walls - Concrete Block	Center) 253A Meeting Room (in Media	540	SF	7	10+ years		
	Walls - Coliciete Block	Center)	340	OI.	,	10+ years		
	Work SInk	253A Meeting Room (in Media	1	EA	7	10+ years		
		Center)				,		
	Ceiling - Lay-in	253C Work Room (in Media Center)	196	SF	7	10+ years		
	Doors - Wood Doors inclu hw	253C Work Room (in Media Center)	3	EA	7	10+ years		
	Floor - Carpet	253C Work Room (in Media Center)	196	SF	7	6-10 years		
	Lighting - Lay-in	253C Work Room (in Media Center)	3	EA	7	6-10 years		
	Power Distribution	253C Work Room (in Media Center)	8	EA	7	10+ years		
	Storage/ Closet	253C Work Room (in Media Center)	130	SF	7	10+ years		
	Walls - Concrete Block	253C Work Room (in Media Center)	390	SF	7	10+ years		
	Work SInk	253C Work Room (in Media Center)	1	EA	7	10+ years		
	Ceiling - Lay-in	301A	202	SF	7	10+ years		
	Doors - Side-lite	301A	40	SF	7	10+ years		
	Doors - Wood Doors inclu hw	301A	1	EA	7	10+ years		
	Floor - Tile	301A	202	SF	6	10+ years		
	Lighting - Lay-in	301A 301A	4	EA	7	10+ years		
			1	EA			Not working	
	Lighting - Lay-in Power Distribution	301A	6	EA	6 7	6-10 years	Not working	
	LOWEL DISHIDURION	301A	0	EA	1	10+ years		



Category : Room			Building : Main-Academic_Unit B					
_	_					Recommend	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	301A	435	SF	7	10+ years		
	Work SInk	301A	1	EA	7	10+ years		
	Ceiling - Lay-in	303A	202	SF	7	10+ years		
	Doors - Side-lite	303A	40	SF	7	10+ years		
	Doors - Wood Doors inclu hw	303A	1	EA	7	10+ years		
	Floor - Tile	303A	197	SF	7	10+ years		
	Floor - Tile	303A	5	SF	4	1-2 years	Damaged floor	
	Lighting - Lay-in	303A	2	EA	7	10+ years		
	Lighting - Lay-in	303A	2	EA	6	6-10 years	Not working	
	Power Distribution	303A	6	EA	7	10+ years		
	Walls - Concrete Block	303A	435	SF	7	10+ years		
	Work SInk	303A	1	EA	7	10+ years		
	Ceiling - Lay-in	305A	220	SF	7	10+ years		
	Doors - Side-lite	305A	40	SF	7	10+ years		
	Doors - Wood Doors inclu hw	305A	1	EA	7	10+ years		
	Floor - Tile	305A	220	SF	7	10+ years		
	Lighting - Lay-in	305A	3	EA	7	10+ years		
	Lighting - Lay-in	305A	1	EA	6	6-10 years		
	Power Distribution	305A	6	EA	7	10+ years		
	Walls - Concrete Block	305A	450	SF	7	10+ years		
	Work SInk	305A	1	EA	7	10+ years		
	Ceiling - Lay-in	307	342	SF	7	10+ years		
	Doors - Side-lite	307	20	SF	7	10+ years		
	Doors - Wood Doors inclu hw	307	1	EA	7	10+ years		
	Floor - Tile	307	340	SF	6	10+ years		
	Floor - Tile	307	2	SF	4	1-2 years	Damaged flooring	
	Lighting - Lay-in	307	6	EA	6	10+ years		
	Power Distribution	307	4	EA	7	10+ years		
	Storage/ Closet	307	8	SF	7	10+ years		
	Walls - Concrete Block	307	640	SF	7	10+ years		
	Walls - Plaster/Drywall	307	30	SF	7	10+ years		
	Ceiling - Lay-in	307A NA moved to CR	556	SF	7	10+ years		
	Doors - Side-lite	307A NA moved to CR	50	SF	7	10+ years		
	Doors - Wood Doors inclu hw	307A NA moved to CR	1	ĒΑ	7	10+ years		
	Floor - Tile	307A NA moved to CR	556	SF	6	10+ years		
	Lighting - Lay-in	307A NA moved to CR	12	ĒΑ	6	6-10 years		
	Power Distribution	307A NA moved to CR	4	EA	7	10+ years		
	Walls - Concrete Block	307A NA moved to CR	680	SF	7	10+ years		
	Walls - Plaster/Drywall	307A NA moved to CR	44	SF	7	10+ years		
	Ceiling - Lay-in	309 - Special Education	530	SF	7	10+ years		
	Doors - Wood Doors inclu hw	309 - Special Education	1	EA	7	10+ years		
	Floor - Tile	309 - Special Education	518	SF	6	10+ years		
	Floor - Tile	309 - Special Education	12	SF	4	1-2 years	Damaged floor	
	Lighting - Lay-in	309 - Special Education	5	EA	6	10+ years	Damagod noor	
	Ligiting Lay III	300 Opeolal Education	3	L/\	Ū	TOT yours		

Campus Name: Kenwood HS Page : 15 of 115 Assessment Date: 07/08/2024



Category : Room		Building : Main-Academic_Unit B					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	309 - Special Education	4	EA	6	6-10 years	Not working
	Power Distribution	309 - Special Education	24	EA	7	10+ years	
	Storage/ Closet	309 - Special Education	220	SF	7	10+ years	
	Walls - Concrete Block	309 - Special Education	637	SF	7	10+ years	
	Walls - Plaster/Drywall	309 - Special Education	44	SF	7	10+ years	
	Ceiling - Splined	309A - Conference Room	130	SF	7	10+ years	
	Doors - Wood Doors inclu hw	309A - Conference Room	1	EA	7	10+ years	
	Floor - Tile	309A - Conference Room	90	SF	7	10+ years	
	Floor - Tile	309A - Conference Room	40	SF	4	1-2 years	Missing tile
	Lighting - Lay-in	309A - Conference Room	2	EA	7	10+ years	
	Power Distribution	309A - Conference Room	6	EA	7	10+ years	
	Walls - Concrete Block	309A - Conference Room	320	SF	7	10+ years	
	Ceiling - Lay-in	314 - Math Office	723	SF	7	10+ years	
	Ceiling - Lay-in	314 - Math Office	20	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	314 - Math Office	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	314 - Math Office	1	EA	7	10+ years	
	Floor - Tile	314 - Math Office	743	SF	6	10+ years	
	Lighting - Lay-in	314 - Math Office	11	EA	7	10+ years	
	Lighting - Lay-in	314 - Math Office	3	EA	6	6-10 years	Not working
	Power Distribution	314 - Math Office	12	EA	7	10+ years	· ·
	Walls - Concrete Block	314 - Math Office	960	SF	7	10+ years	
	Ceiling - Lay-in	321A	155	SF	7	10+ years	
	Doors - Side-lite	321A	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	321A	2	EA	7	10+ years	
	Floor - Tile	321A	155	SF	7	10+ years	
	Lighting - Lay-in	321A	3	EA	7	6-10 years	
	Lighting - Lay-in	321A	1	EA	6	6-10 years	Not working
	Power Distribution	321A	8	EA	7	10+ years	3
	Storage/ Closet	321A	60	SF	7	10+ years	
	Walls - Plaster/Drywall	321A	400	SF	7	10+ years	
	Work SInk	321A	1	ĒΑ	7	10+ years	
	Ceiling - Lay-in	324A	74	SF	7	10+ years	
	Doors - Side-lite	324A	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	324A	1	EA	7	10+ years	
	Floor - Tile/Sheet	324A	74	SF	6	2-5 years	
	Lighting - Lay-in	324A	2	EA	7	6-10 years	
	Power Distribution	324A	8	EA	7	10+ years	
	Walls - Plaster/Drywall	324A	250	SF	7	10+ years	
	Ceiling - Lay-in	325A	144	SF	7	10+ years	
	Doors - Side-lite	325A	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	325A 325A	1	EA	7	10+ years	
	Floor - Tile	325A 325A	144	SF	7	10+ years	
	Lighting - Lay-in	325A 325A	2	EA	7	6-10 years	
	Power Distribution	325A 325A	12	EA	7	10+ years	
	I OWEL DISHIBUTION	JZJA	12	EA	,	10+ years	

Campus Name: Kenwood HS Page : 16 of 115 Assessment Date: 07/08/2024



Catego	ry : Room		В	uilding	: Main-	Academic_Unit	В
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	325A	350	SF	7	10+ years	
	Work SInk	325A	1	EA	7	10+ years	
	Ceiling - Lay-in	Deans office	144	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Deans office	1	EA	7	10+ years	
	Floor - Tile	Deans office	144	SF	7	10+ years	
	Lighting - Lay-in	Deans office	2	EA	7	10+ years	
	Power Distribution	Deans office	4	EA	7	10+ years	
	Walls - Concrete Block	Deans office	440	SF	7	10+ years	
	Ceiling - Lay-in	Pantry between 112 + 113	88	SF	7	10+ years	
	Floor - Tile	Pantry between 112 + 113	88	SF	7	10+ years	
	Lighting - Lay-in	Pantry between 112 + 113	2	EA	7	6-10 years	
	Power Distribution	Pantry between 112 + 113	4	EA	7	10+ years	
	Walls - Concrete Block	Pantry between 112 + 113	256	SF	7	6-10 years	
	Work Slnk	Pantry between 112 + 113	1	ĒΑ	7	6-10 years	
			•		·	o .o you.o	
Clinic							
	Ceiling - Lay-in	244 Nurse Office	288	SF	7	10+ years	
	Doors - Wood Doors inclu hw	244 Nurse Office	1	EA	7	10+ years	
	Floor - Carpet	244 Nurse Office	144	SF	6	2-5 years	
	Floor - Tile/Sheet	244 Nurse Office	134	SF	7	10+ years	
	Floor - Tile/Sheet	244 Nurse Office	10	SF	4	1-2 years	Damaged floor
	Lighting - Lay-in	244 Nurse Office	2	EA	7	6-10 years	
	Walls - Concrete Block	244 Nurse Office	440	SF	7	10+ years	
	Walls - Masonry	244 Nurse Office	230	SF	7	10+ years	
Library							
<u></u>	Casework	160 Media Lab	273	LF	7	10+ years	
	Ceiling - Lay-in	160 Media Lab	5,844	SF	7	10+ years	
	Ceiling - Lay-in	160 Media Lab	70	SF	5	1-2 years	Damaged tile
	Doors - Side-lite	160 Media Lab	192	SF	7	10+ years	zamagea me
	Doors - Wood Doors inclu hw	160 Media Lab	8	ĒΑ	7	10+ years	
	Floor - Carpet	160 Media Lab	5,914	SF	7	6-10 years	
	Lighting - Lay-in	160 Media Lab	9	EA	7	6-10 years	
	Lighting - Lay-in	160 Media Lab	12	EΑ	6	2-5 years	Not working
	Walls - Plaster/Drywall	160 Media Lab	4,474	SF	7	10+ years	Not Working
			.,			, , , , , , , , , , , , , , , , , , , ,	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	221 King Room	1,274	SF	7	10+ years	
	Ceiling - Lay-in	221 King Room	16	SF	5	1-2 years	Damaged tile
	Doors - Side-lite	221 King Room	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	221 King Room	3	EA	7	10+ years	
	Floor - Carpet	221 King Room	1,290	SF	7	6-10 years	
	Lighting - Lay-in	221 King Room	33	EA	7	6-10 years	
		-				•	



Catego	ry : Room		Building : Main-Academic_Unit B				
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Market Board	221 King Room	20	LF	7	6-10 years	
	Storage/ Closet	221 King Room	33	SF	7	10+ years	
	Walls - Concrete Block	221 King Room	910	SF	7	10+ years	
	Walls - Metal Panel	221 King Room	292	SF	7	10+ years	
	Ceiling - Lay-in	222 King Room	1,180	SF	7	10+ years	
	Ceiling - Lay-in	222 King Room	30	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	222 King Room	10	SF	7	10+ years	3
	Doors - Wood Doors inclu hw	222 King Room	2	EA	7	10+ years	
	Floor - Carpet	222 King Room	1,210	SF	7	6-10 years	
	Lighting - Lay-in	222 King Room	33	EA	7	6-10 years	
	Market Board	222 King Room	10	LF	7	6-10 years	
	Walls - Concrete Block	222 King Room	725	SF	7	10+ years	
	Walls - Metal Panel	222 King Room	477	SF	7	10+ years	
	Ceiling - Splined	246 Faculty Serving Line	386	SF	7	10+ years	
	Ceiling - Splined	246 Faculty Serving Line	6	SF	5	1-2 years	Damage tile
	Doors - Transom Window	246 Faculty Serving Line	6	SF	7	10+ years	g
	Doors - Wood Doors inclu hw	246 Faculty Serving Line	1	ĒΑ	7	10+ years	
	Doors - Wood Doors inclu hw	246 Faculty Serving Line	1	EA	7	10+ years	
	Floor - Tile	246 Faculty Serving Line	392	SF	7	10+ years	
	Lighting - Lay-in	246 Faculty Serving Line	5	ĒΑ	7	6-10 years	
	Lighting - Lay-in	246 Faculty Serving Line	3	EA	6	2-5 years	Not working
	Walls - Concrete Block	246 Faculty Serving Line	560	SF	7	10+ years	9
	Walls - Masonry	246 Faculty Serving Line	150	SF	7	10+ years	
MDF_ID	F						
	Doors - Wood Doors inclu hw	in 123 Computer Lab	1	EA	7	10+ years	
	Finishes	in 123 Computer Lab	144	SF	7	10+ years	
	Doors - Wood Doors inclu hw	in 221 + 222 (former storage)	2	ĒA	7	10+ years	
	Finishes	in 221 + 222 (former storage)	166	SF	7	10+ years	
	Other Cooling Unit	in 221 + 222 (former storage)	1	ĒΑ	7	6-10 years	
Mechani	cal/ Service Rooms						
	Air Intake Plenums	1st Floor	28	SF	7	10+ years	
	Janitor's Closet	1st Floor	60	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	256	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	56	SF	7	10+ years	
	Storage Room	1st Floor - Main + Guidance Office	17	SF	7	10+ years	
	Storago (toom	Areas	17	5 1	,	ioi youis	
	Storage Room	1st Floor - Main + Guidance Office	34	SF	7	10+ years	
	-	Areas				·	
	Storage Room	1st Floor - Main + Guidance Office	9	SF	7	10+ years	
	Ot D	Areas	450	0-	-	40	
	Storage Room	1st Floor - Main + Guidance Office Areas	152	SF	7	10+ years	
		, 11040					



Catego	ry : Room		Building : Main-Academic_Unit B					
	_					Recommend	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Storage Room	1st Floor - Main + Guidance Office	6	SF	7	10+ years		
		Areas						
	Storage Room	1st Floor - Main + Guidance Office	7	SF	7	10+ years		
		Areas						
	Janitor's Closet	2nd Floor	54	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	56	SF	7	10+ years		
	Storage Room	2nd Floor	72	SF	7	10+ years		
	Storage Room	2nd Floor	640	SF	5	10+ years		
	Auditorium Plenums	3rd Floor	1,000	SF	7	10+ years		
	Boiler Room	3rd Floor	2,500	SF	7	10+ years		
	Janitor's Closet	3rd Floor	26	SF	7	10+ years		
	Mechanical/ Service Rooms	3rd Floor	2,556	SF	7	10+ years		
	Storage Room	3rd Floor	98	SF	7	10+ years		
	Storage Room	3rd Floor	92	SF	7	10+ years		
	Storage Room	3rd Floor	105	SF	7	10+ years		
_Prep Ro	om							
'	Casework	301A	28	LF	7	10+ years		
	Ceiling - Lay-in	301A	100	SF	7	10+ years		
	Doors - Steel Doors incl hw	301A	1	ĒA	7	10+ years		
	Floor - Tile	301A	100	SF	7	10+ years		
	Lighting - Lay-in	301A	2	EA	6	6-10 years		
	Walls - Concrete Block	301A	300	SF	7	10+ years		
	Work Sink	301A	1	ĒA	7	10+ years		
	Casework	301B	36	LF	7	10+ years		
	Ceiling - Splined	301B	178	SF	7	10+ years		
	Doors - Steel Doors incl hw	301B	1	EA	7	10+ years		
	Floor - Tile	301B	175	SF	7	10+ years		
	Floor - Tile	301B	3	SF	4	1-2 years	Damaged tile	
	Lighting - Lay-in	301B	2	EA	7	6-10 years	•	
	Walls - Concrete Block	301B	464	SF	7	10+ years		
	Casework	301C - Plants	25	LF	7	10+ years		
	Ceiling - Splined	301C - Plants	217	SF	7	10+ years		
	Ceiling - Splined	301C - Plants	1	SF	4	1-2 years	Damaged ceiling	
	Doors - Wood Doors inclu hw	301C - Plants	2	EA	7	10+ years	0 0	
	Floor - Tile	301C - Plants	218	SF	7	10+ years		
	Lighting - Lay-in	301C - Plants	4	EA	7	6-10 years		
	Walls - Concrete Block	301C - Plants	456	SF	7	10+ years		
	Work Sink	301C - Plants	1	EA	7	10+ years		
	Casework	303B	20	LF	7	10+ years		
	Ceiling - Lay-in	303B	100	SF	7	10+ years		
	Doors - Wood Doors inclu hw	303B	1	ĒΑ	7	10+ years		
	Floor - Tile	303B	100	SF	7	10+ years		
	Lighting - Lay-in	303B	2	ĒΑ	7	6-10 years		
						·		



Category : Room		Building : Main-Academic_Unit B						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	303B	320	SF	7	10+ years		
	Work Sink	303B	1	EA	7	10+ years		
	Casework	303C - Plant	23	LF	7	10+ years		
	Ceiling - Splined	303C - Plant	85	SF	7	10+ years		
	Ceiling - Splined	303C - Plant	25	SF	4	1-2 years	Missing tile	
	Doors - Wood Doors inclu hw	303C - Plant	2	EA	7	10+ years		
	Floor - Tile	303C - Plant	94	SF	7	10+ years		
	Floor - Tile	303C - Plant	16	SF	4	1-2 years	Damaged floor	
	Lighting - Lay-in	303C - Plant	1	EΑ	7	6-10 years		
	Lighting - Lay-in	303C - Plant	1	EA	5	1-2 years	No cover	
	Walls - Concrete Block	303C - Plant	288	SF	7	10+ years		
	Work Sink	303C - Plant	1	EA	7	10+ years		
	Casework	305C	36	LF	7	10+ years		
	Ceiling - Splined	305C	172	SF	7	10+ years		
	Ceiling - Splined	305C	8	SF	4	1-2 years	Missing tile	
	Doors - Wood Doors inclu hw	305C	1	EA	7	10+ years	•	
	Floor - Tile	305C	180	SF	7	10+ years		
	Lighting - Lay-in	305C	2	EA	7	6-10 years		
	Walls - Concrete Block	305C	490	SF	7	10+ years		
	Work Sink	305C	1	EA	7	10+ years		
	Casework	310/315	25	LF	7	10+ years		
	Ceiling - Lay-in	310/315	228	SF	7	10+ years		
	Ceiling - Lay-in	310/315	20	SF	4	1-2 years	Damaged tile	
	Doors - Steel Doors incl hw	310/315	2	EA	7	10+ years	o	
	Floor - Tile	310/315	248	SF	7	10+ years		
	Lighting - Lay-in	310/315	3	EA	7	6-10 years		
	Walls - Concrete Block	310/315	670	SF	7	10+ years		
	Work Sink	310/315	2	EΑ	7	10+ years		
	Casework	310B	29	LF	7	10+ years		
	Ceiling - Lay-in	310B	203	SF	7	10+ years		
	Doors - Wood Doors inclu hw	310B	1	ĒΑ	7	10+ years		
	Floor - Tile	310B	203	SF	7	10+ years		
	Lighting - Lay-in	310B	2	ĒΑ	7	6-10 years		
	Power Distribution	310B	14	ΕA	7	10+ years		
	Walls - Concrete Block	310B	436	SF	7	10+ years		
	Work Sink	310B	2	EA	7	10+ years		
	Casework	315A	32	LF	7	10+ years		
	Ceiling - Lay-in	315A	203	SF	7	10+ years		
	Doors - Wood Doors inclu hw	315A	1	EA	7	10+ years		
	Floor - Tile	315A	203	SF	7	10+ years		
	Lighting - Lay-in	315A	203	EA	7	6-10 years		
	Power Distribution	315A	14	EA	7	10+ years		
	Walls - Concrete Block	315A 315A	436	SF	7	10+ years		
	Work Sink	315A	1	EA	7	10+ years		
	WOIN GILIK	313/4	ı	LA	,	TOT years		



Category : Room			Building : Main-Academic_Unit B					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Casework	324B	21	LF	7	10+ years		
	Ceiling - Lay-in	324B	173	SF	7	10+ years		
	Doors - Wood Doors inclu hw	324B	1	EA	7	10+ years		
	Floor - Tile/Sheet	324B	173	SF	6	2-5 years		
	Lighting - Lay-in	324B	4	EA	6	6-10 years		
	Walls - Plaster/Drywall	324B	450	SF	7	10+ years		
	Work Sink	324B	1	EA	7	10+ years		
	Casework	325B	28	LF	7	10+ years		
	Ceiling - Lay-in	325B	110	SF	7	10+ years		
	Doors - Steel Doors incl hw	325B	1	EA	7	10+ years		
	Floor - Tile	325B	110	SF	7	10+ years		
	Lighting - Lay-in	325B	2	EA	7	10+ years		
	Walls - Concrete Block	325B	326	SF	7	10+ years		
	Work Sink	325B	1	EA	7	10+ years		
						,		
Restroor	n							
	Accessories	100M Toilet Room	30	SF	7	6-10 years		
	Ceiling - Lay-in	100M Toilet Room	30	SF	7	10+ years		
	Doors - Wood Doors inclu hw	100M Toilet Room	1	EA	7	10+ years		
	Floor - Tile	100M Toilet Room	30	SF	7	10+ years		
	Lavatory	100M Toilet Room	1	EA	7	10+ years		
	Lighting - Wall Mounted	100M Toilet Room	1	EA	7	6-10 years		
	Walls - Concrete Block	100M Toilet Room	157	SF	7	10+ vears		
	Water Closet	100M Toilet Room	1	EΑ	7	10+ years		
	Accessories	101 Womens Toilet Room inside	30	SF	7	6-10 years		
		principal office				, , , , , , , , , , , , , , , , , , ,		
	Ceiling - Lay-in	101 Womens Toilet Room inside	30	SF	7	10+ years		
		principal office		٠.	•	.o. you.o		
	Doors - Wood Doors inclu hw	101 Womens Toilet Room inside	1	EA	7	10+ years		
	Boold Wood Boold Mold III	principal office	•	_, \	•	io. youro		
	Floor - Tile	101 Womens Toilet Room inside	30	SF	7	10+ years		
	1 looi Tile	principal office	30	Oi.	•	101 years		
	Lavatory	101 Womens Toilet Room inside	1	EA	7	10+ years		
	Lavatory	principal office	'	LA	,	10+ years		
	Lighting - Wall Mounted	101 Womens Toilet Room inside	1	EA	7	6-10 years		
	Lighting - Wall Modified	principal office	'	LA	,	0-10 years		
	Walls - Concrete Block	101 Womens Toilet Room inside	183	SF	7	10 Lyonro		
	Walls - Concrete block		103	SF	1	10+ years		
	Mater Classi	principal office	4	Ε.	7	10		
	Water Closet	101 Womens Toilet Room inside	1	EA	7	10+ years		
	Acceptation	principal office	00	C.E.	7	6.40		
	Accessories	101K North Toilet Room	28	SF	7	6-10 years		
	Ceiling - Lay-in	101K North Toilet Room	28	SF	7	10+ years		
	Doors - Wood Doors inclu hw	101K North Toilet Room	1	EA	7	10+ years		
	Floor - Tile	101K North Toilet Room	28	SF	7	10+ years		



Category : Room			Building : Main-Academic_Unit B					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lavatory	101K North Toilet Room	1	EA	7	10+ years		
	Lighting - Wall Mounted	101K North Toilet Room	1	EA	7	6-10 years		
	Walls - Concrete Block	101K North Toilet Room	179	SF	7	10+ years		
	Water Closet	101K North Toilet Room	1	EA	7	10+ years		
	Accessories	101K South Toilet Room	26	SF	7	6-10 years		
	Ceiling - Lay-in	101K South Toilet Room	26	SF	7	10+ years		
	Doors - Wood Doors inclu hw	101K South Toilet Room	1	EA	7	10+ years		
	Floor - Tile	101K South Toilet Room	26	SF	7	10+ years		
	Lavatory	101K South Toilet Room	1	EA	7	10+ years		
	Lighting - Wall Mounted	101K South Toilet Room	1	EA	7	6-10 years		
	Walls - Concrete Block	101K South Toilet Room	150	SF	7	10+ years		
	Water Closet	101K South Toilet Room	1	EA	7	10+ years		
	Accessories	161 Women	85	SF	7	6-10 years		
	Ceiling - Lay-in	161 Women	69	SF	7	10+ years		
	Ceiling - Lay-in	161 Women	16	SF	5	1-2 years	Damaged tile	
	Doors - Wood Doors inclu hw	161 Women	1	EΑ	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	161 Women	85	SF	7	10+ years		
	Hand Dryer	161 Women	1	EΑ	7	6-10 years		
	Lavatory	161 Women	1	EA	7	10+ years		
	Lighting - Lay-in	161 Women	1	EA	7	6-10 years		
	Partitions	161 Women	2	EA	7	10+ years		
	Walls - Concrete Block	161 Women	300	SF	7	10+ years		
	Water Closet	161 Women	2	EA	7	10+ years		
	Accessories	163 Girls	270	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	163 Girls	270	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	163 Girls	270	SF	7	10+ years		
	Floor Drain	163 Girls	1	EA	7	10+ years		
	Hand Dryer	163 Girls	2	EA	7	6-10 years		
	Lavatory	163 Girls	3	EA	7	10+ years		
	Lighting - Pendent/Surface	163 Girls	4	EA	7	6-10 years		
	Partitions	163 Girls	4	EA	7	6-10 years		
	Walls - Concrete Block	163 Girls	700	SF	7	10+ years		
	Water Closet	163 Girls	4	ĒΑ	7	10+ years		
	Accessories	164 Boys	240	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	164 Boys	240	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	164 Boys	240	SF	6	10+ years		
	Floor Drain	164 Boys	1	ĒΑ	7	10+ years		
	Hand Dryer	164 Boys	2	EΑ	7	6-10 years		
	Lavatory	164 Boys	3	EA	7	10+ years		
	Lighting - Pendent/Surface	164 Boys	4	EΑ	7	10+ years		
	Partitions	164 Boys	2	EΑ	7	6-10 years		
	Urinals	164 Boys	3	EA	7	10+ years		
	Walls - Concrete Block	164 Boys	670	SF	7	10+ years		
	Water Closet	164 Boys	2	EA	7	10+ years		
		10120,0	۷	_/ \	,	ioi youis		

Campus Name: Kenwood HS Page : 22 of 115 Assessment Date: 07/08/2024



Category : Room Building : Main-Academic_Unit B						: B	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st Floor SE Unisex Toilet Room	85	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor SE Unisex Toilet Room	77	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor SE Unisex Toilet Room	8	SF	4	1-2 years	Damaged tile
	Doors - Wood Doors inclu hw	1st Floor SE Unisex Toilet Room	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor SE Unisex Toilet Room	85	SF	7	10+ years	
	Hand Dryer	1st Floor SE Unisex Toilet Room	1	EA	7	6-10 years	
	Lavatory	1st Floor SE Unisex Toilet Room	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor SE Unisex Toilet Room	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor SE Unisex Toilet Room	300	SF	7	10+ years	
	Water Closet	1st Floor SE Unisex Toilet Room	1	EA	6	10+ years	
	Accessories	250 Men	85	SF	7	6-10 years	
	Ceiling - Lay-in	250 Men	85	SF	7	10+ years	
	Doors - Wood Doors inclu hw	250 Men	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	250 Men	85	SF	7	10+ years	
	Hand Dryer	250 Men	1	EA	7	6-10 years	
	Lavatory	250 Men	1	EA	7	10+ years	
	Lighting - Lay-in	250 Men	1	EA	7	6-10 years	
	Partitions	250 Men	1	EA	7	10+ years	
	Urinals	250 Men	1	EA	7	10+ years	
	Walls - Concrete Block	250 Men	300	SF	7	10+ years	
	Water Closet	250 Men	1	EA	7	10+ years	
	Accessories	270 Girls	270	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	270 Girls	270	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	270 Girls	270	SF	7	10+ years	
	Floor Drain	270 Girls	1	EA	7	10+ years	
	Hand Dryer	270 Girls	1	EA	7	10+ years	
	Hand Dryer	270 Girls	1	EΑ	7	6-10 years	
	Lavatory	270 Girls	3	EΑ	7	10+ years	
	Lighting - Pendent/Surface	270 Girls	4	EΑ	7	6-10 years	
	Partitions	270 Girls	4	EA	7	10+ years	
	Walls - Concrete Block	270 Girls	700	SF	7	10+ years	
	Water Closet	270 Girls	4	EA	7	10+ years	
	Accessories	271 Boys	240	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	271 Boys	240	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	271 Boys	240	SF	7	10+ years	
	Floor Drain	271 Boys	1	EA	7	10+ years	
	Hand Dryer	271 Boys	2	EΑ	7	6-10 years	
	Lavatory	271 Boys	3	EΑ	7	10+ years	
	Lighting - Pendent/Surface	271 Boys	4	EΑ	7	6-10 years	
	Partitions	271 Boys	2	EΑ	7	10+ years	
	Urinals	271 Boys	3	EA	7	10+ years	
	Walls - Concrete Block	271 Boys	670	SF	7	10+ years	
	Water Closet	271 Boys	2	EA SF	7	10+ years	
	Accessories	2nd Floor Dean's Office Toilet	84	5F	7	6-10 years	



Category : Room			Building : Main-Academic_Unit B					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	2nd Floor Dean's Office Toilet	84	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor Dean's Office Toilet	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor Dean's Office Toilet	84	SF	6	10+ years		
	Lavatory	2nd Floor Dean's Office Toilet	1	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor Dean's Office Toilet	1	EA	7	6-10 years		
	Partitions	2nd Floor Dean's Office Toilet	2	EA	5	6-10 years		
	Walls - Concrete Block	2nd Floor Dean's Office Toilet	300	SF	7	10+ years		
	Water Closet	2nd Floor Dean's Office Toilet	2	EA	6	10+ years		
	Accessories	340 - Women	85	SF	7	6-10 years		
	Ceiling - Lay-in	340 - Women	69	SF	7	10+ years		
	Ceiling - Lay-in	340 - Women	16	SF	5	1-2 years	Damaged tile	
	Doors - Wood Doors inclu hw	340 - Women	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	340 - Women	85	SF	7	10+ years		
	Hand Dryer	340 - Women	1	EA	7	6-10 years		
	Lavatory	340 - Women	1	EΑ	7	10+ years		
	Lighting - Lay-in	340 - Women	1	EΑ	7	6-10 years		
	Partitions	340 - Women	2	EA	7	10+ years		
	Walls - Concrete Block	340 - Women	300	SF	7	10+ years		
	Water Closet	340 - Women	2	EA	7	10+ years		
	Accessories	345 - Men	85	SF	7	6-10 years		
	Ceiling - Lay-in	345 - Men	69	SF	7	10+ years	5	
	Ceiling - Lay-in	345 - Men	16	SF	5	1-2 years	Damaged tile	
	Doors - Wood Doors inclu hw	345 - Men	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	345 - Men	85	SF	7	10+ years		
	Hand Dryer	345 - Men	1	EA	7	6-10 years		
	Lavatory	345 - Men	1	EΑ	7	10+ years		
	Lighting - Lay-in	345 - Men	1	EA EA	7	6-10 years		
	Partitions Urinals	345 - Men 345 - Men	1	EA EA	7 7	10+ years		
	Walls - Concrete Block	345 - Men 345 - Men	300	SF	7	10+ years		
	Water Closet	345 - Men	300	EA	7	10+ years		
	Accessories	343 - Men 3rd Floor	240	SF	7	10+ years 6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	240	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor	235	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor	5	SF	4	1-2 years	Missing tile behind toilet	
	Floor Drain	3rd Floor	1	EA	7	10+ years	wissing the bening tollet	
	Hand Dryer	3rd Floor	2	EA	7	6-10 years		
	Lavatory	3rd Floor	3	EA	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	6-10 years		
	Partitions	3rd Floor	2	EA	7	10+ years		
	Urinals	3rd Floor	3	EA	7	10+ years		
	Walls - Concrete Block	3rd Floor	670	SF	7	10+ years		
	Water Closet	3rd Floor	2	EA	7	10+ years		
	Accessories	3rd Floor	270	SF	7	6-10 years		
	, 1000001100	014 1 1001	210	٥,	,	o io youis		

Campus Name: Kenwood HS Page : 24 of 115 Assessment Date: 07/08/2024



Catego	ry : Room		Building : Main-Academic_Unit B					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	3rd Floor	270	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd Floor	270	SF	7	10+ years		
	Floor Drain	3rd Floor	1	EA	7	10+ years		
	Hand Dryer	3rd Floor	2	EA	7	6-10 years		
	Lavatory	3rd Floor	3	EA	7	10+ years		
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	6-10 years		
	Partitions	3rd Floor	4	EA	7	10+ years		
	Walls - Concrete Block	3rd Floor	700	SF	7	10+ years		
	Water Closet	3rd Floor	4	EA	7	10+ years		
	Accessories	Women 247	85	SF	7	6-10 years		
	Ceiling - Lay-in	Women 247	85	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Women 247	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Women 247	85	SF	7	10+ years		
	Floor Drain	Women 247	1	EA	7	10+ years		
	Hand Dryer	Women 247	1	EA	7	6-10 years		
	Lavatory	Women 247	1	EA	7	10+ years		
	Lighting - Lay-in	Women 247	1	EA	7	6-10 years		
	Partitions	Women 247	2	EA	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	Women 247	300	SF	7	10+ years		
	Water Closet	Women 247	2	EA	7	10+ years		

Category : Classroom Building : Main-Academic_Unit B

						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroom #106 (Regular Classroom)									
	Casework	1st Floor	16	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	720	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor	46	SF	4	1-2 years	Damaged ceiling		
	Doors - Side-lite	1st Floor	10	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years			
	Floor - Tile	1st Floor	766	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	13	EΑ	7	6-10 years			
	Lighting - Lay-in	1st Floor	1	EΑ	6	6-10 years	Not working		
	Lighting - Lay-in	1st Floor	1	EΑ	5	1-2 years	Missing cover		
	Marker Board	1st Floor	16	LF	7	6-10 years	•		
	Walls - Concrete Block	1st Floor	770	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	52	SF	7	10+ years			
_Classroo	om #107 (Regular Classroom)								
	Casework	1st Floor	16	LF	7	6-10 years			
	Ceiling - Lay-in	1st Floor	700	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor	30	SF	4	1-2 years	Damaged tile		
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	•		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			

Campus Name: Kenwood HS Page : 25 of 115 Assessment Date: 07/08/2024



Catego	Category : Classroom			Building : Main-Academic_Unit B						
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor - Tile	1st Floor	729	SF	7	10+ years				
	Floor - Tile	1st Floor	1	SF	4	1-2 years	Damaged tile			
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years				
	Marker Board	1st Floor	16	LF	7	6-10 years				
	Walls - Concrete Block	1st Floor	750	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	50	SF	7	10+ years				
_Classroo	om #108 (Regular Classroom)									
	Casework	1st Floor	16	LF	6	10+ years				
	Ceiling - Lay-in	1st Floor	710	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor	20	SF	7	10+ years				
	Doors - Side-lite	1st Floor	10	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years				
	Floor - Tile	1st Floor	730	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	14	EA	7	•				
	Lighting - Lay-in	1st Floor			6	6-10 years	Not working			
			1	EA LF		6-10 years	Not working			
	Marker Board	1st Floor	16		7	6-10 years				
	Walls - Concrete Block	1st Floor	750	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	50	SF	7	10+ years				
_Classroo	om #109 (Regular Classroom)									
	Casework	1st Floor	16	LF	6	10+ years				
	Ceiling - Lay-in	1st Floor	20	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor	710	SF	7	10+ years				
	Doors - Side-lite	1st Floor	10	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years				
	Floor - Tile	1st Floor	730	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years				
	Lighting - Lay-in	1st Floor	1	EA	6	6-10 years	Not working			
	Marker Board	1st Floor	16	LF	7	6-10 years				
	Walls - Concrete Block	1st Floor	500	SF	7	10+ years				
	Walls - Metal Panel	1st Floor	250	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	50	SF	7	10+ years				
Classroo	om #110 (Regular Classroom)									
_ Oldssi Ut	Casework	1st Floor	16	LF	6	10 L Voors				
		1st Floor 1st Floor		SF	6	10+ years				
	Ceiling - Lay-in		700		7	10+ years	Domogod soiling			
	Ceiling - Lay-in	1st Floor	66	SF	4	1-2 years	Damaged ceiling			
	Doors - Side-lite	1st Floor	10	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years				
	Floor - Tile	1st Floor	766	SF	7	10+ years				
	Lighting Lay-in	1st Floor	15	EA	7	6-10 years				
	Marker Board	1st Floor	16	LF	7	6-10 years				



Category : Classroom			Building : Main-Academic_Unit B					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	1st Floor	520	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	52	SF	7	10+ years		
Classroo	om #116 (Regular Classroom)							
	Casework	1st Floor	16	LF	6	10+ years		
	Ceiling - Lay-in	1st Floor	700	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	66	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	_	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	766	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years		
	Lighting - Lay-in	1st Floor	2	EA	6	6-10 years	Not working	
	Marker Board	1st Floor	16	LF	7	6-10 years	3	
	Walls - Concrete Block	1st Floor	770	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	52	SF	7	10+ years		
Classroo	om #117 (Regular Classroom)							
	Casework	1st Floor	16	LF	6	6-10 years		
	Ceiling - Lay-in	1st Floor	700	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	30	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	Damagod tilo	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years		
	Floor - Tile	1st Floor	730	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	14	EA	7	6-10 years		
	Lighting - Lay-in	1st Floor	1	EA	6	6-10 years	Not working	
	Marker Board	1st Floor	16	LF	7	6-10 years	Not working	
	Walls - Concrete Block	1st Floor	750	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	50	SF	7	10+ years		
Classro	om #118 (Regular Classroom)							
Classiu	Casework	1st Floor	12	LF	7	10+ years		
	Casework	1st Floor	4	LF LF	, 5	1-2 years	Damaged casework	
	Casework Ceiling - Lay-in	1st Floor	700	SF	5 7	10+ years	Darriaged Casework	
	Ceiling - Lay-in Ceiling - Lay-in	1st Floor	30	SF SF	, 5		Damaged tile	
	Doors - Side-lite	1st Floor		SF SF	5 7	1-2 years	Damaged tile	
			10	SF EA		10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1		7	10+ years		
	Floor - Tile	1st Floor	730	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	13	EΑ	7	6-10 years	Not would a	
	Lighting - Lay-in	1st Floor	2	EA	6	6-10 years	Not working	
	Marker Board	1st Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	750	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	50	SF	7	10+ years		



Category : Classroom			Building : Main-Academic_Unit B					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	m #119 (Regular Classroom)							
	Casework	1st Floor	16	LF	6	10+ years		
	Ceiling - Lay-in	1st Floor	700	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	30	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	730	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years		
	Marker Board	1st Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	750	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	50	SF	7	10+ years		
Classroo	m #120 (Regular Classroom)							
	Casework	1st Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	700	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	66	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	1st Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years		
	Floor - Tile	1st Floor	766	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	15	ĒΑ	7	6-10 years		
	Marker Board	1st Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	1st Floor	770	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	52	SF	7	10+ years		
Classroo	m #121 (Computer Lab)							
	Ceiling - Lay-in	1st Floor	1,366	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	50	SF	7	10+ years		
	Chalk Board	1st Floor	10	LF	4	2-5 years		
	Doors - Side-lite	1st Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years		
	Floor - Tile	1st Floor	1,416	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	25	EA	6	6-10 years		
	Lighting - Lay-in	1st Floor	8	EΑ	6	2-5 years	Not working	
	Walls - Concrete Block	1st Floor	1,290	SF	7	10+ years	Trot Working	
	Walls - Plaster/Drywall	1st Floor	85	SF	7	10+ years		
	Wireless System	1st Floor	1	EA	7	6-10 years		
	Work Sink	1st Floor	1	EA	7	6-10 years		
Classroo	m #122 (Computer Lab)							
	Casework	1st Floor	28	LF	6	10+ years		
	Ceiling - Lay-in	1st Floor	1,200	SF	6	10+ years		
	Ceiling - Lay-in	1st Floor	58	SF	4	1-2 years	Damaged tile	
	Chalk Board	1st Floor	22	LF	4	2-5 years	_ aagoa aro	
			<i></i>		•	_ 0 ,00.0		



Catego	ry : Classroom	В	uilding	: Main-	Academic_Unit	В	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	1st Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	1,258	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	29	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,230	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	120	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #123 (Computer Lab)						
	Ceiling - Lay-in	1st Floor	1,744	SF	7	10+ years	
	Doors - Side-lite	1st Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,744	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	20	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,330	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	120	SF	7	10+ years	
	Wireless System	1st Floor	1 1	EA	7	6-10 years	
	Wireless System	13(1100)	ı	LA	,	0-10 years	
Classroo	om #201 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,238	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	20	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,238	SF	7	10+ years	
	Floor - Tile	2nd Floor	20	SF	4	1-2 years	Damaged floor
	Lighting - Lay-in	2nd Floor	24	EA	7	6-10 years	-
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	188	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	950	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	70	SF	7	10+ years	
Classroo	om #202 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	890	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	30	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	Damaged tile
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	
	Floor - Tile	2nd Floor	900	SF	7	10+ years	
	Floor - Tile Floor - Tile	2nd Floor 2nd Floor	10	SF SF	4	1-2 years	Damaged floor
							Damaged floor
	Lighting - Lay-in	2nd Floor	13	EΑ	7	6-10 years	Not working
	Lighting - Lay-in	2nd Floor	7	EA	6	6-10 years	Not working
	Marker Board	2nd Floor	24	LF	7	6-10 years	



Category : Classroom			Building : Main-Academic_Unit B					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	2nd Floor	900	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	60	SF	7	10+ years		
Classro	om #203 (Regular Classroom)							
	Casework	2nd Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	862	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	48	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	•	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	900	SF	7	10+ years		
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Damaged floor	
	Lighting - Lay-in	2nd Floor	20	EA	7	6-10 years	•	
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	900	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	60	SF	7	10+ years		
	,					, , , , , ,		
Classroo	om #204 (Regular Classroom)							
	Casework	2nd Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	878	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	32	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	910	SF	7	6-10 years		
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years		
	Lighting - Lay-in	2nd Floor	2	EΑ	6	6-10 years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	900	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	60	SF	7	10+ years		
Classroo	om #205 (Regular Classroom)							
	Casework	2nd Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	1,028	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	32	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years		
	Floor - Tile	2nd Floor	1,060	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	24	EA	7	6-10 years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	188	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	950	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	70	SF	7	10+ years		
Classro	om #206 (Regular Classroom)							
UI455100	JIII #200 (Negulai Glassioolii)							



Category : Classroom			В	Building : Main-Academic_Unit B				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Casework	2nd Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	746	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	20	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	756	SF	7	10+ years		
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Damaged floor	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years		
	Marker Board	2nd Floor	16	LF	7	6-10 years		
	Walls - Masonry	2nd Floor	770	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	52	SF	7	10+ years		
Classroo	m #207 (Regular Classroom)							
	Casework	2nd Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	710	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	20	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	g	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	2nd Floor	730	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	15	ĒΑ	7	6-10 years		
	Marker Board	2nd Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	750	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	50	SF	7	10+ years		
Classroo	m #208 (Regular Classroom)							
	Casework	2nd Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	716	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	14	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	Damagea me	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	728	SF	7	10+ years		
	Floor - Tile	2nd Floor	2	SF	4	1-2 years	Damaged floor	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	Damagea neer	
	Marker Board	2nd Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	750	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	50	SF	7	10+ years		
Classroo	m #209 (Regular Classroom)							
	Casework	2nd Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	682	SF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	48	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	Damagod tilo	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years		
						-		



Catego	ory : Classroom	В	Building : Main-Academic_Unit B					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	2nd Floor	730	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years		
	Marker Board	2nd Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	500	SF	7	10+ years		
	Walls - Metal Panel	2nd Floor	250	SF	6	2-5 years	Rough finish on wall	
	Walls - Plaster/Drywall	2nd Floor	50	SF	7	10+ years	-	
_Classroo	om #210 (Regular Classroom)							
	Casework	2nd Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	746	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	20	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	Damagod mo	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years		
	Floor - Tile	2nd Floor	736	SF	6	6-10 years		
	Floor - Tile	2nd Floor	30	SF	4	1-2 years	Damaged floor	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	Damaged 11001	
	Lighting - Lay-in	2nd Floor	3	EA	6	6-10 years		
	Marker Board	2nd Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor		SF				
			520	SF SF	7 7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	52	SF	,	10+ years		
Classroo	om #211 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	1,060	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	1,060	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	22	EA	7	6-10 years		
	Lighting - Lay-in	2nd Floor	2	EA	6	6-10 years	Not working	
	Marker Board	2nd Floor	12	LF	7	6-10 years	-	
	Walls - Concrete Block	2nd Floor	1,186	SF	7	10+ years		
Classroo	om #215 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	830	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years		
	Floor - Concrete	2nd Floor	830	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years		
	Lighting - Lay-in	2nd Floor	6	EΑ	6	6-10 years	Not working	
	Marker Board	2nd Floor	12	LF	7	6-10 years	- · · · · · · · · · · · · · · · · · · ·	
	Walls - Concrete Block	2nd Floor	1,010	SF	7	10+ years		
Classroo	om #216 (Regular Classroom)							
	Casework	2nd Floor	16	LF	7	10+ years		
	Cassimon	2110 1 1001	10	Li	,	ioi youis		



Catego	ry : Classroom		Building : Main-Academic_Unit B				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	746	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	20	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	•
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	700	SF	7	10+ years	
	Floor - Tile	2nd Floor	66	SF	4	1-2 years	Damaged floor
	Lighting - Lay-in	2nd Floor	15	EΑ	6	6-10 years	zamagea nee.
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	770	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	52	SF	7	10+ years	
Classro	om #217 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	710	SF	7 7	10+ years 10+ years	
		2nd Floor 2nd Floor	20	SF SF	4		Damaged tile
	Ceiling - Lay-in					1-2 years	Damaged tile
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	720	SF	7	10+ years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Damaged floor
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	3	EA	6	2-5 years	Not working
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	750	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	50	SF	7	10+ years	
_Classroo	om #218 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	710	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	20	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	g
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	700	SF	7	10+ years	
	Floor - Tile	2nd Floor	30	SF	4	1-2 years	Damaged tile
	Lighting - Lay-in	2nd Floor	13	EA	7	6-10 years	Damaged tile
	Lighting - Lay-in	2nd Floor	2	EA	6	6-10 years	Not working
	Marker Board	2nd Floor	16	LF	7		Not working
						6-10 years	
	Walls - Concrete Block	2nd Floor	750	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	50	SF	7	10+ years	
Classroo	om #219 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	742	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	20	SF	4	1-2 years	Damaged tile



Catego	ry : Classroom	DM Building : Main-Academic_Unit B		t B			
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	720	SF	7	10+ years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Damaged floor
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	750	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	50	SF	7	10+ years	
_Classroo	nm #220 (Regular Classroom)						
	Casework	2nd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	746	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	20	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	2nd Floor	10	SF	7	10+ years	Damagod iiio
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	756	SF	7	10+ years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Damaged floor
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	Damagea noor
	Lighting - Lay-in	2nd Floor	2	EA	6	6-10 years	Not working
	Marker Board	2nd Floor	16	LF	7	6-10 years	Not working
	Walls - Concrete Block	2nd Floor	770	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	52	SF	7	10+ years	
Classroo	om #301 (Science Lab Level 2)						
Classioc	Casework	3rd Floor	176	LF	7	10+ years	
	Casework Ceiling - Lay-in	3rd Floor	1,050	SF	7	10+ years	
	Ceiling - Lay-in Ceiling - Lay-in	3rd Floor	40	SF	, 5	1-2 years	Missing tile
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	wissing the
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	•	
			1		7	10+ years	
	Eye Wash Station	3rd Floor 3rd Floor	1,086	EA	7 7	10+ years 10+ years	
	Floor - Tile Floor - Tile	3rd Floor	1,000	SF SF			Damaged floor
	Gas Line	3rd Floor	7	EA	4 7	1-2 years	Damaged floor
						10+ years	
	Lighting - Lay-in	3rd Floor	24	EA	7	10+ years	
	Marker Board	3rd Floor	14	LF	7	10+ years	
	Science Lab Elements	3rd Floor	1,090	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	905	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	70	SF	7	10+ years	
	Work Sink	3rd Floor	3	EA	7	10+ years	
_Classroo	om #303 (Science Lab Level 2)						
	Casework	3rd Floor	28	LF	7	10+ years	
	Casework	3rd Floor	156	LF	7	10+ years	



Catego	Category : Classroom		В	Building : Main-Academic_Unit B				
			_	Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	3rd Floor	1,024	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	66	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	-	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	1,075	SF	7	10+ years		
	Floor - Tile	3rd Floor	15	SF	4	1-2 years	Damaged floor	
	Gas Line	3rd Floor	9	EA	7	10+ years	ŭ	
	Lighting - Lay-in	3rd Floor	24	EΑ	7	10+ years		
	Marker Board	3rd Floor	14	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	877	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	70	SF	7	10+ years		
	Work Sink	3rd Floor	4	EA	7	10+ years		
01	// // // // // // // // // // // // //							
Classion	om #305 (Science Lab Level 1) Casework	3rd Floor	106	LF	7	10		
			106	LF	7 7	10+ years		
	Casework	3rd Floor	104			10+ years		
	Ceiling - Lay-in	3rd Floor	1,246	SF	7	10+ years		
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Eye Wash Station	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	1,246	SF	7	10+ years		
	Gas Line	3rd Floor	24	EA	7	10+ years		
	Lighting - Lay-in	3rd Floor	28	EA	7	10+ years		
	Marker Board	3rd Floor	14	LF	7	6-10 years		
	Science Lab Elements	3rd Floor	1,246	SF	7	10+ years		
	Science Lab Fume Hood	3rd Floor	1	EA	7	10+ years		
	Walls - Concrete Block	3rd Floor	900	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	86	SF	7	10+ years		
	Work Sink	3rd Floor	12	EA	7	10+ years		
Classroo	om #306 (Science)							
	Casework	3rd Floor	17	LF	7	10+ years		
	Casework	3rd Floor	28	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	726	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	4	SF	4	1-2 years	Damaged tile	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	727	SF	7	10+ years		
	Floor - Tile	3rd Floor	3	SF	4	1-2 years	Damaged tile	
	Gas Line	3rd Floor	4	EA	7	10+ years	zamagoa mo	
	Lighting - Lay-in	3rd Floor	15	EA	7	10+ years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	770	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	60	SF	7	10+ years		
	vvans - i laster/Drywan	314 1 1001	00	OI.	,	10+ years		



Category : Classroom		Building : Main-Academic_Unit B					
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	3rd Floor	2	EA	7	10+ years	
lassroo	m #307A moved from (Other Instruction	al Use)					
	Ceiling - Lay-in	3rd Floor	556	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	556	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	6	6-10 years	Not working
	Marker Board	3rd Floor	20	LF	7	10+ years	G
	Walls - Concrete Block	3rd Floor	680	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	44	SF	7	10+ years	
lassroo	m #308 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	908	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Tile	3rd Floor	878	SF	7	10+ years	
	Floor - Tile	3rd Floor	30	SF	4	1-2 years	Missing tile
	Lighting - Lay-in	3rd Floor	18	EA	7	10+ years	whooling the
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	8	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	870	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	70	SF	7	10+ years	
lassroo	m #310 (Science Lab Level 1)						
	Casework	3rd Floor	58	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,100	SF	7	10+ years	
	Ceiling - Lay in	3rd Floor	20	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years	Damaged tile
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,120	SF	7	•	
	Gas Line	3rd Floor	1,120	EA	7	10+ years 10+ years	
	Lighting - Lay-in	3rd Floor	0 16	EA	7	10+ years 10+ years	
	Marker Board			LF	7 7		
	Science Lab Fume Hood	3rd Floor 3rd Floor	16 1			6-10 years	
			1	EΑ	7	10+ years	
	Science Lab Shower	3rd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,030	SF	7	10+ years	
	Walls - Plaster/Drywall Work Sink	3rd Floor 3rd Floor	84 5	SF EA	7 7	10+ years 10+ years	
		010 1 1001	3	_/\	,	101 youro	
lassroo	m #311 (Regular Classroom)						
	Casework	3rd Floor	25	LF	7	10+ years	



Catego	Category : Classroom			Building : Main-Academic_Unit B					
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	3rd Floor	704	SF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	36	SF	4	1-2 years	Damaged tile		
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	735	SF	7	10+ years			
	Floor - Tile	3rd Floor	5	SF	4	1-2 years	Missing/ damaged tile		
	Lighting - Lay-in	3rd Floor	14	EA	7	6-10 years			
	Lighting - Lay-in	3rd Floor	1	EA	6	6-10 years	Not working		
	Marker Board	3rd Floor	12	LF	7	6-10 years	-		
	Walls - Concrete Block	3rd Floor	1,000	SF	7	10+ years			
	Work Sink	3rd Floor	1	EA	7	2-5 years			
Classroo	om #312 (Other Instructional Use)								
	Casework	3rd Floor	8	LF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	344	SF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	6	SF	4	1-2 years	Damaged tile		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	Barriagoa tilo		
	Floor - Tile	3rd Floor	347	SF	7	10+ years			
	Floor - Tile	3rd Floor	3	SF	4	1-2 years	Damaged tile		
	Lighting - Lay-in	3rd Floor	6	EA	7	10+ years	Damaged tile		
	Marker Board	3rd Floor	5	LF	7	6-10 years			
	Walls - Concrete Block	3rd Floor	618	SF	7	10+ years			
						•			
_Classroc	om #313 (Store Room)								
	Ceiling - Lay-in	3rd Floor	350	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years			
	Floor - Tile	3rd Floor	350	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	6	EA	7	10+ years			
	Marker Board	3rd Floor	8	LF	7	6-10 years			
	Walls - Concrete Block	3rd Floor	620	SF	7	10+ years			
_Classroo	om #315 (Science Lab Level 1)								
	Casework	3rd Floor	58	LF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	1,120	SF	7	10+ years			
	Doors - Side-lite	3rd Floor	20	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years			
	Eye Wash Station	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	1,120	SF	7	10+ years			
	Gas Line	3rd Floor	, 8	ĒΑ	7	10+ years			
	Lighting - Lay-in	3rd Floor	16	EA	7	10+ years			
	Marker Board	3rd Floor	16	LF	7	6-10 years			
	Science Lab Fume Hood	3rd Floor	1	EΑ	7	10+ years			
	Science Lab Shower	3rd Floor	1	EΑ	7	10+ years			
						,			



Category : Classroom			В	Building : Main-Academic_Unit B				
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	3rd Floor	1,030	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	84	SF	7	10+ years		
	Work Sink	3rd Floor	5	EA	7	10+ years		
Classroo	om #316 (Regular Classroom)							
<u> </u>	Casework	3rd Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	754	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	12	SF	4	1-2 years	Damaged tile	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	Damaged tile	
	Doors - Side-lite	3rd Floor	10	SF	7	,		
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years		
						10+ years		
	Floor - Tile	3rd Floor	766	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	10	EA	7	10+ years	No. of the second secon	
	Lighting - Lay-in	3rd Floor	5	EA	6	6-10 years	Not working	
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	770	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	52	SF	7	10+ years		
Classroo	om #317 (Regular Classroom)							
	Casework	3rd Floor	16	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	720	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	10	SF	4	1-2 years	Damaged tile	
	Chalk Board	3rd Floor	24	ĹF	4	2-5 years	3	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	3rd Floor	725	SF	7	10+ years		
	Floor - Tile	3rd Floor	5	SF	4	1-2 years	Damaged floor	
	Lighting - Lay-in	3rd Floor	2	EA	7	2-5 years	Not working	
	Lighting - Lay-in	3rd Floor	13	EΑ	7	10+ years	Ttot Working	
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	750	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	50	SF	7	10+ years		
Classroo	om #318 (Regular Classroom)							
CIGGGIOU	Casework	3rd Floor	16	LF	6	10+ years		
		3rd Floor 3rd Floor		SF				
	Ceiling - Lay-in		710		7	10+ years	Demograd spiling	
	Ceiling - Lay-in	3rd Floor	20	SF	4	1-2 years	Damaged ceiling	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	700	SF	7	10+ years		
	Floor - Tile	3rd Floor	30	SF	4	1-2 years	Damaged missing floor	
	Lighting - Lay-in	3rd Floor	13	EA	7	10+ years		
	Lighting - Lay-in	3rd Floor	2	EA	6	6-10 years		



Catego	ry : Classroom	В	uilding	: Main-	Academic_Unit	: B	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	750	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	50	SF	7	10+ years	
Classroo	om #319 (Regular Classroom)						
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	730	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years	
	Floor - Tile	3rd Floor	728	SF	7	10+ years	
	Floor - Tile	3rd Floor	2	SF	4	1-2 years	Damaged floor
	Lighting - Lay-in	3rd Floor	_ 15	EA	6	10+ years	zamagoa noo.
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	500	SF	7	10+ years	
	Walls - Metal Panel	3rd Floor	250	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	50	SF	7	10+ years	
	walls - i laster/brywall	314 1 1001	30	OI.	,	10+ years	
Classroo	om #320 (Regular Classroom)						
	Casework	3rd Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	746	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	20	SF	4	1-2 years	Damaged ceiling
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	746	SF	7	10+ years	
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Damaged flooring
	Lighting - Lay-in	3rd Floor	14	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	1	EA	6	2-5 years	Not working
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	520	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	52	SF	7	10+ years	
Classroo	om #321 (Science Lab Level 1)						
	Casework	3rd Floor	144	LF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,366	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	24	SF	4	1-2 years	Damaged tile
	Doors - Side-lite	3rd Floor	20	SF	7	10+ years	agoao
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Eye Wash Station	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,390	SF	7	10+ years	
	Gas Line	3rd Floor	22	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	23	EA	7	10+ years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Markor Board	014 1 1001	10	Li	,	o io years	



Catego	ory : Classroom	В	Building : Main-Academic_Unit B					
	,					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Science Lab Elements	3rd Floor	1,390	SF	7	10+ years		
	Science Lab Fume Hood	3rd Floor	1	ĒΑ	7	10+ years		
	Science Lab Shower	3rd Floor	1	ΕA	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,220	SF	7	10+ years		
	Work Sink	3rd Floor	11	EA	7	10+ years		
Classro	om #322 (Computer Lab)							
Classio	• •	01 []	40			40		
	Casework	3rd Floor	18	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	870	SF	7	10+ years		
	Doors - Side-lite	3rd Floor	82	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years		
	Floor - Tile	3rd Floor	850	SF	7	10+ years		
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Damaged floor	
	Lighting - Lay-in	3rd Floor	20	EA	5	0-1 year	Lighting switch box loose at wall	
	Marker Board	3rd Floor	10	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	430	SF	7	10+ years		
	Walls - Metal Panel	3rd Floor	250	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	250	SF	7	10+ years		
	Wireless System	3rd Floor	1	EA	7	10+ years		
Classroo	om #323 (Computer Lab)							
	Casework	3rd Floor	18	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	870	SF	7	10+ years		
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	860	SF	7	10+ years		
	Floor - Tile	3rd Floor	10	SF	4	1-2 years	Damaged floor	
		3rd Floor	20	EA	7		Damaged 11001	
	Lighting - Lay-in	3rd Floor		LF	7	10+ years		
	Marker Board		10			6-10 years		
	Walls - Concrete Block	3rd Floor	200	SF	7	10+ years		
	Walls - Metal Panel	3rd Floor	250	SF	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	480	SF	7	10+ years		
Classroo	om #324 (Science Lab Level 1)							
	Casework	3rd Floor	152	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	1,410	SF	7	10+ years		
	Doors - Side-lite	3rd Floor	20	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years		
	Eye Wash Station	3rd Floor	1	EΑ	7	10+ years		
	Floor - Tile/Sheet	3rd Floor	1,410	SF	7	10+ years		
	Gas Line	3rd Floor	21	EA	7	10+ years		
	Lighting - Lay-in	3rd Floor	22	EA	7	6-10 years		
	Marker Board	3rd Floor	10	LF	7	6-10 years		
	aa. Baila	014 1 1001	10		•	o lo youlo		



Catego	ry : Classroom	В	Building : Main-Academic_Unit B					
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Science Lab Fume Hood	3rd Floor	2	EΑ	7	10+ years		
	Science Lab Shower	3rd Floor	1	EΑ	7	10+ years		
	Walls - Plaster/Drywall	3rd Floor	1,206	SF	7	10+ years		
	Work Sink	3rd Floor	11	EA	7	10+ years		
Classroo	om #325 (Science Classroom)							
	Casework	3rd Floor	84	LF	7	10+ years		
	Casework	3rd Floor	81	LF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	1,310	SF	7	10+ years		
	Ceiling - Lay-in	3rd Floor	4	SF	5	1-2 years	Water damage	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	· ·	
	Floor - Tile	3rd Floor	1,314	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	21	EA	7	10+ years		
	Marker Board	3rd Floor	14	LF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	1,180	SF	7	10+ years		
	Work Sink	3rd Floor	3	EA	7	10+ years		

Category: Interior Building: Main-Academic_Unit B

_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	First Floor Corridors	6,841	SF	7	10+ years	
	Ceiling - Lay-in	First Floor Corridors	607	SF	7	10+ years	
	Ceiling - Lay-in	First Floor Corridors	32	SF	5	1-2 years	Damaged tile
	Doors - Wood Doors include hw	First Floor Corridors	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	First Floor Corridors	2	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	First Floor Corridors	2	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	First Floor Corridors	275	SF	7	10+ years	
	Floor - Tile/Sheet	First Floor Corridors	7,173	SF	7	10+ years	
	Lighting - Lay-in	First Floor Corridors	57	EA	7	6-10 years	
	Student Lockers - One Tier	First Floor Corridors	325	EA	7	10+ years	
	Student Lockers - Two Tiers	First Floor Corridors	12	EA	7	10+ years	
	Walls - Concrete Block	First Floor Corridors	6,365	SF	7	10+ years	
	Walls - Plaster/Drywall	First Floor Corridors	602	SF	7	10+ years	
	Ceiling - Lay-in	Second Floor Corridors	7,038	SF	7	10+ years	
	Doors - Steel Doors incl hw	Second Floor Corridors	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	Second Floor Corridors	3	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	Second Floor Corridors	1	EA	7	6-10 years	
	Floor - Tile/Sheet	Second Floor Corridors	7,038	SF	7	10+ years	
	Lighting - Lay-in	Second Floor Corridors	52	EA	7	6-10 years	
	Student Lockers - One Tier	Second Floor Corridors	338	EA	7	10+ years	
	Student Lockers - Two Tiers	Second Floor Corridors	12	EA	7	10+ years	
	Walls - Concrete Block	Second Floor Corridors	6,063	SF	7	10+ years	
	Walls - Plaster/Drywall	Second Floor Corridors	748	SF	7	10+ years	



Catego	Category : Interior			Building : Main-Academic_Unit B					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Lay-in	Third Floor Corridors	6,234	SF	7	10+ years			
	Drinking Fountains - Single Fountain	Third Floor Corridors	3	EA	7	6-10 years			
	Drinking Fountains - Single Water Cooler	Third Floor Corridors	1	EA	7	6-10 years			
	Floor - Tile/Sheet	Third Floor Corridors	6,234	SF	7	10+ years			
	Lighting - Lay-in	Third Floor Corridors	46	EA	7	6-10 years			
	Student Lockers - One Tier	Third Floor Corridors	353	EA	7	10+ years			
	Student Lockers - Two Tiers	Third Floor Corridors	10	EA	7	10+ years			
	Walls - Concrete Block	Third Floor Corridors	4,488	SF	7	10+ years			
	Walls - Plaster/Drywall	Third Floor Corridors	852	SF	7	10+ years			
Safety									
•	Camera Viewing Station	Entire Campus	3	EA	7	6-10 years			
	Camera Viewing Station	Entire Campus	2	EA	7	6-10 years			
	Security Cameras	Entire Campus	7	EA	7	6-10 years			
	Security Cameras	Entire Campus	12	EA	7	6-10 years			
	Security Cameras	Entire Campus	16	EA	7	6-10 years			
	Security Cameras	Entire Campus	2	EA	7	6-10 years			
Stairs									
	Ceiling - Exposed	North East	123	SF	7	10+ years			
	Ceiling - Lay-in	North East	789	SF	7	10+ years			
	Floor - Terrazzo	North East	220	SF	7	10+ years			
	Floor - Tile	North East	505	SF	7	10+ years			
	Handrails	North East	131	LF	7	10+ years			
	Lighting - Lay-in	North East	4	EA	7	6-10 years			
	Lighting - Pendent/Surface	North East	1	EA	7	6-10 years			
	Lighting - Wall Mounted	North East	1	EA	7	6-10 years			
	Stairs - Terrazzo	North East	280	LF	7	10+ years			
	Walls - Concrete Block	North East	2,225	SF	7	10+ years			
	Ceiling - Exposed	North West	123	SF	7	10+ years			
	Ceiling - Lay-in	North West	789	SF	7	10+ years			
	Floor - Terrazzo	North West	220	SF	7	10+ years			
	Floor - Tile/Sheet	North West	505	SF	7	10+ years			
	Handrails	North West	131	LF	7	10+ years			
	Lighting - Lay-in	North West	4	EA	7	6-10 years			
	Lighting - Pendent/Surface	North West	1	EA	7	6-10 years			
	Lighting - Wall Mounted	North West	3	EA	7	6-10 years			
	Stairs - Terrazzo	North West	280	LF	7	10+ years			
	Walls - Concrete Block	North West	2,225	SF	7	10+ years			
	Ceiling - Exposed	South East	123	SF	7	10+ years			
	Ceiling - Exposed Ceiling - Lay-in	South East	789	SF SF	7	•			
	Floor - Terrazzo		220	SF SF	7	10+ years			
	Floor - Tile	South East		SF SF		10+ years			
		South East	505	SF LF	7	10+ years			
	Handrails	South East	131	ᄕ	7	10+ years			



Catego	ry : Interior		Building : Main-Academic_Unit B				
_			Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	South East	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	South East	1	EA	7	6-10 years	
	Stairs - Terrazzo	South East	280	LF	7	10+ years	
	Walls - Concrete Block	South East	2,225	SF	7	10+ years	
	Ceiling - Exposed	South West	123	SF	7	10+ years	
	Ceiling - Lay-in	South West	789	SF	7	10+ years	
	Floor - Terrazzo	South West	229	SF	7	10+ years	
	Floor - Tile	South West	505	SF	7	10+ years	
	Handrails	South West	10	LF	7	10+ years	
	Handrails	South West	121	LF	7	10+ years	
	Lighting - Lay-in	South West	4	EA	7	6-10 years	
	Lighting - Pendent/Surface	South West	1	EA	7	6-10 years	
	Stairs - Terrazzo	South West	280	LF	7	10+ years	
	Walls - Concrete Block	South West	2,225	SF	7	10+ years	
	Handrails	in Media Center 160	80	LF	7	10+ years	
	Stairs - Concrete	in Media Center 160	66	LF	7	10+ years	
_Vertical	Conveyance						
	Elevator - Hydraulic Elevator	2nd Floor	1	EA	7	10+ years	

Campus Name: Kenwood HS Page : 43 of 115 Assessment Date: 07/08/2024



Category : Exterior Building : Addition-Lunchroom_Unit D

Catego	ry : Exterior		В	uilding	: Addıtı	Building : Addition-Lunchroom_Unit D						
_						Recommend						
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments					
ntrance												
	Exterior Doors - Exterior FRP Door	10	2	EA	6	10+ years						
	Exterior Doors - Transom Lite	10	1	EA	6	10+ years						
	Exterior Doors - Exterior FRP Door	11	2	EA	6	10+ years						
	Exterior Doors - Transom Lite	11	1	EA	6	10+ years						
	Exterior Doors - Exterior FRP Door	12	1	EA	6	10+ years						
	Exterior Doors - Side lite	12	10	EA	6	10+ years						
	Exterior Doors - Transom Lite	12	1	EA	6	10+ years						
	Exterior Doors - Exterior Steel Door	12.1 - Yard Storage 1	1	EA	5	2-5 years						
	Exterior Doors - Overhead Rolling/ Garage	12.2 - Yard Storage 2 OVH	2	EA	5	2-5 years						
	Door	•				•						
	Exterior Doors - Exterior FRP Door	13	1	EA	6	10+ years						
	Exterior Doors - Transom Lite	13	1	EA	6	10+ years						
	Exterior Doors - Exterior Steel Door	14	2	EA	7	10+ years						
	Exterior Doors - Overhead Rolling/ Garage	14. 1 - Transformer Vault OVH	1	EA	6	10+ years						
	Door					,						
	Exterior Doors - Exterior Steel Door	15	1	EA	6	10+ years						
	Exterior Doors - Transom Lite	15	1	EΑ	6	10+ years						
	Exterior Doors - Exterior FRP Door	16	2	EA	6	10+ years						
	Exterior Doors - Transom Lite	16	2	ĒΑ	6	10+ years						
	Exterior Doors - Overhead Rolling/ Garage	17 - OVH	1	EA	5	2-5 years	Corrosion					
	Door		•		•	,						
	Exterior Doors - Exterior FRP Door	18 - Storage Man Door	1	EA	6	10+ years						
			•		-	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						
oundati	on											
- COLINGIAN	Foundation - Concrete	Entire Building	824	LF	7	10+ years						
	Superstructure - Metal Deck/ Concrete	Entire Building	36,736	SF	7	10+ years						
	Topping	Entire Ballating	30,730	Oi	,	101 yours						
	Торріпід											
ahtina												
giinig	Exterior Lighting - Parapet or Roof Mounted	Entire Building	8	EA	7	10+ years						
	Exterior Lighting - Wall Mounted	Entire Building	51	EA	6	10+ years						
	Extends Eighting Trail Wealted	Zitalo Ballallig	0.	_, `	Ü	ioi youlo						
oof Sys	stem											
,	Access Ladder - Metal	Н	1	EA	7	10+ years						
	Coping - Metal	Н	756	LF	6	10+ years						
	Downspouts - Interior Downspouts	H	450	LF	5	2-5 years						
	Parapet - Parapet < 16" Height	Н	756	LF	6	10+ years						
	Roof - Modified Bitumen	Н	19,672	SF	6	6-10 years						
	Roof - Modified Bitumen	H	600	SF	4	1-2 years	Bubbling, soft spots					
	Roof Hatch - Metal	H	1	EA	7	10+ years	g, con opolo					
	Roof Structure - Steel / Metal Deck/	H	20,272	SF	7	10+ years						
		• •	,	•	•	,						



Category : Exterior

Kenwood Academy High School 5015 S Blackstone AVENUE, Chicago, IL 60615

Building : Addition-Lunchroom_Unit D

oalogo	Ty . Exterior			ananig	. Additi	on Lanom com	_01111112
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Concrete Topping		,				
Valls							
valis	Exterior Walls - Brick	Entire Building	9,420	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	7,058	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	10	SF	4	1-2 years	Chipped, spalling
	Exterior Walls - Wood Siding	Entire Building	430	SF	6	10+ years	3
Vindows	S						
	Lintels - Concrete	Entire Building	452	LF	6	10+ years	
	Lintels - Steel	Entire Building	112	LF	6	10+ years	
	Windows - Casement Aluminum Double- pane	Entire Building	3,666	SF	6	10+ years	
	Windows - Louver	Entire Building	306	SF	6	10+ years	
atego	ry : Electrical		В	uildina	: Additi	on-Lunchroom	Unit D
				_		Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
merger	ncy System						
	Automatic Transfer Switch	Electrical Room	2	EA	6	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	Rank adjusted based on current observations that no exit signs nee to be added or moved.
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations. Rank adjusted base on current observations that no exi signs need to be added or moved.
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,644	SF	6	6-10 years	J
	Emergency A/C Power - Lunchrooms	Entire Building	7,875	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	895	SF	6	6-10 years	
	Security System - CCTV	Entire Building	36,736	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	36,736	SF	6	6-10 years	
	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW	Site South	1	EA	6	6-10 years	Serves Bldgs. A, B, C and D. No CPS Asset Tag present.
lain Se	rvice						
	Main Electrical Service - 2001 to 3000 A 277/480/3PH	Electrical Room	1	EA	6	6-10 years	Upgraded in 2020. Rank, Reason and Priority Rep adjusted based or current observations and per reviewith Building Engineer that the



Kenwood Academy High School

ALL I	Schools					5015	S Blackstone AVENUE, Chicago, IL 60615
Catego	ry : Electrical		В	uilding	: Addition	on-Lunchroom	_Unit D
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							disturbances or excessive wear.
	PA System	Entire Building	36,736	SF	5	6-10 years	Served by Bldg. B.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	Quantity changed to match current observations.
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	Quantity changed as total has been divided/aggregated.
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Less than 400	Entire Building	2	EA	7	10+ years	
	amp Transformers - 277/480 - 120/208	Entire Building	4	EA	7	10+ years	Quantity changed to match current
							observations and as the total has been divided/aggregated.
Catego	ry : Fire Protection		В	uilding	: Additi	on-Lunchroom	_Unit D
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	36,736	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	36,736	SF	6	6-10 years	FACP is in Bldg. B.
Catego	ry : Mechanical		В	uilding	: Addition	on-Lunchroom	_Unit D
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	litioning						
	Pipes - Chilled Water Pipe- Steel	Entire Building	300	LF	6	6-10 years	
ir Hand	ling Systems						
	Indoor Return Fans- Centrifugal Squirrel	Mechanical Room	1	EA	6	6-10 years	Associated with AHU-12
	Cage - 5000 - 10000 CFM						
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Mechanical Room	1	EA	6	6-10 years	Associated with AHU-13
	Air Handling Unit- Package Multi Zone-	Mechanical Room - AHU-12	1	EA	6	6-10 years	AHU-12. No CPS Asset Tag preser
	Indoor- Steam Coil and Chilled Water Coils - Less than 6000 cfm						
	Air Intake	Mechanical Room - AHU-12	1	EA	6	6-10 years	
	Zone Dampers	Mechanical Room - AHU-12	6	EA	6	6-10 years	
	Air Handling Unit- Package Multi Zone-	Mechanical Room - AHU-13	1	EA	6	6-10 years	AHU-13. No CPS Asset Tag preser
	Indoor- Steam Coil and Chilled Water Coils - 6000-10000 cfm	INICONANIICAI NOON - ANO-13	ı	EA	Ü	0-10 years	ALIO-13. NO OF 3 ASSEL TAY PIESEL



Category : Mechanical				Building : Addition-Lunchroom_Unit D					
Oalcgo	i y . iniconamicai			unung	. Additi	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Air Intake	Mechanical Room - AHU-13	1	EΑ	6	6-10 years			
	Zone Dampers	Mechanical Room - AHU-13	5	EA	6	6-10 years			
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coil and Chilled Water Coils - 15001-20000 cfm	Mechanical Room - AHU-14	1	EA	6	6-10 years	AHU-14. No CPS Asset Tag present.		
	Air Intake	Mechanical Room - AHU-14	1	EA	6	6-10 years			
	Zone Dampers	Mechanical Room - AHU-14	3	EA	6	6-10 years			
Boiler Sy	vstems								
	Condensate Pump	Entire Building	1	EA	4	2-5 years	No CPS Asset Tag present. Pump is deteriorated and is approaching the end of its anticipated service life.		
	Piping - Condensate Pipe- Steel	Entire Building	200	LF	5	10+ years			
	Piping - Steam Pipe- Steel	Entire Building	200	LF	5	10+ years			
	Steam Traps	Entire Building	25	EA	6	6-10 years	Quantity changed as total has been divided/aggregated. Rank adjusted as steam traps have been upgraded since previous assessment.		
Heat Exc									
	Heat Exchanger - Steam to Hot Water Shell Type	Mechanical Room	1	EA	5	6-10 years	No CPS Asset Tag present.		
	Heat Exchanger - Steam to Hot Water Shell Type	Mechanical Room	1	EA	5	6-10 years	No CPS Asset Tag present.		
Heating	Devices								
ŭ	Cabinet Heaters - With Hot Water Coil	1st Floor	1	EA	5	6-10 years			
	Fin Tube - Hot Water	Entire Building	30	LF	6	6-10 years	Rank, Reason and Priority Rep changed as all leaks have been repaired since previous assessment.		
	Unit Heater - Steam	Entire Building	1	EA	5	6-10 years			
	Unit Heater - Steam	Entire Building	2	EA	5	6-10 years	Misdocumented in previous assessment. Quantity changed to match current observations that there are two unit heaters in Mechanical Room.		
Mechani	cal Plumbing								
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	10+ years			
	Hot Water Pump - 10 - 20 HP	Mechanical Room	1	EA	5	6-10 years	No CPS Asset Tag present.		
	Hot Water Pump - 10 - 20 HP	Mechanical Room	1	EA	5	6-10 years	No CPS Asset Tag present.		
Tempera	ature Control								



Kenwood Academy High School

ATT.	Public Schools						OOD ACADEMY HIGH SCHOO S Blackstone AVENUE, Chicago, IL 6061			
Catego	ory : Mechanical		Building : Addition-Lunchroom_Unit D							
				Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	DDC System	Entire Building	36,736	SF	6	10+ years				
	Electric Thermostat	Entire Building	4	EA	5	6-10 years				
	Thermostats - DDC	Entire Building	17	EA	7	10+ years				
Ventilati	on									
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	2	EA	5	6-10 years				
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	5	6-10 years				
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	3	0-1 year	Unit is nonfunctional awaiting replacement.			
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	6	6-10 years	Rank adjusted based on current observations and per review with Building Engineer.			
	Roof Mounted Duct Work	Entire Building	20	LF	5	6-10 years	Ductwork is fully intact although it shows signs of age-related degradation.			
	Type II Exhaust Hood- Warming Kitchen	Entire Building	5	EA	5	10+ years	Quantity changed to match current observations.			
Catego	ry : Plumbing		В	uilding	: Additi	on-Lunchroom	_Unit D			
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Hot Wat	er									
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room	2	EA	7	10+ years	Rank, Reason and Priority Rep changed as the water heaters have been replaced since previous			

						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Hot Wate	er						
	Gas Heater - 300001 - 600000 BTU/HR	Mechanical Room	2	EA	7	10+ years	Rank, Reason and Priority Rep changed as the water heaters have been replaced since previous assessment.
	Hot Water Storage Tank_Gas - 501 - 1000 Gallons	Mechanical Room	1	EA	6	6-10 years	Rank adjusted based on current observations that only minor insulation damage is present.
_Piping							
. •	Domestic Piping-Hot Water Return Lines	Entire Building	36,736	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	36,736	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	36,736	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	36,736	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	36,736	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	36,736	SF	6	10+ years	
	Sanitary Piping	Entire Building	36,736	SF	6	10+ years	



Catego	ry : Plumbing		Ві	uilding	: Addition	on-Lunchroom	_Unit D
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storm Piping	Entire Building	36,736	SF	6	6-10 years	
	Vent Piping	Entire Building	36,736	SF	6	6-10 years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	10+ years	Serves Bldgs. A, B, C and D. No CPS Asset Tag present.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Elevator pit sump pump. Not accessible at the time of assessment. No CPS Asset Tag available. Condition verified by Building Engineer. Location changed for clarification.

Category : Room Building · Addition-Lunchroom Unit D

Category: Room			Building : Addition-Lunchroom_Unit D					
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
•		Location	Quantity	OOW	Italik	Replacement	Comments	
aminist	trative Suites/Offices							
	Ceiling - Splined	1st Floor - Key Room	315	SF	7	10+ years		
	Ceiling - Splined	1st Floor - Key Room	15	SF	4	1-2 years	Damaged tile	
	Doors - Wood Doors inclu hw	1st Floor - Key Room	1	EA	7	10+ years		
	Floor - Tile	1st Floor - Key Room	230	SF	7	10+ years		
	Floor - Tile	1st Floor - Key Room	100	SF	4	1-2 years	Missing tile	
	Lighting - Lay-in	1st Floor - Key Room	7	EΑ	6	6-10 years		
	Lighting - Lay-in	1st Floor - Key Room	1	EA	5	1-2 years	Missing cover	
	Power Distribution	1st Floor - Key Room	12	EA	7	10+ years		
	Storage/ Closet	1st Floor - Key Room	122	SF	7	10+ years		
	Walls - Concrete Block	1st Floor - Key Room	770	SF	7	10+ years		
	Work SInk	1st Floor - Key Room	1	EΑ	7	10+ years		
	Ceiling - Splined	1st Floor Engineer's Office	229	SF	7	10+ years		
	Ceiling - Splined	1st Floor Engineer's Office	7	SF	5	1-2 years	Missing tile	
	Doors - Wood Doors inclu hw	1st Floor Engineer's Office	2	EA	7	10+ years	•	
	Floor - Tile	1st Floor Engineer's Office	236	SF	7	10+ years		
	Lighting - Lay-in	1st Floor Engineer's Office	5	EA	7	6-10 years		
	Power Distribution	1st Floor Engineer's Office	6	EA	7	10+ years		
	Walls - Concrete Block	1st Floor Engineer's Office	450	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor Old Engineer's Office (now Shipping Office)	101	SF	6	6-10 years		
	Ceiling - Lay-in	1st Floor Old Engineer's Office (now Shipping Office)	25	SF	4	1-2 years	Aging tile	
	Doors - Wood Doors inclu hw	1st Floor Old Engineer's Office (now Shipping Office)	2	EA	7	10+ years		
	Floor - Tile	1st Floor Old Engineer's Office (now Shipping Office)	126	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor Old Engineer's Office (now	2	EA	7	6-10 years		

Campus Name: Kenwood HS Page: 49 of 115 Assessment Date: 07/08/2024



Category : Room		Building : Addition-Lunchroom_Unit D					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	D. Division	Shipping Office)	ā	- ^	_	40	
	Power Distribution	1st Floor Old Engineer's Office (now Shipping Office)	4	EA	7	10+ years	
	Storage/ Closet	1st Floor Old Engineer's Office (now	12	SF	7	10+ years	
	Storage/ Gloset	Shipping Office)	12	OI.	,	10+ years	
	Walls - Concrete Block	1st Floor Old Engineer's Office (now	300	SF	7	10+ years	
	774	Shipping Office)		О.	•	. o . y ca. c	
	Ceiling - Splined	In 223	186	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In 223	1	EA	7	10+ years	
	Floor - Tile	In 223	174	SF	7	10+ years	
	Floor - Tile	In 223	12	SF	4	1-2 years	To many items covering to verify,
					_		missing tiles in previous assessment
	Lighting - Pendent/Surface	In 223	2	EA	7	6-10 years	
	Power Distribution	In 223	8	EA	7	10+ years	
	Walls - Concrete Block	In 223 In 223	430	SF	7	10+ years	
	Work Sink	Kitchen	1 108	EA SF	7 6	10+ years	
	Ceiling - Splined Doors - Side-lite	Kitchen	30	SF SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen	1	EA	7	10+ years 10+ years	
	Floor - Tile	Kitchen	108	SF	7	10+ years	
	Lighting - Lay-in	Kitchen	2	EA	7	6-10 years	
	Power Distribution	Kitchen	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	Kitchen	330	SF	7	10+ years	
						, , , , , ,	
Kitchen							
	Ceiling - Splined	269- Servery	564	SF	7	10+ years	
	Doors - Wood Doors inclu hw	269- Servery	4	EA	7	10+ years	
	Floor - Tile Quarry	269- Servery	564	SF	7	10+ years	
	Lighting - Lay-in	269- Servery	8	EA	7	6-10 years	
	Serving Line	269- Servery	42	LF	7	10+ years	
	Walls - Structural Glazed Tile	269- Servery	1,050	SF	7	10+ years	
	Ceiling - Splined	270 - Servery	556	SF	7	10+ years	
	Ceiling - Splined	270 - Servery	8	SF	5	1-2 years	Missing tile
	Doors - Wood Doors inclu hw	270 - Servery	4	EA	7	10+ years	
	Floor - Tile Quarry	270 - Servery	564	SF	7	10+ years	
	Lighting - Lay-in	270 - Servery	6	EΑ	7	6-10 years	N. d
	Lighting - Lay-in	270 - Servery	2	EA	6	6-10 years	Not working
	Serving Line	270 - Servery	42	LF	7	10+ years	
	Walls - Structural Glazed Tile	270 - Servery	1,050	SF	7	10+ years	
	Ceiling - Splined	274	1,790	SF	7	10+ years	
	Doors - Steel Doors incl hw	274	1	EΑ	7	10+ years	
	Doors - Wood Doors inclu hw	274	3	EΑ	7	10+ years	Draken from himner
	Doors - Wood Doors inclu hw	274	1 700	EA	5	1-2 years	Broken from hinges
	Floor - Tile Quarry	274	1,790	SF	7	10+ years	



Catego	Building : Addition-Lunchroom_Unit D						
Guiogo	. ,		_	uug	7100111	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Lighting - Lay-in	274	40	EA	7	6-10 years	
	Storage/ Closet	274	201	SF	7	10+ years	
	Walls - Structural Glazed Tile	274	1,600	SF	7	10+ years	
	Ceiling - Splined	274 - Canteen	275	SF	7	10+ years	
	Doors - Wood Doors inclu hw	274 - Canteen	1	EA	7	10+ years	
	Floor - Tile Quarry	274 - Canteen	275	SF	7	10+ years	
	Lighting - Lay-in	274 - Canteen	5	ĒΑ	7	6-10 years	
	Walls - Structural Glazed Tile	274 - Canteen	585	SF	7	10+ years	
	Ceiling - Splined	274 - Dishwashing	265	SF	7	10+ years	
	Ceiling - Splined	274 - Dishwashing	10	SF	4	1-2 years	Damaged ceiling
	Doors - Wood Doors inclu hw	274 - Dishwashing	1	ĒΑ	5	1-2 years	Door detached from hinge
	Floor - Tile Quarry	274 - Dishwashing	275	SF	7	10+ years	2 001 001001100 110111 11111 190
	Lighting - Lay-in	274 - Dishwashing	2	ĒΑ	7	6-10 years	
	Lighting - Lay-in	274 - Dishwashing	3	EΑ	6	6-10 years	Not working
	Walls - Structural Glazed Tile	274 - Dishwashing	585	SF	7	10+ years	. ret ireng
	Trans Structural Glazes The	27 7 Bionwaeming	000	O.	•	io. youro	
Lunch &	Multipurpose Room						
	Ceiling - Splined	265 - Faculty	660	SF	7	10+ years	
	Doors - Wood Doors inclu hw	265 - Faculty	2	EΑ	7	10+ years	
	Floor - Tile	265 - Faculty	660	SF	7	10+ years	
	Lighting - Lay-in	265 - Faculty	10	EΑ	7	6-10 years	
	Lighting - Lay-in	265 - Faculty	2	EΑ	6	6-10 years	Not working
	Storage/ Closet	265 - Faculty	12	SF	7	10+ years	-
	Walls - Concrete Block	265 - Faculty	440	SF	7	10+ years	
	Walls - Metal Panel	265 - Faculty	188	SF	7	10+ years	
	Ceiling - Splined	267	7,310	SF	7	10+ years	
	Ceiling - Splined	267	10	SF	4	1-2 years	Loose tile
	Doors - Wood Doors inclu hw	267	10	EA	7	10+ years	
	Floor - Tile	267	7,320	SF	7	10+ years	
	Lighting - Lay-in	267	184	EA	7	6-10 years	
	Serving Line	267	24	LF	7	10+ years	
	Walls - Concrete Block	267	2,340	SF	7	10+ years	
	Walls - Metal Panel	267	300	SF	7	10+ years	
_iviechani	ical/ Service Rooms	Ant Elean	2.4	0=		40	
	Janitor's Closet	1st Floor	34	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	88	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	174	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	2,135	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	268	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	148	SF	7	10+ years	
	Storage Room	1st Floor	325	SF	7	10+ years	
	Storage Room	1st Floor	1,495	SF	7	10+ years	
	Storage Room	1st Floor	128	SF	7	10+ years	



Catego	ry : Room	Building : Addition-Lunchroom_Unit D					
Jaiego	y . IXOOIII		ь				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Oroup	Storage Room	1st Floor	220	SF	7	10+ years	Comments
	Storage Room	1st Floor	385	SF	7	10+ years	
	Vaults	1st Floor	550	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	101	SF	7	10+ years	
	Storage Room	2nd Floor	101	SF	7	•	
	Storage Room	2110 F1001	10	SF	,	10+ years	
Dootroon	_						
Restroon	Accessories	1at Floor Engineer's Toilet Boom	4.4	SF	7	6.10 veers	
		1st Floor Engineer's Toilet Room	44		7	6-10 years	
	Ceiling - Splined	1st Floor Engineer's Toilet Room	42	SF	7	10+ years	Mississatile
	Ceiling - Splined	1st Floor Engineer's Toilet Room	2	SF	5	0-1 year	Missing tile
	Doors - Wood Doors inclu hw	1st Floor Engineer's Toilet Room	2	EA	7	10+ years	
	Floor - Tile	1st Floor Engineer's Toilet Room	44	SF	7	10+ years	
	Lavatory	1st Floor Engineer's Toilet Room	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor Engineer's Toilet Room	1	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor Engineer's Toilet Room	1	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor Engineer's Toilet Room	3	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Engineer's Toilet Room	230	SF	7	10+ years	
	Water Closet	1st Floor Engineer's Toilet Room	1	EA	7	10+ years	
	Accessories	1st Floor Men Janitors	262	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor Men Janitors	62	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor Men Janitors	200	SF	4	1-2 years	Water damaged tile
	Doors - Wood Doors inclu hw	1st Floor Men Janitors	2	EA	7	10+ years	
	Floor - Tile	1st Floor Men Janitors	190	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Men Janitors	63	SF	6	10+ years	
	Floor Drain	1st Floor Men Janitors	1	EA	7	10+ years	
	Lavatory	1st Floor Men Janitors	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor Men Janitors	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor Men Janitors	1	EA	7	6-10 years	
	Showers	1st Floor Men Janitors	1	ĒΑ	7	10+ years	
	Student Lockers - One Tier	1st Floor Men Janitors	17	EA	7	10+ years	
	Urinals	1st Floor Men Janitors	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Men Janitors	818	SF	7	10+ years	
	Water Closet	1st Floor Men Janitors	1	EA	7	10+ years	
	Accessories	1st Floor Mens in Service Corridor	32	SF	7	6-10 years	
	Ceiling - Splined	1st Floor Mens in Service Corridor	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Mens in Service Corridor	1	EA	7	10+ years	
	Floor - Tile	1st Floor Mens in Service Corridor	32	SF	4	•	Domogod flooring
						1-2 years	Damaged flooring
	Lavatory	1st Floor Mens in Service Corridor	1	EΑ	6	6-10 years	
	Lighting - Wall Mounted	1st Floor Mens in Service Corridor	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Mens in Service Corridor	150	SF	7	10+ years	
	Water Closet	1st Floor Mens in Service Corridor	1	EA	7	10+ years	
	Accessories	1st Floor SW in Service Corridor	183	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor SW in Service Corridor	83	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor SW in Service Corridor	100	SF	4	1-2 years	Damaged ceiling tile



Catego	ry : Room		В	uilding	: Additi	on-Lunchroom	_Unit D
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor SW in Service Corridor	2	EA	6	10+ years	
	Floor - Tile	1st Floor SW in Service Corridor	33	SF	6	10+ years	
	Floor - Tile	1st Floor SW in Service Corridor	65	SF	4	1-2 years	Missing tile
	Floor - Tile Ceramic/ Porcelain	1st Floor SW in Service Corridor	85	SF	6	10+ years	
	Floor Drain	1st Floor SW in Service Corridor	1	EA	7	10+ years	
	Lavatory	1st Floor SW in Service Corridor	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor SW in Service Corridor	2	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor SW in Service Corridor	2	EA	6	6-10 years	
	Partitions	1st Floor SW in Service Corridor	2	EA	7	10+ years	
	Student Lockers - One Tier	1st Floor SW in Service Corridor	19	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor SW in Service Corridor	555	SF	7	10+ years	
	Water Closet	1st Floor SW in Service Corridor	2	EA	6	10+ years	
	Accessories	1st Floor Women Janitors	100	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor Women Janitors	76	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor Women Janitors	24	SF	4	1-2 years	Damaged tile
	Doors - Wood Doors inclu hw	1st Floor Women Janitors	2	EA	7	10+ years	•
	Floor - Tile	1st Floor Women Janitors	70	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor Women Janitors	30	SF	7	10+ years	
	Lavatory	1st Floor Women Janitors	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor Women Janitors	2	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor Women Janitors	1	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor Women Janitors	3	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Women Janitors	400	SF	7	10+ years	
	Water Closet	1st Floor Women Janitors	1	EA	7	10+ years	
	Accessories	1st Floor Womens in Service	32	SF	7	6-10 years	
		Corridor				•	
	Ceiling - Splined	1st Floor Womens in Service	32	SF	6	10+ years	
	-	Corridor				-	
	Doors - Wood Doors inclu hw	1st Floor Womens in Service	1	EA	6	10+ years	
		Corridor				•	
	Floor - Tile	1st Floor Womens in Service	32	SF	4	1-2 years	Missing tile
		Corridor				-	-
	Lavatory	1st Floor Womens in Service	1	EA	5	0-1 year	Missing faucet
	•	Corridor				•	•
	Lighting - Wall Mounted	1st Floor Womens in Service	1	EA	7	6-10 years	
		Corridor				•	
	Partitions	1st Floor Womens in Service	1	EA	7	10+ years	
		Corridor				•	
	Walls - Concrete Block	1st Floor Womens in Service	150	SF	7	10+ years	
		Corridor				-	
	Water Closet	1st Floor Womens in Service	1	EA	7	10+ years	
		Corridor				•	
	Accessories	2nd Floor	178	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	178	SF	7	10+ years	
	-					-	



Category : Room			В	Building : Addition-Lunchroom_Unit D					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	178	SF	7	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Lavatory	2nd Floor	3	EA	7	10+ years			
	Lighting - Lay-in	2nd Floor	2	EA	7	6-10 years			
	Partitions	2nd Floor	4	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	465	SF	7	10+ years			
	Water Closet	2nd Floor	4	EA	7	10+ years			
	Accessories	2nd Floor	172	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	172	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	172	SF	7	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Lavatory	2nd Floor	2	EΑ	7	10+ years			
	Lavatory	2nd Floor	1	EA	5	1-2 years	Faucet damaged		
	Lighting - Lay-in	2nd Floor	2	EA	7	6-10 years			
	Partitions	2nd Floor	2	EA	7	10+ years			
	Urinals	2nd Floor	2	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	465	SF	7	10+ years			
	Water Closet	2nd Floor	2	EA	7	10+ years			
	Accessories	Kitchen	28	SF	7	6-10 years			
	Ceiling - Lay-in	Kitchen	22	SF	7	10+ years			
	Ceiling - Lay-in	Kitchen	6	SF	4	1-2 years	Falling tile		
	Doors - Wood Doors inclu hw	Kitchen	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Kitchen	28	SF	7	10+ years			
	Lavatory	Kitchen	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Kitchen	1	EA	5	1-2 years	Wiring not contained		
	Lighting - Wall Mounted	Kitchen	1	EA	6	2-5 years	Not working		
	Walls - Concrete Block	Kitchen	150	SF	7	10+ years			
	Water Closet	Kitchen	1	EA	7	10+ years			
	Accessories	Old Engineer's Office Toilet Room	46	SF	7	6-10 years			
	Ceiling - Splined	Old Engineer's Office Toilet Room	46	SF	6	10+ years			
	Doors - Wood Doors inclu hw	Old Engineer's Office Toilet Room	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	Old Engineer's Office Toilet Room	46	SF	6	10+ years			
	Lavatory	Old Engineer's Office Toilet Room	1	EA	5	1-2 years	Damaged faucet		
	Lighting - Wall Mounted	Old Engineer's Office Toilet Room	1	EA	6	6-10 years	-		
	Showers	Old Engineer's Office Toilet Room	1	EA	7	10+ years			
	Walls - Concrete Block	Old Engineer's Office Toilet Room	210	SF	7	10+ years			
	Water Closet	Old Engineer's Office Toilet Room	1	EA	7	10+ years			
Catego	ry : Classroom		В	uildina	: Additi	on-Lunchroom	Unit D		
90	,			9					

Recommend Item - Type Location Quantity UOM Rank Replacement Comments

Classroom #224-223 (Regular Classroom)



Catego	ry : Classroom		В	uildina	: Additio	on-Lunchroom	Unit D
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Splined	2nd Floor	1,240	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	, 2	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	1,230	SF	7	10+ years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Damaged tile
	Lighting - Lay-in	2nd Floor	14	ĒΑ	7	6-10 years	g
	Lighting - Lay-in	2nd Floor	6	ΕA	6	1-2 years	Not working
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	12	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,000	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	376	SF	7	10+ years	
Classroo	m #266 (Fitness Room)						
	Ceiling - Splined	2nd Floor	1,240	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,220	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,000	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	376	SF	7	10+ years	
Classroo	m #283 (Weight)						
	Ceiling - Splined	2nd Floor	1,600	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	50	SF	4	1-2 years	Damaged ceiling tile
	Chalk Board	2nd Floor	20	LF	4	2-5 years	Damagea coming the
	Doors - Wood Doors inclu hw	2nd Floor	6	EA	7	10+ years	
	Floor - Weight/ Fitness Room Floor Matting	2nd Floor	1,650	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Storage/ Closet	2nd Floor	108	SF	7	10+ years	
	Wall Mirrors	2nd Floor	112	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	630	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	300	SF	7	10+ years	
Classroo	m #Dance - in 267 (Dance Room)						
	Ceiling - Splined	2nd Floor	1,306	SF	7	10+ years	
	Ceiling - Splined	2nd Floor	1	SF	4	1-2 years	Missing tile
	Floor - Weight/ Fitness Room Floor Matting	2nd Floor	1,306	SF	6	2-5 years	3 · ·
	Lighting - Lay-in	2nd Floor	32	EA	7	10+ years	
	Sprung Floor System	2nd Floor	1,306	SF	7	10+ years	
	Wall Mirrors	2nd Floor	434	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	182	SF	7	10+ years	
	Walls - Metal Panel	2nd Floor	476	SF	7	10+ years	
Catego	ry : Interior		В	uilding	: Additio	on-Lunchroom	_Unit D
	Item - Type	Location	Quantity	UOM		Recommend	



						Replacement	,
Corridor							
	Ceiling - Exposed	First Floor Corridors	715	SF	7	10+ years	
	Ceiling - Lay-in	First Floor Corridors	833	SF	7	10+ years	
	Doors - Wood Doors include hw	First Floor Corridors	7	EA	7	10+ years	
	Floor - Concrete	First Floor Corridors	688	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	First Floor Corridors	860	SF	7	10+ years	
	Lighting - Lay-in	First Floor Corridors	12	EA	7	6-10 years	
	Lighting - Pendent/Surface	First Floor Corridors	10	EΑ	7	6-10 years	
	Walls - Concrete Block	First Floor Corridors	4,564	SF	7	10+ years	
	Ceiling - Lay-in	Second Floor Corridors	2,300	SF	7	10+ years	
	Doors - Side-lite	Second Floor Corridors	1,000	SF	7	10+ years	
	Doors - Wood Doors include hw	Second Floor Corridors	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	Second Floor Corridors	2	EA	7	10+ years	
	Floor - Tile/Sheet	Second Floor Corridors	2,300	SF	7	10+ years	
	Lighting - Lay-in	Second Floor Corridors	18	EA	7	6-10 years	
	Walls - Concrete Block	Second Floor Corridors	2,165	SF	7	10+ years	
	77ano - 33no 310 2.33n		_,.00	•	•	,	
Safety							
oalety	Security Cameras	2nd Floor	5	EA	7	6-10 years	
	Security Cameras	2110 F1001	3	LA	,	0-10 years	
Ctoiro							
Stairs	Ceiling - Lay-in	North Stair	270	SF	7	40	
	Ceiling - Lay-in Ceiling - Plaster/Drywall	North Stair		SF SF	7 7	10+ years	
	Floor - Terrazzo	North Stair	32 26	SF	7	10+ years 10+ years	
	Floor - Tile/Sheet	North Stair		SF SF	7		
	Handrails	North Stair	1,518 56	SF LF	7	10+ years	
		North Stair North Stair	3		7	10+ years	
	Lighting - Pendent/Surface Stairs - Terrazzo	North Stair North Stair	3 116	EA LF	7	6-10 years	
	Stairs - Terrazzo Stairs - Terrazzo			LF LF	=	10+ years	Domagad troads
	Walls - Concrete Block	North Stair North Stair	2	SF	5 7	1-2 years	Damaged treads
			945	SF	=	10+ years	
	Ceiling - Lay-in Ceiling - Plaster/Drywall	South Stair South Stair	300 32	SF SF	7 7	10+ years	
	Floor - Terrazzo	South Stair	30	SF SF	7	10+ years	
				SF SF	7	10+ years	
	Floor - Tile/Sheet Handrails	South Stair South Stair	178 56	LF	7	10+ years	
	Lighting - Pendent/Surface	South Stair South Stair	56 1	EA	7	10+ years 6-10 years	
	Stairs - Terrazzo	South Stair	116	LF	7	10+ years	
	Stairs - Terrazzo	South Stair	110	LF	4	1-2 years	Damaged tread
	Walls - Concrete Block	South Stair South Stair	945	SF	4 7	1-2 years 10+ years	Damageu ireau
	vvalis - Cultulete Diuck	South Stall	940	SF	1	10+ years	
Vertical	Conveyance						
vertical	Conveyance Elevator - Freight Elevator	West	1	EA	7	101 20070	
	Elevator - Freight Elevator	vvesi	1	EA	1	10+ years	



Category : Exterior			Building : Branch @ Old Canter					
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance	1		_			· ·		
	Exterior Doors - Exterior AMP Door	#1	4	EA	6	10+ years		
	Exterior Doors - Transom Lite	#1	4	EA	6	10+ years		
	Exterior Stairs - Concrete	#1	24	LF	6	10+ years		
	Entrance Control - Audio and Video	#2	1	ĒΑ	7	10+ years		
	Exterior Doors - Exterior AMP Door	#2	4	EA	6	10+ years		
	Exterior Doors - Transom Lite	#2	4	EA	6	10+ years		
	Exterior Stairs - Concrete	#2	24	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	#3 - Courtyard Boiler Room	1	ĒΑ	6	10+ years		
	Exterior Stairs - Concrete	#3 - Courtyard Boiler Room	3	LF	5	2-5 years		
	Exterior Doors - Exterior Steel Door	#3A	2	ĒΑ	6	10+ years		
	Exterior Doors - Exterior Steel Door	#3B	1	EA	6	6-10 years		
	Exterior Doors - Exterior Steel Door	#4	1	EA	4	0-1 year	Frame corroded, door not closing	
	Exterior Stairs - Concrete	#4	3	LF	6	10+ years	rame corroaca, addring closing	
	Entrance Control - Audio and Video	#5	1	ΕA	7	6-10 years		
	Exterior Doors - Exterior Steel Door	#5	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	#5	2	EA	6	10+ years		
	Exterior Stairs - Stone	#5	30	LF	6	6-10 years		
	Entrance Control - Audio and Video	#6	1	EA	7	10+ years		
	Exterior Doors - Exterior FRP Door	#6	2	EA	7	10+ years		
	Exterior Doors - Transom Lite	#6	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	#0	2	LA	O	10+ years		
Foundati	on							
Odridati	Foundation - Concrete	Entire Building	725	LF	7	10+ years		
	Foundation - Concrete	Entire Building	53	LF	6	10+ years	Seepage, deterioration	
	Superstructure - Steel with Clay Tile Arch	Entire Building	36,825	SF	7	10+ years	ocepage, acterioration	
	Superstructure - Steel with Glay The Arch	Entire ballaring	30,023	OI.	,	10+ years		
_Lighting								
- 5 - 5	Exterior Lighting - Parapet or Roof Mounted	Entire Building	7	EA	7	10+ years		
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	7	10+ years		
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	6	10+ years		
	3 3 3	3				, , , , , ,		
Roof Sys								
_	Access Ladder - Metal	Entire Building	1	EA	4	0-1 year	Too short, spaced far	
	Access Ladder - Metal	Entire Building	2	EA	4	0-1 year	Spaced far apart	
	Access Ladder - Wood	Entire Building	1	EA	4	0-1 year	Broke rung	
	Chimney - Brick Chimney- Stainless Steel	Entire Building	40	LF	6	10+ years	ŭ	
	Liner	-				•		
	Chimney - Metal Flue	Entire Building	20	LF	6	10+ years		
	Coping - Metal	Entire Building	105	LF	6	10+ years		
	Coping - Stone	Entire Building	635	LF	6	10+ years		
	Coping - Stone	Entire Building	255	LF	6	10+ years		
	. •	Ç				·		

Campus Name: Kenwood HS Page : 57 of 115 Assessment Date: 07/08/2024



Catego	ry : Exterior	Building : Branch @ Old Canter					
Ja.0901				ii		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Downspouts - Exterior Downspouts	Entire Building	40	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Entire Building	60	LF	6	10+ years	
	Downspouts - Interior Downspouts	Entire Building	270	LF	6	10+ years	
	Downspouts - Interior Downspouts	Entire Building	15	LF	6	10+ years	
	Parapet - 16" - 30" Height	Entire Building	555	LF	6	10+ years	
	Parapet - 16" - 30" Height	Entire Building	255	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Entire Building	105	LF	6	10+ years	
	Parapet - Parapet > 30"	Entire Building	80	LF	6	10+ years	
	Roof - Metal	Entire Building	132	SF	7	10+ years	
	Roof - Modified Bitumen	Entire Building	8,019	SF	6	10+ years	
	Roof - Modified Bitumen	Entire Building	10,100	SF	6	10+ years	
	Roof - Modified Bitumen	Entire Building	1,000	SF	5	2-5 years	
	Roof Hatch - Metal	Entire Building	2	EA	4	0-1 year	Difficult access
	Roof Structure - Steel with Clay Tile Arch	Entire Building	11,232	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Entire Building	8,019	SF	7	10+ years	
	,	Ŭ	•			,	
Walls							
	Cheek-Wall - Stone	Entire Building	64	SF	7	10+ years	
	Cornice - Cast Stone	Entire Building	119	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	27,264	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	2,750	SF	6	10+ years	
_Windows	3						
	Guard - Guards perforated	Entire Building	1,848	SF	6	10+ years	
	Lintels - Steel	Entire Building	659	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	20	SF	6	6-10 years	
	Windows - Louver	Entire Building	16	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	5,120	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Branc	h @ Old Cante	r
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emergen	ncy System						
	Automatic Transfer Switch	Basement	1	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,250	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose	Entire Building	3,120	SF	6	6-10 years	
	Room Emergency A/C Power - Students Toilets	Entire Building	1,635	SF	6	6-10 years	
		Entire Building	18	EA	5	6-10 years	Quantity changed as total has been
	Exit Signs - Corridors and Stairs	Littire Ballating					
	•	· ·		⊑ ∧	E	6 10 4000	divided/aggregated.
	Exit Signs - Corridors and Stairs Exit Signs - Multipurpose Room Security System - CCTV	Entire Building Entire Building	4 41,382	EA SF	5 6	6-10 years 6-10 years	divided/aggregated.



Kenwood Academy High School

APP S			5015 S Blackstone AVENUE, Chicago, IL 60615 Building: Branch @ Old Canter						
Catego	ry : Electrical			ullaing	: Branc	n @ Old Cantel Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
O. Gup	Security System - Intrusion Detection	Entire Building	41,382	SF	6	6-10 years			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	16	EA	6	6-10 years			
	Emergency Battery Packs - Multipurpose Room	Entire Building	3	EA	6	6-10 years	Quantity changed to match current observations.		
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	Quantity changed to match current observations.		
Main Sei	rvice								
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	Location changed for clarification.		
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years			
	PA System	Entire Building	41,382	SF	5	6-10 years	Branch has a building-dedicated PA system independent from Main Academic Bldg. B.		
Power D	istribution								
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	Quantity changed as total has been divided/aggregated.		
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	7	10+ years	Quantity changed as total has been divided/aggregated.		
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slot exposes live conductors presenting a live front condition.		
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Missing interior cover plate exposes live conductors presenting a live fror condition.		
Catego	ry : Fire Protection		В	uilding	: Branc	h @ Old Cante	r		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Fire Alar									
	Fire ALarm Anunciator	Entire Building	1	EΑ	6	6-10 years	No CPS Asset Tag present.		
	Fire Alarm Panel	Entire Building	14 202	EA SF	6	6-10 years			
	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	41,382 41,382	SF SF	6 6	10+ years 6-10 years			
	The Alami_System	Littile Ballaling	41,302	OI.	U	0-10 years			
Catego	ry : Mechanical		В	uilding	: Branc	h @ Old Cante	r		
Cuarra	Hom Type	Lagation	O.com#ite-	HOM	Donla	Recommend	Comments		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Air Cond	Condensing Unit- Roof Mounted - Less	Lower Roof	1	EA	5	6-10 years	No CPS Asset Tag present.		

Campus Name: Kenwood HS Page : 59 of 115 Assessment Date: 07/08/2024



Categor	Category : Mechanical			Building : Branch @ Old Canter						
			0			Recommend	0			
Group	Item - Type than 5 tons	Location	Quantity	UOM	Rank	Replacement	Comments			
_Air Handl	ing Systems									
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	1	EA	5	6-10 years	Location changed for clarification. No CPS Asset Tag present.			
	Indoor Return Fans- Centrifugal Squirrel Cage - Less than 5000 CFM	Attic	1	EA	5	6-10 years	<u>.</u>			
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room - AHU-1	1	EA	5	6-10 years	AHU-1, serves classrooms. Location changed for clarification.			
	Air Intake	Mechanical Room - AHU-1	1	EA	5	6-10 years	Location changed for clarification.			
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room - AHU-1	1	EA	5	6-10 years	Location changed for clarification.			
	Return Duct Work - Sheet Metal- Exterior	Mechanical Room - AHU-1	90	LF	5	6-10 years	Location changed for clarification.			
	Vertical Shaft and Ducts					-	-			
	Zone Dampers	Mechanical Room - AHU-1	8	EA	5	6-10 years	Location changed for clarification. Quantity changed to match current observations.			
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room - AHU-2	1	EA	5	6-10 years	AHU-2, serves multipurpose room and associated spaces. Location changed for clarification.			
	Air Intake	Mechanical Room - AHU-2	1	EA	6	6-10 years	Location changed for clarification.			
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room - AHU-2	1	ΕA	5	6-10 years	Location changed for clarification.			
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-2	90	LF	6	10+ years				
	Zone Dampers	Mechanical Room - AHU-2	4	EA	5	6-10 years	Location changed for clarification. Quantity changed to match current observations.			
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room - AHU-3	1	EA	5	6-10 years	AHU-3. No CPS Asset Tag present.			
	Air Intake	Mechanical Room - AHU-3	1	EA	6	6-10 years	Wire mesh protective screen is separated from the south face of the damper assembly housing.			
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room - AHU-3	1	EΑ	5	6-10 years				
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room - AHU-3	4	EA	5	6-10 years	Location changed for clarification.			
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room - AHU-3	50	LF	5	6-10 years				
	and Ducts Zone Dampers	Mechanical Room - AHU-3	14	EA	5	6-10 years	Location changed for clarification.			
Boiler Sy	stems									
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 201 - 300 HP	Boiler Room	2	EA	6	6-10 years	Boilers in the midst of seasonal maintenance protocol at the time of assessment.			
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years				
	Combustion Dampers	Boiler Room	2	EA	5	6-10 years	Quantity changed to match current			

Campus Name: Kenwood HS Page : 60 of 115 Assessment Date: 07/08/2024



Category : Mechanical		Building : Branch @ Old Canter						
Proup.	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Group	item - Type	Location	Quantity	UOW	Kank	Replacement	Comments observations.	
	Condensate Pump	Boiler Room	1	EA	5	6-10 years	Located adjacent to AHU-3.	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	10+ years	Located adjacont to 7 ti 10 o.	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	ĒΑ	6	6-10 years	B-1; in the midst of seasonal	
	Steam- Low Pressure Boiler - 201 - 300 HP						maintenance protocol at the time o assessment.	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 201 - 300 HP	Boiler Room	1	EA	6	6-10 years	B-2; in the midst of seasonal maintenance protocol at the time cassessment.	
	Piping - Condensate Pipe- Steel	Boiler Room	250	LF	4	2-5 years	1913 installation. They are pipe clamps. Minor leaks are frequently repaired.	
	Piping - Steam Pipe- Steel	Boiler Room	250	LF	4	2-5 years	1913 installation. They are pipe	
							clamps. Minor leaks are frequently repaired.	
	Steam Traps	Boiler Room	45	EA	5	6-10 years	repaired.	
leating l	Devices							
Ū	Cabinet Heaters - With Electric Coil	1st Floor	1	EA	7	10+ years	Rank and Priority Rep changed as the unit has been replaced since previous assessment.	
	Unit Heater - Steam	Boiler Room	2	EA	5	6-10 years	Quantity changed to match current observations.	
	Wall Heater - Electric	Entire Building	9	EA	6	6-10 years	Quantity changed to match current observations and as the total has been divided/aggregated.	
	Fin Tube - Steam	Entire Building	45	LF	6	6-10 years	Quantity changed to match curren observations.	
	Radiators - Steam	Entire Building	13	EA	5	6-10 years	Quantity changed to match curren observations.	
empera	ature Control							
	Electric Thermostat	Entire Building	2	EA	6	6-10 years		
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	Rank adjusted based on current observations.	
	Electric Thermostat	Entire Building	2	EA	6	6-10 years		
	Pneumatic System	Entire Building	41,382	SF	7	6-10 years	Rank adjusted as the compressor system has been replaced since previous assessment.	
	Thermostats - Pneumatic	Entire Building	35	EA	6	6-10 years	Quantity changed as total has bee divided/aggregated.	



Catego	ry : Mechanical		В	uilding	: Brancl	n @ Old Cante	r
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	3	EA	6	6-10 years	Quantity changed to match current observations.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	Serves 3rd Floor office restroom.
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	3	0-1 year	Serves 2nd Floor office restroom. Location changed for clarification. Unit is damaged and nonfunctional. Rank adjusted as the fan is not operational.

Category: Plumbing **Building: Branch @ Old Canter**

Galego	Category . I fullibring		Bullung : Branch & Old Carter						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Hot Wat	er								
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	10+ years			
						·			
Piping									
	Domestic Piping-Hot Water Return Lines	Entire Building	41,382	SF	6	6-10 years			
	Domestic Piping-Hot Water Return Risers	Entire Building	41,382	SF	6	6-10 years			
	Domestic Piping-Hot Water from Risers to	Entire Building	41,382	SF	6	6-10 years			
	Fixtures	•				•			
	Domestic Piping-Hot/Cold Water Supply	Entire Building	41,382	SF	6	6-10 years			
	(Horizontal Lines)	•				•			
	Domestic Piping-Hot/Cold Water Supply	Entire Building	41,382	SF	6	6-10 years			
	(Risers)								
	Domestic Piping-Hot/Cold Water Supply	Entire Building	41,382	SF	6	6-10 years			
	(from Risers to Fixtures)								
	Sanitary Piping	Entire Building	41,382	SF	6	6-10 years			
	Storm Piping	Entire Building	41,382	SF	6	6-10 years			
	Vent Piping	Entire Building	41,382	SF	6	6-10 years			
_									
Pumps	Donner - Donner Go Donner - Do	Decement				0.40	Demostic cold water become		
	Pumps - Domestic Booster Pump-Duplex	Basement	1	EΑ	5	6-10 years	Domestic cold water house pump.		
	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	7	10+ years	Domestic hot water house pump. No CPS Asset Tag present.		
	Pumps - Sump-Duplex	Basement	1	EA	5	6-10 years	Item Type changed to match current		
							observations. Located adjacent to AHU-3. No CPS Asset Tag present.		
	Pumps - Sump-Duplex	Basement	1	EA	5	6-10 years	Item Type changed to match current		
	i umps - Sump-Duplex	Dasement	ļ	EA	5	0-10 years	observations. Located adjacent to		
							AHU-3. No CPS Asset Tag present.		
							Allo o. No or o Asset ray present.		

Campus Name: Kenwood HS Page : 62 of 115 Assessment Date: 07/08/2024



Category : Plumbing			Building : Branch @ Old Canter				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	Elevator pit sump pump. Not directly accessible at the time of assessment. No CPS Asset Tag available. Condition verified by Building Engineer.

Category : Room **Building: Branch @ Old Canter**

Julogo	, , , , , , , , , , , , , , , , , , ,		Recommend							
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	trative Suites/Offices	2004.011	quantity	•	rtaint	rtopiacomoni				
шпэ	Ceiling - Lay-in	2nd Floor 201 Main Office	400	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor 201 Main Office	400	EA	7	•				
	Floor - Tile	2nd Floor 201 Main Office	395	SF	7	10+ years 10+ years				
	Floor - Tile	2nd Floor 201 Main Office	595 5	SF	4	•	Cracked			
		2nd Floor 201 Main Office	8	EA	7	1-2 years	Clacked			
	Lighting - Lay-in Power Distribution	2nd Floor 201 Main Office	10	EA	7	6-10 years 10+ years				
	Walls - Plaster/Drywall	2nd Floor 201 Main Office	529	SF	7	10+ years				
	Ceiling - Lay-in	2nd Floor 201B Office	108	SF	7	•				
	Doors - Wood Doors inclu hw	2nd Floor 201B Office	100	EA	7	10+ years				
	Floor - Tile	2nd Floor 201B Office	108	SF	7	10+ years 10+ years				
	Lighting - Lay-in	2nd Floor 201B Office	2	EA	7	6-10 years				
	Power Distribution	2nd Floor 201B Office	8	EA	7	•				
	Walls - Plaster/Drywall	2nd Floor 201B Office	o 145	SF	7	10+ years				
	Ceiling - Lay-in	2nd Floor 201C Office	264	SF	7	10+ years 10+ years				
	Doors - Wood Doors inclu hw	2nd Floor 201C Office	204	EA	7	10+ years				
	Floor - Tile	2nd Floor 201C Office	260	SF	7	•				
	Floor - Tile	2nd Floor 201C Office	260 4	SF	4	10+ years	Cracked			
	Lighting - Lay-in	2nd Floor 201C Office	4	EA	7	1-2 years 10+ years	Clacked			
	Power Distribution	2nd Floor 201C Office	12	EA	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor 201C Office	348	SF	7	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor Conference Room 212	320	SF	7	10+ years				
	Doors - Transom Window	2nd Floor Conference Room 212	9	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor Conference Room 212	1	EA	7	10+ years				
	Floor - Tile	2nd Floor Conference Room 212	316	SF	7	10+ years				
	Floor - Tile	2nd Floor Conference Room 212	4	SF	4	1-2 years	Cracked			
	Lighting - Pendent/Surface	2nd Floor Conference Room 212	3	EA	6	6-10 years	Ordonod			
	Power Distribution	2nd Floor Conference Room 212	6	EA	7	10+ years				
	Storage/ Closet	2nd Floor Conference Room 212	60	SF	7	10+ years				
	Walls - Plaster/Drywall	2nd Floor Conference Room 212	423	SF	7	10+ years				
	Ceiling - Plaster/Drywall	3rd Floor Principal Office 312	140	SF	7	10+ years				
	Doors - Transom Window	3rd Floor Principal Office 312	9	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor Principal Office 312	1	EA	7	10+ years				
	Floor - Tile	3rd Floor Principal Office 312	140	SF	7	10+ years				
	Lighting - Pendent/Surface	3rd Floor Principal Office 312	3	EA	7	6-10 years				
		5.4 / 1001 / 111101pai 011100 012	O	_, .	•	5 10 ,0010				



Category : Room Building : Branch @ Old Canter						r	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	3rd Floor Principal Office 312	12	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor Principal Office 312	185	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office (Vacant)	170	SF	6	10+ years	
	Doors - Side-lite	Engineer's Office (Vacant)	16	SF	7	6-10 years	
	Doors - Transom Window	Engineer's Office (Vacant)	21	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	Engineer's Office (Vacant)	1	EA	4	0-1 year	Missing handle
	Floor - Wood	Engineer's Office (Vacant)	170	SF	6	10+ years	
	Lighting - Pendent/Surface	Engineer's Office (Vacant)	2	EA	7	6-10 years	
	Power Distribution	Engineer's Office (Vacant)	6	EA	7	10+ years	
	Storage/ Closet	Engineer's Office (Vacant)	100	SF	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office (Vacant)	470	SF	6	10+ years	
_Gvmnas	ia						
	Ceiling - Plaster/Drywall	1st Floor Multipurpose Space 112	3,120	SF	7	10+ years	
	Floor - Tile	1st Floor Multipurpose Space 112	3,120	SF	7	10+ years	
	Lighting - Lay-in	1st Floor Multipurpose Space 112	16	EA	7	6-10 years	
	Scoreboards	1st Floor Multipurpose Space 112	1	EA	7	6-10 years	
	Sound System	1st Floor Multipurpose Space 112	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor Multipurpose Space 112	90	SF	7	10+ years	
	Walls - Masonry	1st Floor Multipurpose Space 112	1,360	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Multipurpose Space 112	2,000	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	1st Floor	370	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	370	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	4	EA	7	6-10 years	
	Serving Line	1st Floor	20	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	489	SF	7	10+ years	
_MDF_ID	F						
	Doors - Steel Doors incl hw	204A	1	EA	7	10+ years	
	Finishes	204A	130	SF	7	6-10 years	
	Other Cooling Unit	204A	1	EA	7	10+ years	
_Mechani	ical/ Service Rooms						
	Air Tunnel	1st Floor	350	SF	7	10+ years	
	Boiler Room	1st Floor	850	SF	7	10+ years	
	Janitor's Closet	1st Floor	48	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	1,100	SF	7	10+ years	
	Storage Room	1st Floor	112	SF	7	10+ years	
	Janitor's Closet	2nd Floor	48	SF	5	1-2 years	Peeling paint
	Storage Room	2nd Floor	360	SF	7	10+ years	.



Category : Room			В	Building : Branch @ Old Canter				
Ĭ						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•	Janitor's Closet	3rd Floor	48	SF	7	10+ years		
	Storage Room	3rd Floor	72	SF	7	10+ years		
	•							
Restrooi	m							
	Accessories	1st Floor	260	SF	7	6-10 years		
	Ceiling - Lay-in	1st Floor	252	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	8	SF	5	1-2 years	Water damage	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	260	SF	7	10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Hand Dryer	1st Floor	1	EA	7	6-10 years		
	Lavatory	1st Floor	3	ΕA	7	10+ years		
	Lighting - Lay-in	1st Floor	2	ĒΑ	7	6-10 years		
	Partitions	1st Floor	2	EA	7	10+ years		
	Urinals	1st Floor	4	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	129	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	518	SF	7	10+ years		
	Water Closet	1st Floor	2	EA	7	10+ years		
	Accessories	1st Floor	285	SF	7	6-10 years		
	Ceiling - Lay-in	1st Floor	260	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	25	SF	7	10+ years		
	Doors - Transom Window	1st Floor	9	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	285	SF	7	10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Hand Dryer	1st Floor	2	EA	7	6-10 years		
		1st Floor	3	EA	7	•		
	Lavatory	1st Floor	2	EA	7	10+ years		
	Lighting - Lay-in	1st Floor		EA	-	6-10 years		
	Lighting - Pendent/Surface Partitions	1st Floor	1 5	EA EA	6 7	6-10 years		
				SF		10+ years		
	Walls - Plaster/Drywall	1st Floor	135	SF SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	530		7 7	10+ years		
	Water Closet	1st Floor	5	EA		10+ years		
	Accessories	1st Floor	220	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	220	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	220	SF	7	10+ years		
	Floor Drain	1st Floor	1	EΑ	7	10+ years		
	Lavatory	1st Floor	2	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years		
	Partitions	1st Floor	2	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	290	SF	7	10+ years		
	Water Closet	1st Floor	2	EA	7	10+ years		



Category : Room			Building : Branch @ Old Canter					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Accessories	2nd Floor	260	SF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	235	SF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	25	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	260	SF	6	10+ years		
	Floor Drain	2nd Floor	1	EA	7	10+ years		
	Hand Dryer	2nd Floor	1	EA	7	6-10 years		
	Lavatory	2nd Floor	3	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor	2	EA	7	6-10 years		
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years		
	Partitions	2nd Floor	2	EA	7	10+ years		
	Urinals	2nd Floor	4	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	129	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	518	SF	7	10+ years		
	Water Closet	2nd Floor	2	ĒA	7	10+ years		
	Accessories	2nd Floor	285	SF	7	6-10 years		
	Ceiling - Lay-in	2nd Floor	285	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor	285	SF	7	10+ years		
	Floor Drain	2nd Floor	1	EA	7	10+ years		
	Hand Dryer	2nd Floor	2	EA	7	6-10 years		
	Lavatory	2nd Floor	3	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor	2	EA	7	6-10 years		
	Partitions	2nd Floor	5	EA	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	135	SF	7	10+ years		
	Walls - Structural Glazed Tile	2nd Floor	530	SF	7	10+ years		
	Water Closet	2nd Floor	5	EA	7	10+ years		
	Accessories	2nd Floor Staff Restroom Inside Conference Room	60	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor Staff Restroom Inside	60	SF	7	10+ years		
		Conference Room						
	Doors - Wood Doors inclu hw	2nd Floor Staff Restroom Inside Conference Room	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Floor Staff Restroom Inside	60	SF	7	10+ years		
	Floor Drain	Conference Room 2nd Floor Staff Restroom Inside	1	EA	7	10+ years		
	Lavatory	Conference Room 2nd Floor Staff Restroom Inside	1	EA	7	10+ years		
	Lighting - Pendent/Surface	Conference Room 2nd Floor Staff Restroom Inside	2	EA	7	6-10 years		
	Walls - Concrete Block	Conference Room 2nd Floor Staff Restroom Inside	90	SF	7	10+ years		

Campus Name: Kenwood HS Page : 66 of 115 Assessment Date: 07/08/2024



Catego	ry : Room		Building : Branch @ Old Canter						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
		Conference Room							
	Walls - Plaster/Drywall	2nd Floor Staff Restroom Inside	129	SF	7	10+ years			
		Conference Room							
	Water Closet	2nd Floor Staff Restroom Inside	1	EA	7	10+ years			
		Conference Room							
	Accessories	3rd Floor	285	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	285	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	285	SF	7	10+ years			
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Hand Dryer	3rd Floor	2	EA	7	6-10 years			
	Lavatory	3rd Floor	3	EA	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	6-10 years			
	Partitions	3rd Floor	5	EA	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	135	SF	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor	530	SF	7	10+ years			
	Water Closet	3rd Floor	5	EA	7	10+ years			
	Accessories	3rd Floor	260	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	260	SF	7	10+ years			
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	260	SF	7	10+ years			
	Floor Drain	3rd Floor	1	ĒΑ	7	10+ years			
	Hand Dryer	3rd Floor	1	EA	7	6-10 years			
	Lavatory	3rd Floor	3	EA	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	3	EA	7	6-10 years			
	Partitions	3rd Floor	2	EA	7	10+ years			
	Urinals	3rd Floor	4	EA	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	129	SF	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor	518	SF	7	10+ years			
	Water Closet	3rd Floor	2	ĒΑ	7	10+ years			
	Accessories	3rd Floor Staff Restroom Inside	60	SF	7	6-10 years			
		Principal Office		-	-	5 . 5 , 5			
	Ceiling - Plaster/Drywall	3rd Floor Staff Restroom Inside	60	SF	7	10+ years			
	coming in action 2 ty main	Principal Office		٠.	•	. o . y ca. c			
	Doors - Wood Doors inclu hw	3rd Floor Staff Restroom Inside	1	EA	6	6-10 years			
	Boole Wood Boole Illoid IIII	Principal Office	•		Ū	o io youio			
	Floor - Tile	3rd Floor Staff Restroom Inside	60	SF	7	10+ years			
	11001 1110	Principal Office	00	O.	•	ioi youro			
	Floor Drain	3rd Floor Staff Restroom Inside	1	EA	7	10+ years			
	1 Iour Drain	Principal Office		_, .	•	101 yours			
	Lavatory	3rd Floor Staff Restroom Inside	1	EA	7	10+ years			
	Lavatory	Principal Office		_/ \	,	101 yours			
		i inicipal Cinoc							



Category : Room			Building : Branch @ Old Canter				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor Staff Restroom Inside Principal Office	1	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor Staff Restroom Inside Principal Office	96	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor Staff Restroom Inside Principal Office	114	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor Staff Restroom Inside Principal Office	6	SF	4	1-2 years	Water damage
	Water Closet	3rd Floor Staff Restroom Inside Principal Office	1	EA	7	10+ years	
	Accessories	Basement	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	60	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Basement	60	SF	7	10+ years	
	Lavatory	Basement	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement	230	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement	2	SF	5	1-2 years	Water damage
	Water Closet	Basement	1	EA	7	10+ years	<u>-</u>
	Accessories	Engineer's Office	50	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Office	50	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Engineer's Office	50	SF	7	10+ years	
	Lavatory	Engineer's Office	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	1	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	Engineer's Office	216	SF	6	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	4	SF	4	1-2 years	Water damage
	Water Closet	Engineer's Office	1	EA	7	10+ years	ū

Category : Classroom **Building: Branch @ Old Canter**

_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroom #101 (Store Room)							
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	40	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	870	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	860	SF	7	10+ years	
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Missing and cracked
	Lighting - Pendent/Surface	1st Floor	14	EΑ	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,150	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	



Category : Classroom			Building : Branch @ Old Canter					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	m #102 (Art Room)							
Classioc	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	40	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	883	SF	6	10+ years		
	Doors - Transom Window	1st Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	870	SF	7	10+ years		
	Floor - Tile	1st Floor	23	SF	4	1-2 years	Cracked	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	,	Cracked	
			12	LF	7	6-10 years		
	Marker Board	1st Floor				6-10 years		
	Storage/ Closet	1st Floor	60	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	1,165	SF	7	10+ years		
	Work Sink	1st Floor	3	EA	7	10+ years		
Classroo	m #103 (Regular Classroom)							
· · · · · · · · · · · · · · · · · · ·	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	32	LF	6	10+ years		
	Ceiling - Splined	1st Floor	641	SF	6	10+ years	Some peeling paint	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	como poomig panti	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	641	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years		
	Marker Board	1st Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	850	SF	7	10+ years		
	·					·		
_Classroc	m #104 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	12	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	670	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	20	SF	5	1-2 years	Water damage	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	678	SF	7	10+ years		
	Floor - Tile	1st Floor	12	SF	5	1-2 years	Cracked	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	6	10+ years		
	Marker Board	1st Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	915	SF	6	10+ years		
Classroo	m #105 (Regular Classroom)							
_cia55100	,	1ot Floor	4	Г^	7	6.40		
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	10	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	680	SF	6	10+ years		



Category : Classroom			В	Building : Branch @ Old Canter				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Water damage	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	-	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years		
	Floor - Tile	1st Floor	670	SF	7	10+ years		
	Floor - Tile	1st Floor	20	SF	5	1-2 years	Cracked	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years		
	Marker Board	1st Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	915	SF	7	10+ years		
_Classroo	om #106 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	10	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	690	SF	6	10+ years		
	Doors - Transom Window	1st Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	685	SF	7	10+ years		
	Floor - Tile	1st Floor	5	SF	5	1-2 years	Cracked	
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years	Cracked	
	Marker Board	1st Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	915	SF	7	10+ years		
Classroo	om #202 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	12	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	816	SF	6	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	803	SF	7	10+ years		
	Floor - Tile	2nd Floor	13	SF	5	1-2 years	Cracked	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	Oracked	
	Marker Board	2nd Floor	32	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,080	SF	7	10+ years		
Classroo	om #203 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	12	LF	6	10+ years		
	Casework Ceiling - Plaster/Drywall	2nd Floor	690	SF	6	10+ years	Peeling paint	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	i comig panit	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	686	SF	7	10+ years		
	Floor - Tile Floor - Tile	2nd Floor	4	SF SF	4	1-2 years	Chipped	
	Lighting - Pendent/Surface	2nd Floor		EA	6	6-10 years	Chipped	
			14 34	LF	6 7			
	Marker Board	2nd Floor	34	LF	1	10+ years		



r : Classroom Item - Type Walls - Plaster/Drywall Wireless System	Location	Quantity	_		h @ Old Cante	
Walls - Plaster/Drywall		Quantity				
		Quantity	UOM	Rank	Replacement	Comments
Wireless System	2nd Floor	915	SF	7	10+ years	
- 7	2nd Floor	1	EA	7	6-10 years	
n #204 (Faculty Lounge)						
AC Units	2nd Floor	1	EA	7	6-10 years	
		•			•	
						Cracked
						Clacked
					•	
vvalis - Plaster/Drywali	2nd Floor	730	5F	ь	10+ years	
n #205 (Science Classroom)						
AC Units	2nd Floor	1	EA	7		
Casework	2nd Floor			6	10+ years	
	2nd Floor	690		6	10+ years	
Doors - Transom Window	2nd Floor	9		7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Tile	2nd Floor	670	SF	7	10+ years	
Floor - Tile	2nd Floor	20	SF	5		Cracked
			EA		•	
			LF		•	
Walls - Plaster/Drywall	2nd Floor	915	SF	7	10+ years	
n #206 (Regular Classroom)						
	2nd Floor	1	FΔ	7	6-10 years	
						Cracked
						Clacked
walls - Plaster/Drywall	2nd Floor	915	SF	/	10+ years	
n #207 (Regular Classroom)						
AC Units		1	EA	7	6-10 years	
Casework	2nd Floor	12		6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	690	SF	6	10+ years	
Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
COUFFLY LACCOUFFLY LACCOUFFLY LACC	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall #205 (Science Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall #206 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Doors - Wood Doors inclu hw Floor - Tile Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall #207 (Regular Classroom) AC Units Casework Ceiling - Plaster/Drywall	Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Ploor - Tile Ploor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Doors - Transom Window Walls - Plaster/Drywall Doors - Transom Window Doors - Transom Window Doors - Transom Window Doors - Wood Doors inclu hw Ploor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Doors - Wood Doors inclu hw Ploor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Doors - Wood Doors inclu hw Ploor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall Doors - Transom Window Doors - Transom Window Walls - Plaster/Drywall Doors - Wall - Plaster/Drywall Doors - Transom Window Doors - Tile Door - T	Ceiling - Plaster/Drywall 2nd Floor 550 Doors - Transom Window 2nd Floor 9 Doors - Wood Doors inclu hw 2nd Floor 1 Floor - Tile 2nd Floor 545 Floor - Tile 2nd Floor 5 Lighting - Pendent/Surface 2nd Floor 10 Marker Board 2nd Floor 24 Walls - Plaster/Drywall 2nd Floor 730 #205 (Science Classroom) 4 AC Units 2nd Floor 1 Casework 2nd Floor 690 Doors - Transom Window 2nd Floor 690 Doors - Transom Window 2nd Floor 670 Floor - Tile 2nd Floor 670 Floor - Tile 2nd Floor 670 Floor - Tile 2nd Floor 14 Warker Board 2nd Floor 9 Doors - Transom Window 2	Ceiling - Plaster/Drywall 2nd Floor 550 SF Doors - Transom Window 2nd Floor 9 SF Doors - Wood Doors inclu hw 2nd Floor 1 EA Floor - Tile 2nd Floor 545 SF Eighting - Pendent/Surface 2nd Floor 10 EA Marker Board 2nd Floor 24 LF Walls - Plaster/Drywall 2nd Floor 24 LF Walls - Plaster/Drywall 2nd Floor 1 EA AC Units 2nd Floor 1 EA Ceiling - Plaster/Drywall 2nd Floor 12 LF Ceiling - Plaster/Drywall 2nd Floor 9 SF Doors - Wood Doors inclu hw 2nd Floor 9 SF Doors - Wood Doors inclu hw 2nd Floor 1 EA Floor - Tile 2nd Floor 20 SF Floor - Tile 2nd Floor 14 EA Marker Board 2nd Floor 14 EA Walls - Plaster/Drywall 2nd F	Ceiling - Plaster/Drywall	2-and Floor 550 5F 6 10+ years 2-and Floor 9 5F 7 10+ years 2-and Floor 9 5F 7 10+ years 2-and Floor 1 EA 7 10+ years 2-and Floor 10 EA 6 6-10 years 2-and Floor 2-and Flo



Category : Classroom			В	Building : Branch @ Old Canter				
<u> </u>						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	590	SF	7	10+ years		
	Floor - Tile	2nd Floor	100	SF	5	1-2 years	Cracked	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	915	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	1-2 years	Damaged	
Classroo	m #301 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	790	SF	7	•		
				SF	, 5	10+ years	Cracked	
	Floor - Tile	3rd Floor	26			0-1 year	Cracked	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years		
	Marker Board Walls - Plaster/Drywall	3rd Floor 3rd Floor	18 1,080	LF SF	7 7	6-10 years 10+ years		
	·	314 1 1001	1,000	Oi.	,	101 years		
_Classroo	m #302 (Regular Classroom)							
	AC Units	3rd Floor	2	EA	7	6-10 years		
	Casework	3rd Floor	12	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	7	10+ years		
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	796	SF	7	10+ years		
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Cracked	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years		
	Marker Board	3rd Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	1,080	SF	7	10+ years		
Classroo	m #303 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	22	LF	6	10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	690	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	3rd Floor	675	SF	7	10+ years		
	Floor - Tile	3rd Floor	15	SF	4	1-2 years	Cracked	
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	915	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
	TOTA OFFICE	014 1 1001	ı	L/\	,	ioi youis		



Category : Classroom			Building : Branch @ Old Canter						
	w -		0		.	Recommend	0		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #304 (Regular Classroom)								
	AC Units	3rd Floor	2	EA	7	6-10 years			
	Casework	3rd Floor	12	LF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	690	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	670	SF	7	10+ years			
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Cracked		
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years			
	Marker Board	3rd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	915	SF	7	10+ years			
Classroo	m #305 (Regular Classroom)								
	AC Units	3rd Floor	2	EA	7	6-10 years			
	Casework	3rd Floor	12	LF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	390	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	300	SF	5	1-2 years	Damage		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	Damago		
	Floor - Tile	3rd Floor	685	SF	7	10+ years			
	Floor - Tile	3rd Floor	5	SF	4	1-2 years	Cracked		
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	Gracked		
	Marker Board	3rd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	915	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	20	SF	5	1-2 years	Damaged		
lassroo	m #306 (Regular Classroom)								
21033100	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	12	LF		10+ years			
		3rd Floor		SF	6				
	Ceiling - Plaster/Drywall Ceiling - Plaster/Drywall		670	SF SF	6 5	10+ years	Water demand		
		3rd Floor	20			1-2 years	Water damage		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years			
	Floor - Tile	3rd Floor	685	SF	7	10+ years	01:		
	Floor - Tile	3rd Floor	.5	SF	4	1-2 years	Chipped		
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years			
	Marker Board	3rd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	895	SF	6	10+ years			
	Walls - Plaster/Drywall	3rd Floor	40	SF	5	1-2 years	Water damage		
lassroo	m #307 (Science Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	38	LF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	690	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years			
	Floor - Tile	3rd Floor	670	SF	7	10+ years			



Category : Classroom

Kenwood Academy High School 5015 S Blackstone AVENUE, Chicago, IL 60615

Building : Branch @ Old Canter

						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	915	SF	6	10+ years	
	Work Sink	3rd Floor	2	EA	7	10+ years	
ategor	y : Interior		В	uildina	: Brancl	h @ Old Cante	,
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Lay-in	1st Floor	1,750	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	5	1-2 years	Water damage
	Drinking Fountains - Double Fountain	1st Floor	2	EA	7	6-10 years	
	Drinking Fountains - Double Water Cooler	1st Floor	1	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,738	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	12	SF	4	1-2 years	Cracked
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	99	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,100	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,750	SF	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	6-10 years	
	Drinking Fountains - Double Water Cooler	2nd Floor	1	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	1,730	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	20	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	99	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,100	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	1,750	SF	7	10+ years	
	Drinking Fountains - Double Fountain	3rd Floor	2	EA	7	6-10 years	
	Drinking Fountains - Double Water Cooler	3rd Floor	1	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	3rd Floor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	3rd Floor	1,742	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	8	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	3rd Floor	12	ĒΑ	7	6-10 years	-
	Student Lockers - One Tier	3rd Floor	99	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,100	SF	7	10+ years	
afety							
<u>y</u>	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	8	EA	7	6-10 years	



Category : Interior			В	Building : Branch @ Old Canter				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Stairs								
	Ceiling - Plaster/Drywall	North	108	SF	7	10+ years		
	Floor - Terrazzo	North	108	SF	7	10+ years		
	Handrails	North	120	LF	7	10+ years		
	Lighting - Wall Mounted	North	1	EA	7	6-10 years		
	Stairs - Terrazzo	North	348	LF	7	10+ years		
	Walls - Plaster/Drywall	North	1,725	SF	7	10+ years		
	Ceiling - Plaster/Drywall	South	108	SF	7	10+ years		
	Floor - Terrazzo	South	108	SF	7	10+ years		
	Handrails	South	120	LF	7	10+ years		
	Lighting - Pendent/Surface	South	2	EΑ	7	6-10 years		
	Stairs - Terrazzo	South	348	LF	7	10+ years		
	Walls - Plaster/Drywall	South	1,725	SF	7	10+ years		
Vertical (Conveyance							
	Elevator - Hydraulic Elevator	Center	1	EA	7	10+ years		

Campus Name: Kenwood HS Page : 75 of 115 Assessment Date: 07/08/2024



Roof System

Category : Exterior			Building : Linked Addition-Arts_Unit A					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Entrance								
	Exterior Doors - Exterior FRP Door	6	6	EA	6	10+ years		
	Exterior Doors - Side lite	6	9	EA	6	10+ years		
	Exterior Doors - Transom Lite	6	6	EA	6	10+ years		
	Exterior Stairs - Concrete	6	23	LF	6	10+ years		
	Exterior Stairs - Concrete	6	10	LF	5	2-5 years		
	Ramps - Concrete	6	8	LF	6	10+ years		
	Exterior Doors - Side lite	6.1 - Courtyard 2	3	EA	6	10+ years		
	Exterior Doors - Store Front	6.1 - Courtyard 2	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	6.1 - Courtyard 2	2	EA	6	10+ years		
	Exterior Stairs - Concrete	6.1 - Courtyard 2	10	LF	6	10+ years		
	Exterior Doors - Exterior FRP Door	7	2	EA	6	10+ years		
	Exterior Doors - Side lite	7	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	7	2	EA	6	10+ years		
	Exterior Stairs - Concrete	7	10	LF	5	2-5 years		
	Exterior Doors - Exterior FRP Door	8	2	EA	6	10+ years		
	Exterior Doors - Side lite	8	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	8	2	EA	6	10+ years		
	Exterior Stairs - Concrete	8	10	LF	6	10+ years		
	Exterior Doors - Exterior FRP Door	9	6	EA	6	10+ years		
	Exterior Doors - Side lite	9	9	EA	6	10+ years		
	Exterior Doors - Transom Lite	9	6	EA	6	10+ years		
	Exterior Stairs - Concrete	9	30	LF	6	10+ years		
	Ramps - Concrete	9	8	LF	6	10+ years		
	Exterior Doors - Side lite	9.1 - Courtyard 2	3	EA	6	10+ years		
	Exterior Doors - Store Front	9.1 - Courtyard 2	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	9.1 - Courtyard 2	2	EA	6	10+ years		
	Exterior Stairs - Concrete	9.1 - Courtyard 2	10	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	RAD - E	1	EA	6	10+ years		
	Exterior Stairs - Steel or Aluminum	RAD - E	3	LF	5	10+ years		
- - - - - - - - - - - - - - - - - - -	22							
ounuall	Foundation - Concrete	Entire Building	1,020	LF	7	10+ years		
	Foundation - Concrete	Entire Building Entire Building	1,020	LF LF	6	10+ years 10+ years		
				SF	7	•		
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	63,520	ər	1	10+ years		
ighting								
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	4	EA	7	10+ years		
	Exterior Lighting - Wall Mounted	Entire Building	24	EA	6	10+ years		

Campus Name: Kenwood HS Page : 76 of 115 Assessment Date: 07/08/2024



Catego	ry : Exterior	В	uilding	: Linked	d Addition-Arts	_Unit A	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	Roofs F & G	1	EA	7	10+ years	
	Coping - Metal	Roofs F & G	374	LF	6	10+ years	
	Coping - Metal	Roofs F & G	923	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roofs F & G	270	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roofs F & G	420	LF	5	2-5 years	
	Parapet - Parapet < 16" Height	Roofs F & G	374	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roofs F & G	923	LF	6	10+ years	
	Roof - Modified Bitumen	Roofs F & G	21,060	SF	5	2-5 years	
	Roof - Modified Bitumen	Roofs F & G	8,700	SF	5	2-5 years	Upper
	Roof - Modified Bitumen	Roofs F & G	2,000	SF	4	0-1 year	Leaks, ponding, cracks, holes
	Roof Hatch - Metal	Roofs F & G	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roofs F & G	8,700	SF	7	6-10 years	
	Concrete Topping					-	
	Roof Structure - Steel / Metal Deck/	Roofs F & G	23,060	SF	7	10+ years	
	Concrete Topping					•	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	60	SF	6	10+ years	
	Canopy - Concrete/ Stucco	Entire Building	20	SF	4	1-2 years	Cracking
	Exterior Walls - Brick	Entire Building	12,520	SF	6	10+ years	3
	Exterior Walls - Precast Panel Wall	Entire Building	16,568	SF	6	10+ years	
Windows	8						
	Guard - Guards perforated	Entire Building	1,276	SF	6	10+ years	
	Lintels - Concrete	Entire Building	592	LF	6	10+ years	
	Lintels - Steel	Entire Building	3	LF	6	10+ years	
	Storefront Windows	Entire Building	320	SF	6	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	4,352	SF	6	10+ years	
	pane	3	,			,	
Cataga	ry - Flootrical		D	uildina	·Linkor	l Addition_Arts	Linit A

Building: Linked Addition-Arts_Unit A Category : Electrical

	Group Emergen	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	Lineigo	Security System - CCTV Security System - Intrusion Detection Exit Signs - Auditoium	Entire Building Entire Building Entire Building Entire Building	63,520 63,520 6	SF SF EA	6 6 6	6-10 years 6-10 years 6-10 years	Location changed for clarification as the auditorium occupies space on multiple floors. Rank changed based on current observations that no signs need to be added or moved. Rank changed based on current
		Exit Signs - Corridors and Stairs	Entire Building	19	EA	6	6-10 years	Rank changed based on current observations that no signs need to be



Group	Item - Type Emergency A/C Power - Auditoium and	Location	Quantity	_		Addition-Arts Recommend	
Group		Location	Quantity				
	Emergency A/C Power - Auditoium and			UOM	Rank	Replacement	Comments
	Aisle Lighting	Entire Building	8,483	SF	6	6-10 years	added or moved. Location changed for clarification as the auditorium occupies space on multiple floors.
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,529	SF	6	6-10 years	multiple noors.
	Emergency A/C Power - Students Toilets	Entire Building	967	SF	6	6-10 years	
Main Sei	rvice						
	PA System	Entire Building	63,520	SF	6	6-10 years	Served by Bldg. B.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Location changed for clarification. Rank, Reason and Priority Rep changed as the cover/door assembly is missing which exposes live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	7	10+ years	Quantity changed to match current observations and as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Location changed for clarification. Rank, Reason and Priority Rep changed as a missing interior cover plate exposes live conductors presenting a live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	procenting a live from condition.
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	Misidentified in previous assessment Quantity changed to match current observations and as total has been divided/aggregated.
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	2	EA	6	10+ years	Quantity changed to match current observations. Location changed for clarification.
	Transformers - 277/480 - 120/208	Entire Building	1	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Linked	Addition-Arts	_Unit A
_				_		Recommend	
Group Fire Alar	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments



Category : Fire Protection

Kenwood Academy High School 5015 S Blackstone AVENUE, Chicago, IL 60615

Building: Linked Addition-Arts_Unit A

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Strobe Lights	Entire Building	63,520	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	63,520	SF	6	6-10 years	FACP is in Bldg. B.
Catego	ry : Mechanical		В	uilding	: Linked	d Addition-Arts	_Unit A
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond	litioning						
	Pipes - Chilled Water Pipe- Steel	Entire Building	400	LF	6	6-10 years	
_Air Hand	ling Systems						
	Indoor Return Fans- Centrifugal Squirrel	Mechanical Room	1	EA	6	6-10 years	Associated with AHU-1.
	Cage - 5000 - 10000 CFM				•	0.40	A
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Mechanical Room	1	EA	6	6-10 years	Associated with AHU-2
	Indoor Return Fans- Centrifugal Squirrel	Mechanical Room	1	EA	6	6-10 years	Associated with AHU-3.
	Cage - 5000 - 10000 CFM	Wechanical Room		LA	O	0-10 years	Associated with Al 10-5.
	Air Handling Unit- Package Multi Zone-	Mechanical Room - AHU-1	1	EA	6	6-10 years	AHU-1. Cooling only.
	Indoor- Steam Coil and Chilled Water Coils					,	ů ,
	- 15001-20000 cfm						
	Air Intake	Mechanical Room - AHU-1	1	EA	6	6-10 years	
	Zone Dampers	Mechanical Room - AHU-1	8	EA	6	6-10 years	AUU
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coil and Chilled Water Coils	Mechanical Room - AHU-2	1	EA	6	6-10 years	AHU-2. No CPS Asset Tag present.
	- 10001-15000 cfm						
	Air Intake	Mechanical Room - AHU-2	1	EA	6	6-10 years	
	Zone Dampers	Mechanical Room - AHU-2	9	EΑ	6	6-10 years	
	Air Handling Unit- Package Single Zone-	Mechanical Room - AHU-3	1	EA	6	6-10 years	AHU-3. No CPS Asset Tag present.
	Indoor- Steam Coils and Chilled Water Coils					•	.
	- 12001-20000 cfm						
	Air Intake	Mechanical Room - AHU-3	1	EA	6	6-10 years	
.							
_Boiler Sy		Manhanial Dans				0.40	No ODO Assaul Tax
	Condensate Pump	Mechanical Room Mechanical Room	1	EA LF	5	6-10 years	No CPS Asset Tag present.
	Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel	Mechanical Room Mechanical Room	200 200	LF LF	6 6	6-10 years 6-10 years	
	Steam Traps	Mechanical Room	10	EA	5	6-10 years	
	Ctourn Traps	Woonaniou (Com	10	_/ \	Ü	o io youio	
Heating	Devices						
	Cabinet Heaters - With Steam Coil	Entire Building	2	EA	4	0-1 year	Rank, Reason and Priority Rep
		S .				,	changed based on current
							observations that openings in the
							damaged cabinet covers allow for
							possible contact with moving and



Catego	ry : Mechanical		В	uilding	: Linked	d Addition-Arts	_Unit A
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							heat-producing parts presenting a risk of personal injury and with live conductors presenting a live front condition.
	Unit Heater - Steam	Mechanical Room	1	EΑ	5	6-10 years	
	Unit Heater - Steam	Mechanical Room	1	EA	5	6-10 years	Quantity changed as total has been divided/aggregated.
_Tempera	ature Control						
•	DDC System	Entire Building	63,520	SF	7	10+ years	
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	
	Thermostats - DDC	Entire Building	22	EA	7	10+ years	
_Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	3	EA	6	6-10 years	Location changed for clarification. Fans are on east classroom walls.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed based on current observations that the fan has been repaired and reassembled since previous assessment.

Category: Plumbing Building: Linked Addition-Arts_Unit A

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Piping	Rem Type	Location	Quantity	OOM	Rain	Replacement	Comments
- 1 5	Domestic Piping-Hot Water Return Lines	Entire Building	63,520	SF	6	10+ years	Domestic hot and cold water supplied by Bldg. C.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	63,520	SF	6	10+ years	Domestic hot and cold water supplied by Bldg. C.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	63,520	SF	6	10+ years	Domestic hot and cold water supplied by Bldg. C.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	63,520	SF	6	10+ years	Domestic hot and cold water supplied by Bldg. C.
	Sanitary Piping	Entire Building	63,520	SF	6	10+ years	
	Storm Piping	Entire Building	63,520	SF	6	10+ years	
	Vent Piping	Entire Building	63,520	SF	6	10+ years	

Campus Name: Kenwood HS Page : 80 of 115 Assessment Date: 07/08/2024



Category : Room			В	Building : Linked Addition-Arts_Unit A					
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Administ	rative Suites/Offices								
	Ceiling - Lay-in	126A	189	SF	7	10+ years			
	Ceiling - Lay-in	126A	4	SF	5	1-2 years	Water damage		
	Doors - Side-lite	126A	40	SF	7	10+ years	Trailer damage		
	Doors - Wood Doors inclu hw	126A	2	EA	7	10+ years			
	Floor - Carpet	126A	188	SF	7	6-10 years			
	Floor - Carpet	126A	5	SF	4	1-2 years	Torn		
	Lighting - Lay-in	126A	4	ĒΑ	7	6-10 years			
	Storage/ Closet	126A	8	SF	7	10+ years			
	Walls - Concrete Block	126A	242	SF	7	10+ years			
	Ceiling - Splined	126B - Practice Room	42	SF	7	10+ years			
	Doors - Side-lite	126B - Practice Room	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	126B - Practice Room	1	EA	7	10+ years			
	Floor - Carpet	126B - Practice Room	42	SF	7	6-10 years			
	Lighting - Lay-in	126B - Practice Room	1	EA	7	6-10 years			
	Power Distribution	126B - Practice Room	4	EA	7	10+ years			
	Walls - Concrete Block	126B - Practice Room	213	SF	7	10+ years			
	Ceiling - Splined	126C - Practice Room	161	SF	7	10+ years			
	Doors - Side-lite	126C - Practice Room	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	126C - Practice Room	1	EA	7	10+ years			
	Floor - Carpet	126C - Practice Room	161	SF	7	6-10 years			
	Lighting - Lay-in	126C - Practice Room	2	EA	7	6-10 years			
	Power Distribution	126C - Practice Room	10	EA	7	10+ years			
	Walls - Plaster/Drywall	126C - Practice Room	499	SF	7	10+ years			
	Ceiling - Lay-in	128 - Green Room	458	SF	7	10+ years			
	Ceiling - Lay-in	128 - Green Room	6	SF	5	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	128 - Green Room	2	EA	7	10+ years	· ·		
	Floor - Tile	128 - Green Room	464	SF	7	10+ years			
	Lighting - Lay-in	128 - Green Room	11	EΑ	7	6-10 years			
	Power Distribution	128 - Green Room	6	EΑ	7	10+ years			
	Walls - Concrete Block	128 - Green Room	748	SF	7	10+ years			
	Work SInk	128 - Green Room	2	EΑ	7	10+ years			
	Ceiling - Lay-in	133B - Practice Room	53	SF	7	10+ years			
	Doors - Side-lite	133B - Practice Room	14	SF	7	10+ years			
	Doors - Wood Doors inclu hw	133B - Practice Room	1	EΑ	7	10+ years			
	Floor - Tile	133B - Practice Room	53	SF	7	10+ years			
	Lighting - Pendent/Surface	133B - Practice Room	1	EA	5	1-2 years	Missing cover		
	Power Distribution	133B - Practice Room	2	EA	7	10+ years			
	Walls - Concrete Block	133B - Practice Room	298	SF	7	10+ years			
	Ceiling - Lay-in	133C - Practice Room	53	SF	7	10+ years			
	Doors - Side-lite	133C - Practice Room	28	SF	7	10+ years			
	Doors - Wood Doors inclu hw	133C - Practice Room	1	EA	7	10+ years			
	Floor - Tile	133C - Practice Room	53	SF	7	10+ years			
	Lighting - Pendent/Surface	133C - Practice Room	1	EA	6	6-10 years			



Catego	ry : Room		В	uilding	: Linked	Addition-Arts	_Unit A
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	133C - Practice Room	2	EA	7	10+ years	
	Walls - Concrete Block	133C - Practice Room	298	SF	7	10+ years	
	Ceiling - Lay-in	133D - Practice Room	53	SF	7	10+ years	
	Doors - Side-lite	133D - Practice Room	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	133D - Practice Room	1	EA	7	10+ years	
	Floor - Tile	133D - Practice Room	53	SF	7	10+ years	
	Lighting - Pendent/Surface	133D - Practice Room	1	EA	7	6-10 years	
	Power Distribution	133D - Practice Room	2	EA	7	10+ years	
	Walls - Concrete Block	133D - Practice Room	294	SF	7	10+ years	
	Ceiling - Lay-in	133E - Practice Room	47	SF	7	10+ years	
	Doors - Wood Doors inclu hw	133E - Practice Room	1	EA	7	10+ years	
	Floor - Tile	133E - Practice Room	47	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	133E - Practice Room	1	EA	7	6-10 years	
	Power Distribution	133E - Practice Room	2	EA	7	10+ years	
	Walls - Concrete Block	133E - Practice Room	275	SF	7	10+ years	
	Ceiling - Lay-in	134B - Practice Room	53	SF	7	10+ years	
	Doors - Side-lite	134B - Practice Room	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	134B - Practice Room	1	EA	7	10+ years	
	Floor - Tile	134B - Practice Room	53	SF	7	10+ years	
	Lighting - Pendent/Surface	134B - Practice Room	1	EA	4	1-2 years	Missing cover
	Walls - Concrete Block	134B - Practice Room	270	SF	7	10+ years	
	Ceiling - Lay-in	134C - Practice Room	53	SF	7	10+ years	
	Doors - Side-lite	134C - Practice Room	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	134C - Practice Room	1	EA	7	10+ years	
	Floor - Tile	134C - Practice Room	53	SF	7	10+ years	
	Lighting - Pendent/Surface	134C - Practice Room	1	EΑ	7	6-10 years	
	Power Distribution	134C - Practice Room	2	EA	7	10+ years	
	Walls - Concrete Block	134C - Practice Room	270	SF	7	10+ years	
	Ceiling - Lay-in	134D - Practice Room	49	SF	7	10+ years	\\\\-\tag{\chi}
	Ceiling - Lay-in	134D - Practice Room	4	SF	5	1-2 years	Water damage
	Doors - Side-lite	134D - Practice Room	28	SF EA	7	10+ years	
	Doors - Wood Doors inclu hw	134D - Practice Room	1 53	SF	7	10+ years	
	Floor - Tile	134D - Practice Room			7	10+ years	
	Lighting - Pendent/Surface	134D - Practice Room	1	EΑ	7	6-10 years	
	Power Distribution	134D - Practice Room	2	EA SF	7	10+ years	
	Walls - Concrete Block	134D - Practice Room	270 47	SF SF	7 7	10+ years	
	Ceiling - Lay-in Doors - Wood Doors inclu hw	134E - Practice Room 134E - Practice Room	47	SF EA	7	10+ years	
	Floor - Tile	134E - Practice Room 134E - Practice Room	1 47	SF	7	10+ years	
	Lighting - Pendent/Surface	134E - Practice Room	1	EA	7	10+ years 6-10 years	
	Power Distribution	134E - Practice Room	2	EA	7	10+ years	
	Walls - Concrete Block	134E - Practice Room	245	SF	7	10+ years 10+ years	
	Ceiling - Lay-in	134H	389	SF	7	10+ years	
	Doors - Side-lite	134H	36	SF	7	10+ years	
	DOOLS SIGE-IIIC	10711	30	Oi.	,	10+ years	

Campus Name: Kenwood HS Page: 82 of 115 Assessment Date: 07/08/2024



Catego	Category : Room			uilding	: Linked	Addition-Arts	_Unit A
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	134H	2	EA	7	10+ years	
	Floor - Tile	134H	389	SF	7	10+ years	
	Lighting - Lay-in	134H	6	EA	7	6-10 years	
	Power Distribution	134H	6	EA	7	10+ years	
	Walls - Concrete Block	134H	638	SF	7	10+ years	
	Ceiling - Lay-in	144A	61	SF	7	10+ years	
	Doors - Wood Doors inclu hw	144A	1	EA	7	10+ years	
	Floor - Tile	144A	61	SF	7	10+ years	
	Lighting - Lay-in	144A	1	EA	7	6-10 years	
	Power Distribution	144A	2	EA	7	10+ years	
	Walls - Concrete Block	144A	258	SF	7	10+ years	
	Ceiling - Plaster/Drywall	145A - Security Office	377	SF	7	10+ years	
	Doors - Wood Doors inclu hw	145A - Security Office	2	EA	7	10+ years	
	Floor - Wood	145A - Security Office	377	SF	7	10+ years	
	Lighting - Pendent/Surface	145A - Security Office	3	EA	7	6-10 years	
	Power Distribution	145A - Security Office	6	EA	7	10+ years	
	Walls - Concrete Block	145A - Security Office	248	SF	7	10+ years	
	Walls - Plaster/Drywall	145A - Security Office	257	SF	7	10+ years	
	Ceiling - Plaster/Drywall	146 - Dean's Office	377	SF	7	10+ years	
	Doors - Wood Doors inclu hw	146 - Dean's Office	2	EA	7	10+ years	
	Floor - Wood	146 - Dean's Office	377	SF	7	6-10 years	
	Lighting - Pendent/Surface	146 - Dean's Office	3	EA	7	6-10 years	
	Power Distribution	146 - Dean's Office	8	EA	7	10+ years	
	Walls - Concrete Block	146 - Dean's Office	248	SF	7	10+ years	
	Walls - Plaster/Drywall	146 - Dean's Office	257	SF	7	10+ years	
	Ceiling - Splined	225A	340	SF	7	10+ years	
	Doors - Wood Doors inclu hw	225A	1	EA	7	10+ years	
	Floor - Tile	225A	340	SF	7	10+ years	
	Lighting - Pendent/Surface	225A	6	EA	7	6-10 years	
	Power Distribution	225A	20	EA	7	10+ years	
	Walls - Concrete Block	225A	537	SF	7	10+ years	
	Work SInk	225A	2	EA	7	10+ years	
	Ceiling - Splined	226A	950	SF	7	10+ years	
	Doors - Wood Doors inclu hw	226A	1	EA	7	10+ years	
	Floor - Tile	226A	940	SF	6	10+ years	
	Floor - Tile	226A	10	SF	4	0-1 year	Missing
	Lighting - Lay-in	226A	6	EA	6	10+ years	ŭ
	Power Distribution	226A	32	EA	7	10+ years	
	Walls - Metal Panel	226A	342	SF	7	10+ years	
	Walls - Plaster/Drywall	226A	578	SF	7	10+ years	
	Ceiling - Lay-in	235	448	SF	7	10+ years	
	Doors - Side-lite	235	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	235	1	EA	7	10+ years	
	Floor - Tile	235	448	SF	7	10+ years	
			110	-	•	,	



Category : Room			Building : Linked Addition-Arts_Unit A					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	235	6	EA	7	10+ years		
	Power Distribution	235	12	EA	7	10+ years		
	Storage/ Closet	235	160	SF	7	10+ years		
	Walls - Concrete Block	235	726	SF	7	10+ years		
	Ceiling - Lay-in	246 - Audio Visual Room	409	SF	6	10+ years		
	Ceiling - Lay-in	246 - Audio Visual Room	36	SF	5	1-2 years	Water damage	
	Doors - Wood Doors inclu hw	246 - Audio Visual Room	1	EA	7	10+ years		
	Floor - Tile	246 - Audio Visual Room	445	SF	7	10+ years		
	Lighting - Lay-in	246 - Audio Visual Room	10	EA	7	6-10 years		
	Power Distribution	246 - Audio Visual Room	8	EA	7	10+ years		
	Walls - Concrete Block	246 - Audio Visual Room	693	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor - 228	210	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor - 228	1	EΑ	7	10+ years		
	Floor - Tile	2nd Floor - 228	210	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor - 228	6	ĒΑ	7	6-10 years		
	Power Distribution	2nd Floor - 228	18	ĒΑ	7	10+ years		
	Storage/ Closet	2nd Floor - 228	28	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor - 228	436	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor - 228A	110	SF	7	10+ years		
	Doors - Side-lite	2nd Floor - 228A	18	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor - 228A	1	EA	7	10+ years		
	Floor - Tile	2nd Floor - 228A	110	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor - 228A	2	EA	7	6-10 years		
	Power Distribution	2nd Floor - 228A	2	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor - 228A	350	SF	7	10+ years		
A						, , , , , , , , , , , , , , , , , , , ,		
_Auditoriu	um & Theater	440 D (: A)	200					
	Balcony Seating	112 - Performing Arts	280	EA	7	10+ years		
	Ceiling - Plaster/Drywall	112 - Performing Arts	6,698	SF	7	10+ years		
	Doors - Wood Doors inclu hw	112 - Performing Arts	15	EA	7	10+ years		
	Floor - Carpet	112 - Performing Arts	1,320	SF	7	6-10 years		
	Floor - Concrete	112 - Performing Arts	5,378	SF	7	10+ years		
	Lighting - Pendent/Surface	112 - Performing Arts	48	EA	7	6-10 years		
	Main Floor Seating	112 - Performing Arts	496	EA	7	10+ years		
	Sound System	112 - Performing Arts	1	EA	7	6-10 years		
	Stage	112 - Performing Arts	2,159	SF	7	10+ years		
	Stage Curtain	112 - Performing Arts	8	EA	7	10+ years		
	Stage Lighting System	112 - Performing Arts	1	EA	7	6-10 years		
	Stairs - Tile	112 - Performing Arts	396	LF	7	10+ years		
	Storage/ Closet	112 - Performing Arts	1,300	SF	7	10+ years		
	Walls - Concrete Block	112 - Performing Arts	5,000	SF	7	10+ years		
	Ceiling - Lay-in	Little Theatre	1,785	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Little Theatre	4	EA	7	10+ years		
	Floor - Tile	Little Theatre	1,785	SF	7	10+ years		



Catego	ry : Room		Building : Linked Addition-Arts_Unit A					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	Little Theatre	45	EA	7	6-10 years		
	Main Floor Seating	Little Theatre	156	EA	7	10+ years		
	Stage	Little Theatre	120	SF	7	10+ years		
	Stage Curtain	Little Theatre	2	EA	7	10+ years		
	Stage Lighting System	Little Theatre	1	EA	7	6-10 years		
	Stairs - Tile	Little Theatre	66	LF	7	10+ years		
	Walls - Concrete Block	Little Theatre	1,932	SF	7	10+ years		
Mechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	50	SF	7	6-10 years	No access	
	Mechanical/ Service Rooms	1st Floor	36	SF	7	10+ years		
	Janitor's Closet	2nd Floor	58	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	22	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	16	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	12	SF	7	10+ years		
	Storage Room	2nd Floor	390	SF	7	10+ years		
	Storage Room	2nd Floor	390	SF	7	10+ years		
	Mechanical/ Service Rooms	3rd Floor	2,285	SF	7	10+ years		
Restroor	n							
	Accessories	128A - Girls' Dressing Room	186	SF	7	6-10 years		
	Ceiling - Lay-in	128A - Girls' Dressing Room	186	SF	7	10+ years		
	Doors - Wood Doors inclu hw	128A - Girls' Dressing Room	2	ĒΑ	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	128A - Girls' Dressing Room	186	SF	7	10+ years		
	Lavatory	128A - Girls' Dressing Room	1	ĒΑ	7	10+ years		
	Lighting - Lay-in	128A - Girls' Dressing Room	3	EA	7	6-10 years		
	Walls - Concrete Block	128A - Girls' Dressing Room	570	SF	7	10+ years		
	Water Closet	128A - Girls' Dressing Room	1	ĒΑ	7	10+ years		
	Accessories	128C - Boys' Dressing Room	203	SF	7	6-10 years		
	Ceiling - Lay-in	128C - Boys' Dressing Room	203	SF	7	10+ years		
	Doors - Wood Doors inclu hw	128C - Boys' Dressing Room	1	EA	7	10+ years		
	Floor - Tile	128C - Boys' Dressing Room	150	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	128C - Boys' Dressing Room	53	SF	7	10+ years		
	Lavatory	128C - Boys' Dressing Room	1	EA	4	0-1 year	Missing	
	Lighting - Lay-in	128C - Boys' Dressing Room	2	EΑ	7	6-10 years	Wildeling	
	Partitions	128C - Boys' Dressing Room	1	EΑ	7	10+ years		
	Walls - Concrete Block	128C - Boys' Dressing Room	302	SF	7	10+ years		
	Water Closet	128C - Boys' Dressing Room	1	EA	7	10+ years		
	Accessories	143	176	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	143	176	SF	7	10+ years		
	Doors - Wood Doors inclu hw	143	170	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	143	176	SF	7	10+ years		
	Floor Drain	143	170	EA	7	10+ years		
	Hand Dryer	143	2	EA	7	6-10 years		
	Tiana Diyo	170	۷		,	o To years		



Catego	Category : Room Building : Linked Addition-A				d Addition-Arts	_Unit A	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	143	2	EA	7	10+ years	
	Lighting - Pendent/Surface	143	3	EA	7	6-10 years	
	Partitions	143	2	EA	7	10+ years	
	Walls - Concrete Block	143	312	SF	7	10+ years	
	Water Closet	143	2	EA	7	10+ years	
	Accessories	148	187	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	148	187	SF	7	10+ years	
	Doors - Wood Doors inclu hw	148	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	148	187	SF	7	10+ years	
	Floor Drain	148	1	EA	7	10+ years	
	Hand Dryer	148	2	EA	7	6-10 years	
	Lavatory	148	2	EA	7	10+ years	
	Lighting - Lay-in	148	2	EA	5	1-2 years	Missing cover
	Partitions	148	1	EA	7	10+ years	
	Urinals	148	1	EA	6	0-1 year	Out of service
	Walls - Concrete Block	148	492	SF	7	10+ years	
	Water Closet	148	1	EA	7	10+ years	
	Accessories	244 Women's NW Staff Toilet Room	104	SF	7	6-10 years	
	Ceiling - Lay-in	244 Women's NW Staff Toilet Room	104	SF	7	10+ years	
	Doors - Wood Doors inclu hw	244 Women's NW Staff Toilet Room	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	244 Women's NW Staff Toilet Room	104	SF	7	10+ years	
	Lavatory	244 Women's NW Staff Toilet Room	1	EA	7	10+ years	
	Lighting - Pendent/Surface	244 Women's NW Staff Toilet Room	3	EA	7	6-10 years	
	Partitions	244 Women's NW Staff Toilet Room	1	EA	7	10+ years	
	Walls - Concrete Block	244 Women's NW Staff Toilet Room	411	SF	7	10+ years	
	Water Closet	244 Women's NW Staff Toilet Room	1	EA	7	10+ years	
	Accessories	248	187	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	248	187	SF	7	10+ years	
	Doors - Wood Doors inclu hw	248	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	248	187	SF	7	10+ years	
	Floor Drain	248	1	EA	7	10+ years	
	Hand Dryer	248	2	EA	7	6-10 years	
	Lavatory	248	3	EA	7	10+ years	
	Lighting - Pendent/Surface	248	3	EA	7	10+ years	
	Partitions	248	2	EA	7	10+ years	
	Urinals	248	2	EA	7	10+ years	
	Walls - Concrete Block	248	492	SF	7	10+ years	
	Water Closet	248	2	EA	7	10+ years	
	Accessories	2nd Floor	223	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	223	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	223	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	,					,	



Catego	ry : Room		Building : Linked Addition-Arts_Unit A					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lavatory	2nd Floor	3	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	6-10 years		
	Partitions	2nd Floor	3	EA	7	10+ years		
	Walls - Concrete Block	2nd Floor	411	SF	7	10+ years		
	Water Closet	2nd Floor	3	EA	7	10+ years		
	Accessories	2nd Flr NE - Men's Staff Toilet	96	SF	7	6-10 years		
		Room						
	Ceiling - Lay-in	2nd Flr NE - Men's Staff Toilet Room	92	SF	7	10+ years		
	Ceiling - Lay-in	2nd Flr NE - Men's Staff Toilet	4	SF	5	1-2 years	Water damage	
	Doors - Wood Doors inclu hw	Room 2nd FIr NE - Men's Staff Toilet Room	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Flr NE - Men's Staff Toilet Room	95	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	2nd Flr NE - Men's Staff Toilet Room	1	SF	4	1-2 years	Missing	
	Lavatory	2nd Flr NE - Men's Staff Toilet Room	1	EA	7	10+ years		
	Lighting - Pendent/Surface	2nd Flr NE - Men's Staff Toilet Room	3	EA	7	6-10 years		
	Partitions	2nd Flr NE - Men's Staff Toilet Room	1	EA	7	10+ years		
	Walls - Concrete Block	2nd Flr NE - Men's Staff Toilet Room	375	SF	7	10+ years		
	Water Closet	2nd Flr NE - Men's Staff Toilet Room	1	EA	7	10+ years		

Category : Classroom **Building: Linked Addition-Arts_Unit A**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #125 (Computer Lab)						
	Casework	1st Floor	34	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	896	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Carpet	1st Floor	890	SF	7	6-10 years	
	Floor - Carpet	1st Floor	6	SF	4	1-2 years	Torn
	Lighting - Lay-in	1st Floor	21	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,509	SF	7	10+ years	
	Wireless System	1st Floor	1	EA	7	10+ years	
Classroo	om #126 (Choral Room)						
	Casework	1st Floor	43	LF	7	10+ years	



Catego	ry : Classroom	В	Building : Linked Addition-Arts_Unit A					
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	1st Floor	1,289	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	6	SF	5	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years		
	Floor - Tile	1st Floor	1,295	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	25	EA	7	10+ years		
	Lighting - Lay-in	1st Floor	1	EA	5	1-2 years	Missing cover	
	Risers	1st Floor	85	LF	7	10+ years	· ·	
	Risers	1st Floor	20	LF	5	1-2 years	Riser damaged	
	Walls - Concrete Block	1st Floor	1,608	SF	7	10+ years	Ü	
Classroo	m #133 (Band Room)							
	Casework	1st Floor	3	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,430	SF	7	10+ years		
	Chalk Board	1st Floor	[′] 12	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	4	ĒΑ	7	10+ years		
	Floor - Tile	1st Floor	1,430	SF	7	10+ years		
	Instrument Storage Casework	1st Floor	36	LF	7	10+ years		
	Lighting - Lay-in	1st Floor	28	EA	7	6-10 years		
	Risers	1st Floor	160	LF	7	10+ years		
	Storage/ Closet	1st Floor	150	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	1,549	SF	7	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		
Classroo	m #134 (Band Room)							
	Casework	1st Floor	5	LF	6	10+ years		
	Ceiling - Lay-in	1st Floor	1,430	SF	7	10+ years		
	Chalk Board	1st Floor	10	LF	4	2-5 years		
	Doors - Wood Doors inclu hw	1st Floor	3	EΑ	7	10+ years		
	Floor - Tile	1st Floor	1,430	SF	7	10+ years		
	Instrument Storage Casework	1st Floor	54	LF	7	10+ years		
	Lighting - Lay-in	1st Floor	28	ĒΑ	7	6-10 years		
	Risers	1st Floor	160	LF	7	10+ years		
	Storage/ Closet	1st Floor	72	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	1,549	SF	7	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		
Classroo	om #225 (Science Classroom)							
	Casework	2nd Floor	120	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	1,835	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	12	SF	4	0-1 year	Water damage	
	Chalk Board	2nd Floor	7	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years		
			_		-	- ,		



	pry : Classroom	R	Building : Linked Addition-Arts_Unit A					
Calego	ory . Classicolli			ununig	. LIIIKE	Recommend	S_OHIL A	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Oroup	Floor - Tile	2nd Floor	1,837	SF	7	10+ years	Comments	
	Floor - Tile	2nd Floor	10	SF	4	0-1 year	Chipped	
	Lighting - Lay-in	2nd Floor	37	EA	7	6-10 years	Onipped	
	Walls - Concrete Block	2nd Floor 2nd Floor	1,072	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	342	SF	7			
	Walls - Plaster/Drywall Work Sink	2nd Floor 2nd Floor	10	SF EA	7	10+ years 10+ years		
01						,,,,,,		
_Classroo	om #226 (Regular Classroom)							
	Casework	2nd Floor	51	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	938	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	12	SF	5	0-1 year	Water damage	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years		
	Floor - Tile	2nd Floor	800	SF	7	10+ years		
	Floor - Tile	2nd Floor	150	SF	4	0-1 year	Missing	
	Lighting - Lay-in	2nd Floor	16	EΑ	7	6-10 years		
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Walls - Concrete Block	2nd Floor	920	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	114	SF	7	10+ years		
	Work Sink	2nd Floor	1	EA	7	10+ years		
Classroo	om #227 (Regular Classroom)							
	Casework	2nd Floor	48	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	1,290	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	40	SF	5	0-1 year	Water damage	
	Chalk Board	2nd Floor	7	LF	4	2-5 years	Water damage	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	1,330	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor 2nd Floor	24	EA	7	,		
	Marker Board	2nd Floor 2nd Floor	20	LF	7	6-10 years		
		2nd Floor	868	SF	7	6-10 years		
	Walls - Concrete Block					10+ years		
	Walls - Plaster/Drywall	2nd Floor	228	SF	7	10+ years		
	Work Sink	2nd Floor	1	EA	7	10+ years		
Classroo	om #230 (Computer Lab)							
	Ceiling - Lay-in	2nd Floor	388	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	8	SF	5	1-2 years	Water damage	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	-	
	Floor - Tile	2nd Floor	396	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	8	ĒΑ	7	6-10 years		
	Lighting - Lay-in	2nd Floor	1	ΕA	6	6-10 years		
	Walls - Concrete Block	2nd Floor	598	SF	7	10+ years		
						,		



Category : Classroom			Building : Linked Addition-Arts_Unit A					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank		Comments	
	Wireless System	2nd Floor	1	EA	7	6-10 years		
Classroo	om #232 (Art Room)							
	Casework	2nd Floor	86	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	1,434	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	6	SF	4	0-1 year	Cracked	
	Chalk Board	2nd Floor	8	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years		
	Floor - Tile	2nd Floor	1,440	SF	6	10+ years		
	Instructional Surface	2nd Floor	16	LF	7	10+ years		
	Kiln	2nd Floor	1	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor	26	EA	7	6-10 years		
	Storage/ Closet	2nd Floor	40	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	1,130	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	134	SF	7	10+ years		
	Work Sink	2nd Floor	2	EA	7	10+ years		
Classro	om #233 (Art Room)							
Classiu	Casework	2nd Floor	55	LF	7	10+ years		
		2nd Floor 2nd Floor		SF	7			
	Ceiling - Lay-in	2nd Floor 2nd Floor	1,284 12	SF SF	, 5	10+ years 0-1 year	Conging	
	Ceiling - Lay-in Chalk Board	2nd Floor 2nd Floor	27	SF LF	5 4		Sagging	
	Doors - Side-lite	2nd Floor 2nd Floor		SF	7	2-5 years		
			16			10+ years		
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	2	EA SF	7	10+ years		
	Floor - Tile	2nd Floor 2nd Floor	1,291	SF SF	6 4	10+ years	Minning	
	Floor - Tile		5		-	0-1 year	Missing	
	Lighting - Lay-in	2nd Floor	24	EA LF	7	6-10 years		
	Marker Board	2nd Floor	7		7	6-10 years		
	Storage/ Closet	2nd Floor	18	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	823	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	228	SF	7	10+ years		
	Work Sink	2nd Floor	3	EA	7	10+ years		
Classroo	om #234 (Art Room)							
	Casework	2nd Floor	66	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	1,296	SF	7	10+ years		
	Doors - Side-lite	2nd Floor	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years		
	Floor - Tile	2nd Floor	1,296	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	24	EA	7	6-10 years		
	Marker Board	2nd Floor	8	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	48	SF	7	10+ years		



Catego	ry : Classroom	В	Building : Linked Addition-Arts_Unit A					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	2nd Floor	823	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	228	SF	7	10+ years		
	Work Sink	2nd Floor	3	EA	7	10+ years		
Classroo	om #236 (Other Instructional Use)							
	Casework	2nd Floor	30	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	354	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	24	SF	4	1-2 years	Missing and broken	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	•	
	Floor - Tile	2nd Floor	278	SF	7	10+ years		
	Floor - Tile	2nd Floor	100	SF	4	0-1 year	Missing	
	Lighting - Lay-in	2nd Floor	9	EA	7	10+ years	-	
	Walls - Concrete Block	2nd Floor	606	SF	7	10+ years		
	Work Sink	2nd Floor	3	EA	7	10+ years		

Catego	ry : Interior	Building : Linked Addition-Arts_Unit A						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor								
	Ceiling - Lay-in	1st Floor - 126 Practice Rooms	94	SF	7	10+ years		
	Doors - Side-lite	1st Floor - 126 Practice Rooms	48	SF	7	10+ years		
	Doors - Wood Doors include hw	1st Floor - 126 Practice Rooms	1	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor - 126 Practice Rooms	94	SF	7	10+ years		
	Lighting - Lay-in	1st Floor - 126 Practice Rooms	1	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor - 126 Practice Rooms	355	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor - 133 Practice Rooms	94	SF	7	10+ years		
	Doors - Side-lite	1st Floor - 133 Practice Rooms	89	SF	7	10+ years		
	Doors - Wood Doors include hw	1st Floor - 133 Practice Rooms	1	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor - 133 Practice Rooms	94	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor - 133 Practice Rooms	2	EA	7	6-10 years		
	Walls - Concrete Block	1st Floor - 133 Practice Rooms	355	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor - 134 Practice Rooms	94	SF	7	10+ years		
	Doors - Side-lite	1st Floor - 134 Practice Rooms	89	SF	7	10+ years		
	Doors - Wood Doors include hw	1st Floor - 134 Practice Rooms	1	EA	7	10+ years		
	Floor - Tile/Sheet	1st Floor - 134 Practice Rooms	94	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor - 134 Practice Rooms	2	EΑ	7	6-10 years		
	Walls - Concrete Block	1st Floor - 134 Practice Rooms	355	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor - East	1,096	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor - East	4	SF	5	1-2 years	Water damage	
	Doors - Steel Doors incl hw	1st Floor - East	2	EA	7	10+ years	-	
	Doors - Wood Doors include hw	1st Floor - East	4	EA	7	10+ years		
	Drinking Fountains - Single Fountain	1st Floor - East	2	EA	7	6-10 years		
	Floor - Tile/Sheet	1st Floor - East	1,100	SF	7	10+ years		
	Lighting - Lay-in	1st Floor - East	10	EA	7	6-10 years		



Catego	Category : Interior			uilding	: Linked	l Addition-Arts	_Unit A
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs - Terrazzo	1st Floor - East	40	LF	7	10+ years	
	Stairs - Terrazzo	1st Floor - East	50	LF	7	10+ years	
	Student Lockers - One Tier	1st Floor - East	61	EA	7	10+ years	
	Walls - Masonry	1st Floor - East	644	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - East	716	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - North	2,058	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor - North	2,050	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor - North	8	SF	4	1-2 years	Cracked
	Lighting - Lay-in	1st Floor - North	10	EA	7	6-10 years	
	Walls - Masonry	1st Floor - North	1,068	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - North	843	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - West	1,617	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor - West	. 2	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor - West	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor - West	1	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor - West	1	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor - West	1,617	SF	7	10+ years	
	Lighting - Lay-in	1st Floor - West	10	EA	7	6-10 years	
	Stairs - Terrazzo	1st Floor - West	45	LF	7	10+ years	
	Stairs - Terrazzo	1st Floor - West	40	LF	7	10+ years	
	Student Lockers - One Tier	1st Floor - West	58	EA	7	10+ years	
	Walls - Masonry	1st Floor - West	810	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - West	540	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor - East	1,402	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor - East	2	SF	5	0-1 year	Water damage
	Doors - Wood Doors include hw	2nd Floor - East	4	EA	7	10+ years	vvater damage
	Drinking Fountains - Single Fountain	2nd Floor - East	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor - East	1,404	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor - East	10	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor - East	71	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor - East	862	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - East	747	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor - North	984	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor - North	984	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor - North	904	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor - North	870	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - North	387	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor - West	1,275	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor - West	1,275	SF	, 5	0-1 year	Water damage
	Doors - Wood Doors include hw	2nd Floor - West	4	EA	7	10+ years	vvater damage
	Drinking Fountains - Single Fountain	2nd Floor - West	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor - West	1,287	SF	7 7	10+ years	
			•	SF EA		•	
	Lighting - Lay-in	2nd Floor - West	10	EA EA	7 7	6-10 years	
	Student Lockers - One Tier	2nd Floor - West	81	EA	,	10+ years	



atego	ry : Interior		В	uilding	: Linked	l Addition-Arts	_Unit A
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor - West	903	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - West	733	SF	7	10+ years	
afety							
	Metal Detector	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	4	EA	7	6-10 years	
	Security Cameras	Entire Building	3	EA	7	6-10 years	
airs							
	Ceiling - Lay-in	NE - Stair 4	185	SF	7	10+ years	
	Floor - Tile	NE - Stair 4	52	SF	7	10+ years	
	Handrails	NE - Stair 4	53	LF	7	10+ years	
	Lighting - Lay-in	NE - Stair 4	2	EA	7	6-10 years	
	Stairs - Terrazzo	NE - Stair 4	100	LF	7	10+ years	
	Walls - Concrete Block	NE - Stair 4	945	SF	7	10+ years	
	Ceiling - Lay-in	NW - Stair 3	185	SF	7	10+ years	
	Floor - Terrazzo	NW - Stair 3	53	SF	7	10+ years	
	Floor - Tile	NW - Stair 3	52	SF	7	10+ years	
	Handrails	NW - Stair 3	53	LF	7	10+ years	
	Lighting - Lay-in	NW - Stair 3	2	EA	7	6-10 years	
	Stairs - Terrazzo	NW - Stair 3	100	LF	7	10+ years	
	Walls - Concrete Block	NW - Stair 3	945	SF	7	10+ years	
	Ceiling - Exposed	SE - Auditorium/Mech. Access ne	196	SF	7	10+ years	
	Floor - Concrete	SE - Auditorium/Mech. Access ne	113	SF	7	10+ years	
	Handrails	SE - Auditorium/Mech. Access ne	52	LF	7	10+ years	
	Lighting - Pendent/Surface	SE - Auditorium/Mech. Access ne	2	ĒΑ	7	6-10 years	
	Lighting - Wall Mounted	SE - Auditorium/Mech. Access ne	1	EΑ	7	6-10 years	
	Stairs - Concrete	SE - Auditorium/Mech. Access ne	100	LF	7	10+ years	
	Walls - Concrete Block	SE - Auditorium/Mech. Access ne	1,175	SF	6	10+ years	
	Ceiling - Lay-in	SE - Stair 6	279	SF	7	10+ years	
	Ceiling - Lay-in	SE - Stair 6	16	SF	5	1-2 years	Water damage
	Ceiling - Plaster/Drywall	SE - Stair 6	83	SF	7	10+ years	water damage
	Floor - Terrazzo	SE - Stair 6	84	SF	7	10+ years	
	Floor - Tile	SE - Stair 6	85	SF	7	10+ years	
	Handrails	SE - Stair 6	72	LF	7	10+ years	
	Lighting - Lay-in	SE - Stair 6	3	EA	7	6-10 years	
	Stairs - Terrazzo	SE - Stair 6	140	LF	7	•	
	Walls - Concrete Block	SE - Stair 6 SE - Stair 6	1,936	SF	7 7	10+ years	
				SF SF	7 7	10+ years	
	Ceiling - Exposed Floor - Concrete	SW - Auditorium/Mech. Access	196	SF	7 7	10+ years	
		SW - Auditorium/Mech. Access	113			10+ years	
	Handrails	SW - Auditorium/Mech. Access	52	LF	7	10+ years	
	Lighting - Pendent/Surface	SW - Auditorium/Mech. Access	1	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	SW - Auditorium/Mech. Access	1	EA	6	6-10 years	



Catego	ry : Interior	Building : Linked Addition-Arts_Unit A							
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Stairs - Concrete	SW - Auditorium/Mech. Access	100	LF	7	10+ years			
	Walls - Concrete Block	SW - Auditorium/Mech. Access	1,175	SF	7	10+ years			
	Ceiling - Lay-in	SW - Stair 5	295	SF	6	10+ years			
	Ceiling - Plaster/Drywall	SW - Stair 5	83	SF	7	10+ years			
	Floor - Terrazzo	SW - Stair 5	84	SF	7	10+ years			
	Handrails	SW - Stair 5	72	LF	7	10+ years			
	Lighting - Lay-in	SW - Stair 5	3	EA	7	6-10 years			
	Stairs - Terrazzo	SW - Stair 5	140	LF	7	10+ years			
	Walls - Concrete Block	SW - Stair 5	1,936	SF	7	10+ years			
Vertical (Conveyance								
	Elevator - Lula	Entire Building	1	EA	7	10+ years			
	Wheelchair Lift - Platform Lift	Entire Building	1	EA	7	10+ years			

Campus Name: Kenwood HS Page : 94 of 115 Assessment Date: 07/08/2024



Category : Exterior Building : Linked Addition-Athletic Building_Unit C

Categor	ry : Exterior		Б	unuing	Linked		etic Building_Unit C
			0			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance							
	Entrance Control - Audio and Video	1 - Main	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	1 - Main	6	EA	6	10+ years	
	Exterior Doors - Side lite	1 - Main	9	EA	6	10+ years	
	Exterior Doors - Transom Lite	1 - Main	6	EA	6	10+ years	
	Exterior Stairs - Concrete	1 - Main	84	LF	5	2-5 years	Minor Cracks
	Power Door Operator and Controls	1 - Main	1	EΑ	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	1 - Main	102	LF	6	10+ years	
	Ramps - Concrete	1 - Main	51	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	1 - Main	40	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	1.1 - N	2	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	1.1 - N	104	LF	6	10+ years	
	Ramps - Concrete	1.1 - N	52	LF	6	10+ years	
	Exterior Doors - Side lite	1.2 - Courtyard 1	3	EA	6	10+ years	
	Exterior Doors - Store Front	1.2 - Courtyard 1	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	1.2 - Courtyard 1	2	EA	6	10+ years	
	Exterior Stairs - Concrete	1.2 - Courtyard 1	10	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	2	2	EA	6	10+ years	
	Exterior Doors - Side lite	2	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	2	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	3	2	EA	6	10+ years	
	Exterior Doors - Side lite	3	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	3	2	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	4	2	EA	6	10+ years	
	Exterior Stairs - Concrete	4	24	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	5	6	EA	6	10+ years	
	Exterior Doors - Side lite	5	9	EA	6	10+ years	
	Exterior Doors - Transom Lite	5	6	EA	6	10+ years	
	Exterior Stairs - Concrete	5	40	LF	6	10+ years	
	Ramps - Concrete	5	8	LF	6	10+ years	
	Exterior Doors - Side lite	5.1 - Courtyard 1	3	EA	6	10+ years	
	Exterior Doors - Store Front	5.1 - Courtyard 1	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	5.1 - Courtyard 1	2	EA	6	10+ years	
	Exterior Stairs - Concrete	5.1 - Courtyard 1	10	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	RAD - E	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	RAD - NE	2	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	RAD - NE	6	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	RAD - SE	1	EA	6	10+ years	
Foundation	on						
	Foundation - Concrete	Entire Building	1,128	LF	7	10+ years	
	Foundation - Concrete	Entire Building	5	LF	6	10+ years	
	Superstructure - Metal Deck/ Concrete	Entire Building	66,030	SF	7	10+ years	
	Capation and Motor Door Control	_manag	33,330	٥.	•	. o . youro	

Campus Name: Kenwood HS Page: 95 of 115 Assessment Date: 07/08/2024



Catego	ry : Exterior		В	Building : Linked Addition-Athletic Building_Unit C						
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments			
loup	Topping	Location	Quantity	OOW	Ivalik	Replacement	Comments			
	Superstructure - Metal Deck/ Concrete Topping	Entire Building	150	SF	6	6-10 years	Link 2nd floor, cracking			
ghting										
	Exterior Lighting - Wall Mounted	Entire Building	37	EA	6	10+ years				
	Exterior Lighting - Wall Mounted	Entire Building	4	EA	5	2-5 years				
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	1-2 years	Missing cover			
oof Sys	stem									
•	Access Ladder - Metal	D	1	EA	7	10+ years				
	Coping - Metal	D	506	LF	6	10+ years				
	Downspouts - Interior Downspouts	D	682	LF	6	10+ years				
	Parapet - Parapet < 16" Height	D	506	LF	6	10+ years				
	Roof - Modified Bitumen	D	14,282	SF	5	2-5 years				
	Roof Hatch - Metal	D	1	EA	4	0-1 year	Hatch won't stay open, unsafe to access			
	Roof Structure - Steel / Metal Deck/ Concrete Topping	D	14,282	SF	7	10+ years				
	Coping - Metal	E	958	LF	6	10+ years				
	Downspouts - Interior Downspouts	Ē	440	LF	6	10+ years				
	Parapet - Parapet < 16" Height	Ē	958	LF	6	10+ years				
	Roof - Modified Bitumen	Ē	16,308	SF	5	2-5 years				
	Roof - Modified Bitumen	Ē	2,500	SF	4	1-2 years	Leaks, bubbling, cracking			
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Ē	18,808	SF	7	10+ years	Loaks, babbing, dracking			
/alls										
	Canopy - Concrete/ Stucco	Entire Building	90	SF	6	10+ years				
	Canopy - Concrete/ Stucco	Entire Building	10	SF	4	0-1 year	Exposed rebar, courtyard			
	Exterior Walls - Brick	Entire Building	20,280	SF	6	10+ years				
	Exterior Walls - Brick	Entire Building	30	SF	5	2-5 years				
	Exterior Walls - Precast Panel Wall	Entire Building	14,984	SF	6	10+ years				
indows										
	Guard - Guards perforated	Entire Building	1,384	SF	6	10+ years				
	Lintels - Concrete	Entire Building	518	LF	6	10+ years				
	Lintels - Steel	Entire Building	30	LF	6	10+ years				
	Storefront Windows	Entire Building	320	SF	6	10+ years				
	Windows - Casement Aluminum Double-	Entire Building	3,736	SF	6	10+ years				
		= =	2,. 33		-	,				



Catego	ry : Electrical		В	uilding	: Linked		etic Building_Unit C
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	ncy System	Location	Quantity	OOW	IVALIK	Replacement	Comments
<u>=merger</u>	Emergency A/C Power - Corridors and	Entire Building	20 112	SF	6	10	
	Stairs	· ·	20,113		6	10+ years	
	Emergency A/C Power - Gym	Entire Building	8,000	SF	6	10+ years	Location changed for clarification as there are gyms on both the 1st and 2nd floors.
	Emergency A/C Power - Pool	Entire Building	4,000	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,016	SF	6	10+ years	
	Exit Signs - Corridors and Stairs	Entire Building	16	EA	6	6-10 years	Rank adjusted based on current observations that no exit signs need to be added or moved.
	Exit Signs - Gym	Entire Building	8	EA	6	6-10 years	Location changed for clarification as there are gyms on both the 1st and 2nd floors. Rank adjusted based or current observations that no exit signs need to be added or moved.
	Exit Signs - Pool	Entire Building	2	EA	6	6-10 years	Rank adjusted based on current observations that no exit signs need to be added or moved.
	Security System - CCTV	Entire Building	66,180	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	66,180	SF	6	6-10 years	
Main Se	rvice						
	PA System	Entire Building	8,000	SF	6	6-10 years	Served by Bldg. B.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	6	EA	7	10+ years	Location changed for clarification. Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Location changed for clarification. Rank, Reason and Priority Rep changed as an open breaker slot exposes live conductors presenting live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	Quantity changed as total has been divided/aggregated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	0-1 year	Rank, Reason and Priority Rep changed as the panel face has a 4-i by 4-in. opening which exposes live conductors presenting a live front condition. Location changed for clarification.



Catego	ry : Electrical		В	uilding	: Linked	d Addition-Ath	letic Building_Unit C
_				_		Recommend	<u>-</u>
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Distribution Panels - Less than 400 amp	Entire Building	2	EA	7	10+ years	
	Transformers - 277/480 - 120/208	Entire Building	3	EA	7	10+ years	Location changed for clarification.
Catego	ry : Fire Protection		В	uilding	: Linked	d Addition-Ath	letic Building_Unit C
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Strobe Lights	Entire Building	66,180	SF	6	10+ years	
	Fire Alarm_System	Entire Building	66,180	SF	6	6-10 years	FACP is in Bldg. B.
Catego	ry : Mechanical		В	uilding	: Linked		letic Building_Unit C
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond							
	Condensing Unit- Roof Mounted - 5-10 tons	Roof	1	EA	2	0-1 year	Rank, Reason and Priority Rep changed to note that the unit is nonfunctional and obsolete and has been abandoned in place. No CPS Asset Tag present.
Air Hand	lling Systems						
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Mechanical Room	1	EA	5	6-10 years	Associated with AHU-11.
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Mechanical Room	2	EA	5	6-10 years	Associated with AHU-8 (undergoing repairs at the time of assessment) and AHU-9.
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Mechanical Room	2	EA	5	6-10 years	Associated with AHU-10 and AHU-11. Location changed for clarification.
	Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 10001-15000 cfm	Mechanical Room - AHU-10	1	EA	6	10+ years	AHU-10. Location changed for clarification. No CPS Asset Tag present.
	Air Intake	Mechanical Room - AHU-10	1	EA	6	10+ years	Location changed for clarification. Quantity changed as total has been divided/aggregated.
	Zone Dampers	Mechanical Room - AHU-10	3	EA	6	10+ years	Quantity changed as total has been divided/aggregated.
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 8001-12000 cfm	Mechanical Room - AHU-11	1	EA	6	10+ years	AHU-11. No CPS Asset Tag presen
	Air Intake Air Handling Unit- Package Multi Zone- Indoor- Steam Coils - 10001-15000 cfm	Mechanical Room - AHU-11 Mechanical Room - AHU-8	1 1	EA EA	6 6	10+ years 6-10 years	Location changed for clarification. AHU-8

Campus Name: Kenwood HS Page: 98 of 115 Assessment Date: 07/08/2024



Catego	ry : Mechanical	5015 S Blackstone AVENUE, Chicago, IL 60615 Building: Linked Addition-Athletic Building_Unit C						
Jaicgo	y : Mcchaileai			unung	. Lilikee	Recommend	ctic Building_Offit O	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Air Intake	Mechanical Room - AHU-8	1	EA	6	6-10 years		
	Zone Dampers	Mechanical Room - AHU-8	2	EA	6	6-10 years	Not visible; internal to the equipment	
	Air Handling Unit- Package Multi Zone-	Mechanical Room - AHU-9	1	EA	6	6-10 years	AHU-9. No CPS Asset Tag present.	
	Indoor- Steam Coils - 15001-20000 cfm					,	01	
	Air Intake	Mechanical Room - AHU-9	1	EA	6	6-10 years		
	Zone Dampers	Mechanical Room - AHU-9	5	EA	6	6-10 years		
Boiler Sy	estems							
	Condensate Pump	Mechanical Room	1	EA	5	6-10 years	No CPS Asset Tag present.	
	Piping - Condensate Pipe- Steel	Mechanical Room	360	LF	6	10+ years		
	Piping - Steam Pipe- Steel	Mechanical Room	360	LF	6	10+ years		
-leating								
	Cabinet Heaters - With Hot Water Coil	Entire Building	1	EA	5	6-10 years	Location changed for clarification.	
	Cabinet Heaters - With Hot Water Coil	Entire Building	1	EA	4	0-1 year	Location changed for clarification.	
							Reason and Priority Rep changed as	
							a missing cover exposes hot parts	
							presenting a risk of personal injury	
							and live conductors presenting a live	
		M 1 : 15		_ ^	_	0.40	front condition.	
	Unit Heater - Steam	Mechanical Room	4	EA	5	6-10 years	Location changed for clarification.	
							Rank, Reason and Priority Rep adjusted based on current	
							observations and per review with Building Engineer.	
							building Engineer.	
empera	ture Control							
	DDC System	Entire Building	66,180	SF	7	10+ years	O	
	Electric Thermostat	Entire Building	4	EA	5	6-10 years	Quantity changed to match current	
							observations. Location changed for	
	Thermostats - DDC	Entire Building	15	EA	7	10+ years	clarification.	
		9				, , , , , , , , , , , , , , , , , , , ,		
Ventilatio	on Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	E-26, toilet exhaust	
_		g				•		
Catego	ry : Plumbing		В	uilding	: Linked	Addition-Athl	etic Building_Unit C	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
		Location	Qualitity	UUIVI	Nalik	Nepiacement	Comments	
Hot Wate						0.10		
	Gas Heater - Greater than 600000 BTU/HR	Mechanical Room	1	EA	5	6-10 years	Location changed for clarification.	
	Hot Water Storage Tank_Gas - 501 - 1000	Mechanical Room	1	EA	5	6-10 years	Location changed for clarification.	
	Gallons							



Catego	ry : Plumbing		В	uilding	: Linked	d Addition-Ath	letic Building_Unit C
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Dining							
_Piping	Domestic Piping-Hot Water Return Lines	Entire Building	66,180	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	66,180	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	66,180	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	66,180	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	66,180	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	66,180	SF	6	10+ years	
	Sanitary Piping	Entire Building	66,180	SF	6	10+ years	
	Storm Piping	Entire Building	66,180	SF	6	10+ years	
	Vent Piping	Entire Building	66,180	SF	6	10+ years	
Pool Sys	stams						
_1 001 0y3	Pool Drain Piping	Basement	125	LF	6	10+ years	
	Pool Filtration System including Pump	Basement	1	EA	7	6-10 years	Quantity changed based on current observations that there is one pool filtration system; misdocumented in previous assessment. Rank and Priority Rep changed as the system is in the midst of being replaced at the time of assessment.
	Pool Hot Water Heater - Gas Fired	Basement	1	EA	7	10+ years	
	Pool Supply and Return Piping	Basement	250	LF	6	6-10 years	
Pumps							
	Pumps - Ejector-Duplex	Mechanical Room	1	EA	6	6-10 years	Item Type changed to match current observations. No CPS Asset Tag present.

Category : Room

Building : Linked Addition-Athletic Building_Unit C

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Lay-in	174A - Athletic Director	85	SF	7	10+ years	
	Doors - Wood Doors inclu hw	174A - Athletic Director	1	EA	7	10+ years	
	Floor - Tile	174A - Athletic Director	85	SF	7	10+ years	
	Lighting - Pendent/Surface	174A - Athletic Director	2	EΑ	6	6-10 years	
	Power Distribution	174A - Athletic Director	2	EΑ	7	10+ years	
	Walls - Concrete Block	174A - Athletic Director	283	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Linked	d Addition-Ath	letic Building_Unit C
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Exposed	179F Office	80	SF	6	10+ years	
	Doors - Wood Doors inclu hw	179F Office	1	EA	7	10+ years	
	Floor - Tile	179F Office	80	SF	7	10+ years	
	Lighting - Pendent/Surface	179F Office	1	EA	7	6-10 years	
	Walls - Concrete Block	179F Office	274	SF	7	10+ years	
	Ceiling - Lay-in	179G Office	155	SF	7	10+ years	
	Doors - Wood Doors inclu hw	179G Office	1	EA	6	10+ years	
	Floor - Tile	179G Office	155	SF	7	10+ years	
	Lighting - Pendent/Surface	179G Office	4	EA	7	6-10 years	
	Power Distribution	179G Office	16	EA	7	10+ years	
	Walls - Concrete Block	179G Office	369	SF	7	10+ years	
	Ceiling - Lay-in	185J Office	123	SF	7	10+ years	
	Ceiling - Lay-in	185J Office	4	SF	5	1-2 years	Water damage
	Doors - Side-lite	185J Office	32	SF	7	10+ years	· ·
	Doors - Wood Doors inclu hw	185J Office	1	EA	7	10+ years	
	Floor - Tile	185J Office	127	SF	7	10+ years	
	Lighting - Pendent/Surface	185J Office	4	EA	7	6-10 years	
	Power Distribution	185J Office	8	EA	7	10+ years	
	Walls - Concrete Block	185J Office	351	SF	7	10+ years	
	Ceiling - Lay-in	C-102B - Boys Locker Room Office	80	SF	7	10+ years	
	Doors - Steel Doors incl hw	C-102B - Boys Locker Room Office	2	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	C-102B - Boys Locker Room Office	80	SF	7	10+ years	
	Lighting - Lay-in	C-102B - Boys Locker Room Office	1	ĒΑ	7	6-10 years	
	Power Distribution	C-102B - Boys Locker Room Office	2	ĒΑ	7	10+ years	
	Walls - Concrete Block	C-102B - Boys Locker Room Office	274	SF	7	10+ years	
	Ceiling - Lay-in	C-105B - Girls Locker Room Office	72	SF	7	10+ years	
	Doors - Steel Doors incl hw	C-105B - Girls Locker Room Office	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	C-105B - Girls Locker Room Office	72	SF	7	10+ years	
	Lighting - Lay-in	C-105B - Girls Locker Room Office	1	EA	7	6-10 years	
	Power Distribution	C-105B - Girls Locker Room Office	4	EΑ	7	10+ years	
	Walls - Concrete Block	C-105B - Girls Locker Room Office	259	SF	7	10+ years	
	Wallo Colloidto Block	O TOOD CINE ESCHOL ROOM CINE	200	O.	•	101 youro	
_Gvmnas	ia						
_Суппаз	Bleacher Seating	187 Gym	160	EA	7	10+ years	
	Ceiling - Exposed	187 Gym	6,580	SF	7	10+ years	
	Doors - Steel Doors incl hw	187 Gym	6	EA	7	10+ years	
	Floor - Wood	187 Gym	6,580	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	187 Gym	12	EA	7	6-10 years	
	Scoreboards	187 Gym	12	EA	7	,	
	Scoreboards Sound System	187 Gym	1	EA	7	6-10 years 6-10 years	
	Storage/ Closet	187 Gym	217	SF	7 7	10+ years	
	Walls - Concrete Block		7,872	SF SF	7 7	-	
		187 Gym	7,872 384	SF EA		10+ years	
	Bleacher Seating	257 Gym (originally 206)		SF	7 7	10+ years	
	Ceiling - Exposed	257 Gym (originally 206)	8,836	SF	1	10+ years	



Category : Room			Building : Linked Addition-Athletic Building_Unit C						
				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Wood Doors inclu hw	257 Gym (originally 206)	10	EA	7	10+ years			
	Floor - Wood	257 Gym (originally 206)	8,836	SF	7	10+ years			
	Lighting - Metal Halide/ High Pressure Sodium	257 Gym (originally 206)	16	EA	7	6-10 years			
	Scoreboards	257 Gym (originally 206)	1	EA	7	6-10 years			
	Sound System	257 Gym (originally 206)	1	EA	7	6-10 years			
	Storage/ Closet	257 Gym (originally 206)	554	SF	7	10+ years			
	Walls - Concrete Block	257 Gym (originally 206)	5,556	SF	7	10+ years			
Locker/S	Shower Room								
	Accessories	179 Boys Lockers	3,471	SF	7	6-10 years			
	Benches, ped mounted	179 Boys Lockers	120	ĹF	7	10+ years			
	Ceiling - Plaster/Drywall	179 Boys Lockers	3,471	SF	7	10+ years			
	Doors - Steel Doors incl hw	179 Boys Lockers	2	EA	7	10+ years			
	Floor - Concrete Epoxy/ Painted	179 Boys Lockers	2,381	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	179 Boys Lockers	1,070	SF	7	6-10 years			
	Floor - Tile Ceramic/ Porcelain	179 Boys Lockers	10	SF	5	1-2 years	Missing		
	Floor Drain	179 Boys Lockers	4	EA	7	10+ years	Missing		
	Floor Drain	179 Boys Lockers	9	EA	7	-			
						10+ years			
	Hand Dryer	179 Boys Lockers	2	EΑ	7	6-10 years			
	Lavatory	179 Boys Lockers	2	EΑ	6	10+ years			
	Lighting - Pendent/Surface	179 Boys Lockers	39	EA	7	6-10 years			
	Partitions	179 Boys Lockers	2	EA	7	10+ years			
	Showers	179 Boys Lockers	20	EA	7	10+ years			
	Storage/ Closet	179 Boys Lockers	17	SF	7	10+ years			
	Student Lockers - One Tier	179 Boys Lockers	204	EA	7	10+ years			
	Student Lockers - Two Tier	179 Boys Lockers	39	EA	7	10+ years			
	Urinals	179 Boys Lockers	3	EA	7	10+ years			
	Walls - Concrete Block	179 Boys Lockers	2,381	SF	7	10+ years			
	Walls - Structural Glazed Tile	179 Boys Lockers	1,411	SF	7	10+ years			
	Water Closet	179 Boys Lockers	2	EA	7	10+ years			
	Accessories	185 Girls Lockers	3,332	SF	7	6-10 years			
	Benches, ped mounted	185 Girls Lockers	66	LF	7	10+ years			
	Ceiling - Exposed	185 Girls Lockers	3,332	SF	7	10+ years			
	Doors - Steel Doors incl hw	185 Girls Lockers	2	ĒΑ	7	10+ years			
	Floor - Epoxy/ Painted	185 Girls Lockers	2,370	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	185 Girls Lockers	962	SF	7	10+ years			
	Floor Drain	185 Girls Lockers	18	EA	7	10+ years			
	Hand Dryer	185 Girls Lockers	20	EA	7	6-10 years			
	Lavatory	185 Girls Lockers	20	EA	7	10+ years			
	Lighting - Pendent/Surface	185 Girls Lockers	63	EA	7	6-10 years			
	Partitions		4						
		185 Girls Lockers		EΑ	7	10+ years			
	Showers	185 Girls Lockers	18	EA	7	10+ years			
	Storage/ Closet	185 Girls Lockers	78	SF	7	10+ years			



Category : Room		В	uilding	: Linked	Building : Linked Addition-Athletic Building_Unit C						
0	Ham Time	Location	0	11014	Devil	Recommend	Comments				
Group	Item - Type Student Lockers - One Tier	Location	Quantity	UOM EA	Rank	Replacement	Comments				
	Student Lockers - One Her Student Lockers - Two Tier	185 Girls Lockers 185 Girls Lockers	82 306	EA	7 7	10+ years 10+ years					
	Walls - Concrete Block	185 Girls Lockers	2,100	SF	7	10+ years					
	Walls - Structural Glazed Tile	185 Girls Lockers	1,323	SF	7	10+ years					
	Water Closet	185 Girls Lockers	1,323	EA	7	10+ years					
	Accessories	1st Floor East Team Locker Room	429	SF	7	6-10 years					
		182			,	0-10 years					
	Ceiling - Splined (Moister Resistance)	1st Floor East Team Locker Room 182	429	SF	7	10+ years					
	Doors - Steel Doors incl hw	1st Floor East Team Locker Room 182	1	EA	7	10+ years					
	Floor - Concrete Epoxy/ Painted	1st Floor East Team Locker Room 182	429	SF	7	10+ years					
	Floor Drain	1st Floor East Team Locker Room 182	3	EA	7	10+ years					
	Lighting - Pendent/Surface	1st Floor East Team Locker Room 182	4	EA	7	6-10 years					
	Partitions	1st Floor East Team Locker Room 182	1	EA	7	10+ years					
	Urinals	1st Floor East Team Locker Room 182	1	EA	7	10+ years					
	Walls - Concrete Block	1st Floor East Team Locker Room 182	295	SF	7	10+ years					
	Walls - Tile Ceramic/ Porcelain	1st Floor East Team Locker Room 182	966	SF	7	10+ years					
	Water Closet	1st Floor East Team Locker Room 182	1	EA	7	10+ years					
	Accessories	1st Floor West Team Locker Room 180B	405	SF	7	6-10 years					
	Benches, ped mounted	1st Floor West Team Locker Room 180B	36	LF	7	10+ years					
	Ceiling - Exposed	1st Floor West Team Locker Room 180B	405	SF	7	10+ years					
	Doors - Wood Doors inclu hw	1st Floor West Team Locker Room 180B	1	EA	7	10+ years					
	Floor - Tile Ceramic/ Porcelain	1st Floor West Team Locker Room 180B	255	SF	7	10+ years					
	Floor - Tile Ceramic/ Porcelain	1st Floor West Team Locker Room 180B	150	SF	4	0-1 year	Floor cut out, tile removed				
	Floor Drain	1st Floor West Team Locker Room 180B	1	EA	7	10+ years					
	Lighting - Pendent/Surface	1st Floor West Team Locker Room 180B	10	EA	7	6-10 years					
	Walls - Concrete Block	1st Floor West Team Locker Room	645	SF	7	10+ years					



Catego	ry : Room		В	uilding	: Linked	d Addition-Athl	etic Building_Unit C
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	W. II. O	180B	4.0	0=			
	Walls - Concrete Block	1st Floor West Team Locker Room	10	SF	4	0-1 year	Holes
	Water Closet	180B 1st Floor West Team Locker Room	1	EA	•	0.40	
	water Closet	180B	ı	EA	6	6-10 years	
	Accessories	C-102 Boys Pool (175)	826	SF	7	6-10 years	
	Benches, ped mounted	C-102 Boys Fool (175)	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	C-102 Boys Pool (175)	826	SF	7	10+ years	
	Doors - Steel Doors incl hw	C-102 Boys Pool (175)	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	C-102 Boys Pool (175)	796	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	C-102 Boys Pool (175)	30	SF	4	1-2 years	Damaged
	Floor Drain	C-102 Boys Pool (175)	9	EA	7	10+ years	Damaged
	Lavatory	C-102 Boys Pool (175)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	C-102 Boys Pool (175)	18	EA	7	6-10 years	
	Partitions	C-102 Boys Pool (175)	2	EA	7	10+ years	
	Showers	C-102 Boys Pool (175)	8	EA	7	10+ years	
	Storage/ Closet	C-102 Boys Pool (175)	35	SF	7	10+ years	
	Student Lockers - One Tier	C-102 Boys Pool (175)	3	EA	7	10+ years	
	Student Lockers - Two Tier	C-102 Boys Pool (175)	52	EA	7	10+ years	
	Urinals	C-102 Boys Pool (175)	1	EA	7	10+ years	
	Walls - Concrete Block	C-102 Boys Pool (175)	611	SF	7	10+ years	
	Walls - Structural Glazed Tile	C-102 Boys Pool (175)	611	SF	7	10+ years	
	Water Closet	C-102 Boys Pool (175)	2	EA	7	10+ years	
	Accessories	C-105 Girls Pool Locker Room (175)	895	SF	7	6-10 years	
	Benches, ped mounted	C-105 Girls Pool Locker Room (175)	16	LF	7	10+ years	
	Ceiling - Plaster/Drywall	C-105 Girls Pool Locker Room (175)	895	SF	7	10+ years	
	Doors - Steel Doors incl hw	C-105 Girls Pool Locker Room (175)	2	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	C-105 Girls Pool Locker Room (175)	895	SF	7	10+ years	
	Floor Drain	C-105 Girls Pool Locker Room (175)	11	EA	7	10+ years	
	Hand Dryer	C-105 Girls Pool Locker Room (175)	5	EA	7	6-10 years	
	Lavatory	C-105 Girls Pool Locker Room (175)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	C-105 Girls Pool Locker Room (175)	16	EA	7	6-10 years	
	Partitions	C-105 Girls Pool Locker Room (175)	3	EA	7	10+ years	
	Showers	C-105 Girls Pool Locker Room (175)	10	EA	7	10+ years	
	Storage/ Closet	C-105 Girls Pool Locker Room (175)	11	SF	7	10+ years	
	Student Lockers - One Tier	C-105 Girls Pool Locker Room (175)	3	EA	7	10+ years	
	Student Lockers - Two Tier	C-105 Girls Pool Locker Room (175)	52	EA	7	10+ years	
	Walls - Concrete Block	C-105 Girls Pool Locker Room (175)	637	SF	7	10+ years	
	Walls - Structural Glazed Tile	C-105 Girls Pool Locker Room (175)	637	SF	7	10+ years	
	Water Closet	C-105 Girls Pool Locker Room (175)	3	EA	7	10+ years	
_Mechani	cal/ Service Rooms		_				
	Janitor's Closet	1st Floor	9	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	160	SF	7	10+ years	



Category : Room Building : Linked Addition-Athletic E Group Item - Type Location Quantity UOM Rank Replacement Commod Replacement Janitor's Closet 2nd Floor 130 SF 7 10+ years Mechanical/ Service Rooms 2nd Floor 50 SF 7 10+ years Storage Room 2nd Floor 60 SF 7 10+ years Mechanical/ Service Rooms 3rd Floor 2,500 SF 7 10+ years Mechanical/ Service Rooms 3rd Floor 2,500 SF 7 10+ years	nments
GroupItem - TypeLocationQuantityUOMRankReplacementCommon Common	nments
Janitor's Closet2nd Floor130SF710+ yearsMechanical/ Service Rooms2nd Floor50SF710+ yearsStorage Room2nd Floor120SF710+ yearsStorage Room2nd Floor60SF710+ yearsMechanical/ Service Rooms3rd Floor2,500SF710+ years	
Mechanical/ Service Rooms2nd Floor50SF710+ yearsStorage Room2nd Floor120SF710+ yearsStorage Room2nd Floor60SF710+ yearsMechanical/ Service Rooms3rd Floor2,500SF710+ years	
Storage Room2nd Floor120SF710+ yearsStorage Room2nd Floor60SF710+ yearsMechanical/ Service Rooms3rd Floor2,500SF710+ years	
Storage Room 2nd Floor 60 SF 7 10+ years Mechanical/ Service Rooms 3rd Floor 2,500 SF 7 10+ years	
Mechanical/ Service Rooms 3rd Floor 2,500 SF 7 10+ years	
Mechanical/ Service Rooms Laundry Room 112 SF 7 10+ years	
Pool & Natatorium	
Bleachers Seating/Plank Seating C-101 40 EA 7 10+ years	
Ceiling - Exposed C-101 4,766 SF 7 10+ years	
Doors - Steel Doors incl hw C-101 3 EA 7 10+ years	
Floor - Tile Ceramic/ Porcelain C-101 2,838 SF 7 10+ years	
Lighting - Metal Halide/ High Pressure C-101 8 EA 7 6-10 years	
Sodium	
Lighting - Pendent/Surface C-101 3 EA 7 6-10 years	
Pool Basin C-101 1,928 SF 7 10+ years	
Pool Deck C-101 2,838 SF 7 10+ years	
Pool Deck Drains C-101 16 EA 7 10+ years	
Storage/ Closet C-101 134 SF 7 10+ years	
Walls - Concrete Block C-101 4,696 SF 7 10+ years	
Walls - Structural Glazed Tile C-101 1,806 SF 7 10+ years	
_Restroom	
Accessories 179G Restroom 5 SF 7 6-10 years	
Ceiling - Lay-in 179G Restroom 110 SF 7 10+ years	
Doors - Wood Doors inclu hw 179G Restroom 1 EA 7 10+ years	
Floor - Tile Ceramic/ Porcelain 179G Restroom 110 SF 7 10+ years	
Lavatory 179G Restroom 1 EA 7 10+ years	
Lighting - Pendent/Surface 179G Restroom 2 EA 7 6-10 years	
Partitions 179G Restroom 1 EA 7 10+ years	
Showers 179G Restroom 1 EA 7 10+ years	
Student Lockers - One Tier 179G Restroom 5 EA 7 10+ years	
Student Lockers - Two Tiers 179G Restroom 2 EA 7 10+ years	
Walls - Concrete Block 179G Restroom 325 SF 7 10+ years	
Water Closet 179G Restroom 1 EA 7 10+ years	
Accessories 185N Women Toilet/Locker 106 SF 7 6-10 years	
Ceiling - Lay-in 185N Women Toilet/Locker 96 SF 7 10+ years	
o ,	er damage
Doors - Wood Doors inclu hw 185N Women Toilet/Locker 1 EA 7 10+ years	
Floor - Tile Ceramic/ Porcelain 185N Women Toilet/Locker 106 SF 7 10+ years	
Floor Drain 185N Women Toilet/Locker 1 EA 7 10+ years	
Lavatory 185N Women Toilet/Locker 1 EA 7 10+ years	
Lighting - Pendent/Surface 185N Women Toilet/Locker 3 EA 6 6-10 years	
Lighting 1 Shadhidanado 10014 Wolffort Follow Education 0 E/1 0 0-10 years	



Catego	ry : Room		В	uilding	: Linked	Addition-Ath	letic Building_Unit C
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Showers	185N Women Toilet/Locker	1	EA	7	10+ years	
	Student Lockers - One Tier	185N Women Toilet/Locker	6	EA	6	10+ years	
	Walls - Concrete Block	185N Women Toilet/Locker	319	SF	7	10+ years	
	Water Closet	185N Women Toilet/Locker	1	EA	7	10+ years	
	Accessories	186 Girls	154	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	186 Girls	154	SF	7	10+ years	
	Doors - Wood Doors inclu hw	186 Girls	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	186 Girls	154	SF	7	10+ years	
	Floor Drain	186 Girls	1	EA	7	10+ years	
	Hand Dryer	186 Girls	1	EA	7	6-10 years	
	Lavatory	186 Girls	1	EA	7	10+ years	
	Lighting - Pendent/Surface	186 Girls	1	EA	7	6-10 years	
	Partitions	186 Girls	2	EA	7	10+ years	
	Walls - Concrete Block	186 Girls	490	SF	7	10+ years	
	Water Closet	186 Girls	2	EA	7	10+ years	
	Accessories	188 Boys	120	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	188 Boys	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	188 Boys	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	188 Boys	120	SF	7	10+ years	
	Floor Drain	188 Boys	1	EA	7	10+ years	
	Lavatory	188 Boys	1	EA	7	10+ years	
	Lighting - Pendent/Surface	188 Boys	2	EA	7	6-10 years	
	Partitions	188 Boys	1	EA	7	10+ years	
	Urinals	188 Boys	1	EA	7	10+ years	
	Walls - Concrete Block	188 Boys	441	SF	7	10+ years	
	Water Closet	188 Boys	1	EA	7	10+ years	
	Accessories	254 Girls	242	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	254 Girls	242	SF	7	10+ years	
	Doors - Wood Doors inclu hw	254 Girls	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	254 Girls	242	SF	7	10+ years	
	Floor Drain	254 Girls	1	EA	7	10+ years	
	Lavatory	254 Girls	3	EA	7	10+ years	
	Lighting - Pendent/Surface	254 Girls	4	EA	7	6-10 years	
	Partitions	254 Girls	4	EA	7	10+ years	
	Walls - Concrete Block	254 Girls	486	SF	7	10+ years	
	Water Closet	254 Girls	4	EA	7	10+ years	
	Accessories	256 Boys	198	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	256 Boys	198	SF	7	10+ years	
	Doors - Wood Doors inclu hw	256 Boys	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	256 Boys	198	SF	7	10+ years	
	Floor Drain	256 Boys	1	ĒΑ	7	10+ years	
	Lavatory	256 Boys	3	EA	7	10+ years	
	Lighting - Pendent/Surface	256 Boys	4	EΑ	7	6-10 years	
	Partitions	256 Boys	2	EΑ	7	10+ years	
			_		•	,	

Campus Name: Kenwood HS Page : 106 of 115 Assessment Date: 07/08/2024



Catego	ry : Room		В	uilding	: Linked	Addition-Athl	etic Building_Unit C		
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Urinals	256 Boys	3	EA	7	10+ years			
	Walls - Concrete Block	256 Boys	475	SF	7	10+ years			
	Water Closet	256 Boys	2	EA	7	10+ years			
	Accessories	2577C unisex	220	SF	7	6-10 years			
	Benches	2577C unisex	3	LF	7	10+ years			
	Ceiling - Lay-in	2577C unisex	220	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2577C unisex	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2577C unisex	220	SF	7	10+ years			
	Floor Drain	2577C unisex	2	EA	7	10+ years			
	Hand Dryer	2577C unisex	1	EA	7	6-10 years			
	Lavatory	2577C unisex	1	EA	7	10+ years			
	Lighting - Lay-in	2577C unisex	5	EA	7	6-10 years			
	Showers	2577C unisex	1	EA	7	10+ years			
	Student Lockers - One Tier	2577C unisex	4	EA	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	2577C unisex	600	SF	7	10+ years			
	Water Closet	2577C unisex	1	EA	7	10+ years			
Catego	ry : Classroom	R	uildina	· I inker	l Addition-Athl	etic Building Unit C			
Outego	1 9 1 0 10 3 3 1 0 0 111		Building : Linked Addition-Athletic Building_Unit C Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	om #237 (Regular Classroom)		,						
<u> </u>	Ceiling - Lay-in	2nd Floor	800	SF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	40	SF	5	0-1 year	Water damage		
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	water damage		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	810	SF	7	10+ years			
	Floor - Tile	2nd Floor	30	SF	4	0-1 year	Missing		
	Lighting - Lay-in	2nd Floor	20	EA	7	6-10 years	wiissii ig		
	Storage/ Closet	2nd Floor	48	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	961	SF	7	10+ years			
	vvalis - Coliciete Block	2110 11001	901	Si	,	10+ years			
_Classroo	om #238 (Regular Classroom)								
	Ceiling - Lay-in	2nd Floor	888	SF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	30	SF	5	0-1 year	Water damage		
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years	ŭ		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	908	SF	7	10+ years			
	Floor - Tile	2nd Floor	10	SF	4	0-1 year	Chipped		
	Lighting - Pendent/Surface	2nd Floor	20	ĒΑ	7	6-10 years	• •		
	Storage/ Closet	2nd Floor	48	SF	7	10+ years			
	Walls - Concrete Block	2nd Floor	1,012	SF	7	10+ years			



Catego	ry : Interior		В	Building : Linked Addition-Athletic Building_Unit C			
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	-					-	
	Ceiling - Lay-in	1st Floor East Connector	858	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor East Connector	4	SF	5	0-1 year	Water damage
	Doors - Steel Doors incl hw	1st Floor East Connector	2	EA	7	10+ years	Trate: damage
	Doors - Store Front	1st Floor East Connector	_ 1	EΑ	7	10+ years	
	Doors - Store Front	1st Floor East Connector	800	ĒΑ	7	10+ years	
	Doors - Wood Doors include hw	1st Floor East Connector	8	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor East Connector	862	SF	7	10+ years	
	Lighting - Lay-in	1st Floor East Connector	6	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor East Connector	558	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor East Corridor	992	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor East Corridor	2	ĒΑ	7	10+ years	
	Doors - Wood Doors include hw	1st Floor East Corridor	4	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor East Corridor	1	EΑ	7	6-10 years	
	Floor - Tile/Sheet	1st Floor East Corridor	992	SF	7	10+ years	
	Lighting - Lay-in	1st Floor East Corridor	7	ĒΑ	7	6-10 years	
	Walls - Concrete Block	1st Floor East Corridor	1,514	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor South Corridor	1,616	SF	7	10+ years	
	Doors - Side-lite	1st Floor South Corridor	1,250	SF	7	10+ years	
	Doors - Transom Window	1st Floor South Corridor	72	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor South Corridor	8	ĒΑ	7	10+ years	
	Floor - Tile/Sheet	1st Floor South Corridor	1,616	SF	7	10+ years	
	Lighting - Lay-in	1st Floor South Corridor	12	ĒΑ	7	6-10 years	
	Walls - Concrete Block	1st Floor South Corridor	1,359	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor West Connector	852	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor West Connector	10	SF	5	0-1 year	Water damage
	Doors - Side-lite	1st Floor West Connector	800	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor West Connector	3	ĒΑ	7	10+ years	
	Doors - Wood Doors include hw	1st Floor West Connector	4	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor West Connector	862	SF	7	10+ years	
	Lighting - Lay-in	1st Floor West Connector	6	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor West Connector	558	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor West Corridor	844	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor West Corridor	2	ĒΑ	7	10+ years	
	Doors - Wood Doors include hw	1st Floor West Corridor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor West Corridor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor West Corridor	844	SF	7	10+ years	
	Lighting - Lay-in	1st Floor West Corridor	6	ĒΑ	7	6-10 years	
	Walls - Concrete Block	1st Floor West Corridor	1,265	SF	7	10+ years	
	Ceiling - Exposed	1st flr north	900	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st flr north	2	ĒΑ	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st flr north	900	SF	7	10+ years	
	Lighting - Pendent/Surface	1st flr north	7	EΑ	6	6-10 years	
	Student Lockers - One Tier	1st flr north	20	EΑ	7	10+ years	



Catego	ry : Interior		В	uilding	: Linked		etic Building_Unit C
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st flr north	2,000	SF	7	10+ years	
	Ceiling - Lay-in	2nd East Connector	856	SF	7	10+ years	
	Ceiling - Lay-in	2nd East Connector	8	SF	5	0-1 year	Water damage
	Doors - Side-lite	2nd East Connector	1,200	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd East Connector	4	EA	7	10+ years	
	Floor - Tile/Sheet	2nd East Connector	852	SF	7	10+ years	
	Floor - Tile/Sheet	2nd East Connector	10	SF	4	1-2 years	Chipped
	Lighting - Lay-in	2nd East Connector	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd East Connector	360	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor East Corridor	992	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor East Corridor	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor East Corridor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor East Corridor	992	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor East Corridor	7	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor East Corridor	1,514	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor South Corridor	1,063	SF	7	10+ years	
	Doors - Transom Window	2nd Floor South Corridor	72	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor South Corridor	8	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor South Corridor	1,063	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor South Corridor	[′] 12	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor South Corridor	1,351	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor West Corridor	982	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor West Corridor	10	SF	5	0-1 year	Water damage
	Doors - Steel Doors incl hw	2nd Floor West Corridor	2	ĒΑ	7	10+ years	3.
	Drinking Fountains - Single Fountain	2nd Floor West Corridor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor West Corridor	992	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor West Corridor	7	ĒΑ	7	6-10 years	
	Walls - Concrete Block	2nd Floor West Corridor	1,514	SF	7	10+ years	
	Ceiling - Lay-in	2nd West Connector	852	SF	7	10+ years	
	Ceiling - Lay-in	2nd West Connector	8	SF	5	0-1 year	Missing
	Doors - Side-lite	2nd West Connector	1,200	SF	7	10+ years	Miconig
	Doors - Wood Doors include hw	2nd West Connector	4	EA	7	10+ years	
	Floor - Tile/Sheet	2nd West Connector	858	SF	7	10+ years	
	Floor - Tile/Sheet	2nd West Connector	4	SF	4	1-2 years	Cracked
	Lighting - Lay-in	2nd West Connector	6	EA	7	6-10 years	5.45.164
	Walls - Plaster/Drywall	2nd West Connector	360	SF	7	10+ years	
	Talle Tactor Bry Trail		300	0.	•	10. 300.0	
Safety							
-	Security Cameras	1st Floor	8	EA	7	6-10 years	
Stairs							
	Ceiling - Exposed	North East	241	SF	7	10+ years	
	Ceiling - Lay-in	North East	451	SF	7	10+ years	
	Floor - Concrete	North East	115	SF	7	10+ years	
						•	

Campus Name: Kenwood HS Page : 109 of 115 Assessment Date: 07/08/2024



Catego	ry : Interior		В	uilding	: Linked	Addition-Athl	letic Building_Unit C
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Concrete	North East	35	SF	7	10+ years	
	Floor - Terrazzo	North East	98	SF	7	10+ years	
	Floor - Tile	North East	165	SF	7	10+ years	
	Handrails	North East	72	LF	7	10+ years	
	Lighting - Lay-in	North East	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	North East	2	EA	7	6-10 years	
	Stairs - Terrazzo	North East	169	LF	7	10+ years	
	Stairs - Terrazzo	North East	4	LF	5	1-2 years	Chipped
	Walls - Concrete Block	North East	3,115	SF	7	10+ years	
	Ceiling - Exposed	North West	241	SF	7	10+ years	
	Ceiling - Lay-in	North West	451	SF	7	10+ years	
	Floor - Concrete	North West	150	SF	7	10+ years	
	Floor - Terrazzo	North West	98	SF	7	10+ years	
	Floor - Tile	North West	165	SF	7	10+ years	
	Handrails	North West	72	LF	7	10+ years	
	Lighting - Lay-in	North West	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	North West	2	EA	7	6-10 years	
	Stairs - Terrazzo	North West	173	LF	7	10+ years	
	Walls - Concrete Block	North West	3,115	SF	7	10+ years	
	Ceiling - Lay-in	South East	247	SF	7	10+ years	
	Floor - Concrete	South East	100	SF	7	10+ years	
	Floor - Terrazzo	South East	70	SF	7	10+ years	
	Floor - Tile	South East	80	SF	7	10+ years	
	Handrails	South East	36	LF	7	10+ years	
	Lighting - Lay-in	South East	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	South East	1	EΑ	7	6-10 years	
	Stairs - Terrazzo	South East	115	LF	7	10+ years	
	Walls - Concrete Block	South East	1,169	SF	7	10+ years	
	Ceiling - Lay-in	South West	231	SF	7	10+ years	
	Ceiling - Lay-in	South West	16	SF	5	0-1 year	Water damage
	Floor - Concrete	South West	100	SF	7	10+ years	•
	Floor - Terrazzo	South West	70	SF	7	10+ years	
	Floor - Tile	South West	80	SF	7	10+ years	
	Handrails	South West	48	LF	7	10+ years	
	Lighting - Lay-in	South West	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	South West	1	EA	7	6-10 years	
	Stairs - Terrazzo	South West	115	LF	7	10+ years	
	Walls - Concrete Block	South West	1,169	SF	7	10+ years	
			,			,	



Category : Site Building : Site

Calego	ry : Site		В	uilding	: Site		
_		1	0	11014	D	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic_	01	NI		Ε.		40	
	Goalpost	North	2	EA EA	7	10+ years	
	Lighting	North	32		6	10+ years	
	Metal Bleachers	North	311	LF CF	7	10+ years	
	Surface - Synthetic	North	62,160	SF	7	10+ years	
	Surface - Synthetic	North	21,472	SF	7	10+ years	
Civil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	12	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	5	2-5 years	Courtyard drainage issues
	Civil/ Drainage - Site Manhole	Entire Site	21	EA	6	10+ years	
encina							
ania	Fencing - Chain Link	Entire Site	136	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	2,513	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	40	LF	5	2-5 years	
andsca	ne						
	Benches	Entire Site	11	EA	7	10+ years	
	Benches	Entire Site	3	EΑ	5	2-5 years	Branch, wood
	Irrigation	Entire Site	62,160	SF	6	10+ years	2.4
	Landscape - Grass	Entire Site	40,984	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	550	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	43,849	SF	6	10+ years	Some repairs
	Landscape - Hardscape- Concrete	Entire Site	475	SF	4	1-2 years	Spalling, cracks
	Landscape - Hardscape- Pavers	Entire Site	450	SF	6	10+ years	opaning, oracine
	Landscape - Hardscape- Pavers	Entire Site	730	SF	4	0-1 year	Heaving, broken pavers, tree root
	Landscape Trandscape Tavers	Litting Oile	700	O.	7	o i yeai	damage
	Parkway trees	Entire Site	45	EA	6	10+ years	-
	Planting Beds/ Area	Entire Site	22,511	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	3,211	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	200	SF	5	6-10 years	
	Trash Receptacles	Entire Site	5	EA	6	10+ years	
Parking I	ot						
-	Concrete Curbs	Parking Lots	2,245	LF	6	10+ years	
	Interior Plantings	Parking Lots	31	LF	6	10+ years	
	Surface - Asphalt	Parking Lots	67,184	SF	5	2-5 years	
	Surface - Asphalt	Parking Lots	7,350	SF	4	1-2 years	Cracks, potholes, spalling
	Surface - Asphalt	Parking Lots	14,768	SF	4	1-2 years	Cracks, potholes, spalling
	Trash Enclosure - Chain Links	Parking Lots	768	SF	6	10+ years	- ··· -/ F - ··· - · - · - · - · - · · · · · · ·
				LF	-		

Kenwood Academy High School

5015 S Blackstone AVENUE, Chicago, IL 60615

Catego	ry : Site		В	uilding	: Site		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Sidewall	KS.						
	Sidewalks - Internal Walks	Entire Site	920	LF	6	10+ years	Separated internal sidewalks
	Sidewalks - Internal Walks	Entire Site	45	LF	4	1-2 years	Spalling, settling
	Sidewalks - Perimeter Sidewalks	Entire Site	29,123	SF	6	10+ years	Repairs
	Sidewalks - Perimeter Sidewalks	Entire Site	500	SF	5	6-10 years	·
	Sidewalks - Perimeter Sidewalks	Entire Site	30	SF	4	0-1 year	Spalling, missing
	Sidewalks - Perimeter Sidewalks	Entire Site	225	SF	4	1-2 years	Cracks, spalling
Signage							
	Flag Pole - Flag Pole	Entire Site	2	EA	5	0-1 year	Branch and main entrance base cracking
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	7	10+ years	Branch
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	7	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years	
	Monument - Sign	Entire Site	1	EA	7	10+ years	Branch

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").




Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main-Academic_Ur					(0-)	1 11 0 01	1	0.00	
Computer Lab	Computer Lab	1st Floor	121	B121	1,416	0	0	N	N
Computer Lab	Computer Lab	1st Floor	123	B123	1,744	0	0	N	N
Computer Lab	Computer Lab	3rd Floor	322	322	870	152	18	N	N
Computer Lab	Computer Lab	3rd Floor	323	323	870	152	18	N	N
Computer Lab	Special Program	1st Floor	122	122	1,258	0	0	N	N
Other Instructional Use	Office	3rd Floor	307A	307	556	50	25		
			moved from						
Other Instructional Use	Office	3rd Floor	312	312	350	0	0	N	N
Regular Classroom	Regular Classroom	1st Floor	106	B106	766	152	18	N	N
Regular Classroom	Regular Classroom	1st Floor	107	B107	730	152	18	N	N
Regular Classroom	Regular Classroom	1st Floor	108	B108	730	152	18	N	N
Regular Classroom	Regular Classroom	1st Floor	109	B109	730	152	18	N	N
Regular Classroom	Regular Classroom	1st Floor	110	B110	766	152	18	N	N
Regular Classroom	Regular Classroom	1st Floor	116	B116	766	152	18	N	N
Regular Classroom	Regular Classroom	1st Floor	117	B117	730	152	18	N	N
Regular Classroom	Regular Classroom	1st Floor	118	B118	730	152	18	N	N
Regular Classroom	Regular Classroom	1st Floor	119	B119	730	152	18	N	N
Regular Classroom	Regular Classroom	1st Floor	120	B120	766	152	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	1,258	112	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	910	112	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	910	112	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	910	112	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	1,060	112	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	B206	766	152	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	B207	730	152	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	B208	730	152	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	B209	730	152	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	B210	766	152	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	B211	1,060	0	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	B215	830	0	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	766	152	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	730	152	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	730	152	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	730	152	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	220	220	766	152	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	908	190	27	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	740	0	0	N	N
Regular Classroom	Regular Classroom	3rd Floor	316	316	766	152	18	N	N

Campus Name: Kenwood HS Page: 113 of 115 Assessment Date: 07/08/2024





Classro	oom S	ummary

			_	Floor Plan	_	Glazed	Operable		_
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	3rd Floor	317	317	730	152	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	318	318	730	152	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	319	319	730	152	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	320	320	766	152	18	N	N
Science	Science Lab Level 2	3rd Floor	306	306	730	112	18	N	N
Science Classroom	Science Lab Level 3	3rd Floor	325	325	1,314	0	0	N	N
Science Lab Level 1	Science Lab Level 1	3rd Floor	305	305	1,246	140	18	N	N
Science Lab Level 1	Science Lab Level 1	3rd Floor	310	310	1,120	0	0	N	N
Science Lab Level 1	Science Lab Level 1	3rd Floor	315	315	1,120	0	0	N	N
Science Lab Level 1	Science Lab Level 1	3rd Floor	321	321	1,390	38	9	N	N
Science Lab Level 1	Science Lab Level 1	3rd Floor	324	324	1,410	38	9	N	N
Science Lab Level 2	Science Lab Level 2	3rd Floor	301	301	1,090	112	18	N	N
Science Lab Level 2	Science Lab Level 2	3rd Floor	303	303	1,090	140	18	N	N
Store Room	Regular Classroom	3rd Floor	313	313	350	0	0	N	N
	·					•			
Building: Linked Addition-	Arts_Unit A								
Art Room	Art Room	2nd Floor	232	232	1,440	168	84	N	N
Art Room	Art Room	2nd Floor	233	233	1,296	168	84	N	N
Art Room	Art Room	2nd Floor	234	234	1,296	168	84	N	N
Band Room	Band Room	1st Floor	133	133	1,430	0	0	N	N
Band Room	Band Room	1st Floor	134	134	1,430	0	0	N	N
Choral Room	Choral Room	1st Floor	126	126	1,295	0	0	N	N
Computer Lab	Computer Lab	1st Floor	125	125	896	101	16	N	N
Computer Lab	Regular Classroom	2nd Floor	230	230	396	0	0	N	N
Other Instructional Use	Other Instructional Use	2nd Floor	236	236	378	0	0	N	N
Regular Classroom	Regular Classroom	2nd Floor	226	226	950	144	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	227	227	1,330	152	25	N	N
Science Classroom	Science Classroom	2nd Floor	225	225	1,847	177	33	N	N
••••••					.,		- 55		
Building : Branch @ Old C	anter								
Art Room	Science Classroom	1st Floor	102	102	883	228	114	N	N
Faculty Lounge	Regular Classroom	2nd Floor	204	204	550	140	70	N	N
Regular Classroom	Computer Lab	3rd Floor	302	302	816	140	70	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	641	175	88	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	690	140	70	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	690	158	79	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	690	158	79	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	816	140	79	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	202	690	158	70	N	N
			207	203	690	158			
Regular Classroom	Regular Classroom	2nd Floor					79	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	816	140	70	N	N





Classroom Summary

			_	Floor Plan	_	Glazed	Operable		_
Current Heere	Intended Hoose	Doom Location	Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	3rd Floor	303	303	690	140	70	Ν	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	690	158	79	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	305	305	690	158	79	Ν	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	690	158	79	Ν	N
Regular Classroom	Science	2nd Floor	206	206	690	158	79	Ν	N
Science Classroom	Regular Classroom	2nd Floor	205	205	690	158	79	Ν	N
Science Classroom	Regular Classroom	3rd Floor	307	307	690	158	79	N	N
Store Room	Science Classroom	1st Floor	101	101	870	158	79	N	Ν

Building : Addition-Lunch	nroom_Unit D								
Dance Room	Lunch Room	2nd Floor	Dance - in 267	NA	1,306	208	0		
Fitness Room	Lunch Room	2nd Floor	266	266	1,240	152	18	N	N
Regular Classroom	Other Instructional Use	2nd Floor	224-223	224	1,240	342	36	N	N
Weight	Lunch Room	2nd Floor	283	283	1,650	380	0	N	N

Building : Linked Addition-Athletic Building_Unit C										
Regular Classroom	Regular Classroom	2nd Floor	237	C237	840	0	0	N	N	
Regular Classroom	Regular Classroom	2nd Floor	238	C238	918	0	0	N	N	

Campus Name: Kenwood HS Page : 115 of 115 Assessment Date: 07/08/2024