

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1962 | 2 | 51,900 |
| Campus Total | | | 51,900 |

Category : Exterior Building : Main

| Calego | Ty . Exterior | <u> </u> | Building . Walli | | | | |
|----------|--------------------------------------|----------|------------------|-----|------|-------------|------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Entrance | 9 | | | | | | |
| | Entrance Control - Audio and Video | 1 | 1 | EA | 7 | 6-10 years | |
| | Exterior Doors - Side lite | 1 | 4 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | 1 | 3 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | 1 | 7 | EA | 6 | 10+ years | |
| | Power Door Operator and Controls | 1 | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 10 | 1 | EA | 4 | 1-2 years | Corroded, dented |
| | Exterior Stairs - Concrete | 10 | 4 | LF | 7 | 10+ years | |
| | Exterior Doors - Side lite | 11 | 3 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | 11 | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | 11 | 5 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 11 | 10 | LF | 7 | 10+ years | |
| | Exterior Doors - Store Front | 12 | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | 12 | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 12 | 4 | LF | 7 | 10+ years | |
| | Exterior Doors - Store Front | 13 | 1 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | 13 | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 13 | 4 | LF | 7 | 10+ years | |
| | Exterior Doors - Store Front | 2 | 2 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 2 | 8 | LF | 6 | 10+ years | |
| | Exterior Doors - Side lite | 3 | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Store Front | 3 | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Transom Lite | 3 | 2 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 3 | 8 | LF | 5 | 1-2 years | Large crack |
| | Entrance Control - Audio and Video | 4 | 1 | EA | 7 | 10+ years | - |



| Catego | ry : Exterior | | В | uilding | : Main | | , , , , , , , , |
|-----------|---|---------------------------------|----------|----------|--------|-------------|-----------------------|
| | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Exterior Doors - Store Front | 4 | 2 | EA | 5 | 0-1 year | Doors dented. |
| | Power Door Operator and Controls | 4 | 1 | EA | 7 | 10+ years | |
| | Ramps - Concrete | 4 | 16 | LF | 6 | 10+ years | |
| | Exterior Doors - Store Front | 5 | 2 | EA | 5 | 2-5 years | Difficult to open |
| | Exterior Doors - Transom Lite | 5 | 1 | EA | 6 | 10+ years | |
| | Exterior Stairs - Concrete | 5 | 5 | LF | 5 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 6 | 2 | EA | 4 | 1-2 years | Corroded, no hardware |
| | Exterior Stairs - Concrete | 6 | 6 | LF | 5 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 7 | 2 | EA | 6 | 6-10 years | |
| | Exterior Stairs - Concrete | 7 | 6 | LF | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 8 | 2 | EΑ | 7 | 10+ years | |
| | Ramps - Concrete | 8 | 6 | LF | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 9 | 2 | EA | 4 | 1-2 years | Corroded. |
| | Exterior Stairs - Concrete | 9 | 6 | LF | 6 | 10+ years | |
| _Foundat | ion | | | | | | |
| | Foundation - Concrete | Entire Building | 1,047 | LF | 7 | 10+ years | |
| | Superstructure - Metal Deck/ Concrete | Entire Building | 51,900 | SF | 7 | 10+ years | |
| | Topping | · · | | | | • | |
| Liabtina | | | | | | | |
| _Lighting | Exterior Lighting - Parapet or Roof Mounted | Fatire Duilding | 7 | ΕΛ | | 10 | |
| | Exterior Lighting - Parapet of Roof Mounted Exterior Lighting - Wall Mounted | Entire Building Entire Building | 7 8 | EA EA | 6 6 | 10+ years | |
| | Exterior Lighting - Wall Mounted | Entire building | 0 | EA | O | 10+ years | |
| Roof Sys | | | | | | | |
| | Access Ladder - Metal | A - Main | 1 | EA | 7 | 10+ years | |
| | Coping - Metal | A - Main | 654 | LF | 6 | 6-10 years | |
| | Downspouts - Interior Downspouts | A - Main | 138 | LF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | A - Main | 19,592 | SF | 5 | 2-5 years | |
| | Roof Hatch - Metal | A - Main | 1 | EA | 5 | 0-1 year | Hatch closer broken |
| | Roof Structure - Steel / Metal Deck/ | A - Main | 19,592 | SF | 7 | 10+ years | |
| | Concrete Topping | | | | | | |
| | Coping - Metal | B - Center | 14 | LF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | B - Center | 300 | SF | 5 | 0-1 year | Vegetation growth. |
| | Roof Structure - Steel / Metal Deck/ | B - Center | 300 | SF | 7 | 10+ years | |
| | Concrete Topping | | | | | | |
| | Coping - Metal | C - SW | 388 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | C - SW | 40 | LF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | C - SW | 10,146 | SF | 5 | 2-5 years | |
| | Roof Structure - Steel / Metal Deck/ | C - SW | 10,146 | SF | 7 | 10+ years | |
| | Concrete Topping | | | | | | |
| | Chimney - Brick Chimney- Concrete/ Mortar | D - Lower SW | 43 | LF | 6 | 10+ years | |
| | Liner | | | | | | |
| | | | | | | | |



| Catego | ry : Exterior | | В | uilding | : Main | | |
|----------|---|------------------|----------|---------|--------|---|------------------------------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| _ | Chimney - Brick Chimney- Concrete/ Mortar | D - Lower SW | 25 | LF | 5 | 10+ years | |
| | Liner | | | | | | |
| | Chimney - Metal Flue | D - Lower SW | 10 | LF | 6 | 6-10 years | |
| | Coping - Metal | D - Lower SW | 105 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | D - Lower SW | 26 | LF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | D - Lower SW | 1,375 | SF | 6 | 2-5 years | |
| | Roof Structure - Steel / Metal Deck/ | D - Lower SW | 1,375 | SF | 7 | 10+ years | |
| | Concrete Topping | | | | | • | |
| | Coping - Metal | E - Lower NW | 327 | LF | 5 | 2-5 years | |
| | Downspouts - Interior Downspouts | E - Lower NW | 38 | LF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | E - Lower NW | 6,720 | SF | 5 | 0-1 year | No access, screens stuck in window |
| | • | | • | | | , | Vegetation growth. |
| | Roof Structure - Steel / Metal Deck/ | E - Lower NW | 6,720 | SF | 7 | 10+ years | 3 |
| | Concrete Topping | | -, | | | , , , , , | |
| | Coping - Metal | F - Lower SE | 95 | LF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | F - Lower SE | 503 | SF | 5 | 0-1 year | Vegetation growth. |
| | Roof - Modified Bitumen | F - Lower SE | 200 | SF | 6 | 10+ years | - egetamen grennm |
| | Roof Structure - Steel / Metal Deck/ | F - Lower SE | 703 | SF | 7 | 10+ years | |
| | Concrete Topping | | | - | - | , | |
| | 11 3 | | | | | | |
| /alls | Canopy - Concrete/ Stucco | Entire Building | 6,407 | SF | 7 | 10+ years | |
| | Canopy - Concrete/ Stucco | Entire Building | 45 | SF | 6 | | |
| | Exterior Walls - Brick | Entire Building | 13,395 | SF | 7 | 10+ years 10+ years | |
| | Exterior Walls - Brick | Entire Building | 3,000 | SF | 6 | 10+ years | |
| | Exterior Walls - Stone-Cast | Entire Building | 224 | SF | 6 | 10+ years | |
| | Exterior walls - Storie-Cast | Littile building | 224 | OI . | O | 10+ years | |
| /indows | | | | | | | |
| | Curtain wall - Glazed Double Pane | Entire Building | 225 | SF | 6 | 10+ years | |
| | Guard - Guards perforated | Entire Building | 4,265 | SF | 7 | 10+ years | |
| | Guard - Guards perforated | Entire Building | 1,020 | SF | 6 | 10+ years | |
| | Lintels - Steel | Entire Building | 56 | LF | 6 | 10+ years | |
| | Storefront Windows | Entire Building | 262 | SF | 6 | 10+ years | |
| | Windows - Casement Aluminum Double- | Entire Building | 6,144 | SF | 6 | 10+ years | |
| | pane | | | | | | |
| | Windows - Louver | Entire Building | 193 | SF | 6 | 10+ years | |
| | Windows - Louver | Entire Building | 40 | SF | 6 | 10+ years | |
| atego | ry : Electrical | | В | uilding | : Main | | |
| <u> </u> | | | | | | Recommend | |
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | ncy System | | | | | | |
| | Emergency Battery Packs - Multipurpose | 1st Floor | 2 | EA | 7 | 10+ years | Pre - K: Rooms 100 & 102 |
| | EILIGIAGINA PARTORY I AUNO INIGIRIPATA | 1001 | _ | L/\ | | | 1 10 13 13001110 100 0 102 |



| Catego | ry : Electrical | | В | uilding | : Main | | |
|------------|--|-------------------|----------|------------|--------|-------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Room | | | | | | |
| | Emergency Generator- Outdoor- Natural | Central Courtyard | 1 | EA | 6 | 6-10 years | |
| | Gas - Below 60 KW | E 4 | 2.224 | 0= | _ | 40 | |
| | Emergency A/C Power - Auditoium and | Entire Building | 3,881 | SF | 7 | 10+ years | |
| | Aisle Lighting | | | 0.5 | _ | 4.0 | |
| | Emergency A/C Power - Corridors and | Entire Building | 5,052 | SF | 7 | 10+ years | |
| | Stairs | Entire Building | 2.500 | C.E. | 7 | 10 | |
| | Emergency A/C Power - Gym | Entire Building | 3,500 | SF | 7 | 10+ years | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 1,680 | SF | 7 | 10+ years | |
| | Emergency A/C Power - Students Toilets | Entire Building | 1,680 | SF | 7 | 10+ years | |
| | Security System - CCTV | Entire Building | 51,900 | SF | 6 | 6-10 years | No asset tag |
| | Security System - Intrusion Detection | Entire Building | 51,900 | SF | 6 | 6-10 years | No asset tag |
| | Exit Signs - Auditoium | Entire Building | 5 | EA | 6 | 6-10 years | Per building engineer, 95 % of exit |
| | o | ŭ | | | | , | signs have been replaced since last |
| | | | | | | | assessment |
| | Exit Signs - Corridors and Stairs | Entire Building | 11 | EA | 6 | 6-10 years | Per building engineer, 95 % of exit |
| | g | 9 | | | • | , | signs have been replaced since last |
| | | | | | | | assessment |
| | Exit Signs - Gym | Entire Building | 3 | EA | 6 | 6-10 years | Per building engineer, 95 % of exit |
| | Exit digits - dyffi | Little ballaling | 3 | LA | U | 0-10 years | signs have been replaced since last |
| | | | | | | | · |
| | Fuit Oissas - Lumphos and | Fating Building | 0 | - ^ | • | 0.40 | assessment |
| | Exit Signs - Lunchroom | Entire Building | 2 | EA | 6 | 6-10 years | Per building engineer, 95 % of exit |
| | | | | | | | signs have been replaced since last |
| | | | | | _ | | assessment |
| | Automatic Transfer Switch | Gym Closet | 3 | EA | 6 | 6-10 years | |
| Main Ser | vice | | | | | | |
| viaiii Sei | PA System | Entire Building | 51,900 | SF | 7 | 10+ years | PA system is new - recently replaced |
| | . Tr Gyotom | Littilo Ballanig | 01,000 | Ο. | • | io. youro | Trespective new recently replaced |
| Power D | stribution | | | | | | |
| | Lighting and Power Panels - 100 A | Entire Building | 4 | EA | 7 | 6-10 years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Lighting and Power Panels - 100 A | Entire Building | 5 | EA | 6 | 6-10 years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 4 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 2 | EΑ | 6 | 6-10 years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 4 | | Outdated panel, circuit breakers shut |
| | Lighting and Fower Fariets - Above 100 A | Entire Building | 1 | EA | 4 | 0-1 year | off too often. |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 1 | EA | 7 | 10+ years | on too onom |
| | Main Distribution Panels - Greater than 600 | Entire Building | 1 | EA | 4 | 0-1 year | Original to the building and drastically |
| | | Little building | ı | LA | 4 | U-i yeai | deteriorating in boiler room. |
| | | | | | | | uetenoraling in boller 100m. |
| | amp | Castina Duildia a | 4 | - ^ | 4 | 0.4 | وبالودية ومناه المرسوري ومناه البريط ومألف مقالم مناسات |
| | Main Distribution Panels - Less than 400 amp | Entire Building | 1 | EA | 4 | 0-1 year | Original to the building and drastically deteriorating in boiler room. |



| Catego | ry : Fire Protection | | В | uilding | | | |
|-----------|--|-----------------|----------|---------|--------|-----------------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| ire Alar | | | | | | | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 6 | 6-10 years | N |
| | Fire Alarm Strobe Lights | Entire Building | 51,900 | SF | 6 | 6-10 years | No asset tag |
| | Fire Alarm_System | Entire Building | 51,900 | SF | 6 | 6-10 years | |
| Catego | ry : Mechanical | | В | uilding | : Main | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| | ling Systems | Locution | Quantity | COM | Italik | Replacement | Comments |
| чі папи | Air Handling Unit-Package Single Zone- | Kitchen | 1 | EA | 6 | 6-10 years | Serves lunch room. |
| | Indoor- Hot Water Coils - Less than 4000 cfm | Kitchen | l | LA | U | 0-10 years | Serves functi foom. |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000 cfm | Kitchen | 1 | EA | 6 | 6-10 years | Serves kitchen |
| | Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM | Mechanical Room | 1 | EA | 6 | 10+ years | RA6 (classrooms and corridors) Asset 102042 |
| | Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM | Mechanical Room | 3 | EA | 6 | 10+ years | Dedicated RF pictures associated with AHU are included as reference. RA3 (gym, auditorium west), RA2 (auditorium west), and RA1 (auditorium east). |
| | Indoor Return Fans- Centrifugal Inline - Less than 5000 CFM | Mechanical Room | 2 | EA | 6 | 10+ years | RA4 (lunchroom) and RA5 (front offices) |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 8001-12000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | SA1 (auditorium east) |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 8001-12000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | SA 2 (auditorium west) |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 4000-8000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | SA3 (gym) |
| | Air Intake | Mechanical Room | 6 | EA | 6 | 6-10 years | |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | SA4 Serves lunchroom |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Less than 4000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | SA5 (front offices) |
| | Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - Greater than 30,000 cfm | Mechanical Room | 1 | EA | 5 | 6-10 years | SA6 (classrooms and corridors) Ass 102040 |
| soiler Sy | estems | | | | | | |
| | Boiler Auxiliary- Non Condensing Hot Water | Boiler Room | 2 | EA | 6 | 6-10 years | |



| Catego | ry : Mechanical | | B | uilding | · Main | | 0400 0 LOWE AVEIVOL, Officago, IL 00021 |
|-------------|---|-----------------|----------|---------|---------|-------------|---|
| Juliogo | i y i moonamoar | | | ananig | · waiii | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| C. C. P | - 2001 - 3000 MBH | | | | | | |
| | Chemical Pot Feeder | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Combustion Dampers | Boiler Room | 3 | EA | 7 | 10+ years | |
| | Glycol Feed System | Boiler Room | 1 | ΕA | 6 | 6-10 years | 102160 |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | 6-10 years | .02.00 |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump | Boiler Room | 1 | EΑ | 6 | 6-10 years | |
| | Hot Water Pump | Boiler Room | i | EA | 6 | 6-10 years | |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Hot Water Pump | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Non Condensing- Water Tube- Flexible | Boiler Room | 1 | EA | 6 | • | |
| | | Bollet Rooff | ' | EA | O | 10+ years | |
| | Tube- Force Draft- Hot Water Boiler - 2001 - 3000 MBH | | | | | | |
| | Non Condensing- Water Tube- Flexible | Boiler Room | 1 | EA | 6 | 10 | |
| | | Boller Room | 1 | EA | 6 | 10+ years | |
| | Tube- Force Draft- Hot Water Boiler - 2001 | | | | | | |
| | - 3000 MBH | | | | | | |
| | | | | | | | |
| _Gas Boo | | | | | | | |
| | Gas Booster | Boiler Room | 3 | EA | 6 | 6-10 years | No asset tag |
| | | | | | | | |
| _Heating_ | Devices | | | | | | _ |
| | Cabinet Heaters - With Hot Water Coil | Entire Building | 4 | EA | 6 | 6-10 years | |
| | Fin Tube - Hot Water | Entire Building | 768 | LF | 6 | 6-10 years | No asset tag |
| | Unit Heater - Electric | Mechanical Room | 1 | EA | 6 | 6-10 years | 3 |
| | Unit Heater - Hot Water | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | | | | | | , | |
| Mechani | cal Plumbing | | | | | | |
| | Hydronic Supply and Return - Steel | Entire Building | 600 | LF | 6 | 6-10 years | |
| | Trydronic Supply and Netam Steel | Entire Building | 000 | | O | o to years | |
| Tompore | ature Control | | | | | | |
| _тепірета | | Fadas Daiblias | F4 000 | | | 0.40 | |
| | DDC System | Entire Building | 51,900 | SF | 6 | 6-10 years | No seesting |
| | Thermostats - DDC | Entire Building | 45 | EA | 7 | 10+ years | No asset tag |
| | | | | | | | |
| _Ventilatio | | | | | | | |
| | Exhaust Fans- Indoor - 1501 - 8000 CFM | Mechanical Room | 1 | EA | 6 | 6-10 years | No asset tag |
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Indoor - Less than 500 CFM | Mechanical Room | 2 | EA | 6 | 6-10 years | No asset tag |
| | | | | | | | |
| | | | | | | | |



| Catego | ry : Mechanical | | R | uilding | : Main | | 6450 S LOWE AVENUE, Chicago, IL 600 |
|----------|--|-----------------|----------|---------|-----------|---|--|
| outogo. | y i moonamour | | _ | anamg | Recommend | | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Exhaust Fans- Indoor - Less than 500 CFM | Mechanical Room | 1 | EΑ | 6 | 6-10 years | Gym |
| | Type I Exhaust Hood- Kitchen | Mechanical Room | 1 | EA | 2 | 1-2 years | No fire suppression system |
| | Exhaust Fans- Roof Mounted - 1501 - 8000 | Roof | 1 | EΑ | 7 | 10+ years | Asset tag damaged |
| | CFM | | | | | , | The state of the s |
| | Exhaust Fans- Roof Mounted - 500 - 1500 | Roof | 1 | EA | 6 | 6-10 years | Asset tag 102064 |
| | CFM | | | | | , | 3 |
| | Exhaust Fans- Roof Mounted - Less than | Roof | 1 | EA | 6 | 6-10 years | Asset tag damaged |
| | 500 CFM | | | | | • | ŭ ŭ |
| Catego | ry : Plumbing | | В | uilding | : Main | | |
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Hot Wate | er | | | | | | |
| | Gas Heater - 300001 - 600000 BTU/HR | Boiler Room | 1 | EA | 4 | 2-5 years | Showing signs of deterioration and more than 20 years old. |
| Piping | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 51,900 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 51,900 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water from Risers to | Entire Building | 51,900 | SF | 6 | 6-10 years | |
| | Fixtures | | | | | | |
| | Domestic Piping-Hot/Cold Water Supply | Entire Building | 51,900 | SF | 6 | 6-10 years | |
| | (Horizontal Lines) | | | | | | |
| | Domestic Piping-Hot/Cold Water Supply | Entire Building | 51,900 | SF | 6 | 6-10 years | |
| | (Risers) | | | | | | |
| | Domestic Piping-Hot/Cold Water Supply | Entire Building | 51,900 | SF | 6 | 6-10 years | |
| | (from Risers to Fixtures) | | | | | | |
| | Sanitary Piping | Entire Building | 51,900 | SF | 6 | 6-10 years | |
| | Storm Piping | Entire Building | 51,900 | SF | 6 | 6-10 years | |
| | Vent Piping | Entire Building | 51,900 | SF | 6 | 6-10 years | |
| umps | | | | | | | |
| | Pumps - Sump-Simplex | Boiler Room | 1 | EA | 6 | 6-10 years | |
| Catego | ry : Room | | В | uilding | : Main | | |
| _ | | | <u> </u> | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Administ | rative Suites/Offices | | | | | | |
| | AC Unit | 106 | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Splined | 106 | 125 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 106 | 1 | EA | 6 | 6-10 years | |
| | Floor - Carpet | 106 | 125 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 100 | 120 | EA | U | ioi youlo | |



| Catego | Category : Room | | В | Building : Main | | | |
|--------|---|-------------------------------------|-----------|-----------------|--------|-------------|----------------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Power Distribution | 106 | 2 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 106 | 200 | SF | 6 | 10+ years | |
| | Work SInk | 106 | 1 | EA | 7 | 6-10 years | |
| | AC Unit | 106A | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Splined | 106A | 412 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 106A | 2 | EA | 6 | 10+ years | |
| | Floor - Carpet | 106A | 412 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 106A | 6 | EA | 6 | 6-10 years | |
| | Power Distribution | 106A | 6 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 106A | 752 | SF | 6 | 10+ years | |
| | Work SInk | 106A | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Splined | 130. Book storage | 130 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 130. Book storage | 2 | EA | 6 | 10+ years | |
| | Floor - Tile | 130. Book storage | 130 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 130. Book storage | 4 | EA | 5 | 0-1 year | Does not work. |
| | Walls - Plaster/Drywall | 130. Book storage | 200 | SF | 6 | 10+ years | |
| | Ceiling - Splined | 131. Faculty Lounge | 391 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 131. Faculty Lounge | 2 | EA | 6 | 10+ years | |
| | Floor - Tile | 131. Faculty Lounge | 391 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 131. Faculty Lounge | 10 | EΑ | 5 | 6-10 years | |
| | Power Distribution | 131. Faculty Lounge | 4 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 131. Faculty Lounge | 320 | SF | 6 | 10+ years | |
| | Walls - Masonry | 131. Faculty Lounge | 320 | SF | 6 | 10+ years | |
| | Work SInk | 131. Faculty Lounge | 1 | EΑ | 7 | 6-10 years | |
| | AC Unit | 218 | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Splined | 218 | 120 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | 218 | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 218 | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | 218 | 120 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 218 | 2 | EΑ | 6 | 6-10 years | |
| | Power Distribution | 218 | 4 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 218 | 200 | SF | 6 | 10+ years | |
| | Ceiling - Splined | Engineer's Office | 72 | SF EA | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Engineer's Office | 1 | SF | 6 | 10+ years | |
| | Floor - Tile | Engineer's Office | 72 | | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Engineer's Office | 1 | EΑ | 6 | 6-10 years | |
| | Power Distribution | Engineer's Office | 6 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | Engineer's Office Kitchen office | 172 96 | SF SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | | | SF EA | 6 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Kitchen office | 1 | | | 10+ years | |
| | Floor - Tile | Kitchen office | 96 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface Power Distribution | Kitchen office Kitchen office | 1 2 | EA EA | 6 7 | 6-10 years | |
| | Walls - Concrete Block | Kitchen office Kitchen office | 220 | SF | 6 | 6-10 years | |
| | vvalis - Coliciete block | Kitchen onice | 220 | SF | O | 10+ years | |



| Catego | ry : Room | | В | uilding | : Main | | 6450 G LOWE AVENUE, Officago, 12 00021 |
|------------|---|------------------------------------|----------|----------|--------|---|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | AC Unit | Main office | 1 | EA | 7 | 6-10 years | |
| | Ceiling - Splined | Main office | 338 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Main office | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | Main office | 338 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Main office | 7 | EA | 6 | 6-10 years | |
| | Power Distribution | Main office | 4 | EA | 7 | 6-10 years | |
| | Walls - Masonry | Main office | 312 | SF | 6 | 10+ years | |
| | Walls - Masonry | Main office | 208 | SF | 6 | 10+ years | |
| | AC Unit | Principals Office | 1 | ĒΑ | 7 | 6-10 years | |
| | Ceiling - Splined | Principals Office | 176 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Principals Office | 1 | EΑ | 6 | 10+ years | |
| | Floor - Tile | Principals Office | 176 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Principals Office | 2 | EA | 6 | 6-10 years | |
| | Power Distribution | Principals Office | 4 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | Principals Office | 392 | SF | 6 | 10+ years | |
| | Ceiling - Splined | Teachers lounge | 192 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Teachers lounge | 2 | EA | 6 | 10+ years | |
| | Floor - Tile | Teachers lounge | 192 | SF | 6 | • | |
| | Lighting - Pendent/Surface | • | | | | 10+ years | |
| | | Teachers lounge Teachers lounge | 5 8 | EΑ | 6 6 | 6-10 years 6-10 years | |
| | Power Distribution Walls - Concrete Block | Teachers lounge | 376 | EA SF | 6 | 6-10 years | |
| | | Jan 1 1 J | | | | , | |
| _Auditoriu | ım & Theater | | | | | | |
| | Ceiling - Plaster/Drywall | 122 | 2,012 | SF | 6 | 6-10 years | |
| | Ceiling - Splined | 122 | 2,012 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 122 | 5 | EA | 6 | 10+ years | |
| | Floor - Concrete | 122 | 2,772 | SF | 5 | 10+ years | |
| | Floor - Tile | 122 | 1,252 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 122 | 26 | EA | 6 | 6-10 years | |
| | Main Floor Seating | 122 | 327 | EA | 7 | 10+ years | |
| | Sound System | 122 | 1 | EA | 7 | 6-10 years | |
| | Stage | 122 | 972 | SF | 6 | 10+ years | |
| | Stage Curtain | 122 | 3 | EA | 7 | 6-10 years | |
| | Stage Lighting System | 122 | 1 | EA | 7 | 6-10 years | |
| | Stage-Stairs - Terrazzo | 122 | 40 | LF | 7 | 10+ years | |
| | Stairs - Terrazzo | 122 | 20 | LF | 7 | 10+ years | |
| | Storage/ Closet | 122 | 42 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 122 | 4,745 | SF | 6 | 10+ years | |
| | Traile Correlate Blook | | 1,1 10 | O. | Ū | ioi youro | |
| _Gymnas | | | | | | | |
| • | Ceiling - Splined | 125 | 3,798 | SF | 6 | 6-10 years | |
| | Doors - Steel Doors incl hw | 125 | 2 | ĒΑ | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 125 | 4 | EΑ | 6 | 10+ years | |
| | Floor - Wood | 125 | 3,790 | SF | 6 | 10+ years | |
| | | - | 2,100 | | - | · , | |



| AC Unit | | |
|--|----------------|--|
| | | |
| Floor - Wood 125 | | |
| Lighting - Metal Halide/ High Pressure 125 20 | | |
| Sodium | | |
| Sound System 125 | | |
| Storage Closet 125 248 SF 7 6-10 years Walls - Concrete Block 125 3,920 SF 6 10+ years Walls - Masonry 125 400 SF 6 10+ years Walls - Masonry 125 400 SF 6 10+ years Walls - Masonry 125 400 SF 6 10+ years Walls - Masonry 125 400 SF 6 10+ years Walls - Masonry 125 400 SF 6 10+ years Walls - Concrete Block 1st Floor 792 SF 6 10+ years Walls - Concrete Block 1st Floor 1,400 SF 6 10+ years Walls - Concrete Block 1st Floor 4 EA 7 6-10 years Walls - Concrete Block 1st Floor 207 LF 6 6-10 years Walls - Concrete Block 1st Floor 1,680 SF 6 6-10 years Walls - Concrete Block 1st Floor 1,680 SF 6 6-10 years Walls - Concrete Block 1st Floor 2 EA 6 10+ years Walls - Concrete Block 1st Floor 1,680 SF 4 0+ years Walls - Concrete Block 1st Floor 1,680 SF 4 0+ years Walls - Concrete Block 1st Floor 1,680 SF 4 0+ years Walls - Concrete Block 1st Floor 1,680 SF 6 6-10 years Walls - Concrete Block 1st Floor 1,680 SF 6 6-10 years Walls - Concrete Block 1st Floor 1,700 SF 6 6-10 years Walls - Concrete Block 1st Floor 1,700 SF 6 6-10 years Walls - Concrete Block 129 1,700 SF 6 10+ years Hoor - Tile 129 1,700 SF 6 10+ years Hoor - Tile 129 1,700 SF 6 10+ years Hoor - Tile 129 1,700 SF 6 10+ years Hoor - Tile 129 1,700 SF 6 10+ years Hoor - Tile 129 1,700 SF 6 10+ years Hoor - Tile 129 1,700 SF 6 10+ years Hoor - Tile 129 1,700 SF 6 10+ years Hoor - Tile 1,700 SF 6 1,70 | | |
| Walls - Concrete Block 125 3,920 SF 6 10+ years | | |
| Walls - Masonry 125 | | |
| Ceiling - Splined | | |
| Ceiling - Splined | | |
| Ceiling - Splined | | |
| Doors - Wood Doors inclu hw | | |
| Floor - Tile | | |
| Storage Closet 1st Floor 252 SF 7 | | |
| Library | | |
| AC Unit | | |
| Casework | | |
| Casework | | |
| Ceiling - Splined | | |
| Doors - Side-lite | | |
| Doors - Side-lite | | |
| Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years Floor - Carpet 1st Floor 1,680 SF 4 0-1 year Damaged/ripped to the stronger of the strong | | |
| Floor - Carpet | | |
| Lighting - Pendent/Surface 1st Floor 30 EA 6 6-10 years Storage/ Closet 1st Floor 12 SF 7 6-10 years Walls - Concrete Block 1st Floor 748 SF 6 10+ years Walls - Concrete Block 1st Floor 748 SF 6 10+ years Walls - Concrete Block 1st Floor 1,700 SF 6 6-10 years Doors - Steel Doors incl hw 129 | ned throughout | |
| Storage Closet 1st Floor 12 SF 7 6-10 years | oca imoagnout. | |
| Walls - Concrete Block 1st Floor 748 SF 6 10+ years Lunch & Multipurpose Room Ceiling - Splined 129 1,700 SF 6 6-10 years Doors - Steel Doors incl hw 129 4 EA 6 10+ years Floor - Tile 129 1,700 SF 6 10+ years Lighting - Pendent/Surface 129 36 EA 7 6-10 years Serving Line 129 20 LF 6 6-10 years Walls - Concrete Block 129 340 SF 6 10+ years Walls - Plaster/Drywall 129 340 SF 6 10+ years MDF_IDF Doors - Steel Doors incl hw 2nd Floor 1 EA 6 6-10 years Flooring is damage | | |
| Lunch & Multipurpose Room | | |
| Ceiling - Splined 129 1,700 SF 6 6-10 years | | |
| Ceiling - Splined 129 1,700 SF 6 6-10 years Doors - Steel Doors incl hw 129 4 EA 6 10+ years Floor - Tile 129 1,700 SF 6 10+ years Lighting - Pendent/Surface 129 36 EA 7 6-10 years Serving Line 129 20 LF 6 6-10 years Walls - Concrete Block 129 340 SF 6 10+ years Walls - Plaster/Drywall 129 340 SF 6 10+ years MDF_IDF Doors - Steel Doors incl hw 2nd Floor 1 EA 6 6-10 years Flooring is damage Finishes 2nd Floor 320 SF 5 6-10 years Flooring is damage | | |
| Doors - Steel Doors incl hw 129 | | |
| Floor - Tile | | |
| Lighting - Pendent/Surface 129 36 EA 7 6-10 years Serving Line 129 20 LF 6 6-10 years Walls - Concrete Block 129 340 SF 6 10+ years Walls - Plaster/Drywall 129 340 SF 6 10+ years Walls - Plaster/Drywall 129 340 SF 6 10+ years Walls - Plaster/Drywall 129 340 SF 6 10+ years Walls - Plaster/Drywall 129 340 SF 6 10+ years Walls - Plaster/Drywall 129 340 SF 6 10+ years Walls - Plaster/Drywall 129 340 SF 6 10+ years Walls - Plaster/Drywall 129 340 SF 6 10+ years Walls - Plaster/Drywall Wa | | |
| Serving Line 129 20 | | |
| Walls - Concrete Block Walls - Plaster/Drywall MDF_IDF Doors - Steel Doors incl hw Finishes 2nd Floor Floor Finishes 129 340 SF 6 10+ years 340 SF 6 10+ years 1 EA 6 6-10 years 1 EA 6 6-10 years 1 Flooring is damage | | |
| Walls - Plaster/Drywall 129 340 SF 6 10+ years MDF_IDF Doors - Steel Doors incl hw Finishes 2nd Floor 2nd Floor 320 SF 5 6-10 years Flooring is damage | | |
| MDF_IDF Doors - Steel Doors incl hw 2nd Floor 1 EA 6 6-10 years Finishes 2nd Floor 320 SF 5 6-10 years Flooring is damage | | |
| Doors - Steel Doors incl hw 2nd Floor 1 EA 6 6-10 years Finishes 2nd Floor 320 SF 5 6-10 years Flooring is damage | | |
| Finishes 2nd Floor 320 SF 5 6-10 years Flooring is damage | | |
| | | |
| Machanical/ Sarvice Rooms | maged. | |
| IVIECTIANTICAL/ DELVICE INJURIS | | |
| Boiler Room 1st Floor 833 SF 5 10+ years | | |
| Janitor's Closet 1st Floor 72 SF 5 10+ years Damaged flooring. | oring | |
| Mechanical/ Service Rooms 1st Floor 1,800 SF 5 10+ years | g. | |
| ividentalitical/ delivide (Nooths 15t Floot 15t Floot 1,000 SF 3 10+ years | | |



| Catego | ry : Room | | B | uilding | : Main | | |
|---------|---------------------------------|---------------------|----------|----------|--------|-------------|---|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Storage Room | 1st Floor | 340 | SF | 5 | 10+ years | |
| | Storage Room | 1st Floor | 104 | SF | 5 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 48 | SF | 4 | 0-1 year | Flooring and ceiling in really bad condition. |
| | Mechanical/ Service Rooms | 2nd Floor | 1,500 | SF | 7 | 10+ years | |
| | Storage Room | 2nd Floor | 122 | SF | 5 | 10+ years | |
| estroor | n | | | | | | |
| | Accessories | 100A toilet | 25 | SF | 7 | 6-10 years | |
| | Ceiling - Splined | 100A toilet | 25 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 100A toilet | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 100A toilet | 25 | SF | 7 | 10+ years | |
| | Lavatory | 100A toilet | 1 | EΑ | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 100A toilet | 1 | EΑ | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | 100A toilet | 60 | SF | 6 | 10+ years | |
| | Water Closet | 100A toilet | 1 | EA | 6 | 10+ years | |
| | Accessories | 102A Toilet | 25 | SF | 7 | 6-10 years | |
| | Ceiling - Splined | 102A Toilet | 25 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 102A Toilet | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 102A Toilet | 25 | SF | 7 | 10+ years | |
| | Lavatory | 102A Toilet | 1 | ĒΑ | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 102A Toilet | 1 | EA | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | 102A Toilet | 80 | SF | 6 | 10+ years | |
| | Water Closet | 102A Toilet | 1 | EA | 6 | 10+ years | |
| | Accessories | 106B Nurse's Office | 15 | SF | 7 | 6-10 years | |
| | Ceiling - Splined | 106B Nurse's Office | 15 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 106B Nurse's Office | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 106B Nurse's Office | 15 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 106B Nurse's Office | 1 | EA | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | 106B Nurse's Office | 28 | SF | 6 | 10+ years | |
| | Water Closet | 106B Nurse's Office | 1 | EA | 6 | 6-10 years | |
| | | 112 Toilet | 35 | SF | 7 | | |
| | Accessories | | 30 | SF SF | | 6-10 years | |
| | Ceiling - Splined | 112 Toilet | | | 6 | 6-10 years | Matardamas |
| | Ceiling - Splined | 112 Toilet | 5 | SF | 4 | 0-1 year | Water damage. |
| | Doors - Wood Doors inclu hw | 112 Toilet | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 112 Toilet | 35 | SF | 6 | 10+ years | |
| | Lavatory | 112 Toilet | 1 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | 112 Toilet | 1 | EA | 6 | 6-10 years | |
| | Walls - Plaster/Drywall | 112 Toilet | 92 | SF | 6 | 10+ years | |
| | Water Closet | 112 Toilet | 1 | EA | 6 | 10+ years | |
| | Accessories | 1st Floor boys 001 | 88 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor boys 001 | 88 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 1st Floor boys 001 | 1 | EA | 6 | 10+ years | |
| | Floor - Concrete | 1st Floor boys 001 | 88 | SF | 7 | 10+ years | |



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|---------------------------------|---------------------|----------|---------|--------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor Drain | 1st Floor boys 001 | 1 | EΑ | 7 | 10+ years | |
| | Hand Dryer | 1st Floor boys 001 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor boys 001 | 1 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor boys 001 | 1 | EA | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | 1st Floor boys 001 | 204 | SF | 6 | 10+ years | |
| | Water Closet | 1st Floor boys 001 | 1 | EA | 6 | 10+ years | |
| | Accessories | 218A | 15 | SF | 7 | 6-10 years | |
| | Ceiling - Splined | 218A | 15 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 218A | 1 | EA | 6 | 10+ years | |
| | Lavatory | 218A | 1 | EA | 6 | 6-10 years | |
| | Lighting - Wall Mounted | 218A | 1 | EA | 5 | 6-10 years | |
| | Walls - Plaster/Drywall | 218A 218A | 45 | SF | 6 | • | |
| | Water Closet | | | EA | 6 | 10+ years | |
| | | 218A | 1 | | | 6-10 years | |
| | Accessories | 219 | 15 | SF | 7 | 6-10 years | |
| | Ceiling - Splined | 219 | 15 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 219 | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 219 | 15 | SF | 6 | 10+ years | |
| | Lavatory | 219 | 1 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 219 | 1 | EA | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | 219 | 28 | SF | 6 | 10+ years | |
| | Water Closet | 219 | 1 | EA | 6 | 10+ years | |
| | Accessories | Boys 1st floor east | 288 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | Boys 1st floor east | 288 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Boys 1st floor east | 1 | EA | 6 | 10+ years | |
| | Floor - Concrete | Boys 1st floor east | 288 | SF | 7 | 10+ years | |
| | Floor Drain | Boys 1st floor east | 1 | EA | 7 | 6-10 years | |
| | Hand Dryer | Boys 1st floor east | 2 | EA | 7 | 6-10 years | |
| | Lavatory | Boys 1st floor east | 4 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | Boys 1st floor east | 4 | EA | 6 | 6-10 years | |
| | Partitions | Boys 1st floor east | 3 | EA | 7 | 10+ years | |
| | Urinals | Boys 1st floor east | 5 | ĒΑ | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | Boys 1st floor east | 576 | SF | 6 | 10+ years | |
| | Water Closet | Boys 1st floor east | 3 | EA | 6 | 10+ years | |
| | Accessories | Boys 2nd floor | 252 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | Boys 2nd floor | 252 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Boys 2nd floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Boys 2nd floor | 252 | SF | 6 | • | |
| | | | | | | 10+ years | |
| | Floor Drain | Boys 2nd floor | 1 | EΑ | 7 | 6-10 years | |
| | Hand Dryer | Boys 2nd floor | 2 | EΑ | 7 | 6-10 years | |
| | Lavatory | Boys 2nd floor | 4 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | Boys 2nd floor | 4 | EA | 6 | 6-10 years | |
| | Partitions | Boys 2nd floor | 3 | EA | 7 | 6-10 years | |
| | Urinals | Boys 2nd floor | _ 5 | EA | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | Boys 2nd floor | 576 | SF | 6 | 10+ years | |
| | | | | | | | |

Campus Name: Kershaw Page : 12 of 26 Assessment Date: 08/03/2023



| Catego | ry : Room | | В | uilding | : Main | | |
|--------|---------------------------------|----------------------|----------|---------|--------|-------------|----------------|
| _ | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Water Closet | Boys 2nd floor | 3 | EA | 6 | 10+ years | |
| | Accessories | E/W corridor 002 | 88 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | E/W corridor 002 | 88 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | E/W corridor 002 | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | E/W corridor 002 | 88 | SF | 7 | 10+ years | |
| | Hand Dryer | E/W corridor 002 | 1 | EA | 7 | 6-10 years | |
| | Lavatory | E/W corridor 002 | 1 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | E/W corridor 002 | 1 | EA | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | E/W corridor 002 | 204 | SF | 6 | 10+ years | |
| | Water Closet | E/W corridor 002 | 1 | EA | 6 | 10+ years | |
| | Accessories | Engineer's Toilet | 72 | SF | 7 | 6-10 years | |
| | Ceiling - Splined | Engineer's Toilet | 72 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Engineer's Toilet | 1 | EA | 6 | 10+ years | |
| | Floor - Concrete | Engineer's Toilet | 72 | SF | 5 | 10+ years | |
| | Floor Drain | Engineer's Toilet | 1 | EA | 7 | 6-10 years | |
| | Lavatory | Engineer's Toilet | 1 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | Engineer's Toilet | 2 | EA | 5 | 0-1 year | Does not work. |
| | Partitions | Engineer's Toilet | 1 | EA | 5 | 6-10 years | |
| | Showers | Engineer's Toilet | 1 | EA | 7 | 6-10 years | |
| | Student Lockers - One Tier | Engineer's Toilet | 3 | EA | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | Engineer's Toilet | 172 | SF | 6 | 10+ years | |
| | Water Closet | Engineer's Toilet | 1 | EA | 6 | 10+ years | |
| | Accessories | Girls 1st floor east | 288 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | Girls 1st floor east | 288 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Girls 1st floor east | 1 | EA | 6 | 10+ years | |
| | Floor - Concrete | Girls 1st floor east | 288 | SF | 7 | 10+ years | |
| | Floor Drain | Girls 1st floor east | 1 | EA | 7 | 6-10 years | |
| | Hand Dryer | Girls 1st floor east | 2 | EA | 7 | 6-10 years | |
| | Lavatory | Girls 1st floor east | 4 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | Girls 1st floor east | 4 | EA | 6 | 6-10 years | |
| | Partitions | Girls 1st floor east | 7 | EA | 7 | 6-10 years | |
| | Walls - Structural Glazed Tile | Girls 1st floor east | 576 | SF | 6 | 10+ years | |
| | Water Closet | Girls 1st floor east | 7 | EA | 6 | 10+ years | |
| | Accessories | Girls 2nd floor | 252 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | Girls 2nd floor | 252 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Girls 2nd floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile Ceramic/ Porcelain | Girls 2nd floor | 252 | SF | 6 | 10+ years | |
| | Floor Drain | Girls 2nd floor | 1 | EA | 7 | 6-10 years | |
| | Hand Dryer | Girls 2nd floor | 2 | EA | 7 | 6-10 years | |
| | Lavatory | Girls 2nd floor | 4 | EA | 6 | 2-5 years | |
| | Lighting - Pendent/Surface | Girls 2nd floor | 4 | EA | 7 | 6-10 years | |
| | Partitions | Girls 2nd floor | 7 | EA | 7 | 2-5 years | |
| | Walls - Structural Glazed Tile | Girls 2nd floor | 576 | SF | 6 | 10+ years | |
| | Water Closet | Girls 2nd floor | 7 | EA | 6 | 6-10 years | |
| | | | | | | | |

Campus Name: Kershaw Page : 13 of 26 Assessment Date: 08/03/2023



Category : Room

Joshua D Kershaw Elementary School 6450 S Lowe AVENUE, Chicago, IL 60621

| | ry : itooiii | | _ | ananig | | Recommend | |
|-------|---------------------------------|---------------------|----------|------------|--------|----------------|----------|
| roup | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Toup | Accessories | Kitchen Toilet Room | 72 | SF | 7 | 6-10 years | Comments |
| | Ceiling - Splined | Kitchen Toilet Room | 72 | SF | 6 | 6-10 years | |
| | | | | | | | |
| | Doors - Wood Doors inclu hw | Kitchen Toilet Room | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | Kitchen Toilet Room | 72 | SF | 6 | 10+ years | |
| | Lavatory | Kitchen Toilet Room | 1 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | Kitchen Toilet Room | 2 | EA | 6 | 6-10 years | |
| | Partitions | Kitchen Toilet Room | 1 | EA | 5 | 6-10 years | |
| | Student Lockers - One Tier | Kitchen Toilet Room | 4 | EΑ | 6 | 6-10 years | |
| | Walls - Concrete Block | Kitchen Toilet Room | 92 | SF | 6 | 10+ years | |
| | Walls - Structural Glazed Tile | Kitchen Toilet Room | 36 | SF | 6 | 10+ years | |
| | Water Closet | Kitchen Toilet Room | 1 | EA | 6 | 10+ years | |
| | Accessories | Principal's Office | 25 | SF | 7 | 6-10 years | |
| | Ceiling - Splined | Principal's Office | 25 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Principal's Office | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Principal's Office | 25 | SF | 6 | 10+ years | |
| | Lavatory | Principal's Office | 1 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | Principal's Office | 1 | EA | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | | | SF | | | |
| | | Principal's Office | 60 | | 6 | 10+ years | |
| | Water Closet | Principal's Office | 1 | EA | 6 | 10+ years | |
| | Accessories | Teachers Lounge A | 25 | SF | 7 | 6-10 years | |
| | Ceiling - Splined | Teachers Lounge A | 25 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Teachers Lounge A | 1 | EA | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Teachers Lounge A | 25 | SF | 6 | 10+ years | |
| | Lavatory | Teachers Lounge A | 1 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | Teachers Lounge A | 1 | EA | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | Teachers Lounge A | 60 | SF | 6 | 10+ years | |
| | Water Closet | Teachers Lounge A | 1 | EA | 6 | 6-10 years | |
| | Accessories | Teachers Lounge B | 25 | SF | 7 | 6-10 years | |
| | Ceiling - Splined | Teachers Lounge B | 25 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | Teachers Lounge B | 1 | EΑ | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Teachers Lounge B | 25 | SF | 6 | 10+ years | |
| | Lavatory | Teachers Lounge B | 1 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | Teachers Lounge B | 1 | EA | 6 | 6-10 years | |
| | Walls - Structural Glazed Tile | Teachers Lounge B | 60 | SF | 6 | 10+ years | |
| | | | | | | | |
| | Water Closet | Teachers Lounge B | 1 | EA | 6 | 10+ years | |
| 1000 | m Classroom | | - | المائدة | . Main | | |
| ego | ry : Classroom | | В | uilding | . wain | Recommend | |
| OUD | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| oup | Item - Type | LUCALION | Quantity | UUIVI | Rdilk | Replacement | Comments |
| ssroc | om #100 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 63 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 1st Floor | 1,044 | SF | 6 | 6-10 years | |
| | Centrig - Opinied | 1001 | 1,011 | O . | - | 0 . 0 j 0 a. 0 | |

Building : Main

Campus Name: Kershaw Page : 14 of 26 Assessment Date: 08/03/2023



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|----------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Doors - Side-lite | 1st Floor | 24 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,044 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 21 | EA | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 25 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 580 | SF | 6 | 10+ years | |
| | Walls - Masonry | 1st Floor | 120 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Classroo | om #102 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 63 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 1st Floor | 1,044 | SF | 6 | 6-10 years | |
| | Chalk Board | 1st Floor | 4 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 24 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,044 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 1,044 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 580 | SF | 6 | 10+ years | |
| | | | | SF SF | | | |
| | Walls - Masonry | 1st Floor | 120 | | 6 7 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | , | 6-10 years | |
| Classroc | om #105 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 43 | LF | 6 | 10+ years | |
| | Ceiling - Splined | 1st Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 1st Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 835 | SF | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 5 | SF | 4 | 0-1 year | Damaged |
| | Lighting - Pendent/Surface | 1st Floor | 15 | ĒΑ | 6 | 6-10 years | 3.1 |
| | Marker Board | 1st Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 32 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 720 | SF | 6 | 10+ years | |
| Classroo | om #107 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 43 | LF | 6 | 2-5 years | |
| | Casework Ceiling - Splined | 1st Floor | 840 | SF | 6 | | |
| | Chalk Board | 1st Floor | 10 | SF LF | 4 | 6-10 years | |
| | Doors - Side-lite | 1st Floor | | SF | | 2-5 years | |
| | | | 16 | | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|---|------------------------|----------|----------|--------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Tile | 1st Floor | 825 | SF | 6 | 6-10 years | |
| | Floor - Tile | 1st Floor | 15 | SF | 4 | 0-1 year | Damaged |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 6 | 6-10 years | · · |
| | Marker Board | 1st Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 720 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | ĒΑ | 7 | 6-10 years | |
| Classroo | om #108 (Store Room) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 43 | LF | 6 | 10+ years | |
| | Ceiling - Splined | 1st Floor | 840 | SF | 7 | 10+ years | |
| | Chalk Board | 1st Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 10 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 840 | SF | 7 | • | |
| | Lighting - Pendent/Surface | 1st Floor | | EA | | 10+ years | |
| | Marker Board | 1st Floor | 15 20 | LF | 6 | 6-10 years | |
| | | | | SF | 7 | 10+ years | |
| | Storage/ Closet | 1st Floor | 32 | | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 720 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 6-10 years | |
| Classroo | om #109 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 43 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 1st Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 1st Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 820 | SF | 7 | 6-10 years | |
| | Floor - Tile | 1st Floor | 20 | SF | 4 | 0-1 year | Damaged |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 6 | 6-10 years | 3 |
| | Marker Board | 1st Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 720 | SF | 6 | 10+ years | |
| :lassroo | om #110 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 43 | LF | 6 | 10+ years | |
| | Casework Ceiling - Splined | 1st Floor | 840 | SF | 7 | 6-10 years | |
| | Chalk Board | 1st Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | | SF | | | |
| | Doors - Side-lite Doors - Wood Doors inclu hw | 1st Floor 1st Floor | 16 1 | SF EA | 6 6 | 10+ years | |
| | DOOLS - MOOD DOOLS LLICIN LIM | ISI FIOOI | 1 | EA | Ö | 10+ years | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|-----------|----------|---------|--------|-------------|----------|
| _ | | | | _ | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Floor - Tile | 1st Floor | 840 | SF | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 32 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 720 | SF | 6 | 10+ years | |
| Classroc | om #111 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 43 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 1st Floor | 828 | SF | 6 | 6-10 years | |
| | Ceiling - Splined | 1st Floor | 12 | SF | 4 | 1-2 years | Damaged |
| | Chalk Board | 1st Floor | 10 | LF | 4 | 1-2 years | Damageu |
| | Doors - Side-lite | 1st Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 10 | EA | 6 | • | |
| | | | | SF | | 10+ years | |
| | Floor - Tile | 1st Floor | 840 | | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 720 | SF | 6 | 10+ years | |
| Classroo | om #112 (Regular Classroom) | | | | | | |
| | AC Units | 1st Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 1st Floor | 43 | LF | 6 | 10+ years | |
| | Ceiling - Splined | 1st Floor | 805 | SF | 6 | 6-10 years | |
| | Chalk Board | 1st Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 1st Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 805 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 1st Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 32 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 650 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 120 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | ĒΑ | 7 | 6-10 years | |
| Classroo | om #200 (Computer Lab) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 35 | LF | 6 | 6-10 years | |
| | Casework Ceiling - Splined | 2nd Floor | 903 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | | |
| | Doors - Side-lite | | • • | SF | | 2-5 years | |
| | | 2nd Floor | 16 | | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 903 | SF | 7 | 10+ years | |



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|-----------------------------|------------------------|----------|----------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Lighting - Pendent/Surface | 2nd Floor | 17 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 730 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 220 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Classroo | om #201 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 43 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 10 | EA | 6 | • | |
| | Floor - Tile | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | | | | | - | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA LF | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 720 | SF | 6 | 10+ years | |
| Classroo | om #202 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 43 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 720 | SF | 6 | 10+ years | |
| Classroo | om #203 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 43 | LF | 6 | 6-10 years | |
| | Casework Ceiling - Splined | 2nd Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 1-2 years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 10 | EA | 6 | | |
| | | 2nd Floor 2nd Floor | 830 | SF | - | 10+ years | |
| | Floor - Tile | | | | 6 | 10+ years | Damagad |
| | Floor - Tile | 2nd Floor | 10 | SF | 4 | 0-1 year | Damaged |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |

Campus Name: Kershaw Page : 18 of 26 Assessment Date: 08/03/2023



| Catego | ry : Classroom | | В | uilding | : Main | | |
|----------|---|------------------------|---------------------------------------|----------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Storage/ Closet | 2nd Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 720 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| Classroo | om #204 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 43 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | ĹF | 4 | 1-2 years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 720 | SF | 6 | 10+ years | |
| | | | 120 | | 7 | , | |
| | Work Sink | 2nd Floor | ı | EA | / | 6-10 years | |
| Classroc | om #205 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 43 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 0-1 year | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 720 | SF | 6 | 10+ years | |
| Classroo | om #206 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 43 | LF | 6 | 6-10 years | |
| | Casework Ceiling - Splined | 2nd Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 1-2 years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Side-life Doors - Wood Doors inclu hw | 2nd Floor 2nd Floor | 10 | Sr EA | 6 | | |
| | | | · · · · · · · · · · · · · · · · · · · | | - | 10+ years | |
| | Floor - Tile | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 720 | SF | 6 | 10+ years | |



| Catego | ry : Classroom | | В | uilding | : Main | | • |
|-----------|-----------------------------|-----------|----------|---------|--------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | | | _ | | | - | |
| Classroc | om #207 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 43 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 1-2 years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EΑ | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 720 | SF | 6 | 10+ years | |
| | Wireless System | 2nd Floor | 1 | ĒΑ | 7 | 6-10 years | |
| | Work Sink | 2nd Floor | 1 | EΑ | 7 | 6-10 years | |
| | | | | | | , | |
| Classroo | om #208 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 43 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 10 | ĹF | 4 | 1-2 years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EΑ | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 720 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | | | | | | • | |
| _Classroo | om #209 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 43 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 720 | SF | 7 | 10+ years | |
| | | | | | | | |



| Catego | ry : Classroom | | В | uilding | : Main | | o too o cowo Avervoe, omoago, ie ooozi |
|-----------|-----------------------------|-----------|----------|---------|--------|-------------|--|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Classroo | om #210 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 43 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | ĒΑ | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | ĒΑ | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 720 | SF | 6 | 10+ years | |
| | | | | | | • | |
| _Classroo | om #211 (Regular Classroom) | | | | | | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 43 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 720 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 6-10 years | |
| | | | | | | | |
| _Classroo | om #212 (Regular Classroom) | 0.15 | | Ε.Δ. | | 0.40 | |
| | AC Units | 2nd Floor | 2 | EA | 7 | 6-10 years | |
| | Casework | 2nd Floor | 43 | LF | 6 | 6-10 years | |
| | Ceiling - Splined | 2nd Floor | 840 | SF | 6 | 6-10 years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 2nd Floor | 16 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 840 | SF | 6 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd Floor | 15 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 20 | LF | 6 | 6-10 years | |
| | Storage/ Closet | 2nd Floor | 32 | SF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 720 | SF | 6 | 10+ years | |
| | | | | | | | |

Campus Name: Kershaw Page : 21 of 26 Assessment Date: 08/03/2023



| Catego | ry : Interior | | В | uilding | : Main | | ¥ : |
|----------|--------------------------------------|-----------|----------|---------|--------|-------------|--------------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| Corridor | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 1,828 | SF | 6 | 6-10 years | |
| | Ceiling - Splined | 1st Floor | 2,958 | SF | 6 | 6-10 years | |
| | Doors - Side-lite | 1st Floor | 14 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | 1st Floor | 3 | EA | 6 | 10+ years | |
| | Doors - Store Front | 1st Floor | 8 | EA | 6 | 10+ years | |
| | Doors - Transom Window | 1st Floor | 543 | SF | 6 | 10+ years | |
| | Doors - Wood Doors include hw | 1st Floor | 5 | EA | 6 | 10+ years | |
| | Drinking Fountains - Single Fountain | 1st Floor | 7 | EA | 7 | 6-10 years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor | 780 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 3,906 | SF | 5 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 100 | SF | 4 | 1-2 years | Damaged |
| | Lighting - Chandelier, Incandescent | 1st Floor | 2 | EA | 6 | 6-10 years | |
| | Lighting - Pendent/Surface | 1st Floor | 80 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 1st Floor | 2,673 | SF | 6 | 10+ years | |
| | Walls - Masonry | 1st Floor | 5,554 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd floor | 2,094 | SF | 6 | 6-10 years | |
| | Doors - Transom Window | 2nd floor | 432 | SF | 6 | 10+ years | |
| | Drinking Fountains - Single Fountain | 2nd floor | 4 | EA | 5 | 0-1 year | Out of order |
| | Floor - Tile/Sheet | 2nd floor | 2,074 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 2nd floor | 20 | SF | 4 | 0-1 year | Damaged |
| | Lighting - Pendent/Surface | 2nd floor | 34 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd floor | 1,680 | SF | 6 | 10+ years | |
| | Walls - Masonry | 2nd floor | 1,440 | SF | 6 | 10+ years | |
| Safety | | | | | | | |
| | Camera Viewing Station | corridors | 2 | EA | 7 | 6-10 years | |
| | Security Cameras | corridors | 7 | EA | 7 | 6-10 years | |
| Stairs | | | | | | | |
| | Ceiling - Lay-in | North | 496 | SF | 6 | 6-10 years | |
| | Ceiling - Plaster/Drywall | North | 216 | SF | 6 | 6-10 years | |
| | Floor - Terrazzo | North | 160 | SF | 6 | 10+ years | |
| | Floor - Tile | North | 430 | SF | 6 | 10+ years | |
| | Handrails | North | 74 | LF | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | North | 4 | EA | 6 | 6-10 years | |
| | Stairs - Terrazzo | North | 368 | LF | 6 | 10+ years | |
| | Walls - Masonry | North | 1,364 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | South | 496 | SF | 6 | 6-10 years | |
| | Floor - Terrazzo | South | 160 | SF | 6 | 10+ years | |
| | Floor - Tile | South | 430 | SF | 6 | 10+ years | |
| | Handrails | South | 74 | LF | 7 | 6-10 years | |
| | Lighting - Pendent/Surface | South | 4 | EA | 6 | 6-10 years | |
| | | | | | | | |



| Catego | ry : Interior | | Ві | | | | |
|--------|-------------------|----------|----------|-----|------|-------------|----------|
| | | | | | | Recommend | |
| Group | Item - Type | Location | Quantity | UOM | Rank | Replacement | Comments |
| | Stairs - Terrazzo | South | 368 | LF | 6 | 6-10 years | |
| | Walls - Masonry | South | 1,364 | SF | 6 | 10+ years | |

Campus Name: Kershaw Page : 23 of 26 Assessment Date: 08/03/2023



Category : Site **Building: Site**

| omments |
|--------------------|
| |
| |
| |
| |
| |
| |
| |
| |
| lling over. |
| |
| |
| |
| |
| |
| |
| neven, missing |
| |
| |
| |
| |
| |
| |
| oken, disassembled |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| oles |
| |
| |
| |
| |
| |
| |
| |
| ole |



Joshua D Kershaw Elementary School

6450 S Lowe AVENUE, Chicago, IL 60621

| Catego | ry : Site | | Ві | | | | |
|----------|---|-------------|----------|-----|------|--------------------------|--------------|
| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
| Sidewalk | (S | | | | | | |
| | Sidewalks - Internal Walks | Entire Site | 100 | LF | 5 | 1-2 years | Spalling |
| | Sidewalks - Internal Walks | Entire Site | 75 | LF | 4 | 0-1 year | Old, broken. |
| | Sidewalks - Perimeter Sidewalks | Entire Site | 8,238 | SF | 6 | 10+ years | |
| Signage | | | | | | | |
| | Flag Pole - Flag Pole | East | 1 | EA | 6 | 10+ years | |
| | Marquee - Free Standing Back lighted w/ LED | East | 1 | EA | 7 | 6-10 years | |
| | Monument - Building Mounted Cut Letter Sign | East | 1 | EA | 7 | 10+ years | |

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Kershaw Page : 25 of 26 Assessment Date: 08/03/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

| į | | | Room | Floor Plan Room | Area | Glazed Window | Operable Window | Window | Smart- |
|-------------------|-------------------|---------------|----------|--------------------|-------|------------------|--------------------|--------|--------|
| Current Usage | Intended Usage | Room Location | Number | Number | (SF) | Area | Area | Stop | Board |
| Building : Main | | | 11011100 | | (0-) | 1 1 0 0 | 1 11 2 21 | 0.00 | |
| Computer Lab | Computer Lab | 2nd Floor | 200 | 200 | 903 | 151 | 96 | Υ | N |
| Regular Classroom | Computer Lab | 2nd Floor | 207 | 207 | 840 | 151 | 50 | Υ | Υ |
| Regular Classroom | Kindergarten | 1st Floor | 100 | 100 | 1,044 | 230 | 95 | Y | Υ |
| Regular Classroom | Kindergarten | 1st Floor | 102 | 100 | 1,044 | 230 | 95 | Y | Υ |
| Regular Classroom | Kindergarten | 1st Floor | 112 | 112 | 805 | 151 | 50 | Y | Υ |
| Regular Classroom | Regular Classroom | 1st Floor | 105 | 105 | 840 | 151 | 50 | Y | Υ |
| Regular Classroom | Regular Classroom | 1st Floor | 109 | 109 | 840 | 151 | 50 | Y | Υ |
| Regular Classroom | Regular Classroom | 1st Floor | 110 | 110 | 840 | 151 | 50 | Y | Υ |
| Regular Classroom | Regular Classroom | 1st Floor | 111 | 111 | 840 | 151 | 50 | Y | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | 201 | 840 | 151 | 50 | Y | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 202 | 202 | 840 | 151 | 50 | Υ | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 203 | 203 | 840 | 151 | 50 | Υ | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | 205 | 840 | 151 | 50 | Y | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | 206 | 840 | 151 | 50 | Y | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | 208 | 840 | 151 | 50 | Υ | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 209 | 209 | 840 | 151 | 50 | Υ | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 210 | 210 | 840 | 151 | 50 | Υ | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 211 | 211 | 840 | 151 | 50 | Υ | Υ |
| Regular Classroom | Regular Classroom | 2nd Floor | 212 | 212 | 840 | 151 | 50 | Υ | Υ |
| Regular Classroom | Science Classroom | 1st Floor | 107 | 107 | 840 | 151 | 50 | Υ | Υ |
| Regular Classroom | Science Classroom | 2nd Floor | 204 | 204 | 840 | 151 | 50 | Υ | Υ |
| Store Room | Regular Classroom | 1st Floor | 108 | 108 | 840 | 151 | 50 | | |