

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1961	3	60,474
Campus Total			60,474

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	#1 -Main Accessibile- NW	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#1 -Main Accessibile- NW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 -Main Accessibile- NW	2	EA	4	0-1 year	Original single pane glass
	Ramp Handrail - Steel_Ramp Handrail	#1 -Main Accessibile- NW	130	LF	6	6-10 years	
	Ramps - Concrete	#1 -Main Accessibile- NW	65	LF	5	0-1 year	Broken concrete, buckling concrete
	Exterior Doors - Exterior Wood Door	#2- SW	2	EA	4	0-1 year	Rotted, delaminated doors
	Exterior Doors - Transom Lite	#2- SW	2	EA	4	0-1 year	Original single pane transom
	Exterior Stairs - Concrete	#2- SW	55	LF	5	10+ years	
	Exterior Stairs - Concrete	#2- SW	20	LF	3	0-1 year	Broken, shattered landing. Cracked stairs.
	Exterior Stairs - Stone	#2- SW	6	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#2- SW	35	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#3- SW	2	EA	4	1-2 years	Delaminated wood doors
	Exterior Doors - Transom Lite	#3- SW	1	EA	4	0-1 year	Single pane wood transom
	Exterior Stairs - Concrete	#3- SW	10	LF	6	10+ years	
	Exterior Stairs - Concrete	#3- SW	10	LF	4	0-1 year	Broken, spalled, cracked concrete steps
	Exterior Stairs - Stone	#3- SW	36	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#3- SW	20	LF	7	10+ years	
	Exterior Doors - Exterior FRP Door	#4- SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4- SE	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#4- SE	10	LF	5	0-1 year	Crack at the landing, chipped step
	Ramp Handrail - Steel_Ramp Handrail	#4- SE	113	LF	5	2-5 years	Corroding post bases are breaking concrete



Catego	ry : Exterior		B	uilding	: Main		
Sarege	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oreup	Ramp Handrail - Steel_Ramp Handrail	#4- SE	1	LF	4	0-1 year	Corroded, loose and broken post at crack
	Ramps - Concrete	#4- SE	57	LF	5	0-1 year	Cracks along the ramp and at the foundation wall
	Stair Handrail - Steel_Stair Handrail	#4- SE	10	LF	6	6-10 years	
	Exterior Doors - Overhead Rolling/ Garage	#4.5- NE	1	EA	6	6-10 years	
	Door		Į.	L / (Ū	o ro youro	
	Exterior Stairs - Concrete	#4.5- NE	8	LF	5	1-2 years	Broken concrete
	Entrance Control - Audio and Video	#5- Boiler Room- NE	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	#5- Boiler Room- NE	1	EA	4	1-2 years	Corroded door and frame
	Exterior Doors - Transom Lite	#5- Boiler Room- NE	1	EA	7	10+ years	
	Exterior Doors - Exterior Wood Door	#6 - NW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#6 - NW	- 1	EA	6	6-10 years	
	Exterior Stairs - Stone	#6 - NW	68	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#6 - NW	20	LF	6	10+ years	
		#0 - NVV	20		0	TO+ years	
Foundat							
	Foundation - Concrete	Entire Building	939	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	60,474	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	14	EA	7	10+ years	
_Roof Sys	stem						
	Coping - Metal	Boiler roof	134	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Boiler roof	80	LF	7	10+ years	
	Roof - Modified Bitumen	Boiler roof	1,938	SF	7	10+ years	
	Roof Structure - Concrete	Boiler roof	1,938	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Boiler roof	1,740	SF	7	,	
	Concrete Topping	Bollet 1001	192	Эг	'	10+ years	
	Coping - Stone	Low N roof	190	LF	5	1-2 years	Coping sealant has been applied over old sealant or mortar. Peeling off.
	Downspouts - Interior Downspouts	Low N roof	68	LF	6	6-10 years	old obtained montain rooming on
	Parapet - 16" - 30" Height	Low N roof	40	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Low N roof	150	LF	7	10+ years	
	Roof - Modified Bitumen	Low N roof	3,754	SF	7	10+ years	
	Roof Hatch - Metal	Low N roof	3,734	EA	3	1-2 years	Access from below not found
	Roof Structure - Concrete	Low N roof	3,754	SF	7	10+ years	
	Coping - Terra Cotta	Low NW roof	3,754	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low NW roof	22	LF	6	10+ years	No oppos
	Roof - Modified Bitumen	Low NW roof	55	SF	5	6-10 years	No access
	Roof Structure - Concrete	Low NW roof	55	SF	6	10+ years	
	Access Ladder - Metal	Low S roof	2	EA	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	Low S roof	1	EA	4	0-1 year	Unsafe ladder, hard to access or climb
	Chimney - Metal Flue	Low S roof	12	LF	6	10+ years	
	Coping - Stone	Low S roof	382	LF	5	1-2 years	Coping sealant has been applied ove old sealant or mortar. Peeling off.
	Downspouts - Interior Downspouts	Low S roof	136	LF	6	6-10 years	C C
	Parapet - 16" - 30" Height	Low S roof	30	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Low S roof	352	LF	7	10+ years	
	Roof - Modified Bitumen	Low S roof	8,018	SF	7	10+ years	
	Roof Hatch - Metal	Low S roof	3	EA	7	10+ years	
	Roof Structure - Concrete	Low S roof	8,018	SF	7	10+ years	
	Coping - Terra Cotta	Low SW roof	22	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low SW roof	22	LF	6	10+ years	
	Roof - Modified Bitumen	Low SW roof	55	SF	6	6-10 years	No access
	Roof Structure - Concrete	Low SW roof	55	SF	7	10+ years	NO access
	Access Ladder - Metal	Main Roof	1	EA	7		
			55		6	10+ years	
	Chimney - Brick Chimney- Stainless Steel Liner	Main Roof		LF	0	6-10 years	
	Coping - Metal	Main Roof	341	LF	7	10+ years	
	Coping - Stone	Main Roof	138	LF	5	1-2 years	Coping sealant has been applied over old sealant or mortar. Peeling off.
	Downspouts - Exterior Downspouts	Main Roof	2	LF	6	6-10 years	C C
	Downspouts - Interior Downspouts	Main Roof	200	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Main Roof	459	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Main Roof	20	LF	6	6-10 years	
	Roof - Modified Bitumen	Main Roof	11,394	SF	6	10+ years	Minor blistering
	Roof - Modified Bitumen	Main Roof	70	SF	4	0-1 year	Roof is pitched away from the
				01	·	o i your	drainage. Pools, water does not drain.
	Roof Hatch - Metal	Main Roof	2	EA	7	10+ years	
	Roof Structure - Concrete	Main Roof	11,355	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	109	SF	7	10+ years	
	Downspouts - Exterior Downspouts	SE courtyard	6	LF	6	6-10 years	
	Roof - Modified Bitumen	SE courtyard	370	SF	6	6-10 years	No access
	Roof Structure - Concrete	SE courtyard	370	SF	7	10+ years	
			570	01	I	Tor years	
Nalls	Cheek-Wall - Concrete	Entire Building	10	SF	5	10+ years	
	Cheek-Wall - Stone	Entire Building	36	SF	5		Popairod
	Cheek-Wall - Stone	Entire Building	36	SF	7 5	10+ years	Repaired
				SF LF		0-1 year	Settlement of cheek wall, open joints
	Cornice - Cast Stone	Entire Building	100		7	10+ years	
	Cornice - Terra Cotta	Entire Building	1,888	LF	6	10+ years	
	Cornice - Terra Cotta	Entire Building	189	LF	5	0-1 year	Open joints



ego	ry : Exterior		В	uilding	: Main		
						Recommend	
up	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	36,296	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	2,500	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	1,044	SF	4	0-1 year	Open joints cracked brick
	Exterior Walls - Stone-Cast	Entire Building	10	SF	6	2-5 years	
	Exterior Walls - Stone-Cast	Entire Building	20	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	100	SF	6	2-5 years	
	Exterior Walls - Terra Cotta	Entire Building	1,239	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	120	SF	4	0-1 year	Cracked, broken terracotta
	Exterior Walls - Terra Cotta	Entire Building	20	SF	4	0-1 year	Cracked, broken terracotta
	Exterior Walls - Terra Cotta	Entire Building	20	SF	4	0-1 year	Cracked, broken stone with
			20	01	7	0 Tycar	vegetation growing
dows							
	Guard - Guards perforated	Entire Building	3,240	SF	6	10+ years	
	Lintels - Steel	Entire Building	703	LF	5	6-10 years	
	Lintels - Terra Cotta	Entire Building	50	LF	6	6-10 years	
	Windows - Louver	Entire Building	15	SF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	240	SF	6	6-10 years	
				~ -	-	<u> </u>	
ego	Windows - Sash Aluminum Double-pane ry : Electrical	Entire Building	7,000 B	SF uilding	6 : Main	6-10 years	
_	Windows - Sash Aluminum Double-pane ry : Electrical	-	B	uilding	: Main	Recommend	Comments
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type	Entire Building	,		-	-	Comments
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type ncy System	Location	Quantity	uilding UOM	: Main Rank	Recommend Replacement	Comments
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type ncy System Automatic Transfer Switch	Location Boiler Room	B Quantity 1	uilding UOM EA	: Main Rank	Recommend Replacement 6-10 years	Comments
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type Automatic Transfer Switch Emergency A/C Power - Auditoium and Aisle Lighting	Location Boiler Room Entire Building	B Quantity 1 2,970	uilding UOM EA SF	: Main Rank 6 6	Recommend Replacement 6-10 years 10+ years	Comments
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type Automatic Transfer Switch Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs	Location Boiler Room Entire Building Entire Building	B Quantity 1 2,970 7,145	UOM EA SF SF	: Main Rank	Recommend Replacement 6-10 years 10+ years 10+ years	Comments
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type Automatic Transfer Switch Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym	Location Boiler Room Entire Building Entire Building Entire Building	B Quantity 1 2,970 7,145 3,043	UOM EA SF SF SF	: Main Rank 6 6 6 6	Recommend Replacement 6-10 years 10+ years 10+ years 10+ years	Comments
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type Automatic Transfer Switch Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms	Location Boiler Room Entire Building Entire Building	B Quantity 1 2,970 7,145 3,043 1,258	UOM EA SF SF SF SF	: Main Rank 6 6 6 6 6 6 6	Recommend Replacement 6-10 years 10+ years 10+ years	Comments
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type Automatic Transfer Switch Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets	Location Boiler Room Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 1 2,970 7,145 3,043	UOM EA SF SF SF SF SF SF	: Main Rank 6 6 6 6	Recommend Replacement 6-10 years 10+ years 10+ years 10+ years	Comments
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type Automatic Transfer Switch Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Lunchrooms	Location Boiler Room Entire Building Entire Building Entire Building Entire Building	B Quantity 1 2,970 7,145 3,043 1,258	UOM EA SF SF SF SF	: Main Rank 6 6 6 6 6 6 6	Recommend Replacement 6-10 years 10+ years 10+ years 10+ years 10+ years	Comments
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type http://www.alumenterial. Automatic Transfer Switch Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency Battery Packs - Auditoium and	Location Boiler Room Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 1 2,970 7,145 3,043 1,258 2,005	UOM EA SF SF SF SF SF SF	: Main Rank 6 6 6 6 6 6 6 6 6 6	Recommend Replacement 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Comments
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type Automatic Transfer Switch Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs	Location Boiler Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 1 2,970 7,145 3,043 1,258 2,005 2 11	UOM EA SF SF SF SF SF SF EA	: Main Rank 6 6 6 6 6 6 6 6 6	Recommend Replacement 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	Comments Broken light stem
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type Automatic Transfer Switch Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym	Location Boiler Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 1 2,970 7,145 3,043 1,258 2,005 2 11 2	UOM EA SF SF SF SF EA EA EA	: Main Rank 6 6 6 6 6 6 6 6 6 6 6 2	Recommend Replacement 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 0-1 year	
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type Automatic Transfer Switch Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs	Location Boiler Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 1 2,970 7,145 3,043 1,258 2,005 2 11	UOM EA SF SF SF SF EA EA	: Main Rank 6 6 6 6 6 6 6 6 6	Recommend Replacement 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years	Broken light stem No battery or emergency genera
up	Windows - Sash Aluminum Double-pane ry : Electrical Item - Type Automatic Transfer Switch Emergency A/C Power - Auditoium and Aisle Lighting Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Gym Emergency A/C Power - Students Toilets Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Gym Emergency Battery Packs - Students Toilets	Location Boiler Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	B Quantity 1 2,970 7,145 3,043 1,258 2,005 2 11 2 5	UOM EA SF SF SF SF EA EA EA EA	: Main Rank 6 6 6 6 6 6 6 6 6 6 6 6 2 6	Recommend Replacement 6-10 years 10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 0-1 year 6-10 years	Broken light stem



	schools					8	101 S LaSalle STREET, Chicago, IL 6062
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security System - CCTV	Entire Building	60,474	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	60,474	SF	6	6-10 years	
/lain Sei	rvice						
	Independent Electrical Service for emergency power	Boiler Room	1	EA	7	10+ years	
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	60,474	SF	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	Fuse panel contains empty fuse sockets presenting live front condition.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	3	1-2 years	Basement lighting panel LP is live front
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	Kitchen
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years	Auditorium & MDF
	Main Distribution Panels - 400 - 600 amp	Entire Building	4	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire ALarm Anunciator	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	6	2-5 years	
	Fire Alarm Panel	Entire Building	1	EA	6	2-5 years	Second fire alarm panel
	Fire Alarm Strobe Lights	Entire Building	60,474	SF	6	6-10 years	·
	Fire Alarm_System	Entire Building	60,474	SF	6	6-10 years	

Fire Pump - 25-50 hp	Boiler Room	1	EA	6	10+ years
Jockey Pump	Boiler Room	1	EA	6	10+ years
er System					
Coriolder Heada	Entire Duilding	60 474	°L	7	6 10 years
Sprinkler Heads	Entire Building	60,474	SF	7	6-10 years
Sprinkler Piping	Entire Building	60,474	SF	6	10+ years



Lenart Elementary Regional Gifted Center 8101 S LaSalle STREET, Chicago, IL 60620

Single Zone- fm n / and Ducts-	AHU-1 AHU-1 AHU-1 AHU-1	Quantity 1 1 1	UOM EA	Rank	Recommend Replacement 2-5 years	Comments AHU-1 serves auditorium. Leather
fm n / and Ducts-	AHU-1 AHU-1 AHU-1	1	EA			
fm n / and Ducts-	AHU-1 AHU-1	1		5	2-5 years	AHU-1 serves auditorium. Leather
fm n / and Ducts-	AHU-1 AHU-1	1		5	2-5 years	AHU-1 serves auditorium. Leather
/ and Ducts-	AHU-1					belt has been replaced with standard V-notch quad belt pulleys.
/ and Ducts-	AHU-1		EA	5	6-10 years	Common with AHU-2
			EA	7	2-5 years	New belts, motor, pulleys, and controls.
	AHU-1	100	LF	5	6-10 years	
Single Zone w/ 01 - 15000 cfm	AHU-2	1	EA	5	2-5 years	Serves North Tunnel - AHU-2
	AHU-2	1	EA	7	10+ years	
fm	AHU-2	1	EA	5	2-5 years	
kes with Steam	AHU-2	4	EA	4	0-1 year	Manually operated, pneumatic system is non-functional
and Ducts-	AHU-2	100	LF	5	10+ years	eyetenn is nen ranotienal
	AHU-2	12	EA	3	0-1 year	All manual control, pneumatic system nonfunctional.
Single Zone- fm	AHU-3	1	EA	5	2-5 years	AHU-3 serves gymnasium
	AHU-3	1	EA	7	6-10 years	Common with AHU-4
n	AHU-3	1	EA	5	2-5 years	
and Ducts-	AHU-3	100	LF	6	10+ years	Sheet metal ductwork
Single Zone w/ 6001 - 25000 cfm	AHU-4	1	EA	5	2-5 years	AHU-4
20000 0000	AHU-4	1	EA	7	10+ years	
cfm	AHU-4	1	EA	5	2-5 years	
kes with Steam	AHU-4	6	EA	4	0-1 year	Manually open and close. Pneumatic system nonfunctional.
/ and Ducts-	AHU-4	100	LF	5	2-5 years	
	AHU-4	18	EA	3	0-1 year	All manual, pneumatic system nonfunctional
nted- Gas า	Main Roof	1	EA	5	2-5 years	Aged, with flue, corrosion and top of cabinet corrosion
ne- Steam Low HP	Boiler Room	2	EA	6	10+ years	
	Boiler Room	1	EA	6	6-10 years	
	Boiler Room	1	EA	6	6-10 years	
	Boiler Room	1	EA	6		Control needs work
n	e- Steam Low	ted- Gas Main Roof e- Steam Low Boiler Room IP Boiler Room Boiler Room	ted- Gas Main Roof 1 e- Steam Low Boiler Room 2 IP Boiler Room 1 Boiler Room 1 Boiler Room 1	ted- Gas Main Roof 1 EA e- Steam Low Boiler Room 2 EA IP Boiler Room 1 EA Boiler Room 1 EA	ted- Gas Main Roof 1 EA 5 e- Steam Low Boiler Room 2 EA 6 Boiler Room 1 EA 6 Boiler Room 1 EA 6	ted- Gas Main Roof 1 EA 5 2-5 years e- Steam Low Boiler Room 2 EA 6 10+ years IP Boiler Room 1 EA 6 6-10 years Boiler Room 1 EA 6 6-10 years



Category : Mechanical

	y i moonamoan			anang	· main	Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Combustion Dampers	Boiler Room	1	EA	5	1-2 years	Corroded damper blades
	Condensate Pump	Boiler Room	1	EA	4	1-2 years	Extremely active steam coming fro condensate basin. Only one pump functional.
	Condensate Pump	Boiler Room	1	EA	4	1-2 years	Pump has failed.
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	10+ years	i amp nao lanoa.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	10+ years	B-1
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	10+ years	B-2
	Piping - Condensate Pipe- Steel	Boiler Room	500	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	500	LF	5	6-10 years	
	Steam Traps	Boiler Room	50	EA	5	6-10 years	Many failed steam traps
ating	Devices						
	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	
	Fin Tube - Steam	Entire Building	30	LF	6	6-10 years	
	Radiators - Steam	Entire Building	26	EA	6	10+ years	Behind decorative and protective grilles
	Wall Heater - Electric	Entire Building	6	EA	4	0-1 year	Not working per building engineer found in toilet rooms where redun steam radiators exist
mpera	ture Control						
	Pneumatic System	Entire Building	60,474	SF	3	0-1 year	Compressor does not run. System failed.
	Thermostats - Pneumatic	Entire Building	32	EA	4	0-1 year	System nonfunctional per building engineer, manually operated.
entilatio	ึ่งท						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof and 1st Floor	1	EA	5	6-10 years	
	Roof Mounted Duct Work	Roof and 1st Floor	60	LF	4	1-2 years	Heavily corroded, uninsulated Exhaust tech work for kitchen ven hood also showing heavy corrosic
	Type I Exhaust Hood- Kitchen Type II Exhaust Hood- Warming Kitchen	Roof and 1st Floor Roof and 1st Floor	1 1	EA EA	6 6	10+ years 10+ years	,
atego	ry : Plumbing		В	uilding	: Main		
	, ,					Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments

Building : Main



Catego	ry : Plumbing		В	uilding	: Main		
	- 					Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	60,474	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	60,474	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	60,474	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	60,474	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	60,474	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	60,474	SF	6	10+ years	
	Sanitary Piping	Entire Building	60,474	SF	6	10+ years	
	Storm Piping	Entire Building	60,474	SF	6	10+ years	
	Vent Piping	Entire Building	60,474	SF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	7	10+ years	New Symplex booster pump system replaces failed duplex system from previous assessment.
	Pumps - Sump-Duplex	Basement	1	EA	6	10+ years	Duplex pump near AHU-1 which serves auditorium
	Pumps - Sump-Duplex	Basement	1	EA	6	10+ years	Located in south tunnel
	Pumps - Sump-Duplex	Basement	1	EA	6	10+ years	Sump pit behind main live front electrical switchboard.
	Pumps - Sump-Duplex	Basement	1	EA	6	10+ years	Sump pit near boiler water feed tank and pumps
	Pumps - Sump-Simplex	Basement	1	EA	6	10+ years	Some pump at bottom of elevator pit not accessible during time of assessment.
Catogo	ry · Room		B	uilding	• Main		

Catego	Category : Room			uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	rative Suites/Offices						
	AC Unit	1st flr custodian's office next to engineer's office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr custodian's office next to engineer's office	117	SF	7	10+ years	Not accessible, person with keys is not here
	Doors - Wood Doors inclu hw	1st flr custodian's office next to engineer's office	1	EA	7	10+ years	
	Floor - Tile	1st flr custodian's office next to engineer's office	117	SF	7	10+ years	



	Category : Room		B	TOT'S LASAIRE STREET, Chicago, IL 60620			
Catego	ry . Room			uilding		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup	Lighting - Pendent/Surface	1st flr custodian's office next to	1	EA	7	6-10 years	
		engineer's office					
	Power Distribution	1st flr custodian's office next to engineer's office	6	EA	7	10+ years	
	Walls - Masonry	1st flr custodian's office next to engineer's office	396	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st flr engineer's office	137	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr engineer's office	1	EA	7	10+ years	
	Floor - Epoxy/ Painted	1st flr engineer's office	137	SF	7	10+ years	
	Lighting - Pendent/Surface	1st flr engineer's office	1	EA	6	6-10 years	
	Power Distribution	1st flr engineer's office	6	EA	7	10+ years	
	Storage/ Closet	1st flr engineer's office	150	SF	7	10+ years	
	Walls - Plaster/Drywall	1st flr engineer's office	432	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd flr #314	148	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd flr #314	1	ĒA	7	10+ years	
	Floor - Carpet	3rd flr #314	143	SF	7	6-10 years	
	Floor - Carpet	3rd flr #314	5	SF	4	1-2 years	Worn carpet
	Lighting - Pendent/Surface	3rd flr #314	2	EA	7	6-10 years	Repaired
	Power Distribution	3rd flr #314	6	EA	7	10+ years	Repared
	Walls - Plaster/Drywall	3rd flr #314	324	SF	7	10+ years	
	Ceiling - Lay-in	Assistant principal Room 101B	146	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Assistant principal Room 101B	1	EA	7	10+ years	
	Floor - Carpet	Assistant principal Room 101B	126	SF	7	6-10 years	
	Floor - Carpet	Assistant principal Room 101B	20	SF	4	0-1 year	Ripples in carpet
	Lighting - Lay-in	Assistant principal Room 101B	20	EA	4	6-10 years	Ripples in carper
	Power Distribution	Assistant principal Room 101B	4	EA	7	•	
	Walls - Plaster/Drywall	Assistant principal Room 101B Assistant principal Room 101B	4 199	SF	7	10+ years	
		Counselor 109	300	SF		10+ years	
	Ceiling - Plaster/Drywall			SF	7	10+ years	
	Doors - Side-lite	Counselor 109	16		7	10+ years	
	Doors - Wood Doors inclu hw	Counselor 109	1	EA	7	10+ years	
	Floor - Tile/Sheet	Counselor 109	300	SF	7	10+ years	
	Lighting - Pendent/Surface	Counselor 109	4	EA	6	6-10 years	
	Power Distribution	Counselor 109	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Counselor 109	720	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen manager's office	40	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen manager's office	4	SF	4	0-1 year	Cracked ceiling tile
	Doors - Wood Doors inclu hw	Kitchen manager's office	1	EA	7	10+ years	
	Floor - Concrete	Kitchen manager's office	44	SF	7	10+ years	
	Lighting - Lay-in	Kitchen manager's office	1	EA	7	6-10 years	
	Power Distribution	Kitchen manager's office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Kitchen manager's office	92	SF	7	10+ years	
	AC Unit	Office 107, book storage	1	EA	7	6-10 years	
	Ceiling - Lay-in	Office 107, book storage	236	SF	7	10+ years	6 SQUARE FEET OF TILE MISSING.
	Doors - Wood Doors inclu hw	Office 107, book storage	1	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Carpet	Office 107, book storage	236	SF	6	6-10 years	
	Lighting - Lay-in	Office 107, book storage	4	EA	7	6-10 years	
	Power Distribution	Office 107, book storage	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Office 107, book storage	312	SF	7	10+ years	
	Ceiling - Lay-in	Office, Room 107A	119	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office, Room 107A	1	EA	7	10+ years	
	Floor - Carpet	Office, Room 107A	119	SF	7	6-10 years	
	Lighting - Lay-in	Office, Room 107A	2	EA	7	6-10 years	
	Power Distribution	Office, Room 107A	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Office, Room 107A	298	SF	7	10+ years	
	AC Unit	Principal's Office 101A	1	EA	7	6-10 years	
	Ceiling - Lay-in	Principal's Office 101A	154	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office 101A	1	EA	7	10+ years	
	Floor - Carpet	Principal's Office 101A	154	SF	6	6-10 years	
	Lighting - Lay-in	Principal's Office 101A	2	EA	7	6-10 years	
	Power Distribution	Principal's Office 101A	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office 101A	482	SF	7	10+ years	
	AC Unit	Room 101, Main Office	1	ĒA	7	6-10 years	
	Ceiling - Lay-in	Room 101, Main Office	401	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 101, Main Office	1	EA	7	10+ years	
	Floor - Carpet	Room 101, Main Office	200	SF	6	6-10 years	
	Floor - Wood	Room 101, Main Office	200	SF	7	10+ years	
	Lighting - Lay-in	Room 101, Main Office	5	EA	7	6-10 years	
	Power Distribution	Room 101, Main Office	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 101, Main Office	852	SF	7	10+ years	
	Ceiling - Lay-in	Room 105, Faculty Lounge	112	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Room 105, Faculty Lounge	390	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 105, Faculty Lounge	1	EA	7	10+ years	
	Floor - Tile	Room 105, Faculty Lounge	502	SF	7		
				EA	7	10+ years	
	Lighting - Lay-in Lighting - Pendent/Surface	Room 105, Faculty Lounge	2			6-10 years	
		Room 105, Faculty Lounge	6	EA	7	6-10 years	
	Power Distribution	Room 105, Faculty Lounge	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 105, Faculty Lounge	1,154	SF	7	10+ years	
	Work SInk	Room 105, Faculty Lounge	1	EA	7	10+ years	
uditoriu	ım & Theater						
	Balcony Seating	Room 100	75	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Room 100	2,970	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 100	_,4	EA	7	10+ years	
	Floor - Concrete	Room 100	800	SF	7	10+ years	
	Floor - Tile	Room 100	2,970	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	Room 100	2,070	EA	7	6-10 years	
	Main Floor Seating	Room 100	264	EA	7	10+ years	
	Stage	Room 100	513	SF	7	10+ years	
	Olaye		010		'	ior years	



Catego	ry : Room		В	uilding	: Main		
U				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stage Curtain	Room 100	6	EA	7	10+ years	
	Stage Lift	Room 100	1	EA	7	10+ years	
	Stage Lighting System	Room 100	1	EA	7	6-10 years	
	Stage-Stairs - Wood	Room 100	30	LF	7	10+ years	
	Stairs - Asphalt	Room 100	60	LF	7	10+ years	
	Stairs - Terrazzo	Room 100	35	LF	7	10+ years	
	Storage/ Closet	Room 100	65	SF	5	6-10 years	Peeling paint, priority changed to
						-	match current observations
	Walls - Plaster/Drywall	Room 100	6,744	SF	7	10+ years	
	·						
Symnas	ia						
	Ceiling - Plaster/Drywall	Room 111	3,043	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 111	2	EA	7	10+ years	
	Floor - Wood	Room 111	3,043	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	Room 111	8	EA	7	6-10 years	
	Storage/ Closet	Room 111	127	SF	7	10+ years	
	Walls - Masonry	Room 111	1,012	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 111	4,384	SF	7	10+ years	
(italiana							
Kitchen	AC Unit	1st flr SE corner	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st flr SE corner	995	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st flr SE corner	995 2	EA	7	10+ years	
	Floor - Tile/Sheet	1st flr SE corner	995	SF	7	10+ years	
	Lighting - Lay-in	1st flr SE corner	14	EA	7	6-10 years	
	Storage/ Closet	1st flr SE corner	212	SF	7		
	Walls - Plaster/Drywall	1st flr SE corner	1,170	SF	7	10+ years	
	Walls - Flastel/Drywall	TSUIT SE COME	1,170	эг	'	10+ years	
ibrary							
	AC Unit	Room 103	2	EA	7	6-10 years	
	Casework	Room 103	80	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Room 103	926	SF	7	10+ years	
	Doors - Side-lite	Room 103	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 103	2	EA	7	10+ years	
	Floor - Carpet	Room 103	926	SF	7	6-10 years	
	Lighting - Pendent/Surface	Room 103	11	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 103	1,642	SF	7	10+ years	
_unch &	Multipurpose Room						
	Ceiling - Lay-in	Room 113, Formerly Rooms 111 &	1,258	SF	7	10+ years	
		112	,			-	
	Doors - Side-lite	Room 113, Formerly Rooms 111 &	24	SF	7	10+ years	
		112					



Catoro	Category : Room			uilding	· Main		101 S LaSalle STREET, Chicago, IL 60620
Catego	ry : Room		Building : Main			Decommond	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Doors - Wood Doors inclu hw	Room 113, Formerly Rooms 111 &	2	EA	7	10+ years	Comments
		112				-	
	Floor - Tile	Room 113, Formerly Rooms 111 & 112	1,258	SF	7	10+ years	
	Lighting - Lay-in	Room 113, Formerly Rooms 111 & 112	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 113, Formerly Rooms 111 & 112	1,514	SF	7	10+ years	
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	113	SF	5	10+ years	Cracked ceiling
	Storage Room	1st floor east side of building (in boiler room)	231	SF	7	10+ years	
	Storage Room	1st floor east side of building (in boiler room)	187	SF	7	10+ years	
	Janitor's Closet	2nd Floor	113	SF	5	10+ years	
	Janitor's Closet	3rd Floor	113	SF	5	10+ years	
	Boiler Room	Basement	1,634	SF	5	10+ years	Paint peeling
	Crawl Space - Unfinished	Basement	9,970	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	9,850	SF	5	10+ years	
Restroor	n						
	Accessories	1st flr inside Pre-K 106	85	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr inside Pre-K 106	85	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside Pre-K 106	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr inside Pre-K 106	85	SF	7	10+ years	
	Floor Drain	1st flr inside Pre-K 106	1	ĒA	7	10+ years	
	Lavatory	1st flr inside Pre-K 106	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st flr inside Pre-K 106	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st flr inside Pre-K 106	110	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st flr inside Pre-K 106	72	SF	7	10+ years	
	Water Closet	1st flr inside Pre-K 106	2	EA	7	10+ years	
	Accessories	1st flr inside custodian's office	29	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st flr inside custodian's office	29	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside custodian's office	29	EA	7		Not accessible, parson with kove is
			Į	EA	'	10+ years	Not accessible, person with keys is not here
	Floor - Concrete	1st flr inside custodian's office	29	SF	7	10+ years	
	Lavatory	1st flr inside custodian's office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st flr inside custodian's office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st flr inside custodian's office	98	SF	7	10+ years	
	Water Closet	1st flr inside custodian's office	1	EA	7	10+ years	
			29	SF	7	6-10 years	
	ACCESSOFIES	ist in inside endineers onice	/9	SE			
	Accessories Ceiling - Plaster/Drywall	1st flr inside engineer's office 1st flr inside engineer's office	29 29	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Floor - Tile	1st flr inside engineer's office	29	SF	6	2-5 years	
	Lavatory	1st flr inside engineer's office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st flr inside engineer's office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st flr inside engineer's office	98	SF	7	10+ years	
	Water Closet	1st flr inside engineer's office	1	EA	7	10+ years	
	Accessories	1st flr inside kitchen	46	SF	7	6-10 years	
	Ceiling - Lay-in	1st flr inside kitchen	46	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside kitchen	1	EA	7	10+ years	
	Floor - Tile	1st flr inside kitchen	46	SF	6	10+ years	
	Lavatory	1st flr inside kitchen	1	EA	7	10+ years	
	Lighting - Lay-in	1st flr inside kitchen	1	EA	7	6-10 years	
	Student Lockers - Two Tiers	1st flr inside kitchen	8	EA	6	10+ years	
	Walls - Plaster/Drywall	1st flr inside kitchen	92	SF	7	10+ years	
	Water Closet	1st flr inside kitchen	1	EA	7	10+ years	
	Accessories	In Principal's Office	26	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Principal's Office	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Principal's Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Principal's Office	26	SF	6	10+ years	
	Lavatory	In Principal's Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Principal's Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	In Principal's Office	89	SF	7	10+ years	
	Water Closet	In Principal's Office	1	EA	7	10+ years	
	Accessories	Men's Room outside the Auditorium	68	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Men's Room outside the Auditorium	68	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Men's Room outside the Auditorium	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Men's Room outside the Auditorium	68	SF	4	0-1 year	Cracked throughout.
	Floor Drain	Men's Room outside the Auditorium	1	EA	7	10+ years	5
	Lavatory	Men's Room outside the Auditorium	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Men's Room outside the Auditorium	1	EA	7	6-10 years	
	Partitions	Men's Room outside the Auditorium	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Men's Room outside the Auditorium	196	SF	7	10+ years	
	Water Closet	Men's Room outside the Auditorium	1	EA	7	10+ years	
	Accessories	Room 102	330	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 102	330	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 102	330	SF	6	10+ years	
	Floor Drain	Room 102	1	ĒA	7	10+ years	
	Lavatory	Room 102	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Room 102	3	EA	7	6-10 years	
	Partitions	Room 102	2	EA	7	10+ years	
	Urinals	Room 102	6	EA	7	10+ years	
	Walls - Metal Panel	Room 102	255	SF	7	10+ years	
	Walls - Structural Glazed Tile	Room 102	255	SF	7	10+ years	
	Water Closet	Room 102	200	EA	7	10+ years	
	Accessories	Room 105B, in Faculty Lounge	55	SF	7	6-10 years	



Catego	ory : Room		Building : Main				
Ŭ	·			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Room 105B, in Faculty Lounge	55	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 105B, in Faculty Lounge	1	EA	7	10+ years	
	Floor - Tile	Room 105B, in Faculty Lounge	55	SF	7	10+ years	
	Lavatory	Room 105B, in Faculty Lounge	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Room 105B, in Faculty Lounge	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 105B, in Faculty Lounge	99	SF	7	10+ years	
	Water Closet	Room 105B, in Faculty Lounge	1	EA	7	10+ years	
	Accessories	Room 110	310	SF	7	6-10 years	
	Benches	Room 110	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	Room 110	280	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Room 110	30	SF	4	0-1 year	Water damage
	Floor - Tile Ceramic/ Porcelain	Room 110	310	SF	7	10+ years	C C
	Floor Drain	Room 110	1	EA	7	10+ years	
	Lavatory	Room 110	4	EA	7	10+ years	
	Lighting - Pendent/Surface	Room 110	3	EA	7	6-10 years	
	Partitions	Room 110	4	EA	7	10+ years	
	Student Lockers - Two Tiers	Room 110	30	EA	7	10+ years	
	Walls - Masonry	Room 110	250	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 110	235	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 110	15	SF	5	1-2 years	Water damage
	Walls - Tile Ceramic/ Porcelain	Room 110	100	SF	7	10+ years	5
	Water Closet	Room 110	4	EA	6	10+ years	
	Accessories	Room 202	330	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 202	330	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 202	310	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 202	20	SF	4	0-1 year	Damaged/crack tile
	Floor Drain	Room 202	1	EA	7	10+ years	0
	Lavatory	Room 202	1	EA	7	10+ years	Repaired
	Lavatory	Room 202	1	EA	7	10+ years	•
	Lighting - Pendent/Surface	Room 202	3	EA	7	6-10 years	
	Partitions	Room 202	2	EA	7	10+ years	
	Urinals	Room 202	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 202	255	SF	6	10+ years	
	Walls - Structural Glazed Tile	Room 202	255	SF	7	10+ years	
	Water Closet	Room 202	2	ĒA	7	10+ years	
	Accessories	Room 212	310	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 212	310	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 212	310	SF	7	10+ years	
	Floor Drain	Room 212	1	ĒA	7	10+ years	
	Lavatory	Room 212	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Room 212	3	EA	7	6-10 years	
	Partitions	Room 212	8	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 212	250	SF	7	10+ years	
	Walls - Structural Glazed Tile	Room 212	250	SF	7	10+ years	
			200	0.		is. youro	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	Room 212	8	EA	7	10+ years	
	Accessories	Room 214	39	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 214	39	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 214	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 214	39	SF	7	10+ years	
	Lavatory	Room 214	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Room 214	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 214	70	SF	6	10+ years	
	Walls - Plaster/Drywall	Room 214	20	SF	5	0-1 year	Water damage
	Water Closet	Room 214	1	EA	7	6-10 years	
	Accessories	Room 302	330	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 302	330	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 302	315	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 302	15	SF	4	0-1 year	Cracked tiles
	Floor Drain	Room 302	1	EA	7	10+ years	
	Lavatory	Room 302	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Room 302	3	EA	7	6-10 years	
	Partitions	Room 302	2	EA	7	10+ years	
	Urinals	Room 302	6	EA	7	10+ years	
	Walls - Metal Panel	Room 302	255	SF	6	10+ years	
	Walls - Structural Glazed Tile	Room 302	255	SF	7	10+ years	
	Water Closet	Room 302	2	EA	7	10+ years	
	Accessories	Room 310	310	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 310	310	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 310	310	SF	7	10+ years	
	Floor Drain	Room 310	1	EA	7	10+ years	
	Lavatory	Room 310	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Room 310	3	EA	7	6-10 years	
	Partitions	Room 310	7	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 310	250	SF	7	10+ years	
	Walls - Structural Glazed Tile	Room 310	250	SF	7	10+ years	
	Water Closet	Room 310	7	EA	7	10+ years	
	Accessories	Room 314A, Faculty	39	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 314A, Faculty	39	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 314A, Faculty	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Room 314A, Faculty	39	SF	7	10+ years	
	Lavatory	Room 314A, Faculty	1	ĒA	7	10+ years	
	Lighting - Pendent/Surface	Room 314A, Faculty	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Room 314A, Faculty	97	SF	6	2-5 years	
	Walls - Plaster/Drywall	Room 314A, Faculty	3	SF	5	0-1 year	Damaged.
	Water Closet	Room 314A, Faculty	1	EA	7	10+ years	
	Accessories	Women's Room outside the	124	SF	7	6-10 years	
		Auditorium		•.	•	5.0,000	
	Ceiling - Plaster/Drywall	Women's Room outside the	124	SF	7	10+ years	



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Auditorium Doors - Wood Doors inclu hw Women's Room outside the ΕA 7 1 10+ years Auditorium Floor - Tile Ceramic/ Porcelain Women's Room outside the SF 114 6 10+ years Auditorium Floor - Tile Ceramic/ Porcelain Women's Room outside the SF 10 4 0-1 year Cracks Auditorium Floor Drain Women's Room outside the 1 ΕA 7 10+ years Auditorium ΕA Women's Room outside the 1 7 Lavatory 10+ years Auditorium Lighting - Pendent/Surface Women's Room outside the 1 ΕA 7 6-10 years Auditorium Partitions Women's Room outside the 1 ΕA 7 10+ years Auditorium Walls - Plaster/Drywall Women's Room outside the SF 7 208 10+ years Auditorium Walls - Plaster/Drywall Women's Room outside the 10 SF 5 0-1 year Water damage Auditorium Water Closet Women's Room outside the 1 ΕA 6 10+ years Auditorium

Category : Classroom

Calego	ny . Classi 0011		Building . Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	om #104 (Pre School)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	10	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	720	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years		
	Marker Board	1st Floor	14	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,181	SF	7	10+ years		
	Work Sink	1st Floor	1	EA	7	6-10 years		
Classroo	om #106 (Pre School)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	14	LF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	763	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Wood	1st Floor	763	SF	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
						-		

Building : Main



8101 S	S LaSalle	STREET,	Chicago,	IL 60620

Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,281	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #201 (Kindergarten)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	10+ years	Light repaired
	Lighting - Pendent/Surface	2nd Floor	11	EA	7	6-10 years	5
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	906	SF	7	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	7	10+ years	
	Chalk Board	2nd Floor	44	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	906	SF	7	10+ years	
lassroo	om #204 (Regular Classroom)						
31233100	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	710	SF	6	10+ years	
	Floor - Wood	2nd Floor	15	SF	4	0-1 year	Separating.
	Lighting - Pendent/Surface	2nd Floor	13	EA	7	6-10 years	Separating.
	Walls - Plaster/Drywall	2nd Floor	1,183	SF	7	10+ years	
			1,100	0.		i e i yeare	
Classroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
				SF	7		



Catego	ry : Classroom		В	Building : Main			
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	865	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	865	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	140	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,741	SF	7	10+ years	
Classroo	m #207 (Other Instructional Use)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	10+ years	Lights Repaired
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	906	SF	7	10+ years	
Classroc	om #208 (Regular Classroom)						
0.000.00	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	10+ years	Lights Repaired
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	10+ years	Repaired cover
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,183	SF	7	10+ years	
laceroo	om #211 (Computer Lab)						
21022100	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor 2nd Floor	2 8	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	o 1,138	SF	7		
	Doors - Side-lite			SF		10+ years	
		2nd Floor	12		7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Epoxy/ Painted	2nd Floor	1,130	SF	7	10+ years	Densized
	Floor - Epoxy/ Painted	2nd Floor	8	SF	7	6-10 years	Repaired
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	10+ years	Repaired
	Lighting - Pendent/Surface	2nd Floor	11	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	



Floor - Wood

Lighting - Pendent/Surface

Student Lockers - Two Tiers

Wood damage

Repaired

8101 S LaSalle STREET, Ch						101 S LaSalle STREET, Chicago, IL 6062				
Catego	ory : Classroom		В	Building : Main						
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Plaster/Drywall	2nd Floor	1,826	SF	7	10+ years				
	Wireless System	2nd Floor	1	EA	7	6-10 years				
Classro	om #216 (Kindergarten)									
	AC Units	2nd Floor	1	EA	7	6-10 years				
	Casework	2nd Floor	36	LF	4	0-1 year	Rotten wood inside casework.			
	Ceiling - Plaster/Drywall	2nd Floor	928	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years				
	Floor - Epoxy/ Painted	2nd Floor	918	SF	7	10+ years				
	Floor - Epoxy/ Painted	2nd Floor	10	SF	4	0-1 year	Cracking floor, dark marks			
	Lighting - Pendent/Surface	2nd Floor	3	EA	7	10+ years	Lights repaired			
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years				
	Walls - Plaster/Drywall	2nd Floor	1,376	SF	7	10+ years				
Classro	om #301 (Regular Classroom)									
	AC Units	3rd Floor	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	3rd Floor	725	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years				
	Floor - Wood	3rd Floor	725	SF	7	10+ years				
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years				
	Storage/ Closet	3rd Floor	6	SF	7	10+ years				
	Walls - Plaster/Drywall	3rd Floor	906	SF	7	10+ years				
Classro	om #303 (Music Room)									
	AC Units	3rd Floor	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	3rd Floor	725	SF	7	10+ years				
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years				
	Floor - Wood	3rd Floor	720	SF	7	10+ years				
			-	~-		<u> </u>	147 1 1			

5

12

32

SF

ΕA

ΕA

4

7

7

0-1 year

6-10 years

10+ years

10+ years

6-10 years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years

6-10 years

Walls - Plaster/Drywall	3rd Floor	906	SF	7
Classroom #304 (Regular Classroom)				
AC Units	3rd Floor	1	EA	7
Casework	3rd Floor	12	LF	6
Ceiling - Plaster/Drywall	3rd Floor	725	SF	7
Chalk Board	3rd Floor	10	LF	4
Doors - Wood Doors inclu hw	3rd Floor	2	EA	7
Floor - Tile	3rd Floor	725	SF	7
Lighting - Pendent/Surface	3rd Floor	3	EA	7
Lighting - Pendent/Surface	3rd Floor	9	EA	7

3rd Floor

3rd Floor

3rd Floor



Catego	ory : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,228	SF	7	10+ years	
Classro	om #305 (Music Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	725	SF	7	10+ years	
	Chalk Board	3rd Floor	26	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒA	7	10+ years	
	Floor - Tile	3rd Floor	715	SF	7	10+ years	
	Floor - Tile	3rd Floor	10	SF	4	0-1 year	Cracked tile
	Lighting - Pendent/Surface	3rd Floor	11	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	906	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
	WOR SIIK		I	LA	1	10+ years	
Classro	om #306 (Science Lab Level 1)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	865	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
	Floor - Wood	3rd Floor	865	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	10+ years	Lights Repaired
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Science Lab Elements	3rd Floor	865	SF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	140	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,804	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classro	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	725	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood Doors Incld IIW	3rd Floor	725	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	10+ years	Repaired
	Lighting - Pendent/Surface	3rd Floor	4 8	EA	7	6-10 years	Перанец
	Storage/ Closet	3rd Floor	о 6	SF	7	-	
	Walls - Plaster/Drywall		906	SF	7	10+ years	
	vvans - Plaster/Drywall	3rd Floor	906	55	1	10+ years	
Classro	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	22	LF	7	10+ years	
						-	



Catego	ry : Classroom	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor	725	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	725	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	11	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Science Lab Elements	3rd Floor	725	SF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,206	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	

Category : Interior

Catego	ry : Interior						
_						Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	3,363	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	6	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	3	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor	1	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	673	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,690	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	19	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	119	EA	6	10+ years	
	Student Lockers - One Tier	1st Floor	31	EA	4	0-1 year	Damaged lockers
	Student Lockers - Two Tiers	1st Floor	12	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,757	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,757	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,363	SF	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	3	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	2nd Floor	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	673	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,665	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	25	SF	4	0-1 year	Broken/damaged tile
	Lighting - Pendent/Surface	2nd Floor	19	EA	7	6-10 years	0
	Student Lockers - One Tier	2nd Floor	150	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	3,757	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	3,757	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2,206	SF	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	3rd Floor	439	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,762	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2	SF	4	0-1 year	Chipped/cracked tile
	Lighting - Pendent/Surface	3rd Floor	12	ĒA	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	88	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,589	SF	7	10+ years	
			=,000	••	-	,	



, ,	
8101 S LaSalle STREET, Chicago,	IL 60620

Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	3rd Floor	2,589	SF	7	10+ years	
Safety							
	Camera Viewing Station	Entire Building	1	EA	4	1-2 years	No viewing station, has been this w
							for upwards of 10 years
	Security Cameras	Entire Building	2	EA	4	0-1 year	One camera at front door, no acce
							to footage inside the school. Other
							cameras do not work
Stairs							
	Ceiling - Plaster/Drywall	North	699	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North	5	SF	4	0-1 year	Damaged ceiling
	Floor - Terrazzo	North	150	SF	7	10+ years	2 a
	Floor - Terrazzo	North	10	SF	4	0-1 year	Crack terrazzo flooring
	Floor - Tile/Sheet	North	420	SF	7	10+ years	eraelt terrazze heering
	Handrails	North	128	LF	7	10+ years	
	Lighting - Lay-in	North	2	EA	7	10+ years	
	Lighting - Pendent/Surface	North	4	EA	6	6-10 years	
	Stairs - Terrazzo	North	160	LF	7	10+ years	
	Walls - Plaster/Drywall	North	580	SF	6	10+ years	
	Walls - Structural Glazed Tile	North	572	SF	6	10+ years	
	Walls - Structural Glazed Tile	North	8	SF	5	0-1 year	Cracking and broken tiles
	Ceiling - Plaster/Drywall	South	704	SF	7	10+ years	Cracking and broken tiles
	Floor - Terrazzo	South	150	SF	7	10+ years	
	Floor - Terrazzo	South	10	SF	4	0-1 year	Cracking
	Floor - Tile/Sheet	South	420	SF	7	10+ years	Cracking
	Handrails	South	128	LF	7	10+ years	
	Lighting - Lay-in	South	2	EA	7	6-10 years	
	Lighting - Pendent/Surface		4	EA	7		
	Stairs - Terrazzo	South	-	LF	7	6-10 years	
	Walls - Plaster/Drywall	South	160 580	SF	7	10+ years	
	Walls - Flaster/Drywall Walls - Structural Glazed Tile	South	580	SF		10+ years	
		South		SF	7	10+ years	
	Ceiling - Plaster/Drywall	South East	472	SF	7	10+ years	
	Floor - Terrazzo	South East	240	SF	7	10+ years	
	Floor - Tile/Sheet	South East	240	LF	7	10+ years	
	Handrails	South East	64		7	10+ years	
	Lighting - Pendent/Surface	South East	3	EA	7	6-10 years	
	Stairs - Terrazzo	South East	130	LF	7	10+ years	
	Walls - Plaster/Drywall	South East	445	SF	7	10+ years	
	Walls - Structural Glazed Tile	South East	445	SF	7	10+ years	
ertical (Conveyance						
	Elevator - Elevator- Roped Holeless	1st Floor	1	EA	7	10+ years	



	uilding : Main
Group Item - Type Location Quantity	Recommend UOM Rank Replacement Comments



Catego	ry : Site		В	uilding	: Site		
	Recommend up Item - Type Location Quantity UOM Rank Replacement C						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	6	10+ years	
encing							
	Fencing - New Standard Ornamental	Entire Site	20	LF	7	10+ years	demolished old ornamental, replace with new ornamental fence
	Fencing - Old Standard Ornamental	Entire Site	1,664	LF	6	6-10 years	
andsca	De						
	Benches	Entire Site	5	EA	7	10+ years	
	Landscape - Grass	Entire Site	71,969	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	551	SF	6	6-10 years	
	Lighting - Lighting	Entire Site	2	EA	6	6-10 years	
	Parkway trees	Entire Site	55	EA	6	10+ years	
	Parkway trees	Entire Site	1	EA	4	0-1 year	Missing tree
	Planting Beds/ Area	Entire Site	992	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	7,688	SF	7	10+ years	New
	Play Area - Hardscape- Asphalt	Entire Site	13,728	SF	4	0-1 year	Disintegrating surface much alligatorIng. Field verified dimension
	Trash Receptacles	Entire Site	2	EA	6	10+ years	5 5
Parking I	ot						
Ū.	Concrete Curbs	Parking Lot- East	724	LF	6	6-10 years	
	Interior Plantings	Parking Lot- East	25	LF	6	10+ years	New trees
	Interior Plantings	Parking Lot- East	115	LF	6	6-10 years	
	Lighting - Pole Mounted	Parking Lot- East	4	EA	6	10+ years	
	Surface - Asphalt	Parking Lot- East	5,700	SF	7	10+ years	New 2023
	Surface - Asphalt	Parking Lot- East	14,092	SF	6	6-10 years	Repaired
	Surface - Asphalt	Parking Lot- East	1,380	SF	6	6-10 years	Repaired or new
	Surface - Asphalt	Parking Lot- East	300	SF	4	1-2 years	Alligatored surface, potholes
	Surface - Concrete	Parking Lot- East	2,525	SF	6	10+ years	5
	Trash Enclosure - Chain Links	Parking Lot- East	540	SF	7	10+ years	
	Vehicular Screening	Parking Lot- East	374	LF	7	6-10 years	
Playgrou	nd						
	Equipment - School Age 5-12	South	2		7	10+ years	
	Surface - Poured Surface	South	1,520	SF	7	10+ years	
	Surface - Poured Surface	South	2,600	SF	7	10+ years	
Sidewalk	6						



Catego	ry : Site	В	uilding	: Site			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Internal Walks	West	333	LF	6	10+ years	
	Sidewalks - Internal Walks	West	80	LF	4	0-1 year	Broken, upheaved and settled sidewalk
	Sidewalks - Perimeter Sidewalks	West	16,069	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	West	800	SF	4	0-1 year	Broken, pieces/ sections missing, upheaved, crushed
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	5	0-1 year	Broken post base, pole is corroding
	Monument - Sign	Entire Site	2	EA	7	10+ years	

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	·	·							
Computer Lab	Computer Lab	2nd Floor	211	211	1,138	200	80	N	N
Kindergarten	Kindergarten	2nd Floor	216	210	928	240	60	N	N
Kindergarten	Regular Classroom	2nd Floor	201	201	725	125	40	N	Y
Music Room	Regular Classroom	3rd Floor	303	303	725	115	40	N	Y
Music Room	Regular Classroom	3rd Floor	305	305	725	125	40	N	N
Other Instructional Use	Regular Classroom	2nd Floor	207	207	725	125	40	N	N
Pre School	Regular Classroom	1st Floor	104	104	720	118	50	N	Y
Pre School	Regular Classroom	1st Floor	106	108	763	80	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	725	125	40	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	725	125	40	N	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	725	125	40	N	Y
Regular Classroom	Regular Classroom	2nd Floor	206	206	865	240	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	725	125	40	N	Y
Regular Classroom	Regular Classroom	3rd Floor	301	301	725	125	40	N	Y
Regular Classroom	Regular Classroom	3rd Floor	304	304	725	125	40	N	Y
Regular Classroom	Regular Classroom	3rd Floor	307	307	725	125	40	N	Y
Regular Classroom	Science Lab Level 1	3rd Floor	308	308	725	125	40	N	Y
Science Lab Level 1	Science Lab Level 1	3rd Floor	306	306	865	125	40	N	Y