

## **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <u>http://www.cps.edu/facilityassessment</u>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1928	3	213,820
Campus Total			213,820

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Wood Door	#0 N	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#0 N	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#0 N	152	LF	6	10+ years	
	Exterior Stairs - Stone	#0 N	19	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#1 N	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 N	1	EA	6	10+ years	
	Exterior Stairs - Stone	#1 N	160	LF	7	10+ years	Fixed.
	Exterior Doors - Exterior Steel Door	#10 E (Door B)	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#10 E (Door B)	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#11 N (Door #D)	2	EA	6	10+ years	
	Exterior Stairs - Wood	#11 N (Door #D)	54	LF	7	10+ years	
	Stair Handrail - Wood_Stair Handrail	#11 N (Door #D)	8	LF	7	10+ years	
	Entrance Control - Audio and Video	#2 N	1	EA	6	6-10 years	
	Exterior Doors - Exterior Wood Door	#2 N	2	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 N	224	LF	5	2-5 years	
	Power Door Operator and Controls	#2 N	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#2 N	160	LF	4	1-2 years	Rusted at the bottom of rails
	Ramps - Concrete	#2 N	195	LF	5	1-2 years	Exposed rebar
	Stair Handrail - Steel_Stair Handrail	#2 N	24	LF	6	10+ years	·
	Exterior Doors - Exterior Wood Door	#3_Exit N	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3_Exit N	1	EA	6	10+ years	
	Exterior Stairs - Stone	#3_Exit N	172	LF	7	10+ years	Fixed
	Entrance Control - Audio and Video	#4 S	1	EA	7	6-10 years	
	Exterior Doors - Exterior Wood Door	#4 S	2	EA	6	10+ years	



atego	ry : Exterior		В	uilding	: Main		
						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Exterior Doors - Transom Lite	#4 S	1	EA	6	10+ years	
	Exterior Stairs - Stone	#4 S	158	LF	6	6-10 years	Fixed.
	Exterior Doors - Exterior Steel Door	#5 S	2	EA	6	6-10 years	Changed to match current
						<b>,</b>	observations
	Exterior Doors - Transom Lite	#5 S	4	EA	6	10+ years	
	Power Door Operator and Controls	#5 S	1	EA	7	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	#5 S	140	LF	6	10+ years	
	Ramps - Concrete	#5 S	70	LF	6	10+ years	
	Entrance Control - Audio and Video	#6 S	1	EA	6	6-10 years	
	Exterior Doors - Exterior Wood Door	#6 S	4	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 S	14	LF	5	10+ years	
	Exterior Stairs - Stone	#6 S	67	LF	6	10+ years	Fixed
	Exterior Doors - Exterior Steel Door	#7 S	1	EA	6	6-10 years	Changed to match current
							observations. The other door is damaged
	Exterior Doors - Exterior Steel Door	#7 S	1	EA	4	1.2 vooro	Corroded
	Exterior Doors - Transom Lite	#7 S	4	EA	4	1-2 years	Conoded
		#7 S #7 S	-		6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail		140	LF	6	10+ years	
	Ramps - Concrete	#7 S	70	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#7.1 S	2	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	#8 S	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8 S	1	EA	6	10+ years	<u> </u>
	Exterior Stairs - Stone	#8 S	152	LF	7	10+ years	Fixed
	Exterior Doors - Exterior Steel Door	#9 S	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#9 S	140	LF	6	10+ years	
	Exterior Stairs - Stone	#9 S	7	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#9 S	28	LF	6	10+ years	
oundati	on						
	Foundation - Concrete	Entire Building	1,630	LF	6	10+ years	
	Foundation - Concrete	Entire Building	250	LF	6	0-1 year	Seepage is boiler room basement water leaking through the wall
	Superstructure - Concrete	Entire Building	213,820	SF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	20,014	SF	6	10+ years	
		0	,			,	
ghting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	13	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	6-10 years	
	Exterior Lighting - Wair Mounted		5	EA	0	0-10 years	
oof Sys		<b>.</b>					<b>_</b>
	Access Ladder - Metal	Roof #1	1	EA	7	6-10 years	Replaced with one aluminum lade
	Access Ladder - Metal	Roof #1	1	EA	7	10+ years	
	Access Ladder - Metal	Roof #1	4	EA	3	0-1 year	Unused because of the broken ro



Manley Career Academy High School 2935 W Polk STREET, Chicago, IL 60612

Catego	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Oroup	item - Type	Location	Quantity		Italik	Replacement	hatches.
	Coping - Stone	Roof #1	1,765	LF	6	10+ years	hatohoo.
	Downspouts - Exterior Downspouts	Roof #1	35	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof #1	972	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof #1	134	LF	5	6-10 years	
	Parapet - Parapet < 16" Height	Roof #1	50	LF	5	6-10 years	
	Parapet - Parapet > 30"	Roof #1	1,521	LF	5	6-10 years	
	Parapet - Parapet > 30"	Roof #1	60	LF	4	0-1 year	Cracking, missing pieces, falling off
	Roof - Modified Bitumen	Roof #1	65,036	SF	4	0-1 year	Soft spots, bubbling, cracking
			,	•		• • <b>)</b> • •	throughout Water leaking throughout
	Roof Hatch - Metal	Roof #1	1	EA	4	0-1 year	Small hatch
	Roof Hatch - Metal	Roof #1	4	EA	3	0-1 year	Broken, screwed shut
	Roof Structure - Concrete	Roof #1	65,036	SF	7	10+ years	,
	Access Ladder - Metal	Roof #2	1	EA	7	10+ years	
	Access Ladder - Wood	Roof #2	1	EA	5	2-5 years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof #2	55	LF	6	10+ years	
	Liner				÷	, , , , , , , , , , , , , , , , , , ,	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof #2	30	LF	5	6-10 years	
	Liner				÷	- · · · · · · · ·	
	Chimney - Metal Flue	Roof #2	10	LF	6	10+ years	
	Coping - Stone	Roof #2	395	LF	6	10+ years	Changed to match current
					÷	, , , , , , , , , , , , , , , , , , ,	observations
	Downspouts - Interior Downspouts	Roof #2	205	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	Roof #2	160	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof #2	235	LF	5	6-10 years	
	Roof - Asphalt Shingle	Roof #2	1,000	SF	6	10+ years	
	Roof - Modified Bitumen	Roof #2	11,357	SF	4	0-1 year	Soft spots, bubbling, cracking
			,	-		, <b>,</b> , , , , , , , , , , , , , , , , ,	throughout\nWater leaking throughou
	Roof Hatch - Metal	Roof #2	1	EA	4	1-2 years	Broken
	Roof Structure - Steel with Clay Tile Arch	Roof #2	12,357	SF	6	10+ years	
				•	-	, every eche	
Walls							
	Cheek-Wall - Concrete	Entire Building	340	SF	5	2-5 years	
	Cornice - Terra Cotta	Entire Building	120	LF	5	10+ years	
	Exterior Walls - Brick	Entire Building	65,898	SF	5	10+ years	
	Exterior Walls - Brick	Entire Building	940	SF	4	0-1 year	Cracking, open joints
	Exterior Walls - Terra Cotta	Entire Building	3,972	SF	5	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	4	SF	4	0-1 year	Cracking
Windows							
	Guard - Guards wire guard	Entire Building	10,476	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	125	SF	5	6-10 years	
	Lintels - Steel	Entire Building	565	LF	5	6-10 years	- · ·
	Lintels - Steel	Entire Building	1,136	LF	4	0-1 year	Corroded



							; ee.ge; i;
Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lintels - Terra Cotta	Entire Building	1,119	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	10	LF	5	6-10 years	
	Lintels - Terra Cotta	Entire Building	4	LF	4	0-1 year	Cracking
	Skylite - Lexan	Entire Building	224	SF	6	10+ years	C C
	Windows - Casement Aluminum Double-	Entire Building	2,442	SF	6	6-10 years	
	pane	-				-	
	Windows - Casement Steel	Entire Building	18	SF	6	6-10 years	
	Windows - Decorative	Entire Building	48	SF	6	10+ years	
	Windows - Louver	Entire Building	48	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,249	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	23,728	SF	3	0-1 year	Rusted windows. Bad balancers
	Windows - Sash Lexan	Entire Building	12	SF	6	6-10 years	
		0				•	

**Building : Main** 

## **Category : Electrical**

0	- 		Oursetitus		Devile	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	2	EA	6	6-10 years	
	Security System - CCTV	Entire Building	213,820	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	213,820	SF	6	6-10 years	
	Exit Signs - Auditoium	Entire Building	10	EA	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	28	EA	7	6-10 years	
	Exit Signs - Gym	Entire Building	6	EA	7	6-10 years	
	Exit Signs - Lunchroom	Entire Building	3	EA	7	6-10 years	
	Exit Signs - Pool	Entire Building	4	EA	7	6-10 years	
	Emergency A/C Power - Auditoium and	Entire Building	4,878	SF	6	6-10 years	
	Aisle Lighting Emergency A/C Power - Corridors and Stairs	Entire Building	34,145	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	11,948	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	6,083	SF	6	6-10 years	
	Emergency A/C Power - Pool	Entire Building	3,589	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	3,898	SF	7	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	2	SF	7	10+ years	
	Emergency Battery Packs - Pool	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	7	10+ years	
	Emergency Battery Packs - Students Toilets	Entire Building	3	EA	6	6-10 years	
	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW	Site - East	1	EA	4	1-2 years	
Main Se	rvice						
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	Independent Electrical Service for	Electrical Room	1	EA	7	6-10 years	



ALLA :	Schools						2935 W Polk STREET, Chicago, IL 60612
Catego	ry : Electrical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	emergency power						
	PA System	Entire Building	213,820	SF	5	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	5	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	5	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	3	1-2 years	Older unit.
	Lighting and Power Panels - Above 100 A	Entire Building	15	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	2	EA	7	10+ years	
	amp	-				-	
	Main Distribution Panels - Less than 400	Entire Building	2	EA	6	6-10 years	
	amp	-				-	
Catego	ry : Fire Protection		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Panel	Electrical Room	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Electrical Room	213,820	SF	6	6-10 years	
	Fire Alarm_System	Electrical Room	213,820	SF	6	6-10 years	
0-1	w. Mashaniaal						
Catego	ry : Mechanical		В	uilding	: Main	Deserves	
Crown	Item - Type	Location	Quantity	LIOM	Donk	Recommend	Commente
Group		Location	Quantity	UOM	Rank	Replacement	Comments
Air Conc		<b>0</b>			-		
	Condensing Unit- Roof Mounted - Less	Site West	1	EA	6	6-10 years	
	than 5 tons	0% N/ /				0.40	
	Condensing Unit- Roof Mounted - Less	Site West	1	EA	6	6-10 years	
	than 5 tons	0% N/ /		<b>F</b> A	0	0.40	
	Condensing Unit- Roof Mounted - Less	Site West	1	EA	6	6-10 years	
	than 5 tons						
A · 1 1							
Air Hand	Iling Systems		4		-	0.5	
	Air Handling Unit- Built Up-Multi Zone-	Mech Room AHU-1	1	EA	5	2-5 years	AHU-1
	Steam Coils - 8001 - 15000 cfm			<b>F</b> ^	~	0.5	
	Air Intake	Mech Room AHU-1	1	EA	5	2-5 years	
	Auxiliaries - 8001 - 15000 cfm	Mech Room AHU-1	1	EA	5	2-5 years	
	Return Duct Work - Indoor- Vertical Shaft	Mech Room AHU-1	100	LF	6	10+ years	
	and Ducts	Mach Deam AllII 4	^	Γ^	~	0.5	
	Zone Dampers	Mech Room AHU-1	6	EA	5	2-5 years	
	Air Handling Unit- Built Up- Single Zone-	Mech Room AHU-2	1	EA	6	2-5 years	AHU-2



Category : Mechanical **Building : Main** Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Steam Coils - 15001 - 25000 cfm ΕA Air Intake Mech Room AHU-2 5 2-5 vears 1 Auxiliaries - 15001 - 25000 cfm Mech Room AHU-2 1 EΑ 5 2-5 years LF 6 Return Duct Work - Indoor- Vertical Shaft Mech Room AHU-2 100 6-10 years and Ducts Air Handling Unit- Built Up- Single Zone w/ Mech Room AHU-3 EΑ 5 6-10 years AHU-3 1 Air Tunnel- Steam Coils - 15001 - 25000 cfm Air Intake Mech Room AHU-3 1 ΕA 5 2-5 years Auxiliaries - 15001 - 25000 cfm Mech Room AHU-3 1 ΕA 5 2-5 vears Reheat Boxes - Reheat Boxes with Steam Mech Room AHU-3 8 FΑ 5 2-5 years Coil Return Duct Work - Indoor- Vertical Shaft Mech Room AHU-3 100 LF 7 10+ years and Ducts **Zone Dampers** Mech Room AHU-3 21 EΑ 5 2-5 years Air Handling Unit- Built Up- Single Zone w/ Mech Room AHU-4 ΕA 5 2-5 years AHU-4 1 Air Tunnel- Steam Coils - 25001 - 35000 cfm Air Intake Mech Room AHU-4 1 ΕA 6 6-10 vears Auxiliaries - 25001 - 35000 cfm Mech Room AHU-4 1 ΕA 5 6-10 years Same Reheat Boxes - Reheat Boxes with Steam Mech Room AHU-4 8 ΕA 5 2-5 years Coil Return Duct Work - Indoor- Vertical Shaft Mech Room AHU-4 100 LF 6 6-10 years and Ducts Zone Dampers Mech Room AHU-4 24 EΑ 5 2-5 years Air Handling Unit- Built Up-Multi Zone-Mech Room AHU-5 FΑ 5 AHU-5 1 2-5 years Steam Coils - 25001 - 35000 cfm Air Intake Mech Room AHU-5 1 ΕA 5 2-5 vears 5 Auxiliaries - 25001 - 35000 cfm Mech Room AHU-5 EA 2-5 years 1 100 1 F 6 6-10 years Return Duct Work - Indoor- Vertical Shaft Mech Room AHU-5 and Ducts Zone Dampers Mech Room AHU-5 24 ΕA 5 2-5 years Air Handling Unit- Built Up- Single Zone w/ FΑ 5 Mech Room AHU-6 1 2-5 years AHU-6 Air Tunnel- Steam Coils - 15001 - 25000 cfm FΑ 5 Air Intake Mech Room AHU-6 1 2-5 vears Auxiliaries - 15001 - 25000 cfm Mech Room AHU-6 EΑ 5 2-5 years 1 5 Reheat Boxes - Reheat Boxes with Steam Mech Room AHU-6 4 EΑ 2-5 years Coil Return Duct Work - Indoor- Vertical Shaft Mech Room AHU-6 100 1 F 6 2-5 years and Ducts Zone Dampers Mech Room AHU-6 12 ΕA 5 2-5 years Air Handling Unit- Built Up-Multi Zone-Mech Room AHU-7 EΑ 5 2-5 vears AHU-7 1 Steam Coils - 8001 - 15000 cfm FΑ Mech Room AHU-7 6 6-10 vears Air Intake 1 Auxiliaries - 8001 - 15000 cfm Mech Room AHU-7 EΑ 6 2-5 years 1 Return Duct Work - Indoor- Vertical Shaft Mech Room AHU-7 100 LF 6 2-5 years



<u> </u>	Schools						2935 W Polk STREET, Chicago, IL 60612
Catego	ry : Mechanical		B	uilding	: Main		
_			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	and Ducts	Mech Room AHU-7	10		F		
	Zone Dampers		12	EA EA	5	2-5 years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Mech Room AHU-8	1	EA	5	2-5 years	AHU-8
	Air Intake	Mech Room AHU-8	1	EA	5	2-5 years	
	Auxiliaries - 8001 - 15000 cfm	Mech Room AHU-8	1	EA	5	2-5 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mech Room AHU-8	100	LF	6	6-10 years	
	Zone Dampers	Mech Room AHU-8	14	EA	5	2-5 years	
Boiler Sv	vstems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - Greater than 300 HP	Boiler Room	2	EA	6	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	7	10+ years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	7	10+ years	
	Condensate Pump	Boiler Room	1	EA	5	2-5 years	
	Condensate Pump	Boiler Room	1	EA	5	2-5 years	
	Condensate Pump	Boiler Room	1	EA	5	2-5 years	
	Condensate Pump	Boiler Room	1	EA	5	2-5 years	
	Condensate Pump	Boiler Room	1	EA	5	2-5 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	2-5 years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	6	6-10 years	
	Steam- Low Pressure Boiler - Greater than 300 HP		I	EA	0	0-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Greater than 300 HP	Boiler Room	1	EA	6	6-10 years	
	Piping - Condensate Pipe- Steel	Boiler Room	2,000	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	2,000	LF	6	6-10 years	
	Steam Traps	Boiler Room	2,000	EA	7	6-10 years	
	Steam Traps	Boiler Room	130	EA	5	6-10 years	
Heating	Devices						
	Unit Heater - Steam	Boiler Room	2	EA	5	6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building	2	EA	5	2-5 years	
	Fin Tube - Steam	Entire Building	100	LF	5	0-1 year	Damaged cover.
	Fin Tube - Steam	Entire Building	200	LF	5	6-10 years	Danageu over.
	Radiators - Steam	Entire Building	10	EA	5	6-10 years	
			-				
	Radiators - Steam	Entire Building	47 12	EA EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	12	EA	6	6-10 years	



Catego	ory : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Tempera	ature Control						
•	Electric Thermostat	Entire Building	2	EA	6	6-10 years	
	Pneumatic System	Entire Building	213,820	SF	4	0-1 year	Per engineer no pneumatic system disconnected manually controlled.
	Thermostats - Pneumatic	Entire Building	74	EA	5	0-1 year	Does not work.
	Thermostats - Pneumatic	Entire Building	3	EA	4	0-1 year	Does not work.
/entilation	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	6	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	6-10 years	
	Roof Mounted Duct Work	Entire Building	40	LF	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Entire Building	2	EA	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	
Catego	ory : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat							
Hot Wat	er Gas Heater - 300001 - 600000 BTU/HR Hot Water Storage Tank_Gas - 501 - 1000 Gallons	Boiler Room Boiler Room	3 1	EA EA	7 7	10+ years 6-10 years	
	Gas Heater -300001-600000 BTU/HR Hot Water Storage Tank_Gas-501-1000						
	Gas Heater - 300001 - 600000 BTU/HR Hot Water Storage Tank_Gas - 501 - 1000 Gallons Domestic Piping-Hot Water Return Lines	Boiler Room Entire Building	213,828	EA SF	7		
	Gas Heater - 300001 - 600000 BTU/HR Hot Water Storage Tank_Gas - 501 - 1000 Gallons Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers	Boiler Room	1	EA	7	6-10 years 6-10 years 6-10 years	
	Gas Heater - 300001 - 600000 BTU/HR Hot Water Storage Tank_Gas - 501 - 1000 Gallons Domestic Piping-Hot Water Return Lines	Boiler Room Entire Building	213,828	EA SF	7	6-10 years	
	Gas Heater - 300001 - 600000 BTU/HR Hot Water Storage Tank_Gas - 501 - 1000 Gallons Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to	Boiler Room Entire Building Entire Building	1 213,828 213,828	EA SF SF	7 6 6	6-10 years 6-10 years 6-10 years	
	Gas Heater - 300001 - 600000 BTU/HR Hot Water Storage Tank_Gas - 501 - 1000 Gallons Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers)	Boiler Room Entire Building Entire Building Entire Building	1 213,828 213,828 213,828 213,828	EA SF SF SF	7 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	
	Gas Heater - 300001 - 600000 BTU/HR Hot Water Storage Tank_Gas - 501 - 1000 Gallons Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply	Boiler Room Entire Building Entire Building Entire Building Entire Building	1 213,828 213,828 213,828 213,828 213,828	EA SF SF SF SF	7 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	
	Gas Heater - 300001 - 600000 BTU/HR Hot Water Storage Tank_Gas - 501 - 1000 Gallons Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) Sanitary Piping	Boiler Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 213,828 213,828 213,828 213,828 213,828 213,828 213,828 213,828	EA SF SF SF SF SF SF SF	7 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	
Hot Wat	Gas Heater - 300001 - 600000 BTU/HR Hot Water Storage Tank_Gas - 501 - 1000 Gallons Domestic Piping-Hot Water Return Lines Domestic Piping-Hot Water Return Risers Domestic Piping-Hot Water from Risers to Fixtures Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers) Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Boiler Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	1 213,828 213,828 213,828 213,828 213,828 213,828 213,828	EA SF SF SF SF SF SF	7 6 6 6 6 6	6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	



N.	Schools						2935 W Polk STREET, Chicago, IL 606
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Pool Sys	stems						
,	Pool Drain Piping	Basement	100	LF	3	2-5 years	Per engineer pool system not operational
	Pool Filtration System including Pump	Basement	1	EA	3	2-5 years	Per engineer pool system not operational
	Pool Hot Water Heater - Gas Fired	Basement	1	EA	2	2-5 years	Per engineer pool system not operational
	Pool Supply and Return Piping	Basement	100	LF	3	2-5 years	Per engineer pool system not operational
umps							
	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	6	2-5 years	
	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	6	2-5 years	
	Pumps - Ejector-Simplex	Basement	1	EA	6	2-5 years	
	Pumps - Ejector-Simplex	Basement	1	EA	5	2-5 years	
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Basement	1	EA	5	2-5 years	
	Pumps - Sump-Simplex	Basement	1	EA	5	2-5 years	
atego	ry : Room		В	uilding	: Main		
	ltom Turne	Location	Quantity	UOM	Rank	Recommend	Commente
Group	Item - Type trative Suites/Offices	Location	Quantity		Rank	Replacement	Comments
umms	AC Unit	100 Principals NL	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	100 Principals NL	720	SF	6	10+ years	
	Doors - Transom Window	100 Principals NL	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	100 Principals NL	2	EA	6	6-10 years	
	Floor - Tile	100 Principals NL	720	SF	6	10+ years	
	Lighting - Pendent/Surface	100 Principals NL	16	EA	5	1-2 years	Refurbish fixture assembly
	Power Distribution	100 Principals NL	16	EA	6	6-10 years	· · · · · · · · · · · · · · · · · · ·
	Storage/ Closet	100 Principals NL	180	SF	7	10+ years	
	Walls - Plaster/Drywall	100 Principals NL	1,448	SF	6	10+ years	
	Walls - Plaster/Drywall	100 Principals NL	3	SF	5	1-2 years	Hole in wall
	AC Unit	102 counseling	2	EA	7	6-10 years	
		400 II Ŭ		~-	•	10	

Ceiling - Plaster/Drywall

Doors - Transom Window

Floor - Carpet

Work SInk

Power Distribution

Walls - Plaster/Drywall

Doors - Wood Doors inclu hw

Lighting - Pendent/Surface

1,121

1,121

1,444

9

1

24

20

1

SF

SF

ΕA

SF

ΕA

ΕA

SF

ΕA

6

6

6

4

7

7

6

7

10+ years

6-10 years

6-10 years

1-2 years

10+ years

10+ years

10+ years

10+ years

102 counseling

Torn and stained carpet



							2935 W Polk STREET, Chicago, IL 60612
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	103 Office	742	SF	6	10+ years	
	Doors - Transom Window	103 Office	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	103 Office	2	EA	6	6-10 years	
	Floor - Carpet	103 Office	742	SF	6	6-10 years	
	Lighting - Pendent/Surface	103 Office	10	EA	7	10+ years	
	Power Distribution	103 Office	10	EA	6	10+ years	
	Walls - Plaster/Drywall	103 Office	1,130	SF	6	10+ years	
	AC Unit	104-Main office	<sup></sup> 1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	104-Main office	650	SF	6	10+ years	
	Doors - Transom Window	104-Main office	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	104-Main office	1	EA	6	6-10 years	
	Floor - Carpet	104-Main office	650	SF	6	6-10 years	
	Lighting - Pendent/Surface	104-Main office	9	ĒA	7	6-10 years	
	Lighting - Pendent/Surface	104-Main office	1	EA	6	2-5 years	
	Power Distribution	104-Main office	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	104-Main office	1,101	SF	6	10+ years	
	AC Unit	104A-Main office Break Room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	104A-Main office Break Room	360	SF	7	10+ years	
	Doors - Transom Window	104A-Main office Break Room	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	104A-Main office Break Room	1	EA	6	6-10 years	
	Floor - Tile	104A-Main office Break Room	310	SF	7	6-10 years	
	Floor - Tile	104A-Main office Break Room	50	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	104A-Main office Break Room	4	EA	7	6-10 years	Damagea lies
	Power Distribution	104A-Main office Break Room	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	104A-Main office Break Room	819	SF	6	10+ years	
	AC Unit	106 conference	3	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	106 conference	854	SF	6	6-10 years	
	Doors - Transom Window	106 conference	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	106 conference	2	EA	6	6-10 years	
	Floor - Wood Doors inclu fiw	106 conference	2 854	SF	6	10+ years	
	Lighting - Pendent/Surface	106 conference	004 10	EA	7	10+ years	
	Power Distribution	106 conference	16	EA	7	10+ years	
	Walls - Plaster/Drywall		1,223	SF	6	-	
		106 conference				10+ years	Ciels not working
	Work SInk	106 conference	1	EA SF	4	1-2 years	Sink not working
	Ceiling - Plaster/Drywall	107	729	SF	6	10+ years	
	Doors - Transom Window	107	18		6	6-10 years	
	Doors - Wood Doors inclu hw	107	2	EA	6	6-10 years	
	Floor - Carpet	107	729	SF	5	2-5 years	
	Lighting - Pendent/Surface	107	9	EA	7	6-10 years	
	Lighting - Pendent/Surface	107	1	EA	6	2-5 years	
	Power Distribution	107	20	EA	7	10+ years	
	Walls - Plaster/Drywall	107	1,145	SF	6	10+ years	
	Ceiling - Plaster/Drywall	108 careers NL	729	SF	6	10+ years	
	Doors - Wood Doors inclu hw	108 careers NL	2	EA	6	6-10 years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	108 careers NL	729	SF	6	6-10 years	
	Lighting - Pendent/Surface	108 careers NL	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	108 careers NL	1,145	SF	6	10+ years	
	Ceiling - Plaster/Drywall	110 special education office	948	SF	6	10+ years	
	Ceiling - Plaster/Drywall	110 special education office	20	SF	4	1-2 years	Water damaged
	Doors - Transom Window	110 special education office	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	110 special education office	4	EA	6	6-10 years	
	Floor - Tile	110 special education office	938	SF	6	6-10 years	
	Floor - Tile	110 special education office	30	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	110 special education office	10	EA	7	10+ years	
	Walls - Metal Panel	110 special education office	364	SF	6	6-10 years	
	Walls - Plaster/Drywall	110 special education office	1,298	SF	7	10+ years	
	Walls - Plaster/Drywall	110 special education office	20	SF	4	1-2 years	Water damaged
	AC Unit	115 Copy ID room	2	EA	7	6-10 years	
	Ceiling - Lay-in	115 Copy ID room	739	SF	6	10+ years	
	Doors - Wood Doors inclu hw	115 Copy ID room	2	EA	6	6-10 years	
	Floor - Tile	115 Copy ID room	739	SF	7	10+ years	
	Lighting - Pendent/Surface	115 Copy ID room	8	EA	7	10+ years	
	Power Distribution	115 Copy ID room	6	EA	6	10+ years	
	Walls - Plaster/Drywall	115 Copy ID room	1,161	SF	6	10+ years	
	Walls - Plaster/Drywall	115 Copy ID room	3	SF	5	1-2 years	Hole in wall
	Ceiling - Lay-in	116 Reception	450	SF	7	10+ years	
	Doors - Wood Doors inclu hw	116 Reception	1	EA	7	10+ years	
	Floor - Carpet	116 Reception	450	SF	7	10+ years	
	Lighting - Lay-in	116 Reception	12	EA	7	6-10 years	
	Power Distribution	116 Reception	10	EA	7	10+ years	
	Walls - Plaster/Drywall	116 Reception	720	SF	7	10+ years	
	AC Unit	116A - Network	1	EA	7	6-10 years	
	Ceiling - Lay-in	116A - Network	100	SF	7	10+ years	
	Doors - Side-lite	116A - Network	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	116A - Network	1	EA	7	10+ years	
	Floor - Carpet	116A - Network	100	SF	7	6-10 years	
	Lighting - Lay-in	116A - Network	2	EA	7	10+ years	
	Power Distribution	116A - Network	8	EA	7	10+ years	
	Walls - Plaster/Drywall	116A - Network	286	SF	7	10+ years	
	AC Unit	116B - Network	1	EA	7	6-10 years	
	Ceiling - Lay-in	116B - Network	95	SF	7	10+ years	
	Doors - Side-lite	116B - Network	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	116B - Network	1	EA	7	10+ years	
	Floor - Carpet	116B - Network	95	SF	7	6-10 years	
	Lighting - Lay-in	116B - Network	2	EA	7	10+ years	
	Power Distribution	116B - Network	6	EA	7	10+ years	
	Walls - Plaster/Drywall	116B - Network	173	SF	7	10+ years	
	Ceiling - Lay-in	120 - Network	72	SF	7	6-10 years	



			_				2935 W Polk STREET, Chicago, IL 60612
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	120 - Network	1	EA	7	10+ years	
	Floor - Carpet	120 - Network	72	SF	7	6-10 years	
	Lighting - Lay-in	120 - Network	1	EA	7	6-10 years	
	Power Distribution	120 - Network	8	EA	7	10+ years	
	Walls - Plaster/Drywall	120 - Network	222	SF	7	6-10 years	
	AC Unit	120A - Network	1	EA	7	6-10 years	
	Ceiling - Lay-in	120A - Network	120	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	120A - Network	1	EA	7	10+ years	
	Floor - Carpet	120A - Network	120	SF	7	6-10 years	
	Lighting - Lay-in	120A - Network	2	EA	7	10+ years	
	Power Distribution	120A - Network	8	EA	7	10+ years	
	Walls - Plaster/Drywall	120A - Network	278	SF	7	10+ years	
	Ceiling - Lay-in	121A - Safe Passage Office	572	SF	6	6-10 years	
	Doors - Side-lite	121A - Safe Passage Office	48	SF	6	6-10 years	
	Doors - Transom Window	121A - Safe Passage Office	45	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	121A - Safe Passage Office	2	EA	6	6-10 years	
	Floor - Terrazzo	121A - Safe Passage Office	572	SF	6	10+ years	
	Lighting - Lay-in	121A - Safe Passage Office	4	EA	7	6-10 years	
	Power Distribution	121A - Safe Passage Office	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	121A - Safe Passage Office	1,115	SF	6	10+ years	
	AC Unit	122A - Network	· 1	EA	7	6-10 years	
	Ceiling - Lay-in	122A - Network	160	SF	7	6-10 years	
	Doors - Side-lite	122A - Network	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	122A - Network	1	ĒA	7	10+ years	
	Floor - Carpet	122A - Network	160	SF	6	6-10 years	
	Lighting - Lay-in	122A - Network	2	EA	7	10+ years	
	Power Distribution	122A - Network	8	EA	7	10+ years	
	Walls - Plaster/Drywall	122A - Network	342	SF	7	10+ years	
	AC Unit	122B - Network	1	ĒA	7	6-10 years	
	Ceiling - Lay-in	122B - Network	90	SF	7	6-10 years	
	Doors - Side-lite	122B - Network	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	122B - Network	1	ĒA	7	10+ years	
	Floor - Carpet	122B - Network	90	SF	7	6-10 years	
	Lighting - Lay-in	122B - Network	1	EA	7	10+ years	
	Power Distribution	122B - Network	8	EA	7	10+ years	
	Walls - Plaster/Drywall	122B - Network	260	SF	7	10+ years	
	AC Unit	122C - Network		EA	7	6-10 years	
	Ceiling - Lay-in	122C - Network	198	SF	7	10+ years	
	Doors - Wood Doors inclu hw	122C - Network	1	EA	7	10+ years	
	Floor - Carpet	122C - Network	198	SF	7	6-10 years	
	Lighting - Lay-in	122C - Network	2	EA	7	10+ years	
	Power Distribution	122C - Network	8	EA	7	10+ years	
	Walls - Plaster/Drywall	122C - Network	434	SF	7	10+ years	
	AC Unit	124 training		EA	7	6-10 years	
			5	LA	1	o io years	



	Schools						2935 W Polk STREET, Chicago, IL 6
atego	ry : Room		В	uilding	: Main		
			• •••			Recommend	<b>•</b> •
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	124 training	1,120	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	124 training	1	EA	7	10+ years	
	Floor - Carpet	124 training	1,120	SF	7	6-10 years	
	Lighting - Lay-in	124 training	21	EA	7	6-10 years	
	Power Distribution	124 training	10	EA	7	10+ years	
	Storage/ Closet	124 training	240	SF	7	10+ years	
	Walls - Plaster/Drywall	124 training	1,200	SF	7	10+ years	
	Ceiling - Plaster/Drywall	129 Security office	365	SF	6	6-10 years	
	Doors - Transom Window	129 Security office	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	129 Security office	1	EA	6	6-10 years	
	Floor - Wood	129 Security office	365	SF	6	6-10 years	
	Lighting - Pendent/Surface	129 Security office	2	EA	7	6-10 years	
	Power Distribution	129 Security office	6	EA	7	10+ years	
	Storage/ Closet	129 Security office	10	SF	7	10+ years	
	Walls - Plaster/Drywall	129 Security office	874	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	133&133A	864	SF	6	6-10 years	
	Doors - Transom Window	133&133A	27	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	133&133A	3	EA	6	6-10 years	
	Doors - Wood Doors inclu hw	133&133A	2	EA	6	6-10 years	
	Floor - Wood	133&133A	864	SF	6	6-10 years	
	Lighting - Pendent/Surface	133&133A	9	EA	7	6-10 years	
	Lighting - Pendent/Surface	133&133A	5	EA	6	6-10 years	
	Power Distribution	133&133A	10	EA	7	6-10 years	
	Storage/ Closet	133&133A	160	SF	7	6-10 years	
	Walls - Metal Panel	133&133A	172	SF	6	6-10 years	
	Walls - Plaster/Drywall	133&133A	1,200	SF	6	6-10 years	
	Work SInk	133&133A	1	ĒA	7	10+ years	
	Ceiling - Plaster/Drywall	137	729	SF	6	6-10 years	
	Doors - Transom Window	137	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	137	1	EA	6	6-10 years	
	Doors - Wood Doors inclu hw	137	2	EA	6	6-10 years	
	Floor - Tile	137	729	SF	6	6-10 years	
	Lighting - Pendent/Surface	137	6	EA	6	6-10 years	
	Power Distribution	137	16	EA	6	6-10 years	
	Walls - Plaster/Drywall	137	1,083	SF	6	6-10 years	
	AC Unit	225 Admin	1,000	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	225 Admin	464	SF	6	10+ years	
	Doors - Transom Window	225 Admin	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	225 Admin 225 Admin	9	EA	7	10+ years	
	Floor - Tile/Sheet	225 Admin 225 Admin	464	SF	7	6-10 years	
	Lighting - Pendent/Surface	225 Admin 225 Admin	404 4	EA	7		
			4 8	EA	7	10+ years	
	Power Distribution	225 Admin 225 Admin				10+ years	
	Walls - Plaster/Drywall		839	SF EA	6	10+ years	As unit in good sandition
	AC Unit	302A	1	EA	7	6-10 years	Ac unit in good condition



Catego	ry : Room		R	uilding	· Main		2935 W Polk STREET, Chicago, IL 60612
Calego	ry . Room		Di	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Croup	Ceiling - Plaster/Drywall	302A	195	SF	6	6-10 years	Sommerice
	Doors - Side-lite	302A	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	302A	2	EA	6	10+ years	
	Floor - Tile/Sheet	302A	195	SF	5	2-5 years	
	Lighting - Pendent/Surface	302A	3	EA	6	6-10 years	
	Power Distribution	302A	8	EA	6	6-10 years	
	Walls - Plaster/Drywall	302A	498	SF	6	6-10 years	
	AC Unit	315A	1	ĒA	7	6-10 years	Ac unit in good condition
	Ceiling - Plaster/Drywall	315A	195	SF	6	10+ years	0
	Doors - Side-lite	315A	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	315A	2	EA	7	10+ years	
	Floor - Tile/Sheet	315A	195	SF	5	6-10 years	
	Lighting - Pendent/Surface	315A	2	EA	6	6-10 years	
	Power Distribution	315A	8	EA	6	10+ years	
	Walls - Plaster/Drywall	315A	496	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	317A - ROTC office	110	SF	6	6-10 years	
	Doors - Side-lite	317A - ROTC office	40	SF	6	10+ years	
	Doors - Transom Window	317A - ROTC office	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	317A - ROTC office	1	EA	6	10+ years	
	Floor - Tile	317A - ROTC office	110	SF	6	6-10 years	
	Lighting - Pendent/Surface	317A - ROTC office	1	EA	6	6-10 years	
	Power Distribution	317A - ROTC office	8	EA	7	10+ years	
	Walls - Plaster/Drywall	317A - ROTC office	233	SF	6	6-10 years	
	Walls - Plaster/Drywall	317A - ROTC office	10	SF	4	0-1 year	Extensive water damage
	AC Unit	Custodian/Engineers office	1	EA	5	2-5 years	
	Ceiling - Plaster/Drywall	Custodian/Engineers office	191	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Custodian/Engineers office	1	EA	6	10+ years	
	Floor - Terrazzo	Custodian/Engineers office	191	SF	6	10+ years	
	Lighting - Pendent/Surface	Custodian/Engineers office	4	EA	7	6-10 years	
	Power Distribution	Custodian/Engineers office	4	EA	6	6-10 years	
	Storage/ Closet	Custodian/Engineers office	50	SF	7	6-10 years	
	Walls - Plaster/Drywall	Custodian/Engineers office	487	SF	6	10+ years	
	Ceiling - Lay-in	Kitchen office	94	SF	6	6-10 years	
	Doors - Side-lite	Kitchen office	60	SF	6	6-10 years	
	Doors - Transom Window	Kitchen office	45	SF	6	6-10 years	
	Doors - Transom Window	Kitchen office	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Kitchen office	2	EA	6	6-10 years	
	Floor - Tile	Kitchen office	94	SF	7	10+ years	
	Lighting - Lay-in	Kitchen office	1	EA	6	6-10 years	
	Power Distribution	Kitchen office	4	EA	6	6-10 years	
	Walls - Plaster/Drywall	Kitchen office	239	SF	6	10+ years	
	AC Unit	Network Office Suite	3	EA	7	6-10 years	
	Ceiling - Lay-in	Network Office Suite	2,093	SF	7	10+ years	
	Doors - Transom Window	Network Office Suite	18	SF	7	6-10 years	



Category : Room			B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Network Office Suite	7	EA	7	10+ years	
	Floor - Carpet	Network Office Suite	1,757	SF	7	6-10 years	
	Floor - Tile	Network Office Suite	336	SF	7	10+ years	
	Lighting - Lay-in	Network Office Suite	37	EA	7	10+ years	Relamp 1 fixture
	Power Distribution	Network Office Suite	32	EA	7	10+ years	
	Walls - Plaster/Drywall	Network Office Suite	1,137	SF	7	10+ years	
	Work SInk	Network Office Suite	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	North Gym Office 224E	262	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	North Gym Office 224E	2	EA	6	10+ years	
	Floor - Tile	North Gym Office 224E	257	SF	6	6-10 years	
	Floor - Tile	North Gym Office 224E	5	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	North Gym Office 224E	3	EA	7	10+ years	
	Power Distribution	North Gym Office 224E	4	EA	6	10+ years	
	Walls - Plaster/Drywall	North Gym Office 224E	524	SF	7	6-10 years	
	Work SInk	North Gym Office 224E	1	EA	5	1-2 years	Sink not working
	Ceiling - Plaster/Drywall	Pool Office - 124A	56	SF	6	10+ years	5
	Doors - Side-lite	Pool Office - 124A	42	SF	6	6-10 years	
	Doors - Steel Doors incl hw	Pool Office - 124A	1	ĒA	6	6-10 years	
	Floor - Concrete	Pool Office - 124A	56	SF	7	6-10 years	
	Lighting - Pendent/Surface	Pool Office - 124A	1	ĒA	5	2-5 years	
	Power Distribution	Pool Office - 124A	4	EA	6	10+ years	
	Walls - Structural Glazed Tile	Pool Office - 124A	128	SF	6	6-10 years	
	AC Unit	Principals office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Principals office	720	SF	6	10+ years	
	Doors - Transom Window	Principals office	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Principals office	2	EA	6	6-10 years	
	Floor - Tile	Principals office	720	SF	6	10+ years	
	Lighting - Pendent/Surface	Principals office	16	EA	7	10+ years	
	Power Distribution	Principals office	16	EA	6	10+ years	
	Storage/ Closet	Principals office	180	SF	7	10+ years	
	Walls - Plaster/Drywall	Principals office	1,448	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South Gym Office 224G	255	SF	6	10+ years	
	Doors - Side-lite	South Gym Office 224G	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	South Gym Office 224G	3	EA	6	10+ years	
	Floor - Tile	South Gym Office 224G	255	SF	6	10+ years	
	Lighting - Pendent/Surface	South Gym Office 224G	200	EA	7	10+ years	
	Power Distribution	South Gym Office 224G	3	EA	6		
	Storage/ Closet	South Gym Office 224G	-	SF	7	10+ years	
	Walls - Plaster/Drywall	South Gym Office 224G	128 529	SF		6-10 years	
					6	10+ years	
	Work SInk	South Gym Office 224G	1	EA	7	6-10 years	
uditoriu	ım & Theater						
	Balcony Seating	1st Floor	254	EA	7	6-10 years	
	Balcony Seating			EA	7	6-10 years	



	ry : Room		P	uilding	2935 W Polk STREET, Chicago, IL 60612		
calego	iy. Room		D	unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup		Loodion	quantity	00111	Marin	Replacement	balcony; other occupancy signage no
							observed
	Ceiling - Plaster/Drywall	1st Floor	1,951	SF	6	6-10 years	
	Ceiling - Splined	1st Floor	2,927	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	20	EA	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	1st Floor	1,920	SF	7	6-10 years	
	Floor - Epoxy/ Painted	1st Floor	2,958	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	25	EA	6	6-10 years	
	Main Floor Seating	1st Floor	448	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	812	SF	6	6-10 years	
	Stage Curtain	1st Floor	2	EA	7	6-10 years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	6,158	SF	6	6-10 years	
ivmnas	ia						
ymnas	Bleacher Seating	Gymnasium North 226B	13	EA	6	6-10 years	No visible occupancy signage
	Ceiling - Plaster/Drywall	Gymnasium North 226B	5,974	SF	6	6-10 years	
	Doors - Transom Window	Gymnasium North 226B	36	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gymnasium North 226B	6	EA	6	10+ years	
	Floor - Wood	Gymnasium North 226B	5,974	SF	6	10+ years	
	Lighting - Pendent/Surface	Gymnasium North 226B	18	EA	7	10+ years	
	Lighting - Wall Mounted	Gymnasium North 226B	4	EA	7	10+ years	
	Scoreboards	Gymnasium North 226B	1	EA	7	6-10 years	
	Storage/ Closet	Gymnasium North 226B	140	SF	5	6-10 years	
	Walls - Structural Glazed Tile	Gymnasium North 226B	8,280	SF	6	10+ years	
	Bleacher Seating	Gymnasium South	13	EA	6	6-10 years	No visible occupancy signage
	Ceiling - Plaster/Drywall	Gymnasium South	5,974	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Gymnasium South	5	EA	6	10+ years	
	Floor - Wood	Gymnasium South	5,974	SF	6	10+ years	
	Lighting - Pendent/Surface	Gymnasium South	18	EA	7	10+ years	
	Scoreboards	Gymnasium South	1	EA	7	6-10 years	
	Storage/ Closet	Gymnasium South	128	SF	4	1-2 years	Damaged drywall
	Walls - Structural Glazed Tile	Gymnasium South	8,280	SF	6	10+ years	Damagoa arywan
			-,			, ,	
itchen	Ceiling - Exposed	1st Floor	140	SF	6	10+ years	
	Ceiling - Splined	1st Floor	10	SF	7	10+ years	
	Ceiling - Splined	1st Floor	751	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	27	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	6-10 years	
	Floor - Tile	1st Floor	901	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	901 4	EA	7	-	
	Lighting - Fendent/Sunace		4	EA	1	6-10 years	



XICA :							2935 W Polk STREET, Chicago, IL 60612
Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	2	EA	6	2-5 years	Relamp
	Walls - Masonry	1st Floor	1,123	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	369	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	6	SF	6	10+ years	
Library							
,	AC Unit	1st Floor	3	EA	7	6-10 years	
	Casework	1st Floor	120	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,861	SF	6	10+ years	
	Doors - Transom Window	1st Floor	27	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	6	ËA	6	6-10 years	
	Floor - Carpet	1st Floor	1,861	SF	4	0-1 year	Torn carpet
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,783	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	6,083	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	72	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	8	EA	6	6-10 years	
	Floor - Terrazzo	1st Floor	6,083	SF	6	6-10 years	
	Lighting - Lay-in	1st Floor	42	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	3,598	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Dishwashing room	690	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Dishwashing room	2	EA	4	0-1 year	Missing.
	Floor - Terrazzo	Dishwashing room	690	SF	6	10+ years	Wissing.
	Lighting - Pendent/Surface	Dishwashing room	2	EA	5	1-2 years	Refurbish assembly
	Walls - Plaster/Drywall	Dishwashing room	1,338	SF	6	10+ years	Refutbisit assembly
	Ceiling - Lay-in	Servery	1,628	SF	6	10+ years	
	Ceiling - Lay-in	Servery	40	SF	4	1-2 years	Water damaged
	Doors - Transom Window	Servery	40 90	SF	6	6-10 years	Water damaged
	Doors - Wood Doors inclu hw	Servery	90 10	EA	6	6-10 years	
	Floor - Terrazzo	Servery	1,618	SF	6	10+ years	
	Floor - Terrazzo	•	50	SF	6	10+ years	
		Servery	19	EA	7	6-10 years	
	Lighting - Lay-in Lighting - Lay-in	Servery	19	EA	6	2-5 years	
		Servery		LF			
	Serving Line	Servery	140	SF	6	6-10 years	
	Walls - Structural Glazed Tile	Servery	1,309		6	10+ years	
	Ceiling - Plaster/Drywall	Weight Room - 126 (old locker room)	1,368	SF	6	6-10 years	
	Doors - Transom Window	Weight Room - 126 (old locker room)	36	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Weight Room - 126 (old locker room)	4	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Weight Room - 126 (old locker	1,368	SF	6	6-10 years	



Catego	Category : Room		В	uilding	: Main	2935 W POIK STREET, Chicago, IL 60612	
30.00			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-		room)					
	Lighting - Pendent/Surface	Weight Room - 126 (old locker	10	EA	7	6-10 years	
		room)					
	Lighting - Pendent/Surface	Weight Room - 126 (old locker	10	EA	6	6-10 years	
		room)		Ξ.	0	0.40	
	Student Lockers - Two Tier	Weight Room - 126 (old locker	82	EA	6	6-10 years	
	Walls - Structural Glazed Tile	room) Weight Room - 126 (old locker	2,328	SF	6	6-10 years	
	Walls - Structural Glazed The	room)	2,320	3F	0	0-10 years	
		loonij					
_MDF_ID	)F						
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	6-10 years	
	Finishes	2nd Floor	434	SF	5	6-10 years	
	Window AC Unit	2nd Floor	2	EA	7	6-10 years	
Nechan	ical/ Service Rooms	4 at Ela ar	100	0	7	10	
	Janitor's Closet	1st Floor 1st Floor	100	SF SF	7	10+ years	
	Storage Room Janitor's Closet	2nd Floor	3,300 100	SF	7 5	10+ years 6-10 years	Kay brakan ingida laak, na aagaag
	Janitor's Closet	2nd Floor	100	SF	5	6-10 years	Key broken inside lock, no access
	Janitor's Closet	3rd Floor	100	SF	5	6-10 years	
	Janitor's Closet	3rd Floor	100	SF	5	6 10 years	
	Storage Room	3rd Floor	612	SF	5	6-10 years 6-10 years	
	Air Tunnel		5,000	SF	5 7		
		Basement	3,036	SF	7	10+ years	
	Boiler Room	Basement		SF		10+ years	
	Janitor's Closet	Basement	146	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	5,863		7	10+ years	
	Storage Room	Basement	272	SF	7	10+ years	
Pool & N	Natatorium						
	Accessories	1st Floor	3,589	SF	7	6-10 years	
	Bleachers Seating/Plank Seating	1st Floor	45	EA	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	3,589	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	6	10+ years	
	Doors - Transom Window	1st Floor	168	SF	6	10+ years	
	Floor - Concrete	1st Floor	3,589	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	ĒA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	42	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	6	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	7	EA	6	6-10 years	
	Pool Basin	1st Floor	1,500	SF	5	2-5 years	
						•	
	Pool Deck Pool Deck Drains	1st Floor 1st Floor	2,069 6	SF EA	6 7	6-10 years 10+ years	



	Schools						2935 W Polk STREET, Chicago, IL 60
Category : Room			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	80	SF	5	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	3,276	SF	6	6-10 years	
rep Ro	om						
	Casework	302A-2 (plan 302-B)	20	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	302A-2 (plan 302-B)	220	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	302A-2 (plan 302-B)	1	EA	7	10+ years	
	Floor - Tile/Sheet	302A-2 (plan 302-B)	220	SF	7	6-10 years	
	Lighting - Pendent/Surface	302A-2 (plan 302-B)	2	EA	6	6-10 years	Relamp 1 fixture
	Walls - Plaster/Drywall	302A-2 (plan 302-B)	486	SF	6	6-10 years	
	Work Sink	302A-2 (plan 302-B)		EA	7	6-10 years	
	Casework	315B	20	LA	6	•	
				SF	6 6	6-10 years	
	Ceiling - Plaster/Drywall	315B	220			6-10 years	
	Doors - Wood Doors inclu hw	315B	1	EA	7	10+ years	
	Floor - Tile/Sheet	315B	220	SF	5	6-10 years	
	Lighting - Pendent/Surface	315B	3	EA	6	6-10 years	
	Walls - Plaster/Drywall	315B	486	SF	6	10+ years	
	Work Sink	315B	1	EA	7	6-10 years	
	Work Sink	315B	2	EA	7	6-10 years	Quality upgraded sink in good
							condition (dirty)
estroor	m						
	Accessories	1st floor boys east	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor boys east	260	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st floor boys east	3	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	1st floor boys east	2	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor boys east	263	SF	6	6-10 years	
	Floor Drain	1st floor boys east	1	EA	7	10+ years	
	Hand Dryer	1st floor boys east	1	EA	7	6-10 years	
	Lavatory	1st floor boys east	3	EA	7	6-10 years	Quality upgraded, fixtures in goo
		Tachool boys east	5		ľ	U- IU years	condition
	Lighting - Pendent/Surface	1st floor boys east	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st floor boys east	1	EA	5	1-2 years	Cracked cover
	Partitions	1st floor boys east	2	EA	7	10+ years	
	Urinals	1st floor boys east	4	EA	7	6-10 years	Quality upgraded, fixtures in goo
		-			-		condition
	Walls - Structural Glazed Tile	1st floor boys east	1	SF	6	6-10 years	
	Walls - Structural Glazed Tile	1st floor boys east	595	SF	6	6-10 years	
	Water Closet	1st floor boys east	2	EA	7	6-10 years	Quality upgraded, fixtures in goo
		,	_			<b>,</b> '	condition
	Accessories	1st floor boys west	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor boys west	263	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st floor boys west	200	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st floor boys west	263	SF	6	6-10 years	
		ISCHOOL DOYS WEST	203	36	U	U- TO years	



2935 W Polk STREET, Chicago, IL 60612										
Catego	ry : Room		B	uilding	: Main					
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor Drain	1st floor boys west	1	EA	7	10+ years				
	Hand Dryer	1st floor boys west	1	EA	7	6-10 years				
	Lavatory	1st floor boys west	2	EA	7	6-10 years				
	Lighting - Pendent/Surface	1st floor boys west	5	EA	7	6-10 years				
	Partitions	1st floor boys west	2	EA	7	6-10 years				
	Urinals	1st floor boys west	4	EA	7	6-10 years	Quality upgraded, fixtures in good condition			
	Walls - Structural Glazed Tile	1st floor boys west	596	SF	6	6-10 years				
	Water Closet	1st floor boys west	2	EA	7	6-10 years	Quality upgraded, fixtures in good condition			
	Accessories	1st floor girls east	506	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st floor girls east	503	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st floor girls east	3	SF	5	1-2 years	Water damage			
	Doors - Wood Doors inclu hw	1st floor girls east	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st floor girls east	506	SF	6	6-10 years				
	Floor Drain	1st floor girls east	1	EA	7	10+ years				
	Hand Dryer	1st floor girls east	1	EA	7	6-10 years				
	Lavatory	1st floor girls east	2	EA	6	6-10 years				
	Lighting - Pendent/Surface	1st floor girls east	7	EA	7	6-10 years				
	Partitions	1st floor girls east	6	EA	7	10+ years				
	Walls - Plaster/Drywall	1st floor girls east	392	SF	6	10+ years				
	Walls - Tile	1st floor girls east	568	SF	7	10+ years				
	Water Closet	1st floor girls east	6	EA	7	6-10 years	Quality upgraded, fixtures in good			
		-				-	condition			
	Accessories	2nd floor boys east	263	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd floor boys east	263	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd floor boys east	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd floor boys east	263	SF	6	10+ years				
	Floor Drain	2nd floor boys east	2	EA	7	10+ years				
	Hand Dryer	2nd floor boys east	1	EA	7	6-10 years				
	Lavatory	2nd floor boys east	1	EA	6	6-10 years				
	Lighting - Pendent/Surface	2nd floor boys east	3	EA	7	10+ years				
	Lighting - Pendent/Surface	2nd floor boys east	1	EA	6	2-5 years	Relamp fixture			
	Partitions	2nd floor boys east	2	EA	7	6-10 years				
	Urinals	2nd floor boys east	4	EA	6	6-10 years				
	Walls - Plaster/Drywall	2nd floor boys east	266	SF	6	10+ years				
	Walls - Tile	2nd floor boys east	349	SF	6	10+ years				
	Water Closet	2nd floor boys east	1	EA	7	10+ years				
	Water Closet	2nd floor boys east	1	EA	4	1-2 years	Not working			
	Accessories	2nd floor boys west	263	SF	7	6-10 years	, and the second s			
	Ceiling - Plaster/Drywall	2nd floor boys west	263	SF	6	6-10 years				
	Doors - Wood Doors inclu hw	2nd floor boys west	2	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd floor boys west	263	SF	6	6-10 years				
	Floor Drain	2nd floor boys west	1	EA	7	10+ years				
					-					



<b>XUN</b>							2935 W Polk STREET, Chicago, IL 606
Catego	ry : Room		В	uilding	: Main		
	the second se	I section.	<b>O</b>		<b>D</b> . 1	Recommend	0
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hand Dryer	2nd floor boys west	1	EA	7	6-10 years	Quality on and dad. firstones in second
	Lavatory	2nd floor boys west	2	EA	7	6-10 years	Quality upgraded, fixtures in good condition
	Lighting - Pendent/Surface	2nd floor boys west	5	EA	7	6-10 years	
	Partitions	2nd floor boys west	2	EA	7	6-10 years	
	Urinals	2nd floor boys west	4	EA	7	6-10 years	Quality upgraded, fixtures in good condition
	Walls - Structural Glazed Tile	2nd floor boys west	596	SF	6	6-10 years	
	Water Closet	2nd floor boys west	2	EA	7	6-10 years	Quality upgraded, fixtures in good condition
	Accessories	2nd floor girls east	506	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girls east	506	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor girls east	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor girls east	506	SF	6	10+ years	
	Hand Dryer	2nd floor girls east	1	EA	7	6-10 years	
	Lavatory	2nd floor girls east	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd floor girls east	9	EA	7	10+ years	
	Partitions	2nd floor girls east	8	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd floor girls east	384	SF	6	10+ years	
	Walls - Tile	2nd floor girls east	577	SF	6	10+ years	
	Water Closet	2nd floor girls east	8	EA	6	6-10 years	
	Accessories	2nd floor girls west	460	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girls west	455	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girls west	5	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd floor girls west	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor girls west	460	SF	6	6-10 years	
	Floor Drain	2nd floor girls west	1	EA	7	10+ years	
	Lavatory	2nd floor girls west	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd floor girls west	6	EA	6	6-10 years	Relamp 1 fixture
	Lighting - Pendent/Surface	2nd floor girls west	2	EA	5	1-2 years	2 fixtures missing cover
	Partitions	2nd floor girls west	6	EA	7	6-10 years	
	Walls - Structural Glazed Tile	2nd floor girls west	816	SF	7	10+ years	
	Water Closet	2nd floor girls west	3	EA	7	6-10 years	
	Water Closet	2nd floor girls west	3	EA	4	1-2 years	Water closet not functioning
	Accessories	2nd floor west unisex	240	SF	7	6-10 years	
	Ceiling - Lay-in	2nd floor west unisex	200	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor west unisex	40	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	2nd floor west unisex	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor west unisex	240	SF	7	6-10 years	
	Floor Drain	2nd floor west unisex	1	EA	7	10+ years	
	Hand Dryer	2nd floor west unisex	1	EA	7	6-10 years	
	Lavatory	2nd floor west unisex	1	EA	7	6-10 years	
	Lighting - Lay-in	2nd floor west unisex	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd floor west unisex	291	SF	7	10+ years	



	SCHOOIS						2935 W Polk STREET, Chicago, IL 60612
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Tile Ceramic/ Porcelain	2nd floor west unisex	173	SF	7	10+ years	
	Water Closet	2nd floor west unisex	1	EA	7	6-10 years	Quality upgraded, fixtures in good
						2	condition
	Accessories	2nd floor women east	257	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor women east	257	SF	6	6-10 years	
	Doors - Transom Window	2nd floor women east	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor women east	2	EA	6	10+ years	
	Floor - Tile	2nd floor women east	57	SF	6	2-5 years	
	Floor - Tile Ceramic/ Porcelain	2nd floor women east	200	SF	6	6-10 years	
	Lavatory	2nd floor women east	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd floor women east	3	EA	7	6-10 years	
	Partitions	2nd floor women east	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd floor women east	530	SF	6	10+ years	
	Water Closet	2nd floor women east	2	EA	6	6-10 years	
	Water Closet	2nd floor women east	1	EA	3	1-2 years	Water closet removed
	Accessories	3rd floor boys east 325 B	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor boys east 325 B	263	SF	5	1-2 years	Signs of water damage throughout
	Doors - Wood Doors inclu hw	3rd floor boys east 325 B	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor boys east 325 B	263	SF	6	6-10 years	
	Floor Drain	3rd floor boys east 325 B	2	EA	7	10+ years	
	Hand Dryer	3rd floor boys east 325 B	1	EA	7	6-10 years	
	Lavatory	3rd floor boys east 325 B	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	3rd floor boys east 325 B	4	EA	6	6-10 years	
	Partitions	3rd floor boys east 325 B	1	EA	7	6-10 years	Partitions in good condition; need
							painting
	Partitions	3rd floor boys east 325 B	1	EA	7	6-10 years	
	Urinals	3rd floor boys east 325 B	4	EA	7	6-10 years	Urinals in good condition; quality
							upgraded.
	Walls - Structural Glazed Tile	3rd floor boys east 325 B	616	SF	6	6-10 years	
	Water Closet	3rd floor boys east 325 B	1	EA	7	6-10 years	Water closet in good condition;
							quality upgraded.
	Water Closet	3rd floor boys east 325 B	1	EA	4	0-1 year	Water closet not functioning
	Accessories	3rd floor boys west 310B	263	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor boys west 310B	261	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor boys west 310B	2	SF	5	1-2 years	Peeling paint
	Doors - Wood Doors inclu hw	3rd floor boys west 310B	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor boys west 310B	263	SF	6	6-10 years	
	Floor Drain	3rd floor boys west 310B	1	EA	7	6-10 years	
	Hand Dryer	3rd floor boys west 310B	1	EA	7	6-10 years	
	Lavatory	3rd floor boys west 310B	2	EA	7	6-10 years	Quality upgraded, fixtures in good
	Link ting		-		7	0.40	condition
	Lighting - Pendent/Surface	3rd floor boys west 310B	5	EA	7	6-10 years	
	Partitions	3rd floor boys west 310B	2	EA	7	6-10 years	
	Urinals	3rd floor boys west 310B	3	EA	6	6-10 years	



Category : Room Building : Main								
Catego	ry : Room		В	uilding	: Main			
_						Recommend	-	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Urinals	3rd floor boys west 310B	1	EA	5	1-2 years	Not functioning	
	Walls - Structural Glazed Tile	3rd floor boys west 310B	696	SF	6	6-10 years		
	Water Closet	3rd floor boys west 310B	2	EA	7	6-10 years	Quality upgraded, water closet in good condition	
	Accessories	3rd floor girls east 325C	506	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd floor girls east 325C	506	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	3rd floor girls east 325C	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd floor girls east 325C	506	SF	6	6-10 years		
	Floor Drain	3rd floor girls east 325C	1	EA	7	10+ years		
	Hand Dryer	3rd floor girls east 325C	1	EA	7	6-10 years		
	Lavatory	3rd floor girls east 325C	2	EA	6	6-10 years		
	Lighting - Pendent/Surface	3rd floor girls east 325C	9	EA	7	6-10 years	Relamp 3 fixtures	
	Partitions	3rd floor girls east 325C	8	EA	7	6-10 years	•	
	Walls - Plaster/Drywall	3rd floor girls east 325C	584	SF	6	6-10 years		
	Walls - Tile	3rd floor girls east 325C	676	SF	6	6-10 years		
	Water Closet	3rd floor girls east 325C	7	ĒA	7	6-10 years	Water closet in good condition;	
		0.4.1001 g.10 0401 0200		_/ \	-	0.0000	quality upgraded	
	Water Closet	3rd floor girls east 325C	1	EA	4	1-2 years	Water closet not functioning	
	Accessories	3rd floor girls west 310A	342	SF	7	6-10 years	Water closer not randicining	
	Ceiling - Plaster/Drywall	3rd floor girls west 310A	342	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	3rd floor girls west 310A	2	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	3rd floor girls west 310A	342	SF	6	6-10 years		
	Floor Drain	3rd floor girls west 310A	1	EA	7	10+ years		
	Lavatory	3rd floor girls west 310A	2	EA	7	6-10 years		
	Lighting - Pendent/Surface	3rd floor girls west 310A	9	EA	6	6-10 years		
	Partitions	3rd floor girls west 310A	9	EA	7	6-10 years		
	Walls - Structural Glazed Tile	3rd floor girls west 310A	802	SF	6	6-10 years		
	Walls - Structural Glazed The Water Closet	3rd floor girls west 310A	6	EA	7		Quality upgraded, fixtures in good	
		C C	-			6-10 years	condition	
	Accessories	Boiler Room	50	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	Boiler Room	25	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Boiler Room	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	Boiler Room	25	SF	6	10+ years		
	Lighting - Pendent/Surface	Boiler Room	1	EA	7	6-10 years		
	Walls - Plaster/Drywall	Boiler Room	50	SF	5	0-1 year	Water damage.	
	Water Closet	Boiler Room	1	EA	7	6-10 years		
	Accessories	Custodian toliet	45	SF	5	6-10 years		
	Ceiling - Plaster/Drywall	Custodian toliet	45	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Custodian toliet	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	Custodian toliet	45	SF	6	6-10 years		
	Lavatory	Custodian toliet	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	Custodian toliet	1	EA	7	6-10 years		
	Showers	Custodian toliet	1	EA	7	10+ years		
	Walls - Plaster/Drywall	Custodian toliet	75	SF	4	1-2 years	Water damaged	



						2935 W Polk STREET, Chicago, IL 60612		
Catego	ry : Room		В	uilding	: Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Toup	Water Closet	Custodian toliet	1	EA	6	6-10 years	Commente	
	Accessories	First floor womens	252	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	First floor womens	252	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	First floor womens	1	EA	6	6-10 years		
	Floor - Tile Ceramic/ Porcelain	First floor womens	252	SF	6	10+ years		
	Floor Drain	First floor womens	1	EA	7	10+ years		
	Lavatory	First floor womens	2	EA	7	6-10 years	Quality upgraded, fixtures in good condition	
	Lighting - Pendent/Surface	First floor womens	6	EA	5	1-2 years	Missing covers	
	Partitions	First floor womens	6	EA	7	6-10 years	Miceling covere	
	Walls - Structural Glazed Tile	First floor womens	542	SF	6	6-10 years		
	Water Closet	First floor womens	6	EA	7	6-10 years	Quality upgraded, fixtures in good condition	
	Accessories	In 137	64	SF	7	6-10 years	condition	
	Ceiling - Plaster/Drywall	In 137	64	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	In 137	2	EA	6	6-10 years		
	Floor - Tile	In 137	64	SF	6	6-10 years		
	Floor Drain	In 137	1	EA	7	6-10 years		
	Hand Dryer	In 137	1	EA	7	6-10 years		
	Lavatory	In 137	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	In 137	1	EA	6	6-10 years	Relamp	
	Partitions	In 137	1	EA	7	6-10 years	Relation	
	Walls - Plaster/Drywall	In 137	111	SF	6	6-10 years		
	Walls - Flaster/Drywall Water Closet	In 137	1	EA	6	6-10 years		
		In North gym - 224D	110	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	In North gym - 224D	110	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	In North gym - 224D	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	In North gym - 224D	110	SF	6	6-10 years		
	Floor Drain	In North gym - 224D	1	EA	7	10+ years		
	Lavatory	In North gym - 224D	1	EA	7	6-10 years	Quality upgraded, fixtures in good condition	
	Lighting - Pendent/Surface	In North gym - 224D	2	EA	7	6-10 years		
	Showers	In North gym - 224D	1	EA	7	6-10 years		
	Student Lockers - One Tier	In North gym - 224D	5	EA	6	10+ years		
	Walls - Plaster/Drywall	In North gym - 224D	226	SF	6	6-10 years		
	Water Closet	In North gym - 224D	1	EA	6	6-10 years		
	Accessories	Main office	37	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Main office	37	SF	6	6-10 years		
	Doors - Wood Doors inclu hw	Main office	1	EA	6	6-10 years		
	Floor - Tile	Main office	37	SF	7	6-10 years		
	Lavatory	Main office	1	EA	6	6-10 years		
	Lighting - Pendent/Surface	Main office	1	EA	6	6-10 years		
	Partitions	Main office	1	EA	7	6-10 years		
	Walls - Metal Panel	Main office	97	SF	6	6-10 years		



Catego	ry : Room		В	uilding	: Main		
e	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	Main office	1	EA	6	6-10 years	
	Accessories	Network	108	SF	7	6-10 years	
	Ceiling - Lay-in	Network	108	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Network	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Network	100	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Network	8	SF	4	0-1 year	Missing.
	Floor Drain	Network	1	EA	7	10+ years	
	Lavatory	Network	1	EA	6	6-10 years	
	Lighting - Lay-in	Network	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Network	226	SF	6	10+ years	
	Water Closet	Network	1	EA	6	6-10 years	
	Accessories	Pool	176	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Pool	176	SF	6	6-10 years	
	Doors - Steel Doors incl hw	Pool	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Pool	176	SF	6	6-10 years	
	Floor Drain	Pool	1	EA	7	6-10 years	
	Lavatory	Pool	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	Pool	3	EA	7	6-10 years	
	Showers	Pool	1	EA	7	6-10 years	
	Student Lockers - One Tier	Pool	4	EA	7	6-10 years	
	Walls - Masonry	Pool	114	SF	6	6-10 years	
	Walls - Structural Glazed Tile	Pool	254	SF	7	10+ years	
	Walls - Tile	Pool	114	SF	6	6-10 years	
	Water Closet	Pool	1	EA	6	6-10 years	
	Accessories	Principals office	37	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Principals office	37	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principals office	1	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	Principals office	37	SF	6	10+ years	
	Lavatory	Principals office	1	EA	6	10+ years	
	Lighting - Wall Mounted	Principals office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Principals office	65	SF	6	10+ years	
	Water Closet	Principals office	1	EA	6	10+ years	

## Category : Classroom

Building	Main
Dunung	wan

				Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Classroo	m #111 (Store Room)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	12	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years			
	Chalk Board	1st Floor	35	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	18	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years			
	Floor - Wood	1st Floor	720	SF	6	10+ years			



NICA S							2935 W Polk STREET, Chicago, IL 6061
Catego	ry : Classroom		В	uilding			
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	10	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,346	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	5	SF	6	6-10 years	Peeling paint
Classroo	m #112 (Laboratory/Shop)						
	Ceiling - Splined	1st Floor	455	SF	6	6-10 years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒA	7	10+ years	
	Floor - Tile	1st Floor	455	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	408	SF	6	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	408	SF	7	10+ years	
		151 F1001	440	ЗГ	'	10+ years	
Classroo	m #113 (Faculty Lounge)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	840	SF	7	10+ years	
	Chalk Board	2nd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	1	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Wood	2nd Floor	840	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	80	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,252	SF	6	10+ years	
Classroo	m #114 (Carpentry)						
	Casework	1st Floor	52	LF	7	6-10 years	
	Ceiling - Splined	1st Floor	2,700	SF	6	6-10 years	
	Doors - Transom Window	1st Floor	2,100	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Tile	1st Floor	2,700	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	2,700	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	24	EA	5	2-5 years	
	Walls - Plaster/Drywall			SF		•	
	Walls - Plaster/Drywall Walls - Structural Glazed Tile	1st Floor 1st Floor	1,469	SF SF	6	6-10 years	
			1,469		6	10+ years	
	Wood Shop Equipment	1st Floor	20	EA	7	6-10 years	
	Work Sink	1st Floor	3	EA	7	10+ years	
Classroo	m #125 (Office)						
	Casework Ceiling - Plaster/Drywall	1st Floor	15	LF	6	10+ years	
		1st Floor	720	SF	6	6-10 years	



)	Schools						2935 W Polk STREET, Chicago, IL 6061
Catego	ry : Classroom		В	uilding	: Main		
_			<b>•</b>			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	6-10 years	
	Doors - Transom Window	1st Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	6-10 years	
	Floor - Wood	1st Floor	720	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	5	2-5 years	
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,346	SF	6	6-10 years	
	Work Sink	1st Floor	1	EA	5	10+ years	
Classroo	om #200 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	861	SF	6	10+ years	
	Chalk Board	2nd Floor	15	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	5 1	EA	6	10+ years	
	Floor - Wood	2nd Floor	861	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	5	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,102	SF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	4	1-2 years	Damaged plaster
	Work Sink	2nd Floor	5	EA	5	1-2 years	Sink not working
	WOR SINK		I	EA	5	1-2 years	Sink not working
Classroc	om #201 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	14	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,176	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	1,176	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	22	EA	5	2-5 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,481	SF	6	6-10 years	
	Wireless System	2nd Floor	. 1	EA	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #202 (Faculty Lounge)						
	AC Units	2nd Floor	2	EA	5	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	808	SF	6	6-10 years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Chair Doard	2101100	22	LI	т	2-0 years	



Category : Classroom     Building : Wain       Group Item - Type     Location     Quantify UOM     Rank     Replacement Replacement     Comments       Doors - Wood Doors inclu hw     2nd Floor     808     SF     7     10+ years       Floor - Wood     2nd Floor     808     SF     7     10+ years       Classroom #204 (Computer Lab)     -     -     -     -     -     -       Classroom #204 (Computer Lab)     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -     -		Schools						2935 W Polk STREET, Chicago, IL 60612	
Group Item - Type     Location     Quantity     UOM     Rank     Replacement     Comments       Doors - Wood Doors inclub     2nd Floor     808     SF     7     10 + years       Lighting - Lay-in     2nd Floor     12     EA     6     6-10 years       Walls - Plaster/Drywall     2nd Floor     1,137     SF     6     10 + years       -Classcoorn #204 (Computer Lab)	Catego	ry : Classroom		B	uilding				
Doors - Wood Doors inclu hw     2nd Floor     1     EA     6     10+ years       Floor     12     EA     6     6-10 years       Walls - Plaster/Drywall     2nd Floor     12     EA     6     6-10 years       Classmon #204 (Computer Lah)     2nd Floor     14     EA     7     6-10 years       Casework     2nd Floor     12     EA     6     6-10 years       Ceiling - Floster/Drywall     2nd Floor     72     EF     6     6-10 years       Doors - Wood Doors inclu hw     2nd Floor     724     SF     6     6-10 years       Doors - Wood Doors inclu hw     2nd Floor     724     SF     6     6-10 years       Floor - Wood     2nd Floor     12     EA     7     10+ years       Wireless System     2nd Floor     11,32     SF     6     6-10 years       Classroon #206 (Regular Classnom)     2nd Floor     1     EA     7     6-10 years       Classroon #206 (Regular Classnom)     2nd Floor     1     EA     7     6-10 years </th <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th>									
Floor-Wood     2nd Floor     808     SF     7     10-years       Walls - Plaster/Drywall     2nd Floor     1,137     SF     6     10-years       Classmon #204 (Computer Lab)	Group			2				Comments	
Lighting - Lay-in Walls - Plaster/Drywall     2nd Floor     12     EA     6     6-0 (years)       Classmon #204 (Computer Lab)									
Walls - Plaster/Drywall     2nd Floor     1,137     SF     6     10+ years       Classmon #204 (Computer Lab)									
Classmon #204 (Computer Lah).     AC Units   2nd Floor   4   EA   7   6-10 years     Casework   2nd Floor   12   LF   6   6-10 years     Doors - Transom Window   2nd Floor   9   SF   7   10+ years     Doors - Wood Doors inclu hw   2nd Floor   1   EA   6   6-10 years     Doors - Wood Doors inclu hw   2nd Floor   1   EA   6   6-10 years     Lighting - Pendent/Surface   2nd Floor   12   EA   7   10+ years     Walls - Plaster/Drywall   2nd Floor   1,132   SF   6   10 years     Classmont #206 (Regular Classroom)   1   EA   7   6-10 years     Casework   2nd Floor   1   EA   7   6-10 years     Casework   2nd Floor   1   EA   7   6-10 years     Doors - Transon Window   2nd Floor   16   SF   6   6-10 years     Casework   2nd Floor   1   EA   7   6-10 years     Doors - Transon Window   2nd Floor   12   EA   <						-	•		
AC Units     2nd Floor     4     EA     7     6-10 years       Casswork     2nd Floor     12     LF     6     6-10 years       Doors - Transom Window     2nd Floor     724     SF     6     6-10 years       Doors - Wood Doors inclu hw     2nd Floor     7     12     EA     6     6-10 years       Doors - Wood Doors inclu hw     2nd Floor     12     EA     7     10- years       Lighting - Pendent/Surface     2nd Floor     12     EA     7     10- years       Walls - Plaster/Drywall     2nd Floor     1.32     SF     6     6-10 years       Classroom #206 (Regular Classroom)     1     EA     7     6-10 years       Classroom #206 (Regular Classroom)     2nd Floor     1     EA     7     6-10 years       Cassroon #206 (Regular Classroom)     2nd Floor     1     EA     7     6-10 years       Cassroon #206 (Regular Classroom)     2nd Floor     18     SF     6     6-10 years       Cassroork     2nd Floor     78     5     6-10		Walls - Plaster/Drywall	2nd Floor	1,137	SF	6	10+ years		
Casework     2nd Floor     12     LF     6     6-10 years       Ceiling - Plaster/Drywall     2nd Floor     7     10+ years       Doors - Transom Window     2nd Floor     9     SF     7     10+ years       Doors - Wood Doors inclu hw     2nd Floor     1     EA     6     6-10 years       Floor - Wood     2nd Floor     724     SF     6     6-10 years       Lighting - Pendent/Surface     2nd Floor     12     EA     7     10+ years       Walls - Plaster/Drywall     2nd Floor     1     EA     7     6-10 years       Classmom #206 (Regular Classmom)     2nd Floor     1     EA     7     6-10 years       Casework     2nd Floor     1     EA     7     6-10 years       Ceiling - Lay-in     2nd Floor     16     SF     6     6-10 years       Doors - Transom Window     2nd Floor     708     SF     6     6-10 years       Doors - Wood Doors inclu hw     2nd Floor     724     SF     6     6-10 years       Doors -	Classroo	om #204 (Computer Lab)							
Ceiling - Plaster/Dryvall2nd Floor724SF66-10 yearsDoors - Transom Window2nd Floor9SF710+ yearsDoors - Wood Doors inclu hw2nd Floor724SF66-10 yearsLighting - Pendent/Surface2nd Floor724SF66-10 yearsLighting - Pendent/Surface2nd Floor12EA710+ yearsWalls - Plaster/Dryvall2nd Floor1EA76-10 yearsClassmom #206 (Regular Classmom)Classmom #206 (Regular Classmom)		AC Units	2nd Floor	4		7	6-10 years		
Doors     Transom Window     2nd Floor     9     SF     7     10-years       Doors     Wood Doors inclu hw     2nd Floor     1     EA     6     6-10 years       Lighting - Pendent/Surface     2nd Floor     12     EA     7     10-years       Walls - Plaster/Dywall     2nd Floor     12     EA     7     6-10 years       Classroom #206 (Regular Classroom)     1     EA     7     6-10 years       Classroom #206 (Regular Classroom)     1     EA     7     6-10 years       Casework     2nd Floor     1     EA     7     6-10 years       Ceiling - Lay-in     2nd Floor     1     EA     7     6-10 years       Doors - Transom Window     2nd Floor     16     SF     6     6-10 years       Doors - Wood Doors inclu hw     2nd Floor     18     SF     6     6-10 years       Doors - Wood Doors inclu hw     2nd Floor     12     EA     5     2-5 years       Highting - Lay-in     2nd Floor     12     EA     5     2-5 years </td <td></td> <td>Casework</td> <td>2nd Floor</td> <td>12</td> <td>LF</td> <td>6</td> <td>6-10 years</td> <td></td>		Casework	2nd Floor	12	LF	6	6-10 years		
Doors - Wood Doors inclu hw     2nd Floor     1     EA     6     6-10 years       Floor - Wood     2nd Floor     12     EA     7     10+ years       Walls - Plaster/Drywall     2nd Floor     132     SF     6     10+ years       Walls - Plaster/Drywall     2nd Floor     1,132     SF     6     10+ years       Classroom     1     EA     7     6-10 years       Ceiling - Lay-in     2nd Floor     78     SF     6     6-10 years       Doors - Wood Doors inclu hw     2nd Floor     72     SF     6     6-10 years       Doors - Wood Doors inclu hw     2nd Floor     12     EA     5		Ceiling - Plaster/Drywall	2nd Floor	724		6	6-10 years		
Doors - Wood Doors inclu hw     2nd Floor     1     EA     6     6-10 years       Lighting - Pendent/Surface     2nd Floor     12     EA     7     10+ years       Walls - Plaster/Drywall     2nd Floor     12     EA     7     6-10 years       Walls - Plaster/Drywall     2nd Floor     1     EA     7     6-10 years       Classroom #206 (Regular Classroom)       EA     7     6-10 years       Classroom #206 (Regular Classroom)       EA     7     6-10 years       Casework     2nd Floor     1     EA     7     6-10 years       Ceiling - Lay-in     2nd Floor     8     LF     6     6-10 years       Doors - Transom Window     2nd Floor     18     SF     6     6-10 years       Doors - Wood Doors inclu hw     2nd Floor     12     EA     6     6-10 years       Liphting - Lay-in     2nd Floor     12     EA     5     2-5 years       Marker Board     2nd Floor     12     EA     5     2-5 years			2nd Floor	9	SF	7			
Floor - Wood2nd Floor724SF66 - 10 yearsLighting - Pendent/Surface2nd Floor12F710- yearsWalls - Plaster/Drywall2nd Floor11.132SF610- yearsClassroom#206 (Regular Classroom)Classroom#206 (Regular Classroom)A C Units2nd Floor1EA76-10 yearsCasework2nd Floor1EA76-10 yearsCeiling - Lay-in2nd Floor708SF66-10 yearsDoors - Transom Window2nd Floor708SF66-10 yearsDoors - Vood2 EA66-10 yearsDoors - Vood2nd Floor12EA66-10 yearsDoors - Vood2nd Floor724SF610- yearsDoors - Vood2nd Floor12EA66-10 yearsDoors - Wood2nd Floor724SF610- yearsLighting - Lay-in2nd Floor12EA52-5 yearsMarker Board2nd Floor12EA52-5 yearsWalls - Plaster/Drywall2nd Floor1EA76-10 yearsClassroom #207 (CulinaryA C Units2nd Floor1EA76-10 yearsClassroom #207 (Culinary)Classro		Doors - Wood Doors inclu hw	2nd Floor	1	EA	6			
Lighting - Pendent/Surface Walls - Plaster/Drywall2nd Floor12EA710+ ýearsWireless System2nd Floor1EA76-10 yearsClassroom#206 (Regular Classroom)Classroom#206 (Regular Classroom)Cale Floor1EA7666Colspan="4">Colspan="4">Classroom#200 (Classroom)Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4">Colspan="4"Colspan="4">Colsp		Floor - Wood	2nd Floor	724	SF	6			
Walts - Plaster/Drywall Wireless System2nd Floor1,132SF610+ ýearsClassroom #206 (Regular Classroom)		Lighting - Pendent/Surface		12					
Wireless System2nd Floor1EA76-10 yearsClassroom #206 (Regular Classroom)AC Units2nd Floor1EA76-10 yearsCasework2nd Floor8LF66-10 yearsCeiling - Lay-in2nd Floor16SF66-10 yearsCoiling - Lay-in2nd Floor708SF66-10 yearsDoors - Transom Window2nd Floor72EA66-10 yearsDoors - Transom Wood2nd Floor724SF610 yearsDoors - Wood Doors inclu hw2nd Floor724SF610 yearsDoors - Wood Doors inclu hw2nd Floor724SF610 yearsLighting - Lay-in2nd Floor724SF66-10 yearsMarker Board2nd Floor1EA76-10 yearsWalls - Plaster/Drywall2nd Floor1EA76-10 yearsClassroom #207 (Culinary)					SF	6			
AC Units2nd Floor1EA76-10 yearsCasework2nd Floor8LF66-10 yearsCeiling - Lay-in2nd Floor16SF66-10 yearsDoors - Transom Window2nd Floor708SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor18SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsLighting - Lay-in2nd Floor724SF610- yearsKer Board2nd Floor12EA52-5 yearsWalls - Plaster/Drywall2nd Floor1EA76-10 yearsClassroom #207 (Culinary)2nd Floor1EA76-10 yearsClassroom #207 (Culinary)2nd Floor1EA76-10 yearsClassroom #207 (Culinary)2nd Floor1EA76-10 yearsClassroom #207 (Culinary)2nd Floor1EA76-10 yearsCulinary Exhaust Hood - Type I2nd Floor1EA66-10 yearsCulinary Kitchen Equipment2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsCulinary Kitchen Equipment2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 years <td></td> <td></td> <td>2nd Floor</td> <td></td> <td></td> <td></td> <td></td> <td></td>			2nd Floor						
AC Units2nd Floor1EA76-10 yearsCasework2nd Floor8LF66-10 yearsCeiling - Lay-in2nd Floor16SF66-10 yearsDoors - Transom Window2nd Floor708SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor18SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsLighting - Lay-in2nd Floor724SF610- yearsKer Board2nd Floor12EA52-5 yearsWalls - Plaster/Drywall2nd Floor1EA76-10 yearsClassroom #207 (Culinary)2nd Floor1EA76-10 yearsClassroom #207 (Culinary)2nd Floor1EA76-10 yearsClassroom #207 (Culinary)2nd Floor1EA76-10 yearsClassroom #207 (Culinary)2nd Floor1EA76-10 yearsCulinary Exhaust Hood - Type I2nd Floor1EA66-10 yearsCulinary Kitchen Equipment2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsCulinary Kitchen Equipment2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 years <td>Classroo</td> <td>om #206 (Regular Classroom)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Classroo	om #206 (Regular Classroom)							
Casework2nd Floor8LF66-10 yearsCeiling - Lay-in2nd Floor16SF66-10 yearsDoors - Transom Window2nd Floor708SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsDoors - Wood Doors inclu hw2nd Floor724SF6610 yearsLighting - Lay-in2nd Floor12EA52-5 yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor1EA76-10 yearsClassroom #207 (Culinary)2nd Floor1EA76-10 yearsCasework2nd Floor30LF66-10 yearsCasework2nd Floor1EA76-10 yearsCulinary Kithaust Hood - Type I2nd Floor1EA66-10 yearsCulinary Kithaust Hood - Type I2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor2EA710+ years <td></td> <td></td> <td>2nd Floor</td> <td>1</td> <td>ΕA</td> <td>7</td> <td>6-10 years</td> <td></td>			2nd Floor	1	ΕA	7	6-10 years		
Ceiling - Lay-in2nd Floor16SF66-10 yearsCeiling - Lay-in2nd Floor708SF66-10 yearsDoors - Transom Window2nd Floor18SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsDoors - Vood2nd Floor2EA66-10 yearsFloor - Wood2nd Floor724SF610-yearsKiphing - Lay-in2nd Floor12EA52-5 yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor1,132SF66-10 yearsClassroom #207 (CulinaryClassroom #207 (CulinaryClassroom #207 (CulinaryClassroom #101EA76-10 yearsCulinary Exhaust Hood - Type I2nd Floor1EA76-10 yearsCulinary Exhaust Hood - Type I2nd Floor1EA66-10 yearsCulinary Kitchen Equipment2nd Floor1EA66-10 yearsCulinary Kitchen Equipment2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor2EA66-10 yearsDoors - T									
Ceiling - Lay-in2nd Floor708SF66-10 yearsDoors - Transom Window2nd Floor18SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsFloor - Wood2nd Floor724SF610+ yearsLighting - Lay-in2nd Floor12EA52-5 yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor1,132SF66-10 yearsClassroom #207 (Culinary)Classroom #207 (Culinary)A C Units2nd Floor1EA7666Classroom #207 (Culinary)A floor1EA76Classroom #207 (Culinary)A floor <td co<="" td=""><td></td><td></td><td></td><td></td><td></td><td>-</td><td></td><td></td></td>	<td></td> <td></td> <td></td> <td></td> <td></td> <td>-</td> <td></td> <td></td>						-		
Doors - Transom Window2nd Floor18SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsFloor - Wood2nd Floor724SF610 + yearsLighting - Lay-in2nd Floor12EA52-5 yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor6LF76-10 yearsClassroom #207 (Cullinary)Classroom #207 (Cullinary)A C Units2 nd Floor1EAClassroom #207 (CullinaryClassroom #207 (Cullinary)A C Units2 nd Floor1EAClassroom #207 (CullinaryClassroom #207 (CullinaryClassroom #207 (CullinaryClassroom #207 (CullinaryClassroom #207 (Cullinary <td< td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>									
Doors - Wood Doors inclu hw2nd Floor2EA66-10 yearsFloor - Wood2nd Floor724SF610+ yearsLighting - Lay-in2nd Floor12EA52-5 yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor1,132SF66-10 yearsClassroom #207 (Culinary)Classroom #207 (CulinaryAC Units2nd Floor1EA66Culinary Exhaust Hood - Type I2nd Floor1EA666Culinary Exhaust Hood - Type I2nd Floor1EA666Culinary Exhaust Hood - Type I2nd Floor9 <td col<="" td=""><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td>	<td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>								
Floor - Wood2nd Floor724SF610+ yearsLighting - Lay-in2nd Floor12EA52-5 yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor1,132SF66-10 yearsClassroom #207 (Culinary)Classroom #207 (Culinary)AC Units2nd Floor1EA766Clainary Kitchen Equipment2nd Floor1EA66Colspan="4">Culinary Kitchen Equipment2nd Floor1EA66Colspan="4">66Classroom Window2nd Floor1EA666Colspan="4">Classroom Window2nd Floor9 <t< td=""><td></td><td></td><td></td><td></td><td></td><td>-</td><td>•</td><td></td></t<>						-	•		
Lighting - Lay-in2nd Floor12EA52-5 yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor1,132SF66-10 yearsClassroom #207 (Culinary)Classroom #207 (Culinary)AC Units2nd Floor1EA76-10 yearsCasework2nd Floor1EA76-10 yearsCeiling - Lay-in2nd Floor1EA66-10 yearsCulinary Exhaust Hood - Type I2nd Floor1EA66-10 yearsCulinary Kitchen Equipment2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor2EA66-10 yearsLighting - Lay-in2nd Floor2EA710+ yearsMarker Board </td <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>									
Marker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor1,132SF66-10 yearsClassroom #207 (Culinary)AC Units2nd Floor1EA76-10 yearsCasework2nd Floor30LF66-10 yearsCasework2nd Floor30LF66-10 yearsCeiling - Lay-in2nd Floor1,416SF66-10 yearsCulinary Exhaust Hood - Type I2nd Floor1EA66-10 yearsCulinary Kitchen Equipment2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1,416SF610+ yearsLighting - Lay-in2nd Floor23EA710+ yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years						-			
Walls - Plaster/Drywall2nd Floor1,132SF66-10 yearsClassroom #207 (Culinary)AC Units2nd Floor1EA76-10 yearsCasework2nd Floor30LF66-10 yearsCeiling - Lay-in2nd Floor1,416SF66-10 yearsCulinary Exhaust Hood - Type I2nd Floor1EA66-10 yearsCulinary Kitchen Equipment2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor2EA66-10 yearsDoors - Tile Ceramic/ Porcelain2nd Floor2EA66-10 yearsLighting - Lay-in2nd Floor23EA710+ yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years									
AC Units2nd Floor1EA76-10 yearsCasework2nd Floor30LF66-10 yearsCeiling - Lay-in2nd Floor1,416SF66-10 yearsCulinary Exhaust Hood - Type I2nd Floor1EA66-10 yearsCulinary Kitchen Equipment2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor2EA66-10 yearsDoors - Transom Window2nd Floor2EA66-10 yearsDoors - Transom Window2nd Floor2EA66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1,416SF610+ yearsLighting - Lay-in2nd Floor23EA710+ yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years				-					
AC Units2nd Floor1EA76-10 yearsCasework2nd Floor30LF66-10 yearsCeiling - Lay-in2nd Floor1,416SF66-10 yearsCulinary Exhaust Hood - Type I2nd Floor1EA66-10 yearsCulinary Kitchen Equipment2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor2EA66-10 yearsDoors - Transom Window2nd Floor2EA710+ yearsHore - Tile Ceramic/ Porcelain2nd Floor23EA710+ yearsLighting - Lay-in2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years	Classroo	om #207 (Culinary)							
Casework2nd Floor30LF66-10 yearsCeiling - Lay-in2nd Floor1,416SF66-10 yearsCulinary Exhaust Hood - Type I2nd Floor1EA66-10 yearsCulinary Kitchen Equipment2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor2EA66-10 yearsDoors - Transom Window2nd Floor2EA66-10 yearsDoors - Transom Window2nd Floor2EA66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1,416SF610+ yearsLighting - Lay-in2nd Floor23EA710+ yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years			2nd Floor	1	FA	7	6-10 years		
Ceiling - Lay-in2nd Floor1,416SF66-10 yearsCulinary Exhaust Hood - Type I2nd Floor1EA66-10 yearsCulinary Kitchen Equipment2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1,416SF610+ yearsLighting - Lay-in2nd Floor23EA710+ yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years									
Culinary Exhaust Hood - Type I2nd Floor1EA66-10 yearsCulinary Kitchen Equipment2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1,416SF610+ yearsLighting - Lay-in2nd Floor23EA710+ yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years									
Culinary Kitchen Equipment2nd Floor1EA66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1,416SF610+ yearsLighting - Lay-in2nd Floor23EA710+ yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years						-			
Doors - Transom Window2nd Floor9SF66-10 yearsDoors - Transom Window2nd Floor9SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1,416SF610+ yearsLighting - Lay-in2nd Floor23EA710+ yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years				•					
Doors - Transom Window2nd Floor9SF66-10 yearsDoors - Wood Doors inclu hw2nd Floor2EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1,416SF610+ yearsLighting - Lay-in2nd Floor23EA710+ yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years		· · ·		=		-			
Doors - Wood Doors inclu hw2nd Floor2EA66-10 yearsFloor - Tile Ceramic/ Porcelain2nd Floor1,416SF610+ yearsLighting - Lay-in2nd Floor23EA710+ yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years						-			
Floor - Tile Ceramic/ Porcelain2nd Floor1,416SF610+ yearsLighting - Lay-in2nd Floor23EA710+ yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years						-			
Lighting - Lay-in2nd Floor23EA710+ yearsMarker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years						-			
Marker Board2nd Floor6LF76-10 yearsWalls - Plaster/Drywall2nd Floor2,032SF610+ years									
Walls - Plaster/Drywall2nd Floor2,032SF610+ years									
Work Sills 210 Floor 4 EA 7 10+ years		Work Sink					-		
		VVUIR SIIIK		4	EA	1	iu+ years		



Catego	ry : Classroom		B	uilding			
	.,		_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroo	om #208 (Computer Lab)						
	AC Units	2nd Floor	4	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	10+ years	
	Chalk Board	2nd Floor	6	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒA	6	6-10 years	
	Floor - Wood	2nd Floor	724	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	ĒA	7	10+ years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Jassroo	m #209A (Office) AC Units	2nd Floor	A	EA	7	6-10 years	
		2nd Floor 2nd Floor	1				
	Casework	2nd Floor 2nd Floor	6	SF	6	6-10 years	
	Ceiling - Plaster/Drywall Doors - Transom Window		508	SF	6	10+ years	
		2nd Floor	9 1	EA	6	10+ years	
	Doors - Wood Doors inclu hw Floor - Wood	2nd Floor 2nd Floor		SF	6	10+ years	
		2nd Floor 2nd Floor	508		7	10+ years	
	Lighting - Pendent/Surface		8	EA LF	7	10+ years	
	Marker Board Walls - Plaster/Drywall	2nd Floor 2nd Floor	6 1,035	SF	7 6	6-10 years 10+ years	
	Walls - Flastel/Drywall	2110 F1001	1,035	SF	0	TO+ years	
lassroo	m #209B (Other Instructional Use)	- ·					
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	508	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	508	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,035	55	6	10+ years	
lassroc	m #210 (Vacant)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	4	LF	6	6-10 years	
	Casework	2nd Floor	4	LF	5	1-2 years	Broken glass and missing drawe
	Ceiling - Lay-in	2nd Floor	700	SF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	24	SF	4	1-2 years	Damaged tiles
	Chalk Board	2nd Floor	27	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	



)	Schools					2935 W Polk STREET, Chicago, IL 6061	
Category : Classroom		В	uilding				
			• • • •			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	724	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	6	10+ years	
lassroc	m #212 (Computer Lab)						
	Casework	2nd Floor	14	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	10+ years	
	Chalk Board	2nd Floor	2	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	724	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	10	ĒA	6	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	6	10+ years	
	Wireless System	2nd Floor	1,102	EA	7	6-10 years	
	Work Sink	2nd Floor	1	EA	5	1-2 years	Sink missing faucet and hardware
		21011001	·	LA	0		
lassroc	m #213 (Computer Lab)	- · · -·			_		
	AC Units	2nd Floor	4	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	1,053	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Carpet	2nd Floor	1,053	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,474	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
lassroc	m #214 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Lay-in	2nd Floor	700	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	24	SF	4	0-1 year	Water damaged or broken tiles.
	Chalk Board	2nd Floor	24 30	LF	4	2-5 years	water damaged of broken tiles.
	Doors - Transom Window	2nd Floor	18	SF	4 6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	•	
				SF	-	6-10 years	
	Floor - Wood	2nd Floor	724		6	6-10 years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	



							2935 W Polk STREET, Chicago, IL 60612
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,129	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	1-2 years	Hole in wall
Classroc	om #215 (Culinary)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Lay-in	2nd Floor	902	SF	6	6-10 years	
	Culinary Kitchen Equipment	2nd Floor	1	EA	6	6-10 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Tile	2nd Floor	632	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	270	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,621	SF	6	10+ years	
	Work Sink	2nd Floor	2	EA	7	6-10 years	
Classroc	m #216 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Tile	2nd Floor	719	SF	7	10+ years	
	Floor - Tile	2nd Floor	5	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	2nd Floor	16	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	6	10+ years	
Classroc	m #218 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	10+ years	
	Chalk Board	2nd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years	
	Floor - Wood	2nd Floor	724	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	6	10+ years	
Classroc	m #220 (Regular Classroom)						
	Casework	2nd Floor	8	LF	6	6-10 years	
			0		0		



	Schools						2935 W Polk STREET, Chicago, IL 60612		
Catego	ry : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	10+ years			
	Chalk Board	2nd Floor	15	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	18	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years			
	Floor - Wood	2nd Floor	724	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years			
	Marker Board	2nd Floor	8	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	6	10+ years			
Classroc	om #222 (Store Room)								
	Casework	2nd Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	10+ years			
	Chalk Board	2nd Floor	20	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years			
	Floor - Wood	2nd Floor	724	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years			
	Marker Board	2nd Floor	8	LF	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	6	10+ years			
Classroc	om #223 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	18	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years			
	Floor - Wood	2nd Floor	724	SF	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	10+ years			
	Marker Board	2nd Floor	24	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	6	10+ years			
	om #227 (Regular Classroom)								
วเขออเป็น	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8		6	6-10 years			
	Casework Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	6-10 years			
	Chalk Board	2nd Floor	30	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor 2nd Floor		SF	4 6				
					-	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years			
	Floor - Wood	2nd Floor	724	SF	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	10+ years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	6	10+ years			



,	2935 W Polk STREET, Chicago, IL 60612	

Category : Classroom			Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
0									
Classroo	om #229 (Regular Classroom)					0.40			
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	10+ years			
	Chalk Board	2nd Floor	15	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years			
	Floor - Wood	2nd Floor	724	SF	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years			
	Marker Board	2nd Floor	4	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	6	10+ years			
Classes									
	om #231 (Regular Classroom) AC Units	2nd Floor	A	Ε ^	7	6 10 10000			
			1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	10+ years			
	Chalk Board	2nd Floor	10	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	18	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years			
	Floor - Wood	2nd Floor	724	SF	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	10	EA	6	10+ years			
	Marker Board	2nd Floor	20	LF	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,132	SF	6	10+ years			
Classro	om #233 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	6-10 years			
	Chalk Board	2nd Floor	15	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	18	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	6-10 years			
	Floor - Wood	2nd Floor	724	SF	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	10+ years			
	Marker Board	2nd Floor	10	LF	6	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,129	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	1-2 years	Hole in wall		
Classroo	om #235 (Regular Classroom)				_				
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	10+ years			



Category : Classroom			Building : Main				2955 W FUR STREET, Chicago, IE 00012		
				J		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Chalk Board	2nd Floor	12	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years			
	Floor - Wood	2nd Floor	724	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	6-10 years			
	Marker Board	2nd Floor	12	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,129	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	1-2 years	Hole in wall		
Classroo	om #237 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	724	SF	6	10+ years			
	Chalk Board	2nd Floor	48	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years			
	Floor - Wood	2nd Floor	724	SF	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor	10	EA	7	10+ years			
	Marker Board	2nd Floor	10	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,129	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	3	SF	5	1-2 years	Hole in wall		
	walls i lastel/Drywall	21011001	5	01	0	1 2 years			
Classroo	om #300 (Vacant)								
	Casework	3rd Floor	8	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	817	SF	6	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	5	0-1 year	Water damage		
	Chalk Board	3rd Floor	3	LF	4	2-5 years			
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years			
	Floor - Wood	3rd Floor	822	SF	7	6-10 years			
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years			
	Marker Board	3rd Floor	10	LF	6	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	1,298	SF	6	6-10 years			
	Work Sink	3rd Floor	, 1	EA	7	6-10 years			
Classroo	om #301 (Regular Classroom)								
	Casework	1st Floor	10	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	822	SF	6	6-10 years			
	Chalk Board	1st Floor	10	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Wood	1st Floor	822	SF	7	6-10 years	Newly refinished		
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years			
			0	_/ \	,	e le yourd			



Category : Classroom			В	uilding			
	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,208	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	100	SF	4	0-1 year	Water damage
	Work Sink	1st Floor	1	EA	7	6-10 years	sink functioning well; needs cleanin
lassroo	m #302 (Science Lab Level 2)						
	AC Units	3rd Floor	1	EA	7	6-10 years	AC unit in good condition
	Casework	3rd Floor	20	LF	6	6-10 years	-
	Ceiling - Plaster/Drywall	3rd Floor	1,118	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	C
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,128	SF	7	6-10 years	
	Gas Line	3rd Floor	7	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,048	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	6	SF	4	0-1 year	Water damage
	Work Sink	3rd Floor	7	EA	7	6-10 years	
lassroc	m #302B (Store Room)						
	Casework	3rd Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	367	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	367	SF	5	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	1-2 years	Cover missing
	Walls - Plaster/Drywall	3rd Floor	1,006	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	6	SF	5	0-1 year	Hole in wall
	Walls - Plaster/Drywall	3rd Floor	12	SF	4	0-1 year	Water damage
lassroc	m #304 (Other Instructional Use)						
	Ceiling - Plaster/Drywall	3rd Floor	822	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	7	EA	7	10+ years	
	Floor - Tile	3rd Floor	822	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	ĒA	7	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,308	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
lassroo	m #305 (Regular Classroom)						
	Casework	1st Floor	4	LF	6	6-10 years	



Category : Classroom			В				
J				U		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	822	SF	7	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	822	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	6	6-10 years	
	Storage/ Closet	1st Floor	15	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,455	SF	7	10+ years	
Classro	om #307 (Science Lab Level 2)						
	AC Units	3rd Floor	1	EA	7	6-10 years	Ac unit in good condition
	Casework	3rd Floor	80	LF	6	6-10 years	3
	Ceiling - Plaster/Drywall	3rd Floor	1,254	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,254	SF	7	6-10 years	
	Gas Line	3rd Floor	7	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	22	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,996	SF	6	10+ years	
	Work Sink	3rd Floor	7	EA	7	6-10 years	Work sinks in good condition
Classro	om #308 (Health)						
	Casework	3rd Floor	15	LF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	822	SF	7	6-10 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
	Floor - Tile	3rd Floor	822	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	8	ĒA	6	6-10 years	Relamp 3 fixtures
	Storage/ Closet	3rd Floor	62	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,450	SF	7	10+ years	
	Work Sink	3rd Floor	2	EA	7	6-10 years	Currently in good condition
Classro	om #309 (Vacant)						
	Casework	3rd Floor	4	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	822	SF	7	6-10 years	
	Chalk Board	3rd Floor		LF	4	2-5 years	
	Doors - Wood Doors inclu bw	3rd Floor	2		7	$10 \pm v_{0}$	

(	Jasework	3rd Floor	4	LF	6	6-10 years	
(	Ceiling - Plaster/Drywall	3rd Floor	822	SF	7	6-10 years	
(	Chalk Board	3rd Floor	1	LF	4	2-5 years	
I	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
I	Floor - Wood	3rd Floor	822	SF	7	6-10 years	
l	ighting - Pendent/Surface	3rd Floor	9	EA	6	6-10 years	Cover hanging on 1 fixture
l	ighting - Pendent/Surface	3rd Floor	1	EA	5	1-2 years	Missing cover and Relamp fixture
I	Aarker Board	3rd Floor	20	LF	7	6-10 years	



Catego	ry : Classroom	B	uilding	: Main			
3				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	1,455	SF	6	10+ years	
Classroo	om #310 (Science Lab Level 1)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	85	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,249	SF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	5	SF	4	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	18	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	6-10 years	
	Eye Wash Station	3rd Floor	1	EA	7	6-10 years	
	Floor - Tile	3rd Floor	1,254	SF	7	6-10 years	
	Gas Line	3rd Floor	40	EA	7	10+ vears	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	7	6-10 years	
	Science Lab Shower	3rd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,991	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Water damage
	Work Sink	3rd Floor	11	EA	7	6-10 years	
Classroo	om #312 (Store Room)						
	Casework	3rd Floor	28	LF	4	1-2 years	Shelving/cabinet unit badly damaged
	Ceiling - Plaster/Drywall	3rd Floor	802	SF	6	6-10 years	chorning, cashiot and sadiy damage
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	822	SF	4	0-1 year	The majority of the floor is not visible
			022	01		o i you	a large portion of visible floor is
							damaged (see deficient casement
							photo). Shows signs of water damage
	Lighting - Pendent/Surface	3rd Floor	10	EA	6	6-10 years	Relamp 2 fixtures
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,268	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	40	SF	4	0-1 year	Water damage
	Work Sink	3rd Floor	1	EA	5	2-5 years	trator durhago
						-	
lassroo	om #313 (Store Room)						
	Casework	3rd Floor	36	LF	6	6-10 vears	

Classroom #313 (Store Room)						
Casework	3rd Floor	36	LF	6	6-10 years	
Ceiling - Plaster/Drywall	3rd Floor	808	SF	6	6-10 years	
Ceiling - Plaster/Drywall	3rd Floor	14	SF	4	0-1 year	Water damage
Doors - Transom Window	3rd Floor	18	SF	6	10+ years	C C
Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
Floor - Wood	3rd Floor	822	SF	5	2-5 years	



	Category : Classroom			uilding	: Main		
					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	10	EA	6	6-10 years	Relamp 1 fixture
	Marker Board	3rd Floor	5	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,284	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	12	SF	4	0-1 year	Water damage
	Work Sink	3rd Floor	1	EA	5	1-2 years	Sink not functioning
	Work Sink		I	LA	5	1-2 years	Sink not functioning
lassroo	om #315 (Science Lab Level 1)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	70	LF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	1,249	SF	7	6-10 years	
	Ceiling - Lay-in	3rd Floor	5	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	3
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒA	7	10+ years	
	Eve Wash Station	3rd Floor	- 1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,254	SF	7	6-10 years	
	Gas Line	3rd Floor	7	EA	7	10+ years	
	Lighting - Lay-in	3rd Floor	18	EA	7	6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Science Lab Fume Hood	3rd Floor	1	EA	7	6-10 years	
	Science Lab Shower	3rd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,570	SF	7	10+ years	
	Work Sink	3rd Floor	7	EA	7	6-10 years	
Classroo	om #316 (Other Instructional Use) AC Units	3rd Floor	1	EA	7	6-10 years	
		310 F1001			7 6	6-10 years	
		2rd Floor	0			b-10 years	
	Casework	3rd Floor	8	LF			
	Casework Ceiling - Plaster/Drywall	3rd Floor	724	SF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall Chalk Board	3rd Floor 3rd Floor	724 40	SF LF	6 4	6-10 years 2-5 years	
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window	3rd Floor 3rd Floor 3rd Floor	724 40 18	SF LF SF	6 4 7	6-10 years 2-5 years 10+ years	
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw	3rd Floor 3rd Floor 3rd Floor 3rd Floor	724 40 18 2	SF LF SF EA	6 4 7 7	6-10 years 2-5 years 10+ years 10+ years	
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	724 40 18 2 723	SF LF SF EA SF	6 4 7 7 7	6-10 years 2-5 years 10+ years 10+ years 6-10 years	
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Floor - Wood	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	724 40 18 2 723 1	SF LF SF EA SF SF	6 4 7 7 7 4	6-10 years 2-5 years 10+ years 10+ years 6-10 years 1-2 years	Chipped
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Floor - Wood Lighting - Pendent/Surface	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	724 40 18 2 723 1 10	SF LF SF EA SF EA	6 4 7 7 7 4 6	6-10 years 2-5 years 10+ years 10+ years 6-10 years 1-2 years 6-10 years	Chipped Relamp 4 fixtures
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Floor - Wood Lighting - Pendent/Surface Marker Board	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	724 40 18 2 723 1 10 20	SF LF SF EA SF EA LF	6 4 7 7 4 6 6	6-10 years 2-5 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years	• •
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Floor - Wood Lighting - Pendent/Surface	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	724 40 18 2 723 1 10	SF LF SF EA SF EA	6 4 7 7 7 4 6	6-10 years 2-5 years 10+ years 10+ years 6-10 years 1-2 years 6-10 years	••
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Floor - Wood Lighting - Pendent/Surface Marker Board	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	724 40 18 2 723 1 10 20	SF LF SF EA SF EA LF	6 4 7 7 4 6 6	6-10 years 2-5 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years	• •
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Floor - Wood Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	724 40 18 2 723 1 10 20	SF LF SF EA SF EA SF	6 4 7 7 4 6 6	6-10 years 2-5 years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years	• •
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Floor - Wood Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	724 40 18 2 723 1 10 20 1,132 4	SF LF SF EA SF EA LF	6 4 7 7 4 6 6 6 7	6-10 years 2-5 years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years	••
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall om #317 (Vacant) AC Units Casework	3rd Floor 3rd Floor	724 40 18 2 723 1 10 20 1,132 4 68	SF LF SF EA LF SF EA LF	6 4 7 7 4 6 6 6 7 6	6-10 years 2-5 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	• •
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall om #317 (Vacant) AC Units Casework Ceiling - Exposed	3rd Floor 3rd Floor	724 40 18 2 723 1 10 20 1,132 4 68 800	SF LF SF EA LF SF EA LF SF	6 4 7 7 4 6 6 6 7 6 6	6-10 years 2-5 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Relamp 4 fixtures
	Casework Ceiling - Plaster/Drywall Chalk Board Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall om #317 (Vacant) AC Units Casework	3rd Floor 3rd Floor	724 40 18 2 723 1 10 20 1,132 4 68	SF LF SF EA LF SF EA LF	6 4 7 7 4 6 6 6 7 6	6-10 years 2-5 years 10+ years 6-10 years 6-10 years 6-10 years 10+ years 10+ years 6-10 years 6-10 years 6-10 years	• •



Catego	ry : Classroom		В	uilding	: Main		
J				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,702	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	29	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	5	2-5 years	
	Walls - Plaster/Drywall	3rd Floor	2,436	SF	6	6-10 years	
	Walls - Tile	3rd Floor	800	SF	6	6-10 years	
	Walls - Tile	3rd Floor	6	SF	4	0-1 year	Water damage
Classroo	om #318 (Vacant)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	724	SF	6	6-10 years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	724	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	6	6-10 years	Relamp 3 fixtures
	Marker Board	3rd Floor	30	LA	6	6-10 years	Relating 5 lixtures
	Walls - Plaster/Drywall	3rd Floor	1,132	SF	6	6-10 years	
	Walls - Plastel/Drywall	310 F1001	1,132	ЗГ	0	0-10 years	
Classroo	om #319 (Music Room)						
	Ceiling - Plaster/Drywall	3rd Floor	1,692	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	4	1-2 years	Water damage
	Chalk Board	3rd Floor	30	LF	4	2-5 years	, and the second s
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,702	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	19	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	20	SF	5	2-5 years	
	Walls - Plaster/Drywall	3rd Floor	2,020	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Water damage
Classroo	om #320 (Vacant)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	20	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	724	SF	6	6-10 years	
	Chalk Board	3rd Floor	15	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	724	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,132	SF	6	-	
	vvalis - Flastel/Diywall		1,132	3F	0	6-10 years	



Catego	ategory : Classroom			uilding			
outogo				anang	. main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroo	m #321 (Regular Classroom)						
21000100	AC Units	3rd Floor	3	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,692	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,702	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	33	EA	6	6-10 years	Relamp several fixtures
	Storage/ Closet	3rd Floor	55	SF	7	6-10 years	Relating Several fixtures
	Walls - Plaster/Drywall	3rd Floor	2,030	SF	6	10+ years	
		314 1 1001	2,030	51	0	TOF years	
lassroo	m #322 (Office)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	724	SF	6	6-10 years	
	Chalk Board	3rd Floor	30	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years	
	Floor - Wood	3rd Floor	724	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	5	LF	6	2-5 years	
	Walls - Plaster/Drywall	3rd Floor	1,132	SF	6	10+ years	
	······		.,		-	, e e e e e e e e e e e e e e e e e e e	
lassroo	m #323 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	4	SF	5	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	č
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	724	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	ĒA	6	6-10 years	Relamp 3 fixtures
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,132	SF	6	10+ years	
						-	
lassroo	m #324 (Fitness Room)						
	Ceiling - Plaster/Drywall	3rd Floor	1,400	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	60	SF	4	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood Floor - Wood	3rd Floor 3rd Floor	1,450	SF SF	6	6-10 years 1-2 years	



<u> </u>	Schools						2935 W Polk STREET, Chicago, IL 6061
Catego	ry : Classroom		В	uilding	: Main		
_			-			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	31	EA	6	6-10 years	Relamp 1 fixture
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	1-2 years	Fixture wiring is exposed
	Storage/ Closet	3rd Floor	150	SF	5	2-5 years	
	Walls - Plaster/Drywall	3rd Floor	890	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Water damage
	Walls - Structural Glazed Tile	3rd Floor	890	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	10	SF	5	1-2 years	Major cracks
lassroo	om #325 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	722	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	2	SF	5	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	724	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,132	SF	6	6-10 years	
	Wallo Thatan Diywall		1,102	01	Ũ	o ro youro	
lassroo	om #327 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	724	SF	6	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	724	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	6	6-10 years	Relamp 1 fixture
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,132	SF	6	6-10 years	
lassroo	om #329 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	724	SF	6	6-10 years	
	Chalk Board	3rd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	724	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	6	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,132	SF	6	6-10 years	
	vvalis - Flastel/Diywall		1,132	3F	U	0-10 years	



Category : Classroom

				2935 W Polk STREET, Chicago, IL 60612
В	uilding	: Main		
ntity	UOM	Rank	Recommend Replacement	Comments
1	EA	7	6-10 years	

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #331 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	724	SF	6	6-10 years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	6-10 years	
	Doors - Transom Window	3rd Floor	9	SF	5	0-1 year	Cracked glass
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	5
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Wood	3rd Floor	724	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	6	6-10 years	Relamp 1 fixture
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,132	SF	6	6-10 years	
Classroo	om #333 (Vacant)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	724	SF	6	6-10 years	
	Chalk Board	3rd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	724	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	6	6-10 years	Relamp 2 fixtures
	Marker Board	3rd Floor	6	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,132	SF	6	6-10 years	
Classroo	om #335 (Store Room)						
_01033100	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	4	SF	5	1-2 years	Water damage
	Chalk Board	3rd Floor	20	LF	4	2-5 years	Water damage
	Doors - Transom Window	3rd Floor	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	724	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,124	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4	SF	5	1-2 years	Water damage
Closerer	m #227 (Storp Boom)						
	om #337 (Store Room) Casework	2rd Floor	0	LF	E	6 10 10000	
		3rd Floor	8		6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	722	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	2	SF	5	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	



Catego	ry : Classroom	Building : Main					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	3rd Floor	724	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,124	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4	SF	4	0-1 year	Water damage

<b>Category :</b>	Interior
-------------------	----------

Catego	Category : Interior			uilding			
0	Hanna Tama	Landan	0		David	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor	Coiling Blooter/Dravell	1 at Elear	10.044	SF	6	10	
	Ceiling - Plaster/Drywall Doors - Wood Doors include hw	1st Floor 1st Floor	10,044 12	EA	6 6	10+ years 6-10 years	
	Drinking Fountains - Single Water Cooler	1st Floor	5	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	1,196	SF	6	6-10 years	
	Floor - Terrazzo	1st Floor	70	SF	4	0-1 year	Cracking.
	Floor - Tile/Sheet	1st Floor	8,778	SF	4	6-10 years	Cracking.
	Lighting - Pendent/Surface	1st Floor	125	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	125	EA	5	1-2 years	Refurbish assembly
	Stairs - Terrazzo	1st Floor	6	LF	6	6-10 years	Relubish assembly
	Student Lockers - One Tier	1st Floor	552	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	7,793	SF	6	•	
	Walls - Structural Glazed Tile	1st Floor	11,587	SF	6	10+ years 10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	9,890	SF	6	•	
	Doors - Wood Doors include hw	2nd Floor 2nd Floor	9,890	EA	6	10+ years 10+ years	
	Drinking Fountains - Single Fountain	2nd Floor 2nd Floor	2	EA	7		
	Drinking Fountains - Single Pountain	2nd Floor 2nd Floor	6	EA	7	6-10 years 6-10 years	
	Floor - Terrazzo	2nd Floor 2nd Floor	1,112	SF	6	10+ years	
	Floor - Tile/Sheet	2nd Floor 2nd Floor	8,778	SF	7		
		2nd Floor 2nd Floor	0,778	EA	7	10+ years	
	Lighting - Lay-in Lighting - Pendent/Surface	2nd Floor 2nd Floor	88	EA	7	10+ years 10+ years	
	Student Lockers - One Tier	2nd Floor 2nd Floor	569	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	7,496	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor 2nd Floor	9,942	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	9,890	SF	6	10+ years	
	Doors - Wood Doors include hw	3rd Floor	9,090	EA	6	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	2 8	EA	7	6-10 years	
	Floor - Terrazzo	3rd Floor	1,112	SF	6	10+ years	
	Floor - Tile/Sheet	3rd Floor	8,778	SF	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	89	EA	6	6-10 years	
	Student Lockers - One Tier	3rd Floor	557	EA	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	7,496	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	9,942	SF	6	10+ years	
	wais - Structural Glazeu Tile	310 F1001	9,942	ЗГ	U	iu+ years	

Safety



Catego	ry : Interior			uilding	• Main		
Jaiego				unung	. main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Toup	Camera Viewing Station	1st Floor	1	EA	7	6-10 years	
	Metal Detector	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	60	EA	7	6-10 years	
			00	<b>L</b> /(		o ro youro	
tairs							
	Ceiling - Plaster/Drywall	Auditorium stairs	715	SF	6	6-10 years	
	Floor - Terrazzo	Auditorium stairs	631	SF	6	6-10 years	
	Floor - Terrazzo	Auditorium stairs	1	SF	5	1-2 years	Cracked floor
	Handrails	Auditorium stairs	42	LF	7	10+ years	
	Lighting - Pendent/Surface	Auditorium stairs	2	EA	5	6-10 years	Covers missing
	Stairs - Terrazzo	Auditorium stairs	24	LF	6	6-10 years	
	Walls - Concrete Block	Auditorium stairs	24	SF	6	6-10 years	
	Walls - Plaster/Drywall	Auditorium stairs	2,003	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Gym	1,200	SF	6	10+ years	
	Floor - Terrazzo	Gym	1,200	SF	6	10+ years	
	Handrails	Gym	60	LF	7	10+ years	
	Lighting - Pendent/Surface	Gym	14	EA	6	10+ years	Relamp 2 fixtures
	Stairs - Terrazzo	Gym	42	LF	6	10+ years	·
	Walls - Plaster/Drywall	Gym	1,500	SF	6	10+ years	
	Walls - Structural Glazed Tile	Gym	1,226	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North	672	SF	6	6-10 years	
	Floor - Terrazzo	North	288	SF	6	6-10 years	
	Handrails	North	110	LF	7	10+ years	
	Lighting - Pendent/Surface	North	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	North	4	EA	6	6-10 years	
	Stairs - Terrazzo	North	54	LF	6	10+ years	
	Walls - Plaster/Drywall	North	1,110	SF	6	6-10 years	
	Walls - Plaster/Drywall	North	12	SF	5	0-1 year	Water damage
	Walls - Plaster/Drywall	North	800	SF	5	10+ years	Paint is peeling
	Walls - Structural Glazed Tile	North	940	SF	6	10+ years	i antio pooning
	Ceiling - Plaster/Drywall	North East	416	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North East	200	SF	4	0-1 year	Extensive water damage
	Floor - Terrazzo	North East	566	SF	6	10+ years	
	Floor - Terrazzo	North East	3	SF	4	1-2 years	Cracked floor
	Handrails	North East	106	LF	7	10+ years	
	Lighting - Pendent/Surface	North East	9	EA	5	0-1 year	Lights functioning but missing cove
	Stairs - Terrazzo	North East	9 60	LF	6	10+ years	Lights functioning but missing cove
	Stairs - Terrazzo	North East	1	LF	5	1-2 years	Domogod trood
		North East	1,522	SF	5 6	•	Damaged tread
	Walls - Plaster/Drywall		-	SF	-	10+ years	Extensive water demoge
	Walls - Plaster/Drywall	North East	200		4	0-1 year	Extensive water damage
	Walls - Structural Glazed Tile	North East	730	SF	6	10+ years	Creaked have
	Walls - Structural Glazed Tile	North East	8	SF	5	1-2 years	Cracked base
	Ceiling - Plaster/Drywall	North West	596	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	North West	10	SF	4	0-1 year	Water damage



Catego	Category : Interior		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	North West	544	SF	6	6-10 years	
	Handrails	North West	106	LF	7	10+ years	
	Lighting - Pendent/Surface	North West	3	EA	5	6-10 years	Lights functioning but missing cove
	Stairs - Terrazzo	North West	58	LF	6	10+ years	
	Walls - Plaster/Drywall	North West	1,722	SF	6	6-10 years	
	Walls - Structural Glazed Tile	North West	730	SF	6	6-10 years	
	Walls - Structural Glazed Tile	North West	8	SF	5	1-2 years	Cracks at base
	Ceiling - Plaster/Drywall	South East	616	SF	6	6-10 years	
	Floor - Terrazzo	South East	544	SF	6	6-10 years	
	Handrails	South East	106	LF	7	10+ years	
	Lighting - Pendent/Surface	South East	9	EA	5	6-10 years	Covers missing
	Stairs - Terrazzo	South East	58	LF	6	6-10 years	5
	Walls - Plaster/Drywall	South East	1,222	SF	6	6-10 years	
	Walls - Structural Glazed Tile	South East	736	SF	6	6-10 years	
	Walls - Structural Glazed Tile	South East	2	SF	5	1-2 years	Cracked base
	Ceiling - Plaster/Drywall	South West	616	SF	6	6-10 years	
	Floor - Terrazzo	South West	543	SF	6	6-10 years	
	Floor - Terrazzo	South West	1	SF	4	1-2 years	Cracked floor
	Handrails	South West	106	LF	7	10+ years	
	Lighting - Pendent/Surface	South West	2	EA	7	10+ years	
	Lighting - Pendent/Surface	South West	1	EA	7	6-10 years	Quality upgraded condition is good
	Stairs - Terrazzo	South West	58	LF	6	6-10 years	, , , , , , , , , , , , , , , , , , , ,
	Walls - Plaster/Drywall	South West	1,726	SF	6	6-10 years	
	Walls - Structural Glazed Tile	South West	736	SF	6	6-10 years	
	Walls - Structural Glazed Tile	South West	2	SF	5	1-2 years	Cracked at base; patch work starte
/ertical	Conveyance						
	Elevator - Hydraulic Elevator	North	1	EA	6	6-10 years	



Category : Site			В	uilding	: Site		
_			•			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra							
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	24	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	2	EA	4	1-2 years	Sinking/Quantity changed to match current observations
Fencing							
	Fencing - Chain Link	Entire Site	273	LF	6	6-10 years	
	Fencing - Guard Rail	Entire Site	668	LF	6	10+ years	
	Fencing - Guard Rail	Entire Site	20	LF	4	1-2 years	Bending
	Fencing - New Standard Ornamental	Entire Site	1,183	LF	6	10+ years	C C
Landsca	De						
	Benches	Entire Site	4	EA	6	10+ years	
	Landscape - Grass	Entire Site	10,120	SF	6	10+ years	Quantity changed to match current observations
	Landscape - Hardscape- Concrete	Entire Site	2,586	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	450	SF	4	1-2 years	Extensive cracking by east parking lo
	Landscape - Mulch	Entire Site	7,560	SF	6	6-10 years	Quantity added to reflect that part of the grass is mulch
	Parkway trees	Entire Site	20	EA	6	10+ years	3
	Parkway trees	Entire Site	2	EA	4	0-1 year	Missing
	Planting Beds/ Area	Entire Site	1,600	SF	6	10+ years	3
	Retaining Wall - Concrete	Entire Site	1,581	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	16	SF	4	0-1 year	Missing pieces
	Retaining Wall - Masonry	Entire Site	114	SF	5	6-10 years	micening procee
	Trash Receptacles	Entire Site	1	EA	6	10+ years	
Parking I	ot						
	Concrete Curbs	Parking Lot- East	77	LF	6	6-10 years	
	Concrete Curbs	Parking Lot- East	28	LF	4	0-1 year	Broken
	Surface - Asphalt	Parking Lot- East	20,159	SF	4	0-1 year	Extensive cracking/potholes throughout
	Trash Compactor	Parking Lot- East	1	EA	6	10+ years	
	Trash Enclosure - Chain Links	Parking Lot- East	252	SF	6	10+ years	
	Vehicular Screening	Parking Lot- East	36	LF	6	10+ years	
	Surface - Asphalt	South Courtyard	32,295	SF	4	0-1 year	Extensive cracking/potholes throughout
Sidewalk	s						
	Sidewalks - Internal Walks	Entire Site	200	LF	6	10+ years	



Catego	ry : Site		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Internal Walks	Entire Site	20	LF	4	1-2 years	Extensive cracking
	Sidewalks - Perimeter Sidewalks	Entire Site	29,242	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	100	SF	4	1-2 years	Cracking/sinking
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	10+ years	
	Monument - Sign	Entire Site	1	EA	7	6-10 years	

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

## Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



## Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main			ł						
Carpentry	Laboratory/Shop	1st Floor	114	114	2,700	120	60	N	Ν
Computer Lab	Computer Lab	2nd Floor	213	213	1,053	150	60	N	N
Computer Lab	Regular Classroom	2nd Floor	200	200	861	192	72	N	N
Computer Lab	Regular Classroom	2nd Floor	201	201	1,176	150	60	N	N
Computer Lab	Regular Classroom	2nd Floor	204	204	724	192	72	N	N
Computer Lab	Regular Classroom	2nd Floor	208	208	724	192	72	N	N
Computer Lab	Regular Classroom	2nd Floor	212	212	724	192	72	N	N
Culinary	Culinary	2nd Floor	207	207	1,416	200	50	N	N
Culinary	Culinary	2nd Floor	215	215	902	200	100	N	N
Faculty Lounge	Computer Lab	2nd Floor	202	202	808	192	72	N	N
Faculty Lounge	Regular Classroom	2nd Floor	113	113	840	100	50	N	Ν
Fitness Room	Music Room	3rd Floor	324	324	1,460	150	50	N	N
Health	Art Room	3rd Floor	308	308	822	192	72	N	N
Laboratory/Shop	Laboratory/Shop	1st Floor	112	112	455	38	18	N	N
Music Room	Music Room	3rd Floor	319	319	1,702	90	45	N	N
Office	Regular Classroom	1st Floor	125	125	720	120	60	N	N
Office	Regular Classroom	2nd Floor	209A	209	508	75	30	N	N
Office	Regular Classroom	3rd Floor	322	322	724	192	72	N	N
Other Instructional Use	Art Room	3rd Floor	304	304	822	192	72	N	Ν
Other Instructional Use	Regular Classroom	2nd Floor	209B	209B	508	75	30	N	Ν
Other Instructional Use	Regular Classroom	3rd Floor	316	316	724	192	72	N	N
Regular Classroom	Regular Classroom	1st Floor	301	301	822	192	72	N	N
Regular Classroom	Regular Classroom	1st Floor	305	305	822	192	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	724	192	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	724	192	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	216	216	724	192	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	724	192	72	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	220	220	724	192	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	223	223	724	192	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	227	227	724	192	72	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	229	229	724	192	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	231	231	724	192	72	N	N
Regular Classroom	Regular Classroom	2nd Floor	233	233	724	192	72	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	235	235	724	192	72	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	237	237	724	192	72	N	Ν
Regular Classroom	Regular Classroom	3rd Floor	321	ROTC 321	1,702	90	45	N	Y
Regular Classroom	Regular Classroom	3rd Floor	323	323	724	192	72	N	N
Regular Classroom	Regular Classroom	3rd Floor	325	325	724	192	72	N	N



Vacant

Smart-Board

> Ν Ν

Ν

Ν Ν Ν

Ν

Ν

Ν

Ν

Ν

Ν

Ν

Ν

Ν Ν Ν Ν

Ν

Ν

Ν

Ν

Classroom Summary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop
Regular Classroom	Regular Classroom	3rd Floor	327	327	724	192	72	N
Regular Classroom	Regular Classroom	3rd Floor	329	329	724	192	72	N
Regular Classroom	Regular Classroom	3rd Floor	331	331	724	192	72	N
Science Lab Level 1	Science	3rd Floor	310	310	1,254	320	120	N
Science Lab Level 1	Science	3rd Floor	315	315	1,254	320	120	N
Science Lab Level 2	Science	3rd Floor	302	302	1,128	320	120	N
Science Lab Level 2	Science	3rd Floor	307	307	1,254	320	120	N
Store Room	Other Instructional Use	3rd Floor	302B	302B	367	128	48	N
Store Room	Regular Classroom	1st Floor	111	111	720	120	60	N
Store Room	Regular Classroom	2nd Floor	222	222	724	192	72	N
Store Room	Regular Classroom	3rd Floor	312	312	822	192	72	N
Store Room	Regular Classroom	3rd Floor	313	313	822	192	72	N
Store Room	Regular Classroom	3rd Floor	335	335	724	192	72	N
Store Room	Regular Classroom	3rd Floor	337	337	724	192	72	N
Vacant	Regular Classroom	2nd Floor	210	210	724	192	72	N
Vacant	Regular Classroom	3rd Floor	300	300	822	192	72	N
Vacant	Regular Classroom	3rd Floor	309	309	822	192	72	N
Vacant	Regular Classroom	3rd Floor	317	ROTC 317	1,702	130	45	N
Vacant	Regular Classroom	3rd Floor	318	318	724	192	72	N
Vacant	Regular Classroom	3rd Floor	320	320	724	192	72	N

333

333

192

724

72

3rd Floor

Regular Classroom