

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1929	2	82,739
Annex	1971	2	23,616
Campus Total			106,355

Category : Exterior Building : Main

	y i Exterior		_	anamg		Decemmend	
oup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
rance		Location	Quantity	OOW	Italik	Replacement	Comments
папсе	Entrance Control - Audio and Video	#1 - main entrance - SE	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#1 - main entrance - SE	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 - main entrance - SE	1	EA	6	10+ years	
	Exterior Stairs - Stone	#1 - main entrance - SE	60	LF	7	10+ years	Repaired
	Stair Handrail - Steel_Stair Handrail	#1 - main entrance - SE	8	LF	6	10+ years	rtopanou
	Exterior Doors - Exterior Wood Door	#10 - NE	2	EA	5	6-10 years	
	Exterior Doors - Transom Lite	#10 - NE	1	EΑ	6	10+ years	
	Exterior Stairs - Stone	#10 - NE	48	LF	7	10+ years	Repaired
	Entrance Control - Audio and Video	#11 - N	1	EA	6	10+ years	. 10 pa 0 a
	Exterior Doors - Exterior Steel Door	#11 - N	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#11 - N	1	ΕA	6	10+ years	
	Exterior Stairs - Concrete	#11 - N	12	LF	6	10+ years	
	Power Door Operator and Controls	#11 - N	1	EΑ	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#11 - N	60	LF	6	10+ years	
	Ramps - Concrete	#11 - N	30	LF	5	10+ years	
	Stair Handrail - Steel Stair Handrail	#11 - N	12	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#2 - SE	2	EA	4	1-2 years	Delaminating on doors
	Exterior Doors - Transom Lite	#2 - SE	1	EA	6	10+ years	ŭ
	Exterior Stairs - Stone	#2 - SE	72	LF	5	10+ years	
	Exterior Doors - Exterior Wood Door	#3 - S	2	EA	5	2-5 years	
	Exterior Doors - Transom Lite	#3 - S	1	EA	6	10+ years	
	Exterior Stairs - Stone	#3 - S	44	LF	7	10+ years	
	Exterior Stairs - Stone	#3 - S	6	LF	7	10+ years	Repaired



Catego	ry : Exterior		В	uilding	: Main		., , , , , , , , , , , , , , , , , , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Stairs - Stone	#3 - S	6	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#4 - SW	2	EA	5	2-5 years	
	Exterior Doors - Transom Lite	#4 - SW	1	EA	6	10+ years	
	Ramps - Concrete	#4 - SW	4	LF	5	10+ years	
	Entrance Control - Audio and Video	#5 - SW	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5 - SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 - SW	1	EA	6	10+ years	
	Exterior Stairs - Stone	#5 - SW	7	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#5.5 - W Boiler	1	EA	5	2-5 years	
	Exterior Doors - Transom Lite	#5.5 - W Boiler	1	EA	6	10+ years	
	Exterior Stairs - Stone	#5.5 - W Boiler	3	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#6 - W	2	EA	4	1-2 years	Delaminating, some repairs made
	Exterior Doors - Transom Lite	#6 - W	1	EA	6	10+ years	
	Exterior Stairs - Stone	#6 - W	14	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#7 - NW	1	EA	6	10+ years	
	Exterior Doors - Side lite	#7 - NW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 - NW	1	EA	6	10+ years	
	Exterior Stairs - Steel or Aluminum	#7 - NW	16	LF	6	10+ years	
	Exterior Stairs - Stone	#7 - NW	3	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#7 - NW	12	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#8 - E	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8 - E	1	EA	6	10+ years	
	Exterior Stairs - Stone	#8 - E	4	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	#9 - E	2	EA	5	6-10 years	
	Exterior Doors - Transom Lite	#9 - E	1	EA	6	10+ years	
	Exterior Stairs - Stone	#9 - E	60	LF	5	6-10 years	
	Exterior Doors - Exterior Steel Door	fire escape	1	EA	6	10+ years	
	Exterior Doors - Side lite	fire escape	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	fire escape	1	EA	6	10+ years	
_Fire Esc	ape						
	Exterior Doors - Exterior Steel Door	Façade- NW	1	EA	6	6-10 years	
	Fire Escape	Façade- NW	36	LF	6	6-10 years	
	Paints	Façade- NW	36	LF	5	2-5 years	
Foundati	ion						
_i ounuat	Foundation - Concrete	Entire Building	1,107	LF	7	10+ years	
	Foundation - Concrete	Entire Building Entire Building	230	LF	6	6-10 years	
	Superstructure - Concrete	Entire Building Entire Building	82,024	SF	7	10+ years	
	Superstructure - Concrete	Entire Building	715	SF	6	10+ years	
	Superstructure - Concrete	Littile building	713	01	U	10+ years	
_Lighting							
J	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	6	10+ years	

Campus Name: Mann Page : 2 of 47 Assessment Date: 03/06/2024



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	10+ years	
Roof Sys	stem						
•	Access Ladder - Metal	Boiler house roof	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Boiler house roof	60	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Boiler house roof	20	LF	5	2-5 years	Stepped cracking at top
	Coping - Terra Cotta	Boiler house roof	214	LF	6	10+ years	
	Downspouts - Interior Downspouts	Boiler house roof	18	LF	6	10+ years	
	Parapet - Parapet > 30"	Boiler house roof	214	LF	6	10+ years	
	Roof - Modified Bitumen	Boiler house roof	2,820	SF	7	•	Panairad
						10+ years	Repaired
	Roof Structure - Concrete	Boiler house roof	2,820	SF	7	10+ years	
	Coping - Terra Cotta	Low E roof	42	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low E roof	15	LF	6	10+ years	
	Parapet - 16" - 30" Height	Low E roof	42	LF	6	10+ years	
	Roof - Metal	Low E roof	160	SF	5	10+ years	
	Roof Structure - Concrete	Low E roof	160	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	5	EA	7	10+ years	
	Access Ladder - Wood	Main Roof	1	EA	4	0-1 year	Worn, unstable/ladder is not secured
	Coping - Terra Cotta	Main Roof	1,123	LF	5	6-10 years	vvoin, and abionada is not obtained
	Downspouts - Interior Downspouts	Main Roof	408	LF	6	10+ years	
		Main Roof	90	LF	6		
	Parapet - 16" - 30" Height				-	10+ years	
	Parapet - Parapet > 30"	Main Roof	1,083	LF	6	10+ years	5.11
	Roof - Modified Bitumen	Main Roof	34,009	SF	4	0-1 year	Bubbling, leaks cracks throughout
	Roof Hatch - Metal	Main Roof	5	EA	7	10+ years	
	Roof Structure - Concrete	Main Roof	34,009	SF	7	10+ years	
Walls							
	Cheek-Wall - Stone	Entire Building	72	SF	7	10+ years	Repaired
	Cheek-Wall - Stone	Entire Building	78	SF	6	10+ years	
	Cornice - Terra Cotta	Entire Building	1,337	LF	5	10+ years	
	Exterior Walls - Brick	Entire Building	42,430	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	344	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	1,347	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	1,337	SF	6	10+ years	
Mindo							
Windows	Guard - Guards perforated	Entire Building	3,420	SF	6	10+ years	
	•			LF			
	Lintels - Steel	Entire Building	746	LF LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	150		6	10+ years	
	Windows - Decorative	Entire Building	30	SF	6	10+ years	
	Windows - Sash Aluminum	Entire Building	72	SF	6	10+ years	

Campus Name: Mann Page : 3 of 47 Assessment Date: 03/06/2024



Catego	ry : Exterior		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Windows - Sash Aluminum Double-pane	Entire Building	6,738	SF	6	10+ years	Comments
	Windows - Sash Aluminum Double-pane	Entire Building	748	SF	5	2-5 years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Basement	1	EΑ	4	1-2 years	50 years old, non functional
	Exit Signs - Auditoium	Entire Building	9	EA	2	0-1 year	Quantity changed to match current observations. Location changed for clarification as the auditorium occupies space on multiple floors. Signs have no backup batteries and the school has no emergency generator.
	Exit Signs - Corridors and Stairs	Entire Building	16	EA	2	0-1 year	Signs have no backup batteries and the school has no emergency generator.
	Exit Signs - Gym	Entire Building	6	EA	2	0-1 year	Signs have no backup batteries and the school has no emergency generator. Location changed for clarification as the gym occupies space on multiple floors.
	Exit Signs - Lunchroom	Entire Building	4	EA	2	0-1 year	Quantity changed to match current observations. Signs have no backup batteries and the school has no emergency generator.
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	4,026	SF	4	0-1 year	No backup power
	Emergency A/C Power - Corridors and Stairs	Entire Building	13,816	SF	4	0-1 year	No backup power
	Emergency A/C Power - Lunchrooms	Entire Building	2,585	SF	4	0-1 year	No backup power
	Security System - CCTV	Entire Building	82,739	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	82,379	SF	6	2-5 years	
Main Se	rvice						
	Main Electrical Service - 2000 A 120/208/3PH	Basement	1	EA	4	2-5 years	Antiquated
	Independent Electrical Service for emergency power	Basement	1	EA	6	6-10 years	
	PA System	Entire Building	82,739	SF	5	1-2 years	Serves Main and Annex. PA system employs antiquated technology and operates intermittently.

Campus Name: Mann Page : 4 of 47 Assessment Date: 03/06/2024



Catego	ry : Electrical		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	istribution		444				
OWO: D	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	2-5 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building	1	EA EA	6		
			1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1			6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building		EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Rusting
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	6	6-10 years	Kitchen
	Main Distribution Panels - Less than 400	Entire Building	1	EA	6	6-10 years	
	amp	.				, , , , , , , , , , , , , , , , , , , ,	
atego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
re Alar	m						
	Fire ALarm Anunciator	Entire Building	1	EA	7	10+ years	
	Fire Alarm Panel	Entire Building	1	EA	7	6-10 years	No CPS Asset Tag present.
	Fire Alarm Strobe Lights	Entire Building	82,739	SF	7	10+ years	
	Fire Alarm_System	Entire Building	82,739	SF	7	10+ years	
atego	ry : Mechanical		В	uilding	: Main		
roup	Itom - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Item - Type ling Systems	Location	Quantity	COIVI	IVALIA	Replacement	Comments
штани	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mech. Room - AHU-1	1	EA	5	6-10 years	AHU-1, serves auditorium. No CF Asset Tag present.



Catego	ry : Mechanical	-	В	uilding	: Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	Air Intake	Mech. Room - AHU-1	1	EA	7	10+ years		
	Auxiliaries - 8001 - 15000 cfm	Mech. Room - AHU-1	1	EA	5	6-10 years		
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mech. Room - AHU-1	100	LF	5	6-10 years		
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mech. Room - AHU-2	1	EA	5	6-10 years	AHU-2, serves south sections of Main. No CPS Asset Tag present.	
	Air Intake	Mech. Room - AHU-2	1	EA	7	10+ years	31	
	Auxiliaries - 15001 - 25000 cfm	Mech. Room - AHU-2	1	EA	5	6-10 years		
	Reheat Boxes - Reheat Boxes with Steam Coil	Mech. Room - AHU-2	10	EA	5	6-10 years		
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mech. Room - AHU-2	100	LF	5	6-10 years		
	Zone Dampers	Mech. Room - AHU-2	23	EA	5	6-10 years	Zone dampers are functional though generally require manual adjustment.	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mech. Room - AHU-3	1	EA	5	6-10 years	AHU-3, serves north sections of Main.	
	Air Intake	Mech. Room - AHU-3	1	EA	7	10+ years	Quantity changed as total has been divided/aggregated. Location changed for clarification.	
	Auxiliaries - 15001 - 25000 cfm	Mech. Room - AHU-3	1	EA	5	6-10 years	Quantity changed as total has been divided/aggregated.	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mech. Room - AHU-3	6	EA	5	6-10 years	Quantity changed as total has been divided/aggregated. Location changed for clarification.	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mech. Room - AHU-3	100	LF	5	6-10 years	Quantity changed as total has been divided/aggregated.	
	Zone Dampers	Mech. Room - AHU-3	18	EA	5	6-10 years	Quantity changed as total has been divided/aggregated. Location changed for clarification. Zone dampers are functional though generally they require manual adjustment.	
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mech. Room - AHU-4	1	EA	5	6-10 years	AHU-4, serves gym. No CPS Asset Tag present.	
	Air Intake	Mech. Room - AHU-4	1	EA	7	10+ years	. .	
	Auxiliaries - 8001 - 15000 cfm	Mech. Room - AHU-4	1	EA	5	6-10 years		
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mech. Room - AHU-4	100	LF	5	6-10 years		
_Boiler Sv	estems							
<u></u>	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	5	6-10 years		
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	Priority Rep adjusted based on current observations and per review	

Page : 6 of 47 Campus Name: Mann Assessment Date: 03/06/2024



Catego	ry : Mechanical		В	uilding	: Main		30 0 Ghapper Av ENGE, Ghicago, ile 00017
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	•						with Building Engineer.
	Combustion Dampers	Boiler Room	2	EA	5	6-10 years	
	Feed Water Pumps and Tank Non Condensing, Fire Tube, Seeteh Marine	Boiler Room Boiler Room	1	EA EA	4	2-5 years	Feed water system is well-maintained and leak-free but there are distinct signs of age-related degradation indicating that the system has reached the end of its anticipated service life. B-2
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP		•		5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	6-10 years	B-1
	Piping - Condensate Pipe- Steel	Boiler Room	250	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	250	LF	6	6-10 years	
	Steam Traps	Boiler Room	120	EA	6	6-10 years	Rank, Reason and Priority Rep adjusted based on repairs completed since previous assessment.
_Heating	Devices						
	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations.
	Unit Heater - Electric	Entire Building	1	EA	5	2-5 years	Unit shows signs of age-related degradation to indicate that the equipment has reached the end of its anticipated service life.
	Unit Heater - Gas	Entire Building	1	EA	7	10+ years	
	Fin Tube - Steam	Entire Building	192	LF	6	6-10 years	Rank and Priority Rep adjusted based on current observations and per review with Building Engineer that the equipment is operational and well-maintained with no signs of leakage.
	Radiators - Steam	Entire Building	6	EA	6	6-10 years	Rank and Priority Rep adjusted based on current observations and per review with Building Engineer that the units are operational and well-maintained with no signs of leakage.
	Wall Heater - Electric	Entire Building	7	EA	6	6-10 years	Ç Ç
_Tempera	ature Control						
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	
	Pneumatic System	Entire Building	82,739	SF	4	1-2 years	Rank, Reason and Priority Rep changed per review with Building Engineer that the system is largely

Campus Name: Mann Page : 7 of 47 Assessment Date: 03/06/2024



Catego	ry : Mechanical		В	uilding	: Main	_	
Cuarra	Ham Tune	Leastion	Outama!!!	LICA	Denle	Recommend	Comments
Group	Item - Type Thermostats - Pneumatic	Location Entire Building	Quantity 36	EA	Rank 4	1-2 years	nonfunctional with temperature in most areas of the building under manual control. Based on review with Building Engineer, the thermostats throughout the building are nonfunctional or damaged.
Ventilati	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed based on repairs completed since previous assessment.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	Rank, Reason and Priority Rep changed as the unit was replaced since previous assessment.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	3	EA	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	2	EA	7	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wat		Location	Quantity	OOM	Italik	Replacement	Comments
. 10. 170.	Electric Heater - Less than 20 KW Gas Heater - 150000 - 300000 BTU/HR	1st Floor Boiler Room	1	EA EA	6 6	6-10 years 6-10 years	Item Type changed to match current observations.
Piping							
- Pug	Domestic Piping-Hot Water Return Lines	Entire Building	82,739	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	82,739	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	82,739	SF	6	2-5 years	
	Fixtures	Entire Building	82,739	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	9					
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	82,739	SF	6	2-5 years	
	(Horizontal Lines) Domestic Piping-Hot/Cold Water Supply	-	82,739 82,739	SF SF	6 6	2-5 years 6-10 years	

Campus Name: Mann Page: 8 of 47 Assessment Date: 03/06/2024



Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Storm Piping Vent Piping	Entire Building Entire Building	82,739 82,739	SF SF	6 6	6-10 years 6-10 years	
Pumps							
•	Pumps - Sump-Duplex	Basement	1	EA	6	6-10 years	No CPS Asset Tag present.
	Pumps - Sump-Simplex	Basement	2	EA	6	6-10 years	Item Type, Quantity, Location, Rank, Reason and Priority Rep changed to match current observations. Submersible pumps with no CPS Asset Tag present.
	Pumps - Sump-Simplex	Boiler Room	1	EA	6	6-10 years	Priority Rep adjusted to coincide with current observations, Rank and Reason.

Category : Room Building · Main

Catego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	AC Unit	114 - Principal Suite	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	114 - Principal Suite	631	SF	7	10+ years	
	Doors - Transom Window	114 - Principal Suite	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	114 - Principal Suite	2	EA	7	10+ years	
	Floor - Tile	114 - Principal Suite	621	SF	7	10+ years	
	Floor - Tile	114 - Principal Suite	10	SF	5	1-2 years	Cracked tile
	Lighting - Pendent/Surface	114 - Principal Suite	10	EA	7	6-10 years	
	Power Distribution	114 - Principal Suite	4	EA	7	10+ years	
	Storage/ Closet	114 - Principal Suite	100	SF	7	10+ years	
	Walls - Plaster/Drywall	114 - Principal Suite	977	SF	7	10+ years	
	Ceiling - Plaster/Drywall	114 - Principal's Office inside Suite	248	SF	7	10+ years	
	Doors - Wood Doors inclu hw	114 - Principal's Office inside Suite	1	EA	7	10+ years	
	Floor - Tile	114 - Principal's Office inside Suite	248	SF	7	6-10 years	
	Lighting - Pendent/Surface	114 - Principal's Office inside Suite	4	EA	7	6-10 years	
	Power Distribution	114 - Principal's Office inside Suite	4	EA	7	10+ years	
	Walls - Plaster/Drywall	114 - Principal's Office inside Suite	634	SF	7	10+ years	
	Ceiling - Plaster/Drywall	121 - Counselor's Office	364	SF	7	10+ years	
	Doors - Side-lite	121 - Counselor's Office	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	121 - Counselor's Office	3	EA	7	10+ years	
	Floor - Tile/Sheet	121 - Counselor's Office	344	SF	7	10+ years	
	Floor - Tile/Sheet	121 - Counselor's Office	20	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	121 - Counselor's Office	6	EA	7	6-10 years	
	Walls - Plaster/Drywall	121 - Counselor's Office	983	SF	7	10+ years	
	Walls - Plaster/Drywall	121 - Counselor's Office	58	SF	5	1-2 years	Damaged wall
	Work SInk	121 - Counselor's Office	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	110	SF	7	10+ years	

Campus Name: Mann Page : 9 of 47 Assessment Date: 03/06/2024





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	90	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	20	SF	4	1-2 years	Cracked floor
	Lighting - Pendent/Surface	1st Floor	1	EA	7	10+ years	
	Power Distribution	1st Floor	4	EA	7	10+ years	
	Walls - Masonry	1st Floor	150	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	100	SF	7	10+ years	
	AC Unit	1st Floor - Administrative Office inside Main Office	1	EA	7	2-5 years	
	Ceiling - Plaster/Drywall	1st Floor - Administrative Office	127	SF	6	10 L Vooro	
	Ceiling - Plaster/Drywaii	inside Main Office	127	SF	O	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Administrative Office	1	EA	7	10+ years	
	Doors - Wood Doors Inclu IIW	inside Main Office	ı	EA	1	10+ years	
	Floor - Tile	1st Floor - Administrative Office	127	SF	6	10	
	FIOOI - THE		127	SF	О	10+ years	
	Lighting Dandont/Curface	inside Main Office 1st Floor - Administrative Office	2	EA	7	6.10 , , , , , , , ,	
	Lighting - Pendent/Surface		2	EA	7	6-10 years	
	Davis Distribution	inside Main Office	4	- ^	7	40	
	Power Distribution	1st Floor - Administrative Office	4	EA	7	10+ years	
	Malla Diagtan/Dunasali	inside Main Office	50.4	0.	7	40	
	Walls - Plaster/Drywall	1st Floor - Administrative Office	534	SF	7	10+ years	
	40113	inside Main Office	4	_ ^	_	0.40	
	AC Unit	1st Floor - Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Main Office	329	SF	6	10+ years	
	Doors - Transom Window	1st Floor - Main Office	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Main Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Main Office	329	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Main Office	5	EΑ	7	6-10 years	
	Power Distribution	1st Floor - Main Office	9	EA	7	10+ years	
	Storage/ Closet	1st Floor - Main Office	161	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Main Office	854	SF	7	10+ years	
	Ceiling - Plaster/Drywall	214A	384	SF	7	10+ years	
	Doors - Transom Window	214A	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	214A	2	EA	7	10+ years	
	Floor - Tile	214A	354	SF	7	10+ years	
	Floor - Tile	214A	30	SF	4	1-2 years	Broken chipped
	Lighting - Pendent/Surface	214A	5	EA	7	6-10 years	
	Power Distribution	214A	6	EA	7	10+ years	
	Walls - Plaster/Drywall	214A	1,443	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Teacher's Lunch Room/ Storage	454	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Teacher's Lunch Room/ Storage	1	EA	7	10+ years	
	Floor - Terrazzo	2nd Teacher's Lunch Room/ Storage	454	SF	7	10+ years	



Catego	Category : Room		В	uilding	: Main			
	,					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Pendent/Surface	2nd Teacher's Lunch Room/	9	EΑ	7	6-10 years		
		Storage						
	Power Distribution	2nd Teacher's Lunch Room/	4	EA	7	10+ years		
		Storage						
	Storage/ Closet	2nd Teacher's Lunch Room/	130	SF	7	10+ years		
		Storage						
	Walls - Plaster/Drywall	2nd Teacher's Lunch Room/	970	SF	6	10+ years		
		Storage						
	Walls - Plaster/Drywall	2nd Teacher's Lunch Room/	10	SF	5	1-2 years	Water damage	
		Storage			_			
	AC Unit	Boiler Room - Engineer	_1	EA	5	2-5 years		
	Ceiling - Lay-in	Boiler Room - Engineer	77	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	Boiler Room - Engineer	1	EA	6	10+ years		
	Floor - Tile	Boiler Room - Engineer	77	SF	6	10+ years		
	Lighting - Lay-in	Boiler Room - Engineer	2	EA	7	6-10 years		
	Power Distribution	Boiler Room - Engineer	6	EA	7	10+ years		
	Walls - Plaster/Drywall	Boiler Room - Engineer	293	SF	7	10+ years		
	Work SInk	Boiler Room - Engineer	1	EA	7	10+ years		
	Ceiling - Lay-in	Kitchen Office	77	SF	7	10+ years		
	Doors - Wood Doors inclu hw	Kitchen Office	2	EA	7	10+ years		
	Floor - Tile	Kitchen Office	77	SF	6	10+ years		
	Lighting - Lay-in	Kitchen Office	2	EΑ	7	6-10 years		
	Power Distribution	Kitchen Office	4	EA SF	7	10+ years		
	Walls - Plaster/Drywall Walls - Plaster/Drywall	Kitchen Office Kitchen Office	350 20	SF SF	7 4	10+ years 1-2 years	Domogod well	
	walls - Plaster/Drywall	Kitchen Office	20	SF	4	1-2 years	Damaged wall	
_Auditoriu	um & Theater							
	Balcony Seating	1st Floor	78	EA	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	3,826	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	200	SF	4	1-2 years	Damaged ceilings	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	6	10+ years		
	Floor - Carpet	1st Floor	967	SF	7	6-10 years		
	Floor - Epoxy/ Painted	1st Floor	2,160	SF	7	10+ years		
	Floor - Terrazzo	1st Floor	351	SF	7	10+ years		
	Floor - Wood	1st Floor	548	SF	7	10+ years		
	Lighting - Chandelier, Incandescent	1st Floor	6	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years		
	Lighting - Wall Mounted	1st Floor	14	EA	7	6-10 years		
	Main Floor Seating	1st Floor	93	EA	7	10+ years		
	Stage	1st Floor	548	SF	7	10+ years		
	Stage Curtain	1st Floor	6	EA	7	10+ years		
	Stage Lighting System	1st Floor	1	EA	7	10+ years		
	Stage-Stairs - Wood	1st Floor	28	LF	7	10+ years		
	Stairs - Terrazzo	1st Floor	120	LF	7	10+ years		



Catego	Category : Room		В	uilding	: Main				
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	1st Floor	6,057	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	105	SF	5	1-2 years	Damaged wall		
Gymnas	ia								
•	Ceiling - Plaster/Drywall	1st Floor	2,749	SF	6	10+ years			
	Doors - Transom Window	1st Floor	24	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	4	EΑ	6	10+ years			
	Floor - Wood	1st Floor	2,749	SF	6	10+ years			
	Lighting - Metal Halide/Sodium Vapor	1st Floor	15	EA	7	6-10 years			
	Scoreboards	1st Floor	1	EA	7	10+ years			
	Walls - Masonry	1st Floor	1,582	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	2,260	SF	6	10+ years			
Kitchen									
	Ceiling - Plaster/Drywall	1st Floor	829	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years			
	Floor - Tile Quarry	1st Floor	829	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	21	EA	7	6-10 years			
	Storage/ Closet	1st Floor	214	SF	5	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,150	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	200	SF	6	10+ years			
Locker/S	Shower Room								
LUCKEI/C	Accessories	1st Floor - For Kitchen Staff	191	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor - For Kitchen Staff	183	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor - For Kitchen Staff	8	SF	4	1-2 years	Damaged ceiling		
	Doors - Wood Doors inclu hw	1st Floor - For Kitchen Staff	2	EA	7	10+ years	Damaged Celling		
	Floor - Tile/Sheet	1st Floor - For Kitchen Staff	187	SF	7	10+ years			
	Floor - Tile/Sheet	1st Floor - For Kitchen Staff	4	SF	4	1-2 years	Damaged tile		
	Lavatory	1st Floor - For Kitchen Staff	1	EA	6	10+ years	Damaged tile		
	Lighting - Pendent/Surface	1st Floor - For Kitchen Staff	2	EA	7	6-10 years			
	Lighting - Wall Mounted	1st Floor - For Kitchen Staff	1	EA	7	6-10 years			
	Partitions	1st Floor - For Kitchen Staff	1	EA	7	10+ years			
	Student Lockers - One Tier	1st Floor - For Kitchen Staff	6	EA	7	6-10 years			
	Walls - Concrete Block	1st Floor - For Kitchen Staff	347	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor - For Kitchen Staff	463	SF	6	10+ years			
	Water Closet	1st Floor - For Kitchen Staff	403	EA	7	10+ years			
	Accessories	Coach's Room	491	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Coach's Room	491	SF	6	10+ years			
	Doors - Steel Doors incl hw	Coach's Room	1	EA	7	10+ years			
	Doors - Steel Doors incliniw Doors - Transom Window	Coach's Room	9	SF	7	•			
	Doors - Wood Doors inclu hw	Coach's Room		Sr EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	Coach's Room	2 491	SF	6	10+ years			
	Floor - The Ceramic/ Porcelain	Coach's Room	491	SF	ю	10+ years			

Campus Name: Mann Page : 12 of 47 Assessment Date: 03/06/2024



atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	Coach's Room	1	EA	7	10+ years	
	Lavatory	Coach's Room	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	Coach's Room	5	EA	7	10+ years	
	Partitions	Coach's Room	7	EA	7	10+ years	
	Showers	Coach's Room	4	EA	7	10+ years	
	Walls - Masonry	Coach's Room	426	SF	7	10+ years	
	Walls - Plaster/Drywall	Coach's Room	512	SF	6	10+ years	
	Water Closet	Coach's Room	1	EA	6	10+ years	
ınch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	2,585	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2,505	EA	7	10+ years	
	Floor - Tile	1st Floor	2,550	SF	6	10+ years	
	Floor - Tile Floor - Tile	1st Floor		SF SF			Damaged tiles
			35		4	1-2 years	Damaged tiles
	Lighting - Lay-in	1st Floor	71	EA	7	6-10 years	
	Serving Line	1st Floor	22	LF	7	10+ years	
	Walls - Concrete Block	1st Floor	468	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,612	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	4	1-2 years	Damaged wall
	Ceiling - Lay-in	Staff Lounge	416	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Staff Lounge	1	EA	7	10+ years	
	Floor - Tile	Staff Lounge	416	SF	7	10+ years	
	Lighting - Lay-in	Staff Lounge	6	ĒΑ	7	6-10 years	
	Lighting - Lay-in	Staff Lounge	3	EA	5	1-2 years	Missing cover
	Walls - Plaster/Drywall	Staff Lounge	810	SF	7	10+ years	Missing cover
	Walls - Plaster/Drywall	Staff Lounge	15	SF	4	1-2 years	Damaged wall
echani	cal/ Service Rooms						
20110111	Janitor's Closet	1st Floor	20	SF	7	10+ years	
	Janitor's Closet	1st Floor	20	SF	5	10+ years	
	Storage Room	1st Floor	60	SF	7	•	
				SF SF	, 5	10+ years	
	Storage Room	1st Floor	326			2-5 years	
	Storage Room	1st Floor	490	SF	5	2-5 years	
	Janitor's Closet	2nd Floor	67	SF	5	10+ years	
	Storage Room	2nd Floor	123	SF	7	10+ years	
	Air Intake Plenums	Basement	60	SF	7	10+ years	
	Air Tunnel	Basement	3,045	SF	7	10+ years	
	Auditorium Plenums	Basement	2,300	SF	7	10+ years	
	Boiler Room	Basement	2,553	SF	5	10+ years	
	Coal Room	Basement	928	SF	5	2-5 years	No specific seepage observed
	Crawl Space - Unfinished	Basement	2,760	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	6,223	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	440	SF	5	2-5 years	
		Basement	1,150	SF	7		
	Storage Room	Dasement	1,150	ЗF	,	10+ years	

Campus Name: Mann Page : 13 of 47 Assessment Date: 03/06/2024



Category : Room		В	uilding	: Main	_			
	_					Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Storage Room	Basement	412	SF	5	2-5 years		
estroor								
	Accessories	116	171	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	116	171	SF	7	10+ years		
	Doors - Wood Doors inclu hw	116	3	EA	7	10+ years		
	Floor - Terrazzo	116	111	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	116	60	SF	7	10+ years		
	Floor Drain	116	1	EA	7	10+ years		
	Hand Dryer	116	1	EA	7	6-10 years		
	Lavatory	116	2	EA	7	10+ years		
	Lighting - Pendent/Surface	116	4	EΑ	7	6-10 years		
	Partitions	116	2	EA	7	10+ years		
	Walls - Plaster/Drywall	116	810	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	116	140	SF	7	10+ years		
	Water Closet	116	2	EA	7	10+ years		
	Accessories	1st Floor	85	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	85	SF	7	10+ years		
	Doors - Transom Window	1st Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor	85	SF	7	10+ years		
	Floor Drain	1st Floor	1	EA	7	10+ years		
	Lavatory	1st Floor	1	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor	2	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	70	SF	7	10+ years		
	Walls - Tile Ceramic/ Porcelain	1st Floor	130	SF	7	10+ years		
	Water Closet	1st Floor	130	EA	7	10+ years		
	Accessories	1st Floor - Boys South	248	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor - Boys South	248	SF	7	,		
	Doors - Side-lite	1st Floor - Boys South	240	SF	7	10+ years		
			18	SF	7	10+ years		
	Doors - Transom Window	1st Floor - Boys South				10+ years		
	Doors - Wood Doors inclu hw	1st Floor - Boys South	2	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor - Boys South	248	SF	7	10+ years		
	Floor Drain	1st Floor - Boys South	1	EΑ	7	10+ years		
	Lavatory	1st Floor - Boys South	2	EA	7	10+ years		
	Lighting - Pendent/Surface	1st Floor - Boys South	3	EA	7	6-10 years		
	Partitions	1st Floor - Boys South	2	EΑ	7	10+ years		
	Urinals	1st Floor - Boys South	4	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor - Boys South	449	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor - Boys South	456	SF	7	10+ years		
	Water Closet	1st Floor - Boys South	1	EA	7	10+ years		
	Accessories	1st Floor - North	400	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor - North	370	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor - North	30	SF	5	1-2 years	Cracking plaster	

Campus Name: Mann Page : 14 of 47 Assessment Date: 03/06/2024





Catego	Category : Room		В	uilding	: Main		···		
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Transom Window	1st Floor - North	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor - North	2	EA	7	10+ years			
	Floor - Tile/Sheet	1st Floor - North	400	SF	7	10+ years			
	Floor Drain	1st Floor - North	1	EA	7	10+ years			
	Lavatory	1st Floor - North	3	EΑ	7	10+ years			
	Lighting - Pendent/Surface	1st Floor - North	6	EΑ	7	6-10 years			
	Partitions	1st Floor - North	8	EA	7	10+ years			
	Walls - Masonry	1st Floor - North	505	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor - North	716	SF	7	10+ years			
	Water Closet	1st Floor - North	8	EA	7	10+ years			
	Accessories	1st Floor - North Boys	225	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor - North Boys	248	SF	6	10+ years			
	Doors - Transom Window	1st Floor - North Boys	16	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor - North Boys	2	ĒΑ	6	10+ years			
	Floor - Tile/Sheet	1st Floor - North Boys	248	SF	7	10+ years			
	Floor Drain	1st Floor - North Boys	1	EA	7	10+ years			
	Lavatory	1st Floor - North Boys	2	EΑ	7	10+ years			
	Lighting - Pendent/Surface	1st Floor - North Boys	5	EA	7	6-10 years			
	Partitions	1st Floor - North Boys	2	EA	7	10+ years			
	Urinals	1st Floor - North Boys	4	EA	7	10+ years			
	Walls - Concrete Block	1st Floor - North Boys	84	SF	7	10+ years			
	Walls - Masonry	1st Floor - North Boys	367	SF	7	10+ years			
	Walls - Masority Walls - Plaster/Drywall	1st Floor - North Boys	442	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor - North Boys	15	SF	4	1-2 years	Cracking plaster		
	Water Closet	1st Floor - North Boys	2	EA	7	10+ years	Cracking plaster		
		1st Floor - South		SF	7				
	Accessories Ceiling - Plaster/Drywall	1st Floor - South	310 310	SF SF	7	6-10 years			
				EA		10+ years			
	Doors - Wood Doors inclu hw	1st Floor - South	2 40	SF	6 7	10+ years			
	Floor - Tile Coronia/ Boroslain	1st Floor - South		SF SF		10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor - South 1st Floor - South	270	SF EA	6 7	10+ years			
	Floor Drain		1			10+ years			
	Lavatory	1st Floor - South	2	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor - South	4	EA	7	10+ years			
	Partitions	1st Floor - South	5	EA	7	10+ years			
	Walls - Plaster/Drywall	1st Floor - South	325	SF	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor - South	325	SF	7	10+ years			
	Water Closet	1st Floor - South	5	EA	7	10+ years			
	Accessories	2nd Floor	248	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	248	SF	7	10+ years			
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years			
	Floor - Tile/Sheet	2nd Floor	248	SF	7	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Lavatory	2nd Floor	2	EΑ	7	10+ years			

Campus Name: Mann Page : 15 of 47 Assessment Date: 03/06/2024





Catego	ory : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	5	EA	5	6-10 years	
	Partitions	2nd Floor	5	EΑ	7	6-10 years	
	Walls - Masonry	2nd Floor	418	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	567	SF	7	10+ years	
	Water Closet	2nd Floor	5	EA	7	10+ years	
	Accessories	2nd Floor	423	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	423	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	423	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years	
	Partitions	2nd Floor	3	EA	7	6-10 years	
	Urinals	2nd Floor	4	ΕA	7	10+ years	
	Walls - Concrete Block	2nd Floor	113	SF	7	10+ years	
	Walls - Masonry	2nd Floor	407	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	853	SF	6	10+ years	
	Water Closet	2nd Floor	3	EA	7	10+ years	
	Accessories	2nd Floor Staff Unisex	139	SF	7	6-10 years	
	Ceiling - Lay-in	2nd Floor Staff Unisex	139	SF	7	10+ years	
	Doors - Transom Window	2nd Floor Staff Unisex	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Staff Unisex	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor Staff Unisex	139	SF	7	10+ years	
	Lavatory	2nd Floor Staff Unisex	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor Staff Unisex	2	EA	7	6-10 years	
	Partitions	2nd Floor Staff Unisex	2	EA	7	6-10 years	
	Walls - Masonry	2nd Floor Staff Unisex	283	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Staff Unisex	326	SF	7	10+ years	
	Water Closet	2nd Floor Staff Unisex	2	EA	7	10+ years	
	Accessories	2nd- South Boy's RR	218	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd- South Boy's RR 2nd- South Boy's RR	218	SF	6	10+ years	
	Doors - Transom Window	2nd- South Boy's RR 2nd- South Boy's RR	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd- South Boy's RR 2nd- South Boy's RR	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd- South Boy's RR 2nd- South Boy's RR	218	SF	7	10+ years	
	Floor Drain	2nd- South Boy's RR 2nd- South Boy's RR	1	EA	7	10+ years	
						•	
	Lavatory Lighting - Pendent/Surface	2nd- South Boy's RR 2nd- South Boy's RR	2 5	EA EA	7 7	10+ years	
	Partitions	2nd- South Boy's RR 2nd- South Boy's RR	2	EA EA	7	6-10 years	
						6-10 years	
	Urinals	2nd- South Boy's RR	4	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd- South Boy's RR	416	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd- South Boy's RR	417	SF	7	10+ years	
	Water Closet	2nd- South Boy's RR	2	EA	7	10+ years	

Campus Name: Mann Page : 16 of 47 Assessment Date: 03/06/2024





Catego	ry : Room		В	uilding	: Main		
	un Itam - Type				_	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	2nd- South Girl's RR	378	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd- South Girl's RR	378	SF	7	10+ years	
	Doors - Transom Window	2nd- South Girl's RR	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd- South Girl's RR	4	EA	7	10+ years	
	Floor - Tile/Sheet	2nd- South Girl's RR	378	SF	7	10+ years	
	Floor Drain	2nd- South Girl's RR	1	EA	7	10+ years	
	Hand Dryer	2nd- South Girl's RR	1	EA	7	6-10 years	
	Lavatory	2nd- South Girl's RR	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd- South Girl's RR	6	EA	7	6-10 years	
	Partitions	2nd- South Girl's RR	6	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd- South Girl's RR	511	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd- South Girl's RR	511	SF	7	10+ years	
	Water Closet	2nd- South Girl's RR	6	ĒΑ	7	10+ years	
	Accessories	2nd- Staff RR inside 214A	88	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd- Staff RR inside 214A	88	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd- Staff RR inside 214A	1	EA	7	10+ years	
	Floor - Tile	2nd- Staff RR inside 214A	78	SF	6	6-10 years	
	Floor - Tile	2nd- Staff RR inside 214A	10	SF	4		Cracked
				EA		1-2 years	Cracked
	Lavatory	2nd- Staff RR inside 214A	2		7	10+ years	
	Lighting - Pendent/Surface	2nd- Staff RR inside 214A	2	EΑ	7	6-10 years	
	Lighting - Wall Mounted	2nd- Staff RR inside 214A	1	EΑ	7	6-10 years	
	Partitions	2nd- Staff RR inside 214A	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd- Staff RR inside 214A	508	SF	7	10+ years	
	Water Closet	2nd- Staff RR inside 214A	2	EA	7	10+ years	
	Accessories	Administrative Office inside Main Office	24	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Administrative Office inside Main Office	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Administrative Office inside Main Office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Administrative Office inside Main Office	24	SF	6	10+ years	
	Lavatory	Administrative Office inside Main Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Administrative Office inside Main Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Administrative Office inside Main Office	240	SF	6	10+ years	
	Water Closet	Administrative Office inside Main Office	1	EA	7	10+ years	
	Accessories	Auditorium - Men	80	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Auditorium - Men	60	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Auditorium - Men	20	SF	4	1-2 years	Damaged ceiling
	Doors - Wood Doors inclu hw	Auditorium - Men	1	EA	6	10+ years	Damaged coming
	20013 WOOG 20013 IIIOIG IIW	Additionally Men	'	L A	U	TOT years	



Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	Auditorium - Men	80	SF	7	10+ years	
	Lavatory	Auditorium - Men	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Auditorium - Men	1	EA	7	6-10 years	
	Partitions	Auditorium - Men	1	EA	7	10+ years	
	Urinals	Auditorium - Men	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Auditorium - Men	340	SF	7	10+ years	
	Walls - Plaster/Drywall	Auditorium - Men	15	SF	5	1-2 years	Damaged wall
	Water Closet	Auditorium - Men	1	EA	6	10+ years	
	Accessories	Auditorium - Women	113	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Auditorium - Women	113	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Auditorium - Women	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Auditorium - Women	111	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Auditorium - Women	2	SF	4	1-2 years	Damaged tile
	Lavatory	Auditorium - Women	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Auditorium - Women	1	EA	7	6-10 years	
	Partitions	Auditorium - Women	1	EΑ	5	1-2 years	No door
	Walls - Plaster/Drywall	Auditorium - Women	410	SF	6	10+ years	
	Water Closet	Auditorium - Women	1	EA	7	10+ years	
	Accessories	Boiler Room	100	SF	4	1-2 years	Damaged and missing throughout
	Ceiling - Plaster/Drywall	Boiler Room	70	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Boiler Room	30	SF	4	1-2 years	Damaged ceiling
	Doors - Wood Doors inclu hw	Boiler Room	2	EA	6	6-10 years	
	Floor - Concrete	Boiler Room	100	SF	5	1-2 years	Poor condition throughout
	Lighting - Pendent/Surface	Boiler Room	2	EA	6	6-10 years	
	Showers	Boiler Room	1	EA	5	1-2 years	Not in tact
	Walls - Plaster/Drywall	Boiler Room	372	SF	6	10+ years	
	Walls - Plaster/Drywall	Boiler Room	100	SF	4	1-2 years	Significantly damaged wall
	Accessories	Boiler room on mezzanine	25	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Boiler room on mezzanine	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Boiler room on mezzanine	1	EΑ	6	6-10 years	
	Floor - Concrete Epoxy/ Painted	Boiler room on mezzanine	25	SF	5	1-2 years	Damaged
	Lighting - Pendent/Surface	Boiler room on mezzanine	1	EA	4	1-2 years	Missing cover
	Walls - Plaster/Drywall	Boiler room on mezzanine	125	SF	6	10+ years	
	Walls - Plaster/Drywall	Boiler room on mezzanine	30	SF	5	1-2 years	Damaged plaster
	Water Closet	Boiler room on mezzanine	1	EA	7	10+ years	
	Accessories	Engineer's Restroom	25	SF	7	6-10 years	
	Ceiling - Lay-in	Engineer's Restroom	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Restroom	1	EA	7	10+ years	
	Floor - Tile	Engineer's Restroom	25	SF	6	10+ years	
	Lighting - Lay-in	Engineer's Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Engineer's Restroom	153	SF	5	1-2 years	Damaged wall
	Water Closet	Engineer's Restroom	1	EA	7	10+ years	

Campus Name: Mann Page: 18 of 47 Assessment Date: 03/06/2024



Catego	ry : Classroom		В	uilding	: Main		30 0 Onapper Avervoe, Onicago, ie 00017
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #112 (Faculty Lounge)		·				
	Ceiling - Lay-in	1st Floor	505	SF	7	6-10 years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	505	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor	11	ĒΑ	7	6-10 years	
	Lighting - Lay-in	1st Floor	1	EA	5	1-2 years	Cracked cover
	Walls - Concrete Block	1st Floor	220	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	665	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	5	1-2 years	Damaged wall
Classroo	om #116/118 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,246	SF	7	10+ years	
	Doors - Transom Window	1st Floor	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Wood	1st Floor	1,246	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	10+ years	
	Storage/ Closet	1st Floor	128	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,549	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	nm #117 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	34	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	768	SF	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	768	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	7	10+ years	New fixtures
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,432	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #119 (Kindergarten)						
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	720	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	

Campus Name: Mann Page : 19 of 47 Assessment Date: 03/06/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,229	SF	6	10+ years	
assroo	m #120 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Floor - Wood	1st Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,129	SF	6	10+ years	
eeroo	m #122 (Special Education)						
00100	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	720	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	35	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,179	SF	6	10+ years	
assroo	m #123 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	60	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	860	SF	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	820	SF	7	10+ years	
	Floor - Tile	1st Floor	40	SF	5	1-2 years	Cracked and damaged tile
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EΑ	5	1-2 years	Missing cover
	Marker Board	1st Floor	10	LF	7	6-10 years	···g · - ·
	Storage/ Closet	1st Floor	110	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,494	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	5	SF	5	1-2 years	Cracking wall cover
	Work Sink	1st Floor	2	EA	7	10+ years	. .
aceroo	m #135 (Regular Classroom)						

Campus Name: Mann Page : 20 of 47 Assessment Date: 03/06/2024



Catego	ry : Classroom		R	uilding	: Main	- 00	30 S Chapper AVENUE, Chicago, IL 60617
Guiogo	ry r Glader Geni			anamg	· Maii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	AC Units	1st Floor	1	EΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	720	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,149	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	80	SF	4	1-2 years	Damaged plaster
	Walls - Vinyl Coated Gypsum Panel	1st Floor	104	SF	7	10+ years	G .
Classroo	om #208 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,350	SF	7	10+ years	
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,350	SF	6	10+ years	
Classroo	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	7	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,350	SF	6	10+ years	

Campus Name: Mann Page : 21 of 47 Assessment Date: 03/06/2024





Catego	ry : Classroom		В	uilding	: Main		30 3 Chappel AVENOE, Chicago, IL 60617
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
01	(1040 (D						
_Classroo	om #212 (Regular Classroom)	Ond Floor	4	ΓΛ	7	C 10	
	AC Units	2nd Floor	1	EA LF	7	6-10 years	
	Casework	2nd Floor	9		6	10+ years	
	Ceiling - Plaster/Drywall Chalk Board	2nd Floor 2nd Floor	720	SF LF	6	10+ years	
	Doors - Transom Window	2nd Floor 2nd Floor	6	SF	4 7	2-5 years	
			8		7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA SF	=	10+ years	
	Floor - Wood	2nd Floor 2nd Floor	720		6	10+ years	
	Lighting - Pendent/Surface Marker Board	2nd Floor	14 22	EA LF	7 7	6-10 years	
						6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,350	SF	6	10+ years	
Classroo	om #213 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,350	SF	6	10+ years	
Classias							
Classroo	om #214 (Regular Classroom)	0. 151		Ε.Δ.	-	0.40	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,271	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4	SF	4	1-2 years	Cracked
Classroo	om #215 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
						,	

Campus Name: Mann Page : 22 of 47 Assessment Date: 03/06/2024



Catego	ory : Classroom		В	uilding	: Main		oo o onapper Avervoe, omeago, ie ooor
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	730	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,275	SF	6	10+ years	
Classroo	om #216 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	7	10+ years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,250	SF	6	10+ years	
Classro	om #217 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,281	SF	6	10+ years	
Classro	om #218 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Boots inclu tiw	2nd Floor	730	SF	6	10+ years	
		2nd Floor		EA	7		
	Lighting - Pendent/Surface Walls - Plaster/Drywall	2nd Floor 2nd Floor	14 1,275	SF		6-10 years	
	Walls - Plaster/Drywall	2na Floor	1,275	SF	6	10+ years	
Classroo	om #219 (Faculty Lounge)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,285	SF	6	10+ years	
Classroo	om #220 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	45	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,275	SF	6	10+ years	
Classroo	om #221 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	7	10+ years	
	Floor - Wood	2nd Floor	5	SF	5	1-2 years	Chipped
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	Опіррец
	Walls - Plaster/Drywall	2nd Floor	1,275	SF	7	10+ years	
Classros	om #222 (Science Classroom)						
_CIASSIU(Ond Floor	4	Г^	7	6.10	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	62	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,016	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,006	SF	6	10+ years	0 1 1
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,500	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	



Catego	ry : Classroom		Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #223 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,275	SF	6	10+ years	
Classroo	m #235 (Play Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	730	SF	6	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	720	SF	7	10+ years	
	Floor - Wood	2nd Floor	10	SF	5	1-2 years	Chipped
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,150	SF	6	10+ years	
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	104	SF	6	10+ years	
Catego	ry : Interior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	6,916	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	3	EA	7	10+ years	
	Doors - Transom Window	1st Floor	34	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	4	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	5,669	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,247	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	61	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EΑ	6	2-5 years	
	Lighting - Wall Mounted	1st Floor	2	EA	7	6-10 years	
	Stairs - Terrazzo	1st Floor	9	LF.	7	10+ years	
	Student Lockers - One Tier	1st Floor	233	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	147	SF	7	10+ years	
	Walls - Masonry	1st Floor	1,185	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	11,859	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	400	SF	6	2-5 years	





Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor 2nd Floor	1 1 4	UOM SF SF EA SF SF EA EA SF SF	Rank 7 7 7 7 7 4 7 7 6	Recommend Replacement 10+ years 10+ years 6-10 years 10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years	Cracked
Walls - Structural Glazed Tile Ceiling - Plaster/Drywall Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Plaster/Drywall Camera Viewing Station Camera Viewing Station Security Cameras Entire building Security Cameras Entire building Entire building Entire building Entire building	465 5,271 4 801 5,460 10 53 587 2,528 100	SF SF SF SF EA SF	7 7 7 7 4 7 7 7	10+ years 10+ years 6-10 years 10+ years 10+ years 1-2 years 6-10 years 10+ years 10+ years	
Ceiling - Plaster/Drywall Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Ploor Pendent/Surface Student Lockers - One Tier Ploor Plaster/Drywall Plaster/Drywall Ploor Safety Camera Viewing Station Camera Viewing Station Ploor Entire building Security Cameras Entire building	5,271 4 801 5,460 10 53 587 2,528 100	SF EA SF SF EA SF EA	7 7 7 7 4 7 7 7 6	10+ years 6-10 years 10+ years 10+ years 1-2 years 6-10 years 10+ years 10+ years	Cracked
Drinking Fountains - Single Water Cooler Floor - Terrazzo Floor - Tile/Sheet Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Plaster/Drywall Camera Viewing Station Camera Viewing Station Security Cameras Entire building Entire building Entire building Entire building Entire building	4 801 5,460 10 53 587 2,528 100	EA SF SF EA EA SF SF	7 7 7 4 7 7 7 6	6-10 years 10+ years 10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years	Cracked
Floor - Terrazzo 2nd Floor 5 Floor - Tile/Sheet 2nd Floor 5 Floor - Tile/Sheet 2nd Floor 5 Lighting - Pendent/Surface 2nd Floor 5 Student Lockers - One Tier 2nd Floor 4 Walls - Plaster/Drywall 2nd Floor 12 Walls - Plaster/Drywall 2nd Floor 12 Safety 2nd Floor 5 Camera Viewing Station Entire building 5 Security Cameras Entire building 5	801 5,460 10 53 587 2,528 100	SF SF SF EA SF SF	7 7 4 7 7 7 6	10+ years 10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years	Cracked
Floor - Tile/Sheet 2nd Floor Floor - Tile/Sheet 2nd Floor Lighting - Pendent/Surface 2nd Floor Student Lockers - One Tier 2nd Floor Walls - Plaster/Drywall 2nd Floor Walls - Plaster/Drywall 2nd Floor Safety Camera Viewing Station Entire building Camera Viewing Station Entire building Security Cameras Entire building	5,460 10 53 587 2,528 100 1 1 1	SF SF EA SF SF	7 4 7 7 7 6	10+ years 1-2 years 6-10 years 10+ years 10+ years 10+ years	Cracked
Floor - Tile/Sheet Lighting - Pendent/Surface Student Lockers - One Tier Walls - Plaster/Drywall Walls - Plaster/Drywall Camera Viewing Station Camera Viewing Station Security Cameras Entire building Security Cameras 2nd Floor 2nd Fl	10 53 587 2,528 100	SF EA SF SF	4 7 7 7 6	1-2 years 6-10 years 10+ years 10+ years 10+ years	Cracked
Lighting - Pendent/Surface 2nd Floor Student Lockers - One Tier 2nd Floor Walls - Plaster/Drywall 2nd Floor Walls - Plaster/Drywall 2nd Floor Safety Camera Viewing Station Entire building Camera Viewing Station Entire building Security Cameras Entire building	53 587 2,528 100 1 1 1	EA EA SF SF	7 7 7 6	6-10 years 10+ years 10+ years 10+ years	Cracked
Student Lockers - One Tier Walls - Plaster/Drywall Walls - Plaster/Drywall 2nd Floor 2	587 2,528 100 1 1 1	EA SF SF	7 7 6	6-10 years 10+ years 10+ years 10+ years	
Student Lockers - One Tier Walls - Plaster/Drywall Walls - Plaster/Drywall 2nd Floor 2	587 2,528 100 1 1 1	SF SF EA	7 6	10+ years 10+ years 10+ years	
Walls - Plaster/Drywall Walls - Plaster/Drywall 2nd Floor 2nd Floor Safety Camera Viewing Station Camera Viewing Station Entire building Security Cameras Entire building	2,528 100 1 1 1 4	SF SF EA	7 6	10+ years 10+ years	
Walls - Plaster/Drywall Safety Camera Viewing Station Camera Viewing Station Entire building Security Cameras Entire building Entire building	100 1 1 4	SF EA	6	10+ years	
Camera Viewing Station Entire building Camera Viewing Station Entire building Security Cameras Entire building	1 4		7		
Camera Viewing Station Entire building Camera Viewing Station Entire building Security Cameras Entire building	1 4		7	0.40	
Camera Viewing Station Entire building Security Cameras Entire building	4	EΑ		6-10 years	
Security Cameras Entire building			7	6-10 years	
	_	EΑ	7	6-10 years	
	5	EA	7	6-10 years	
Stairs					
Ceiling - Plaster/Drywall Coach's Office	230	SF	6	10+ years	
Floor - Terrazzo Coach's Office	40	SF	7	10+ years	
Handrails Coach's Office	51	LF	7	10+ years	
Lighting - Pendent/Surface Coach's Office	2	EA	6	10+ years	
Stairs - Terrazzo Coach's Office	96	LF	7	10+ years	
	1,021	SF	6	10+ years	
Ceiling - Plaster/Drywall East - Red	236	SF	7	10+ years	
Floor - Terrazzo East - Red	111	SF	7	10+ years	
Handrails East - Red	64	LF	7	10+ years	
Lighting - Pendent/Surface East - Red	2	EA	7	•	
Stairs - Terrazzo East - Red		LF	7	6-10 years	
	159	LF LF	4	10+ years	Chinnad
Stairs - Terrazzo East - Red	3		7	1-2 years	Chipped
Walls - Plaster/Drywall East - Red	965	SF		10+ years	
Ceiling - Plaster/Drywall North - Blue	256	SF	7	10+ years	
Floor - Terrazzo North - Blue	121	SF	7	10+ years	
Handrails North - Blue	64	LF	7	10+ years	
Lighting - Pendent/Surface North - Blue	2	EA	7	6-10 years	
Stairs - Terrazzo North - Blue	162	LF	7	10+ years	
	1,014	SF	7	10+ years	
Ceiling - Plaster/Drywall Northwest - Yellow	236	SF	7	10+ years	
Floor - Terrazzo Northwest - Yellow	110	SF	7	10+ years	
Handrails Northwest - Yellow	64	LF	7	10+ years	
Lighting - Pendent/Surface Northwest - Yellow	2	EA	7	6-10 years	
Stairs - Terrazzo Northwest - Yellow	162	LF	7	10+ years	
Walls - Plaster/Drywall Northwest - Yellow	960	SF	7	10+ years	
Ceiling - Plaster/Drywall South - Green	253	SF	7	10+ years	

Campus Name: Mann Page : 26 of 47 Assessment Date: 03/06/2024



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	South - Green	122	SF	7	10+ years	
	Handrails	South - Green	64	LF	7	10+ years	
	Lighting - Pendent/Surface	South - Green	2	EΑ	7	10+ years	
	Stairs - Terrazzo	South - Green	162	LF	7	10+ years	
	Walls - Plaster/Drywall	South - Green	1,004	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Southwest - Orange	221	SF	7	10+ years	
	Floor - Terrazzo	Southwest - Orange	99	SF	7	10+ years	
	Handrails	Southwest - Orange	64	LF	7	10+ years	
	Lighting - Pendent/Surface	Southwest - Orange	2	EΑ	7	6-10 years	
	Stairs - Terrazzo	Southwest - Orange	162	LF	7	10+ years	
	Walls - Plaster/Drywall	Southwest - Orange	940	SF	7	10+ years	
	Ceiling - Plaster/Drywall	To Teacher's Lunch/ Storage	59	SF	6	10+ years	
	Floor - Terrazzo	To Teacher's Lunch/ Storage	16	SF	6	10+ years	
	Handrails	To Teacher's Lunch/ Storage	26	LF	7	10+ years	
	Lighting - Pendent/Surface	To Teacher's Lunch/ Storage	1	EΑ	7	10+ years	
	Stairs - Terrazzo	To Teacher's Lunch/ Storage	40	LF	7	10+ years	
	Walls - Plaster/Drywall	To Teacher's Lunch/ Storage	555	SF	6	10+ years	



Category : Exterior Building : Annex

Catego	ry : Exterior		В	uilaing	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	<u>,</u>						
	Entrance Control - Audio and Video	#12 - S	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#12 - S	2	EA	5	1-2 years	Bent/damaged
	Exterior Doors - Side lite	#12 - S	2	ĒΑ	5	1-2 years	Rusting, holes, corrosion
	Exterior Doors - Transom Lite	#12 - S	1	EA	6	6-10 years	,g,g,
	Exterior Doors - Exterior Steel Door	#13 - N	2	EA	5	1-2 years	Corrosion, deformed
	Exterior Doors - Side lite	#13 - N	2	EA	6	10+ years	, , , , , , , , , , , , , , , , , , , ,
	Exterior Doors - Transom Lite	#13 - N	2	EA	6	10+ years	
Foundati	ion						
	Foundation - Concrete	Entire Building	271	LF	6	10+ years	
	Foundation - Concrete	Entire Building	200	LF	4	1-2 years	Sinking throughout, walls titled.
		g			•	/ 00.0	Scheduled for demolition 2024
	Superstructure - Concrete	Entire Building	23,616	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	6-10 years	
Roof Sys	etem						
TOOL Oy.	Coping - Metal	Main Roof	466	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	75	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Main Roof	11,808	SF	4	0-1 year	Ladder access over 10 feet. To
			,,,,,			,	access roof an piece of metal is used as a foot brace. Unsafe conditions. Cannot access roof. Per Engineer roof leaks throughout
	Roof Hatch - Metal	Main Roof	1	EA	7	6-10 years	•
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Main Roof	11,808	SF	7	10+ years	
Walls							
	Exterior Walls - Precast Panel Wall	Entire Building	6,625	SF	5	2-5 years	
	Exterior Walls - Precast Panel Wall	Entire Building	5,025	SF	3	0-1 year	Walls tilting/cracks/bowing and separation
Windows	3						
	Curtain wall - Louver	Entire Building	160	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	1,376	SF	6	10+ years	
	Windows - Casement Aluminum Double- pane	Entire Building	2,208	SF	6	10+ years	

Campus Name: Mann Page : 28 of 47 Assessment Date: 03/06/2024



Catego	ry : Electrical		Е	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerger	ncy System Automatic Transfer Switch	Electrical Room	1	EA	4	0-1 year	Unable to access the interior of the enclosure at the time of assessment. Unit is 50-plus years old and is producing a loud audible "hum" such as may be associated with an
	Exit Signs - Corridors and Stairs	Entire Building	4	EA	2	0-1 year	electrical disturbance. Quantity changed as total has been divided/aggregated. Location changed for clarification. Signs have no backup batteries and the school has no emergency generator.
	Security System - CCTV	Entire Building	23,616	SF	5	6-10 years	3 7 3
	Security System - Intrusion Detection	Entire Building	23,616	SF	6	6-10 years	
Main Sei	vice						
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	Rank, Reason and Priority Rep adjusted based on current observations. Equipment is 50-plus years old but without undue signs of age-related degradation.
	PA System	Entire Building	23,616	SF	5	1-2 years	Served by Main. PA system employs antiquated technology and operates intermittently.
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	6-10 years	Quantity changed as total has been divided/aggregated. Location changed for clarification.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	4	0-1 year	Item Type changed to match current observations. Rank, Reason and Priority Rep changed as a missing interior cover plate exposes live conductors presenting a live front condition.
Catego	ry : Fire Protection		Е	uilding	: Annex		
Group	Itom - Typo	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group Fire Alar	Item - Type m	Location	Quantity	COM	Nalik	Replacement	Comments
/	Fire ALarm Anunciator	Electrical Room	1	EA	7	6-10 years	

Campus Name: Mann Page : 29 of 47 Assessment Date: 03/06/2024



Category : Fire Protection

Horace Mann Elementary School 8050 S Chappel AVENUE, Chicago, IL 60617

Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm Stype Lights Fire Alarm Stype Lights Fire Alarm Stype Location The Coll Unit Floor Mounted - Electric Entire Building Fan Coil Unit- Floor Mount	category : Fire Protection			Building	: Annex		
Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm Stype Fire Control Fire Building Fire Alarm Stype Fire Alarm Stype Fire Alarm Stype Fire Alarm Stype Fire Control Fire Building Fire Alarm Stype Fire Alarm Stype Fire Control Fire Building Fire Alarm Stype Fire Control Fire Building Fire Alarm Stype Fire Control Fire Building Fire Alarm Stype Fire Coll years Fire Coll years F							
Fire Alarm Strobe Lights Electrical Room 23,616 SF 7 10+ years Fire Alarm_System Electrical Room 23,616 SF 7 10+ years Fire Alarm_System Electrical Room 23,616 SF 7 10+ years Followers Follo	, , , , , , , , , , , , , , , , , , ,						
Category : Mechanical Building : Annex Recommend Group Item Type Location Guantity UOM Rank Replacement Fan Coil Unit- Floor Mounted - Electric Fan Coil U			·			•	No CPS Asset Tag present.
Category : Mechanical Building : Annex Replacement Comments				_			
Recommend Replacement Recommend Replacement Comments	Fire Alarm_System	Electrical Room	23,616	SF	7	6-10 years	
Strough Item - Type Location Quantity UOM Rank Replacement Comments	Category : Mechanical		i	Building	: Annex		
Air Handling Systems Fan Coil Unit- Floor Mounted - Electric Entire Building Fan Coil							
Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in Select	Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected froughout the build Located	Air Handling Systems						
Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Located in s	Fan Coil Unit- Floor Mounted - Electric	Entire Building	1	EA	6	6-10 years	Located in selected classrooms throughout the building.
Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Early Entire Building 1 EA 6 6-10 years Located in selected throughout the build Early Entire Building 1 EA 6 6-10 years Located in selected throughout the build Early Entire Building 1 EA 6 6-10 years Located in selected throughout the build Early Entire Building 1 EA 6 6-10 years Located in selected throughout the build Early Entire Building 1 EA 6 6-10 years Located in selected throughout the build Early Entire Building 1 EA 6 6-10 years Located in selected throughout the build Early Entire Building 1 EA 6 6-10 years Located in selected throughout the build Early Entire Building Entire Building 1 EA 6 6-10 years Located in selected throughout the build Early Entire E	Fan Coil Unit- Floor Mounted - Electric	Entire Building	1	EA	6	6-10 years	Located in selected classrooms throughout the building.
Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Entire Building 1 EA 6 6-10 years Located in selected throughout the build Located in	Fan Coil Unit- Floor Mounted - Electric	Entire Building	1	EA	6	6-10 years	Located in selected classrooms
Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Earlie Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Earlie Entire Building 1 EA 6 6-10 years Located in selected throughout the build Heating Devices Wall Heater - Electric Entire Building 15 EA 6 6-10 years Quantity changed to observations. PTAC - Electric Heating and Self Contained Cooling Entire Building 1 EA 6 6-10 years Cooling PTAC - Electric Heating and Self Contained Entire Building 2 EA 4 0-1 year Quantity changed at divided/aggregated. and Priority Rep cha are nonfunctional. Temperature Control Electric Thermostat Entire Building 7 EA 6 6-10 years Quantity changed to observations. Temperature Control Entire Building 7 EA 6 6-10 years Quantity changed to observations. Temp for the seven floor meaning devices, while equipment is provide internal thermostats. Unit Ventilation	Fan Coil Unit- Floor Mounted - Electric	Entire Building	1	EA	6	6-10 years	Located in selected classrooms
Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Located in selected throughout Located in selected throughout the build Located in selected throughout Located Indicated Located Indica	Fan Coil Unit- Floor Mounted - Electric	Entire Building	1	EA	6	6-10 years	Located in selected classrooms
Fan Coil Unit- Floor Mounted - Electric Entire Building 1 EA 6 6-10 years Located in selected throughout the build Heating Devices Wall Heater - Electric Entire Building 15 EA 6 6-10 years Quantity changed to observations. PTAC - Electric Heating and Self Contained Cooling PTAC - Electric Heating and Self Contained Entire Building 2 EA 4 0-1 year Quantity changed as divided/aggregated. And Priority Rep charge are nonfunctional. Temperature Control Electric Thermostat Entire Building 7 EA 6 6-10 years Quantity changed to observations. Temp for the seven floor meating devices, while equipment is provide internal thermostats. Unit Ventilation	Fan Coil Unit- Floor Mounted - Electric	Entire Building	1	EA	6	6-10 years	Located in selected classrooms
Wall Heater - Electric Entire Building 15 EA 6 6-10 years Quantity changed to observations. PTAC - Electric Heating and Self Contained Cooling PTAC - Electric Heating and Self Contained Cooling PTAC - Electric Heating and Self Contained Entire Building 2 EA 4 0-1 year Quantity changed as divided/aggregated. and Priority Rep cha are nonfunctional. Temperature Control Electric Thermostat Entire Building 7 EA 6 6-10 years Quantity changed to observations. Temp for the seven floor meating devices, while equipment is provide internal thermostats. Unit Ventilation	Fan Coil Unit- Floor Mounted - Electric	Entire Building	1	EA	6	6-10 years	Located in selected classrooms
Wall Heater - Electric Entire Building PTAC - Electric Heating and Self Contained Entire Building Cooling PTAC - Electric Heating and Self Contained Entire Building Cooling PTAC - Electric Heating and Self Contained Entire Building Cooling Entire Building Entire Building Entire Building Temperature Control Electric Thermostat Entire Building Entire Building Temperature Control Electric Thermostat Entire Building Entire Building Temperature Control Electric Thermostat Entire Building Ent							throughout the bulluling.
PTAC - Electric Heating and Self Contained Entire Building PTAC - Electric Heating and Self Contained Cooling PTAC - Electric Heating and Self Contained Entire Building PTAC - Electric Heating and Self Contained Entire Building Cooling PTAC - Electric Heating and Self Contained Entire Building PTAC - Electric Heating and Self Contain							
Cooling PTAC - Electric Heating and Self Contained Entire Building Cooling 2 EA 4 0-1 year Quantity changed as divided/aggregated. and Priority Rep cha are nonfunctional. Temperature Control Electric Thermostat Entire Building 7 EA 6 6-10 years Quantity changed to observations. Temp for the seven floor meating devices, whi equipment is provide internal thermostats. Unit Ventilation	Wall Heater - Electric	Entire Building	15	EA	6	6-10 years	Quantity changed to match current observations.
Cooling divided/aggregated. and Priority Rep cha are nonfunctional. Temperature Control Electric Thermostat Entire Building 7 EA 6 6-10 years Quantity changed to observations. Temp for the seven floor m heating devices, whi equipment is provide internal thermostats. Unit Ventilation		Entire Building	1	EA	6	6-10 years	
Electric Thermostat Entire Building 7 EA 6 6-10 years Quantity changed to observations. Temp for the seven floor meating devices, which equipment is provided internal thermostats. Unit Ventilation	· · · · · · · · · · · · · · · · · · ·	Entire Building	2	EA	4	0-1 year	Quantity changed as total has been divided/aggregated. Rank, Reason and Priority Rep changed as the unit are nonfunctional.
observations. Temp for the seven floor meating devices, which is provided internal thermostats. Unit Ventilation	Temperature Control						
	Electric Thermostat	Entire Building	7	EA	6	6-10 years	Quantity changed to match current observations. Temperature control for the seven floor mounted fan coil heating devices, while other equipment is provided with integral internal thermostats.
	Unit Ventilation						
Unit Ventilators- Floor Mounted- Electric Entire Building 14 EA 6 6-10 years Location changed to	Unit Ventilators- Floor Mounted- Electric	Entire Building	14	EA	6	6-10 years	Location changed for clarification.

Building: Annex

Campus Name: Mann Page: 30 of 47 Assessment Date: 03/06/2024



Catego	ry : Mechanical		В	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
огоар	Heating & DX Cooling Coil W/ Self Contained Compressor	23341611	quantity		, rum	Keplusomoni	Quantity changed to match current observations, per review with Building Engineer, and as the total has been divided/aggregated. Dataplates inaccessible. Units are well maintained and fully operational vintage equipment.
/entilation	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	6	6-10 years	Quantity changed as total has been divided/aggregated. Not directly accessible in a safe manner at the time of assessment due to unreliable climbing means.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	4	1-2 years	Not directly accessible in a safe manner at the time of assessment due to unreliable climbing means. Rank, Reason and Priority Rep established based on the unit missing its primary housing cover, exposing the motor assembly to the elements.
Catego	ry : Plumbing		В	uilding	: Annex		
	, and the second se					Recommend	

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wat		Location	Quantity	COM	Rank	Replacement	Comments
	Electric Heater - 20 - 50 KW	1st Floor	1	EA	5	2-5 years	Rank, Reason and Priority Rep established based on current observations and on the age of the unit as it has reached the end of its anticipated service life. Location changed for clarification.
	Electric Heater - 20 - 50 KW	1st Floor	1	EA	4	1-2 years	Rank, Reason and Priority Rep established based on current observations that the unit shows considerable signs of age-related deterioration and signs of leakage. Location changed for clarification.
Piping							
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	23,616	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	23,616	SF	6	6-10 years	

Campus Name: Mann Page : 31 of 47 Assessment Date: 03/06/2024



Catego	ry : Plumbing		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	(Horizontal Lines)						
	Domestic Piping-Hot/Cold Water Supply	Entire Building	23,616	SF	6	6-10 years	
	(Risers)	· ·				•	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	23,616	SF	6	6-10 years	
	(from Risers to Fixtures)	_				•	
	Sanitary Piping	Entire Building	23,616	SF	6	6-10 years	
	Storm Piping	Entire Building	23,616	SF	6	6-10 years	
	Vent Piping	Entire Building	23,616	SF	6	6-10 years	
	. •	· ·				•	
Pumps							
	Pumps - Sump-Simplex	1st Floor	1	EA	6	6-10 years	Priority Rep adjusted based on current observations. No CPS Asset Tag present.

Category: Room **Building: Annex**

0	Ham. Toma	Location	0	11014	DI	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	AC Unit	1st - Assistant Principals Office - Vacant	1	EA	7	6-10 years	
	Ceiling - Lay-in	1st - Assistant Principals Office - Vacant	322	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st - Assistant Principals Office - Vacant	1	EA	7	10+ years	
	Floor - Tile	1st - Assistant Principals Office - Vacant	322	SF	7	10+ years	
	Lighting - Lay-in	1st - Assistant Principals Office - Vacant	1	EA	7	6-10 years	
	Lighting - Lay-in	1st - Assistant Principals Office - Vacant	1	EA	5	1-2 years	Missing cover
	Lighting - Pendent/Surface	1st - Assistant Principals Office - Vacant	1	EA	7	6-10 years	
	Power Distribution	1st - Assistant Principals Office - Vacant	10	EA	7	10+ years	
	Walls - Metal Panel	1st - Assistant Principals Office - Vacant	400	SF	7	10+ years	
	Walls - Plaster/Drywall	1st - Assistant Principals Office - Vacant	133	SF	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st - Lunchroom 1	747	SF	7	10+ years	
	Ceiling - Lay-in	1st - Lunchroom 1	16	SF	5	1-2 years	Damaged tile
	Doors - Steel Doors incl hw	1st - Lunchroom 1	1	EA	7	10+ years	

Campus Name: Mann Page : 32 of 47 Assessment Date: 03/06/2024



Catego	ry : Room		В	uildina	: Annex		550 C Chapper Avervoe, Chicago, ie 60017
54.590	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st - Lunchroom 1	738	SF	7	10+ years	
	Floor - Tile	1st - Lunchroom 1	25	SF	4	1-2 years	Damaged tile
	Lighting - Lay-in	1st - Lunchroom 1	12	ĒΑ	7	6-10 years	3
	Walls - Metal Panel	1st - Lunchroom 1	229	SF	7	10+ years	
	Walls - Plaster/Drywall	1st - Lunchroom 1	456	SF	7	10+ years	
	Ceiling - Lay-in	1st - Lunchroom 2	757	SF	7	10+ years	
	Chalk Board	1st - Lunchroom 2	16	LF	4	2-5 years	Obsolete
	Doors - Steel Doors incl hw	1st - Lunchroom 2	1	ĒΑ	7	10+ years	
	Floor - Tile	1st - Lunchroom 2	732	SF	6	10+ years	
	Floor - Tile	1st - Lunchroom 2	25	SF	4	1-2 years	Damaged floor
	Lighting - Lay-in	1st - Lunchroom 2	12	EΑ	7	6-10 years	zamagea neer
	Walls - Metal Panel	1st - Lunchroom 2	633	SF	7	10+ years	
	Walls - Plaster/Drywall	1st - Lunchroom 2	121	SF	7	10+ years	
	Walls - Plaster/Drywall	1st - Lunchroom 2	20	SF	4	1-2 years	Damaged wall
	Ceiling - Lay-in	1st - Serving area between	258	SF	7	10+ years	Damagoa wan
	Coming Lay III	lunchrooms	200	01	,	101 yours	
	Doors - Steel Doors incl hw	1st - Serving area between	1	EA	7	10+ years	
	Doors Gleer Doors mer nw	lunchrooms	'	L/ \	,	101 years	
	Floor - Tile	1st - Serving area between	258	SF	7	10+ years	
	1 loor - Tile	lunchrooms	230	OI.	'	10+ years	
	Lighting - Lay-in	1st - Serving area between	2	EA	7	6-10 years	
	Lighting - Lay-in	lunchrooms	۷	LA	′	0-10 years	
	Lighting - Pendent/Surface	1st - Serving area between	1	EA	7	6-10 years	Switch not located
	Lighting - Pendent/Surface	lunchrooms	'	EA	,	0-10 years	Switch not located
	Conting Line		15	LF	7	10	
	Serving Line	1st - Serving area between	15	LF	7	10+ years	
	Ctorogo/Cloopt	lunchrooms	45	C.E.	7	10	
	Storage/ Closet	1st - Serving area between	15	SF	7	10+ years	
	M II M (I D)	lunchrooms	400	0.5	-	4.0	
	Walls - Metal Panel	1st - Serving area between	192	SF	7	10+ years	
	M II DI (/D II	lunchrooms	400	0.5	-	4.0	
	Walls - Plaster/Drywall	1st - Serving area between	129	SF	7	10+ years	
		lunchrooms					
_MDF_ID							
	Doors - Steel Doors incl hw	1st - inside mechanical room	1	EA	7	10+ years	
	Finishes	1st - inside mechanical room	148	SF	4	1-2 years	Damaged finishes throughout
	Window AC Unit	1st - inside mechanical room	1	EA	7	6-10 years	
Machani	cal/ Service Rooms						
_wechall	Janitor's Closet	1st Floor	47	SF	7	10+ years	
				SF	7 7	•	
	Mechanical/ Service Rooms	1st Floor	291	SF SF		10+ years	Matar damaga
	Storage Room	1st Floor	262		5	2-5 years	Water damage
	Janitor's Closet	2nd Floor	47	SF	7	10+ years	
	Storage Room	2nd Floor	266	SF	5	10+ years	

Campus Name: Mann Page : 33 of 47 Assessment Date: 03/06/2024





ategor	y : Room		В	uilding	: Annex		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
stroon	1						
	Accessories	1st - Boys	203	SF	7	6-10 years	
	Ceiling - Lay-in	1st - Boys	40	SF	5	1-2 years	Damaged tile
	Ceiling - Plaster/Drywall	1st - Boys	163	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st - Boys	4	EA	7	10+ years	
	Floor - Tile	1st - Boys	24	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - Boys	179	SF	7	10+ years	
	Floor Drain	1st - Boys	1	EA	7	10+ years	
	Lavatory	1st - Boys	2	EA	7	10+ years	
	Lighting - Lay-in	1st - Boys	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st - Boys	2	EA	7	6-10 years	
	Partitions	1st - Boys	2	EA	7	10+ years	
	Urinals	1st - Boys	5	EA	7	10+ years	
	Walls - Metal Panel	1st - Boys	530	SF	7	10+ years	
	Water Closet	1st - Boys	2	EA	7	10+ years	
	Accessories	1st - Boys 1st - Girls	247	SF	7	6-10 years	
	Ceiling - Lay-in	1st - Girls 1st - Girls	231	SF	7	10+ years	
			_	SF			Damaged tiles
	Ceiling - Lay-in	1st - Girls	16	Sr EA	5	1-2 years	Damaged tiles
	Doors - Steel Doors incl hw	1st - Girls	4		7	10+ years	
	Floor - Tile	1st - Girls	24	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st - Girls	223	SF	7	10+ years	
	Floor Drain	1st - Girls	1	EA	7	10+ years	
	Lavatory	1st - Girls	2	EA	7	10+ years	
	Lighting - Lay-in	1st - Girls	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st - Girls	2	EA	6	6-10 years	
	Partitions	1st - Girls	7	EA	7	10+ years	
	Walls - Metal Panel	1st - Girls	563	SF	7	10+ years	
	Water Closet	1st - Girls	7	EA	7	10+ years	
	Accessories	1st - Toilet 1 inside Ass. Principal Office	46	SF	7	6-10 years	
	Ceiling - Lay-in	1st - Toilet 1 inside Ass. Principal Office	22	SF	7	10+ years	
	Ceiling - Lay-in	1st - Toilet 1 inside Ass. Principal Office	24	SF	4	1-2 years	Water stained
	Doors - Steel Doors incl hw	1st - Toilet 1 inside Ass. Principal Office	1	EA	7	10+ years	
	Floor - Tile	1st - Toilet 1 inside Ass. Principal Office	46	SF	7	10+ years	
	Lavatory	1st - Toilet 1 inside Ass. Principal Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st - Toilet 1 inside Ass. Principal Office	1	EA	6	6-10 years	
	Walls - Metal Panel	1st - Toilet 1 inside Ass. Principal	126	SF	7	10+ years	





Catego	Category: Room			uilding	: Annex		
Graun	Hom. Tuno	Lagation	Ougatitu-	HOM	Donk	Recommend	Comments
Group	Item - Type	Location Office	Quantity	UOM	Rank	Replacement	Comments
	Walls - Vinyl Coated Gypsum Panel	1st - Toilet 1 inside Ass. Principal Office	126	SF	7	10+ years	
	Water Closet	1st - Toilet 1 inside Ass. Principal Office	1	EA	7	10+ years	
	Accessories	1st - Toilet 2 inside Ass. Principal Office	46	SF	7	6-10 years	
	Ceiling - Lay-in	1st - Toilet 2 inside Ass. Principal Office	46	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st - Toilet 2 inside Ass. Principal Office	1	EA	7	10+ years	
	Floor - Tile	1st - Toilet 2 inside Ass. Principal Office	46	SF	7	10+ years	
	Lavatory	1st - Toilet 2 inside Ass. Principal Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st - Toilet 2 inside Ass. Principal Office	1	EA	7	6-10 years	
	Walls - Metal Panel	1st - Toilet 2 inside Ass. Principal Office	126	SF	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st - Toilet 2 inside Ass. Principal Office	126	SF	7	10+ years	
	Water Closet	1st - Toilet 2 inside Ass. Principal Office	1	EA	7	10+ years	
	Accessories	2nd - Boys	169	SF	7	6-10 years	
	Ceiling - Lay-in	2nd - Boys	169	SF	7	10+ years	
	Ceiling - Lay-in	2nd - Boys	24	SF	4	1-2 years	Water damage
	Doors - Steel Doors incl hw	2nd - Boys	4	EA	7	10+ years	
	Floor - Tile	2nd - Boys	24	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd - Boys	145	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd - Boys	24	SF	4	0-1 year	Cracked
	Floor Drain	2nd - Boys	1	EA	7	10+ years	
	Hand Dryer	2nd - Boys	1	EA	7	6-10 years	
	Lavatory	2nd - Boys	2	EA	7	10+ years	
	Lighting - Lay-in	2nd - Boys	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd - Boys	2	EA	7	6-10 years	
	Partitions	2nd - Boys	2	EA	7	6-10 years	
	Urinals	2nd - Boys	5	EA	7	10+ years	
	Walls - Metal Panel	2nd - Boys	525	SF	7	10+ years	
	Water Closet	2nd - Boys	2	EA	7	10+ years	
	Accessories	2nd - Girls	244	SF	7	6-10 years	
	Ceiling - Lay-in	2nd - Girls	244	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd - Girls	4	EA	7	10+ years	
	Floor - Tile	2nd - Girls	24	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd - Girls	220	SF	7	10+ years	





Catego	Category : Room			Building : Annex						
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Floor Drain	2nd - Girls	1	EA	7	10+ years				
	Hand Dryer	2nd - Girls	1	EA	7	6-10 years				
	Lavatory	2nd - Girls	2	EA	7	10+ years				
	Lighting - Lay-in	2nd - Girls	3	EΑ	7	6-10 years				
	Partitions	2nd - Girls	7	EΑ	7	6-10 years				
	Walls - Metal Panel	2nd - Girls	488	SF	6	10+ years				
	Water Closet	2nd - Girls	7	EΑ	7	10+ years				
	Accessories	2nd - Mens Staff Restroom	49	SF	7	6-10 years				
	Ceiling - Lay-in	2nd - Mens Staff Restroom	25	SF	6	10+ years				
	Ceiling - Lay-in	2nd - Mens Staff Restroom	24	SF	4	0-1 year	Water damage			
	Doors - Steel Doors incl hw	2nd - Mens Staff Restroom	1	EA	7	10+ years				
	Floor - Tile	2nd - Mens Staff Restroom	49	SF	7	10+ years				
	Lavatory	2nd - Mens Staff Restroom	1	EA	7	10+ years				
	Lighting - Pendent/Surface	2nd - Mens Staff Restroom	1	EA	7	6-10 years				
	Walls - Metal Panel	2nd - Mens Staff Restroom	128	SF	7	10+ years				
	Walls - Vinyl Coated Gypsum Panel	2nd - Mens Staff Restroom	128	SF	7	10+ years				
	Water Closet	2nd - Mens Staff Restroom	1	EA	7	10+ years				
	Accessories	2nd - Women Staff Restroom	48	SF	7	6-10 years				
	Ceiling - Lay-in	2nd - Women Staff Restroom	40	SF	7	10+ years				
	Ceiling - Lay-in	2nd - Women Staff Restroom	8	SF	4	1-2 years	Water damage			
	Doors - Steel Doors incl hw	2nd - Women Staff Restroom	1	EA	7	10+ years				
	Floor - Tile	2nd - Women Staff Restroom	48	SF	7	10+ years				
	Lavatory	2nd - Women Staff Restroom	1	EA	7	10+ years				
	Lighting - Pendent/Surface	2nd - Women Staff Restroom	1	EA	7	6-10 years				
	Walls - Metal Panel	2nd - Women Staff Restroom	128	SF	7	10+ years				
	Walls - Vinyl Coated Gypsum Panel	2nd - Women Staff Restroom	128	SF	7	10+ years				
	Water Closet	2nd - Women Staff Restroom	1	EA	7	10+ years				

Building: Annex Category : Classroom

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	,	Location	Quantity	UCIVI	Naiik	Replacement	Comments
_Classroo	om #150 (Other Instructional Use)						
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	745	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	5	1-2 years	Damaged tiles
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	756	SF	6	10+ years	
	Floor - Tile	1st Floor	5	SF	4	1-2 years	Cracking tile
	Lighting - Lay-in	1st Floor	12	EΑ	7	6-10 years	
	Walls - Metal Panel	1st Floor	498	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	360	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	50	SF	5	1-2 years	Damaged plaster

Campus Name: Mann Page : 36 of 47 Assessment Date: 03/06/2024



Catego	Category : Classroom			uildina	: Annex		30 3 Chapper AVENUE, Chicago, IL 60617
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #152 (Store Room)						
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	725	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	4	1-2 years	Damaged tile
	Chalk Board	1st Floor	16	LF	4	2-5 years	-
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	741	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Walls - Metal Panel	1st Floor	762	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	75	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	60	SF	4	1-2 years	Damaged wall
_Classroo	om #154 (Other Instructional Use)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	738	SF	7	10+ years	
	Chalk Board	1st Floor	16	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	738	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	760	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	4	1-2 years	Damaged wall
_Classroo	om #156 (Store Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	719	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	24	SF	4	1-2 years	Damaged tile
	Chalk Board	1st Floor	16	LF	4	2-5 years	3
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	743	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Walls - Metal Panel	1st Floor	762	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	110	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	25	SF	4	1-2 years	Damaged wall
_Classroo	om #157 (Store Room)						
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	741	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	4	1-2 years	Damaged
	Chalk Board	1st Floor	16	LF	4	2-5 years	····~g~~
				<u> </u>	•	7 00.0	

Campus Name: Mann Page : 37 of 47 Assessment Date: 03/06/2024



Catego	ry : Classroom	Category : Classroom			: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	754	SF	7	10+ years	
	Floor - Tile	1st Floor	3	SF	4	1-2 years	Damaged tile
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	ŭ
	Walls - Metal Panel	1st Floor	768	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	114	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	25	SF	4	1-2 years	Damaged wall
Classroc	om #158 (Store Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	727	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	5	1-2 years	Damaged tile
	Chalk Board	1st Floor	16	LF	4		Damaged tile
	Doors - Steel Doors incl hw	1st Floor	10	EA	7	2-5 years	
						10+ years	
	Floor - Tile	1st Floor	743	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	763	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	109	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	25	SF	4	1-2 years	Damaged wall
Classroc	om #159 (Store Room)						
	Ceiling - Lay-in	1st Floor	733	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	32	SF	5	1-2 years	Damaged tile
	Chalk Board	1st Floor	15	LF	4	2-5 years	ŭ
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	765	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Walls - Metal Panel	1st Floor	500	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	274	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	145	SF	4	1-2 years	Damaged wall
Classroo	om #160 (Other Instructional Use)						
	Casework	1st Floor	8	LF	7	10+ years	
	Casework Ceiling - Lay-in	1st Floor	725	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	36	SF	, 5	•	Damaged wall
	Chalk Board	1st Floor	16	SF LF		1-2 years	Damayeu wali
					4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	761	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Walls - Metal Panel	1st Floor	498	SF	7	10+ years	

Campus Name: Mann Page : 38 of 47 Assessment Date: 03/06/2024



atego	ry : Classroom	B	Building : Annex				
	Home Time	Lacation	Overetite.	LIOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	351	SF SF	7	10+ years	Domogod wall
	Walls - Plaster/Drywall	1st Floor	60	SF	4	1-2 years	Damaged wall
Classroo	om #250 (Music Room)						
	AC Units	2nd Floor	4	EA	7	6-10 years	
	Casework	2nd Floor	16	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,784	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	54	SF	7	10+ years	
	Doors - Store Front	2nd Floor	2	EA	7	10+ years	
	Doors - Transom Window	2nd Floor	23	SF	7	10+ years	
	Floor - Tile	2nd Floor	1,775	SF	7	10+ years	
	Floor - Tile	2nd Floor	9	SF	4	1-2 years	Chipped
	Lighting - Lay-in	2nd Floor	26	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	6	EA	7	6-10 years	
	Walls - Metal Panel	2nd Floor	1,099	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	607	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	25	SF	5	1-2 years	Water damage
Classroo	om #252 (Vacant)						
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	741	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	10	EA	7	10+ years	
	Floor - Tile	2nd Floor	741	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Metal Panel	2nd Floor	758	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	125	SF	6	6-10 years	
		2nd Floor	125	SF	5	,	Water damage
	Walls - Plaster/Drywall	2110 F1001	10	SF	Э	1-2 years	Water damage
Classroo	om #253 (Store Room)						
	Ceiling - Lay-in	2nd Floor	243	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	1-2 years	Water damage
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	251	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	Walls - Metal Panel	2nd Floor	490	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	103	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	25	SF	4	0-1 year	Water damage

Campus Name: Mann Page : 39 of 47 Assessment Date: 03/06/2024



Category : Classroom Group Item - Type Location Quantity UOM Rank Replacement Casework 2nd Floor 8 LF 6 10+ years	Comments
Casework 2nd Floor 8 LF 6 10+ years	Comments
Ceiling - Lay-in 2nd Floor 724 SF 6 10+ years	
Ceiling - Lay-in 2nd Floor 12 SF 4 1-2 years	Water damage
Chalk Board 2nd Floor 16 LF 4 2-5 years	
Doors - Steel Doors incl hw 2nd Floor 1 EA 7 10+ years	
Floor - Tile 2nd Floor 736 SF 7 10+ years	
Lighting - Lay-in 2nd Floor 12 EA 7 6-10 years	
Walls - Metal Panel 2nd Floor 772 SF 6 10+ years	
Walls - Plaster/Drywall 2nd Floor 105 SF 6 10+ years	
Walls - Plaster/Drywall 2nd Floor 30 SF 4 0-1 year	Water damage
Classroom #255 (Store Room)	
AC Units 2nd Floor 2 EA 7 6-10 years	
Casework 2nd Floor 8 LF 6 10+ years	
Ceiling - Lay-in 2nd Floor 731 SF 6 10+ years	
Ceiling - Lay-in 2nd Floor 24 SF 5 1-2 years	Sagging
Chalk Board 2nd Floor 16 LF 4 2-5 years	Cagging
Doors - Steel Doors incl hw 2nd Floor 1 EA 7 10+ years	
Floor - Tile 2nd Floor 755 SF 7 10+ years	
Lighting - Lay-in 2nd Floor 12 EA 7 6-10 years	
Marker Board 2nd Floor 10 LF 6 6-10 years	
Walls - Metal Panel 2nd Floor 773 SF 6 10+ years	
	Material and a
Walls - Plaster/Drywall 2nd Floor 30 SF 4 0-1 year	Water damage
_Classroom #256 (Store Room)	
AC Units 2nd Floor 1 EA 7 6-10 years	
Ceiling - Lay-in 2nd Floor 445 SF 6 10+ years	
Chalk Board 2nd Floor 8 LF 4 2-5 years	
Doors - Steel Doors incl hw 2nd Floor 1 EA 7 10+ years	
Floor - Tile 2nd Floor 445 SF 7 10+ years	
Lighting - Lay-in 2nd Floor 4 EA 7 6-10 years	
Walls - Metal Panel 2nd Floor 675 SF 6 10+ years	
Walls - Plaster/Drywall 2nd Floor 81 SF 6 10+ years	
Walls - Plaster/Drywall 2nd Floor 30 SF 4 0-1 year	Water damage
Classroom #257 (Other Instructional Use)	
Casework 2nd Floor 8 LF 6 10+ years	
Ceiling - Lay-in 2nd Floor 744 SF 6 10+ years	
Ceiling - Lay-in 2nd Floor 8 SF 4 1-2 years	Water damage
Chalk Board 2nd Floor 16 LF 4 2-5 years	Tracer damage
Doors - Steel Doors incl hw 2nd Floor 1 EA 7 10+ years	
Floor - Tile 2nd Floor 752 SF 7 10+ years	
1.001 1.10 Zilu 1.001 10T years	



Catego	ry : Classroom		В	uildina	: Annex		30 0 Onapper Avervoe, Onicago, ie 00017
	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Lighting - Lay-in	2nd Floor	12	EΑ	7	6-10 years	
	Walls - Metal Panel	2nd Floor	769	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	138	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	4	0-1 year	Water damage
_Classroo	nm #258 (Vacant)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	741	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	746	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Walls - Metal Panel	2nd Floor	766	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Water damage
	Wallo Flactor/Drywall	2110 1 1001	10	O.	Ü	1 2 youro	vvator damage
Classroo	m #259 (Vacant)						
	Ceiling - Lay-in	2nd Floor	213	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	36	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	249	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	Walls - Metal Panel	2nd Floor	486	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	110	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	4	0-1 year	Water damage
_Classroo	om #260 (Other Instructional Use)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	729	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	1-2 years	Water damage
	Chalk Board	2nd Floor	16	LF	4	2-5 years	3
	Doors - Steel Doors incl hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	741	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Walls - Metal Panel	2nd Floor	765	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	130	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Water damage
Classroo	om #261 (Other Instructional Use)						
	Casework	2nd Floor	8	LF	6	10+ years	
	Cucowork	2110 1 1001	O	LI	U	ioi yeais	



Category : Classroom

Horace Mann Elementary School 8050 S Chappel AVENUE, Chicago, IL 60617

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	747	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	16	SF	4	1-2 years	Water damage
	Chalk Board	2nd Floor	16	LF	4	2-5 years	G
	Doors - Steel Doors incl hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	763	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Walls - Metal Panel	2nd Floor	505	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	393	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	1-2 years	Water damage
	Traile Tractor Bry Wall	2110 1 1001	20	O.	Ü	1 <i>2 youro</i>	Trator damage
Classroo	om #262 (Other Instructional Use)						
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	739	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	24	SF	5	1-2 years	Water damage
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	755	SF	7	10+ years	
	Floor - Tile	2nd Floor	8	SF	4	1-2 years	Missing
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	Wildowig
	Walls - Metal Panel	2nd Floor	504	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	386	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	30	SF	5	1-2 years	Water damage
	vvalio i laotoi/bi y wali	2114 1 1001	00	O.	Ü	1 2 youro	vvator damago
Catego	ry : Interior		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	1,704	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	99	SF	7	10+ years	
	Doors - Side-lite	1st Floor	36	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	ĒΑ	7	10+ years	
	Doors - Transom Window	1st Floor	30	SF	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,831	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	20	SF	4	1-2 years	Cracked and damaged tile
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	4	EΑ	7	6-10 years	
	Walls - Metal Panel	1st Floor	2,979	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,623	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	36	SF	4	1-2 years	Water damage
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	6-10 years	Tratol damage
		<u> - 110 1 1001</u>	_			•	
		2nd Floor	1 630	SE	/	1() ∔ \/∆arc	
	Floor - Tile/Sheet	2nd Floor	1,639	SF SF	7 1	10+ years	Broken
	Floor - Tile/Sheet Floor - Tile/Sheet	2nd Floor	20	SF	4	1-2 years	Broken
	Floor - Tile/Sheet						Broken
	Floor - Tile/Sheet Floor - Tile/Sheet	2nd Floor	20 9	SF	4	1-2 years	Broken

Building : Annex

Recommend



Catego	ry : Interior		Building : Annex					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
•	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years		
	Walls - Metal Panel	2nd Floor	1,567	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	50	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	35	SF	5	0-1 year	Water damage	
Safety								
,	Security Cameras	Entire building	2	EA	7	6-10 years		
Stairs								
	Ceiling - Lay-in	North	113	SF	7	10+ years		
	Ceiling - Lay-in	North	16	SF	4	1-2 years	Water damage	
	Floor - Tile	North	38	SF	7	10+ years	-	
	Handrails	North	61	LF	7	10+ years		
	Lighting - Pendent/Surface	North	1	EΑ	7	6-10 years		
	Stairs - Concrete	North	99	LF	7	10+ years		
	Walls - Metal Panel	North	578	SF	7	10+ years		
	Ceiling - Lay-in	South	117	SF	7	10+ years		
	Ceiling - Lay-in	South	12	SF	4	1-2 years	Water damage	
	Floor - Tile	South	34	SF	7	10+ years		
	Handrails	South	61	LF	7	6-10 years		
	Lighting - Pendent/Surface	South	1	EΑ	7	6-10 years		
	Stairs - Concrete	South	99	LF	7	10+ years		
	Walls - Metal Panel	South	578	SF	7	10+ years		

Campus Name: Mann Page: 43 of 47 Assessment Date: 03/06/2024



Category : Site Building : Site

Calegoi	y : Site		D	ullaing	. Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Asphalt	North	8,000	SF	7	10+ years	
	Surface - Synthetic	West	3,150	SF	7	10+ years	
	•		•			•	
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	9	EΑ	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	1	EΑ	4	1-2 years	Inside yard of modular /sinking
	Olvin Brainago Olio Marinolo	Zittire Cite	•	_, ,		. L youro	melae yara er medalar /emiling
Fencing							
. <u> </u>	Fencing - Chain Link	Entire Site	110	LF	7	10+ years	
	Fencing - Chain Link	Entire Site	1,720	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	40	LF	5	1-2 years	Leaning/missing pieces
	Fencing - Guard Rail	Entire Site	30	LF	7	10+ years	g,g p
	Fencing - New Standard Ornamental	Entire Site	169	LF	7	10+ years	
	3					,	
Landscar	oe						
	Benches	Entire Site	3	EA	7	10+ years	
	Landscape - Grass	Entire Site	13,299	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	2,000	SF	7	10+ years	
	Parkway trees	Entire Site	25	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	800	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	35,261	SF	6	10+ years	
	Play Area - Poured Rubber Surface	Entire Site	1,500	SF	7	10+ years	
	Play Area - Synthetic Turf	Entire Site	5,800	SF	7	10+ years	
	Trash Receptacles	Entire Site	3	EA	7	6-10 years	
	Walking Path - Hardscape- Asphalt	Entire Site	1,335	SF	7	10+ years	
Dankina I	-4						
Parking L	Surface - Asphalt	Parking Lot- North	7,854	SF	5	2-5 years	
	Surface - Asphalt	Parking Lot- North	7,834 500	SF	4	0-1 year	Cracked
	Surface - Asphalt	Parking Lot- South	22,234	SF	6	10+ years	Ordonou
	Surface - Asphalt	Parking Lot- South	500	SF	5	1-2 years	Cracked surface
	Surface - Asphalt Surface - Concrete	Parking Lot- South	2,000	SF	7	10+ years	Ordoned Surface
	Trash Enclosure - Chain Links	Parking Lot- South	1,600	SF	7	10+ years	
	Trasti Etiolosule - Ottalii Eliiks	I diking Lot- South	1,000	OI.	,	10+ years	
Playgrou	nd						
, ,	Equipment - Combo 3-12	West	1	EA	7	10+ years	
	Equipment - Swingset	West	1	EA	7	10+ years	
	Surface - Square Rubber Mats			SF	7		



Category : Site			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Sidewalk	(S						
	Sidewalks - Internal Walks	Entire Site	200	LF	7	10+ years	
	Sidewalks - Internal Walks	Entire Site	183	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	17,505	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	2,100	SF	4	0-1 year	Large cracks, missing sections
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	6	10+ years	
	Monument - Sign	Entire Site	4	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Mann Page: 45 of 47 Assessment Date: 03/06/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary									
				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main				•					
Computer Lab	Regular Classroom	2nd Floor	221	221	730	165	30	N	N
Faculty Lounge	Regular Classroom	1st Floor	112	112	505	100	40	N	N
Faculty Lounge	Regular Classroom	2nd Floor	219	219	730	165	50	N	N
Kindergarten	Library	1st Floor	123	121	860	231	70	N	Υ
Kindergarten	Regular Classroom	1st Floor	117	117	768	125	50	N	N
Kindergarten	Regular Classroom	1st Floor	119	119	720	165	60	N	Υ
Kindergarten	Regular Classroom	1st Floor	120	120	720	165	60	N	Υ
Play Room	Regular Classroom	2nd Floor	235	235	730	165	50	N	N
Pre School	Kindergarten	1st Floor	116/118	116/118	1,246	284	70	N	Υ
Regular Classroom	Regular Classroom	1st Floor	135	135	720	165	60	N	Υ
Regular Classroom	Regular Classroom	1st Floor	216	216	730	165	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	720	180	65	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	720	180	65	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	720	180	65	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	212	212	720	180	65	N	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	720	180	65	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	730	165	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	730	1,635	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	730	165	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	730	165	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	220	220	730	165	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	223	223	730	165	50	N	Υ
Science Classroom	Science Classroom	2nd Floor	222	222	1,016	190	7	N	Υ
Special Education	Regular Classroom	1st Floor	122	122	720	165	60	N	Υ
Building : Annex									
Music Room	Regular Classroom	2nd Floor	250	I -	1,784	176	58	N	N
Other Instructional Use	Regular Classroom	1st Floor	150		761	88	29	N	N
Other Instructional Use	Regular Classroom	1st Floor	154	-	738	88	29	N	Y
Other Instructional Use	Regular Classroom	1st Floor	160	-	761	88	29	N	N
Other Instructional Use	Regular Classroom	2nd Floor	257	-	752	88	29	N	Y
Other Instructional Use	Regular Classroom	2nd Floor	260		741	88	29	N	Y
Other Instructional Use	Regular Classroom	2nd Floor	261	-	763	88	29	N	N
Other Instructional Use	Regular Classroom	2nd Floor	262	<u>-</u>	763	88	29	N	Y
Store Room	Regular Classroom	1st Floor	152	-	763	88	29	N	Y
Store Room	Regular Classroom Regular Classroom	1st Floor	156	-	741	88	29	N	N
Store Room	Regular Classroom Regular Classroom	1st Floor	157	-	757	88	29	N N	Y
Store Room	Regular Classroom Regular Classroom	1st Floor	157	-	743	88	29	N N	Y
Stole Koolii	Regular Classroom	181 11001	158		143	οŏ	29	IN	<u> </u>



Classroom Summary

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Store Room	Regular Classroom	1st Floor	159	-	765	88	29	N	Ν
Store Room	Regular Classroom	2nd Floor	254	-	736	88	29	N	N
Store Room	Regular Classroom	2nd Floor	255	-	755	88	29	N	N
Store Room	Regular Classroom	2nd Floor	256	-	445	22	7	N	N
Store Room	Special Education	2nd Floor	253	-	251	22	7	N	N
Vacant	Regular Classroom	2nd Floor	252	-	741	88	29	N	N
Vacant	Regular Classroom	2nd Floor	258	-	741	88	29	N	Υ
Vacant	Special Education	2nd Floor	259	-	249	22	7	N	N