

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1963	3	65,017
Campus Total			65,017

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance			·			_	
	Entrance Control - Audio and Video	#1- Main Accessible- SE	1	EA	6	6-10 years	
	Exterior Doors - Store Front	#1- Main Accessible- SE	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1- Main Accessible- SE	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#1- Main Accessible- SE	48	LF	6	10+ years	
	Power Door Operator and Controls	#1- Main Accessible- SE	1	EA	4	0-1 year	Not working
	Ramp Handrail - Steel_Ramp Handrail	#1- Main Accessible- SE	75	LF	6	10+ years	-
	Ramps - Concrete	#1- Main Accessible- SE	35	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#1- Main Accessible- SE	20	LF	6	10+ years	
	Exterior Doors - Side lite	#10- N	2	EA	6	6-10 years	
	Exterior Doors - Store Front	#10- N	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#10- N	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	#10- N	40	LF	5	2-5 years	
	Exterior Stairs - Stone	#10- N	10	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#10- N	10	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#10.5 - Roof Doors	2	EA	5	0-1 year	Corrosion
	Exterior Doors - Exterior FRP Door	#2- SE	1	EA	5	6-10 years	
	Exterior Doors - Transom Lite	#2- SE	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#2- SE	12	LF	6	10+ years	
	Exterior Stairs - Stone	#2- SE	3	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#2- SE	7	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#3- SE	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#3- SE	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#3- SE	12	LF	5	0-1 year	Cracking/chipping.
	Exterior Stairs - Stone	#3- SE	3	LF	6	10+ years	3 3
						•	



Category : Exterior			Building : Main				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stair Handrail - Steel_Stair Handrail	#3- SE	7	LF	6	10+ years	
	Exterior Doors - Store Front	#4- SE	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#4- SE	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#4- SE	30	LF	6	10+ years	
	Exterior Stairs - Stone	#4- SE	9	LF	6	10+ years	
	Exterior Doors - Side lite	#5- SW	2	EA	6	6-10 years	
	Exterior Doors - Store Front	#5- SW	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#5- SW	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#5- SW	30	LF	5	2-5 years	
	Exterior Stairs - Stone	#5- SW	8	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#5- SW	10	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	#6- SW	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	#6- SW	25	LF	6	6-10 years	
	Ramp Handrail - Steel_Ramp Handrail	#6- SW	75	LF	6	10+ years	
	Ramps - Concrete	#6- SW	35	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#6- SW	32	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#7- NW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#7- NW	12	LF	6	10+ years	
	Exterior Stairs - Stone	#7- NW	3	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#7- NW	12	LF	6	6-10 years	
	Stair Handrail - Steel_Stair Handrail	#7- NW	12	LF	3	0-1 year	Missing handrail
	Exterior Doors - Exterior Steel Door	#8- Boiler Room- NW	1	EA	6	6-10 years	G
	Exterior Doors - Transom Lite	#8- Boiler Room- NW	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#8- Boiler Room- NW	10	LF	6	10+ years	
	Exterior Stairs - Stone	#8- Boiler Room- NW	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#8.5 - NW - exterior storage	1	EA	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#8.5 - NW - exterior storage	20	LF	6	10+ years	
	Ramps - Concrete	#8.5 - NW - exterior storage	10	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#9- NW	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#9- NW	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#9- NW	12	LF	6	10+ years	
	Exterior Stairs - Stone	#9- NW	3	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#9- NW	10	LF	6	6-10 years	
Eoundet:						•	
_Foundati	Foundation - Concrete	Entire Building	932	LF	7	10+ years	
	Foundation - Concrete Foundation - Concrete	Entire Building Entire Building	932 25	LF LF	7 5	0-1 years	Foundat cracks
	Superstructure - Concrete	Entire Building Entire Building	64,017	SF	7	10+ years	roundat cracks
				SF		•	Clab araska throughout at interior
	Superstructure - Concrete	Entire Building	600	SF SF	5	0-1 year	Slab cracks throughout at interior
	Superstructure - Concrete	Entire Building	400	5F	5	0-1 year	Spalling, loose concrete at exterior.
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	7	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	5	6-10 years	

Campus Name: Mays Page : 2 of 31 Assessment Date: 07/20/2023



Catego	ry : Exterior		В	uilding	: Main		
	_					Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	0-1 year	Missing
Roof Sys	atom						
YOUI Sys	Coping - Metal	Low N roof	90	LF	6	10+ years	
	Downspouts - Interior Downspouts	Low N roof	13	LF	6	10+ years	
	Roof - Modified Bitumen	Low N roof	1,058	SF	5	2-5 years	Some patching
	Roof Structure - Concrete		1,058	SF	7		Some patering
		Low N roof	1,056 277	SF LF		10+ years	
	Coping - Metal	Main center roof			6	10+ years	
	Downspouts - Exterior Downspouts	Main center roof	10	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main center roof	50	LF	6	10+ years	
	Roof - Modified Bitumen	Main center roof	9,450	SF	5	2-5 years	Some patching
	Roof Hatch - Metal	Main center roof	1	EA	7	10+ years	
	Roof Structure - Concrete	Main center roof	9,450	SF	7	10+ years	
	Access Ladder - Metal	Upper N roof	1	EA	7	10+ years	
	Chimney - Brick Chimney- Stainless Steel	Upper N roof	42	LF	6	10+ years	
	Liner				•	40	
	Chimney - Metal Flue	Upper N roof	86	LF	6	10+ years	
	Coping - Metal	Upper N roof	391	LF	6	10+ years	
	Downspouts - Interior Downspouts	Upper N roof	72	LF	6	10+ years	
	Roof - Modified Bitumen	Upper N roof	7,988	SF	6	6-10 years	
	Roof Structure - Concrete	Upper N roof	7,988	SF	7	10+ years	
	Access Ladder - Metal	Upper SW roof	1	EA	7	10+ years	
	Coping - Metal	Upper SW roof	422	LF	6	10+ years	
	Downspouts - Interior Downspouts	Upper SW roof	72	LF	6	10+ years	
	Roof - Modified Bitumen	Upper SW roof	9,022	SF	6	6-10 years	
	Roof - Modified Bitumen	Upper SW roof	100	SF	2	0-1 year	Active leak
	Roof Structure - Concrete	Upper SW roof	9,122	SF	7	10+ years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	3,088	SF	6	10+ years	
	Canopy - Concrete/ Stucco	Entire Building	98	SF	6	10+ years	
	Canopy - Concrete/ Stucco	Entire Building	98	SF	6	10+ years	
	Canopy - Concrete/ Stucco	Entire Building	75	SF	5	6-10 years	
	Canopy - Metal	Entire Building	75	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	36	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	36	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	18,164	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	1,860	SF	6	10+ years	
	Exterior Walls - Precast Panel Wall	Entire Building	246	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	1,152	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	185	SF	5	10+ years	

Campus Name: Mays Page : 3 of 31 Assessment Date: 07/20/2023



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Clerestory - Glass Double-Pane	Entire Building	202	SF	6	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	768	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	1,700	SF	6	10+ years	
	Curtain wall - Insulated Panel	Entire Building	189	SF	5	2-5 years	
	Curtain wall - Louver	Entire Building	184	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	3,986	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	264	SF	6	6-10 years	
	Lintels - Steel	Entire Building	93	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	8,052	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System		•			•	
	Automatic Transfer Switch	Electrical Room	3	EA	4	2-5 years	Original, approximately 40 years old.
	Emergency A/C Power - Corridors and	Entire Building	1,060	SF	2	0-1 year	Non existent.
	Stairs	3	,			, , , , ,	
	Emergency A/C Power - Gym	Entire Building	3,243	SF	2	0-1 year	None existent.
	Emergency A/C Power - Lunchrooms	Entire Building	1,324	SF	2	0-1 year	Non existent.
	Emergency A/C Power - Students Toilets	Entire Building	1,632	SF	2	0-1 year	Non existent.
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	7	10+ years	
	Exit Signs - Gym	Entire Building	4	EA	7	10+ years	
	Exit Signs - Lunchroom	Entire Building	1	EA	7	10+ years	
	Security System - CCTV	Entire Building	65,017	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	65,017	SF	6	6-10 years	
Main Se	rvice						
	Independent Electrical Service for	Electrical Room	1	EA	4	1-2 years	Older unit
	emergency power					•	
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	4	1-2 years	Cover missing, corrosion observed.
	PA System	Entire Building	65,017	SF	6	2-5 years	
Power D	istribution Lighting and Power Panels - 100 A	Entiro Buildina		EA	4	0.1.400	Corroded panels.
		Entire Building	2			0-1 year	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	4	0-1 year	Corroded.
	Lighting and Power Panels - Above 100 A	Entire Building	3	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EΑ	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	0-1 year	Older units, corroded.

Campus Name: Mays Page : 4 of 31 Assessment Date: 07/20/2023



Catego	ry : Electrical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Live front.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	
		g	·		-	- · · · · · · · · · · · · · · · · · · ·	
atego	ry : Fire Protection		В	uilding	: Main		
	Mana - T ama	Landin	0	HOM	D I-	Recommend	0
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar	m						
	Fire Alarm Panel	Electrical Room	1	EA	6	10+ years	
	Fire Alarm Strobe Lights	Electrical Room	65,017	SF	6	6-10 years	
	Fire Alarm_System	Electrical Room	65,017	SF	6	6-10 years	
	- ,		,			,	
atego	ry : Mechanical		В	uilding	: Main		
`*a	Itam Tuna	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Item - Type	Location	Quantity	UOW	Kalik	Replacement	Comments
ur Hand	lling Systems	. —					
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 8001-12000 cfm	2nd Floor	1	EA	4	1-2 years	Serves gym. The pipes and valve are rusted.
	Air Intake	2nd Floor	1	EA	5	2-5 years	Air filters packed with dust.
	Air Handling Unit-Package Single Zone-	Boiler Room	1	EA	5	2-5 years	7 til littore packed with adet.
	Indoor- Hot Water Coils - Less than 4000	Bollet Room	'	L/ \	9	2 o yours	
	cfm						
	Air Intake	Boiler Room	1	EA	5	2 E voore	
	Indoor Return Fans- Centrifugal Squirrel	Boiler Room	1	EA	6	2-5 years 6-10 years	
		Bollet Room	I	EA	О	6-10 years	
	Cage - Less than 5000 CFM						
Boiler Sy	vstems						
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	5	6-10 years	
	Pressure Boiler - 101 - 150 HP					-	
	Chemical Feed System	Boiler Room	1	EA	6	2-5 years	
	Chemical Feeder	Boiler Room	1	EA	6	2-5 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EΑ	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	2-5 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	4	2-5 years	Tank rusted and paint peeling off.
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	5	6-10 years	rank rustou and paint peeiing on.
	Steam- Low Pressure Boiler - 101 - 150 HP	Polici I/Ooili	I	LA	5	U-10 years	
		Poilor Poom	1	EA	5	6 10 voors	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	ĽΑ	5	6-10 years	
	Steam- Low Pressure Boiler - 101 - 150 HP	D :	100		_	0.40	
	Piping - Condensate Pipe- Steel	Boiler Room	100	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	100	LF	5	6-10 years	
	Steam Traps	Boiler Room	29	EA	5	6-10 years	

Campus Name: Mays Page : 5 of 31 Assessment Date: 07/20/2023



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Gas Boo							
	Gas Booster	Boiler Room	2	EA	5	2-5 years	
Heat Exc	changers						
	Heat Exchanger - Steam to hot Water Plate Type	Boiler Room	1	EA	5	2-5 years	
Heating	Devices						
Ü	Fin Tube - Hot Water	1st Floor	8	LF	5	6-10 years	Nurses office only.
	Cabinet Heaters - With Hot Water Coil	Entire Building	15	EA	5	2-5 years	
Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	1	EA	7	10+ years	
	Hot Water Pump - Less than 10	Boiler Room	1	EΑ	7	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	300	LF	6	10+ years	
Tempera	ture Control						
	Pneumatic System Thermostats - Pneumatic	Entire Building Entire Building	65,017 47	SF EA	6	2-5 years 2-5 years	New compressor was installed, and all pneumatic lines removed, but DDC system was never installed, just running on local controls. New compressor was installed, and all pneumatic lines removed, but DDC system was never installed, just
	Thermostats - Pneumatic	Entire Building	2	EA	4	0-1 year	running on local controls. Not functional.
Unit Ven							
	Unit Ventilators- Floor Mounted- Hot Water Heating Coils Only	Entire Building	47	EA	6	6-10 years	
Ventilation	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Roof, Boiler Room & Warming Kitchen	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof, Boiler Room & Warming Kitchen	3	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof, Boiler Room & Warming Kitchen	1	EA	3	0-1 year	Does not work.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof, Boiler Room & Warming Kitchen	3	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof, Boiler Room & Warming Kitchen	1	EA	3	0-1 year	Does not work.
	-						



742	JEI 10013					0000	3 Normal BOOLE VARD, Chicago, iL 60621
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Roof Mounted - Less than	Roof, Boiler Room & Warming	2	ΕA	6	6-10 years	
	500 CFM	Kitchen				,	
	Type II Exhaust Hood- Warming Kitchen	Roof, Boiler Room & Warming	1	EA	6	6-10 years	
	.,,p =g	Kitchen			•	- · · · · · · · · · · · · · · · · · · ·	
Catego	ry : Plumbing		R	uilding	· Main		
Juliogo	. y . r .a			unung	· maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	7.	Location	Quantity	OOW	IValik	Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	4	1-2 years	Unit is beyond service life. Burners
							appear corroded. Some piping
							insulation missing. Recently installed
							new temperature control valve,
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	65,017	SF	4	1-2 years	The pipes are rusted and clamped.
							Some fittings are leaking.
	Domestic Piping-Hot Water Return Risers	Entire Building	65,017	SF	4	1-2 years	The pipes are rusted and clamped.
							Some fittings are leaking.
	Domestic Piping-Hot Water from Risers to	Entire Building	65,017	SF	4	1-2 years	The pipes are rusted and clamped.
	Fixtures						Some fittings are leaking.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	65,017	SF	4	1-2 years	The pipes are rusted and clamped.
	(Horizontal Lines)						Some fittings are leaking.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	65,017	SF	4	1-2 years	The pipes are rusted and clamped.
	(Risers)						Some fittings are leaking.
	Domestic Piping-Hot/Cold Water Supply	Entire Building	65,017	SF	4	1-2 years	The pipes are rusted and clamped.
	(from Risers to Fixtures)						Some fittings are leaking.
	Sanitary Piping	Entire Building	65,017	SF	6	6-10 years	
	Storm Piping	Entire Building	65,017	SF	6	6-10 years	
	Vent Piping	Entire Building	65,017	SF	6	6-10 years	
Pumps							
	Pumps - Sump-Duplex	Boiler Room	1	EA	5	2-5 years	
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	AC Unit	100	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	100	829	SF	7	10+ years	
	Doors - Side-lite	100	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	100	1	EA	7	10+ years	
	Floor - Tile	100	829	SF	7	10+ years	
			3_0	٠.	•	121 ,00.0	

Campus Name: Mays Page : 7 of 31 Assessment Date: 07/20/2023



Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	100	10	EA	7	10+ years	
	Power Distribution	100	18	EA	7	10+ years	
	Storage/ Closet	100	83	SF	7	10+ years	
	Walls - Concrete Block	100	1,429	SF	7	10+ years	
	AC Unit	100B	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	100B	370	SF	7	10+ years	
	Doors - Wood Doors inclu hw	100B	1	EA	6	10+ years	
	Floor - Tile	100B	370	SF	7	6-10 years	
	Lighting - Pendent/Surface	100B	8	EA	7	6-10 years	
	Power Distribution	100B	6	EA	7	6-10 years	
	Storage/ Closet	100B	18	SF	7	6-10 years	
	Walls - Concrete Block	100B	704	SF	7	10+ years	
	Ceiling - Plaster/Drywall	114	200	SF	7	10+ years	
	Doors - Wood Doors inclu hw	114	1	EA	7	10+ years	
	Floor - Tile	114	200	SF	7	10+ years	
	Lighting - Pendent/Surface	114	4	EA	7	6-10 years	
	Power Distribution	114	8	EA	7	10+ years	
	Walls - Concrete Block	114	420	SF	7	10+ years	
	AC Unit	114 B	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	114 B	250	SF	7	10+ years	Quantity changed based on current
	,					,	conditions
	Doors - Wood Doors inclu hw	114 B	2	EA	7	10+ years	Quantity changed based on current
						-	conditions
	Floor - Tile	114 B	250	SF	7	10+ years	Quantity changed based on current
							conditions
	Lighting - Pendent/Surface	114 B	6	EA	7	6-10 years	Quantity changed based on current
	-					•	conditions
	Walls - Concrete Block	114 B	460	SF	7	10+ years	Quantity changed based on current
							conditions
	Ceiling - Plaster/Drywall	114A	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	114A	1	EA	7	10+ years	
	Floor - Tile	114A	120	SF	7	10+ years	
	Lighting - Pendent/Surface	114A	4	EA	7	6-10 years	
	Power Distribution	114A	8	EA	7	10+ years	
	Storage/ Closet	114A	10	SF	7	10+ years	
	Walls - Concrete Block	114A	272	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	160	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	160	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years	Rank changed to match current
	-					-	observation
	Power Distribution	1st Floor	4	EA	7	10+ years	
	Storage/ Closet	1st Floor	97	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	303	SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Unit	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	650	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	650	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	6-10 years	
	Power Distribution	1st Floor	2	EΑ	7	10+ years	
	Walls - Concrete Block	1st Floor	760	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	100	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EΑ	7	10+ years	
	Floor - Tile	Basement	100	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	2	EA	7	6-10 years	
	Power Distribution	Basement	8	EA	7	10+ years	
	Storage/ Closet	Basement	20	SF	7	10+ years	
	Walls - Concrete Block	Basement	260	SF	7	10+ years	
	Ceiling - Splined	Room 316	365	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Room 316	1	ĒΑ	7	10+ years	
	Floor - Tile	Room 316	361	SF	7	10+ years	
	Floor - Tile	Room 316	4	SF	4	0-1 year	Broken tiles
	Lighting - Pendent/Surface	Room 316	4	EΑ	6	6-10 years	2. enem mee
	Power Distribution	Room 316	6	ΕA	7	10+ years	
	Walls - Concrete Block	Room 316	668	SF	7	10+ years	
Gymnas	ia						
	Ceiling - Plaster/Drywall	1st Floor	3,243	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	3,243	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	15	EΑ	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Sound System	1st Floor	1	ΕA	7	6-10 years	
	Stage	1st Floor	593	SF	6	10+ years	
	Stage Curtain	1st Floor	8	EΑ	7	6-10 years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	12	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	4,594	SF	7	10+ years	
			1,00	0.		,	
Kitchen	0.111						
	Ceiling - Plaster/Drywall	Room 111B	625	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 111B	3	EA	7	10+ years	
	Floor - Tile Quarry	Room 111B	625	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 111B	15	EA	7	6-10 years	
	Serving Line	Room 111B	18	LF	7	6-10 years	
	Storage/ Closet	Room 111B	80	SF	7	10+ years	
	Walls - Structural Glazed Tile	Room 111B	936	SF	7	ioi youlo	



Category : Room			Building : Main					
Croun	Itam Tuna	Location	Oventity	UOM	Rank	Recommend	Comments	
Group	Item - Type	Location	Quantity	UOW	Kank	Replacement	Comments	
Locker/S	shower Room							
	Accessories	Basement	120	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	Basement	120	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	Basement	2	EA	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	Basement	120	SF	7	10+ years		
	Lavatory	Basement	1	ĒΑ	6	10+ years		
	Lighting - Lay-in	Basement	2	EΑ	6	6-10 years		
	Student Lockers - One Tier	Basement	1	EΑ	7	10+ years		
	Walls - Concrete Block	Basement	220	SF	6	10+ years		
	Water Closet	Basement	1	EA	7	10+ years		
lab 0	Multinumana Dagra							
LUNCH &	Multipurpose Room	Acceptable Lunchus and Act Elect	4.004	- CF		10		
	Ceiling - Splined	Accessible Lunchroom, 1st Floor	1,324	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Accessible Lunchroom, 1st Floor	1	EA	7	10+ years		
	Floor - Tile	Accessible Lunchroom, 1st Floor	1,324	SF	6	10+ years		
	Lighting - Pendent/Surface	Accessible Lunchroom, 1st Floor	24	EA	7	6-10 years		
	Storage/ Closet	Accessible Lunchroom, 1st Floor	80	SF	7	10+ years		
	Walls - Concrete Block	Accessible Lunchroom, 1st Floor	1,536	SF	7	10+ years		
MDF_IDI								
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years		
	Finishes	2nd Floor	234	SF	7	10+ years		
	Window AC Unit	2nd Floor	1	EA	7	6-10 years		
Mechani	cal/ Service Rooms							
	Boiler Room	1st Floor	1,200	SF	7	10+ years		
	Janitor's Closet	1st Floor	45	SF	7	10+ years		
	Storage Room	1st Floor	600	SF	7	10+ years	Quantity changed to match current	
	otorago ricom				•	.o. you.o	observation	
	Vaults	1st Floor	30	SF	7	10+ years		
	Janitor's Closet	2nd Floor	45	SF	5	10+ years	Beside boys bathroom	
	Janitor's Closet	2nd Floor	90	SF	5	10+ years	Beside girls bathroom	
	Storage Room	2nd Floor	410	SF	5	10+ years	Front of classroom 215	
	Storage Room	2nd Floor	134	SF	5	10+ years	Front of door 200	
	Janitor's Closet	3rd Floor	25	SF	7	10+ years		
	Janitor's Closet	3rd Floor	90	SF	7	10+ years		
	Storage Room	Book Room 2nd floor	237	SF	5	6-10 years		
Restroon	n							
. 10000000	Accessories	100D	44	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	100D	44	SF	7	10+ years		
	Doors - Wood Doors inclu hw	100D	1	EA	7	10+ years		
	POOLS - MOOU POOLS HIGH HW	1000	l l	_∧	,	IUT VEGIS		

Campus Name: Mays Page : 10 of 31 Assessment Date: 07/20/2023



Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	100D	44	SF	6	10+ years	
	Lavatory	100D	1	EA	7	10+ years	
	Lighting - Lay-in	100D	1	EA	7	6-10 years	
	Walls - Concrete Block	100D	88	SF	7	10+ years	
	Water Closet	100D	1	EA	7	10+ years	
	Accessories	114A	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	114A	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	114A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	114A	36	SF	7	10+ years	
	Lavatory	114A	1	EA	7	10+ years	
	Lighting - Wall Mounted	114A	1	EA	7	6-10 years	
	Walls - Concrete Block	114A	60	SF	7	10+ years	
	Water Closet	114A	1	EA	7	10+ years	
	Accessories	115A	124	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	115A	124	SF	7	10+ years	
	Doors - Wood Doors inclu hw	115A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	115A	124	SF	7	10+ years	
	Lavatory	115A	1	EA	6	10+ years	
	Lighting - Lay-in	115A	4	EA	7	6-10 years	
	Partitions	115A	1	EA	7	6-10 years	
	Student Lockers - One Tier	115A	6	EA	7	10+ years	
	Walls - Concrete Block	115A	214	SF	7	10+ years	
	Water Closet	115 <u>A</u>	1	EA	7	10+ years	no access door is locked no key
	Accessories	1st Floor	267	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	267	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	267	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EA	7	6-10 years	
	Partitions	1st Floor	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	312	SF	7	10+ years	
	Water Closet	1st Floor	5	EA	7	10+ years	
	Accessories	1st Floor	277	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	277	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	277	SF	7	10+ years	
	Floor Drain	1st Floor	1	EΑ	7	10+ years	
	Hand Dryer	1st Floor	1	EΑ	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EΑ	7	6-10 years	
	Partitions	1st Floor	2	EΑ	7	10+ years	
	Urinals	1st Floor	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	324	SF	7	10+ years	

Campus Name: Mays Page : 11 of 31 Assessment Date: 07/20/2023



Catego	ategory : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor	2	EΑ	7	10+ years	
	Accessories	1st floor unisex - NO ACCESS	40	SF	7	6-10 years	Door was locked, not accessible.
	Ceiling - Plaster/Drywall	1st floor unisex - NO ACCESS	40	SF	6	10+ years	Door was locked, not accessible.
	Doors - Wood Doors inclu hw	1st floor unisex - NO ACCESS	1	EA	6	10+ years	Door was locked, not accessible.
	Floor - Tile	1st floor unisex - NO ACCESS	40	SF	6	10+ years	,
	Lavatory	1st floor unisex - NO ACCESS	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	1st floor unisex - NO ACCESS	1	EA	7	10+ years	
	Partitions	1st floor unisex - NO ACCESS	1	EΑ	7	10+ years	
	Walls - Concrete Block	1st floor unisex - NO ACCESS	69	SF	6	10+ years	
	Water Closet	1st floor unisex - NO ACCESS	1	EΑ	7	10+ years	no access
	Accessories	2nd Floor	267	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	267	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	4	EΑ	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	267	SF	6	6-10 years	
	Floor Drain	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	2	EΑ	6	6-10 years	
	Partitions	2nd Floor	5	EA	7	2-5 years	
	Walls - Structural Glazed Tile	2nd Floor	312	SF	6	6-10 years	
	Water Closet	2nd Floor	5	EA	6	6-10 years	
	Accessories	2nd Floor	280	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	280	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	280	SF	6	6-10 years	
	Floor Drain	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	3	EA	6	6-10 years	
	Partitions	2nd Floor	2	EA	7	2-5 years	
	Urinals	2nd Floor	5	EA	6	6-10 years	
	Walls - Structural Glazed Tile	2nd Floor	356	SF	6	6-10 years	
	Water Closet	2nd Floor	2	EA	6	6-10 years	
	Accessories	3rd Floor	267	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	267	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	267	SF	7	6-10 years	
	Floor Drain	3rd Floor	1	EA	7	6-10 years	
	Lavatory	3rd Floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	6-10 years	
	Lighting - Pendent/Surface Lighting - Pendent/Surface	3rd Floor	1	EA	7	6-10 years 6-10 years	rank changed to match current
	Eignang - r endembounace	Sid i looi	1	ĽA	,	0-10 years	observation
	Partitions	3rd Floor	6	EA	7	10+ years	
	Partitions	3rd Floor	1	EA	5	0-1 year	door is bent
	Walls - Structural Glazed Tile	3rd Floor	510	SF	7	10+ years	
	Water Closet	3rd Floor	7	EA	7	10+ years	
						·	

Campus Name: Mays Page : 12 of 31 Assessment Date: 07/20/2023



Catego	Category : Room			uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	3rd Floor	200	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	200	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	200	SF	7	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Lavatory	3rd Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	2	EA	7	6-10 years	
	Partitions	3rd Floor	2	EA	7	10+ years	
	Urinals	3rd Floor	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	480	SF	7	10+ years	
	Water Closet	3rd Floor	2	EA	7	10+ years	
	Accessories	Engineer's office	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's office	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineer's office	1	EΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Engineer's office	25	SF	7	10+ years	
	Lavatory	Engineer's office	1	EΑ	7	10+ years	
	Lighting - Lay-in	Engineer's office	1	ΕA	7	6-10 years	
	Walls - Concrete Block	Engineer's office	60	SF	7	10+ years	
	Water Closet	Engineer's office	1	EA	7	10+ years	
	Accessories	In Kindergarten Room 101 Room	34	SF	7	6-10 years	
	7.0000001100	101A	0.	O.	•	o to youro	
	Ceiling - Plaster/Drywall	In Kindergarten Room 101 Room 101A	34	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Kindergarten Room 101 Room 101A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Kindergarten Room 101 Room 101A	34	SF	7	10+ years	
	Floor Drain	In Kindergarten Room 101 Room 101A	1	EA	7	10+ years	
	Lavatory	In Kindergarten Room 101 Room 101A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Kindergarten Room 101 Room 101A	1	EA	7	10+ years	
	Walls - Concrete Block	In Kindergarten Room 101 Room 101A	42	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	In Kindergarten Room 101 Room 101A	25	SF	7	10+ years	
	Water Closet	In Kindergarten Room 101 Room 101A	1	EA	7	10+ years	
	Accessories	In Pre-K Room 102 Room 102A	34	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Pre-K Room 102 Room 102A	34	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Pre-K Room 102 Room 102A	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Pre-K Room 102 Room 102A	34	SF	7	10+ years	
	Floor Drain	In Pre-K Room 102 Room 102A	1	EA	7	10+ years	
						-	

Campus Name: Mays Page: 13 of 31 Assessment Date: 07/20/2023



Catego	Category : Room			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	In Pre-K Room 102 Room 102A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Pre-K Room 102 Room 102A	1	EA	7	10+ years	
	Walls - Concrete Block	In Pre-K Room 102 Room 102A	25	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	In Pre-K Room 102 Room 102A	42	SF	7	10+ years	
	Water Closet	In Pre-K Room 102 Room 102A	1	EA	7	6-10 years	
	Accessories	Men's Room, 2nd Floor	89	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Men's Room, 2nd Floor	89	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Men's Room, 2nd Floor	1	EA	6	10+ years	
	Floor - Tile	Men's Room, 2nd Floor	80	SF	6	10+ years	
	Floor - Tile	Men's Room, 2nd Floor	9	SF	4	0-1 year	Damaged
	Lavatory	Men's Room, 2nd Floor	1	EA	6	6-10 years	· ·
	Lighting - Pendent/Surface	Men's Room, 2nd Floor	2	EA	7	6-10 years	
	Partitions	Men's Room, 2nd Floor	1	EA	5	2-5 years	
	Urinals	Men's Room, 2nd Floor	1	EA	7	10+ years	
	Walls - Concrete Block	Men's Room , 2nd Floor	147	SF	6	10+ years	
	Water Closet	Men's Room , 2nd Floor	1	EA	6	6-10 years	
	Accessories	Room 316A, In Teacher's Lounge	94	SF	7	6-10 years	Rank changed to match current
		,				,	observation
	Ceiling - Plaster/Drywall	Room 316A, In Teacher's Lounge	94	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 316A, In Teacher's Lounge	1	EA	7	10+ years	
	Floor - Tile	Room 316A, In Teacher's Lounge	80	SF	6	10+ years	
	Floor - Tile	Room 316A, In Teacher's Lounge	14	SF	4	0-1 year	Missing floor tiles
	Lavatory	Room 316A, In Teacher's Lounge	1	ĒΑ	6	10+ years	3
	Lighting - Pendent/Surface	Room 316A, In Teacher's Lounge	1	EA	6	6-10 years	
	Lighting - Wall Mounted	Room 316A, In Teacher's Lounge	1	EA	5	1-2 years	Cover missing
	Partitions	Room 316A, In Teacher's Lounge	2	EA	7	10+ years	Rank changed to match current
						·	observation
	Walls - Concrete Block	Room 316A, In Teacher's Lounge	163	SF	7	10+ years	
	Water Closet	Room 316A, In Teacher's Lounge	2	EA	7	10+ years	
	Accessories	Unisex Restroom, 2nd Floor, T207	96	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Unisex Restroom, 2nd Floor, T207	91	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	Unisex Restroom, 2nd Floor, T207	5	SF	4	0-1 year	Hole.
	Doors - Wood Doors inclu hw	Unisex Restroom, 2nd Floor, T207	1	EA	6	10+ years	
	Floor - Tile	Unisex Restroom, 2nd Floor, T207	96	SF	6	10+ years	
	Lavatory	Unisex Restroom, 2nd Floor, T207	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Unisex Restroom, 2nd Floor, T207	1	EA	5	0-1 year	No cover
	Lighting - Wall Mounted	Unisex Restroom, 2nd Floor, T207	1	EA	5	2-5 years	
	Partitions	Unisex Restroom, 2nd Floor, T207	2	EA	5	10+ years	
	Walls - Concrete Block	Unisex Restroom, 2nd Floor, T207	116	SF	6	10+ years	
	Water Closet	Unisex Restroom, 2nd Floor, T207	2	EA	6	6-10 years	
	Accessories	next to 109	72	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	next to 109	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	next to 109	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	next to 109	72	SF	7	10+ years	

Campus Name: Mays Page : 14 of 31 Assessment Date: 07/20/2023



Category : Room

Benjamin E Mays Elementary Academy 6656 S Normal BOULEVARD, Chicago, IL 60621

Group	Item - Type Floor Drain	Location	Quantity	UOM		Recommend	
Group		Location	Quantity	LION			
	Floor Drain		Quantity	UOW	Rank	Replacement	Comments
		next to 109	1	EA	7	10+ years	
	Hand Dryer	next to 109	1	EA	7	6-10 years	
	Lavatory	next to 109	1	EA	7	10+ years	
	Lighting - Pendent/Surface	next to 109	1	EΑ	7	10+ years	
	Walls - Concrete Block	next to 109	150	SF	7	10+ years	
	Water Closet	next to 109	1	EA	7	10+ years	
	valor closet	HOXE TO TOO	•		•	101 youro	
`atonor	y : Classroom		B	uilding	· Main		
Jalegor	y . Ciassiooni		ь	unung	. IVIAIII	December	
	Ham Time	Lanation	O. antitu	ПОМ	Dank	Recommend	Comments
-	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroor	m #101 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	48	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	998	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	998	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	ĒA	7	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Storage/ Closet	1st Floor	36	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,158	SF	7	10+ years	
	Work Sink	1st Floor	1,130	EA	7	10+ years	
	Work Clink	1001	•		•	101 youro	
Classroor	m #102 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	48	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	998	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	998	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	6-10 years	
	Marker Board	1st Floor	18	LF	7	10+ years	
	Storage/ Closet	1st Floor	36	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,158	SF	7	10+ years	
	Work Sink	1st Floor	1,130	EA	7	10+ years	
	WOIR SILIK	13111001	ı	LA	,	10+ years	
lassroor	m #103 (Computer Lab)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	822	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	822	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	622	SF	6	10+ years	
	20.0.0.0		JLL	٥.	•	.c. jouro	

Building: Main

Campus Name: Mays Page : 15 of 31 Assessment Date: 07/20/2023



	Category : Classroom		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Plaster/Drywall	1st Floor	207	SF	6	10+ years		
Classroo	m #104 (Kindergarten)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	24	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	822	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	820	SF	6	10+ years		
	Floor - Tile	1st Floor	2	SF	4	0-1 year	Cracked tiles	
	Lighting - Pendent/Surface	1st Floor	16	ĒΑ	7	6-10 years		
	Marker Board	1st Floor	32	LF	7	6-10 years		
	Storage/ Closet	1st Floor	36	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	829	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	72	SF	7	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		
Classroo	m #105 (Kindergarten)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	24	LF	6	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor	822	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	822	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years		
	Marker Board	1st Floor	32	LF	7	6-10 years		
	Storage/ Closet	1st Floor	36	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	829	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor	72	SF	7	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		
Classroo	m #106 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		
	Casework	1st Floor	24	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	822	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	802	SF	6	10+ years		
	Floor - Tile	1st Floor	20	SF	4	0-1 year	Cracked floor tiles.	
	Lighting - Pendent/Surface	1st Floor	16	ĒΑ	7	6-10 years		
	Marker Board	1st Floor	32	LF	7	6-10 years		
	Storage/ Closet	1st Floor	36	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	829	SF	7	10+ years		
Classroo	m #107 (Regular Classroom)							
	AC Units	1st Floor	1	EA	7	6-10 years		



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	36	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	6-10 years	
	Floor - Carpet	1st Floor	530	SF	7	6-10 years	
	Floor - Tile	1st Floor	200	SF	7	10+ years	Quantity changed based on currer
						•	observation
	Lighting - Pendent/Surface	1st Floor	20	EΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	982	SF	7	10+ years	
`lassroo	om #108 (Regular Classroom)						
1000100	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	36	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA			
					6	10+ years	
	Floor - Tile	1st Floor	729	SF	7	10+ years	D 1 47
	Floor - Tile	1st Floor	1	SF	4	0-1 year	Broken tiles
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	982	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	72	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassroc	om #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	36	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	730	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	700	SF	6	10+ years	
	Floor - Tile	1st Floor	30	SF			Cracked floor tiles
					4	0-1 year	Cracked floor tiles
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	40	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	982	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassroc	om #111 (Lunch Room)						
	Ceiling - Plaster/Drywall	1st Floor	822	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	822	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Lighting - i endent/ounace	13(1100)	10		,	o-10 years	

Campus Name: Mays Page: 17 of 31 Assessment Date: 07/20/2023



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	32	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	829	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #203 (Art Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	822	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	822	SF	7	10+ years	
	Instructional Surface	2nd Floor	6	LF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	15	EΑ	6	2-5 years	
	Lighting - Pendent/Surface	2nd Floor	1	ΕA	5	0-1 year	Damaged
	Marker Board	2nd Floor	32	LF	7	6-10 years	244904
	Storage/ Closet	2nd Floor	24	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	829	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
	Work Clink	2110 1 1001	•		•	o ro youro	
Classroo	m #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	822	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	760	SF	7	10+ years	
	Floor - Tile	2nd Floor	62	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	•
	Marker Board	2nd Floor	32	LF	7	10+ years	
	Storage/ Closet	2nd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	829	SF	7	10+ years	
Classroo	m #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	822	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	722	SF	6	10+ years	
	Floor - Tile	2nd Floor	100	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	32	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	36	SF	5	10+ years	
	Walls - Concrete Block	2nd Floor	829	SF	7	10+ years	
	Control Dion	2.10.1.1001	323	٥.	•	.c. youro	
Classroo	m #206 (Regular Classroom)						

Campus Name: Mays Page: 18 of 31 Assessment Date: 07/20/2023



atego	ry : Classroom		В	uilding	: Main				
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	AC Units	2nd Floor	1	EΑ	7	6-10 years			
	Casework	2nd Floor	24	LF	6	6-10 years			
	Ceiling - Splined	2nd Floor	822	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years			
	Floor - Tile	2nd Floor	722	SF	6	10+ years			
	Floor - Tile	2nd Floor	100	SF	4	0-1 year	Damaged		
	Lighting - Pendent/Surface	2nd Floor	16	ĒΑ	6	6-10 years			
	Marker Board	2nd Floor	32	LF	7	10+ years			
	Storage/ Closet	2nd Floor	36	SF	5	6-10 years			
	Walls - Concrete Block	2nd Floor	829	SF	7	10+ years			
:lassror	om #207 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor 2nd Floor	36	LF	6	6-10 years			
	Casework Ceiling - Splined	2nd Floor	730	SF	7	-			
	Doors - Wood Doors inclu hw			EA	6	10+ years			
		2nd Floor	1		-	10+ years			
	Floor - Tile	2nd Floor	630	SF SF	6	10+ years	Damagad		
	Floor - Tile	2nd Floor	100		4	0-1 year	Damaged		
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years			
	Marker Board	2nd Floor	36	LF	7	10+ years			
	Storage/ Closet	2nd Floor	40	SF	5	10+ years			
	Walls - Concrete Block	2nd Floor	982	SF	7	10+ years			
lassroc	om #208 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	36	LF	6	6-10 years			
	Ceiling - Splined	2nd Floor	730	SF	7	6-10 years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	670	SF	7	10+ years			
	Floor - Tile	2nd Floor	60	SF	4	0-1 year	Damaged		
	Lighting - Pendent/Surface	2nd Floor	15	ĒΑ	7	6-10 years	3.0		
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	0-1 year	Damaged		
	Marker Board	2nd Floor	36	LF	7	10+ years	_ aagoa		
	Storage/ Closet	2nd Floor	40	SF	5	6-10 years			
	Walls - Concrete Block	2nd Floor	982	SF	7	10+ years			
lassroc	om #209 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	36	LF	6	10+ years			
	Casework Ceiling - Splined	2nd Floor	730	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	130	EA	6	10+ years			
	Floor - Tile	2nd Floor 2nd Floor	670	SF	6	-			
				SF SF		10+ years	Damagad		
	Floor - Tile	2nd Floor	60	SF.	4	0-1 year	Damaged		

Campus Name: Mays Page : 19 of 31 Assessment Date: 07/20/2023



Catego	Category : Classroom		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	36	LF	7	10+ years	
	Walls - Concrete Block	2nd Floor	982	SF	7	10+ years	
Classroo	om #210 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	36	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	705	SF	6	2-5 years	
	Floor - Tile	2nd Floor	25	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	13	ĒΑ	6	6-10 years	g
	Lighting - Pendent/Surface	2nd Floor	3	ΕA	5	0-1 year	Damaged
	Marker Board	2nd Floor	36	LF	7	10+ years	24904
	Storage/ Closet	2nd Floor	40	SF	5	6-10 years	
	Walls - Concrete Block	2nd Floor	982	SF	7	10+ years	
Classro	om #211 (Music Room)						
Oldoorox	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	36	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	730	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	700	SF	6	10+ years	
	Floor - Tile	2nd Floor	30	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	Damageu
	Marker Board	2nd Floor	36	LF	7	10+ years	
	Storage/ Closet	2nd Floor	40	SF	5	6-10 years	
	Walls - Concrete Block	2nd Floor	982	SF	7	10+ years	
Classro	om #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	6-10 years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	822	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor 2nd Floor	772	SF	6	2-5 years	
	Floor - Tile	2nd Floor	50	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	16	Sr EA	6	2-5 years	Damayeu
	Marker Board	2nd Floor 2nd Floor	32	LF	7	2-5 years 10+ years	
	Storage/ Closet	2nd Floor 2nd Floor	32	SF			
	Walls - Concrete Block	2nd Floor 2nd Floor	829	SF SF	5 7	6-10 years 10+ years	
		2110 1 1001	323	J.	,	ioi youis	
_Classroo	om #213 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	



Category : Classroom			В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	2nd Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	822	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	780	SF	6	6-10 years	
	Floor - Tile	2nd Floor	42	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	ŭ
	Marker Board	2nd Floor	16	LF	7	10+ years	
	Storage/ Closet	2nd Floor	36	SF	5	6-10 years	
	Walls - Concrete Block	2nd Floor	829	SF	7	10+ years	
Classroo	om #214 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	822	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	790	SF	6	10+ years	
	Floor - Tile	2nd Floor	32	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	Damaged
	Marker Board	2nd Floor	32	LF	7	10+ years	
	Storage/ Closet	2nd Floor	36	SF	, 5	2-5 years	
	Walls - Concrete Block	2nd Floor 2nd Floor		SF SF	5 6		
	Work Sink		829 1	EA	7	10+ years 6-10 years	
	Work Sirik	2nd Floor	1	EA	,	6-10 years	
Classroc	om #215 (Office)						
	Casework	2nd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	360	SF	7	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	6-10 years	
	Floor - Tile	2nd Floor	300	SF	7	10+ years	
	Floor - Tile	2nd Floor	60	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	2nd Floor	8	EA	6	6-10 years	Ç
	Marker Board	2nd Floor	32	LF	7	10+ years	
	Storage/ Closet	2nd Floor	18	SF	5	6-10 years	
	Walls - Concrete Block	2nd Floor	624	SF	7	10+ years	
Classroo	om #216 (Library)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	72	LF	6	6-10 years	
	Ceiling - Splined	2nd Floor	1,456	SF	7	10+ years	
	Ceiling - Splined	2nd Floor	4	SF	4	0-1 year	Damaged
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	6	6-10 years	
	Floor - Carpet	2nd Floor	1,460	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,950	SF	7	10+ years	
	TTAILS CONTOINED DIOUN	Z110 1 1001	1,330	01	,	ioi yeais	

Campus Name: Mays Page : 21 of 31 Assessment Date: 07/20/2023



Catego	ry : Classroom		В	uilding	: Main		
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #216A (Library)						
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	36	LF	6	10+ years	
	Ceiling - Splined	2nd Floor	730	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Carpet	2nd Floor	730	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Walls - Concrete Block	2nd Floor	982	SF	7	10+ years	
						•	
Classroc	m #303 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	24	LF	6	6-10 years	
	Ceiling - Splined	3rd Floor	822	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
	Floor - Tile	3rd Floor	740	SF	5	6-10 years	
	Floor - Tile	3rd Floor	82	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	6	6-10 years	3.0
	Marker Board	3rd Floor	16	LF	7	10+ years	
	Storage/ Closet	3rd Floor	36	SF	5	6-10 years	
	Walls - Concrete Block	3rd Floor	829	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	72	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
						•	
Classroc	m #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	24	LF	6	6-10 years	
	Ceiling - Splined	3rd Floor	822	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	770	SF	6	6-10 years	
	Floor - Tile	3rd Floor	52	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	32	LF	7	10+ years	
	Storage/ Closet	3rd Floor	36	SF	5	6-10 years	
	Walls - Concrete Block	3rd Floor	829	SF	7	6-10 years	
	a John old Blook	3.3 . 1331	020	٥.	•	o lo youlo	
Classroc	m #305 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	24	LF	6	6-10 years	
	Ceiling - Splined	3rd Floor	800	SF	6	10+ years	
	Ceiling - Splined	3rd Floor	22	SF	4	0-1 year	Water damage
			1	ĒΑ	6	10+ years	-
	Doors - Wood Doors inclu hw	3rd Floor			U	IOT VEGIG	

Campus Name: Mays Page : 22 of 31 Assessment Date: 07/20/2023



Category : Classroom		В	uilding	: Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	3rd Floor	22	SF	4	0-1 year	Damaged	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years		
	Marker Board	3rd Floor	32	LF	7	10+ years		
	Storage/ Closet	3rd Floor	36	SF	5	2-5 years		
	Walls - Concrete Block	3rd Floor	829	SF	7	10+ years		
Classroo	om #306 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	24	LF	6	6-10 years		
	Ceiling - Splined	3rd Floor	802	SF	6	6-10 years		
	Ceiling - Splined	3rd Floor	20	SF	4	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	Water damage	
	Floor - Tile	3rd Floor	802	SF	6	10+ years		
	Floor - Tile	3rd Floor	20	SF	4	0-1 year	Damaged	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	Damageu	
		3rd Floor	36	LF	7			
	Marker Board			SF		10+ years		
	Storage/ Closet	3rd Floor	36	SF SF	5	6-10 years		
	Walls - Concrete Block	3rd Floor	829	SF	7	10+ years		
Classroc	om #307 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	36	LF	6	6-10 years		
	Ceiling - Splined	3rd Floor	715	SF	6	10+ years		
	Ceiling - Splined	3rd Floor	15	SF	4	0-1 year	Water damage	
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years		
	Floor - Tile	3rd Floor	700	SF	7	10+ years		
	Floor - Tile	3rd Floor	30	SF	4	0-1 year	Damaged	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	•	
	Marker Board	3rd Floor	36	LF	7	10+ years		
	Storage/ Closet	3rd Floor	10	SF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	982	SF	7	10+ years		
Classroo	om #308 (Regular Classroom)							
	AC Units	3rd Floor	1	EA	7	6-10 years		
	Casework	3rd Floor	36	LF	7	6-10 years		
	Ceiling - Splined	3rd Floor	730	SF	7	6-10 years		
	Doors - Wood Doors inclu hw	3rd Floor	130	EA	6	6-10 years		
	Floor - Tile	3rd Floor	700	SF	6	6-10 years		
	Floor - Tile Floor - Tile			SF SF	_	,	Domogod	
		3rd Floor	30		4	0-1 year	Damaged	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years		
	Marker Board	3rd Floor	36	LF	7	10+ years		
	Storage/ Closet	3rd Floor	40	SF	7	6-10 years		
	Walls - Concrete Block	3rd Floor	982	SF	7	10+ years		

Campus Name: Mays Page : 23 of 31 Assessment Date: 07/20/2023



Category : Classroom			Building : Main			Recommend	
		l anatin :	0	Overstites HOM Base			Comments
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	10+ years	
	Casework	3rd Floor	36	LF	6	2-5 years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	Water damage
	Floor - Tile	3rd Floor	660	SF	6	10+ years	
	Floor - Tile	3rd Floor	70	SF	4	0-1 year	Damaged
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	2-5 years	Damageu
	Marker Board	3rd Floor	36	LF	7	10+ years	
	Storage/ Closet	3rd Floor	40	SF	7		
				SF	7	2-5 years	
	Walls - Concrete Block	3rd Floor	982	5F	/	10+ years	
lassroc	om #310 (Counseling Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	36	LF	6	6-10 years	
	Ceiling - Splined	3rd Floor	696	SF	6	10+ years	
	Ceiling - Splined	3rd Floor	14	SF	4	0-1 year	Damaged ceiling tiles
	Ceiling - Splined	3rd Floor	20	SF	3	0-1 year	Damaged ceiling tiles.
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	zamagea comig mee.
	Floor - Tile	3rd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	3rd Floor	982	SF	7	10+ years	
`loooroo	om #311 (Regular Classroom)						
Jassioc		01 51	4			0.40	
	AC Units	3rd Floor	1	EA LF	7	6-10 years	
	Casework	3rd Floor	36		6	6-10 years	
	Ceiling - Splined	3rd Floor	723	SF	6	10+ years	
	Ceiling - Splined	3rd Floor	7	SF	4	0-1 year	Missing tile
	Doors - Wood Doors inclu hw	3rd Floor	_1	EA	4	0-1 year	Broken door handle
	Floor - Tile	3rd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years	
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	982	SF	7	10+ years	
lassroc	om #312 (Art Room)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	24	LF	6	2-5 years	
	Ceiling - Splined	3rd Floor	822	SF	7	6-10 years	
						•	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	2-5 years	

Campus Name: Mays Page : 24 of 31 Assessment Date: 07/20/2023



Category : Classroom			В	uilding	: Main				
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	3rd Floor	817	SF	6	6-10 years			
	Floor - Tile	3rd Floor	5	SF	4	0-1 year	Damaged		
	Instructional Surface	3rd Floor	6	LF	6	10+ years	•		
	Lighting - Pendent/Surface	3rd Floor	16	EA	6	6-10 years			
	Marker Board	3rd Floor	32	LF	7	10+ years			
	Storage/ Closet	3rd Floor	36	SF	5	6-10 years			
	Walls - Concrete Block	3rd Floor	829	SF	6	10+ years			
lassroo	om #313 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	24	LF	6	6-10 years			
	Ceiling - Splined	3rd Floor	813	SF	6	10+ years			
	Ceiling - Splined	3rd Floor	9	SF	4	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	vvater damage		
	Floor - Tile	3rd Floor	822	SF	6	6-10 years			
	Lighting - Pendent/Surface	3rd Floor	13	EA	-				
					6	6-10 years	Do Domorod		
	Lighting - Pendent/Surface	3rd Floor	3	EA	4	0-1 year	Da Damaged		
	Marker Board	3rd Floor	32	LF	7	10+ years			
	Storage/ Closet	3rd Floor	36	SF	5	2-5 years			
	Walls - Concrete Block	3rd Floor	829	SF	6	10+ years			
lassroc	om #314 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	24	LF	6	6-10 years			
	Ceiling - Splined	3rd Floor	822	SF	6	6-10 years			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years			
	Floor - Tile	3rd Floor	821	SF	6	6-10 years			
	Floor - Tile	3rd Floor	1	SF	4	0-1 year	Damaged		
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	3		
	Lighting - Pendent/Surface	3rd Floor	4	EA	4	0-1 year	Damaged		
	Marker Board	3rd Floor	16	LF	7	10+ years			
	Storage/ Closet	3rd Floor	36	SF	5	2-5 years			
	Walls - Concrete Block	3rd Floor	829	SF	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor	72	SF	7	10+ years			
	Work Sink	3rd Floor	1	EA	7	6-10 years			
:lassror	om #315 (Counseling Room)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	8	LF	6	6-10 years			
		3rd Floor		SF					
	Ceiling - Splined	3rd Floor 3rd Floor	360		6	6-10 years			
	Doors - Wood Doors inclu hw		1	EA	6	6-10 years			
	Floor - Tile	3rd Floor	360	SF	6	6-10 years			
	Lighting - Pendent/Surface	3rd Floor	6	EA	6	6-10 years			

Campus Name: Mays Page : 25 of 31 Assessment Date: 07/20/2023



Category : Classroom

Benjamin E Mays Elementary Academy 6656 S Normal BOULEVARD, Chicago, IL 60621

				Recommend	
Item - Type Location	Quantity	UOM	Rank	Replacement	Comments
Lighting - Pendent/Surface 3rd Floor	2	EA	4	0-1 year	Damaged
Marker Board 3rd Floor	32	LF	7	10+ years	
Storage/ Closet 3rd Floor	6	SF	5	2-5 years	
Walls - Concrete Block 3rd Floor	624	SF	7	10+ years	
ory : Interior	В	uilding	: Main		
Mana Tama	0	11014	Danila	Recommend	0
Item - Type Location	Quantity	UOM	Rank	Replacement	Comments
Dr .					
Ceiling - Plaster/Drywall 1st Floor	3,982	SF	7	10+ years	
Doors - Steel Doors incl hw 1st Floor	8	EA	7	10+ years	
Doors - Wood Doors include hw 1st Floor	4	EA	7	10+ years	
Drinking Fountains - Double Fountain 1st Floor	3	EA	7	6-10 years	
Floor - Tile/Sheet 1st Floor	3,982	SF	7	10+ years	
Lighting - Pendent/Surface 1st Floor	56	EA	7	6-10 years	
Walls - Concrete Block 1st Floor	2,005	SF	7	10+ years	
Walls - Structural Glazed Tile 1st Floor	3,859	SF	7	10+ years	
Ceiling - Plaster/Drywall 2nd Floor	3,682	SF	6	6-10 years	
Drinking Fountains - Double Fountain 2nd Floor	2	ĒΑ	7	6-10 years	
Floor - Tile/Sheet 2nd Floor	3,682	SF	5	10+ years	
Lighting - Pendent/Surface 2nd Floor	51	ĒΑ	7	6-10 years	
Walls - Concrete Block 2nd Floor	1,855	SF	7	6-10 years	
Walls - Structural Glazed Tile 2nd Floor	3,709	SF	7	6-10 years	
Ceiling - Plaster/Drywall 3rd Floor	2,318	SF	7	10+ years	
Drinking Fountains - Single Fountain 3rd Floor	2,510	EA	7	6-10 years	
Floor - Tile/Sheet 3rd Floor	2,310	SF	7	10+ years	Rank changed to match current
1 1001 - Tile/Offeet Stull 1001	2,310	OI.	'	10+ years	observation
Floor - Tile/Sheet 3rd Floor	0	SF	4	0.1 voor	
	8 36	EA	4	0-1 year	missing tiles
Lighting - Pendent/Surface 3rd Floor			7	6-10 years	
Walls - Concrete Block 3rd Floor	1,185	SF	7	10+ years	
Walls - Structural Glazed Tile 3rd Floor	2,369	SF	7	10+ years	
Camera Viewing Station Entire Building	3	EA	7	6-10 years	
Security Cameras Entire Building	8	EA	7	6-10 years	
Security Cameras Entire Building	9	EA	7	6-10 years	
Ceiling - Plaster/Drywall East	240	SF	6	6-10 years	
Floor - Terrazzo East	240	SF	6	6-10 years	
Handrails East	128	LF	7	2-5 years	
				,	
				•	
Lighting - Pendent/Surface Stairs - Terrazzo	ce East East	ce East 5	ce East 5 EA East 60 LF	ce East 5 EA 6 East 60 LF 6	ce East 5 EA 6 6-10 years East 60 LF 6 6-10 years

Building: Main

Assessment Date: 07/20/2023 Campus Name: Mays Page : 26 of 31



Category : Interior			В					
_				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Structural Glazed Tile	East	480	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	North	483	SF	6	6-10 years		
	Floor - Terrazzo	North	520	SF	6	6-10 years		
	Handrails	North	128	LF	7	2-5 years		
	Lighting - Pendent/Surface	North	5	EA	6	6-10 years		
	Stairs - Terrazzo			6-10 years				
	Walls - Concrete Block	North	540	SF	7	10+ years		
	Walls - Structural Glazed Tile	North	540	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	South	260	SF	6	6-10 years		
	Floor - Terrazzo	South	260	SF	6	6-10 years		
	Handrails	South	128	LF	7	2-5 years		
	Lighting - Pendent/Surface	South	5	EA	7	6-10 years		
	Stairs - Terrazzo	South	60	LF	6	6-10 years		
	Walls - Structural Glazed Tile	South	532	SF	7	10+ years		
	Ceiling - Plaster/Drywall	West	483	SF	6	6-10 years		
	Floor - Terrazzo	West	520	SF	6	6-10 years		
	Handrails	West	128	LF	7	2-5 years		
	Lighting - Pendent/Surface	West	5	•		6-10 years		
	Stairs - Terrazzo	West	60	LF	6	6-10 years		
	Walls - Concrete Block	West	540	SF	7	10+ years		
	Walls - Structural Glazed Tile	West	540	SF	7	6-10 years		

Campus Name: Mays Page : 27 of 31 Assessment Date: 07/20/2023



Category : Site Building : Site

Category : Site			В	uilding			
_	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Asphalt	North	5,631	SF	7	10+ years	
	Surface - Synthetic including exc & retention	North	4,747	SF	7	10+ years	
/5							
Civil/Dra		a					
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	6	10+ years	
encing							
<u> </u>	Fencing - Chain Link	Entire Site	475	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	825	LF	7	10+ years	
andsca	•	Furting Oits	40	ΕΛ	7	40	
	Benches	Entire Site	13	EA	7	10+ years	
	Landscape - Grass	Entire Site	4,914	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	975	SF	7	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	3,064	SF	7	10+ years	
	Parkway trees	Entire Site	22	EA	7	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	3,200	SF	7	10+ years	
	Trash Receptacles	Entire Site	3	EA	7	10+ years	
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
Parking I	Lot						
3	Surface - Asphalt	Parking Lot- West	4,500	SF	7	10+ years	
	Surface - Asphalt	Parking Lot- West	2,000	SF	6	6-10 years	
	Surface - Asphalt	Parking Lot- West	1,884	SF	4	0-1 year	Cracking and holes throughout
	Surface - Concrete	Parking Lot- West	1,700	SF	7	10+ years	3
	Trash Enclosure - Chain Links	Parking Lot- West	1,200	SF	7	10+ years	
5 1							
Playgrou	Equipment - Combo 3-12	North	1	EA	7	10+ years	
	Surface - Poured Surface	North	2,308	SF	7	10+ years	
	Canado i Garda Gariado	110101	2,500	51	•	101 years	
idewalk							
	Sidewalks - Internal Walks	Entire Site	20	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	5	LF	5	0-1 year	Damaged.
	Sidewalks - Perimeter Sidewalks	Entire Site	15,135	SF	6	10+ years	
Signage							
idirade	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	riag i dio - i lag i die	Little Oile	'	LA	U	TOT years	



Building: Site Category: Site

				Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Mays Page: 29 of 31 Assessment Date: 07/20/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	intended Osage	100m Eddation	Humber	Number	(0.)	Alca	Aica	Стор	Doard
Art Room	Regular Classroom	2nd Floor	203	203	822	160	80	N	Υ
Art Room	Regular Classroom	3rd Floor	312	312	822	160	80	N	N
Computer Lab	Regular Classroom	1st Floor	103	103	822	160	80	N	N
Counseling Room	Regular Classroom	3rd Floor	310	310	730	112	48	N	N
Counseling Room	Special Program	3rd Floor	315	315	360	80	40	N	N
Kindergarten	Kindergarten	1st Floor	101	101	998	164	66	N	N
Kindergarten	Kindergarten	1st Floor	104	104	822	160	80	N	Y
Kindergarten	Kindergarten	1st Floor	105	105	822	160	80	N	Y
Library	Regular Classroom	2nd Floor	216	202/201	1,460	224	96	N	N
Library	Regular Classroom	2nd Floor	216A	200	730	112	48	N	N
Lunch Room	Regular Classroom	1st Floor	111	112	822	160	80	N	N
Music Room	Regular Classroom	2nd Floor	211	211	730	112	48	N	N
Office	Special Program	2nd Floor	215	215	360	80	40	N	N
Pre School	Pre School	1st Floor	102	102	998	164	66	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	822	160	80	N	Y
Regular Classroom	Regular Classroom	1st Floor	107	107	730	112	48	N	Y
Regular Classroom	Regular Classroom	1st Floor	108	108	730	112	48	N	N
Regular Classroom	Regular Classroom	1st Floor	109	109	730	112	48	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	822	112	48	N	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	822	160	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	822	160	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	730	112	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	208	208	730	112	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	730	112	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	210	210	730	112	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	822	160	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	822	160	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	822	160	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	822	160	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	822	160	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	822	160	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	730	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	730	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	730	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	730	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	313	313	822	112	48	N	N
Regular Classroom	Regular Classroom	3rd Floor	314	314	822	160	80	N	N
Science Classroom	Regular Classroom	3rd Floor	303	303	822	160	80	N	N

Campus Name: Mays Page : 30 of 31 Assessment Date: 07/20/2023



Classroom Summary

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board

Campus Name: Mays Page : 31 of 31 Assessment Date: 07/20/2023