

the end of this report.

**Facility Assessment Report** 

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1905	4	77,900
Annex	1986	2	20,400
Modular 1 (2-Classroom)	1995	1	1,960
Campus Total			100,260

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	#1 E	1	EA	6	6-10 years	
	Exterior Doors - Store Front	#1 E	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#1 E	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#1 E	38	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	#10_Exit W (Gym Fire Escape)	1	EA	5	0-1 year	Damaged.
	Entrance Control - Audio and Video	#2 S	1	EA	6	6-10 years	-
	Exterior Doors - Store Front	#2 S	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#2 S	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	#2 S	11	LF	7	10+ years	Repaired
	Power Door Operator and Controls	#2 S	1	EA	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	#2 S	9	LF	6	10+ years	
	Entrance Control - Audio	#3 N	1	EA	5	2-5 years	
	Exterior Doors - Store Front	#3 N	3	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#3 N	3	EA	6	6-10 years	
	Exterior Stairs - Stone	#3 N	11	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#4 W	1	EA	6	6-10 years	
	Exterior Doors - Side lite	#4 W	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	#4 W	6	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#5 W	1	EA	6	6-10 years	
	Exterior Doors - Exterior Wood Door	#6 W	1	EA	5	2-5 years	
	Exterior Doors - Transom Lite	#6 W	1	EA	5	2-5 years	
	Exterior Doors - Exterior Steel Door	#7_Exit S	2	EA	4	0-1 year	Door/Frame detaching from rough



atego	ry : Exterior		Building : Main					
_				_		Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
-							opening	
	Exterior Stairs - Concrete	#7_Exit S	5	LF	6	10+ years		
	Exterior Doors - Exterior Wood Door	#8_Exit W (Auditorium Fire Escape)	2	EA	4	0-1 year	Wood core exposed/deteriorating	
	Stair Handrail - Steel_Stair Handrail	#8_Exit W (Auditorium Fire Escape)	16	LF	6	10+ years	Troca core expected action or a mily	
	Exterior Doors - Exterior Wood Door	#9_Exit W (Auditorium Fire Escape)	2	EΑ	4	1-2 years	Deteriorating to the core. Expose	
	Extend Book Extend Wood Book	"O_EXIL VV (Maditorial II II o Eddapo)	_		•	1 2 youro	wood subject to rot	
	Stair Handrail - Steel_Stair Handrail	#9_Exit W (Auditorium Fire Escape)	16	LF	6	10+ years	wood subject to for	
	Otali Hanarali Otoci_Otali Hanarali	#3_Exit vv (Additionally Fire Escape)	10		O	TOT years		
ire Esca	ane							
IIC LOC	Exterior Doors - Exterior Steel Door	#10_Exit W (Gym Fire Escape)	1	EA	5	0-1 year	Damaged.	
	Fire Escape	#10_Exit W (Gym Fire Escape)	150	LF	6	6-10 years	Damaged.	
	Paints	#10_Exit W (Gym Fire Escape)	150	LF	5	6-10 years		
						•		
	Swing Stairs	#10_Exit W (Gym Fire Escape)	1	EΑ	5	10+ years	\\\ \ \/	
	Exterior Doors - Exterior Wood Door	#8_Exit W (Auditorium Fire Escape)	2	EA	4	0-1 year	Wood core exposed/deteriorating	
	Fire Escape	#8_Exit W (Auditorium Fire Escape)	16	LF	5	10+ years		
	Paints	#8_Exit W (Auditorium Fire Escape)	16	LF	5	10+ years		
	Exterior Doors - Exterior Wood Door	#9_Exit W (Auditorium Fire Escape)	2	EA	4	1-2 years	Deteriorating to the core. Expose wood subject to rot	
	Fire Escape	#9_Exit W (Auditorium Fire Escape)	16	LF	5	10+ years	•	
	Paints	#9_Exit W (Auditorium Fire Escape)	16	LF	5	10+ years		
oundati								
	Foundation - Masonry	Entire Building	22,100	LF	7	10+ years		
	Superstructure - Steel with Clay Tile Arch	Entire Building	75,200	SF	7	10+ years		
ghting								
	Exterior Lighting - Wall Mounted	Entire Building	15	EA	6	6-10 years		
oof Sys	stem							
•	Coping - Clay Tile	NW Low Roof	100	LF	6	10+ years		
	Downspouts - Exterior Downspouts	NW Low Roof	12	LF	6	10+ years		
	Parapet - Parapet < 16" Height	NW Low Roof	100	LF	6	6-10 years		
	Roof - Modified Bitumen	NW Low Roof	950	SF	5	2-5 years		
	Roof Structure - Steel with Clay Tile Arch	NW Low Roof	950	SF	7	10+ years		
	Access Ladder - Metal	Roof #1	1	EA	7	10+ years		
	Access Ladder - Metal	Roof #1	2	EA	4	1-2 years	Two piece ladders with center	
	Access Lauder - Wetai	1001 #1	۷	LA	7	1-2 years	pins/screws in each. Unstable/unsafe.	
	Access Ladder - Wood	Roof #1	2	EA	4	1-2 years	Ladder is not properly secured. Unsafe to access	
	Coping - Metal	Roof #1	445	LF	6	10+ years		
	Parapet - 16" - 30" Height	Roof #1	445	LF	6	10+ years		
	Roof - Metal	Roof #1	10,511	SF	6	10+ years	Roof not accessible due to Unsaf	



Catego	ry : Exterior		В	uilding	: Main		<u>-                                    </u>
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof - Modified Bitumen	Roof #1	2,980	SF	5	2-5 years	conditions.  Roof not accessible due to Unsafe conditions.
	Roof Hatch - Metal	Roof #1	1	EA	7	10+ years	oonanione.
	Roof Structure - Steel with Clay Tile Arch	Roof #1	13,491	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof #2	70	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof #2	20	LF	5	2-5 years	
	Coping - Clay Tile	Roof #2	180	LF	5	2-5 years	
	Coping - Stone	Roof #2	162	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof #2	170	LF	6	6-10 years	
	Downspouts - Interior Downspouts	Roof #2	130	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof #2	428	LF	5	2-5 years	
	Parapet - 16" - 30" Height	Roof #2	20	LF	5	10+ years	
	Parapet - Parapet < 16" Height	Roof #2	315	LF	5	2-5 years	
	Parapet - Parapet > 30"	Roof #2	24	LF	5	2-5 years	
	Roof - Asphalt Gravel Ballast	Roof #2	3,264	SF	5	2-5 years	Cannot access roof due to unsafe conditions
	Roof - Modified Bitumen	Roof #2	8,345	SF	5	2-5 years	Cannot access roof due to unsafe conditions
	Roof Structure - Steel with Clay Tile Arch	Roof #2	11,609	SF	7	10+ years	
	Chimney - Metal Flue	SW - Low Roof	52	LF	7	10+ years	
	Coping - Clay Tile	SW - Low Roof	125	LF	5	2-5 years	
	Coping - Stone	SW - Low Roof	70	LF	5	2-5 years	
	Downspouts - Exterior Downspouts	SW - Low Roof	24	LF	6	6-10 years	
	Parapet - 16" - 30" Height	SW - Low Roof	163	LF	6	6-10 years	
	Parapet - Parapet < 16" Height	SW - Low Roof	32	LF	6	6-10 years	
	Roof - Modified Bitumen	SW - Low Roof	3,100	SF	5	1-2 years	Soft spots/deteriorating seams
	Roof Structure - Steel with Clay Tile Arch	SW - Low Roof	3,100	SF	7	10+ years	
_Walls							
	Cornice - Metal Projecting	Entire Building	1,748	LF	5	6-10 years	
	Exterior Walls - Brick	Entire Building	200	SF	7	10+ years	Repaired
	Exterior Walls - Brick	Entire Building	20	SF	7	10+ years	Repaired
	Exterior Walls - Brick	Entire Building	31,600	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	800	SF	5	6-10 years	
	Exterior Walls - Stone-Cast	Entire Building	1,570	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	960	SF	5	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	660	SF	6	10+ years	
Windows	3						
	Guard - Guards perforated	Entire Building	3,535	SF	6	6-10 years	



Categor	y : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lintels - Steel	Entire Building	544	LF	6	10+ years	
	Lintels - Steel	Entire Building	10	LF	5	2-5 years	
	Lintels - Stone	Entire Building	327	LF	6	10+ years	
	Windows - Decorative	Entire Building	64	SF	6	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	8,055	SF	6	6-10 years	
Categor	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	cy System	Location	Quantity	COM	IVALIK	Replacement	Comments
-mergen	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
			77,900				
	Security System - CCTV	Entire Building		SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	77,900	SF	6	6-10 years	
	Emergency A/C Power - Auditoium and	Entire Building	3,465	SF	6	10+ years	Location changed for clarification as
	Aisle Lighting						the auditorium occupies space on
							multiple floors. Aisle lighting is not
							present.
	Emergency A/C Power - Corridors and	Entire Building	13,283	SF	6	10+ years	•
	Stairs	3	,			,	
	Emergency A/C Power - Gym	Entire Building	3,040	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	3,942	SF	6	10+ years	
	Exit Signs - Auditoium	Entire Building	8	EA	6	6-10 years	Location changed for clarification as
	Extragris - Additional	Little building	O	LA	O	0-10 years	the auditorium occupies space on multiple floors.
	Exit Signs - Corridors and Stairs	Entire Building	18	EA	6	6-10 years	·
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	Rank, Reason and Priority Rep changed as the signs have been replaced with exit signs having backup batteries since previous assessment.
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations.
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	3	EA	6	6-10 years	
Main Ser	vice						
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	77,900	SF	6	6-10 years	Serves Main, Annex and Modular.
Dower Di	stribution						



Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	3	0-1 year	Open breaker slots expose live conductors presenting a live front condition.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	3	0-1 year	Open fuse receptacles expose live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	12	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	3	0-1 year	Open breaker slot exposes live conductors presenting a live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Aları	n						
	Fire ALarm Anunciator	Entire Building	1	EA	6	6-10 years	No CPS Asset Tag present.
	Fire Alarm Panel	Entire Building	1	EΑ	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	77,900	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	77,900	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 45001 - 60000 cfm	Mechanical Room - AHU-1	1	EA	5	6-10 years	AHU-1
	Air Intake	Mechanical Room - AHU-1	1	EΑ	5	6-10 years	Location changed for clarification.
	Auxiliaries - 45001 - 60000 cfm	Mechanical Room - AHU-1	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-1	200	LF	6	10+ years	
	Zone Dampers	Mechanical Room - AHU-1	17	EA	6	6-10 years	
	Zone Dampers	Mechanical Room - AHU-1	15	EA	6	6-10 years	Quantity changed based on current observations and as total has been divided/aggregated. Location changed for clarification.
	Air Handling Unit- Built Up-Multi Zone-	Mechanical Room - AHU-2	1	EA	5	6-10 years	AHU-2

Campus Name: Mccormick Page : 5 of 44 Assessment Date: 02/28/2024



Catego	ry : Mechanical		В	uilding	: Main		7 12 3 Sawyer AVENUE, Chicago, IL 60623
	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Steam Coils - 8001 - 15000 cfm		_			-	
	Air Intake	Mechanical Room - AHU-2	1	EA	5	6-10 years	Location changed for clarification.
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room - AHU-2	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft	Mechanical Room - AHU-2	100	LF	6	6-10 years	
	and Ducts						
	Zone Dampers	Mechanical Room - AHU-2	5	EA	5	6-10 years	Location changed for clarification.
Boiler Sy	vstems						
•	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	2	EA	5	6-10 years	
	Pressure Boiler - 76 - 100 HP					•	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	1	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EΑ	6	10+ years	
	Feed Water Pumps and Tank	Boiler Room	1	ΕA	5	10+ years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	5	6-10 years	B-1
	Steam- Low Pressure Boiler - 76 - 100 HP	200	·	_, ,	•	0 10 700.0	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	5	6-10 years	B-2
	Steam- Low Pressure Boiler - 76 - 100 HP	Bollet Room	'	L/\	0	o to years	D 2
	Piping - Condensate Pipe- Steel	Boiler Room	500	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	500	LF	5	6-10 years	
	Steam Traps	Boiler Room	40	EA	5	6-10 years	
	Oteam Traps	Doller Room	40	L/\	J	o to years	
Heating	Devices						
	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	7	ΕA	5	6-10 years	
	Wall Heater - Electric	Entire Building	2	EΑ	5	6-10 years	Location changed for clarification.
	Wall Heater - Electric	Entire Building	2	EA	4	0-1 year	Reason and Priority Rep changed to
	Wall Floater Elocatio	Entire Banaring	_		•	o i youi	reflect that the missing electrical
							compartment cover exposes live
							conductors presenting a live front
							condition.
							condition.
_Tempera	ature Control						
•	Pneumatic System	Entire Building	77,900	SF	4	2-5 years	Leaks, mostly manually operated.
	Thermostats - Pneumatic	Entire Building	6	EΑ	5	6-10 years	-,, <del>-</del>
	Thermostats - Pneumatic	Entire Building	35	EA	4	2-5 years	Damaged does not work.
		g			-	,	<b>g</b>
<u>Ventilation</u>							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	6	6-10 years	
	CFM	-				•	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	2	EA	5	6-10 years	
	CFM	Č				,	



<b>VII</b> 3	Schools					2	712 S Sawyer AVENUE, Chicago, IL 60623
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	5	6-10 years	
	CFM						
	Exhaust Fans- Roof Mounted - Less than	Entire Building	2	EA	6	6-10 years	
	500 CFM						
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression.
			_				
Catego	ry : Plumbing		В	uilding	: Main		
			<u> </u>			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate							
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	5	2-5 years	Serves Main. Reason and Priority
							Rep changed as unit is 17 years old
					_		and approaching its EUL.
	Hot Water Storage Tank_Gas - 501 - 1000	Boiler Room	1	EA	2	0-1 year	Tank is not needed to serve the
	Gallons						building and was taken out of service
							a number of years ago. It has been
							isolated from the domestic plumbing
							system and abandoned in place.
							Rank, Reason and Priority Rep
							changed to account for the tank
							having become obsolete.
Dining							
Piping	Domostic Dining Het Weter from Disease to	Entire Duilding	77.000			40	
	Domestic Piping-Hot Water from Risers to	Entire Building	77,900	SF	6	10+ years	
	Fixtures Domestic Piping-Hot/Cold Water Supply	Entire Building	77,900	SF	6	10+ years	
	(Horizontal Lines)	Entire Building	77,900	SI	O	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	77,900	SF	6	10+ years	
	(Risers)	Little Ballaling	77,300	OI.	U	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	77,900	SF	6	10+ years	
	(from Risers to Fixtures)	Entire Banding	77,000	O.	O	To Tyouro	
	Sanitary Piping	Entire Building	77,900	SF	6	10+ years	
	Storm Piping	Entire Building	77,900	SF	6	10+ years	
	Vent Piping	Entire Building	77,900	SF	6	10+ years	
		3	,	•	-	<b>,</b>	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	5	6-10 years	Serves Main.
	po 20out 2000011 dilip olimpiox		·	_, .	Ŭ	o .o you.o	
Catego	ry : Room		В	uilding	: Main		
2 2.30 g <b>0</b> .				9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	rative Suites/Offices						
, willingt							
	AC Unit	008 Teacher's Room	2	EΑ	7	6-10 years	

Campus Name: Mccormick Page : 7 of 44 Assessment Date: 02/28/2024



Category : Room			В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	008 Teacher's Room	1,760	SF	6	10+ years	
	Doors - Wood Doors inclu hw	008 Teacher's Room	3	EA	6	10+ years	
	Floor - Carpet	008 Teacher's Room	1,760	SF	7	6-10 years	
	Lighting - Pendent/Surface	008 Teacher's Room	14	EA	7	6-10 years	
	Power Distribution	008 Teacher's Room	8	EA	7	10+ years	
	Storage/ Closet	008 Teacher's Room	40	SF	5	10+ years	
	Walls - Masonry	008 Teacher's Room	2,557	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement-Book Room	761	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement-Book Room	4	EA	6	10+ years	
	Floor - Wood	Basement-Book Room	761	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement-Book Room	12	EA	6	6-10 years	
	Lighting - Pendent/Surface	Basement-Book Room	1	EA	5	1-2 years	Not working
	Lighting - Wall Mounted	Basement-Book Room	1	EA	7	6-10 years	
	Power Distribution	Basement-Book Room	8	EΑ	7	10+ years	
	Storage/ Closet	Basement-Book Room	65	SF	5	10+ years	
	Storage/ Closet	Basement-Book Room	72	SF	5	10+ years	
	Walls - Masonry	Basement-Book Room	370	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement-Book Room	330	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Book Room	70	SF	5	1-2 years	Slumping wall material
	Ceiling - Lay-in	Engineer's office	130	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's office	2	EA	6	10+ years	
	Floor - Carpet	Engineer's office	130	SF	4	1-2 years	Stained carpet
	Lighting - Lay-in	Engineer's office	1	EA	7	6-10 years	
	Power Distribution	Engineer's office	2	EA	7	10+ years	
	Storage/ Closet	Engineer's office	360	SF	5	2-5 years	
	Walls - Plaster/Drywall	Engineer's office	322	SF	6	10+ years	
	AC Unit	Main office	1	EA	7	6-10 years	
	Ceiling - Lay-in	Main office	393	SF	6	10+ years	
	Ceiling - Lay-in	Main office	12	SF	4	1-2 years	Water damage
	Doors - Side-lite	Main office	6	SF	6	10+ years	
	Doors - Transom Window	Main office	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main office	2	EA	6	10+ years	
	Floor - Carpet	Main office	270	SF	6	6-10 years	
	Floor - Tile	Main office	125	SF	7	10+ years	
	Floor - Tile	Main office	10	SF	4	1-2 years	Broken
	Lighting - Lay-in	Main office	5	EA	7	6-10 years	
	Power Distribution	Main office	12	EA	7	10+ years	
	Storage/ Closet	Main office	20	SF	5	10+ years	
	Walls - Plaster/Drywall	Main office	790	SF	6	10+ years	
	AC Unit	Principals office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Principals office	445	SF	6	10+ years	
	Doors - Transom Window	Principals office	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principals office	2	ĒΑ	6	10+ years	
	Floor - Carpet	Principals office	445	SF	6	6-10 years	
	•				-	,	

Campus Name: Mccormick Page : 8 of 44 Assessment Date: 02/28/2024



Catego	ry : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	Principals office	5	EΑ	7	6-10 years			
	Power Distribution	Principals office	8	EA	7	10+ years			
	Storage/ Closet	Principals office	75	SF	5	10+ years			
	Walls - Plaster/Drywall	Principals office	871	SF	7	10+ years			
	Walls - Plaster/Drywall	Principals office	12	SF	5	1-2 years	Damaged.		
Auditoriu	ım & Theater								
	Balcony Seating	1st floor	82	EA	5	10+ years			
	Ceiling - Plaster/Drywall	1st floor	3,465	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st floor	3,403	EA	6	10+ years			
						•			
	Floor - Carpet	1st floor	845	SF	5	6-10 years			
	Floor - Wood	1st floor	2,620	SF	5	10+ years			
	Lighting - Pendent/Surface	1st floor	26	EA	7	6-10 years			
	Main Floor Seating	1st floor	468	EA	5	10+ years			
	Sound System	1st floor	1	EA	7	6-10 years			
	Stage	1st floor	750	SF	5	10+ years			
	Stage Curtain	1st floor	1	EA	5	6-10 years			
	Stage Lighting System	1st floor	1	EA	7	6-10 years			
	Stairs - Wood	1st floor	12	LF	6	10+ years			
	Walls - Plaster/Drywall	1st floor	5,265	SF	6	10+ years			
	Walls - Plaster/Drywall	1st floor	85	SF	5	1-2 years	Water damage		
•									
Gymnas									
	Ceiling - Exposed	3rd Floor	300	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	2,740	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EΑ	6	10+ years			
	Floor - Wood	3rd Floor	3,040	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	12	EA	5	6-10 years			
	Walls - Plaster/Drywall	3rd Floor	5,739	SF	6	10+ years			
Kitchen									
	Ceiling - Lay-in	Basement	1,230	SF	6	10+ years			
	Doors - Steel Doors incl hw	Basement	1	EA	6	10+ years			
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years			
	Floor - Tile Quarry	Basement	1,230	SF	6	10+ years			
	Lighting - Lay-in	Basement	20	EΑ	7	6-10 years			
	Storage/ Closet	Basement	190	SF	5	10+ years			
	Walls - Plaster/Drywall	Basement	1,135	SF	6	10+ years			
Locker/S	Shower Room								
	Accessories	Basement teachers lockers	81	SF	7	10+ years			
	Ceiling - Plaster/Drywall			SF SF		10+ years 10+ years			
	Doors - Wood Doors inclu hw	Basement teachers lockers Basement teachers lockers	81 1	SF EA	6 6	10+ years 10+ years			



Catego	ry : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile Quarry	Basement teachers lockers	81	SF	6	10+ years			
	Lighting - Pendent/Surface	Basement teachers lockers	2	EA	6	6-10 years			
	Student Lockers - One Tier	Basement teachers lockers	11	EA	6	10+ years			
	Walls - Plaster/Drywall	Basement teachers lockers	240	SF	6	10+ years			
unch &	Multipurpose Room								
	Ceiling - Exposed	North lunch room	2,160	SF	6	10+ years			
	Doors - Wood Doors inclu hw	North lunch room	2	ĒΑ	6	10+ years			
	Floor - Epoxy/ Painted	North lunch room	2,160	SF	7	10+ years			
	Lighting - Pendent/Surface	North lunch room	18	EA	7	6-10 years			
	Serving Line	North lunch room	25	LF	7	10+ years			
	Walls - Masonry	North lunch room	432	SF	6	10+ years			
	Walls - Vinyl Coated Gypsum Panel	North lunch room	1,298	SF	6	10+ years			
	Ceiling - Exposed	South lunch room	1,782	SF	6	10+ years			
	Floor - Concrete Epoxy/ Painted	South lunch room	1,782	SF	5	10+ years			
	Lighting - Pendent/Surface		1,762	EA	5 5				
		South lunch room				6-10 years			
	Walls - Masonry	South lunch room	378	SF SF	6	10+ years			
	Walls - Vinyl Coated Gypsum Panel	South lunch room	1,132		6	10+ years			
	Ceiling - Plaster/Drywall	Teacher lunch room	356	SF	6	10+ years			
	Doors - Steel Doors incl hw	Teacher lunch room	1	EA	6	10+ years			
	Doors - Wood Doors inclu hw	Teacher lunch room	1	EA	6	10+ years			
	Floor - Tile Quarry	Teacher lunch room	356	SF	6	10+ years			
	Lighting - Pendent/Surface	Teacher lunch room	4	EA	7	6-10 years			
	Walls - Plaster/Drywall	Teacher lunch room	518	SF	6	10+ years			
MDF_ID	F								
	Finishes	2nd Floor inside classroom 202	182	SF	7	6-10 years			
	Window AC Unit	2nd Floor inside classroom 202	1	EA	7	6-10 years			
Mechani	cal/ Service Rooms								
	Janitor's Closet	1st Floor	24	SF	5	10+ years			
	Janitor's Closet	1st Floor	24	SF	5	10+ years			
	Janitor's Closet	2nd Floor	18	SF	5	10+ years			
	Janitor's Closet	2nd Floor	18	SF	5	10+ years			
	Janitor's Closet	3rd Floor	8	SF	5	10+ years			
	Janitor's Closet	3rd Floor	8	SF	5	10+ years			
	Boiler Room	Basement	650	SF	5	2-5 years			
	Coal Room	Basement	210	SF	5	2-5 years 2-5 years			
	Mechanical/ Service Rooms		1,008	SF SF	5 5				
		Basement		SF SF		2-5 years			
	Mechanical/ Service Rooms	Basement	668		5	2-5 years			
	Storage Room	Basement	910	SF	5	2-5 years			
	Storage Room	Basement	108	SF	5	2-5 years			
	Storage Room	Basement	846	SF	5	2-5 years			



Catego	ry : Room	·	В	uilding	: Main		·
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Storage Room	Basement	437	SF	5	2-5 years	
	Storage Room	Basement	154	SF	5	2-5 years	
	ŭ					,	
estroo	m						
	Accessories	101	135	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	101	135	SF	6	10+ years	
	Doors - Wood Doors inclu hw	101	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	101	135	SF	5	10+ years	
	Lavatory	101	1	EA	6	10+ years	
	Lighting - Pendent/Surface	101	2	EA	7	6-10 years	
	Partitions	101	2	EA	5	10+ years	
	Walls - Plaster/Drywall	101	380	SF	6	10+ years	
	Water Closet	101	2	ĒΑ	6	10+ years	
	Accessories	2nd floor boys	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor boys	54	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd floor boys	4	SF	4	1-2 years	Cracked
	Doors - Wood Doors inclu hw	2nd floor boys	1	EΑ	6	10+ years	0.40.00
	Floor - Tile Ceramic/ Porcelain	2nd floor boys	58	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor boys	2	SF	4	1-2 years	Missing
	Floor Drain	2nd floor boys	1	EA	7	10+ years	·····oog
	Lavatory	2nd floor boys	1	EA	6	10+ years	
	Lighting - Lay-in	2nd floor boys	1	EA	7	6-10 years	
	Partitions	2nd floor boys	1	EA	7	10+ years	
	Urinals	2nd floor boys	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor boys	60	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd floor boys	49	SF	6	10+ years	
	Water Closet	2nd floor boys	1	EA	6	10+ years	
	Accessories	2nd floor girls	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girls  2nd floor girls	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor girls  2nd floor girls	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor girls  2nd floor girls	60	SF	6	-	
	Floor Drain	2nd floor girls 2nd floor girls	1	EA	7	10+ years	
		2nd floor girls 2nd floor girls	1	EA	6	10+ years	
	Lavatory		•			10+ years	
	Lighting - Lay-in	2nd floor girls	1	EΑ	6	6-10 years	
	Partitions	2nd floor girls	2	EA SF	7	10+ years	
	Walls - Plaster/Drywall	2nd floor girls	60	SF SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd floor girls	49		6	10+ years	
	Water Closet	2nd floor girls	2	EA	6	10+ years	
	Accessories	2nd floor unisex	182	SF	7	6-10 years	
	Ceiling - Lay-in	2nd floor unisex	110	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd floor unisex	72	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd floor unisex	2	EA	6	10+ years	
	Floor - Tile	2nd floor unisex	110	SF	6	6-10 years	
	Floor - Tile Ceramic/ Porcelain	2nd floor unisex	72	SF	6	6-10 years	



Catego	ry : Room		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor Drain	2nd floor unisex	1	EA	7	10+ years	
	Lavatory	2nd floor unisex	1	EA	6	10+ years	
	Lighting - Lay-in	2nd floor unisex	5	EA	7	6-10 years	
	Partitions	2nd floor unisex	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor unisex	70	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd floor unisex	269	SF	6	10+ years	
	Water Closet	2nd floor unisex	2	EA	6	10+ years	
	Accessories	3rd floor men restroom storage	306	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor men restroom storage	296	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd floor men restroom storage	10	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	3rd floor men restroom storage	1	EA	6	10+ years	3
	Floor - Tile	3rd floor men restroom storage	306	SF	4	0-1 year	Damaged
	Lavatory	3rd floor men restroom storage	1	ĒΑ	6	10+ years	3
	Lighting - Pendent/Surface	3rd floor men restroom storage	3	EA	7	6-10 years	
	Partitions	3rd floor men restroom storage	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	3rd floor men restroom storage	909	SF	6	10+ years	
	Water Closet	3rd floor men restroom storage	2	EA	6	10+ years	
	Accessories	Basement	120	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement	120	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	120	SF	7	10+ years	
	Floor Drain	Basement	120	EA	7	10+ years	
	Hand Dryer	Basement	1	EA	7	10+ years	
	Lavatory	Basement	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement	50	SF	7	10+ years	
	Walls - Flaster/Drywall Walls - Tile Ceramic/ Porcelain	Basement	140	SF	7	10+ years	
	Water Closet	Basement	140	EA	7	10+ years	
	Accessories		325	SF	7		
		Basement boys	325	SF SF		6-10 years	
	Ceiling - Plaster/Drywall Floor - Tile Ceramic/ Porcelain	Basement boys	325	SF SF	7 7	10+ years	
	Floor Prain	Basement boys		Sr EA	7	10+ years	
		Basement boys	1	EA		10+ years	
	Hand Dryer	Basement boys	2		7	6-10 years	
	Lavatory	Basement boys	3	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Basement boys	4	EΑ	7	6-10 years	
	Partitions	Basement boys	6	EΑ	7	10+ years	
	Urinals	Basement boys	3	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement boys	80	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement boys	310	SF	7	10+ years	
	Water Closet	Basement boys	6	EA	7	10+ years	
	Accessories	Basement girls	216	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement girls	216	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement girls	216	SF	7	10+ years	
	Floor Drain	Basement girls	1	EA	7	10+ years	

Page : 12 of 44 Campus Name: Mccormick Assessment Date: 02/28/2024



Catego	Category : Room			uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hand Dryer	Basement girls	2	EA	7	6-10 years	
	Lavatory	Basement girls	3	EA	6	10+ years	
	Lighting - Pendent/Surface	Basement girls	7	EA	7	6-10 years	
	Partitions	Basement girls	12	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement girls	90	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement girls	310	SF	7	10+ years	
	Water Closet	Basement girls	12	EA	7	10+ years	
	Accessories	Main office	20	SF	5	6-10 years	
	Ceiling - Lay-in	Main office	12	SF	7	6-10 years	
	Ceiling - Lay-in	Main office	8	SF	4	1-2 years	Water damage
	Doors - Wood Doors inclu hw	Main office	1	EA	6	10+ years	
	Floor - Tile	Main office	20	SF	6	10+ years	
	Lavatory	Main office	1	EA	6	10+ years	
	Lighting - Wall Mounted	Main office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Main office	70	SF	6	10+ years	
	Water Closet	Main office	1	EA	6	10+ years	
	Accessories	Toilet in Boiler Room	25	SF	5	6-10 years	
	Ceiling - Exposed	Toilet in Boiler Room	25	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Toilet in Boiler Room	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Toilet in Boiler Room	25	SF	5	1-2 years	Worn finish
	Lighting - Wall Mounted	Toilet in Boiler Room	1	EA	7	6-10 years	
	Walls - Masonry	Toilet in Boiler Room	60	SF	5	1-2 years	Damaged throughout
	Water Closet	Toilet in Boiler Room	1	EA	6	10+ years	-

Categor	Category : Classroom			uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Classroon	m #101 (Faculty Lounge)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	33	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	5	10+ years	
	Chalk Board	1st Floor	4	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Floor - Tile	1st Floor	850	SF	5	10+ years	
	Floor - Tile	1st Floor	50	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	4	LF	7	6-10 years	
	Storage/ Closet	1st Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,375	SF	6	10+ years	
Classroor	m #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	6	10+ years	

Campus Name: Mccormick Page : 13 of 44 Assessment Date: 02/28/2024



Categor	Category : Classroom		В	uilding	: Main				
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Doors - Transom Window	1st Floor	9	SF	6	10+ years			
	Floor - Wood	1st Floor	900	SF	5	10+ years			
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years			
	Storage/ Closet	1st Floor	120	SF	5	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,475	SF	6	10+ years			
Classroor	m #103 (Office)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	9	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	840	SF	5	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	10	SF	4	1-2 years	Water damage		
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	water damage		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Wood	1st Floor	850	SF	6	10+ years			
	Lighting - Metal Halide/Sodium Vapor	1st Floor	16	EA	7	6-10 years			
	Marker Board	1st Floor	20	LF	7	6-10 years			
	Storage/ Closet	1st Floor	120	SF	5	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,230	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	25	SF	4	0-1 year	Water damage		
Classroor	m #104 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	9	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	825	SF	6	10+ years			
	Doors - Transom Window	1st Floor	18	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒA	7	10+ years			
	Floor - Wood	1st Floor	825	SF	5	10+ years			
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years			
	Marker Board	1st Floor	8	LF	7	6-10 years			
	Storage/ Closet	1st Floor	120	SF	5	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,275	SF	6	10+ years			
	·		,			,			
Classroor	m #106 (Regular Classroom)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	48	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	825	SF	6	10+ years			
	Doors - Transom Window	1st Floor	18	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Carpet	1st Floor	825	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Floor	16	EA	6	6-10 years			
	Storage/ Closet	1st Floor	120	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,175	SF	6	10+ years			
			· ·		_	ioi youis			
	Walls - Plaster/Drywall	1st Floor	50	SF	4	1-2 years	Water damage		



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	m #107 (Regular Classroom)	=1				0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	840	SF	6	10+ years	_
	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Damaged.
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	820	SF	6	10+ years	
	Floor - Tile	1st Floor	30	SF	4	1-2 years	Broken tile
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	23	LF	7	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,253	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	2	SF	5	1-2 years	Hole in wall
Classroo	m #108 (Library)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	900	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	900	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,430	SF	6	10+ years	
_Classroo	m #109 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	880	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	20	SF	5	1-2 years	Cracked
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Floor - Wood	1st Floor	890	SF	6	10+ years	
	Floor - Wood	1st Floor	10	SF	4	1-2 years	Broken
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,371	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	4	SF	4	1-2 years	Hole
Classroo	m #201 (Regular Classroom)						
CidaaiUU	III #201 (Negulai Classicolit)						

Campus Name: Mccormick Page : 15 of 44 Assessment Date: 02/28/2024



Catego	ry : Classroom		В	uilding	: Main		7 12 3 Sawyer AVENUE, Chicago, IL 60623
Guioge	.,		_	ug	1 1114111	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	880	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	4	SF	5	1-2 years	Cracked
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	34	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	182	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	852	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4	SF	5	1-2 years	Cracked
Classroo	om #202 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	884	SF	6	10+ years	
	Chalk Board	2nd Floor	22	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	1	SF	6	10+ years	
	Floor - Wood	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	4	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	182	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
_Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	880	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	4	SF	5	1-2 years	Water damage
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	ŭ
	Floor - Wood	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	30	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	182	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	846	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Water damage
_Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	884	SF	6	10+ years	



Catego	ategory : Classroom		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years		
	Floor - Wood	2nd Floor	884	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years		
	Marker Board	2nd Floor	18	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	182	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	856	SF	6	10+ years		
Classroo	m #205 (Office)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	7	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	879	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Cracked	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	Cracked	
	Floor - Wood	2nd Floor	884	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years		
	Marker Board	2nd Floor	12	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	856	SF	6		Dealing point throughout	
	walls - Plaster/Drywall	211d F1001	000	SF	б	10+ years	Peeling paint throughout.	
Classroo	m #206 (Faculty Lounge)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	7	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	874	SF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Water damage	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years		
	Floor - Wood	2nd Floor	884	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years		
	Marker Board	2nd Floor	32	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	182	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	846	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Water damage	
Classroo	m #207 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	7	LF	6	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	884	SF	6	10+ years		
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years		
	Floor - Wood	2nd Floor	884	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	182	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	856	SF	6	10+ years		
laceron	m #208 (Computer Lab)							

Campus Name: Mccormick Page : 17 of 44 Assessment Date: 02/28/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	884	SF	6	10+ years	
	Chalk Board	2nd Floor	14	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	182	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	852	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4	SF	4	1-2 years	Chipped
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Classroo	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	844	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	40	SF	5	1-2 years	Water damage
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	Water damage
	Floor - Wood	2nd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	182	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	856	SF	6	10+ years	
0.	·					•	
_Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	884	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Floor - Wood	3rd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	34	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	182	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	856	SF	6	10+ years	
Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	884	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	884	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Lighting I chachirounace	014 1 1001	13	LA	,	o To years	

Page : 18 of 44 Campus Name: Mccormick Assessment Date: 02/28/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	182	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	856	SF	6	10+ years	
	•					-	
lassroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	844	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	40	SF	5	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	Trais: damage
	Floor - Wood	3rd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	182	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	806	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	50	SF	5	0-1 year	Water damage.
	vvalio i laotoi/Diywali	014 1 1001	00	O.	Ü	o i youi	vvator damage.
lassroo	om #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	884	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Floor - Wood	3rd Floor	884	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	182	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	856	SF	6	10+ years	
	are #205 (Bassiles Classes						
lassroo	om #305 (Regular Classroom)	3rd Floor	2	ГΛ	7	6.10 40000	
	AC Units Ceiling - Plaster/Drywall		2	EA SF	7	6-10 years	
		3rd Floor 3rd Floor	588	SF SF	6 5	10+ years	Water demand
	Ceiling - Plaster/Drywall Doors - Transom Window	3rd Floor 3rd Floor	400 18	SF SF	5 6	1-2 years	Water damage
	Floor - Wood	3rd Floor		SF SF	6	10+ years	
			988			10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA LF	7 7	6-10 years	
	Marker Board Walls - Plaster/Drywall	3rd Floor 3rd Floor	31	SF	<i>7</i> 6	6-10 years 10+ years	
			905	SF SF		•	Water demand
	Walls - Plaster/Drywall	3rd Floor	40	5F	5	1-2 years	Water damage
lassroo	om #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	834	SF	6	10+ years	



Catego	ategory : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	3rd Floor	50	SF	5	1-2 years	Water damage		
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years			
	Floor - Wood	3rd Floor	884	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years			
	Marker Board	3rd Floor	40	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	182	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	857	SF	6	10+ years			
Classroc	om #307 (Regular Classroom)								
	AC Units	3rd Floor	2	EA	7	6-10 years			
	Casework	3rd Floor	7	LF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	884	SF	6	10+ years			
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years			
	Floor - Wood	3rd Floor	884	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	15	SF EA	7				
						6-10 years			
	Marker Board	3rd Floor	22	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	182	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	854	SF	6	10+ years			
	Walls - Plaster/Drywall	3rd Floor	2	SF	4	1-2 years	Water damage		
Classroc	om #308 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	7	LF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	864	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Water damage		
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	4	1-2 years	Water damage		
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	5	0-1 year	Damaged.		
	Floor - Tile	3rd Floor	56	SF	6	10+ years	2 amagoa.		
	Floor - Wood	3rd Floor	828	SF	6	10+ years			
		3rd Floor	15	EA	7				
	Lighting - Pendent/Surface	3rd Floor 3rd Floor	22	LF	7 7	6-10 years			
	Marker Board					6-10 years			
	Storage/ Closet	3rd Floor	182	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	856	SF	6	10+ years			
Classroc	om #309 (Regular Classroom)								
	AC Units	3rd Floor	2	EA	7	6-10 years			
	Casework	3rd Floor	7	LF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	879	SF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	5	SF	4	1-2 years	Water damage		
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	3		
	Floor - Wood	3rd Floor	884	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	15	EA	6	6-10 years			
	Marker Board	3rd Floor	22	LF	6	6-10 years			
	ואומותכו שטמוע	SIU FIOOI	22	LF	U	0-10 years			



**Building: Main Category: Classroom** 

Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Storage/ Closet 182 6-10 years 3rd Floor SF 7 Walls - Plaster/Drywall 3rd Floor 852 SF 6 10+ years

Category : Interior **Building** · Main

Catego	ategory : Interior		Building : Main				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	item - Type	Location	Quantity	CON	Naiik	Replacement	Comments
Corridor	0.11. Di 1.70. II	4 . 🖂	0.000			40	
	Ceiling - Plaster/Drywall	1st Floor	3,936	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	2	EΑ	5	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Asphalt Floor	1st Floor	3,936	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	2	EA	5	6-10 years	
	Walls - Plaster/Drywall	1st Floor	7,126	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	240	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,276	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Asphalt Floor	2nd Floor	3,276	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	4,464	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	3,256	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	5	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	54	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	EA	7	10+ years	
	Floor - Asphalt Floor	3rd Floor	3,276	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4,459	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	5	SF	5	1-2 years	Water damage
	Ceiling - Exposed	Basement	2,500	SF	5	0-1 year	Peeling throughout
	Ceiling - Plaster/Drywall	Basement	179	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	232	SF	5	1-2 years	Peeling paint
	Doors - Side-lite	Basement	40	SF	6	10+ years	
	Doors - Transom Window	Basement	29	SF	6	10+ years	
	Doors - Wood Doors include hw	Basement	6	EA	6	10+ years	
	Drinking Fountains - Single Water Cooler	Basement	4	EA	7	10+ years	
	Floor - Asphalt Floor	Basement	1,196	SF	7	6-10 years	
	Floor - Asphalt Floor	Basement	1,400	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement	315	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	34	EA	7	6-10 years	
	Stairs - Concrete Stairs	Basement	128	LF	6	10+ years	
	Walls - Masonry	Basement	5,484	SF	6	10+ years	
	Walls - Masonry	Basement	200	SF	5	1-2 years	Spalled wall
	Walls - Plaster/Drywall	Basement	100	SF	6	10+ years	•



Catago	m Intonion				. Main		712 S Sawyer AVENUE, Chicago, IL 60623				
Catego	ry : Interior		Building : Main								
•	B	To a set a se	0			Recommend	•				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
Safety											
	Camera Viewing Station	1st Floor	1	EΑ	7	6-10 years					
	Security Cameras	1st Floor	20	EΑ	7	10+ years					
	Security Cameras	1st Floor	23	EA	7	6-10 years					
Stairs											
	Ceiling - Plaster/Drywall	Center stair 1st floor to main entry	354	SF	6	10+ years					
	Handrails	Center stair 1st floor to main entry	18	LF	7	10+ years					
	Lighting - Lay-in	Center stair 1st floor to main entry	2	EΑ	6	6-10 years					
	Stairs - Asphalt	Center stair 1st floor to main entry	23	LF	6	10+ years					
	Walls - Plaster/Drywall	Center stair 1st floor to main entry	570	SF	6	10+ years					
	Ceiling - Plaster/Drywall	North and south stairs	950	SF	6	10+ years					
	Ceiling - Plaster/Drywall	North and south stairs	100	SF	5	0-1 year	Water damage.				
	Floor - Asphalt	North and south stairs	200	SF	6	10+ years	-				
	Handrails	North and south stairs	320	LF	7	10+ years					
	Lighting - Pendent/Surface	North and south stairs	6	EΑ	7	6-10 years					
	Stairs - Asphalt	North and south stairs	282	LF	6	10+ years					
	Walls - Plaster/Drywall	North and south stairs	1,912	SF	6	10+ years					





Category : Exterior **Building: Annex** 

				. ,	Recommend	
oup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
trance		•			•	
Entrance Control - Audio and Video	#1 E	1	EA	6	6-10 years	
Exterior Doors - Exterior FRP Door	#1 E	4	EA	6	6-10 years	
Exterior Doors - Side lite	#1 E	4	EA	6	6-10 years	
Exterior Doors - Transom Lite	#1 E	2	EA	6	6-10 years	
Exterior Stairs - Concrete	#1 E	63	LF	5	10+ years	
Stair Handrail - Steel_Stair Handrail	#1 E	12	LF	6	6-10 years	
Exterior Doors - Exterior FRP Door	#2 E	4	EA	6	6-10 years	
Exterior Doors - Side lite	#2 E	4	EA	6	6-10 years	
Exterior Doors - Transom Lite	#2 E	2	EA	6	6-10 years	
Exterior Stairs - Concrete	#2 E	58	LF	5	2-5 years	
Ramp Handrail - Steel_Ramp Handrail	#2 E	20	LF	6	10+ years	
Ramps - Concrete	#2 E	20	LF	5	2-5 years	
Stair Handrail - Steel_Stair Handrail	#2 E	8	LF	7	6-10 years	Repaired
Exterior Doors - Exterior FRP Door	#3 W	1	EA	6	6-10 years	
Exterior Doors - Side lite	#3 W	2	EA	6	6-10 years	
Exterior Doors - Transom Lite	#3 W	1	EA	6	6-10 years	
Exterior Stairs - Concrete	#3 W	10	LF	5	2-5 years	
Exterior Stairs - Steel or Aluminum	#3 W	30	LF	6	6-10 years	
Stair Handrail - Steel_Stair Handrail	#3 W	16	LF	6	6-10 years	
Exterior Doors - Exterior FRP Door	#4 W	1	EA	6	6-10 years	
Exterior Doors - Side lite	#4 W	2	EA	6	6-10 years	
Exterior Doors - Transom Lite	#4 W	1	EA	6	6-10 years	
Exterior Stairs - Steel or Aluminum	#4 W	30	LF	6	6-10 years	
Exterior Stairs - Steel or Aluminum	#4 W	10	LF	5	2-5 years	
Stair Handrail - Steel_Stair Handrail	#4 W	16	LF	5	6-10 years	
undation						
Foundation - Concrete	Entire Building	460	LF	7	10+ years	
Superstructure - Metal Deck/ Concrete	Entire Building	20,400	SF	7	10+ years	
Topping		23, 100	٥.	•	, , , , , , ,	
hting						
hting Exterior Lighting - Wall Mounted	Entire Building	5	EA	6	6-10 years	
	Ŭ				•	
of System	E C D 31				0.40	
Coping - Metal	Entire Building	460	LF	6	6-10 years	
Downspouts - Interior Downspouts	Entire Building	100	LF	6	6-10 years	No de la companya de
Roof - Asphalt Gravel Ballast	Entire Building	10,200	SF	5	0-1 year	Vegetation growth.
Roof Hatch - Metal	Entire Building	1	EA	7	10+ years	
Roof Structure - Steel / Metal Deck/	Entire Building	10,200	SF	7	10+ years	
Concrete Topping						



Category : Exterior

# Cyrus H McCormick Elementary School 2712 S Sawyer AVENUE, Chicago, IL 60623

**Building: Annex** 

Recommend

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Walls							
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	9,004	SF	5	2-5 years	Peeling paint on west side of building
Window	s						
	Guard - Guards perforated Windows - Casement Aluminum Double- pane	Entire Building Entire Building	1,256 3,496	SF SF	6 6	6-10 years 6-10 years	
Catego	ry : Electrical		Е	Buildina	: Annex	1	
Guiogo			_	, and m	. / (11110)	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerge	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	Serves Annex.
	Exit Signs - Corridors and Stairs	Electrical Room	2	EA	5	6-10 years	
	Exit Signs - Corridors and Stairs	Electrical Room	6	EA	5	6-10 years	
	Exit Signs - Lunchroom	Electrical Room	2	EA	2	0-1 year	No battery packs/damaged.
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,496	SF	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	4	EA	6	6-10 years	
	Security System - CCTV	Entire Building	20,400	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	20,400	SF	6	6-10 years	
Main Se	rvice						
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	20,400	SF	6	6-10 years	Served by Main.
Power D	Distribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	Location changed for clarification. Installed approx. 8 feet above floor level. Panels have no doors/covers by design.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	-
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Location changed for clarification.
Campus	Name: Mccormick		Page : 24 of 44				Assessment Date: 02/28/2024

Campus Name: Mccormick Page: 24 of 44 Assessment Date: 02/28/2024



Catego	ry : Electrical		В	uilding	: Annex	,	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	Quantity changed to match current observations. Rank, Reason and Priority Rep changed as an open fuse receptacle exposes live conductors presenting a live front condition.  Quantity changed based on current observations and as total has been
							divided/aggregated.
	Main Distribution Panels - Greater than 600 amp	Entire Building	2	EA	7	10+ years	Quantity changed based on current observations and as total has been divided/aggregated.
Catego	ry · Fire Protection		B	uildina	· Anney		

Category : Fire Protection Building : Annex

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire ALarm Anunciator	Electrical Room	1	EA	3	2-5 years	No CPS Asset Tag present. System is fully operational and passes inspection, however it is 35-plus years old and has exceeded its EUL.
	Fire Alarm Panel	Electrical Room	1	EA	3	2-5 years	No CPS Asset Tag present. System is fully operational and passes inspection, however it is 35-plus years old and has exceeded its EUL.
	Fire Alarm Strobe Lights	Electrical Room	20,400	SF	3	0-1 year	Rank, Reason and Priority Rep changed based on current observations that there is only one strobe light throughout the building, located in the designated accessible rest room, and there are no strobes in classrooms, offices or corridors.
	Fire Alarm_System	Electrical Room	20,400	SF	4	2-5 years	System is fully operational and passes inspection, however the Rank, Reason and Priority Rep changed to reflect that the system is 35-plus years old and has exceeded its EUL.
_Sprinkle	r System						
	Dry Sprinkler System	Entire Building	20,400	SF	6	10+ years	City water pressure, tankless air compressor. Location and quantity changed for clarification.
	Sprinkler Heads	Entire Building	20,400	SF	7	10+ years	
	Sprinkler Piping	Entire Building	20,400	SF	6	10+ years	

Campus Name: Mccormick Page : 25 of 44 Assessment Date: 02/28/2024



Catego	ry : Fire Protection		В	uilding	: Annex		
Froup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
atego	ry : Mechanical		В	uilding	: Annex		
iroup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
leating	Devices						
	Unit Heater - Electric Wall Heater - Electric	1st Floor Entire Building	4 5	EA EA	6 6	10+ years 6-10 years	Location changed for clarification. Located in student restrooms and i switchgear room. Quantity change to match current observations.
empera	ture Control						
•	Electric Thermostat	Entire Building	9	EA	5	6-10 years	
Jnit Ven	tilation						
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	3	EA	6	6-10 years	
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	10	EA	6	6-10 years	
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	2	EA	5	6-10 years	
	Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor	Entire Building	7	EA	5	6-10 years	
entilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Roof	2	EA	6	6-10 years	
atego	ry : Plumbing		В	uilding	: Annex		
iroup lot Wate	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
or vvale	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	5	6-10 years	Fully operational and leak-free with signs of superficial oxidation consistent with the age of the

Campus Name: Mccormick Page : 26 of 44 Assessment Date: 02/28/2024



Catego	ry : Plumbing		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							equipment.
_Piping_							
	Domestic Piping-Hot Water Return Lines	Entire Building	20,400	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	20,400	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	20,400	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	20,400	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	20,400	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	20,400	SF	6	10+ years	
	Sanitary Piping	Entire Building	20,400	SF	6	10+ years	
	Storm Piping	Entire Building	20,400	SF	6	10+ years	
	Vent Piping	Entire Building	20,400	SF	6	10+ years	

Category: Room **Building: Annex** 

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	rative Suites/Offices	Location	Quantity	OOW	Italik	Replacement	Comments
_Auminsi		217	150	SF	6	10. vooro	
	Ceiling - Plaster/Drywall	— • •	150		6	10+ years	
	Doors - Steel Doors incl hw	217	1 450	EA	6	10+ years	
	Floor - Tile	217	150	SF	6	10+ years	
	Lighting - Pendent/Surface	217	2	EA	_	6-10 years	
	Power Distribution	217	4	EA	7	10+ years	
	Walls - Plaster/Drywall	217	484	SF	6	10+ years	
	Ceiling - Plaster/Drywall	RM 106-Teacher's Lounge	135	SF	6	10+ years	
	Doors - Steel Doors incl hw	RM 106-Teacher's Lounge	1	EA	6	10+ years	
	Floor - Tile	RM 106-Teacher's Lounge	135	SF	6	10+ years	
	Lighting - Pendent/Surface	RM 106-Teacher's Lounge	3	EA	6	6-10 years	
	Power Distribution	RM 106-Teacher's Lounge	4	EA	7	10+ years	
	Storage/ Closet	RM 106-Teacher's Lounge	30	SF	5	10+ years	
	Walls - Plaster/Drywall	RM 106-Teacher's Lounge	371	SF	6	10+ years	
	Ceiling - Plaster/Drywall	RM 109-Main Office-MOD	97	SF	6	10+ years	
	Ceiling - Plaster/Drywall	RM 109-Main Office-MOD	3	SF	5	1-2 years	Damaged.
	Ceiling - Splined	RM 109-Main Office-MOD	305	SF	6	10+ years	•
	Doors - Side-lite	RM 109-Main Office-MOD	54	SF	6	10+ years	
	Doors - Steel Doors incl hw	RM 109-Main Office-MOD	1	EA	6	10+ years	
	Floor - Tile	RM 109-Main Office-MOD	394	SF	6	10+ years	
	Floor - Tile	RM 109-Main Office-MOD	11	SF	4	1-2 years	Cracked and damaged tile
	Lighting - Pendent/Surface	RM 109-Main Office-MOD	7	ĒΑ	6	6-10 years	
	Power Distribution	RM 109-Main Office-MOD	10	EA	7	10+ years	
	Storage/ Closet	RM 109-Main Office-MOD	108	SF	7	10+ years	

Campus Name: Mccormick Page : 27 of 44 Assessment Date: 02/28/2024



Catego	ry : Room		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	RM 109-Main Office-MOD	965	SF	6	10+ years	
	Ceiling - Splined	RM 113-Resource Room	300	SF	6	10+ years	
	Doors - Steel Doors incl hw	RM 113-Resource Room	1	EA	6	10+ years	
	Floor - Tile	RM 113-Resource Room	298	SF	6	10+ years	
	Floor - Tile	RM 113-Resource Room	2	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	RM 113-Resource Room	4	EA	7	6-10 years	
	Power Distribution	RM 113-Resource Room	7	EA	7	10+ years	
	Walls - Plaster/Drywall	RM 113-Resource Room	554	SF	6	10+ years	
	Ceiling - Plaster/Drywall	RM-110-Copy Room	75	SF	6	10+ years	
	Doors - Steel Doors incl hw	RM-110-Copy Room	1	EΑ	6	10+ years	
	Floor - Tile	RM-110-Copy Room	67	SF	5	10+ years	
	Floor - Tile	RM-110-Copy Room	8	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	RM-110-Copy Room	1	EA	7	6-10 years	
	Power Distribution	RM-110-Copy Room	2	EA	7	10+ years	
	Walls - Plaster/Drywall	RM-110-Copy Room	277	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 101-Office	172	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 101-Office	8	SF	4	1-2 years	Damaged ceiling
	Doors - Wood Doors inclu hw	Room 101-Office	1	EA	6	10+ years	
	Floor - Tile	Room 101-Office	179	SF	6	10+ years	
	Floor - Tile	Room 101-Office	1	SF	4	1-2 years	Damaged floor
	Lighting - Pendent/Surface	Room 101-Office	2	EA	7	6-10 years	
	Power Distribution	Room 101-Office	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 101-Office	429	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 203	238	SF	6	10+ years	
	Doors - Steel Doors incl hw	Room 203	1	EA	6	10+ years	
	Floor - Tile	Room 203	238	SF	6	6-10 years	
	Lighting - Pendent/Surface	Room 203	2	EΑ	7	6-10 years	
	Power Distribution	Room 203	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 203	592	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Room 204 school psychologists	170	SF	6	10+ years	
	5 0 15 11	office				4.0	
	Doors - Steel Doors incl hw	Room 204 school psychologists	1	EA	6	10+ years	
	E. T.	office	470	0.5		0.40	
	Floor - Tile	Room 204 school psychologists	170	SF	6	6-10 years	
	11.14. 5.1.40.4	office			_	0.40	
	Lighting - Pendent/Surface	Room 204 school psychologists	2	EA	7	6-10 years	
	B	office	•		_	4.0	
	Power Distribution	Room 204 school psychologists	6	EA	7	10+ years	
	W II DI + /D II	office	470	0.5		40	
	Walls - Plaster/Drywall	Room 204 school psychologists	470	SF	6	10+ years	
		office					
160							
_Kitchen_	Osilia a Diastan/D	Danie 400	400			40	
	Ceiling - Plaster/Drywall	Room 103	400	SF	6	10+ years	

Campus Name: Mccormick Page : 28 of 44 Assessment Date: 02/28/2024



Catego	ry : Room		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	Room 103	2	EA	6	10+ years	
	Floor - Epoxy/ Painted	Room 103	400	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 103	4	EA	7	6-10 years	
	Serving Line	Room 103	10	LF	6	10+ years	
	Storage/ Closet	Room 103	90	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 103	576	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Plaster/Drywall	Room 102	1,770	SF	6	10+ years	
	Doors - Steel Doors incl hw	Room 102	2	EA	6	10+ years	
	Doors - Transom Window	Room 102	24	SF	6	10+ years	
	Floor - Tile	Room 102	1,746	SF	6	10+ years	
	Floor - Tile	Room 102	24	SF	4	1-2 years	Damaged floor
	Lighting - Pendent/Surface	Room 102	18	EA	7	6-10 years	Damaged 11001
	Storage/ Closet	Room 102	45	SF	5	10+ years	
	Walls - Plaster/Drywall	Room 102	1,980	SF	6	10+ years	
	Walls - Flastel/Drywall	ROUIII 102	1,960	SF	b	10+ years	
Mechani	cal/ Service Rooms						
	Janitor's Closet	2nd Floor	25	SF	7	10+ years	
	Storage Room	RM 104-Storage Room	90	SF	7	10+ years	
	Mechanical/ Service Rooms	RM 105-Electrical Switchgear	180	SF	7	10+ years	
	Mechanical/ Service Rooms	RM 107-Fire Sprinkler Room	50	SF	4	1-2 years	Damaged flooring
	Janitor's Closet	RM 112-Janitor's Closet	25	SF	5	1-2 years	Damaged wall
	Storage Room	Rm 108-Storage Room	100	SF	5	2-5 years	
Restroor	n						
	Accessories	2nd Floor	16	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	16	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	16	SF	6	10+ years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	48	SF	7	10+ years	
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	Boys 2nd floor	166	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys 2nd floor	166	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys 2nd floor	161	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys 2nd floor	5	SF	4	1-2 years	Damaged tile floor
	Floor Drain	Boys 2nd floor	2	EA	7	10+ years	2 aagaa ma naar
	Lavatory	Boys 2nd floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Boys 2nd floor	4	EA	7	6-10 years	
	Partitions	Boys 2nd floor	3	EA	7	10+ years	
	Urinals	Boys 2nd floor	3	EA	6	•	
	Ullida	Duys Zhu huul	3	EA	О	10+ years	

Page : 29 of 44 Campus Name: Mccormick Assessment Date: 02/28/2024



Catego	ry : Room		В	uilding	: Annex		<u> </u>
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Tile Ceramic/ Porcelain	Boys 2nd floor	528	SF	6	10+ years	
	Water Closet	Boys 2nd floor	3	EA	6	10+ years	
	Accessories	Boys first floor	112	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boys first floor	112	SF	6	10+ years	
	Doors - Steel Doors incl hw	Boys first floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Boys first floor	112	SF	6	10+ years	
	Floor Drain	Boys first floor	2	EA	7	10+ years	
	Lavatory	Boys first floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Boys first floor	3	EA	7	6-10 years	
	Partitions	Boys first floor	2	EA	7	10+ years	
	Urinals	Boys first floor	2	EΑ	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Boys first floor	238	SF	6	10+ years	
	Water Closet	Boys first floor	2	ĒΑ	6	10+ years	
	Accessories	Girl's first floor	112	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girl's first floor	112	SF	6	10+ years	
	Doors - Steel Doors incl hw	Girl's first floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girl's first floor	110	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girl's first floor	2	SF	4	1-2 years	Damaged and missing tile
	Floor Drain	Girl's first floor	1	EA	7	10+ years	Damaged and missing inc
	Lavatory	Girl's first floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Girl's first floor	3	EA	7	6-10 years	
	Partitions	Girl's first floor	3	EA	5	10+ years	
	Walls - Tile Ceramic/ Porcelain	Girl's first floor	234	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Girl's first floor	3	SF	4	1-2 years	Missing and damaged tile
	Water Closet	Girl's first floor	3	EA	6	10+ years	whoshing and damaged the
	Accessories	Girls 2nd floor	166	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Girls 2nd floor	166	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girls 2nd floor	166	SF	6	6-10 years	
	Floor Drain	Girls 2nd floor	1	EA	7	10+ years	
	Lavatory	Girls 2nd floor	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Girls 2nd floor	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	Girls 2nd floor	1	EA	5	1-2 years	Not working
	Partitions	Girls 2nd floor	4	EA	7	10+ years	Not working
	Walls - Tile Ceramic/ Porcelain	Girls 2nd floor	527	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Girls 2nd floor	1	SF	5	1-2 years	Damaged wall tile
	Water Closet	Girls 2nd floor	4	EA	6	10+ years	Damaged wall tile
	Accessories	Men's room 116	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Men's room 116	25	SF	6	10+ years	
	Doors - Steel Doors incl hw	Men's room 116	25	EA	6	10+ years	
	Floor - Tile	Men's room 116	25	SF	4	1-2 years	Cracked throughout
	Lavatory	Men's room 116	25	EA	6	10+ years	Orached initiagnout
	Lighting - Pendent/Surface	Men's room 116	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Men's room 116	52	SF	6	•	
	Water Closet	Men's room 116	52	EA	6	10+ years 10+ years	
	vvaldi Olusci	INICITS TOOTH I TO	ı	ĽA	O	10+ years	

Campus Name: Mccormick Page : 30 of 44 Assessment Date: 02/28/2024



Catego	ry : Room		R	uildina	: Annex		712 S Sawyer AVENUE, Chicago, IL 60623
Outogo	19 : 100111			ananig	· Alliox	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Accessories	Room 114A	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 114A	25	SF	6	10+ years	
	Doors - Steel Doors incl hw	Room 114A	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Room 114A	25	SF	6	10+ years	
	Lavatory	Room 114A	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Room 114A	1	EA	6	6-10 years	
	Walls - Tile Ceramic/ Porcelain	Room 114A	60	SF	6	10+ years	
	Water Closet	Room 114A	1	ĒΑ	6	10+ years	
	Accessories	Womens room 202	23	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Womens room 202	23	SF	6	10+ years	
	Doors - Steel Doors incl hw	Womens room 202	1	ĒΑ	6	10+ years	
	Floor - Tile	Womens room 202	18	SF	6	6-10 years	
	Floor - Tile	Womens room 202	5	SF	4	1-2 years	Damaged tile
	Lavatory	Womens room 202	1	EA	6	10+ years	zamagea me
	Lighting - Pendent/Surface	Womens room 202	1	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	Womens room 202	50	SF	6	10+ years	
	Walls - Plaster/Drywall	Womens room 202	2	SF	5	1-2 years	Damaged wall
	Water Closet	Womens room 202	1	EA	6	10+ years	Damagoa wan
	Water Closet	VV61116116 166111 262		_, 、	ŭ	ioi youlo	
Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	m #111 (Kindergarten)						
	Casework	1st Floor	22	LF	6	10+ years	
	Ceiling - Splined	1st Floor	841	SF	6	10+ years	
	Doors - Side-lite	1st Floor	6	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	841	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	928	SF	6	10+ years	
	Work Sink	1st Floor	1	EΑ	7	10+ years	
Classroc	m #114 (Pre School)		·				
Classroc	Casework	1st Floor	25	LF	6	10+ years	
Classroc	Casework Ceiling - Plaster/Drywall	1st Floor	25 90	LF SF	6	10+ years 10+ years	
Classroc	Casework Ceiling - Plaster/Drywall Ceiling - Splined	1st Floor 1st Floor	25 90 1,060	LF SF SF	6 6	•	
Classroo	Casework Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite	1st Floor 1st Floor 1st Floor	25 90 1,060 12	LF SF SF SF	6 6 6	10+ years	
Classroc	Casework Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Steel Doors incl hw	1st Floor 1st Floor 1st Floor 1st Floor	25 90 1,060	LF SF SF SF EA	6 6 6	10+ years 10+ years	
Classroc	Casework Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Steel Doors incl hw Floor - Tile	1st Floor 1st Floor 1st Floor	25 90 1,060 12	LF SF SF SF	6 6 6 6	10+ years 10+ years 10+ years	
Classroc	Casework Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Steel Doors incl hw	1st Floor 1st Floor 1st Floor 1st Floor	25 90 1,060 12 1	LF SF SF EA SF EA	6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	
Classroc	Casework Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Steel Doors incl hw Floor - Tile	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	25 90 1,060 12 1 1,150	LF SF SF EA SF EA LF	6 6 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 6-10 years	
Classroc	Casework Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	25 90 1,060 12 1 1,150	LF SF SF EA SF EA	6 6 6 6 7	10+ years 10+ years 10+ years 10+ years 10+ years	



Catego	ry : Classroom		В	uilding	: Annex		
			•		ъ.	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroo	m #115 (Kindergarten)						
	Casework	1st Floor	25	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	90	SF	6	10+ years	
	Ceiling - Splined	1st Floor	743	SF	6	10+ years	
	Ceiling - Splined	1st Floor	8	SF	4	1-2 years	Stained tile
	Doors - Side-lite	1st Floor	12	SF	6	10+ years	Clairied the
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	841	SF	6		
						10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	846	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #210 (Regular Classroom)						
	Casework	2nd Floor	21	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	217	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	649	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	4	SF	4	1-2 years	Damaged ceiling
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	Damaged Celling
	Doors - Steel Doors incl hw				_		
		2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	856	SF	6	10+ years	A.4: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Floor - Tile	2nd Floor	14	SF	4	1-2 years	Missing and damaged tile
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,264	SF	6	10+ years	
lassroo	m #211 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	217	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	653	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	860	SF	6	6-10 years	
	Floor - Tile	2nd Floor 2nd Floor	10	SF	4	1-2 years	Cracked and damaged floor
						-	Cracked and damaged 11001
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,264	SF	6	10+ years	
lassroo	m #212 (Regular Classroom)						
	Ceiling - Plaster/Drywall	2nd Floor	217	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	653	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
			•	EA	•	,	



Catego	ry : Classroom		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	870	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	1-2 years	Not working
	Marker Board	2nd Floor	8	LF	7	6-10 years	3
	Walls - Plaster/Drywall	2nd Floor	1,264	SF	6	10+ years	
Nooroe	om #214 (Regular Classroom)						
JIASSIUC		0-15	047	0.5		40	
	Ceiling - Plaster/Drywall	2nd Floor	217	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	653	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	860	SF	6	6-10 years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Damaged floor
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	•	
						6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,264	SF	6	10+ years	
lassroo	om #215 (Kindergarten)						
	Ceiling - Plaster/Drywall	2nd Floor	84	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	776	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	7	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	-	
	Floor - Tile			SF		10+ years	
		2nd Floor	840		6	10+ years	5
	Floor - Tile	2nd Floor	20	SF	4	1-2 years	Damaged flooring
	Lighting - Wall Mounted	2nd Floor	9	EΑ	7	6-10 years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	657	SF	6	10+ years	
Classroo	om #216 (Kindergarten)						
	Ceiling - Plaster/Drywall	2nd Floor	217	SF	6	10+ years	
	Ceiling - Splined	2nd Floor	635	SF	6	10+ years	
	Ceiling - Splined Ceiling - Splined	2nd Floor	18	SF	4	1-2 years	Stained tile
				SF SF			Statiled tile
	Doors - Side-lite	2nd Floor	7		6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	850	SF	6	6-10 years	
	Floor - Tile	2nd Floor	20	SF	4	1-2 years	Cracked and damaged floor
	Lighting - Pendent/Surface	2nd Floor	9	EA	7	6-10 years	•
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,264	SF	6	10+ years	
:lassror	om #218 (Regular Classroom)						
2.400.00	Ceiling - Plaster/Drywall	2nd Floor	144	SF	6	10+ years	
						•	
	Ceiling - Splined	2nd Floor	432	SF	6	10+ years	

Campus Name: Mccormick Page : 33 of 44 Assessment Date: 02/28/2024



#### Cyrus H McCormick Elementary School 2712 S Sawyer AVENUE, Chicago, IL 60623

ry : Classroom		В	uilding	: Annex	(	, ,
		_			Recommend	_
					<u>-</u>	Comments
		7			,	
Doors - Steel Doors incl hw	2nd Floor			6	10+ years	
Floor - Tile		575		6	10+ years	
Floor - Tile	2nd Floor	1	SF	4	1-2 years	Damaged tile
Lighting - Pendent/Surface	2nd Floor	9	EA	7	6-10 years	
Marker Board	2nd Floor	16	LF	7	6-10 years	
Walls - Plaster/Drywall	2nd Floor	837	SF	6	10+ years	
m #219 (Special Program)						
	2nd Floor	238	SF.	6	10± vears	
					•	
					,	
Walls - Plaster/Drywall	2nd Floor	345	SF	6	10+ years	
m #220 (Multi Purpose Room)						
Ceiling - Plaster/Drywall	2nd Floor	245	SF	6	10+ years	
Ceiling - Splined	2nd Floor	735	SF	6	10+ years	
	2nd Floor	14	SF		10+ years	
	2nd Floor	2	EA			
Walls - Plaster/Drywall	2nd Floor	1,424	SF	6	10+ years	
v · Interior		R	uildina	· Annex	•	
y . Interior			ununig	. Amica	Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Coiling Plactor/Drawall	1st Floor	2/10	QE.	6	10 L VOORS	
					•	
						Department of the st
		-				Damaged ceiling
Drinking Fountains - Single Fountain	1st Floor	2	EA	5	10+ years	
Floor - Tile/Sheet	1st Floor	1,904	SF	5	10+ years	
Floor - Tile/Sheet Floor - Tile/Sheet	1st Floor 1st Floor	1,904 10	SF	4	1-2 years	Damaged tile
Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor	1,904 10 19	SF EA		•	Damaged tile
Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall	1st Floor 1st Floor	1,904 10 19 2,002	SF EA SF	4	1-2 years	Damaged tile
Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor 1st Floor 1st Floor	1,904 10 19	SF EA	4 7	1-2 years 6-10 years	Damaged tile
Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall Ceiling - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor	1,904 10 19 2,002 379	SF EA SF SF	4 7 6 6	1-2 years 6-10 years 10+ years 10+ years	Damaged tile
Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Walls - Plaster/Drywall	1st Floor 1st Floor 1st Floor 1st Floor 2nd Floor	1,904 10 19 2,002	SF EA SF	4 7 6	1-2 years 6-10 years 10+ years	Damaged tile
	Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall  m #219 (Special Program) Ceiling - Plaster/Drywall Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall  m #220 (Multi Purpose Room) Ceiling - Plaster/Drywall Ceiling - Splined Doors - Side-lite Doors - Steel Doors incl hw Floor - Tile Lighting - Pendent/Surface Marker Board Walls - Plaster/Drywall  ry: Interior  Item - Type  Ceiling - Plaster/Drywall Ceiling - Splined Ceiling - Splined Ceiling - Splined Ceiling - Splined Doors - Steel Doors incl hw	Item - Type	Location   Quantity	Location	Location	



Catego	ry : Interior	В	uilding	: Annex			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	2nd Floor	1,123	SF	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	5	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	2nd Floor	11	EA	7	6-10 years	· ·
	Walls - Plaster/Drywall	2nd Floor	2,709	SF	6	10+ years	
Safety							
,	Camera Viewing Station	Entire Building	1	EA	7	10+ years	
	Security Cameras	Entire Building	16	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North	106	SF	6	10+ years	
	Ceiling - Splined	North	119	SF	6	10+ years	
	Floor - Tile	North	226	SF	6	6-10 years	
	Handrails	North	45	LF	7	10+ years	
	Lighting - Pendent/Surface	North	3	EA	7	6-10 years	
	Stairs - Rubber	North	25	LF	6	10+ years	
	Walls - Plaster/Drywall	North	560	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	106	SF	6	10+ years	
	Ceiling - Splined	South	119	SF	6	10+ years	
	Floor - Tile	South	226	SF	6	6-10 years	
	Handrails	South	45	LF	7	10+ years	
	Lighting - Pendent/Surface	South	3	EA	7	6-10 years	
	Stairs - Rubber	South	72	LF	6	10+ years	Updated quantity
	Stairs - Rubber	South	3	LF	4	1-2 years	Damaged tread
	Walls - Plaster/Drywall	South	560	SF	6	10+ years	Ŭ

Campus Name: Mccormick Page : 35 of 44 Assessment Date: 02/28/2024





Category: Exterior Building: Modular 1 (2-Classroom) Recommend Location Replacement Comments Item - Type Quantity **UOM** Rank Group Entrance #1 S FΑ Entrance Control - Audio and Video 1 6 6-10 years #1 S 2 EΑ 7 Exterior Doors - Exterior FRP Door 10+ years Exterior Stairs - Steel or Aluminum #1 S LF 40 7 10+ years Power Door Operator and Controls #1 S 1 EΑ 7 10+ years Ramp Handrail - Steel Ramp Handrail LF #1 S 90 7 10+ years Ramps - Steel or Aluminum LF #1 S 45 7 10+ years LF Stair Handrail - Steel\_Stair Handrail #1 S 25 7 10+ years Exterior Doors - Exterior FRP Door #2 N 1 EΑ 7 10+ years Exterior Stairs - Steel or Aluminum #2 N 36 LF 7 10+ years #2 N LF 7 Stair Handrail - Steel Stair Handrail 20 10+ years Exterior Doors - Exterior FRP Door #3 N 1 EΑ 7 10+ years LF 7 Exterior Stairs - Steel or Aluminum #3 N 36 10+ years ΙF Stair Handrail - Steel Stair Handrail #3 N 20 7 10+ years Foundation Foundation - Concrete LF 7 **Entire Building** 236 10+ years Superstructure - Slab on Grade **Entire Building** 41,184 SF 7 10+ years \_Liahtina Exterior Lighting - Wall Mounted **Entire Building** 11 EΑ 6 6-10 years Roof System Coping - Metal **Entire Building** LF 6-10 years 236 6 LF Downspouts - Exterior Downspouts **Entire Building** 78 6 6-10 years Roof - Modified Bitumen **Entire Building** 3,168 SF 5 2-5 years SF Roof Structure - Heavy Timber **Entire Building** 3.168 7 10+ years Walls Exterior Walls - Wood Siding 3.068 SF 6 **Entire Building** 6-10 years Windows Guard - Guards wire guard **Entire Building** 320 SF 6 6-10 years Windows - Sash Aluminum 320 SF 6 6-10 years **Entire Building** Category: Electrical Building: Modular 1 (2-Classroom) Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Emergency System Security System - CCTV 1st Floor 1,960 SF 6 6-10 years Security System - Intrusion Detection 1st Floor 1,960 SF 5 6-10 years



Catego	ry : Electrical		В	uildina	: Modul	ar 1 (2-Classro	om )		
			_	9	5	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
·	Exit Signs - Corridors and Stairs	1st Floor	4	EA	2	0-1 year	Signs have no backup batteries and the school has no emergency generator.		
	Emergency Battery Packs - Corridors and Stairs	1st Floor	3	EA	6	6-10 years	Quantity changed to match current observations.		
	Item - Type Exit Signs - Corridors and Stairs  Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Students Toilet  Vice PA System  Stribution Lighting and Power Panels - 100 A  Lighting and Power Panels - Above 100 A  Ty: Fire Protection  Item - Type  Image: Fire Alarm Anunciator Fire Alarm Strobe Lights Fire Alarm_System  Ty: Mechanical  Item - Type  Item -	1st Floor	2	EA	6	6-10 years			
Main Se	rvice								
	PA System	1st Floor	1,960	SF	6	6-10 years	Served by Main.		
Power D	vistribution								
	Lighting and Power Panels - 100 A	1st Floor 1st Floor	3	EA EA	7	0-1 year 10+ years	Quantity changed to match current observations. Rank, Reason and Priority Rep changed as open fuse receptacles expose live conductors presenting a live front condition. Quantity and Item Type changed to match current observations.		
Catego	ry : Fire Protection	В	uilding	: Modul	ar 1 (2-Classro	om )			
_			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Fire Alar	m								
	Fire ALarm Anunciator	1st Floor	1	EA	6	6-10 years	No CPS Asset Tag present.		
		1st Floor	1	EA	6	10+ years			
		1st Floor	1,960	SF	6	10+ years			
	Fire Alarm_System	1st Floor	1,960	SF	6	10+ years			
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (2-Classro	om )		
	_					Recommend	_		
Group		Location	Quantity	UOM	Rank	Replacement	Comments		
Tempera		Classesses	4	ΕΛ		C 40			
	Electric Thermostat	Classrooms	4	EA	6	6-10 years	Location changed for clarification.		
Unit Ven									
	Heat & Self Contained Cooling	1st Floor	1	EA	6	6-10 years			
	Heat & Self Contained Cooling	1st Floor	1	EA	6	6-10 years	SE new motor		
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	1st Floor	2	EA	6	6-10 years	Quantity changed as total has bee divided/aggregated. Location changed for clarification.		

Campus Name: Mccormick Page : 37 of 44 Assessment Date: 02/28/2024



#### Cyrus H McCormick Elementary School 2712 S Sawyer AVENUE, Chicago, IL 60623

Catego	ry : Mechanical		E	Building	: Modul	ar 1 (2-Classro	oom )	
_						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
entilatio		Entire Duilding	2	ГΛ	F	6.10 years		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	5	6-10 years		
	CFIVI							
atego	ry : Plumbing		E	Building	: Modul	ar 1 (2-Classro	oom )	
	,					Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
ot Wate	er							
	Electric Heater - Less than 20 KW	1st Floor	1	EA	7	6-10 years	Rank adjusted based on current	
							observations and on the age of the	
							equipment.	
iping	Domostic Dining Hot Water Datum Lines	Entire Building	4.000	C.E.		10		
	Domestic Piping-Hot Water Return Lines Domestic Piping-Hot/Cold Water Supply	Entire Building Entire Building	1,960 1,960	SF SF	6 6	10+ years 10+ years		
	(Horizontal Lines)	Little building	1,900	J.	O	TOT years		
	Sanitary Piping	Entire Building	1,960	SF	6	10+ years		
	Storm Piping	Entire Building	1,960	SF	6	10+ years		
	Vent Piping	Entire Building	1,960	SF	6	10+ years		
ateno	ry : Classroom		p	Ruildina	· Modul	ar 1 (2-Classro	nom )	
alcgo	19 : 01033100111		Building : Modular 1 (2-Classroom ) Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
lassroo	m #116 (Office)		_			<u>-</u>		
	Casework	1st Floor	12	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,120	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years		
	Floor - Tile	1st Floor	1,120	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years		
	Marker Board	1st Floor	20	LF	7	6-10 years		
	Storage/ Closet	1st Floor	87	SF	7	10+ years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,048	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	7	6-10 years		
Classroo	m #117 (Office)							
	Casework	1st Floor	12	LF	7	10+ years		
	Ceiling - Lay-in	1st Floor	1,120	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years		
	Floor - Tile	1st Floor	1,120	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor	6	EA	7	6-10 years		
	Lighting - Lay-in	1st Floor	9	EΑ	5	1-2 years	Not working from main switch	
	3 · 3 <del>,</del>		· ·		-	. = ,		
amplie N	Jame: Mccormick		Page : 38 of 44				Assessment Date: 02/28	

Campus Name: Mccormick Assessment Date: 02/28/2024 Page : 38 of 44



Catego	ry : Classroom		В	uilding	: Modul	ar 1 (2-Classro	om )	
	Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Marker Board	1st Floor	20	LF	7	6-10 years		
	Walls - Vinyl Coated Gypsum Panel	1st Floor	1,048	SF	6	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		

Category: Room Building: Modular 1 (2-Classroom)

atego	ry : Room		Building : Modular 1 (2-Classroom )						
	H T	Landin.	0	шом	DI	Recommend	0		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
estroor									
	Accessories	1st Floor	48	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor	48	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	45	SF	7	6-10 years			
	Floor - Tile	1st Floor	3	SF	4	1-2 years	Cracked and damaged tile		
	Hand Dryer	1st Floor	1	EA	7	10+ years			
	Lavatory	1st Floor	1	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	82	SF	7	10+ years			
	Water Closet	1st Floor	1	EA	7	10+ years			
	Accessories	Bathroom in Room 116	48	SF	7	6-10 years			
	Ceiling - Lay-in	Bathroom in Room 116	48	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Bathroom in Room 116	1	EA	7	10+ years			
	Floor - Tile	Bathroom in Room 116	48	SF	7	6-10 years			
	Floor Drain	Bathroom in Room 116	1	EA	7	10+ years			
	Hand Dryer	Bathroom in Room 116	1	EA	7	10+ years			
	Lavatory	Bathroom in Room 116	1	EA	6	10+ years			
	Lighting - Lay-in	Bathroom in Room 116	1	EA	6	6-10 years			
	Lighting - Lay-in	Bathroom in Room 116	1	EA	5	1-2 years	Not working		
	Walls - Vinyl Coated Gypsum Panel	Bathroom in Room 116	82	SF	6	10+ years	· ·		
	Water Closet	Bathroom in Room 116	1	EA	7	10+ years			
	Accessories	Bathroom in Room 117	48	SF	7	6-10 years			
	Ceiling - Lay-in	Bathroom in Room 117	48	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Bathroom in Room 117	1	EA	7	10+ years			
	Floor - Tile	Bathroom in Room 117	48	SF	7	6-10 years			
	Floor Drain	Bathroom in Room 117	1	EA	7	10+ years			
	Hand Dryer	Bathroom in Room 117	1	EA	7	6-10 years			
	Lavatory	Bathroom in Room 117	1	EA	7	10+ years			
	Lighting - Lay-in	Bathroom in Room 117	2	EA	7	6-10 years			
	Walls - Vinyl Coated Gypsum Panel	Bathroom in Room 117	82	SF	6	10+ years			
	Water Closet	Bathroom in Room 117	1	ĒΑ	7	10+ years			

Campus Name: Mccormick Page : 39 of 44 Assessment Date: 02/28/2024



Catego	ry : Interior		В	uilding	: Modul	ar 1 (2-Classro	oom )
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	160	SF	6	10+ years	
	Floor - Tile/Sheet	1st Floor	159	SF	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1	SF	4	1-2 years	Damaged tile
	Lighting - Lay-in	1st Floor	3	EA	7	6-10 years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	300	SF	6	10+ years	
Safety							
,	Security Cameras	1st Floor	2	EA	7	10+ years	

Campus Name: Mccormick Page : 40 of 44 Assessment Date: 02/28/2024





Category : Site **Building: Site** 

Catego	ry : Site		В	ullaing	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	6	10+ years	
	Civil Brainage Cite Mannele	Emilio Oito	· ·		J	101 youro	
Canaina							
Fencing	Faraina Chain Link	Finding City	220	1.5	4	0.4.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Damarad
	Fencing - Chain Link	Entire Site	320	LF LF	4	0-1 year	Damaged.
	Fencing - New Standard Ornamental	Entire Site	826	LF	6	6-10 years	
Landsca	•						
	Benches	Entire Site	4	EA	6	6-10 years	
	Landscape - Grass	Entire Site	3,009	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	4,299	SF	6	10+ years	
	Landscape - Mulch	Entire Site	50	SF	7	6-10 years	
	Parkway trees	Entire Site	20	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	1,324	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	11,024	SF	7	10+ years	Repaired
	Trash Receptacles	Entire Site	5	EA	6	6-10 years	
Parking							
	Surface - Asphalt	Northwest	460	SF	7	10+ years	Repaired
	Surface - Asphalt	Parking Lot- South	4,240	SF	7	10+ years	Repaired
	Surface - Asphalt	Parking Lot- South	2,000	SF	7	10+ years	Repaired
	Surface - Asphalt	Parking Lot- South	2,000	SF	7	10+ years	Repaired
	Surface - Asphalt	Parking Lot- South	2,000	SF	7	10+ years	Repaired
	Trash Compactor	Parking Lot- South	1	EA	6	6-10 years	·
	Trash Enclosure - Chain Links	Parking Lot- South	100	SF	5	2-5 years	
	Vehicular Screening	Parking Lot- South	20	LF	7	10+ years	
Playgrou							
	Equipment - Pre K 3-5	North East Site	1	EA	6	6-10 years	
	Surface - Poured Surface	North East Site	1,296	SF	6	6-10 years	
Sidewalk							
	Sidewalks - Perimeter Sidewalks	Entire Site	13,854	SF	6	10+ years	
Signage							
Signage	Flag Pole - Building Mounted Flag Pole	East Facade, Northeast	1	EA	7	6-10 years	
	Marquee - Building Mounted Plag Fole  Marquee - Building Mounted Back Lighted	East Facade, Northeast	1	EA	7	6-10 years	Replaced.
	Marquee - Building Mounted Back Lighted  Marquee - Building Mounted Back Lighted	East Facade, Northeast	1	EA	6	2-5 years	Nopidocu.
	Monument - Building Mounted Cut Letter	East Facade, Northeast	1	EA	7	10+ years	
	Sign	Last Facade, Northeast	ļ	EA	,	10+ years	
	Sign						



#### **Cyrus H McCormick Elementary School**

Recommend

2712 S Sawyer AVENUE, Chicago, IL 60623

Category : Site Building : Site

Group Item - Type Location Quantity UOM Rank Replacement Comments

<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Mccormick Page : 42 of 44 Assessment Date: 02/28/2024





**Classroom Summary** 

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Computer Lab	Regular Classroom	2nd Floor	202	202	884	52	26	N	N
Computer Lab	Regular Classroom	2nd Floor	208	208	884	112	56	N	N
Faculty Lounge	Kindergarten	1st Floor	101	101	900	150	75	N	N
Faculty Lounge	Regular Classroom	2nd Floor	206	206	884	110	55	N	N
Library	Regular Classroom	1st Floor	108	108	900	116	58	N	N
Office	Regular Classroom	1st Floor	103	103	850	100	50	N	N
Office	Regular Classroom	2nd Floor	205	205	884	90	45	N	N
Regular Classroom	Kindergarten	1st Floor	109	109	900	150	75	N	N
Regular Classroom	Library	1st Floor	106	106	825	88	33	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	900	68	34	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	825	110	55	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	850	100	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	884	150	75	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	884	100	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	884	110	55	N	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	884	100	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	884	150	75	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	301	884	110	55	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	884	110	55	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	884	84	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	884	84	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	305	305	988	91	46	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	884	84	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	884	84	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	884	110	55	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	884	110	55	N	N
				•	l .	l .			l
Building : Annex									
Kindergarten	Regular Classroom	1st Floor	111	111	841	126	26	N	Υ
Kindergarten	Regular Classroom	1st Floor	115	115	841	126	26	N	Υ
Kindergarten	Regular Classroom	2nd Floor	215	215	860	126	26	N	Υ
Kindergarten	Regular Classroom	2nd Floor	216	216	870	126	26	N	Υ
Multi Purpose Room	Regular Classroom	2nd Floor	220	220	980	210	43	N	N
Pre School	Kindergarten	1st Floor	114	114	1,150	183	26	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	210	210	870	126	26	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	870	126	26	N	Y
Regular Classroom	Regular Classroom	2nd Floor	212	212	870	126	26	N	Y
Regular Classroom	Regular Classroom	2nd Floor	214	214	870	126	26	N	Y



**Classroom Summary** 

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	2nd Floor	218	218	576	126	26	N	Υ
Special Program	Regular Classroom	2nd Floor	219	N/A	238	42	9	N	N

Building : Modular 1 (2-Classroom )											
Office	Pre School	1st Floor	116	N/A	1,120	96	48	N	N		
Office	Pre School	1st Floor	117	N/A	1 120	96	48	N	Υ		