

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1881	3	58,108
Campus Total			58,108

atego	ry : Exterior		ь	uilding	. IVIAIII		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ell Equ	ipment						
	Cell Equipment - Antenna	Roofs	3	EA	7	10+ years	
	Cell Equipment - Cabinets	Roofs	2	EA	7	10+ years	
ntrance							
	Exterior Doors - Store Front	8-Courtyard	1	EA	7	10+ years	
	Entrance Control - Audio and Video	Door 1 - West	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 1 - West	2	EA	5	1-2 years	Corroding frames, doors also showing evidence of corrosion
	Exterior Doors - Transom Lite	Door 1 - West	1	EA	6	10+ years	-
	Exterior Stairs - Concrete	Door 1 - West	7	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 2 - North	2	EA	6	6-10 years	Confirmed that this is surface rus
	Exterior Doors - Transom Lite	Door 2 - North	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 2 - North	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 3 - West center	1	EA	4	0-1 year	Corroded door and frame
	Exterior Doors - Exterior Steel Door	Door 4 - Southwest	3	EA	4	1-2 years	Corroding doors
	Exterior Doors - Transom Lite	Door 4 - Southwest	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 4 - Southwest	9	LF	5	6-10 years	
	Entrance Control - Audio and Video	Door 5 - south	1	EA	7	10+ years	
	Exterior Doors - Store Front	Door 5 - south	4	EA	7	10+ years	
	Power Door Operator and Controls	Door 5 - south	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 6 - East	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 7 - South West	1	EA	4	0-1 year	Oh, rotting, wood frame, corrode metal cover on door, holes
	Exterior Doors - Exterior Steel Door	Doors 9,10,11,12,13 Fire escape	1	EA	7	10+ years	

Campus Name: Minoso Page : 1 of 25 Assessment Date: 11/14/2023





Catego	ry : Exterior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Wood Door	Doors 9,10,11,12,13 Fire escape	4	EA	6	6-10 years	
	Exterior Doors - Exterior Wood Door	Doors 9,10,11,12,13 Fire escape	1	EA	5	0-1 year	Door is not opening on the second floor.room 206
	Exterior Doors - Transom Lite	Doors 9,10,11,12,13 Fire escape	3	EA	6	6-10 years	
	Exterior Stairs - Concrete	Doors 9,10,11,12,13 Fire escape	15	LF	6	10+ years	
_Fire Esc	ane						
	Exterior Doors - Exterior Steel Door	NW Site	1	EA	6	10+ years	
	Exterior Doors - Exterior Wood Door	NW Site	4	EA	6	6-10 years	
	Exterior Doors - Exterior Wood Door	NW Site	1	EA	5	0-10 years	Doesn't open
	Fire Escape	NW Site	135	LF	6	6-10 years	Doesn't open
	Paints	NW Site	135	LF	3	1-2 years	Fire escape is corroding
		····· one	100		Ü	. 2 yours	r no occupe to containing
_Foundat							
	Foundation - Masonry	Entire Building	534	LF . –	7	10+ years	
	Foundation - Masonry	Entire Building	50	LF	5	1-2 years	Missing, deteriorate mortar. Verified condition. Missing masonry
	Superstructure - Concrete	Entire Building	58,108	SF	7	10+ years	
Lighting							
0 0	Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	6-10 years	Added 3 new fixtures
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	4	0-1 year	Broken
Roof Sy	stem						
•	Access Ladder - Metal	Roof 1	2	EA	7	10+ years	New
	Coping - Metal	Roof 1	23	LF	7	10+ years	New
	Coping - Stone	Roof 1	298	LF	7	10+ years	New
	Downspouts - Exterior Downspouts	Roof 1	189	LF	7	10+ years	New
	Parapet - 16" - 30" Height	Roof 1	275	LF	7	10+ years	New
	Parapet - Parapet < 16" Height	Roof 1	46	LF	7	10+ years	New
	Roof - Modified Bitumen	Roof 1	8,250	SF	7	10+ years	Revised quantity to match existing
	Roof Hatch - Metal	Roof 1		EΑ	7	10+ years	New
	Roof Structure - Heavy Timber	Roof 1	8,250	SF	7	10+ years	
	Access Ladder - Metal	Roof 2	1	ĒΑ	7	10+ years	
	Coping - Stone	Roof 2	258	LF	7	10+ years	New
	Downspouts - Exterior Downspouts	Roof 2	134	LF	7	10+ years	New
	Parapet - 16" - 30" Height	Roof 2	68	LF	7	10+ years	New
	Parapet - Parapet > 30"	Roof 2	190	LF	7	10+ years	New
	Roof - Modified Bitumen	Roof 2	3,962	SF	7	10+ years	
	Roof Hatch - Metal	Roof 2	3,302	EA	7	10+ years	
	Roof Structure - Heavy Timber	Roof 2	3,962	SF	7	10+ years	
	Access Ladder - Metal	Roof 3	3,962	EA	7	10+ years 10+ years	
	Access Ladder - Metal	Roof 3	1	EA	4	0-1 year	Dangerous transition from one ladder
	Access Laudel - Metal	1,001 3	1	EA	4	0-i yeai	Dangerous transition from one lauder

Campus Name: Minoso Page : 2 of 25 Assessment Date: 11/14/2023



Category : Exterior

Building : Main

Category : Exterior Building : Main							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	•					•	to the other. Nowhere to hold onto,
							one has to twist one's body with
							nowhere to hold onto
	Coping - Stone	Roof 3	155	LF	7	10+ years	New
	Downspouts - Exterior Downspouts	Roof 3	63	LF	7	10+ years	New
	Parapet - 16" - 30" Height	Roof 3	155	LF	7	10+ years	New
	Roof - Modified Bitumen	Roof 3	2,185	SF	7	10+ years	Recombined quantities
	Roof Hatch - Metal	Roof 3	2,103	EA	7	10+ years	recombined quantities
	Roof Structure - Heavy Timber	Roof 3	2,185	SF	7	10+ years	
	Access Ladder - Metal	Roof 4 - lower east	2,103	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 4 - lower east	65	LF	6	10+ years	
	Liner	Rooi 4 - lower east	00	LF	O	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Poof 4 Jower cost	90	LF	6	6 10 vooro	Danairad
		Roof 4 - lower east	80	LF	6	6-10 years	Repaired
	Liner	Doct 4 January 2004	40		7	40	Marri
	Coping - Stone	Roof 4 - lower east	16	LF	7	10+ years	New
	Coping - Stone	Roof 4 - lower east	176	LF	6	10+ years	New
	Downspouts - Exterior Downspouts	Roof 4 - lower east	40	LF	7	10+ years	New
	Parapet - 16" - 30" Height	Roof 4 - lower east	192	LF	7	10+ years	New
	Roof - Modified Bitumen	Roof 4 - lower east	2,522	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 4 - lower east	2,522	SF	7	10+ years	
	Concrete Topping						
	Coping - Stone	Roof 5 - lower west roofs	25	LF	7	10+ years	New
	Downspouts - Exterior Downspouts	Roof 5 - lower west roofs	32	LF	7	10+ years	New
	Parapet - Parapet < 16" Height	Roof 5 - lower west roofs	25	LF	7	10+ years	New
	Roof - Modified Bitumen	Roof 5 - lower west roofs	100	SF	7	10+ years	
	Roof - Modified Bitumen	Roof 5 - lower west roofs	31	SF	6	10+ years	
	Roof Structure - Heavy Timber	Roof 5 - lower west roofs	131	SF	7	10+ years	
	Coping - Stone	Roof 6	34	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 6	15	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 6	34	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 6	240	SF	7	10+ years	
	Roof Structure - Heavy Timber	Roof 6	240	SF	7	10+ years	
	Coping - Stone	Roof 7 - Southwest Entrance	34	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 7 - Southwest Entrance	15	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 7 - Southwest Entrance	34	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 7 - Southwest Entrance	250	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 7 - Southwest Entrance	250	SF	7	10+ years	
	Concrete Topping					, , , , , , , , , , , , , , , , , , , ,	
	Consists ropping						
_Walls							
vvalis	Canopy - Metal	Entire Building	0.4	OE.	7	10 L VOORS	
		Entire Building	84	SF	7	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	1,168	LF	6	10+ years	Name
	Cornice - Metal Projecting	Entire Building	403	LF	7	10+ years	New
	Cornice - Metal Projecting	Entire Building	20	LF	7	10+ years	New

Campus Name: Minoso Page : 3 of 25 Assessment Date: 11/14/2023



Building: Main Category: Exterior Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments SF Exterior Walls - Brick **Entire Building** 1.125 7 10+ years Exterior Walls - Brick Entire Building 4.200 SF 7 10+ years Exterior Walls - Brick **Entire Building** 34,740 SF 6 10+ years Entire Building 100 SF 0-1 year Open joints, cracked brick. Some Exterior Walls - Brick repairs of previous assessment have been made Exterior Walls - Prefabricated Metal Panel **Entire Building** 90 SF 6-10 years 6 Wall Exterior Walls - Stone-Cast **Entire Building** 580 SF 6 10+ years SF Exterior Walls - Stone-Cast **Entire Building** 30 4 0-1 year Spalled, broken stone Windows Curtain wall - Glazed Double Pane **Entire Building** 200 SF 7 10+ years SF Guard - Guards perforated **Entire Building** 2.968 6 6-10 years Lintels - Brick Entire Building LF 6 10+ years 15 Lintels - Stone **Entire Building** 479 LF 6 10+ years Entire Building LF Lintels - Terra Cotta 72 6 10+ years SF 7 Windows - Louver **Entire Building** 16 10+ years Not previously assessed SF Windows - Sash Aluminum Double-pane **Entire Building** 4,961 6 6-10 years Corrected quantity

Category : Electrical Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
ŭ	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,146	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	4,503	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	2,747	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	10	EA	7	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	4	EA	7	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	6	6-10 years	
	Security System - CCTV	Entire Building	58,108	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	58,108	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	18	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	4	EA	6	6-10 years	
	Emergency Generator- Outdoor- Diesel - 60 - 100 KW	Site - East	1	EA	5	2-5 years	

Main Service



Catego	ry : Electrical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	58,108	SF	5	2-5 years	
	Independent Electrical Service for	Mechanical Room	1	EA	6	6-10 years	For fire
	emergency power	Weenaniea Room	•	L/\	Ū	o to years	1 of file
Power D	istribution						
01101 D	Lighting and Power Panels - 100 A	Entire Building	7	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A Lighting and Power Panels - Above 100 A	Entire Building	7	EA	7	10+ years	
	Lighting and Dower Panels - Above 100 A					•	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EΑ	6	6-10 years	-
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	10+ years	Front door off, exposed wires
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire Alarm Panel	Entire Building	1	EA	7	6-10 years	Annunciator panel
	Fire Alarm Panel	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	58,108	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	58,108	SF	6	6-10 years	
	Fire Pump Controller	Entire Building	1	EA	4	1-2 years	Obsolete parts
Pump Ro	oom Assembly						
	Fire Pump - 25-50 hp	Fire Pump Room	1	EA	5	2-5 years	
	•	·				•	
Sprinkler	System Dry Sprinkler System	Entire Building	58,108	SF	5	2-5 years	
	Sprinkler Heads	Entire Building	58,108	SF	7	6-10 years	
			,	SF		•	
	Sprinkler Piping	Entire Building	58,108	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main	D	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Cond	litionina						
	Condensing Unit- Ground Mounted - Less than 5 tons	Central Courtyard	1	EA	6	6-10 years	
	Condensing Unit- Ground Mounted - Less than 5 tons	Central Courtyard	1	EA	5	6-10 years	
	Condensing Unit- Roof Mounted - Less	Lower Roof	1	EA	6	10+ years	Difficult/unsafe to access



Catego	y : Mechanical B				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Condensing Unit- Roof Mounted - Less than 5 tons	Lower Roof	1	EA	6	10+ years	
Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Electric	Basement	1	EA	6	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	Basement	1	EA	6	6-10 years	
	Make Up Air Unit-Ground Mounted- Gas	Central Courtyard	1	EA	5	6-10 years	
	Heating - Less than 6000 cfm						
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 15000 - 30000 cfm	Entire Building	1	EA	5	6-10 years	Exterior housing rusting with excessive peeling paint
	Air Intake	Entire Building	1	EA	5	6-10 years	
	Auxiliaries - 15000 - 30000 cfm	Entire Building	1	EA	6	6-10 years	
	Return Duct Work - Masonry and Ducts-	Entire Building	100	LF	6	6-10 years	
	Missing or Existing Shaft	3			-	,	
	Zone Dampers	Entire Building	35	EA	6	6-10 years	
Boiler Sv	vstems						
,	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 50 - 75 HP	Entire Building	2	EA	5	6-10 years	
	Chemical Feed System	Entire Building	1	EA	6	6-10 years	
	Combustion Dampers	Entire Building	2	EA	5	6-10 years	
	Condensate Pump	Entire Building	1	EA	5	6-10 years	
	Condensate Pump	Entire Building	1	EA	5	6-10 years	
	Feed Water Pumps and Tank	Entire Building	1	EA	5	6-10 years	
	Non Condensing - Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP	Entire Building	1	EA	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP	Entire Building	1	EA	5	6-10 years	
	Piping - Condensate Pipe- Steel	Entire Building	350	LF	6	6-10 years	
	Piping - Condensate ripe- Steel	Entire Building	350	LF	6	6-10 years	
	Steam Traps	Entire Building	35	EA	6	6-10 years	
	Cleam Traps	Littine Building	33	L/\	Ū	o ro years	
leating	Devices Characteristics Characteristics	Ond Floor				C 40	
	Radiators - Steam	2nd Floor	2	EΑ	6	6-10 years	
	Unit Heater - Gas	Boiler Room	1	EΑ	5	2-5 years	
	Wall Heater - Electric	Entire Building	6	EΑ	6	6-10 years	Oldon vmit
	Wall Heater - Electric	Entire Building	6	EA	5	2-5 years	Older unit
Tempera	ature Control						
	DDC System	Entire Building	58,108	SF	6	6-10 years	
	Electric Thermostat	Entire Building	5	EA	5	2-5 years	Indoor fan, unit heater, FCUs
	Pneumatic System	Entire Building	58,108	SF	3	0-1 year	Abandoned/not in use

Campus Name: Minoso Page: 6 of 25 Assessment Date: 11/14/2023





Category : Mechanical **Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Thermostats - DDC **Entire Building** 32 EΑ 6 6-10 years Thermostats - Pneumatic 3 EΑ 0-1 vear **Entire Building** 4 Not in use Ventilation Exhaust Fans- Indoor - 500 - 1500 CFM 2 EΑ 6 **Entire Building** 6-10 years Exhaust Fans- Roof Mounted - 1501 - 8000 2 FΑ **Entire Building** 6 10+ years CFM Exhaust Fans- Roof Mounted - 1501 - 8000 **Entire Building** 1 FΑ 5 6-10 years Wall mounted CFM Exhaust Fans- Roof Mounted - 1501 - 8000 **Entire Building** 2 EΑ 3 0-1 year Abandoned CFM Exhaust Fans- Roof Mounted - 500 - 1500 **Entire Building** 1 EΑ 6 10+ years CFM Exhaust Fans- Roof Mounted - 500 - 1500 **Entire Building** FΑ 5 6-10 years 1 CFM Exhaust Fans- Roof Mounted - Less than FΑ 6 Wall mounted **Entire Building** 1 6-10 years 500 CFM Roof Mounted Duct Work **Entire Building** 25 LF 6 6-10 years Wall mounted EΑ Type II Exhaust Hood- Warming Kitchen **Entire Building** 1 5 6-10 years **Category: Plumbing Building: Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Hot Water Gas Heater - 150000 - 300000 BTU/HR **Boiler Room** 1 EΑ 6 6-10 years Gas Heater - 150000 - 300000 BTU/HR Boiler Room EΑ 6 10+ years 1 Piping SF 6 Domestic Piping-Hot Water Return Lines **Entire Building** 58.108 6-10 years Domestic Piping-Hot Water Return Risers 58,108 SF 6 6-10 years **Entire Building** Domestic Piping-Hot Water from Risers to 58.108 SF 6 **Entire Building** 6-10 years **Fixtures** Domestic Piping-Hot/Cold Water Supply SF **Entire Building** 58,108 6 6-10 years Recent renovation, some copper (Horizontal Lines) piping and new insulation installed Domestic Piping-Hot/Cold Water Supply **Entire Building** 58,108 SF 6 6-10 years (Risers) Domestic Piping-Hot/Cold Water Supply **Entire Building** 58,108 SF 6 6-10 years (from Risers to Fixtures) SF Sanitary Piping **Entire Building** 58.108 6 6-10 years Storm Piping Entire Building 58.108 SF 6 6-10 years SF Vent Piping **Entire Building** 58.108 6-10 years Pumps





Category: Plumbing **Building: Main** Recommend Quantity UOM Location Group Item - Type Rank Replacement Comments Pumps - Domestic Booster Pump-Duplex 10+ years **Basement** EΑ 6 Pumps - Domestic Booster Pump-Simplex Basement 1 EΑ 6 6-10 years Irrigation System Pumps - Sump-Duplex 6-10 years Basement 1 EΑ 6 Pumps - Sump-Simplex 10+ years **Basement** EΑ 6 1 Pumps - Sump-Simplex Basement 6 EΑ 6-10 years Pumps - Sump-Simplex 0-1 year Disconnected and piping cut off from **Basement** EΑ sanitary line, abandoned

Category : Room Building : Main

Jaiogo	iy . Room		_	unung		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
minis	trative Suites/Offices						
	AC Unit	107 Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	107 Main Office	525	SF	7	10+ years	
	Doors - Transom Window	107 Main Office	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	107 Main Office	1	EA	6	10+ years	
	Floor - Tile	107 Main Office	525	SF	6	6-10 years	
	Lighting - Pendent/Surface	107 Main Office	10	EA	7	10+ years	
	Power Distribution	107 Main Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	107 Main Office	324	SF	7	10+ years	
	Walls - Plaster/Drywall	107 Main Office	760	SF	7	10+ years	
	AC Unit	107A Principal Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	107A Principal Office	160	SF	7	10+ years	
	Doors - Side-lite	107A Principal Office	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	107A Principal Office	1	EA	7	10+ years	
	Floor - Wood	107A Principal Office	160	SF	6	10+ years	
	Lighting - Pendent/Surface	107A Principal Office	3	EA	7	10+ years	
	Power Distribution	107A Principal Office	4	EA	7	10+ years	
	Storage/ Closet	107A Principal Office	5	SF	7	10+ years	
	Walls - Plaster/Drywall	107A Principal Office	312	SF	7	10+ years	
	Walls - Plaster/Drywall	107A Principal Office	312	SF	6	10+ years	
	Ceiling - Plaster/Drywall	107B Conference Room	195	SF	6	10+ years	
	Doors - Transom Window	107B Conference Room	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw	107B Conference Room	2	EA	7	10+ years	
	Floor - Carpet	107B Conference Room	195	SF	6	6-10 years	
	Lighting - Pendent/Surface	107B Conference Room	7	EA	7	10+ years	
	Power Distribution	107B Conference Room	2	EA	7	10+ years	
	Walls - Plaster/Drywall	107B Conference Room	300	SF	7	10+ years	
	Walls - Plaster/Drywall	107B Conference Room	300	SF	6	10+ years	
	Ceiling - Plaster/Drywall	109 Teachers Lounge	260	SF	7	10+ years	
	Doors - Side-lite	109 Teachers Lounge	44	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109 Teachers Lounge	1	EA	7	10+ years	
	Floor - Tile	109 Teachers Lounge	260	SF	6	6-10 years	
	Lighting - Pendent/Surface	109 Teachers Lounge	4	EA	7	10+ years	

Campus Name: Minoso Page: 8 of 25 Assessment Date: 11/14/2023



Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	109 Teachers Lounge	4	EA	7	10+ years	
	Storage/ Closet	109 Teachers Lounge	120	SF	5	2-5 years	
	Walls - Plaster/Drywall	109 Teachers Lounge	700	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor Nurse's Office	139	SF	7	10+ years	
	Doors - Side-lite	2nd Floor Nurse's Office	70	SF	7	10+ years	
	Doors - Transom Window	2nd Floor Nurse's Office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Nurse's Office	1	EA	7	10+ years	
	Floor - Tile	2nd Floor Nurse's Office	139	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor Nurse's Office	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor Nurse's Office	670	SF	6	10+ years	
	Ceiling - Exposed	Counselors Room A Basement	506	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Counselors Room A Basement	1	EA	7	10+ years	
	Floor - Tile	Counselors Room A Basement	506	SF	6	6-10 years	
	Lighting - Pendent/Surface	Counselors Room A Basement	6	EA	7	10+ years	
	Power Distribution	Counselors Room A Basement	12	EA	7	10+ years	
	Storage/ Closet	Counselors Room A Basement	30	SF	7	10+ years	
	Walls - Masonry	Counselors Room A Basement	800	SF	6	10+ years	
	Ceiling - Exposed	Counselors Room B Basement	170	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Counselors Room B Basement	1	EA	7	10+ years	
	Floor - Tile	Counselors Room B Basement	170	SF	7	10+ years	
	Lighting - Pendent/Surface	Counselors Room B Basement	4	EA	7	10+ years	
	Power Distribution	Counselors Room B Basement	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Counselors Room B Basement	630	SF	7	10+ years	
	Ceiling - Exposed	Engineer's Office	150	SF	4	0-1 year	Cracking
	Doors - Wood Doors inclu hw	Engineer's Office	1	EA	6	6-10 years	ŭ
	Floor - Tile	Engineer's Office	150	SF	7	10+ years	
	Lighting - Pendent/Surface	Engineer's Office	2	EA	7	10+ years	
	Power Distribution	Engineer's Office	10	EA	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office	484	SF	6	10+ years	
	Ceiling - Lay-in	Kitchen Manager	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Manager	1	EA	7	10+ years	
	Floor - Tile Quarry	Kitchen Manager	35	SF	7	10+ years	
	Lighting - Lay-in	Kitchen Manager	1	EA	7	10+ years	
	Power Distribution	Kitchen Manager	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Manager	243	SF	7	10+ years	
Gvmnasi	ia						
	Ceiling - Plaster/Drywall	3rd Floor	3,565	SF	6	10+ years	Updated to match current observations, no max occupancy sign
	Doors - Side-lite	3rd Floor	10	SF	7	10+ years	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,
	Doors - Steel Doors incl hw	3rd Floor	4	EA	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Floor - Wood	3rd Floor	3,565	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure	3rd Floor	15	EA	7	10+ years	
		2.4	.0	_, .	•	. o . youro	



Building: Main Category: Room Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Sodium EΑ 7 Lighting - Pendent/Surface 3rd Floor 10 6-10 years Sound System 3rd Floor 1 FΑ 7 6-10 years 365 SF Stage 3rd Floor 6 10+ years 7 Stage Curtain 3rd Floor 2 EΑ 6-10 years LF 7 Stage-Stairs - Wood 3rd Floor 12 10+ years Storage/ Closet 3rd Floor 7 SF 7 10+ years Walls - Plaster/Drywall SF 3rd Floor 3.360 7 10+ years Walls - Plaster/Drywall 3rd Floor 960 SF 6 10+ years Kitchen Ceiling - Lay-in Basement 500 SF 7 10+ years Doors - Wood Doors inclu hw Basement 3 EΑ 7 10+ years SF Floor - Tile Quarry Basement 500 7 10+ years EΑ 7 Lighting - Lay-in Basement 7 10+ years Storage/ Closet Basement 100 SF 7 10+ years Walls - Vinyl Coated Gypsum Panel SF Basement 900 7 10+ years Lunch & Multipurpose Room Ceiling - Exposed Lunchroom A 1.435 SF 7 10+ years Doors - Wood Doors inclu hw Lunchroom A 3 EΑ 7 10+ years SF Floor - Tile Lunchroom A 1.185 7 10+ years SF Floor - Tile Quarry Lunchroom A 250 7 10+ years Lighting - Pendent/Surface 7 Lunchroom A 15 EΑ 10+ years Serving Line Lunchroom A 20 LF 7 10+ years Walls - Plaster/Drywall SF 7 Lunchroom A 850 10+ years SF Walls - Plaster/Drywall Lunchroom A 500 7 10+ years 750 SF 7 Ceiling - Exposed 10+ years Lunchroom B Doors - Steel Doors incl hw Lunchroom B 2 FΑ 7 10+ years SF Floor - Tile Lunchroom B 750 7 10+ years Lighting - Pendent/Surface 7 Lunchroom B 8 EΑ 10+ years Storage/ Closet 75 SF Lunchroom B 7 10+ years Walls - Plaster/Drywall 500 SF 7 Lunchroom B 10+ years Walls - Plaster/Drywall Lunchroom B 500 SF 7 10+ years MDF IDF Doors - Steel Doors incl hw Basement - Inside Counselor B EΑ 1 6 10+ years **Finishes** Basement - Inside Counselor B 117 SF 7 10+ years EΑ 7 Other Cooling Unit Basement - Inside Counselor B 1 6-10 years Ductless split Mechanical/ Service Rooms Janitor's Closet 1st Floor 6 SF 5 10+ years Water damage 2nd Floor SF 5 Janitor's Closet 60 10+ years Water damage to ceiling





Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Janitor's Closet	3rd Floor	191	SF	7	10+ years	Updated mechanical room to reflect usage as janitors closet
	Air Intake Plenums	Basement	250	SF	7	10+ years	
	Boiler Room	Basement	900	SF	5	10+ years	
	Coal Room	Basement	400	SF	5	10+ years	
	Janitor's Closet	Basement	50	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	72	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	330	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	300	SF	5	10+ years	
	Storage Room	Basement	500	SF	7	10+ years	
	Storage Room	Basement	150	SF	7	10+ years	
	Storage Room	Basement	100	SF	7	10+ years	
	Storage Room	Basement	125	SF	7	10+ years	
	Storage Room	Basement	25	SF	7	10+ years	
	Storage Room	Basement	125	SF	7	10+ years	
	Storage Room	Basement	100	SF	7	10+ years	
	Storage Room	Basement	125	SF	5	10+ years	Seepage, peeling paint
	· ·					•	
_Restroor	n						
	Accessories	1.5 floor inside teachers lounge	30	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1.5 floor inside teachers lounge	30	SF	5	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1.5 floor inside teachers lounge	1	EA	6	10+ years	
	Floor - Tile	1.5 floor inside teachers lounge	30	SF	4	0-1 year	Cracking, chipping, and separating tiles. Quantity updated to match current observations
	Lavatory	1.5 floor inside teachers lounge	1	EA	6	10+ years	odironi obcorvationo
	Lighting - Pendent/Surface	1.5 floor inside teachers lounge	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1.5 floor inside teachers lounge	150	SF	7	10+ years	
	Water Closet	1.5 floor inside teachers lounge	1	EA	7	10+ years	
	Accessories	1st Floor inside Classroom #104	46	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor inside Classroom #104	46	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor inside Classroom #104	1	EA	6	10+ years	
	Floor - Tile	1st Floor inside Classroom #104	26	SF	6	6-10 years	
	Floor - Tile	1st Floor inside Classroom #104	20	SF	5	1-2 years	Chipped and cracking tiles
	Lavatory	1st Floor inside Classroom #104	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor inside Classroom #104	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor inside Classroom #104	260	SF	6	10+ years	
	Water Closet	1st Floor inside Classroom #104	1	ĒΑ	6	10+ years	
	Accessories	1st Floor inside Classroom #108	30	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor inside Classroom #108	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor inside Classroom #108	1	EA	7	10+ years	
	Floor - Tile	1st Floor inside Classroom #108	30	SF	6	6-10 years	
	Lavatory	1st Floor inside Classroom #108	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor inside Classroom #108	1	EA	7	10+ years	
	<u> </u>		•		-	- ,	

Campus Name: Minoso Page : 11 of 25 Assessment Date: 11/14/2023



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor inside Classroom #108	80	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor inside Classroom #108	80	SF	6	10+ years	
	Water Closet	1st Floor inside Classroom #108	1	EA	6	10+ years	
	Accessories	2nd Floor - Boys Toilet	460	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Boys Toilet	460	SF	6	10+ years	
	Doors - Transom Window	2nd Floor - Boys Toilet	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor - Boys Toilet	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Boys Toilet	460	SF	6	10+ years	
	Floor Drain	2nd Floor - Boys Toilet	1	EA	7	10+ years	
	Lavatory	2nd Floor - Boys Toilet	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor - Boys Toilet	12	EA	7	6-10 years	
	Partitions	2nd Floor - Boys Toilet	3	EA	7	6-10 years	
	Urinals	2nd Floor - Boys Toilet	5	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor - Boys Toilet	1,020	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor - Boys Toilet	185	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor - Boys Toilet	500	SF	7	10+ years	
	Water Closet	2nd Floor - Boys Toilet	3	EA	6	10+ years	
	Accessories	2nd Floor Girls Toilet across from Library 205	317	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Girls Toilet across from	317	SF	6	10+ years	
		Library 205					
	Doors - Wood Doors inclu hw	2nd Floor Girls Toilet across from Library 205	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Girls Toilet across from Library 205	317	SF	6	10+ years	
	Floor Drain	2nd Floor Girls Toilet across from Library 205	1	EA	7	10+ years	
	Lavatory	2nd Floor Girls Toilet across from Library 205	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girls Toilet across from Library 205	3	EA	7	6-10 years	Updated quantity in condition, previous pendant, lights, replaced with can lighting
	Partitions	2nd Floor Girls Toilet across from Library 205	8	EA	7	6-10 years	3 3
	Walls - Plaster/Drywall	2nd Floor Girls Toilet across from Library 205	515	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Girls Toilet across from Library 205	505	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Girls Toilet across from Library 205	10	SF	6	1-2 years	Cracking tile
	Water Closet	2nd Floor Girls Toilet across from Library 205	8	EA	7	6-10 years	
	Accessories	2nd Floor Unisex at SE corner	66	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor Unisex at SE corner	66	SF	6	10+ years	Unpainted patches
	,					,	

Campus Name: Minoso Page : 12 of 25 Assessment Date: 11/14/2023



Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor Unisex at SE corner	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Unisex at SE corner	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor Unisex at SE corner	66	SF	7	10+ years	
	Hand Dryer	2nd Floor Unisex at SE corner	1	EA	7	10+ years	
	Lavatory	2nd Floor Unisex at SE corner	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Unisex at SE corner	2	EA	7	6-10 years	
	Partitions	2nd Floor Unisex at SE corner	1	EA	7	6-10 years	
	Urinals	2nd Floor Unisex at SE corner	1	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Unisex at SE corner	240	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor Unisex at SE corner	240	SF	7	10+ years	
	Water Closet	2nd Floor Unisex at SE corner	1	EA	7	6-10 years	
	Accessories	2nd Floor inside Nurse's Office	86	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor inside Nurse's Office	86	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor inside Nurse's Office	1	EA	7	10+ years	
	Floor - Tile	2nd Floor inside Nurse's Office	80	SF	6	6-10 years	
	Floor - Tile	2nd Floor inside Nurse's Office	6	SF	5	1-2 years	Damaged and missing tile
	Lavatory	2nd Floor inside Nurse's Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor inside Nurse's Office	1	EA	7	6-10 years	
	Partitions	2nd Floor inside Nurse's Office	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor inside Nurse's Office	514	SF	7	10+ years	
	Water Closet	2nd Floor inside Nurse's Office	2	EA	7	6-10 years	
	Accessories	Basement - Unisex	135	SF	7	10+ years	
	Ceiling - Exposed	Basement - Unisex	65	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Basement - Unisex	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement - Unisex	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement - Unisex	135	SF	7	10+ years	
	Floor Drain	Basement - Unisex	1	EA	7	10+ years	
	Hand Dryer	Basement - Unisex	1	EA	7	6-10 years	
	Lavatory	Basement - Unisex	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement - Unisex	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement - Unisex	50	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement - Unisex	144	SF	7	10+ years	
	Water Closet	Basement - Unisex	1	EA	7	10+ years	
	Accessories	Basement Boys Toilet	200	SF	7	10+ years	
	Ceiling - Exposed	Basement Boys Toilet	200	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Basement Boys Toilet	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Basement Boys Toilet	200	SF	7	10+ years	
	Floor Drain	Basement Boys Toilet	1	EA	7	10+ years	
	Hand Dryer	Basement Boys Toilet	1	EA	7	6-10 years	
	Lavatory	Basement Boys Toilet	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Basement Boys Toilet	5	EA	7	10+ years	
	Partitions	Basement Boys Toilet	2	EA	7	10+ years	
	Urinals	Basement Boys Toilet	3	EA	7	10+ years	
	Walls - Plaster/Drywall	Basement Boys Toilet	120	SF	7	10+ years	
			0	٠.	•	,	

Campus Name: Minoso Page: 13 of 25 Assessment Date: 11/14/2023





ry : Room		В	uilding	: Main		<u> </u>
					Recommend	
						Comments
					•	
Water Closet						
Accessories						
	Basement Girls Toilet	200				
Doors - Wood Doors inclu hw	Basement Girls Toilet	1			10+ years	
Floor - Tile Ceramic/ Porcelain	Basement Girls Toilet	200	SF	7	10+ years	
Floor Drain	Basement Girls Toilet	1	EA	7	10+ years	
Hand Dryer	Basement Girls Toilet	1	EA	7	6-10 years	
Lavatory	Basement Girls Toilet	3	EA	7	10+ years	
Lighting - Pendent/Surface	Basement Girls Toilet	5	EA	7	10+ years	
Partitions	Basement Girls Toilet	5	EA	7	10+ years	
Walls - Plaster/Drywall	Basement Girls Toilet	120	SF	7	10+ years	
Walls - Tile Ceramic/ Porcelain	Basement Girls Toilet	600	SF	7		
Water Closet	Basement Girls Toilet	5	EA	7	10+ years	
rv : Classroom		В	uildina	: Main		
					Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
					•	Paint chipping
					10+ years	
Walls - Masonry	Basement	1,220			10+ years	
Work Sink	Basement	3	EA	7	10+ years	
m #101 (Regular Classroom)						
,	1st Floor	2	EA	7	6-10 years	
		1			•	
		820 820				
			_	-		
Storage/ Closet				-		Corrected quantity
Walls - Plaster/Drywall	1st Floor	1,493	SF	6	10+ years	Corrected quartity
m #102 (Regular Classroom)						
	1et Floor	1	ΕΛ	7	6-10 years	
		· · · · · · · · · · · · · · · · · · ·				
	1st Floor	950	SF	6	10+ years	
	191 11001	930			•	0 10 11
Ceiling - Plaster/Drywall		^	C.L			(orrooted () lightity
Doors - Transom Window	1st Floor	9	SF	7	10+ years	Corrected Quantity
Doors - Transom Window Doors - Wood Doors inclu hw Floor - Wood		9 1 950	SF EA SF	7 7 6	10+ years 10+ years 10+ years	Corrected Quantity Corrected Quantity
	Ceiling - Exposed Doors - Wood Doors inclu hw Floor - Tile Ceramic/ Porcelain Floor Drain Hand Dryer Lavatory Lighting - Pendent/Surface Partitions Walls - Plaster/Drywall Walls - Tile Ceramic/ Porcelain Water Closet ry : Classroom Item - Type Im #008 (Art Room) Ceiling - Exposed Floor - Epoxy/ Painted Lighting - Pendent/Surface Walls - Masonry Work Sink Im #101 (Regular Classroom) AC Units Ceiling - Lay-in Chalk Board Doors - Transom Window Doors - Wood Lighting - Pendent/Surface Storage/ Closet	Item - Type	Name	Name	Name	

Campus Name: Minoso Page : 14 of 25 Assessment Date: 11/14/2023



Catego	ry : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years			
	Marker Board	1st Floor	24	LF	7	6-10 years			
	Storage/ Closet	1st Floor	125	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,512	SF	7	10+ years			
Classroc	om #103 (Regular Classroom)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	4	LF	6	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	942	SF	6	10+ years			
	Chalk Board	1st Floor	5	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	Corrected Quantity		
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	Corrected Quantity		
	Floor - Tile	1st Floor	936	SF	6	10+ years			
	Floor - Tile	1st Floor	6	SF	4	1-2 years	Chipped tiles		
	Lighting - Pendent/Surface	1st Floor	18	EA	7	10+ years	omprod mod		
	Marker Board	1st Floor	40	LF	7	6-10 years			
	Storage/ Closet	1st Floor	90	SF	7	10+ years	Corrected Quantity		
	Walls - Plaster/Drywall	1st Floor	1,544	SF	6	10+ years	Corrected Quartity		
			.,	•	· ·	.o. yea.e			
Classroc	om #104 (Kindergarten)	4 . =							
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	25	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	870	SF	6	10+ years			
	Doors - Transom Window	1st Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	870	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years			
	Marker Board	1st Floor	12	LF	7	6-10 years			
	Storage/ Closet	1st Floor	90	SF	7	10+ years	Corrected Quantity		
	Walls - Plaster/Drywall	1st Floor	1,512	SF	6	10+ years			
Classroc	om #105 (Regular Classroom)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	6	LF	7	10+ years	Corrected classification		
	Ceiling - Plaster/Drywall	1st Floor	790	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	10	SF	6	10+ years	Cracking		
	Chalk Board	1st Floor	40	LF	4	2-5 years	2.23/9		
	Doors - Transom Window	1st Floor	6	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood Books including	1st Floor	800	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	12	EA	6	10+ years 10+ years			
	Marker Board	1st Floor	26	LF	6	6-10 years			
		1st Floor		SF	7		Corrected Quantity		
	Storage/ Closet	IST LIOOL	120	SF.	1	10+ years	Corrected Quantity		



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,377	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	15	SF	6	10+ years	Crack above closet
Classroc	om #106 (Science Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	830	SF	6	10+ years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Wood	1st Floor	830	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	8	LF	6	6-10 years	
	Marker Board	1st Floor	6	LF	4	0-1 year	Cracking whiteboard
	Storage/ Closet	1st Floor	125	SF	7	10+ years	ŭ
	Walls - Plaster/Drywall	1st Floor	1,413	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	6	10+ years	Minor cracks in plaster
Classroo	om #108 (Kindergarten)						
Oldoorot	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	8	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	946	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	Corrected Quantity
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	Corrected Quartity
	Floor - Tile	1st Floor	946	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	6	10+ years	
	Storage/ Closet	1st Floor	27	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,479	SF	6	10+ years	
	Work Sink	1st Floor	1,479	EA	7	10+ years	
	WOIR SIIIR	151 11001	1	EA	1	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	950	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	Corrected Quantity
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	950	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	133	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,512	SF	6	10+ years	
Classroc	om #203 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	3	LF	7	10+ years	



Category : Classroom			В	uilding	: Main		-
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	942	SF	7	10+ years	
	Chalk Board	2nd Floor	15	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	Corrected Quantity
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	,
	Floor - Wood	2nd Floor	942	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	100	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,544	SF	7	10+ years	
lassroc	m #204 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	950	SF	7	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	Corrected Quantity
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	Corrected Quartity
	Floor - Wood	2nd Floor	950	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	21	EA	7	6-10 years	
	Marker Board	2nd Floor 2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor 2nd Floor		SF			
			150	SF SF	7 7	6-10 years	Updated to match observations
	Walls - Plaster/Drywall	2nd Floor	1,312	SF	/	10+ years	
lassroc	nm #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	3	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	809	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	Corrected Quantity
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	•
	Floor - Tile	2nd Floor	809	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	180	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,405	SF	7	10+ years	
lassroc	om #206 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	851	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	Corrected Quantity
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	cocolou duaminy
	Floor - Wood	2nd Floor	851	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	175	SF	, 5	10+ years	Lights nonfunctional
			_	SF SF	_		Ligitis Horituricuoriai
	Walls - Plaster/Drywall	2nd Floor	1,436	25	6	10+ years	



Category : Classroom			В	uilding	: Main				
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
lassroo	m #207 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	926	SF	6	10+ years			
	Chalk Board	2nd Floor	8	ĹF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	Corrected Quantity		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years			
	Floor - Wood	2nd Floor	926	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	21	ĒΑ	7	6-10 years			
	Marker Board	2nd Floor	14	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	150	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,589	SF	6	10+ years			
lassroo	m #208 (Faculty Lounge)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	10	LF	7	10+ years	Not previously assessed		
	Ceiling - Plaster/Drywall	2nd Floor	785	SF	6	10+ years	140t providuoly addocada		
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	Corrected Quantity		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	Corrocted Quartity		
	Floor - Tile	2nd Floor	785	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years			
	Marker Board	2nd Floor	10	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	159	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,145	SF	7	10+ years			
	Work Sink	2nd Floor	1	EA	7	10+ years			
lassroo	om #301 (Computer Lab)								
	AC Units	3rd Floor	2	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	854	SF	6	10+ years			
	Chalk Board	3rd Floor	40	LF	4	2-5 years			
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	Corrected Quantity		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	Controlled Quantity		
	Floor - Wood	3rd Floor	854	SF	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	18	EA	7	6-10 years			
	Marker Board	3rd Floor	2	LF	6	6-10 years			
	Storage/ Closet	3rd Floor	120	SF	7	10+ years	Corrected Quantity		
	Walls - Plaster/Drywall	3rd Floor	1,425	SF	6	10+ years	Concolor Quantity		
lassroo	om #302 (Regular Classroom)								
	AC Units	3rd Floor	2	EA	7	6-10 years			
	Casework	3rd Floor	6	LF	7	10+ years	Not previously assessed		
	Ceiling - Plaster/Drywall	3rd Floor	950	SF	6	10+ years			
	Chalk Board	3rd Floor	28	LF	4	2-5 years			
	CHAIK DOALO								

Campus Name: Minoso Page: 18 of 25 Assessment Date: 11/14/2023



Catego	ry : Classroom		В	uilding	: Main					
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years				
	Floor - Wood	3rd Floor	950	SF	6	10+ years				
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	6-10 years				
	Marker Board	3rd Floor	12	LF	7	6-10 years				
	Storage/ Closet	3rd Floor	120	SF	7	10+ years	Corrected Quantity			
	Walls - Plaster/Drywall	3rd Floor	1,512	SF	6	10+ years				
Classroo	om #303 (Regular Classroom)									
	AC Units	3rd Floor	2	EA	7	6-10 years				
	Casework	3rd Floor	6	LF	7	10+ years	Not previously assessed			
	Ceiling - Plaster/Drywall	3rd Floor	942	SF	6	10+ years	Updated to match current			
	,					-	observations			
	Chalk Board	3rd Floor	44	LF	4	2-5 years				
	Doors - Transom Window	3rd Floor	6	SF	7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years				
	Floor - Wood	3rd Floor	942	SF	6	10+ years				
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	6-10 years				
	Marker Board	3rd Floor	8	LF	7	6-10 years				
	Storage/ Closet	3rd Floor	120	SF	7	10+ years	Corrected Quantity			
	Walls - Plaster/Drywall	3rd Floor	1,544	SF	6	10+ years				
Classroo	om #304 (Regular Classroom)									
	AC Units	3rd Floor	2	EA	7	6-10 years				
	Casework	3rd Floor	6	LF	7	10+ years				
	Ceiling - Plaster/Drywall	3rd Floor	1,181	SF	6	10+ years				
	Chalk Board	3rd Floor	44	LF	4	2-5 years				
	Doors - Transom Window	3rd Floor	8	SF	7					
			0		7	10+ years				
	Doors - Wood Doors inclu hw	3rd Floor	•	EA		10+ years				
	Floor - Wood	3rd Floor	1,181	SF	6	10+ years				
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	6-10 years				
	Marker Board	3rd Floor	12	LF	7	6-10 years				
	Storage/ Closet	3rd Floor	120	SF	7	10+ years	Corrected Quantity			
	Walls - Plaster/Drywall	3rd Floor	1,512	SF	6	10+ years				
Classroo	om #306 (Office)									
	AC Units	3rd Floor	1	EA	7	6-10 years				
	Casework	3rd Floor	4	LF	7	10+ years				
	Ceiling - Plaster/Drywall	3rd Floor	416	SF	7	10+ years				
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	Corrected Quantity			
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	221122100 20011111			
	Floor - Wood	3rd Floor	416	SF	6	10+ years				
	Lighting - Pendent/Surface	3rd Floor	3	EA	7	6-10 years				
			6	LF						
	Marker Board	3rd Floor	E	1 -	7	6-10 years				



Cotomo				يم مدالمال	. Main		527 S Wallace STREET, Chicago, IL 6060
Catego	ry : Classroom		В	uilding	: wain	D	
O	Hom. Time	Laastian	Overetite.	ПОМ	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	3rd Floor	2	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,236	SF	6	10+ years	
Classroc	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	925	SF	6	10+ years	
	Chalk Board	3rd Floor	25	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	69	SF	7	10+ years	Corrected Quantity
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	7	10+ years	,
	Floor - Wood	3rd Floor	925	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	21	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	120	SF	7	10+ years	Corrected Quantity
	Walls - Plaster/Drywall	3rd Floor	1,572	SF	6	10+ years	Corrodica Quartity
	Walls - Flaster/Drywall	314 1 1001	1,072	OI.	O	10+ years	
lassroc	om #308 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	895	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	7	10+ years	Corrected Quantity
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	21	EA	7	6-10 years	
	Marker Board	3rd Floor	4	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	87	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,458	SF	6	10+ years	
Catego	ry : Interior		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor		4 of Floor	0.5	C.E.		10	
	Ceiling - Exposed	1st Floor	85	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	2,998	SF	6	10+ years	One obine a majest
	Ceiling - Plaster/Drywall	1st Floor	95	SF	5	0-1 year	Cracking paint
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	213	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,850	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	30	SF	4	1-2 years	Chipped tiles throughout
		4 a 4 🗀 a a a	20	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor					
	Stairs - Concrete Stairs	1st Floor	20	LF	7	10+ years	
	Stairs - Concrete Stairs Walls - Plaster/Drywall			LF SF	7 7		
	Stairs - Concrete Stairs	1st Floor	20	LF	7	10+ years	Cracking paint



Catego	Category : Interior			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	2,665	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	150	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	8	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	Corrected Quantity
	Drinking Fountains - Single Fountain	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	213	SF	7	10+ years	
	Floor - Wood	2nd Floor	2,432	SF	7	10+ years	
	Floor - Wood	2nd Floor	20	SF	6	6-10 years	Seal needs refinishing
	Lighting - Pendent/Surface	2nd Floor	19	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	4,963	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,382	SF	6	10+ years	Corrected Quantity
	Doors - Transom Window	3rd Floor	75	SF	7	10+ years	
	Doors - Wood Doors include hw	3rd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	3rd Floor	1	EA	5	1-2 years	Out of order, corrected type
	Floor - Asphalt Floor	3rd Floor	429	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	230	SF	7	10+ years	Not previously assessed
	Floor - Wood	3rd Floor	723	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	10	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	3,261	SF	7	10+ years	
	Ceiling - Exposed	Basement Corridor North	1,500	SF	6	10+ years	
	Doors - Steel Doors incl hw	Basement Corridor North	1	EA	7	10+ years	
	Floor - Concrete	Basement Corridor North	1,050	SF	7	10+ years	
	Floor - Tile/Sheet	Basement Corridor North	450	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement Corridor North	21	EA	7	10+ years	
	Stairs - Concrete Stairs	Basement Corridor North	25	LF	7	10+ years	
	Student Lockers - One Tier	Basement Corridor North	6	EA	7	10+ years	
	Walls - Masonry	Basement Corridor North	2,170	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement Corridor North	500	SF	7	10+ years	
	Ceiling - Exposed	Basement South	340	SF	7	10+ years	
	Doors - Wood Doors include hw	Basement South	2	ĒΑ	7	10+ years	
	Drinking Fountains - Single Fountain	Basement South	3	EA	7	10+ years	
	Floor - Tile/Sheet	Basement South	340	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement South	4	ĒΑ	7	10+ years	
	Walls - Plaster/Drywall	Basement South	750	SF	7	10+ years	
	Ceiling - Lay-in	Elevator Lobby South Ground Floor Entrance	120	SF	7	10+ years	
	Doors - Store Front	Elevator Lobby South Ground Floor	8	EA	7	10+ years	
	Floor - Concrete	Entrance Elevator Lobby South Ground Floor Entrance	120	SF	7	10+ years	
	Lighting - Pendent/Surface	Elevator Lobby South Ground Floor Entrance	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Elevator Lobby South Ground Floor Entrance	416	SF	7	10+ years	

Campus Name: Minoso Page : 21 of 25 Assessment Date: 11/14/2023





Catego	ry : Interior		В	uilding	: Main		-
<u> </u>				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	South Elevator Lobby 1st Floor	320	SF	7	10+ years	
	Floor - Tile/Sheet	South Elevator Lobby 1st Floor	320	SF	7	10+ years	
	Lighting - Lay-in	South Elevator Lobby 1st Floor	4	EA	7	10+ years	
	Walls - Plaster/Drywall	South Elevator Lobby 1st Floor	410	SF	7	10+ years	
Safety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	1	EΑ	7	6-10 years	
	Security Cameras	Entire Building	8	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North (Stair B)	420	SF	6	10+ years	
	Floor - Asphalt	North (Stair B)	225	SF	6	10+ years	
	Handrails	North (Stair B)	156	LF	7	10+ years	
	Lighting - Lay-in	North (Stair B)	2	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	North (Stair B)	1	EA	6	6-10 years	
	Stairs - Asphalt	North (Stair B)	75	LF	6	10+ years	
	Walls - Plaster/Drywall	North (Stair B)	2,033	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South (Stair A)	350	SF	7	10+ years	
	Floor - Asphalt	South (Stair A)	350	SF	7	10+ years	
	Handrails	South (Stair A)	158	LF	7	10+ years	
	Lighting - Lay-in	South (Stair A)	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	South (Stair A)	1	EA	7	6-10 years	
	Stairs - Asphalt	South (Stair A)	75	LF	7	10+ years	
	Walls - Plaster/Drywall	South (Stair A)	1,880	SF	7	10+ years	
_Vertical (Conveyance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	



Category : Site Building : Site

atogoi	y . Site			unung	. Oile	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	item - Type	Location	Qualitity	UOIVI	Kalik	Replacement	Comments
thletic	Overforce Overthootic	O Al-	5.000			0.40	
	Surface - Synthetic	South	5,980	SF	7	6-10 years	
	Lighting	South	4 705	EA SF	7	10+ years	
	Surface - Synthetic	South	1,795	5F	7	10+ years	
ivil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	7	10+ years	Recombined quantities
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	4	EA	7	10+ years	
encina							
пспд	Fencing - Chain Link	Entire Site	482	LF	7	10+ years	
	Fencing - Chain Link	Entire Site	32	LF	4	0-1 year	Bent, damaged links
	Fencing - Guard Rail	Entire Site	30	LF	6	10+ years	Don, damagod iiino
	Fencing - Iron and Concrete Post	Entire Site	60	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	431	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	20	LF	4	0-10 years 0-1 year	Severely damaged, bent fence posts
	Tending New Standard Smallierita	Little Oile	20		-	o i yeai	near door, seven
ndscap		Entire Site	6	ΕΛ	7	10	
	Benches		6	EΑ	-	10+ years	Detted deserved weed benefice
	Benches	Entire Site	5	EA SF	4	0-1 year	Rotted, decayed, wood benches
	Landscape - Grass	Entire Site	1,054		6	10+ years	Dana asil
	Landscape - Grass	Entire Site	500	SF	4	1-2 years	Bare soil
	Landscape - Hardscape- Asphalt	Entire Site	581	SF	7	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	743	SF	7	10+ years	New
	Parkway trees	Entire Site	15	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	108	SF	7	10+ years	
	Trash Receptacles	Entire Site	2	EA	7	6-10 years	
rking L	ot						
-	Concrete Curbs	NE Parking Lot	163	LF	6	10+ years	
	Concrete Curbs	NE Parking Lot	15	LF	4	0-1 year	Broken, missing concrete
	Interior Plantings	NE Parking Lot	50	LF	5	2-5 years	-
	Surface - Asphalt	NE Parking Lot	8,128	SF	6	6-10 years	
	Surface - Asphalt	NE Parking Lot	3,000	SF	5	0-1 year	Confirmed area of damage. Potholes alligatoring, large cracks
	Trash Enclosure - Chain Links	NE Parking Lot	400	SF	6	10+ years	Verified dimension
	Vehicular Screening	NE Parking Lot	60	LF	6	10+ years	t standa dimensioni
	G	Ŭ				,	
aygrou	nd						

Campus Name: Minoso Page : 23 of 25 Assessment Date: 11/14/2023

Minnie Miñoso Academy

3527 S Wallace STREET, Chicago, IL 60609

Catego	Category : Site			uilding	: Site		
_				_	Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Equipment - Pre K 3-5	Entire Site	1	EA	6	6-10 years	
	Equipment - School Age 5-12	Entire Site	1	EA	7	10+ years	
	Surface - Poured Surface	Entire Site	1,400	SF	6	10+ years	
	Surface - Poured Surface	Entire Site	1,625	SF	6	10+ years	
	Surface - Poured Surface	Entire Site	100	SF	4	1-2 years	Surface drops about 9 inches when stepped upon at this location
_Sidewall	KS.						
	Sidewalks - Internal Walks	Entire Site	51	LF	7	10+ years	
	Sidewalks - Internal Walks	Entire Site	106	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	8,232	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	25	SF	4	0-1 year	Settlement of sidewalk, tripping hazard
_Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	5	1-2 years	Cracked base, leaning pole
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	5	2-5 years	Incorrect name
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	5	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	5	0-1 year	Broken stone letters

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Minoso Page : 24 of 25 Assessment Date: 11/14/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

,			Room	Floor Plan Room	۸۳۵۵	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	Area (SF)	Area	Area	Stop	Board
Building : Main	on coage	1100	1100000	1 110	(0.)	700	7		
Art Room	Play Room	Basement	008	008	828	60	30	N	N
Computer Lab	Regular Classroom	3rd Floor	301	301	854	140	80	N	N
Faculty Lounge	Regular Classroom	2nd Floor	208	208	785	75	36		
Kindergarten	Regular Classroom	1st Floor	104	104	870	175	100	N	N
Kindergarten	Regular Classroom	1st Floor	108	108	946	175	100	N	N
Office	Office	3rd Floor	306	306	416	35	20	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	820	175	100	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	950	175	100	N	Υ
Regular Classroom	Regular Classroom	1st Floor	103	103	942	100	48	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	800	140	80	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	950	175	100	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	942	100	48	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	204	204	950	175	100	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	809	75	36	N	N
Regular Classroom	Regular Classroom	2nd Floor	206	206	851	140	80	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	207	207	926	75	36	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	950	175	100	N	N
Regular Classroom	Regular Classroom	3rd Floor	303	303	942	100	48	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	1,181	175	100	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	307	925	75	36	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	895	180	96	N	N
Science Classroom	Regular Classroom	1st Floor	106	106	830	140	80	N	N