

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	2000	3	218,126
Campus Total			218,126

Category: Exterior **Building: Main** Recommend Item - Type Location Quantity **UOM** Rank Replacement Comments Group Entrance Exterior Doors - Store Front Entrance 2-SW 3 EΑ 6 10+ years Exterior Doors - Transom Lite Entrance 2-SW 3 EΑ 7 10+ years Exterior Doors - Store Front Entrance 3-NW 3 FΑ 10+ years 6 3 Exterior Doors - Transom Lite Entrance 3-NW FΑ 7 10+ years Entrance Control - Audio and Video **Entrance 4-East** 1 EΑ 7 10+ years Exterior Doors - Store Front **Entrance 4-East** 3 FΑ 6 10+ years 3 7 Exterior Doors - Transom Lite **Entrance 4-East** EΑ 10+ years 2 Exterior Doors - Exterior Steel Door Entrance 5A-SE - Outside yard EΑ 6 6-10 years storage Exterior Doors - Exterior Steel Door Entrance 6-SW - Electrical 1 FΑ 6 10+ years Exterior Doors - Exterior Steel Door 2 FΑ Entrance 7-E 6 10+ years Entrance Control - Audio Entrance 9-SW - Kitchen 1 FΑ 4 0-1 year Not working 6 Exterior Doors - Exterior Steel Door Entrance 9-SW - Kitchen FΑ 6-10 years Corrosion at bottom 1 Exterior Doors - Exterior Steel Door Exit 5-S 2 FΑ 6 10+ years Exterior Doors - Exterior Steel Door Exit 8-N - Lunchroom 2 EΑ 7 10+ years Entrance Control - Audio and Video 1 EΑ 7 10+ years Main Entrance 1 - West Exterior Doors - Side lite Main Entrance 1 - West 4 EΑ 7 10+ years Exterior Doors - Store Front Main Entrance 1 - West 4 EΑ 6 6-10 years Exterior Doors - Transom Lite Main Entrance 1 - West 2 FΑ 10+ years Foundation Foundation - Concrete LF 7 **Entire Building** 1.150 10+ years SF 7 Superstructure - Metal Deck/ Concrete **Entire Building** 218,126 10+ years Topping



Category : Exterior			В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Lighting							
<u> </u>	Exterior Lighting - Parapet or Roof Mounted	Entire Building	25	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	16	EA	7	10+ years	
Roof Sys	stem						
,	Access Ladder - Metal	Roof 1 - Main	1	EA	7	10+ years	
	Coping - Stone	Roof 1 - Main	800	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 1 - Main	900	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 1 - Main	800	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 1 - Main	25,625	SF	5	2-5 years	Roof was recoated but not replaced
	Roof Hatch - Metal	Roof 1 - Main	1	EA	5	2-5 years	•
	Roof Structure - Steel / Metal Deck/	Roof 1 - Main	25,625	SF	7	10+ years	
	Concrete Topping		•			,	
	Coping - Stone	Roof 2 - South	260	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 2 - South	25	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 2 - South	125	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 2 - South	260	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 2 - South	6,820	SF	4	0-1 year	Bubbling, cracks, water under
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 2 - South	6,820	SF	7	10+ years	membrane
	Coping - Stone	Roof 3 - West	270	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3 - West	160	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 3 - West	270	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3 - West	2,055	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	Roof 3 - West	2,055	SF	7	10+ years	
	Concrete Topping	Noor 5 - West	2,000	OI.	,	10+ years	
	Chimney - Metal Flue	Roof 4 - North	60	LF	6	10+ years	
	Coping - Stone	Roof 4 - North	260	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 4 - North	125	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 4 - North	25	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 4 - North	260	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 4 - North	6,820	SF	5	2-5 years	
	Roof Structure - Steel / Metal Deck/	Roof 4 - North	6,820	SF	7	10+ years	
	Concrete Topping		5,5_5			, , , , , , , , , , , , , , , , , , ,	
Walls							
7 TONO	Canopy - Metal	Entire Building	800	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	29,050	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	6,030	SF	7	10+ years	
Windows							



Catego	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Clerestory - Glass Double-Pane	Entire Building	720	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	2,720	SF	6	6-10 years	
	Lintels - Steel	Entire Building	1,490	LF	7	10+ years	
	Windows - Louver	Entire Building	610	SF	7	10+ years	Difficult to ones
	Windows - Sash Aluminum Double-pane	Entire Building	8,120	SF	5	2-5 years	Difficult to open
	Windows - Sash Aluminum Double-pane	Entire Building	20	SF	4	1-2 years	Cracked glass
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	cy System	Location	Quantity	00111	Italik	Replacement	Comments
_merger	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	
	Security System - CCTV	Entire Building	218,126	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	218,126	SF	6	6-10 years	
	Emergency A/C Power - Corridors and	Entire Building	22,406	SF	7	10+ years	
	Stairs	Zittiro Ballallig	22, 100	O.	•	Tot youro	
	Emergency A/C Power - Gym	Entire Building	4,153	SF	7	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	4,112	SF	7	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	18	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	4	EA	6	6-10 years	Quantity changed to match current observations.
	Emergency Battery Packs - Lunchrooms	Entire Building	6	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	28	EA	2	0-1 year	Quantity changed as total has been divided/aggregated. Signs have no backup batteries and the school has no emergency generator.
	Exit Signs - Gym	Entire Building	2	EA	2	0-1 year	Quantity changed to match current observations. Signs have no backubatteries and the school has no emergency generator.
	Exit Signs - Lunchroom	Entire Building	3	EA	2	0-1 year	Quantity changed to match current observations and as total has been divided/aggregated. Signs have no backup batteries and the school has no emergency generator.
Main Ser	vice						
	Main Electrical Service - 2000 A 277/480/3PH	Electrical Room	1	EA	7	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	218,126	SF	6	6-10 years	



Category : Electrical Building : Main							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	21	EA	7	10+ years	Location changed for clarification. Quantity changed as total has been divided/aggregated.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	Location changed for clarification.
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	Location changed for clarification.
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	Location changed for clarification.
	Transformers - 277/480 - 120/208	Entire Building	5	EA	6	10+ years	Quantity changed as total has been divided/aggregated. Location changed for clarification.

Building: Main

Category : Fire Protection

Group Fire Alar	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
FIIE AIdII	Fire ALarm Anunciator	Entire Building	1	EA	3	2-5 years	No CPS Asset Tag present. System is operational and passes inspection but is 20-plus years old and has reached the end of its anticipated service life.
	Fire Alarm Panel	Entire Building	1	EA	3	2-5 years	Rank, Reason and Priority Rep changed as the panel is operational and passes inspection but is 20-plus years old and has reached the end of its anticipated service life. Location changed for clarification.
	Fire Alarm Strobe Lights	Entire Building	218,126	SF	6	2-5 years	Rank, Reason and Priority Rep changed as the system is operational and passes inspection but is 20-plus years old and has reached the end of its anticipated service life.
	Fire Alarm_System	Entire Building	218,126	SF	4	2-5 years	Rank, Reason and Priority Rep changed as the system is operational and passes inspection but is 20-plus years old and has reached the end of its anticipated service life.
	Fire Pump Controller	Entire Building	1	EA	6	6-10 years	Priority Rep adjusted based on current observations and on the age of the equipment. Location changed for clarification.



Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Pump Ro	pom Assembly						
	Fire Pump - 25-50 hp Jockey Pump	Fire Pump Room Fire Pump Room	1 1	EA EA	6 6	10+ years 10+ years	Location changed for clarification. Location changed for clarification.
Sprinkler	System						
	Sprinkler Heads Sprinkler Piping Wet Sprinkler System	Entire Building Entire Building Entire Building	218,126 218,126 218,126	SF SF SF	7 7 6	10+ years 10+ years 10+ years	Location changed for clarification.
Catego	ry : Mechanical		В	uilding	: Main		
240110	Itam Tuna	Location	Quantity	UOM	Donk	Recommend	Comments
Group Air Cond	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
ui Cono	Chemical Pot Feeder	Entire Building	1	EA	7	6-10 years	Location changed for clarification.
	Chemical Pot Feeder	Entire Building	1	EA	7	6-10 years	200dion onangoa for olarmoation.
	Chiller-Air Cooled- Recipricating-Roof Mounted - 201 - 300 tons	Entire Building	1	EA	6	6-10 years	North chiller, serves lunchroom and kitchen spaces, 2nd Floor and 3rd Floor.
	Chiller-Air Cooled- Recipricating-Roof Mounted - 50 - 100 tons	Entire Building	1	EA	6	6-10 years	South chiller, serves gym spaces a 1st Floor.
	Pipes - Chilled Water Pipe- Steel	Entire Building	300	LF	6	10+ years	Associated with south chiller. Quantity changed to match current observations and per review with Building Engineer.
	Pipes - Chilled Water Pipe- Steel	Entire Building	300	LF	6	10+ years	Associated with north chiller. Quantity changed to match current observations and per review with Building Engineer.
	Pressure Fill System	Entire Building	1	EA	6	10+ years	3 3 3
	Pressure Fill System	Entire Building	1	EA	6	10+ years	
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	4	2-5 years	Component of a ductless split systes serving the MDF Room. Dataplate not accessible. Original to the building, unit has been well-maintained and has undergone recent repairs to keep the unit operational, but it shows signs of a related degradation and has reached the end of its anticipated service life CPS Asset Tag not legible.

Campus Name: New Sullivan Page : 5 of 39 Assessment Date: 04/22/2024



atego	ry : Mechanical		R	uilding	: Main		
atogo	i y : incondinoai			unung	. wan	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Гоцр	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	51	EA	6	10+ years	Quantity changed as total has been divided/aggregated. Located throughout the building above the suspended ceiling grid.
	VAV Box	Entire Building	40	EA	6	10+ years	Quantity changed as total has been divided/aggregated. Location changed for clarification. Located above the suspended ceiling grid throughout the building.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	Mech. Room - AHU-1	1	EA	6	10+ years	AHU-1, serves 1st Floor
	Air Intake	Mech. Room - AHU-1	1	EA	7	10+ years	
	Air Handling Unit-Package Single Zone-Indoor- Hot Water and Chilled Water Coils - 20001-30000 cfm	Mech. Room - AHU-2	1	EA	6	10+ years	AHU-2, serves 2nd and 3rd Floors.
	Air Intake	Mech. Room - AHU-2	1	EA	7	10+ years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 8001-12000 cfm	Mech. Room - AHU-3	1	EA	6	10+ years	AHU-3, serves lunchroom, kitchen, and associated spaces.
	Air Intake	Mech. Room - AHU-3	1	EA	7	10+ years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 4000-8000 cfm	Mech. Room - AHU-4	1	EA	6	10+ years	AHU-4, serves gym.
	Air Intake	Mech. Room - AHU-4	1	EA	7	10+ years	
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Rooms	1	EA	6	10+ years	RF-3. Location changed for clarification. Dataplate inaccessible due to lack of reliable climbing means.
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Mechanical Rooms	1	EA	6	10+ years	RF-4. Location changed for clarification. Quantity changed as total has been divided/aggregated.
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Rooms	1	EA	6	10+ years	RF-2. Location changed for clarification.
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Rooms	1	EA	6	10+ years	RF-1
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	Roof	1	EA	3	0-1 year	Unit is not in service and is not functional. Rank, Reason and Priority Rep changed to document that the unit is not needed to serve the kitchen as originally intended and has been deemed obsolete.

Boiler Systems

Campus Name: New Sullivan Page : 6 of 39 Assessment Date: 04/22/2024



Catego	ry : Mechanical		В	uilding	: Main		, , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Boiler Auxiliary- Non Condensing Hot Water - 2001 - 3000 MBH	North Mechanical Room	3	EA	6	10+ years	Location changed for clarification.
	Chemical Pot Feeder	North Mechanical Room	1	EA	6	10+ years	Quantity changed to match current observations. Location changed for clarification.
	Combustion Dampers	North Mechanical Room	3	EA	6	10+ years	Location changed for clarification.
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 3001 - 4000 MBH	North Mechanical Room	1	EA	6	10+ years	B-2. Location changed for clarification.
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 3001 - 4000 MBH	North Mechanical Room	1	EA	6	10+ years	B-1. Location changed for clarification.
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 3001 - 4000 MBH	North Mechanical Room	1	EA	6	10+ years	B-3. Location changed for clarification.
	Water Fill System	North Mechanical Room	1	EA	6	10+ years	Location changed for clarification I
Gas Boo	ster						
	Gas Booster	Mechanical Room	1	EA	6	10+ years	Location changed for clarification.
Heating	Devices						
- U	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations and per review with Building Engineer. One each located in the Fire Pump Room and Electrical Room. Priority Rep adjusted based on current observations and on the age of the equipment.
	Unit Heater - Hot Water	Entire Building	3	EA	6	10+ years	Quantity changed as total has been divided/aggregated. Location changed for clarification.
	Unit Heater - Hot Water	Entire Building	4	EA	6	10+ years	-
	Cabinet Heaters - With Hot Water Coil	Entire Building	21	EA	6	6-10 years	
	Radiator Panels - Hot Water	Entire Building	18	EA	6	6-10 years	Quantity changed to match current observations. Ceiling mounted in student restrooms and select office spaces.
_Mechani	cal Plumbing						
	Hydronic Supply and Return - Copper Hydronic Supply and Return - Steel	Entire Building Entire Building	1,000 500	LF LF	7 7	10+ years 10+ years	Quantity changed to match current observations and per review with Building Engineer.



Catego	ry : Mechanical		В	uilding	: Main		TO Mackinaw Avenue, Chicago, in 60017
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chilled Water Pump - 10 - 20 HP	Mechanical Rooms	1	EΑ	6	6-10 years	
	Chilled Water Pump - 10 - 20 HP	Mechanical Rooms	1	EA	6	6-10 years	
	Chilled Water Pump - 10 - 20 HP	Mechanical Rooms	1	EA	6	6-10 years	
	Chilled Water Pump - 10 - 20 HP	Mechanical Rooms	1	EΑ	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Mechanical Rooms	1	EΑ	6	6-10 years	
	Hot Water Pump - 10 - 20 HP	Mechanical Rooms	1	EA	6	10+ years	
	Hot Water Pump - Less than 10	Mechanical Rooms	1	EA	7	10+ years	Air handler recirculating pump. No CPS Asset Tag present. Location changed for clarification. Rank and Priority Rep changed based on current observations and per review with Building Engineer that the pump
	Hot Water Pump - Less than 10	Mechanical Rooms	1	EA	6	6-10 years	has been replaced since previous assessment. Air handler recirculating pump. No CPS Asset Tag present. Location changed for clarification. Rank and
							Priority Rep adjusted based on current observations and per review with Building Engineer that the pump has been repaired since previous assessment.
	Hot Water Pump - Less than 10	Mechanical Rooms	1	EA	6	6-10 years	Air handler recirculating pump. Location changed for clarification. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer that the pump has been repaired since previous assessment.
	Hot Water Pump - Less than 10	Mechanical Rooms	1	EA	6	6-10 years	Air handler recirculating pump. No CPS Asset Tag present. Location changed for clarification. Rank and Priority Rep adjusted based on current observations and per review with Building Engineer that the pump has been repaired since previous assessment.
_Tempera	ature Control						
·	DDC System	Entire Building	218,126	SF	4	0-1 year	Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that the DDC system is nonfunctional, employs



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	antiquated technology and is not a candidate for a software upgrade to restore operation to the system. Temperatures throughout the building are manually controlled such as by opening/closing valves, energizing/deenergizing units, or other manual adjustments.
	Electric Thermostat	Entire Building	10	EA	6	6-10 years	Priority Rep adjusted based on current observations and on the age of the devices.
	Thermostats - DDC	Entire Building	113	EA	4	2-5 years	Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer that the DDC thermostats have outlasted their anticipated service life and have no effective communication with the failed temperature control system. Temperatures throughout the building are manually controlled such as by opening/closing valves, energizing/deenergizing units, or other manual adjustments.
_Ventilation	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	3	EA	6	10+ years	One each located in the Fire Pump Room, Electrical Room, and South Mechanical Room.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Mechanical Noom.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	6	6-10 years	Quantity changed to match current observations. Rank adjusted based on current observations and per review with Building Engineer that repairs have been completed since previous assessment.
	Type I Exhaust Hood- Kitchen	Entire Building	2	EA	7	6-10 years	Quantity changed to match current observations.
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	7	10+ years	



Catego	Category : Plumbing		В	Building : Main			1 3 Mackinaw Avenue, Chicago, it 60617
Calogo	. ,			aag		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er					_	
	Electric Heater - Greater than 50 KW	Kitchen	1	EA	6	6-10 years	
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	7	10+ years	Rank and Priority Rep changed as the water heater was replaced since previous assessment.
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	7	10+ years	Priority Rep changed as the water heater was replaced since previous assessment.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	218,126	SF	7	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	218,126	SF	7	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	218,126	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	218,126	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	218,126	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	218,126	SF	7	10+ years	
	Sanitary Piping	Entire Building	218,126	SF	7	10+ years	
	Storm Piping	Entire Building	218,126	SF	7	10+ years	
	Vent Piping	Entire Building	218,126	SF	7	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	10+ years	Elevator pit sump pump. Not directly accessible at the time of assessment. No CPS Asset Tag available. Condition verified by Building Engineer. Location changed for clarification.

Category: Room **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Lay-in	109A gym office	55	SF	6	10+ years	
	Ceiling - Lay-in	109A gym office	48	SF	4	0-1 year	Water damage
	Doors - Side-lite	109A gym office	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	109A gym office	1	EΑ	6	10+ years	
	Floor - Tile	109A gym office	103	SF	6	10+ years	
	Lighting - Lay-in	109A gym office	1	EA	7	6-10 years	

Campus Name: New Sullivan Page : 10 of 39 Assessment Date: 04/22/2024



Category : Room		В	uilding	: Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Power Distribution	109A gym office	4	EA	7	6-10 years		
	Walls - Concrete Block	109A gym office	380	SF	7	10+ years		
	Ceiling - Lay-in	113 counselor	121	SF	7	10+ years		
	Doors - Wood Doors inclu hw	113 counselor	1	EA	7	10+ years		
	Floor - Tile	113 counselor	121	SF	7	10+ years		
	Lighting - Lay-in	113 counselor	2	EA	7	6-10 years		
	Power Distribution	113 counselor	4	EA	7	6-10 years		
	Walls - Concrete Block	113 counselor	225	SF	7	10+ years		
	Ceiling - Lay-in	116 # 1-44	125	SF	6	10+ years		
	Doors - Wood Doors inclu hw	116 # 1-44	1	EA	6	10+ years		
	Floor - Tile	116 # 1-44	125	SF	6	10+ years		
	Lighting - Lay-in	116 # 1-44	2	EA	7	6-10 years		
	Power Distribution	116 # 1-44	3	EA	7	6-10 years		
	Walls - Concrete Block	116 # 1-44	410	SF	6	10+ years		
	Ceiling - Lay-in	1st Floor Engineers Office	144	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Floor Engineers Office	1	ĒA	6	10+ years		
	Doors - Transom Window	1st Floor Engineers Office	8	SF	7	10+ years		
	Floor - Tile	1st Floor Engineers Office	144	SF	6	10+ years		
	Lighting - Lay-in	1st Floor Engineers Office	2	ĒΑ	7	10+ years		
	Power Distribution	1st Floor Engineers Office	4	ĒΑ	7	10+ years		
	Walls - Concrete Block	1st Floor Engineers Office	454	SF	6	10+ years		
	Ceiling - Exposed	212	144	SF	7	10+ years		
	Doors - Wood Doors inclu hw	212	1	EA	7	10+ years		
	Floor - Tile	212	144	SF	7	10+ years		
	Lighting - Pendent/Surface	212	2	EA	7	10+ years		
	Power Distribution	212	4	EA	7	10+ years		
	Walls - Concrete Block	212	340	SF	7	10+ years		
	Ceiling - Lay-in	214 Office # 2-28	215	SF	6	10+ years		
	Doors - Wood Doors inclu hw	214 Office # 2-28	1	EA	6	10+ years		
	Floor - Tile	214 Office # 2-28	215	SF	6	10+ years		
	Lighting - Lay-in	214 Office # 2-28	6	EA	7	6-10 years		
	Power Distribution	214 Office # 2-28	10	EΑ	7	6-10 years		
	Storage/ Closet	214 Office # 2-28	180	SF	7	10+ years		
	Walls - Concrete Block	214 Office # 2-28	94	SF	6	10+ years		
	Walls - Plaster/Drywall	214 Office # 2-28	557	SF	6	10+ years		
	Work Sink	214 Office # 2-28	1	EA	7	10+ years		
	Ceiling - Exposed	317 Office #3-26	147	SF	7	10+ years		
	Doors - Wood Doors inclu hw	317 Office #3-26	1	EA	6	10+ years		
	Floor - Tile	317 Office #3-26	147	SF	6	10+ years		
	Lighting - Pendent/Surface	317 Office #3-26	3	EA	7	6-10 years		
	Walls - Concrete Block	317 Office #3-26	225	SF	6	10+ years		
	Walls - Plaster/Drywall	317 Office #3-26	327	SF	6	10+ years		
	Ceiling - Lay-in	Kitchen office	63	SF	6	10+ years		
	Ceiling - Lay-in	Kitchen office	8	SF	4	0-1 year	Water damage	
	Cenning - Lay-III	MICHELI OHICE	0	ЗF	4	u-i yeai	vvater uarriage	



Category : Room			В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	Kitchen office	16	SF	6	10+ years	
	Doors - Steel Doors incl hw	Kitchen office	1	EA	6	10+ years	
	Doors - Transom Window	Kitchen office	8	SF	7	10+ years	
	Floor - Tile	Kitchen office	67	SF	6	10+ years	
	Floor - Tile	Kitchen office	4	SF	4	1-2 years	Chipped
	Lighting - Lay-in	Kitchen office	1	EA	7	6-10 years	
	Power Distribution	Kitchen office	4	EA	7	6-10 years	
	Walls - Concrete Block	Kitchen office	344	SF	6	10+ years	
	Ceiling - Lay-in	Office 117 in room 107	83	SF	6	10+ years	
	Ceiling - Lay-in	Office 117 in room 107	8	SF	4	0-1 year	Missing
	Doors - Wood Doors inclu hw	Office 117 in room 107	1	EA	6	10+ years	•
	Floor - Tile	Office 117 in room 107	91	SF	6	10+ years	
	Lighting - Lay-in	Office 117 in room 107	1	EA	7	10+ years	
	Power Distribution	Office 117 in room 107	4	EA	7	10+ years	
	Walls - Concrete Block	Office 117 in room 107	141	SF	6	10+ years	
	Walls - Plaster/Drywall	Office 117 in room 107	237	SF	6	10+ years	
	Ceiling - Lay-in	Practice room 2 In room 107	61	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Practice room 2 In room 107	1	EA	6	10+ years	
	Floor - Tile	Practice room 2 In room 107	61	SF	6	10+ years	
	Lighting - Lay-in	Practice room 2 In room 107	1	EA	7	10+ years	
	Power Distribution	Practice room 2 In room 107	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Practice room 2 In room 107	122	SF	6	10+ years	
	Ceiling - Lay-in	Practice room 3. In room 107	61	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Practice room 3. In room 107	1	EA	6	10+ years	
	Floor - Tile	Practice room 3. In room 107	61	SF	6	10+ years	
	Lighting - Lay-in	Practice room 3. In room 107	1	EA	7	10+ years	
	Power Distribution	Practice room 3. In room 107	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Practice room 3. In room 107	122	SF	6	10+ years	
	Ceiling - Lay-in	Practice room 4 in room 107	64	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Practice room 4 in room 107	1	ĒΑ	6	10+ years	
	Floor - Tile	Practice room 4 in room 107	64	SF	6	10+ years	
	Lighting - Lay-in	Practice room 4 in room 107	1	ĒΑ	7	10+ years	
	Power Distribution	Practice room 4 in room 107	4	EA	7	10+ years	
	Walls - Concrete Block	Practice room 4 in room 107	113	SF	6	10+ years	
	Walls - Plaster/Drywall	Practice room 4 in room 107	212	SF	6	10+ years	
	Ceiling - Lay-in	Practice room 6 in room 107	76	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Practice room 6 in room 107	1	EA	6	10+ years	
	Floor - Tile	Practice room 6 in room 107	76	SF	6	10+ years	
	Lighting - Lay-in	Practice room 6 in room 107	1	EA	7	10+ years	
	Power Distribution	Practice room 6 in room 107	4	EΑ	7	10+ years	
	Walls - Concrete Block	Practice room 6 in room 107	360	SF	6	10+ years	
	Ceiling - Lay-in	Rm101 Principal's Office	292	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Rm101 Principal's Office	1	EA	6	10+ years	
	Floor - Carpet	Rm101 Principal's Office	292	SF	6	6-10 years	
	1 iooi odipot	Tanto i i moipai s Omoe	232	O.	J	o io years	



Catego	ry : Room	Building : Main							
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Lay-in	Rm101 Principal's Office	4	EA	7	10+ years			
	Power Distribution	Rm101 Principal's Office	12	EA	7	10+ years			
	Walls - Concrete Block	Rm101 Principal's Office	84	SF	6	10+ years			
	Walls - Plaster/Drywall	Rm101 Principal's Office	536	SF	6	10+ years			
	Ceiling - Lay-in	Rm102 Dean of students	148	SF	6	10+ years			
	Ceiling - Lay-in	Rm102 Dean of students	8	SF	4	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	Rm102 Dean of students	1	EA	6	10+ years			
	Floor - Carpet	Rm102 Dean of students	156	SF	6	6-10 years			
	Lighting - Lay-in	Rm102 Dean of students	2	EA	7	10+ years			
	Power Distribution	Rm102 Dean of students	12	EA	7	10+ years			
	Walls - Concrete Block	Rm102 Dean of students	86	SF	6	10+ years			
	Walls - Plaster/Drywall	Rm102 Dean of students	336	SF	6	10+ years			
	Ceiling - Lay-in	Rm103 Asst Principal	148	SF	6	10+ years			
	Ceiling - Lay-in	Rm103 Asst Principal	4	SF	4	1-2 years	Water damage		
	Doors - Wood Doors inclu hw	Rm103 Asst Principal	1	EA	6	10+ years	•		
	Floor - Carpet	Rm103 Asst Principal	152	SF	6	6-10 years			
	Lighting - Lay-in	Rm103 Asst Principal	2	EA	7	10+ years			
	Power Distribution	Rm103 Asst Principal	12	EA	7	6-10 years			
	Walls - Concrete Block	Rm103 Asst Principal	87	SF	6	10+ years			
	Walls - Plaster/Drywall	Rm103 Asst Principal	339	SF	6	10+ years			
	Ceiling - Lay-in	Rm105 main office	680	SF	6	10+ years			
	Doors - Side-lite	Rm105 main office	40	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Rm105 main office	2	EA	6	10+ years			
	Floor - Carpet	Rm105 main office	546	SF	6	6-10 years			
	Floor - Terrazzo	Rm105 main office	134	SF	7	10+ years			
	Lighting - Lay-in	Rm105 main office	10	EA	7	10+ years			
	Power Distribution	Rm105 main office	14	EA	7	10+ years			
	Storage/ Closet	Rm105 main office	12	SF	7	10+ years			
	Walls - Concrete Block	Rm105 main office	380	SF	6	10+ years			
	Walls - Plaster/Drywall	Rm105 main office	450	SF	6	10+ years			
	Walls - Structural Glazed Tile	Rm105 main office	586	SF	6	10+ years			
	Ceiling - Lay-in	Rm110	127	SF	6	10+ years			
	Ceiling - Lay-in	Rm110	4	SF	4	1-2 years	Water damage		
	Doors - Wood Doors inclu hw	Rm110	1	EA	6	10+ years	•		
	Floor - Tile	Rm110	131	SF	6	10+ years			
	Lighting - Lay-in	Rm110	2	EA	7	10+ years			
	Power Distribution	Rm110	12	EA	7	10+ years			
	Walls - Concrete Block	Rm110	135	SF	6	10+ years			
	Walls - Plaster/Drywall	Rm110	331	SF	6	10+ years			
	Work SInk	Rm110	1	EA	7	10+ years			
_Gymnas	ia								
	Bleacher Seating	1st Floor	82	EA	6	10+ years			
	Ceiling - Exposed	1st Floor	4,153	SF	6	10+ years			
	Coming Exposed	1001	7,100	0.	J	ioi youis			



Catego	Category : Room		В	uilding	: Main		1 O Mackinaw Avenue, Officago, ie 60017
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	6	10+ years	
	Floor - Wood	1st Floor	4,153	SF	6	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	16	EΑ	6	6-10 years	
	Scoreboards	1st Floor	1	EA	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Storage/Closet	1st Floor	180	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	7,762	SF	6	10+ years	
Kitchen							
TRICHELL	Ceiling - Lay-in	1st Floor	1,612	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	3	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	1,612	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Lighting - Lay-III Lighting - Wall Mounted	1st Floor	10	EA	7	6-10 years	
	Storage/ Closet	1st Floor	130	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	4,032	SF	6	10+ years	
	Walls - Collete Block	151 11001	4,032	SI	O	10+ years	
Library							
	Casework	2nd Floor	35	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	3,600	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	6	10+ years	
	Floor - Carpet	2nd Floor	3,600	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	46	EΑ	6	6-10 years	
	Walls - Concrete Block	2nd Floor	1,100	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,200	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Exposed	1st Floor	3,155	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	957	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EΑ	6	10+ years	
	Floor - Tile/Sheet	1st Floor	4,106	SF	5	10+ years	
	Floor - Tile/Sheet	1st Floor	, 6	SF	4	0-1 year	Chipped
	Lighting - Lay-in	1st Floor	12	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EΑ	7	6-10 years	
	Serving Line	1st Floor	54	LF	6	10+ years	
	Walls - Concrete Block	1st Floor	7,166	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,237	SF	6	10+ years	
MDF ID	E						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Finishes	2nd Floor 2nd Floor	123	SF	7	10+ years	
	Other Cooling Unit	2nd Floor 2nd Floor	123	EA	7	10+ years	
	Other Cooling Offic	2110 1 1001	ı	LA	,	10+ years	



Catego	ory : Room		В	uilding	: Main		TO Mackinaw Avenue, Onicago, ie 00017
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechan	ical/ Service Rooms						
	Janitor's Closet	1st Floor	29	SF	7	10+ years	
	Janitor's Closet	1st Floor	15	SF	7	10+ years	
	Janitor's Closet	1st Floor	12	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	70	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	271	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	406	SF	5	10+ years	
	Storage Room	1st Floor	451	SF	7	10+ years	
	Storage Room	1st Floor	140	SF	7	10+ years	
	Storage Room	1st Floor	194	SF	7	10+ years	
	Vaults	1st Floor	248	SF	7	10+ years	
	Boiler Room	2nd Floor	2,019	SF	7	10+ years	
	Janitor's Closet	2nd Floor	12	SF	7	10+ years	
	Janitor's Closet	2nd Floor	12	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	85	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	28	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	1,850	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	28	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	69	SF	7	10+ years	
	Storage Room	2nd Floor	1,121	SF	7	10+ years	
	Janitor's Closet	3rd Floor	11	SF	7	10+ years	
	Janitor's Closet	3rd Floor	11	SF	7	10+ years	
	Storage Room	3rd Floor	82	SF	7	10+ years	
	Gio. ago 1 ioo	0.0.100.	~	О.	•	. o · you.o	
Restroo	m						
	Accessories	1st Fl Boys North	194	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Fl Boys North	194	SF	6	10+ years	
	Floor - Terrazzo	1st FI Boys North	194	SF	7	10+ years	
	Floor Drain	1st Fl Boys North	2	EA	7	10+ years	
	Lavatory	1st FI Boys North	3	EA	7	10+ years	
	Lighting - Lay-in	1st Fl Boys North	4	EA	7	10+ years	
	Partitions	1st FI Boys North	2	EA	7	10+ years	
	Urinals	1st Fl Boys North	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Fl Boys North	696	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st FI Boys North	810	SF	6	10+ years	
	Water Closet	1st Fl Boys North	2	EA	7	10+ years	
	Accessories	1st Fl Boys South	194	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Fl Boys South	194	SF	6	10+ years	
	Floor - Terrazzo	1st Fl Boys South	194	SF	5	10+ years	
	Floor Drain	1st Fl Boys South	2	EA	7	10+ years	
	Lavatory	1st Fl Boys South	3	EA	7	10+ years	
	Lighting - Lay-in	1st Fl Boys South	4	EA	7	10+ years	
	Partitions	1st Fl Boys South	2	EA	7	10+ years	
	i aimono	13t 1 1 Doys South	2	LA	,	10+ years	



Catego	Category : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Urinals	1st Fl Boys South	2	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st Fl Boys South	516	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st Fl Boys South	810	SF	6	10+ years			
	Water Closet	1st Fl Boys South	2	EA	6	10+ years			
	Accessories	1st Fl Girls North	192	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Fl Girls North	192	SF	6	10+ years			
	Floor - Terrazzo	1st Fl Girls North	192	SF	7	10+ years			
	Floor Drain	1st Fl Girls North	2	EA	7	10+ years			
	Lavatory	1st Fl Girls North	3	EA	7	10+ years			
	Lighting - Lay-in	1st FI Girls North	4	EA	7	10+ years			
	Partitions	1st FI Girls North	4	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st FI Girls North	789	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st FI Girls North	810	SF	6	10+ years			
	Water Closet	1st FI Girls North	4	EA	6	10+ years			
	Accessories	1st FI Girls South	192	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st FI Girls South	192	SF	6	10+ years			
	Floor - Terrazzo	1st FI Girls South	182	SF	6	10+ years			
	Floor - Terrazzo	1st FI Girls South	10	SF	5	0-1 year	Cracked		
	Floor Drain	1st FI Girls South	2	EA	7	10+ years			
	Lavatory	1st FI Girls South	3	EA	7	10+ years			
	Lighting - Lay-in	1st FI Girls South	4	EA	7	10+ years			
	Partitions	1st Fl Girls South	4	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st Fl Girls South	516	SF	7	10+ years			
	Water Closet	1st Fl Girls South	4	ĒA	7	10+ years			
	Accessories	1st FI Men's North	60	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Fl Men's North	60	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st FI Men's North	1	ĒΑ	6	10+ years			
	Floor - Terrazzo	1st Fl Men's North	60	SF	6	10+ years			
	Floor Drain	1st Fl Men's North	1	ĒA	7	10+ years			
	Lavatory	1st Fl Men's North	1	EA	6	10+ years			
	Lighting - Lay-in	1st Fl Men's North	1	ĒΑ	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st Fl Men's North	256	SF	6	10+ years			
	Water Closet	1st Fl Men's North	1	ĒΑ	6	10+ years			
	Accessories	1st Fl Room 119 Restroom	33	SF	7	6-10 years			
	Ceiling - Lay-in	1st Fl Room 119 Restroom	33	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Fl Room 119 Restroom	1	ĒΑ	6	10+ years			
	Floor - Tile	1st Fl Room 119 Restroom	33	SF	6	10+ years			
	Floor Drain	1st Fl Room 119 Restroom	1	ĒΑ	7	10+ years			
	Lavatory	1st Fl Room 119 Restroom	1	EΑ	6	10+ years			
	Lighting - Lay-in	1st Fl Room 119 Restroom	1	EA	7	6-10 years			
	Walls - Tile Ceramic/ Porcelain	1st FI Room 119 Restroom	206	SF	6	10+ years			
	Water Closet	1st FI Room 119 Restroom	1	EA	6	10+ years			
	Accessories	1st FI South	52	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Fl South	52	SF	6	10+ years			
	John G Flactor Dry Wall	.5011 50001	02	0.	J	ioi youis			



Catego	ry : Room		В	uilding	: Main		. 5 :
J						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Fl South	1	EA	6	10+ years	
	Floor - Terrazzo	1st Fl South	52	SF	7	10+ years	
	Floor Drain	1st Fl South	1	EA	7	10+ years	
	Lavatory	1st Fl South	1	EA	6	10+ years	
	Lighting - Lay-in	1st Fl South	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Fl South	271	SF	6	10+ years	
	Water Closet	1st Fl South	1	EA	6	10+ years	
	Accessories	1st FI Women's North	74	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Fl Women's North	74	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl Women's North	1	EA	6	10+ years	
	Floor - Terrazzo	1st Fl Women's North	74	SF	7	10+ years	
	Floor Drain	1st Fl Women's North	1	EA	7	10+ years	
	Lavatory	1st Fl Women's North	1	EA	7	10+ years	
	Lighting - Lay-in	1st FI Women's North	1	EA	7	10+ years	
	Student Lockers - One Tier	1st Fl Women's North	6	EA	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st FI Women's North	324	SF	6	10+ years	
	Water Closet	1st Fl Women's North	1	EA	7	10+ years	
	Accessories	1st FI inside Main Office	37	SF	7	6-10 years	
	Ceiling - Lay-in	1st FI inside Main Office	37	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI inside Main Office	1	EA	6	10+ years	
	Floor - Tile	1st FI inside Main Office	37	SF	6	10+ years	
	Floor Drain	1st FI inside Main Office	1	EA	7	10+ years	
	Lavatory	1st FI inside Main Office	1	EA	7	10+ years	
	Lighting - Lay-in	1st FI inside Main Office	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st FI inside Main Office	219	SF	6	10+ years	
	Water Closet	1st FI inside Main Office	1	EA	7	10+ years	
	Accessories	1st Fl, Rm 114 restroom	33	SF	7	6-10 years	
	Ceiling - Lay-in	1st Fl, Rm 114 restroom	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl, Rm 114 restroom	1	EA	6	10+ years	
	Floor - Tile	1st Fl, Rm 114 restroom	33	SF	6	10+ years	
	Floor Drain	1st Fl, Rm 114 restroom	1	EA	7	10+ years	
	Lavatory	1st Fl, Rm 114 restroom	1	EA	6	10+ years	
	Lighting - Lay-in	1st Fl, Rm 114 restroom	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Fl, Rm 114 restroom	206	SF	6	10+ years	
	Water Closet	1st Fl, Rm 114 restroom	1	EA	6	10+ years	
	Accessories	1st Fl, Rm 117 restroom	33	SF	7	6-10 years	
	Ceiling - Lay-in	1st Fl, Rm 117 restroom	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl, Rm 117 restroom	1	ĒA	6	10+ years	
	Floor - Tile	1st Fl, Rm 117 restroom	33	SF	7	10+ years	
	Floor Drain	1st Fl, Rm 117 restroom	1	EA	7	10+ years	
	Lavatory	1st Fl, Rm 117 restroom	1	EA	6	10+ years	
	Lighting - Lay-in	1st Fl, Rm 117 restroom	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st Fl, Rm 117 restroom	206	SF	6	10+ years	
	Water Closet	1st Fl, Rm 117 restroom	1	ĒΑ	6	10+ years	
		,			-	,	



Catego	ry : Room		В	uilding	: Main		. 5 :
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st FI, Rm 118 restroom	33	SF	7	6-10 years	
	Ceiling - Lay-in	1st FI, Rm 118 restroom	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st FI, Rm 118 restroom	1	EA	6	10+ years	
	Floor - Tile	1st FI, Rm 118 restroom	33	SF	6	10+ years	
	Floor Drain	1st FI, Rm 118 restroom	1	EA	7	10+ years	
	Lighting - Lay-in	1st FI, Rm 118 restroom	1	EA	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	1st FI, Rm 118 restroom	206	SF	6	10+ years	
	Water Closet	1st FI, Rm 118 restroom	1	EA	6	10+ years	
	Accessories	1st FI, Rm 120 restroom	33	SF	7	6-10 years	
	Ceiling - Lay-in	1st FI, Rm 120 restroom	33	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Fl, Rm 120 restroom	1	EA	6	10+ years	
	Floor - Tile	1st FI, Rm 120 restroom	33	SF	6	10+ years	
	Floor Drain	1st FI, Rm 120 restroom	1	EA	7	10+ years	
	Lavatory	1st Fl, Rm 120 restroom	1	EA	6	10+ years	
	Lighting - Lay-in	1st Fl, Rm 120 restroom	1	EA	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Fl, Rm 120 restroom	206	SF	6	10+ years	
	Water Closet	1st Fl, Rm 120 restroom	1	EA	6	10+ years	
	Accessories	2nd FI Boys South	194	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd FI Boys South	194	SF	6	10+ years	
	Floor - Terrazzo	2nd Fl Boys South	194	SF	7	10+ years	
	Floor Drain	2nd FI Boys South	2	EA	7	10+ years	
	Lavatory	2nd FI Boys South	3	EA	7	10+ years	
	Lighting - Lay-in	2nd FI Boys South	4	EA	7	6-10 years	
	Partitions	2nd Fl Boys South	2	EA	7	10+ years	
	Urinals	2nd FI Boys South	2	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Fl Boys South	516	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Fl Boys South	810	SF	6	10+ years	
	Water Closet	2nd FI Boys South	2	EA	7	10+ years	
	Accessories	2nd Fl Girls North	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Fl Girls North	192	SF	6	10+ years	
	Floor - Terrazzo	2nd Fl Girls North	192	SF	7	10+ years	
	Floor Drain	2nd Fl Girls North	2	EA	7	10+ years	
	Lavatory	2nd Fl Girls North	3	EΑ	7	10+ years	
	Lighting - Lay-in	2nd Fl Girls North	4	EA	7	6-10 years	
	Partitions	2nd Fl Girls North	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Fl Girls North	516	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Fl Girls North	810	SF	6	10+ years	
	Water Closet	2nd Fl Girls North	4	ĒΑ	7	10+ years	
	Accessories	2nd Fl North	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Fl North	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Fl North	1	EΑ	6	10+ years	
	Floor - Terrazzo	2nd Fl North	60	SF	7	10+ years	
	Floor Drain	2nd Fl North	1	EA	7	10+ years	
	Lavatory	2nd Fl North	1	EA	7	10+ years	
			•		•	,	



Category : Room		В	uilding	: Main		<u> </u>		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Lighting - Lay-in	2nd Fl North	1	EΑ	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd Fl North	252	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd Fl North	4	SF	5	1-2 years	Hole	
	Water Closet	2nd Fl North	1	EA	6	10+ years		
	Accessories	2nd FI South	52	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd FI South	52	SF	6	10+ years		
	Doors - Wood Doors inclu hw	2nd Fl South	1	EA	6	10+ years		
	Floor - Terrazzo	2nd FI South	52	SF	7	10+ years		
	Floor Drain	2nd Fl South	1	EA	7	10+ years		
	Lavatory	2nd Fl South	1	EA	7	10+ years		
	Lighting - Lay-in	2nd Fl South	1	EA	7	6-10 years		
	Walls - Tile Ceramic/ Porcelain	2nd Fl South	271	SF	6	10+ years		
	Water Closet	2nd Fl South	1	ĒA	7	10+ years		
	Accessories	2nd Flr boys south 2	192	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Flr boys south 2	192	SF	6	10+ years		
	Floor - Terrazzo	2nd Flr boys south 2	192	SF	7	10+ years		
	Floor Drain	2nd Flr boys south 2	2	ĒA	7	10+ years		
	Lavatory	2nd Flr boys south 2	3	EA	7	10+ years		
	Lighting - Lay-in	2nd Flr boys south 2	4	EA	7	6-10 years		
	Partitions	2nd Flr boys south 2	2	ĒΑ	7	10+ years		
	Urinals	2nd Flr boys south 2	2	EA	7	10+ years		
	Walls - Structural Glazed Tile	2nd Flr boys south 2	516	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd Flr boys south 2	810	SF	6	10+ years		
	Water Closet	2nd Flr boys south 2	2	ĒA	7	10+ years		
	Accessories	2nd Flr girls North 2	194	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	2nd Flr girls North 2	194	SF	6	10+ years		
	Floor - Terrazzo	2nd Flr girls North 2	194	SF	7	10+ years		
	Floor Drain	2nd Flr girls North 2	2	ĒΑ	7	10+ years		
	Lavatory	2nd Flr girls North 2	3	EA	7	10+ years		
	Lighting - Lay-in	2nd Flr girls North 2	4	EA	7	6-10 years		
	Partitions	2nd Flr girls North 2	4	ĒΑ	7	10+ years		
	Walls - Structural Glazed Tile	2nd Flr girls North 2	516	SF	6	10+ years		
	Walls - Tile Ceramic/ Porcelain	2nd Flr girls North 2	810	SF	6	10+ years		
	Water Closet	2nd Flr girls North 2	4	ĒΑ	7	10+ years		
	Accessories	3rd Fl Boys North #3-16	194	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	3rd Fl Boys North #3-16	194	SF	6	10+ years		
	Floor - Terrazzo	3rd Fl Boys North #3-16	194	SF	7	10+ years		
	Floor Drain	3rd Fl Boys North #3-16	2	EA	7	10+ years		
	Lavatory	3rd Fl Boys North #3-16	3	ĒΑ	6	10+ years		
	Lighting - Lay-in	3rd Fl Boys North #3-16	4	EA	7	6-10 years		
	Partitions	3rd Fl Boys North #3-16	2	EΑ	7	10+ years		
	Urinals	3rd Fl Boys North #3-16	2	EΑ	6	10+ years		
	Walls - Structural Glazed Tile	3rd Fl Boys North #3-16	516	SF	6	10+ years		
	Water Closet	3rd Fl Boys North #3-16	2	EA	6	10+ years		
		2.22	_		ū	,		



Category : Room			В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	3rd Fl Boys South #3-15	194	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Fl Boys South #3-15	194	SF	6	10+ years	
	Floor - Terrazzo	3rd FI Boys South #3-15	194	SF	7	10+ years	
	Floor Drain	3rd FI Boys South #3-15	2	EA	7	10+ years	
	Lavatory	3rd Fl Boys South #3-15	3	EA	6	10+ years	
	Lighting - Lay-in	3rd Fl Boys South #3-15	4	EA	7	6-10 years	
	Partitions	3rd FI Boys South #3-15	2	EA	7	10+ years	
	Urinals	3rd Fl Boys South #3-15	2	EΑ	6	10+ years	
	Walls - Structural Glazed Tile	3rd Fl Boys South #3-15	516	SF	6	6-10 years	
	Water Closet	3rd FI Boys South #3-15	2	EA	6	10+ years	
	Accessories	3rd Fl Girls North #3-02	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Fl Girls North #3-02	192	SF	6	10+ years	
	Floor - Terrazzo	3rd Fl Girls North #3-02	192	SF	7	10+ years	
	Floor Drain	3rd Fl Girls North #3-02	2	EA	7	10+ years	
	Lavatory	3rd Fl Girls North #3-02	3	EA	7	10+ years	
	Lighting - Lay-in	3rd Fl Girls North #3-02	4	EA	7	6-10 years	
	Partitions	3rd Fl Girls North #3-02	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Fl Girls North #3-02	516	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Fl Girls North #3-02	810	SF	6	10+ years	
	Water Closet	3rd Fl Girls North #3-02	4	EA	7	10+ years	
	Accessories	3rd Fl Girls South #3-01	192	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Fl Girls South #3-01	192	SF	6	10+ years	
	Floor - Terrazzo	3rd Fl Girls South #3-01	192	SF	7	10+ years	
	Floor Drain	3rd Fl Girls South #3-01	2	EA	7	10+ years	
	Lavatory	3rd Fl Girls South #3-01	3	EA	7	10+ years	
	Lighting - Lay-in	3rd Fl Girls South #3-01	4	EA	7	6-10 years	
	Partitions	3rd Fl Girls South #3-01	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	3rd Fl Girls South #3-01	516	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Fl Girls South #3-01	810	SF	6	10+ years	
	Water Closet	3rd Fl Girls South #3-01	4	ĒΑ	7	10+ years	
	Accessories	3rd Fl North #3-18	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Fl North #3-18	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Fl North #3-18	1	ĒΑ	6	10+ years	
	Floor - Terrazzo	3rd Fl North #3-18	60	SF	7	10+ years	
	Floor Drain	3rd Fl North #3-18	1	EA	7	10+ years	
	Lavatory	3rd Fl North #3-18	1	EA	7	10+ years	
	Lighting - Lay-in	3rd Fl North #3-18	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	3rd Fl North #3-18	256	SF	6	10+ years	
	Water Closet	3rd Fl North #3-18	1	EA	7	10+ years	
	Accessories	3rd Fl South #3-04	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Fl South #3-04	52	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Fl South #3-04	1	EA	6	10+ years	
	Floor - Terrazzo	3rd Fl South #3-04	52	SF	6	10+ years	
	Floor Drain	3rd Fl South #3-04	1	EA	7	10+ years	
		5.4 1 1 5 5441	•	_, .	•	,	



Category : Room

William K New Sullivan Elementary School 8331 S Mackinaw AVENUE, Chicago, IL 60617

Building: Main

oup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Lavatory	3rd Fl South #3-04	1	EA	6	10+ years	
	Lighting - Lay-in	3rd Fl South #3-04	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	3rd Fl South #3-04	271	SF	6	10+ years	
	Water Closet	3rd Fl South #3-04	1	EA	6	10+ years	
·otomo	w. Classraam		В	ر المائم م	. Main	-	
atego	ry : Classroom		В	uilding	: wain	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroc	m #107 (Band Room)						
	Casework	1st Floor	46	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	2,075	SF	6	10+ years	
	Doors - Side-lite	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	6	10+ years	
	Floor - Tile	1st Floor	2,065	SF	6	10+ years	
	Floor - Tile	1st Floor	10	SF	4	0-1 year	Cracked
	Instrument Storage Casework	1st Floor	24	LF	6	10+ years	
	Lighting - Lay-in	1st Floor	34	EA	7	10+ years	
	Risers	1st Floor	16	LF	6	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Storage/ Closet	1st Floor	134	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	959	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	788	SF	6	10+ years	
lassroc	m #112 (Regular Classroom)						
	Casework	1st Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	895	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	895	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	ĒΑ	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	520	SF	6	10+ years	
	·		020	٥.	J	.o. youro	
lassroc	m #114 (Pre School)						
	Casework	1st Floor	60	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,052	SF	7	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,052	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main	,,,,,	1 3 Mackinaw Avenue, Chicago, ic 60617
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	581	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	710	SF	6	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	
Classroo	om #115 (Kindergarten)						
	Casework	1st Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	895	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	895	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	520	SF	6	10+ years	
Classro	om #117 (Regular Classroom)						
Ciassion	Casework	1st Floor	60	LF	6	10+ years	
	Casework Ceiling - Lay-in	1st Floor	1,104	SF	7	10+ years	
	Doors - Side-lite	1st Floor	1,104	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,104	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7		
	Walls - Concrete Block	1st Floor	581	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	710	SF		10+ years	
	Work Sink	1st Floor	710	Sr EA	6 7	10+ years 10+ years	
	WOIR SIIIR	151 F1001	2	EA	,	10+ years	
Classroo	om #118 (Kindergarten)						
	Casework	1st Floor	60	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,104	SF	7	10+ years	
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,104	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	581	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	710	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classras	om #119 (Pre School)						
Classion	Casework	1st Floor	60	LF	6	10+ years	
	Casework Ceiling - Lay-in	1st Floor	1,104	SF	6	•	
	Doors - Side-lite	1st Floor	1,104	SF	7	10+ years 10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,104	SF	6	10+ years	
		1st Floor	•	EA	7	6-10 years	
	Lighting - Lay-in Marker Board	1st Floor	17	LF	7		
	Storage/ Closet	1st Floor 1st Floor	12 72	SF		6-10 years	
	Walls - Concrete Block			SF SF	5 7	10+ years	
		1st Floor	581		-	10+ years	
	Walls - Plaster/Drywall	1st Floor	710	SF	6	10+ years	
	Work Sink	1st Floor	1	EΑ	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #120 (Regular Classroom)						
	Casework	1st Floor	60	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,080	SF	6	10+ years	
	Doors - Side-lite	1st Floor	. 8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,080	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	17	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	71	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	936	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	355	SF	6	10+ years	
	Work Sink	1st Floor	3	EA	7	10+ years	
Classras	om #123 (Covid Care Room)						
_Classiuc	Casework	1st Floor	42	LF	6	10+ years	
	Casework Ceiling - Lay-in	1st Floor	43 873	SF	6 6	10+ years 10+ years	
	Doors - Side-lite	1st Floor	8	SF SF	6	10+ years 10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	873	SF	6		
	Lighting - Lay-in	1st Floor			7	10+ years 10+ years	
	Lighting - Lay-in Marker Board	1st Floor	12	EA LF	7		
	Storage/ Closet	1st Floor 1st Floor	24 6	SF	7 7	6-10 years	
	Walls - Concrete Block	1st Floor	_	SF SF		10+ years	
	Walls - Concrete Block Walls - Plaster/Drywall		539	SF SF	6	10+ years	
		1st Floor	520		6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #124 (Faculty Lounge)						
	Casework	1st Floor	80	LF	6	10+ years	



Calego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	875	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	875	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	459	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	472	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #133 (Regular Classroom)						
	Casework	1st Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	895	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	895	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	107	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	520	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #201 (Regular Classroom)						
	Casework	2nd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	871	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	785	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	244	SF	6	10+ years	
Classror	om #202 (Regular Classroom)						
	Casework	2nd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	915	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	915	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		1 6 Mackinaw Avenoe, Gilleago, ie 60017
<u> </u>						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	856	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	243	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
	Casework	2nd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	915	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	915	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	856	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	243	SF	6	10+ years	
Classroo	om #204 (Store Room)						
	Casework	2nd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	867	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	vvator damage
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	871	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor 2nd Floor	785	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	244	SF	6	10+ years	
Classroo	om #205 (Office)						
Ciassiot	Casework	2nd Floor	18	LF	6	10+ years	
		2nd Floor 2nd Floor	456	SF			
	Ceiling - Lay-in Doors - Side-lite	2nd Floor 2nd Floor	450	SF SF	6 7	10+ years	
	Doors - Side-lite Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	8	SF EA	<i>7</i> 6	10+ years	
				SF		10+ years	
	Floor - Tile	2nd Floor	456		6	10+ years	
	Lighting - Lay-in	2nd Floor	8	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	340	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	123	SF	6	10+ years	
Classroo	om #206 (Office)						
	Casework	2nd Floor	23	LF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	543	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	543	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	309	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	518	SF	6	10+ years	
Classroo	om #207 (Office)						
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	539	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	4	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	S .
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	543	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	9	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	309	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	518	SF	6	10+ years	
Classroo	om #208 (Regular Classroom)						
	Casework	2nd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	895	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	520	SF	6	10+ years	
Classroo	om #209 (Regular Classroom)						
	Casework	2nd Floor	56	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	871	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	871	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	a	2.10 1 1001	21		•	3 .0 ,00.0	



Calego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	550	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	482	SF	6	10+ years	
Classroo	om #210 (Regular Classroom)						
	Casework	2nd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	915	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	915	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	856	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	243	SF	6	10+ years	
Classroo	om #211 (Science Classroom)						
	Casework	2nd Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	1,192	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	8	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	ŭ
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒA	6	10+ years	
	Floor - Tile	2nd Floor	1,200	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	120	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	778	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	484	SF	6	10+ years	
	Work Sink	2nd Floor	3	EA	7	10+ years	
Classroo	om #216 (Computer Lab)						
<u></u>	Ceiling - Lay-in	2nd Floor	1,185	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	0-1 year	Water damage
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	1,197	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	19	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	878	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	506	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	



Categor	ry : Classroom		В	uilding	: Main		1 3 Mackinaw Avenue, Chicago, il 60017
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #217 (Regular Classroom)						
	Casework	2nd Floor	35	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	456	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	456	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	530	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
Classroo	m #218 (Regular Classroom)						
	Casework	2nd Floor	35	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	456	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	456	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	530	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	340	SF	6	10+ years	
_Classroo	m #219 (Regular Classroom)						
	Casework	2nd Floor	35	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	456	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	456	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	10	ĒA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	800	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	270	SF	6	10+ years	
Classroo	m #301 (Regular Classroom)						
<u>Jidooi oo</u>	Casework	3rd Floor	56	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	869	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	16	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	vvater damage
	Doors - Wood Doors inclu hw	3rd Floor	0	EA	6	10+ years	
	Floor - Tile	3rd Floor	873	SF	6	10+ years	
	1 1001 1 110	014 1 1001	013	01	U	io i years	



em - Type Ighting - Lay-in Iarker Board Itorage/ Closet If alls - Concrete Block If alls - Plaster/Drywall If all all all all all all all all all al	Location 3rd Floor	Quantity 12 24 6 539 520	UOM EA LF SF SF SF	Rank 7 7 7 6 6	Recommend Replacement 6-10 years 6-10 years 10+ years 10+ years 10+ years	Comments
ghting - Lay-in larker Board torage/ Closet /alls - Concrete Block /alls - Plaster/Drywall #302 (Regular Classroom) asework eiling - Lay-in eiling - Lay-in oors - Side-lite oors - Wood Doors inclu hw loor - Tile	3rd Floor	12 24 6 539 520	EA LF SF SF SF	7 7 7 6 6	6-10 years 6-10 years 10+ years 10+ years	Comments
larker Board torage/ Closet /alls - Concrete Block /alls - Plaster/Drywall #302 (Regular Classroom) asework eiling - Lay-in eiling - Lay-in oors - Side-lite oors - Wood Doors inclu hw loor - Tile	3rd Floor	24 6 539 520 58 883	LF SF SF SF	7 7 6 6	6-10 years 10+ years 10+ years	
larker Board torage/ Closet /alls - Concrete Block /alls - Plaster/Drywall #302 (Regular Classroom) asework eiling - Lay-in eiling - Lay-in oors - Side-lite oors - Wood Doors inclu hw loor - Tile	3rd Floor	58 883	SF SF SF	7 6 6	10+ years 10+ years	
/alls - Concrete Block /alls - Plaster/Drywall #302 (Regular Classroom) asework eiling - Lay-in eiling - Lay-in oors - Side-lite oors - Wood Doors inclu hw loor - Tile	3rd Floor	539 520 58 883	SF SF LF	6 6	10+ years 10+ years	
/alls - Concrete Block /alls - Plaster/Drywall #302 (Regular Classroom) asework eiling - Lay-in eiling - Lay-in oors - Side-lite oors - Wood Doors inclu hw loor - Tile	3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor 3rd Floor	520 58 883	SF LF	6	10+ years	
#302 (Regular Classroom) asework eiling - Lay-in eiling - Lay-in oors - Side-lite oors - Wood Doors inclu hw loor - Tile	3rd Floor 3rd Floor 3rd Floor 3rd Floor	520 58 883	SF LF			
asework eiling - Lay-in eiling - Lay-in oors - Side-lite oors - Wood Doors inclu hw loor - Tile	3rd Floor 3rd Floor 3rd Floor	883				
asework eiling - Lay-in eiling - Lay-in oors - Side-lite oors - Wood Doors inclu hw loor - Tile	3rd Floor 3rd Floor 3rd Floor	883		6		
eiling - Lay-in eiling - Lay-in oors - Side-lite oors - Wood Doors inclu hw loor - Tile	3rd Floor 3rd Floor 3rd Floor	883		n	10+ years	
eiling - Lay-in oors - Side-lite oors - Wood Doors inclu hw loor - Tile	3rd Floor 3rd Floor		SF	6	10+ years	
oors - Side-lite oors - Wood Doors inclu hw loor - Tile	3rd Floor	•=	SF	4	1-2 years	Water damage
oors - Wood Doors inclu hw loor - Tile		8	SF	7	10+ years	Trator damage
loor - Tile	3rd Floor	1	EA	6	10+ years	
	3rd Floor	895	SF	6	10+ years	
	3rd Floor	12	EA	7	6-10 years	
larker Board	3rd Floor	24	LF	7	6-10 years	
torage/ Closet	3rd Floor	6	SF	7	10+ years	
/alls - Concrete Block	3rd Floor	560	SF	6	10+ years	
/alls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
#303 (Regular Classroom) asework	3rd Floor	58	LF	6	10+ years	
eiling - Lay-in	3rd Floor	895	SF	6	10+ years	
oors - Side-lite	3rd Floor	8	SF	7	10+ years	
oors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
loor - Tile	3rd Floor	895	SF	6	10+ years	
					,	
/alls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
#304 (Regular Classroom)						
asework	3rd Floor	58	LF	6	10+ years	
eiling - Lay-in	3rd Floor	890	SF	6		
oors - Side-lite	3rd Floor	8	SF	7		
oors - Wood Doors inclu hw	3rd Floor	1	ĒΑ			
loor - Tile	3rd Floor	890	SF	6		
	3rd Floor		ĒΑ	7	6-10 years	
ghting - Lay-in	3rd Floor	24	LF	7		
ghting - Lay-in larker Board				7		
larker Board					•	
larker Board torage/ Closet	3rd Floor					
18 to /: /: # 8 6 0 0	304 (Regular Classroom) asework eiling - Lay-in bors - Side-lite bors - Wood Doors inclu hw bor - Tile ghting - Lay-in arker Board borage/ Closet	arker Board 3rd Floor orage/ Closet 3rd Floor alls - Concrete Block 3rd Floor alls - Plaster/Drywall 3rd Floor 304 (Regular Classroom) asework 3rd Floor bors - Side-lite 3rd Floor ors - Wood Doors inclu hw 3rd Floor or - Tile 3rd Floor ophting - Lay-in 3rd Floor arker Board 3rd Floor arker Board 3rd Floor	ghting - Lay-in 3rd Floor 12 arker Board 3rd Floor 24 brage/ Closet 3rd Floor 6 alls - Concrete Block 3rd Floor 560 alls - Plaster/Drywall 3rd Floor 520 304 (Regular Classroom) 3rd Floor 58 eiling - Lay-in 3rd Floor 890 bors - Side-lite 3rd Floor 8 bors - Wood Doors inclu hw 3rd Floor 1 bor - Tile 3rd Floor 890 ghting - Lay-in 3rd Floor 12 arker Board 3rd Floor 24 borage/ Closet 3rd Floor 6	ghting - Lay-in 3rd Floor 12 EA arker Board 3rd Floor 24 LF orage/ Closet 3rd Floor 6 SF alls - Concrete Block 3rd Floor 560 SF alls - Plaster/Drywall 3rd Floor 520 SF 304 (Regular Classroom) 3rd Floor 58 LF eiling - Lay-in 3rd Floor 890 SF oors - Side-lite 3rd Floor 8 SF oors - Wood Doors inclu hw 3rd Floor 1 EA oor - Tile 3rd Floor 890 SF ghting - Lay-in 3rd Floor 12 EA arker Board 3rd Floor 24 LF orage/ Closet 3rd Floor 6 SF	ghting - Lay-in 3rd Floor 12 EA 7 arker Board 3rd Floor 24 LF 7 borage/ Closet 3rd Floor 6 SF 7 alls - Concrete Block 3rd Floor 560 SF 6 alls - Plaster/Drywall 3rd Floor 520 SF 6 304 (Regular Classroom) 3rd Floor 58 LF 6 asework 3rd Floor 890 SF 6 bors - Side-lite 3rd Floor 8 SF 7 bors - Wood Doors inclu hw 3rd Floor 1 EA 6 bor - Tile 3rd Floor 890 SF 6 ghting - Lay-in 3rd Floor 12 EA 7 arker Board 3rd Floor 24 LF 7 borage/ Closet 3rd Floor 6 SF 7	ghting - Lay-in 3rd Floor 12 EA 7 6-10 years arker Board 3rd Floor 24 LF 7 6-10 years arker Board 6 SF 7 10+ years arker Board 560 SF 6 10+ years arker Board 550 SF 6 10+ years arker Board 520 SF 6 10+ years arker Board 520 SF 6 10+ years arker Board 6 SF 7 10+ years arker Board 6 SF 7 10+ years arker Board 7 SF 6 10+ years arker Board 7 SF 6 10+ years arker Board 7 SF 6 10+ years arker Board 7 SF 7 10+ years arker Board



Catego	ry : Classroom		В	uilding	: Main		1 3 Mackinaw Avenue, Chicago, iL 60617
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classroo	om #305 (Store Room)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	885	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	10	SF	4	1-2 years	Water damage
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
_Classroo	om #306 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
_Classroo	om #307 (Regular Classroom)						
'	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
Classroo	om #308 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	865	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	865	SF	6	10+ years	
						·	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
Classroo	m #309 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	907	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	8	SF	4	1-2 years	Water damage
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
				SF		-	
	Floor - Tile	3rd Floor 3rd Floor	915	SF EA	6 7	10+ years	
	Lighting - Lay-in		12			6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	856	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	243	SF	6	10+ years	
Classroo	om #310 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	893	SF	6	10+ years	
	Floor - Tile	3rd Floor	2	SF	5	1-2 years	Chipped
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
Classroo	om #311 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Side-lite Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile		895	SF	6		
		3rd Floor			-	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
0	N T	Laartian	0		D !-	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #312 (Art Room)						
	Casework	3rd Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,143	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	20	SF	4	0-1 year	Water damage
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	Trator damage
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,163	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	122	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	778	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	484	SF	6	10+ years	
	Work Sink	3rd Floor	404	SF EA	7		
	WORK SILIK	31d F1001	2	EA	,	10+ years	
Classroo	om #313 (Other Instructional Use)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	893	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	2	SF	4	1-2 years	Water damage
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	ŭ
	Doors - Transom Window	3rd Floor	1	SF	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
	walls - Flastel/Drywall	314 F1001	320	SI	O	10+ years	
Classroo	om #314 (Regular Classroom)						
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	895	SF	6	10+ years	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	895	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years	
Classes -							
Classion	om #315 (Regular Classroom)	Ord Floor	50			40	
	Casework	3rd Floor	58	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	874	SF	6	10+ years	



Category : Classroom		В	uilding	: Main				
				_		Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	3rd Floor	16	SF	4	1-2 years	Water damage	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	· ·	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	890	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	6	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	560	SF	6	10+ years		
			520					
	Walls - Plaster/Drywall	3rd Floor	520	SF	6	10+ years		
lassroc	om #316 (Regular Classroom)							
	Casework	3rd Floor	58	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	907	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	8	SF	4	0-1 year	Water damage	
	Doors - Side-lite	3rd Floor	8	SF	6	10+ years	Trate: damage	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years		
	Floor - Tile	3rd Floor	915	SF	6	•		
						10+ years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Storage/ Closet	3rd Floor	6	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	856	SF	6	10+ years		
	Walls - Plaster/Drywall	3rd Floor	243	SF	6	10+ years		
Classroc	om #918 (Regular Classroom)							
	Casework	1st Floor	20	LF	6	10+ years		
	Ceiling - Lay-in	1st Floor	745	SF	6	10+ years		
	Doors - Side-lite	1st Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years		
	Floor - Tile	1st Floor	743	SF	6	•		
				SF SF		10+ years	Crackad	
	Floor - Tile	1st Floor	2		5	0-1 year	Cracked	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Storage/ Closet	1st Floor	36	SF	7	10+ years		
	Walls - Concrete Block	1st Floor	576	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	514	SF	6	10+ years		
Catego	ry : Interior		В	uilding	: Main			
		1		11617		Recommend		
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Corridor	Ceiling - Lay-in	1st Floor	7,840	SF	6	10+ years		
			•		6	•		
	Doors - Side-lite	1st Floor	28	SF	6	10+ years		
	Doors - Steel Doors incl hw	1st Floor	6	EA	6	10+ years		



Catego	ry : Interior		В	uilding	: Main		1 6 Mackillaw Avenue, Officago, ie 60017
	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Store Front	1st Floor	4	EA	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	7,340	SF	5	2-5 years	Sagging
	Floor - Tile/Sheet	1st Floor	500	SF	5	10+ years	
	Lighting - Lay-in	1st Floor	190	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	9,639	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	6,580	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	6	EA	6	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	6,580	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	170	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	7,654	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	6,548	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	32	SF	4	0-1 year	Water damage
	Doors - Steel Doors incl hw	3rd Floor	6	EA	6	10+ years	•
	Drinking Fountains - Double Fountain	3rd Floor	2	EA	7	10+ years	
	Floor - Terrazzo	3rd Floor	6,580	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	170	EA	7	6-10 years	
	Walls - Concrete Block	3rd Floor	7,654	SF	6	10+ years	
Safety							
	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	16	EA	7	6-10 years	
Stairs							
_Olalis	Ceiling - Lay-in	Stair#1	314	SF	6	10+ years	
	Floor - Terrazzo	Stair#1	520	SF	7	10+ years	
	Handrails	Stair#1	112	LF	7	10+ years	
	Lighting - Lay-in	Stair#1	6	EA	6	6-10 years	
	Stairs - Terrazzo	Stair#1	448	LF	7	10+ years	
	Walls - Concrete Block	Stair#1	860	SF	6	10+ years	
	Ceiling - Lay-in	Stair#2	219	SF	6	10+ years	
	Floor - Terrazzo	Stair#2	420	SF	7	10+ years	
	Handrails	Stair#2	112	LF	7	10+ years	
	Lighting - Lay-in	Stair#2	6	EA	6	6-10 years	
	Stairs - Terrazzo	Stair#2	448	LF	7	10+ years	
	Walls - Structural Glazed Tile	Stair#2	760	SF	6	6-10 years	
	Ceiling - Lay-in	Stair#3	302	SF	6	10+ years	
	Ceiling - Lay-in	Stair#3	12	SF	4	0-1 year	Water damage
	Floor - Terrazzo	Stair#3	520	SF	7	10+ years	Trator damage
	Handrails	Stair#3	112	LF	7	10+ years	
	Lighting - Lay-in	Stair#3	6	EA	6	6-10 years	
	3 · 3, ···	- · · · · · ·	·		-	, ,	



Category : Interior			В	Building : Main					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
	Stairs - Terrazzo Walls - Concrete Block	Stair#3 Stair#3	448 860	LF SF	7 6	10+ years 10+ years			
Vertical	Vertical Conveyance								
	Elevator - Hydraulic Elevator	1st Floor	1	EA	6	10+ years			

Campus Name: New Sullivan Page : 35 of 39 Assessment Date: 04/22/2024





Category : Site **Building: Site**

Calego	ry . Site		ь	unamg	. Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	7	EA	6	10+ years	
	Olvii, Brainage Olic Marinole	Little Oile	•	L/ \	O	101 years	
Fencing	Familia w Navy Otan dand One an antal	Fatina Oita	0.005			40	
	Fencing - New Standard Ornamental	Entire Site	3,005	LF	6	10+ years	
Landsca	20						
_anusca	Benches	Entire Site	18	EA	6	10+ years	
	Benches	Entire Site	10	EA	4	1-2 years	Deteriorated
	Landscape - Grass	Entire Site	51,475	SF	6	10+ years	Deteriorated
		Entire Site		SF	7		
	Landscape - Hardscape- Concrete		60	SF SF	=	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	5,355		6	10+ years	
	Lighting - Pole Mounted	Entire Site	4	EΑ	7	10+ years	
	Parkway trees	Entire Site	44	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	5,005	SF	6	10+ years	
	Trash Receptacles	Entire Site	1	EA	6	10+ years	
Parking I	ot						
<u> </u>	Concrete Curbs	East	1,158	LF	7	10+ years	
	Interior Plantings	East	1,100	LF	6	6-10 years	
	Lighting - Pole Mounted	East	5	EA	7	10+ years	
	Surface - Asphalt	East	20,885	SF	5	2-5 years	
	Surface - Asphalt	East	9,000	SF	4	0-1 year	Holes, spalling
	Trash Compactor	East	9,000	EA	6	10+ years	Holes, spalling
	Trash Enclosure - Masonry	East	3,150	SF	7	10+ years	
	Trasif Efficiosure - Masority	Lasi	3,130	SF	,	10+ years	
Playgrou	nd						
	Equipment - Pre K 3-5	SE Site	1	EA	6	6-10 years	
	Equipment - School Age 5-12	SE Site	1	EA	6	6-10 years	
	Surface - Poured Surface	SE Site	5,000	SF	6	6-10 years	
Sidewalk				. –		0.10	
	Sidewalks - Internal Walks	Entire Site	1,215	LF	6	6-10 years	
	Sidewalks - Perimeter Sidewalks	Entire Site	13,020	SF	6	6-10 years	
Signage							
Armaga	Flag Pole - Flag Pole	NW corner of site	1	EA	7	10+ years	
	Marquee - Building Mounted Back Lighted	NW corner of site	1	EA	7	10+ years	
	Marquee - Building Mounted Back Lighted Marquee - Building Mounted Back Lighted	NW corner of site	1	EA	7	10+ years	
	w/ LED	1444 COLLICE OF SILE	'	L /\	,	TOT years	
	229						



William K New Sullivan Elementary School

Recommend

8331 S Mackinaw AVENUE, Chicago, IL 60617

Category : Site Building : Site

Group Item - Type Location Quantity UOM Rank Replacement Comments

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: New Sullivan Page : 37 of 39 Assessment Date: 04/22/2024



Classroom Summary

Classroom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Art Room	3rd Floor	312	3-24	1,163	119	23	Υ	N
Band Room	Band Room	1st Floor	107	1-13	2,075	360	26	Y	N
Computer Lab	Computer Lab	2nd Floor	216	2-31	1,197	119	23	Y	Υ
Covid Care Room	Regular Classroom	1st Floor	123	1-79	873	120	12	Y	N
Faculty Lounge	Regular Classroom	1st Floor	124	1-60	875	120	12	Υ	N
Kindergarten	Regular Classroom	1st Floor	115	1-42	895	89	17	Υ	N
Kindergarten	Regular Classroom	1st Floor	118	1-50	1,104	89	17	Υ	N
Office	Regular Classroom	2nd Floor	205	2-10	456	80	8	Υ	N
Office	Regular Classroom	2nd Floor	206	2-10	543	80	8	Υ	N
Office	Regular Classroom	2nd Floor	207	2-12	543	80	8	Υ	N
Other Instructional Use	Regular Classroom	3rd Floor	313	3-27	895	89	17	Υ	N
Pre School	Kindergarten	1st Floor	119	1-53	1,104	120	12	Υ	N
Pre School	Pre School	1st Floor	114	1-39	1,052	89	17	Υ	N
Regular Classroom	Art Room	1st Floor	133	1-33	895	89	17	Υ	N
Regular Classroom	Regular Classroom	1st Floor	112	1-36	895	89	17	Υ	N
Regular Classroom	Regular Classroom	1st Floor	117	1-47	1,104	89	17	Υ	N
Regular Classroom	Regular Classroom	1st Floor	120	1-56	1,080	120	8	Υ	N
Regular Classroom	Regular Classroom	1st Floor	918	1-18	745	120	8	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201	2-06	871	120	12	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	202	2-07	915	120	12	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	203	2-08	915	120	12	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	208	2-13	895	120	12	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	209	2-14	871	120	12	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	210	2-22	915	89	17	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	217	2-33	456	59	11	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	218	2-35	456	59	11	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	219	2-37	456	59	11	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	301	3-07	873	89	17	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	302	3-08	895	89	17	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	303	3-09	895	89	17	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	3-10	890	89	17	Υ	Υ
Regular Classroom	Regular Classroom	3rd Floor	306	3-12	895	89	17	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	307	3-13	895	89	17	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	308	3-14	865	89	17	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	309	3-21	915	89	17	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	310	3-22	895	89	17	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	311	3-23	895	89	17	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	314	3-28	895	89	17	Υ	N



Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	3rd Floor	315	3-29	890	89	17	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	316	3-30	915	89	17	Υ	N
Science Classroom	Science Classroom	2nd Floor	211	2-24	1,200	119	23	Y	N
Store Room	Regular Classroom	2nd Floor	204	2-09	871	120	12	Y	N
Store Room	Regular Classroom	3rd Floor	305	3-11	895	89	17	Υ	N

Campus Name: New Sullivan Page : 39 of 39 Assessment Date: 04/22/2024