

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <http://www.cps.edu/facilityassessment>.

| Campus Summary | | | |
|----------------|------------------|------------------|-----------------------|
| BuildingName | Year Constructed | Number of Floors | Building Area (Sq Ft) |
| Main | 1981 | 3 | 73,518 |
| Campus Total | | | 73,518 |

Category : Exterior

Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------|--------------------------------------|------------------|----------|-----|------|-----------------------|-------------------------|
| Entrance | | | | | | | |
| | Entrance Control - Audio and Video | 1 west | 1 | EA | 6 | 2-5 years | |
| | Exterior Doors - Exterior FRP Door | 1 west | 2 | EA | 6 | 6-10 years | |
| | Exterior Doors - Side lite | 1 west | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Transom Lite | 1 west | 2 | EA | 6 | 6-10 years | |
| | Power Door Operator and Controls | 1 west | 1 | EA | 7 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 10 Roof C Access | 1 | EA | 7 | 10+ years | |
| | Exterior Stairs - Steel or Aluminum | 10 Roof C Access | 3 | LF | 5 | 2-5 years | Surface rust, verified |
| | Exterior Doors - Exterior FRP Door | 2 west | 2 | EA | 6 | 6-10 years | |
| | Exterior Doors - Side lite | 2 west | 1 | EA | 6 | 6-10 years | |
| | Exterior Doors - Transom Lite | 2 west | 2 | EA | 6 | 6-10 years | |
| | Entrance Control - Audio and Video | 3 east | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | 3 east | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Side lite | 3 east | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | 3 east | 2 | EA | 7 | 10+ years | |
| | Power Door Operator and Controls | 3 east | 1 | EA | 7 | 6-10 years | |
| | Exterior Doors - Exterior FRP Door | 4 east | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Side lite | 4 east | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | 4 east | 2 | EA | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 5 north | 2 | EA | 6 | 6-10 years | |
| | Exterior Doors - Exterior Steel Door | 6 south | 2 | EA | 6 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 7 southwest | 2 | EA | 4 | 1-2 years | Corroded door and frame |
| | Exterior Doors - Exterior FRP Door | 8 east | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Transom Lite | 8 east | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Exterior FRP Door | 8a East | 1 | EA | 7 | 10+ years | |

Category : Exterior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------|---|-----------------|----------|-----|------|-----------------------|---|
| | Exterior Doors - Transom Lite | 8a East | 1 | EA | 7 | 10+ years | |
| | Exterior Doors - Exterior Steel Door | 9 southeast | 2 | EA | 6 | 6-10 years | |
| Foundation | | | | | | | |
| | Foundation - Concrete | Entire Building | 607 | LF | 7 | 10+ years | Unable to see the foundation CMU is cracked in all stair halls, gym and some classrooms indicating settlement of foundation |
| | Foundation - Concrete | Entire Building | 50 | LF | 5 | 10+ years | |
| | Superstructure - Metal Deck/ Concrete Topping | Entire Building | 73,518 | SF | 7 | 10+ years | |
| Lighting | | | | | | | |
| | Exterior Lighting - Wall Mounted | Entire Building | 26 | EA | 7 | 10+ years | New |
| | Exterior Lighting - Wall Mounted | Entire Building | 10 | EA | 6 | 6-10 years | |
| Roof System | | | | | | | |
| | Coping - Metal | Roof A | 65 | LF | 7 | 10+ years | Roof is showing signs of blistering Corroded hatch |
| | Roof - Modified Bitumen | Roof A | 1,394 | SF | 5 | 2-5 years | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Roof A | 1,394 | SF | 7 | 10+ years | |
| | Access Ladder - Metal | Roof B | 1 | EA | 7 | 10+ years | |
| | Coping - Metal | Roof B | 742 | LF | 6 | 10+ years | |
| | Downspouts - Interior Downspouts | Roof B | 395 | LF | 7 | 10+ years | |
| | Parapet - Parapet < 16" Height | Roof B | 759 | LF | 7 | 10+ years | |
| | Parapet - Parapet < 16" Height | Roof B | 58 | LF | 6 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | Roof B | 20,392 | SF | 6 | 6-10 years | |
| | Roof Hatch - Metal | Roof B | 1 | EA | 4 | 1-2 years | |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Roof B | 20,392 | SF | 7 | 10+ years | |
| | Coping - Metal | Roof C | 80 | LF | 7 | 10+ years | |
| | Downspouts - Interior Downspouts | Roof C | 47 | LF | 7 | 10+ years | |
| | Downspouts - Interior Downspouts | Roof C | 5 | LF | 5 | 1-2 years | |
| | Parapet - Parapet < 16" Height | Roof C | 80 | LF | 7 | 10+ years | |
| | Roof - Asphalt Gravel Ballast | Roof C | 4,080 | SF | 6 | 10+ years | damaged drain, homemade repair |
| | Roof Structure - Steel / Metal Deck/ Concrete Topping | Roof C | 4,080 | SF | 7 | 10+ years | |
| Walls | | | | | | | |
| | Exterior Walls - Brick | Entire Building | 29,980 | SF | 6 | 10+ years | Corrected quantity. Open joints, cracked brick. Previous deficiencies repaired Verified that Stucco has certain imperfections like dimples and is |
| | Exterior Walls - Brick | Entire Building | 10 | SF | 4 | 0-1 year | |
| | Exterior Walls - Stucco | Entire Building | 7,045 | SF | 6 | 6-10 years | |

Category : Exterior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-------------|----------|----------|-----|------|-----------------------|---|
| | | | | | | | generally in fair good condition. Consolidated numbers |

Windows

| | | | | | |
|---|-----------------|-------|----|---|-----------|
| Clerestory - Glass Double-Pane | Entire Building | 213 | SF | 7 | 10+ years |
| Guard - Guards perforated | Entire Building | 28 | SF | 7 | 10+ years |
| Lintels - Steel | Entire Building | 700 | LF | 6 | 10+ years |
| Windows - Casement Aluminum Double-pane | Entire Building | 3,652 | SF | 7 | 10+ years |
| Windows - Casement Lexan | Entire Building | 399 | SF | 7 | 10+ years |
| Windows - Louver | Entire Building | 83 | SF | 6 | 2-5 years |

Category : Electrical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------------|--|-----------------|----------|-----|------|-----------------------|--------------------------------|
| <u>Emergency System</u> | | | | | | | |
| | Automatic Transfer Switch | Electrical Room | 1 | EA | 6 | 6-10 years | |
| | Security System - CCTV | Entire Building | 73,518 | SF | 6 | 6-10 years | Poor coverage |
| | Security System - Intrusion Detection | Entire Building | 73,518 | SF | 6 | 6-10 years | Replace non-functional devices |
| | Exit Signs - Corridors and Stairs | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Exit Signs - Corridors and Stairs | Entire Building | 24 | EA | 6 | 6-10 years | |
| | Exit Signs - Gym | Entire Building | 2 | EA | 6 | 6-10 years | |
| | Exit Signs - Multipurpose Room | Entire Building | 5 | EA | 6 | 10+ years | |
| | Emergency Battery Packs - Corridors and Stairs | Entire Building | 15 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Gym | Entire Building | 4 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Multipurpose Room | Entire Building | 4 | EA | 6 | 6-10 years | |
| | Emergency Battery Packs - Students Toilets | Entire Building | 6 | EA | 6 | 6-10 years | |
| | Emergency A/C Power - Corridors and Stairs | Entire Building | 8,889 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Gym | Entire Building | 4,432 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Lunchrooms | Entire Building | 5,856 | SF | 6 | 6-10 years | |
| | Emergency A/C Power - Students Toilets | Entire Building | 1,310 | SF | 6 | 6-10 years | |

Main Service

| | | | | | | |
|--|-----------------|--------|----|---|------------|-------------------------------|
| Main Electrical Service - 1600 A 277/480/3PH | Electrical Room | 1 | EA | 6 | 6-10 years | |
| Independent Electrical Service for emergency power | Electrical Room | 1 | EA | 6 | 6-10 years | |
| PA System | Entire Building | 73,518 | SF | 6 | 6-10 years | Recently maintained/repaired. |

Power Distribution

Category : Electrical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|--|-----------------|----------|-----|------|-----------------------|---|
| | Lighting and Power Panels - 100 A | Entire Building | 5 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - 100 A | Entire Building | 1 | EA | 7 | 10+ years | EM panel in mech room |
| | Lighting and Power Panels - Above 100 A | Entire Building | 3 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 5 | EA | 7 | 10+ years | |
| | Lighting and Power Panels - Above 100 A | Entire Building | 1 | EA | 3 | 1-2 years | Panel WH has live front condition due to missing breakers |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 3 | EA | 7 | 10+ years | Quantity updated to reflect observed conditions |
| | Main Distribution Panels - 400 - 600 amp | Entire Building | 3 | EA | 7 | 10+ years | |
| | Transformers - 277/480 - 120/208 | Entire Building | 3 | EA | 7 | 10+ years | |
| | Transformers - 277/480 - 120/208 | Entire Building | 1 | EA | 7 | 10+ years | |
| | Transformers - 277/480 - 120/208 | Entire Building | 4 | EA | 6 | 6-10 years | |

Category : Fire Protection
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------|--------------------------|-----------------|----------|-----|------|-----------------------|----------|
| <u>Fire Alarm</u> | | | | | | | |
| | Fire ALarm Anunciator | Entire Building | 1 | EA | 7 | 10+ years | |
| | Fire Alarm Panel | Entire Building | 1 | EA | 7 | 10+ years | |
| | Fire Alarm Strobe Lights | Entire Building | 73,518 | SF | 7 | 10+ years | |
| | Fire Alarm_System | Entire Building | 73,518 | SF | 7 | 10+ years | |

Category : Mechanical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------------------|--|------------|----------|-----|------|-----------------------|---|
| <u>Air Conditioning</u> | | | | | | | |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 7 | 2-5 years | 2023 installation, serves MDF room |
| | Condensing Unit- Roof Mounted - Less than 5 tons | Roof | 1 | EA | 2 | 0-1 year | Abandoned in place no longer functional |
| | Chiller-Air Cooled-Screw Type-Ground Mounted - 201 - 300 tons | Site South | 1 | EA | 6 | 6-10 years | |
| | Pipes - Chilled Water Pipe- Steel | Site South | 450 | LF | 6 | 10+ years | |
| <u>Air Handling Systems</u> | | | | | | | |
| | Air Handling Unit- Built Up- Single Zone- Dual Temperature Coils - 4000 - 8000 cfm | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Air Intake | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Auxiliaries - 15001 - 25000 cfm | 1st Floor | 1 | EA | 6 | 6-10 years | |
| | Return Duct Work - Indoor- Vertical Shaft and Ducts | 1st Floor | 50 | LF | 6 | 10+ years | |
| | Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 20001- | 2nd Floor | 1 | EA | 5 | 6-10 years | |

Category : Mechanical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------------------------|--|-----------------|----------|-----|------|-----------------------|---|
| | 30000 cfm | | | | | | |
| | Air Intake | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 20001-30000 cfm | 3rd Floor | 1 | EA | 5 | 6-10 years | |
| | Air Intake | 3rd Floor | 1 | EA | 5 | 10+ years | |
| | Make Up Air Unit- Indoor Mounted- Hot Water Coils - Less than 6000 cfm | Entire Building | 2 | EA | 5 | 6-10 years | |
| | Fan Coil Unit- Celing Mounted - Dual Temperature Coil | Entire Building | 33 | EA | 4 | 2-5 years | Located above ceilings, more than 40 years old, |
| Boiler Systems | | | | | | | |
| | Boiler Auxiliary- Condensing Hot Water - 2001 - 3000 HP | Boiler Room | 2 | EA | 5 | 6-10 years | |
| | Chemical Pot Feeder | Boiler Room | 1 | EA | 6 | 6-10 years | |
| | Condensing- Hot Water Boiler - 2001 - 3000 MBH | Boiler Room | 2 | EA | 6 | 6-10 years | B-1 does not have proper control over its combustion fan, cycles continuously |
| | Glycol Feed System | Boiler Room | 1 | EA | 5 | 6-10 years | Manually fed |
| | Water Fill System | Boiler Room | 1 | EA | 6 | 10+ years | |
| Heating Devices | | | | | | | |
| | Fin Tube - Electric | Entire Building | 47 | LF | 6 | 6-10 years | |
| | Unit Heater - Electric | Entire Building | 4 | EA | 5 | 6-10 years | Quantity updated to reflect observed conditions |
| | Cabinet Heaters - With Electric Coil | Entire Building | 5 | EA | 4 | 1-2 years | Some repairs have been made, units original to building |
| Mechanical Plumbing | | | | | | | |
| | Hydronic Supply and Return - Steel | Entire Building | 600 | LF | 6 | 10+ years | |
| | Dual Temperature Pump - Less than 10 | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Dual Temperature Pump - Less than 10 | Mechanical Room | 1 | EA | 6 | 6-10 years | |
| | Dual Temperature Pump - Less than 10 | Mechanical Room | 1 | EA | 6 | 6-10 years | Return pump previously categorized as chilled water pump |
| | Dual Temperature Pump - Less than 10 | Mechanical Room | 1 | EA | 6 | 6-10 years | Return pump previously categorized as chilled water pump |
| Temperature Control | | | | | | | |
| | DDC System | Entire Building | 73,518 | SF | 6 | 6-10 years | |
| | Electric Thermostat | Entire Building | 3 | EA | 5 | 6-10 years | Serve exhaust fan and room 101, MDF room |
| | Thermostats - DDC | Entire Building | 33 | EA | 6 | 6-10 years | Recent work getting temperature sensors connected to BAS |

Category : Mechanical
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------------------------|--|-----------------|----------|-----|------|-----------------------|----------|
| Unit Ventilation | | | | | | | |
| | Unit Ventilators- Ceiling Mounted- Dual Temperature Coils (Hot/Chilled) Water | 1st Floor | 1 | EA | 5 | 6-10 years | |
| | Unit Ventilators- Floor Mounted- Electric Heating & DX Cooling Coil W/ Self Contained Compressor | Entire Building | 1 | EA | 6 | 10+ years | |

Ventilation

| | | | | | | | |
|--|--|-----------------|---|----|---|------------|--|
| | Exhaust Fans- Indoor - 500 - 1500 CFM | Entire Building | 1 | EA | 5 | 6-10 years | Ceiling mounted in-line fan serves mechanical room |
| | Exhaust Fans- Indoor - Less than 500 CFM | Entire Building | 1 | EA | 6 | 6-10 years | |
| | Exhaust Fans- Indoor - Less than 500 CFM | Entire Building | 7 | EA | 6 | 6-10 years | Mounted in ceilings and only accessible through ceiling access panels. |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 5 | EA | 6 | 6-10 years | Quantity segregated to reflect observed conditions |
| | Exhaust Fans- Roof Mounted - 500 - 1500 CFM | Entire Building | 1 | EA | 5 | 0-1 year | Missing cover, still functioning |
| | Exhaust Fans- Roof Mounted - Greater than 8000 CFM | Entire Building | 2 | EA | 6 | 6-10 years | |

Category : Plumbing
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|------------------|---|-----------------|----------|-----|------|-----------------------|--|
| Hot Water | | | | | | | |
| | Electric Heater - Less than 20 KW | Mechanical Room | 1 | EA | 5 | 6-10 years | Vintage but functional |
| | Electric Heater - Less than 20 KW | Mechanical Room | 1 | EA | 5 | 6-10 years | Serves janitor closet located in boiler room |
| Piping | | | | | | | |
| | Domestic Piping-Hot Water Return Lines | Entire Building | 73,518 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water Return Risers | Entire Building | 73,518 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot Water from Risers to Fixtures | Entire Building | 73,518 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot/Cold Water Supply (Horizontal Lines) | Entire Building | 73,518 | SF | 6 | 6-10 years | |
| | Domestic Piping-Hot/Cold Water Supply (Risers) | Entire Building | 73,518 | SF | 6 | 10+ years | |
| | Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures) | Entire Building | 73,518 | SF | 6 | 6-10 years | |
| | Sanitary Piping | Entire Building | 73,518 | SF | 5 | 6-10 years | |
| | Storm Piping | Entire Building | 73,518 | SF | 6 | 6-10 years | |

Category : Plumbing
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-------------|-----------------|----------|-----|------|-----------------------|----------|
| | Vent Piping | Entire Building | 73,518 | SF | 6 | 6-10 years | |

Pumps

| | | | | | | |
|--------------------------------------|-----------------|---|----|---|------------|---|
| Pumps - Domestic Booster Pump-Duplex | Mechanical Room | 1 | EA | 3 | 1-2 years | 1981 installation, abandoned in place non-functional not required |
| Pumps - Sump-Simplex | Mechanical Room | 1 | EA | 5 | 6-10 years | Located under elevator inaccessible at time of assessment |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-------------|----------|----------|-----|------|-----------------------|----------|
|-------|-------------|----------|----------|-----|------|-----------------------|----------|

Administrative Suites/Offices

| | | | | | | |
|-----------------------------|-----------------------------------|-----|----|---|------------|-------------------------|
| Ceiling - Lay-in | 100 Main Office | 480 | SF | 6 | 10+ years | small stained area |
| Doors - Side-lite | 100 Main Office | 140 | SF | 7 | 10+ years | |
| Doors - Transom Window | 100 Main Office | 40 | SF | 7 | 10+ years | |
| Doors - Wood Doors inclu hw | 100 Main Office | 2 | EA | 6 | 10+ years | |
| Floor - Tile | 100 Main Office | 480 | SF | 6 | 10+ years | |
| Lighting - Lay-in | 100 Main Office | 9 | EA | 7 | 10+ years | |
| Power Distribution | 100 Main Office | 145 | EA | 7 | 10+ years | |
| Storage/ Closet | 100 Main Office | 25 | SF | 7 | 10+ years | |
| Walls - Concrete Block | 100 Main Office | 612 | SF | 7 | 10+ years | |
| Ceiling - Lay-in | 100A Assistant Principal's Office | 250 | SF | 6 | 10+ years | |
| Doors - Wood Doors inclu hw | 100A Assistant Principal's Office | 1 | EA | 7 | 10+ years | |
| Floor - Tile | 100A Assistant Principal's Office | 250 | SF | 6 | 6-10 years | |
| Lighting - Lay-in | 100A Assistant Principal's Office | 4 | EA | 7 | 10+ years | |
| Power Distribution | 100A Assistant Principal's Office | 8 | EA | 7 | 10+ years | |
| Storage/ Closet | 100A Assistant Principal's Office | 40 | SF | 7 | 10+ years | |
| Walls - Concrete Block | 100A Assistant Principal's Office | 522 | SF | 7 | 10+ years | |
| Ceiling - Lay-in | 100D Principal's Office | 312 | SF | 6 | 10+ years | |
| Doors - Wood Doors inclu hw | 100D Principal's Office | 1 | EA | 7 | 10+ years | |
| Floor - Tile | 100D Principal's Office | 312 | SF | 7 | 6-10 years | |
| Lighting - Lay-in | 100D Principal's Office | 6 | EA | 7 | 10+ years | |
| Power Distribution | 100D Principal's Office | 6 | EA | 7 | 10+ years | |
| Walls - Concrete Block | 100D Principal's Office | 666 | SF | 7 | 10+ years | |
| Ceiling - Lay-in | 100F Main office workroom | 195 | SF | 6 | 10+ years | |
| Doors - Steel Doors incl hw | 100F Main office workroom | 1 | EA | 7 | 10+ years | |
| Floor - Tile | 100F Main office workroom | 195 | SF | 6 | 10+ years | |
| Lighting - Lay-in | 100F Main office workroom | 2 | EA | 7 | 10+ years | |
| Power Distribution | 100F Main office workroom | 6 | EA | 7 | 10+ years | Not previously assessed |
| Walls - Concrete Block | 100F Main office workroom | 504 | SF | 7 | 10+ years | |
| Work Sink | 100F Main office workroom | 1 | EA | 7 | 10+ years | |
| Ceiling - Lay-in | 100I Conference Room | 892 | SF | 6 | 10+ years | |
| Doors - Wood Doors inclu hw | 100I Conference Room | 2 | EA | 7 | 10+ years | |
| Floor - Carpet | 100I Conference Room | 892 | SF | 6 | 6-10 years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-----------------------------|----------------------------|----------|-----|------|-----------------------|-------------------------|
| | Lighting - Lay-in | 100I Conference Room | 13 | EA | 7 | 10+ years | |
| | Power Distribution | 100I Conference Room | 22 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 100I Conference Room | 1,170 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 120/124 copy room | 120 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 120/124 copy room | 63 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 120/124 copy room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 120/124 copy room | 120 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 120/124 copy room | 2 | EA | 7 | 10+ years | |
| | Power Distribution | 120/124 copy room | 4 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 120/124 copy room | 256 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 121 gym office | 180 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 121 gym office | 16 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 121 gym office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 121 gym office | 180 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 121 gym office | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 121 gym office | 8 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 121 gym office | 468 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 213A Library Office | 110 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 213A Library Office | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 213A Library Office | 110 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 213A Library Office | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 213A Library Office | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 213A Library Office | 340 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 213B Library Resource Room | 236 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 213B Library Resource Room | 16 | SF | 5 | 2-5 years | Ceiling tiles missing |
| | Doors - Side-lite | 213B Library Resource Room | 48 | SF | 7 | 10+ years | Not previously assessed |
| | Doors - Steel Doors incl hw | 213B Library Resource Room | 1 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 213B Library Resource Room | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | 213B Library Resource Room | 252 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 213B Library Resource Room | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | 213B Library Resource Room | 6 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 213B Library Resource Room | 332 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 213B Library Resource Room | 248 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 220 Work Room | 520 | SF | 6 | 6-10 years | |
| | Doors - Wood Doors inclu hw | 220 Work Room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 220 Work Room | 520 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 220 Work Room | 9 | EA | 6 | 6-10 years | |
| | Power Distribution | 220 Work Room | 10 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 220 Work Room | 800 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 316 Dean's Office | 110 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 316 Dean's Office | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | 316 Dean's Office | 110 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 316 Dean's Office | 2 | EA | 7 | 6-10 years | |
| | Power Distribution | 316 Dean's Office | 2 | EA | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|-----------------------------|--------------------------|----------|-----|------|-----------------------|--|
| | Walls - Concrete Block | 316 Dean's Office | 270 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Engineer's Office | 208 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Engineer's Office | 8 | SF | 5 | 1-2 years | Stained |
| | Doors - Wood Doors inclu hw | Engineer's Office | 2 | EA | 6 | 10+ years | |
| | Floor - Concrete | Engineer's Office | 108 | SF | 7 | 10+ years | |
| | Floor - Tile | Engineer's Office | 108 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | Engineer's Office | 4 | EA | 7 | 6-10 years | |
| | Power Distribution | Engineer's Office | 6 | EA | 7 | 10+ years | |
| | Storage/ Closet | Engineer's Office | 108 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | Engineer's Office | 832 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Kitchen manager's office | 165 | SF | 7 | 10+ years | Quantity updated to match current observations |
| | Doors - Wood Doors inclu hw | Kitchen manager's office | 1 | EA | 7 | 10+ years | |
| | Floor - Concrete | Kitchen manager's office | 167 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | Kitchen manager's office | 4 | EA | 7 | 10+ years | |
| | Power Distribution | Kitchen manager's office | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Kitchen manager's office | 416 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Library Work Room | 272 | SF | 6 | 10+ years | |
| | Doors - Side-lite | Library Work Room | 156 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Library Work Room | 1 | EA | 7 | 10+ years | |
| | Floor - Carpet | Library Work Room | 272 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | Library Work Room | 6 | EA | 6 | 6-10 years | |
| | Power Distribution | Library Work Room | 22 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Library Work Room | 264 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Library Work Room | 450 | SF | 6 | 10+ years | |

Gymnasias

| | | | | | | | |
|--|---|-----------|-------|----|---|-----------|--|
| | Ceiling - Exposed | 1st Floor | 4,432 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 5 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 4,432 | SF | 6 | 10+ years | |
| | Lighting - Metal Halide/ High Pressure Sodium | 1st Floor | 12 | EA | 6 | 10+ years | Rank updated to match current observations |
| | Storage/ Closet | 1st Floor | 432 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 7,500 | SF | 6 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 50 | SF | 5 | 0-1 year | Cracked |

Kitchen

| | | | | | | | |
|--|-----------------------------|-----------|-------|----|---|-----------|---------------|
| | Ceiling - Lay-in | 1st Floor | 734 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 32 | SF | 5 | 1-2 years | Missing tiles |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | 1st Floor | 766 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 10 | EA | 7 | 10+ years | |
| | Serving Line | 1st Floor | 10 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,000 | SF | 6 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------------------------------------|-----------------------------|-------------------|----------|-----|------|-----------------------|-------------------------|
| <u>Library</u> | | | | | | | |
| | Casework | Library 2nd Floor | 120 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | Library 2nd Floor | 2,080 | SF | 6 | 10+ years | |
| | Doors - Side-lite | Library 2nd Floor | 80 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | Library 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | Library 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | Library 2nd Floor | 2,080 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | Library 2nd Floor | 35 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | Library 2nd Floor | 783 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | Library 2nd Floor | 640 | SF | 6 | 10+ years | |
| <u>Lunch & Multipurpose Room</u> | | | | | | | |
| | Ceiling - Lay-in | 1st Floor | 2,880 | SF | 6 | 10+ years | |
| | Ceiling - Plaster/Drywall | 1st Floor | 2,976 | SF | 6 | 10+ years | |
| | Doors - Side-lite | 1st Floor | 200 | SF | 7 | 10+ years | Not previously assessed |
| | Doors - Store Front | 1st Floor | 10 | EA | 7 | 10+ years | Not previously assessed |
| | Doors - Transom Window | 1st Floor | 60 | SF | 7 | 10+ years | Not previously assessed |
| | Doors - Wood Doors inclu hw | 1st Floor | 4 | EA | 7 | 10+ years | Not previously assessed |
| | Floor - Tile | 1st Floor | 5,806 | SF | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 50 | SF | 5 | 1-2 years | Worn and cracked |
| | Lighting - Lay-in | 1st Floor | 67 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 2,106 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 1st Floor | 450 | SF | 6 | 6-10 years | |
| <u>MDF_IDE</u> | | | | | | | |
| | Doors - Steel Doors incl hw | In Room 314 | 1 | EA | 7 | 10+ years | |
| | Finishes | In Room 314 | 140 | SF | 7 | 6-10 years | |
| | Other Cooling Unit | In Room 314 | 1 | EA | 7 | 6-10 years | Ductless split |
| <u>Mechanical/ Service Rooms</u> | | | | | | | |
| | Boiler Room | 1st Floor | 216 | SF | 7 | 10+ years | |
| | Janitor's Closet | 1st Floor | 45 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 380 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 1st Floor | 680 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 1,211 | SF | 7 | 10+ years | |
| | Storage Room | 1st Floor | 1,000 | SF | 7 | 10+ years | |
| | Vaults | 1st Floor | 300 | SF | 7 | 10+ years | |
| | Janitor's Closet | 2nd Floor | 45 | SF | 7 | 10+ years | |
| | Mechanical/ Service Rooms | 2nd Floor | 290 | SF | 7 | 10+ years | |
| | Janitor's Closet | 3rd Floor | 45 | SF | 5 | 10+ years | Water stain on ceiling |
| | Mechanical/ Service Rooms | 3rd Floor | 45 | SF | 7 | 10+ years | Electrical Room |
| | Mechanical/ Service Rooms | 3rd Floor | 290 | SF | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------|---------------------------------|---------------------------------------|----------|-----|------|-----------------------|---------------|
| Restroom | | | | | | | |
| | Accessories | 100I-A in main office conference room | 66 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 100I-A in main office conference room | 66 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 100I-A in main office conference room | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 100I-A in main office conference room | 66 | SF | 6 | 10+ years | |
| | Lavatory | 100I-A in main office conference room | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 100I-A in main office conference room | 1 | EA | 5 | 10+ years | Missing cover |
| | Walls - Concrete Block | 100I-A in main office conference room | 272 | SF | 7 | 10+ years | |
| | Water Closet | 100I-A in main office conference room | 1 | EA | 7 | 10+ years | |
| | Accessories | 121A Gym Office | 25 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 121A Gym Office | 25 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 121A Gym Office | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 121A Gym Office | 25 | SF | 6 | 10+ years | |
| | Lavatory | 121A Gym Office | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 121A Gym Office | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 121A Gym Office | 200 | SF | 7 | 10+ years | |
| | Water Closet | 121A Gym Office | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor 103A | 36 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor 103A | 36 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor 103A | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor 103A | 36 | SF | 6 | 10+ years | |
| | Hand Dryer | 1st Floor 103A | 1 | EA | 7 | 6-10 years | |
| | Lavatory | 1st Floor 103A | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor 103A | 1 | EA | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor 103A | 192 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor 103A | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor 105A | 36 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 1st Floor 105A | 36 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor 105A | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor 105A | 36 | SF | 6 | 10+ years | |
| | Lavatory | 1st Floor 105A | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor 105A | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor 105A | 192 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor 105A | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor boys | 1,874 | SF | 7 | 6-10 years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---------------------------------|-----------------|----------|-----|------|-----------------------|---|
| | Ceiling - Lay-in | 1st Floor boys | 187 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor boys | 187 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor boys | 1 | EA | 7 | 10+ years | |
| | Lavatory | 1st Floor boys | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor boys | 2 | EA | 6 | 10+ years | |
| | Partitions | 1st Floor boys | 1 | EA | 7 | 10+ years | |
| | Urinals | 1st Floor boys | 2 | EA | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor boys | 448 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor boys | 1 | EA | 7 | 10+ years | |
| | Accessories | 1st Floor girls | 187 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 1st Floor girls | 181 | SF | 7 | 10+ years | Type and rank updated to match current observations |
| | Ceiling - Plaster/Drywall | 1st Floor girls | 6 | SF | 5 | 1-2 years | Water damage |
| | Floor - Tile Ceramic/ Porcelain | 1st Floor girls | 187 | SF | 6 | 10+ years | |
| | Floor Drain | 1st Floor girls | 1 | EA | 7 | 10+ years | |
| | Lavatory | 1st Floor girls | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 1st Floor girls | 2 | EA | 7 | 6-10 years | |
| | Partitions | 1st Floor girls | 3 | EA | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 1st Floor girls | 448 | SF | 7 | 10+ years | |
| | Water Closet | 1st Floor girls | 3 | EA | 7 | 10+ years | |
| | Accessories | 2nd floor boys | 234 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd floor boys | 234 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 2nd floor boys | 234 | SF | 6 | 6-10 years | |
| | Floor Drain | 2nd floor boys | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd floor boys | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd floor boys | 3 | EA | 7 | 6-10 years | |
| | Partitions | 2nd floor boys | 3 | EA | 7 | 10+ years | |
| | Urinals | 2nd floor boys | 3 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd floor boys | 560 | SF | 6 | 10+ years | |
| | Water Closet | 2nd floor boys | 3 | EA | 7 | 10+ years | |
| | Accessories | 2nd floor girls | 234 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd floor girls | 222 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd floor girls | 12 | SF | 5 | 1-2 years | Water damage to multiple tiles |
| | Floor - Tile Ceramic/ Porcelain | 2nd floor girls | 234 | SF | 6 | 10+ years | |
| | Floor Drain | 2nd floor girls | 1 | EA | 7 | 10+ years | |
| | Lavatory | 2nd floor girls | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd floor girls | 3 | EA | 7 | 6-10 years | |
| | Partitions | 2nd floor girls | 5 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 2nd floor girls | 560 | SF | 6 | 10+ years | |
| | Water Closet | 2nd floor girls | 5 | EA | 7 | 10+ years | |
| | Accessories | 2nd floor mens | 35 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd floor mens | 29 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd floor mens | 6 | SF | 5 | 1-2 years | Water stain on ceiling |
| | Doors - Wood Doors inclu hw | 2nd floor mens | 1 | EA | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---------------------------------|------------------|----------|-----|------|-----------------------|----------|
| | Floor - Tile | 2nd floor mens | 35 | SF | 6 | 10+ years | |
| | Lavatory | 2nd floor mens | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd floor mens | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd floor mens | 190 | SF | 6 | 10+ years | |
| | Water Closet | 2nd floor mens | 1 | EA | 7 | 10+ years | |
| | Accessories | 2nd floor womens | 35 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 2nd floor womens | 35 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd floor womens | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd floor womens | 35 | SF | 7 | 6-10 years | |
| | Lavatory | 2nd floor womens | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 2nd floor womens | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd floor womens | 190 | SF | 7 | 10+ years | |
| | Water Closet | 2nd floor womens | 1 | EA | 7 | 10+ years | |
| | Accessories | 3rd floor boys | 234 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 3rd floor boys | 234 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd floor boys | 234 | SF | 6 | 6-10 years | |
| | Floor Drain | 3rd floor boys | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 3rd floor boys | 1 | EA | 7 | 10+ years | |
| | Lavatory | 3rd floor boys | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd floor boys | 3 | EA | 7 | 6-10 years | |
| | Partitions | 3rd floor boys | 3 | EA | 7 | 10+ years | |
| | Urinals | 3rd floor boys | 2 | EA | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 3rd floor boys | 560 | SF | 7 | 10+ years | |
| | Water Closet | 3rd floor boys | 3 | EA | 7 | 10+ years | |
| | Accessories | 3rd floor girls | 234 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | 3rd floor girls | 234 | SF | 6 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd floor girls | 234 | SF | 6 | 6-10 years | |
| | Floor Drain | 3rd floor girls | 1 | EA | 7 | 10+ years | |
| | Hand Dryer | 3rd floor girls | 1 | EA | 7 | 10+ years | |
| | Lavatory | 3rd floor girls | 2 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd floor girls | 3 | EA | 7 | 6-10 years | |
| | Partitions | 3rd floor girls | 5 | EA | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | 3rd floor girls | 560 | SF | 7 | 10+ years | |
| | Water Closet | 3rd floor girls | 5 | EA | 7 | 10+ years | |
| | Accessories | 3rd floor mens | 35 | SF | 7 | 6-10 years | |
| | Ceiling - Plaster/Drywall | 3rd floor mens | 35 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd floor mens | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | 3rd floor mens | 35 | SF | 7 | 10+ years | |
| | Hand Dryer | 3rd floor mens | 1 | EA | 7 | 10+ years | |
| | Lavatory | 3rd floor mens | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd floor mens | 1 | EA | 7 | 6-10 years | |
| | Walls - Tile Ceramic/ Porcelain | 3rd floor mens | 190 | SF | 7 | 10+ years | |
| | Water Closet | 3rd floor mens | 1 | EA | 7 | 10+ years | |
| | Accessories | 3rd floor womens | 35 | SF | 7 | 6-10 years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---------------------------------|--|----------|-----|------|-----------------------|---------------|
| | Ceiling - Lay-in | 3rd floor womens | 35 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd floor womens | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd floor womens | 35 | SF | 6 | 6-10 years | |
| | Lavatory | 3rd floor womens | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | 3rd floor womens | 1 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd floor womens | 190 | SF | 7 | 10+ years | |
| | Water Closet | 3rd floor womens | 1 | EA | 7 | 10+ years | |
| | Accessories | Kitchen - Unisex Staff 1st Floor | 40 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | Kitchen - Unisex Staff 1st Floor | 40 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Kitchen - Unisex Staff 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | Kitchen - Unisex Staff 1st Floor | 40 | SF | 6 | 10+ years | |
| | Lavatory | Kitchen - Unisex Staff 1st Floor | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Kitchen - Unisex Staff 1st Floor | 1 | EA | 5 | 10+ years | Missing cover |
| | Student Lockers - One Tier | Kitchen - Unisex Staff 1st Floor | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Kitchen - Unisex Staff 1st Floor | 208 | SF | 7 | 10+ years | |
| | Water Closet | Kitchen - Unisex Staff 1st Floor | 1 | EA | 7 | 10+ years | |
| | Accessories | Principal's Restroom | 42 | SF | 7 | 10+ years | |
| | Ceiling - Lay-in | Principal's Restroom | 42 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Principal's Restroom | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Principal's Restroom | 42 | SF | 6 | 10+ years | |
| | Lavatory | Principal's Restroom | 1 | EA | 7 | 10+ years | |
| | Lighting - Pendent/Surface | Principal's Restroom | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Principal's Restroom | 288 | SF | 7 | 10+ years | |
| | Water Closet | Principal's Restroom | 1 | EA | 7 | 10+ years | |
| | Accessories | Unisex Southwest 1st Floor | 80 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | Unisex Southwest 1st Floor | 80 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Unisex Southwest 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Unisex Southwest 1st Floor | 80 | SF | 6 | 10+ years | |
| | Floor Drain | Unisex Southwest 1st Floor | 1 | EA | 7 | 10+ years | |
| | Lavatory | Unisex Southwest 1st Floor | 1 | EA | 6 | 10+ years | |
| | Lighting - Lay-in | Unisex Southwest 1st Floor | 1 | EA | 7 | 10+ years | |
| | Showers | Unisex Southwest 1st Floor | 1 | EA | 7 | 10+ years | |
| | Walls - Tile Ceramic/ Porcelain | Unisex Southwest 1st Floor | 288 | SF | 7 | 10+ years | |
| | Water Closet | Unisex Southwest 1st Floor | 1 | EA | 7 | 10+ years | |
| | Accessories | Unisex across from main office workroom | 42 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | Unisex across from main office workroom | 42 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Unisex across from main office workroom | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | Unisex across from main office workroom | 42 | SF | 6 | 10+ years | |
| | Lavatory | Unisex across from main office workroom | 1 | EA | 7 | 10+ years | |

Category : Room
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|---------------------------------|---|----------|-----|------|-----------------------|---|
| | Lighting - Pendant/Surface | Unisex across from main office workroom | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Unisex across from main office workroom | 288 | SF | 7 | 10+ years | |
| | Water Closet | Unisex across from main office workroom | 1 | EA | 7 | 10+ years | |
| | Accessories | Women's Southwest 1st Floor (now security office) | 80 | SF | 7 | 6-10 years | |
| | Ceiling - Lay-in | Women's Southwest 1st Floor (now security office) | 80 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | Women's Southwest 1st Floor (now security office) | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Ceramic/ Porcelain | Women's Southwest 1st Floor (now security office) | 80 | SF | 6 | 10+ years | |
| | Floor Drain | Women's Southwest 1st Floor (now security office) | 1 | EA | 7 | 10+ years | |
| | Lighting - Lay-in | Women's Southwest 1st Floor (now security office) | 1 | EA | 7 | 10+ years | Inaccessible, due to security officer not coming in today |
| | Partitions | Women's Southwest 1st Floor (now security office) | 1 | EA | 5 | 10+ years | |
| | Showers | Women's Southwest 1st Floor (now security office) | 1 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Women's Southwest 1st Floor (now security office) | 288 | SF | 6 | 10+ years | |
| | Water Closet | Women's Southwest 1st Floor (now security office) | 1 | EA | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--|-----------------------------|-----------|----------|-----|------|-----------------------|----------|
| Classroom #101 (Multi Purpose Room) | | | | | | | |
| | Casework | 1st Floor | 5 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 1st Floor | 1,110 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 4 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 3 | EA | 6 | 10+ years | |
| | Floor - Tile | 1st Floor | 1,110 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 13 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 6 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 40 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 3,879 | SF | 6 | 10+ years | |
| | Work Sink | 1st Floor | 1 | EA | 7 | 10+ years | |
| Classroom #103 (Pre School) | | | | | | | |
| | Casework | 1st Floor | 12 | LF | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|------------------------------------|-----------------------------|-----------|----------|-----|------|-----------------------|-------------------------|
| | Ceiling - Lay-in | 1st Floor | 550 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 8 | LF | 4 | 2-5 years | |
| | Doors - Steel Doors incl hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 550 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 7 | 10+ years | |
| | Marker Board | 1st Floor | 8 | LF | 7 | 6-10 years | |
| | Storage/ Closet | 1st Floor | 49 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,080 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |
| <hr/> | | | | | | | |
| Classroom #105 (Pre School) | | | | | | | |
| | Casework | 1st Floor | 12 | LF | 7 | 10+ years | Not previously assessed |
| | Ceiling - Lay-in | 1st Floor | 550 | SF | 6 | 10+ years | |
| | Chalk Board | 1st Floor | 4 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile | 1st Floor | 550 | SF | 6 | 10+ years | |
| | Lighting - Lay-in | 1st Floor | 12 | EA | 6 | 10+ years | |
| | Storage/ Closet | 1st Floor | 49 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 1,080 | SF | 7 | 10+ years | |
| | Work Sink | 1st Floor | 2 | EA | 7 | 10+ years | |
| <hr/> | | | | | | | |
| Classroom #200 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 6 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 841 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 841 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 7 | 10+ years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,050 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| <hr/> | | | | | | | |
| Classroom #201 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 6 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 841 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 841 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 13 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,050 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|--|
| | Casework | 2nd Floor | 6 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 667 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 16 | LF | 4 | 2-5 years | Chalk board not in current use but still up and exposed. |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 667 | SF | 6 | 2-5 years | |
| | Lighting - Lay-in | 2nd Floor | 11 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 936 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #205 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 6 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 870 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 870 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 13 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,062 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #206 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 6 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 841 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 841 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 7 | 10+ years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,050 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 5 | 1-2 years | Sink is dripping when turned off. |
| Classroom #207 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 6 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 841 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 16 | LF | 4 | 6-10 years | Chalk board is covered up and not in use. |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 841 | SF | 7 | 10+ years | |
| | Lighting - Lay-in | 2nd Floor | 13 | EA | 7 | 10+ years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,050 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #208 (Regular Classroom) | | | | | | | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|-----------------------------|-----------|----------|-----|------|-----------------------|--|
| | Casework | 2nd Floor | 6 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 870 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 16 | LF | 4 | 6-10 years | Chalk board is covered up and not in use. |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 870 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 13 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,034 | SF | 6 | 10+ years | |
| | Walls - Concrete Block | 2nd Floor | 28 | SF | 5 | 10+ years | Mortar cracks |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #211 (Science Classroom) | | | | | | | |
| | Casework | 2nd Floor | 12 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 841 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 8 | LF | 4 | 2-5 years | Chalk board is not in use but still exposed. |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 841 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 6 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 837 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #212 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 12 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 1,011 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 1,011 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 16 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,188 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 200 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #222 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 12 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 1,010 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 8 | LF | 4 | 2-5 years | Chalk board not in use but still exposed. |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 1,010 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 2nd Floor | 8 | LF | 7 | 6-10 years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--|-----------------------------|-----------|----------|-----|------|-----------------------|---|
| | Walls - Concrete Block | 2nd Floor | 1,188 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 200 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #223 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 12 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 841 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 16 | LF | 4 | 2-5 years | Chalk board is covered up and not in use. |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 6-10 years | |
| | Floor - Tile | 2nd Floor | 841 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 12 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 837 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 2nd Floor | 200 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #225 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 6 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 870 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 2nd Floor | 870 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 15 | EA | 7 | 6-10 years | |
| | Marker Board | 2nd Floor | 22 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,062 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | Sink is dripping even when turned off. |
| Classroom #226 (Regular Classroom) | | | | | | | |
| | Casework | 2nd Floor | 6 | LF | 6 | 10+ years | |
| | Ceiling - Lay-in | 2nd Floor | 841 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 16 | LF | 4 | 2-5 years | Chalk board is covered up and not in use. |
| | Doors - Wood Doors inclu hw | 2nd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 2nd Floor | 841 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 2nd Floor | 14 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 1,050 | SF | 6 | 10+ years | |
| | Work Sink | 2nd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #2nd Floor Lab (Computer Lab) | | | | | | | |
| | Ceiling - Lay-in | 2nd Floor | 1,100 | SF | 6 | 10+ years | |
| | Chalk Board | 2nd Floor | 10 | LF | 4 | 2-5 years | Chalk board possibly still in use. |
| | Doors - Side-lite | 2nd Floor | 160 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 2nd Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Carpet | 2nd Floor | 760 | SF | 6 | 2-5 years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|---|--------------------------------------|-----------|----------|-----|------|-----------------------|----------------------------|
| | Lighting - Metal Halide/Sodium Vapor | 2nd Floor | 6 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 800 | SF | 7 | 10+ years | |
| | Walls - Plaster/Drywall | 2nd Floor | 3,168 | SF | 6 | 10+ years | |
| Classroom #300 (Regular Classroom) | | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 841 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 8 | LF | 4 | 2-5 years | Chalk board still exposed. |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 841 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,050 | SF | 6 | 10+ years | |
| Classroom #301 (Regular Classroom) | | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 841 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 16 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 841 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 1,050 | SF | 6 | 10+ years | |
| Classroom #302 (Special Program) | | | | | | | |
| | Casework | 3rd Floor | 6 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 667 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 16 | LF | 4 | 2-5 years | Chalk board is exposed. |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 667 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 11 | EA | 6 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 936 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #305 (Art Room) | | | | | | | |
| | Casework | 3rd Floor | 6 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 870 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 870 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,062 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #306 (Faculty Lounge) | | | | | | | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--|-----------------------------|-----------|----------|-----|------|-----------------------|--|
| | Casework | 3rd Floor | 6 | LF | 7 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 841 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 16 | LF | 4 | 2-5 years | Chalk board is exposed. |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 841 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,050 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #307 (Play Room) | | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 841 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 5 | LF | 4 | 2-5 years | Chalk board still exposed. |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 841 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 10 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,050 | SF | 6 | 10+ years | |
| Classroom #308 (Regular Classroom) | | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 870 | SF | 7 | 10+ years | No water stain anymore from previous deficiency. |
| | Chalk Board | 3rd Floor | 16 | LF | 4 | 2-5 years | Chalk board is exposed but most likely not in use. |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 7 | 10+ years | |
| | Floor - Tile | 3rd Floor | 870 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 5 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,012 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 50 | SF | 6 | 10+ years | Mortar crack |
| Classroom #312 (Store Room) | | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 841 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 16 | LF | 4 | 2-5 years | Chalk board is exposed but not in use. |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 841 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 837 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 200 | SF | 7 | 10+ years | |
| Classroom #313 (Multi Purpose Room) | | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 1,011 | SF | 6 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|------------------------------------|-----------------------------|-----------|----------|-----|------|-----------------------|---|
| | Chalk Board | 3rd Floor | 8 | LF | 4 | 2-5 years | Chalk board is exposed and potentially in use. |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,011 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 14 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,888 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 200 | SF | 7 | 10+ years | |
| Classroom #314 (Computer Lab) | | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 1,314 | SF | 6 | 10+ years | Corrected quantity |
| | Doors - Side-lite | 3rd Floor | 30 | SF | 7 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 1,314 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 18 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 504 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 445 | SF | 6 | 10+ years | |
| | Wireless System | 3rd Floor | 1 | EA | 7 | 6-10 years | |
| Classroom #314A (Play Room) | | | | | | | |
| | Casework | 3rd Floor | 85 | LF | 6 | 10+ years | Chalk board is exposed. Not previously assessed |
| | Ceiling - Lay-in | 3rd Floor | 937 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 8 | LF | 4 | 2-5 years | |
| | Doors - Side-lite | 3rd Floor | 30 | SF | 7 | 10+ years | |
| | Doors - Steel Doors incl hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Carpet | 3rd Floor | 937 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 11 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 440 | SF | 6 | 10+ years | |
| | Walls - Plaster/Drywall | 3rd Floor | 470 | SF | 6 | 10+ years | |
| | Work Sink | 3rd Floor | 1 | EA | 7 | 10+ years | |
| Classroom #325 (Science Classroom) | | | | | | | |
| | Casework | 3rd Floor | 16 | LF | 7 | 10+ years | Chalk board is exposed but probably not in use. |
| | Ceiling - Lay-in | 3rd Floor | 1,011 | SF | 6 | 10+ years | |
| | Chalk Board | 3rd Floor | 12 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 1,011 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 1,088 | SF | 6 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 200 | SF | 7 | 10+ years | |
| | Work Sink | 3rd Floor | 2 | EA | 7 | 10+ years | |

Category : Classroom
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|------------------------------------|-----------------------------|-----------|----------|-----|------|-----------------------|---|
| Classroom #326 (Science Classroom) | | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 841 | SF | 6 | 10+ years | Chalk board is exposed but probably not in use. |
| | Chalk Board | 3rd Floor | 6 | LF | 4 | 2-5 years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 841 | SF | 6 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 12 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 837 | SF | 7 | 10+ years | |
| | Walls - Metal Panel | 3rd Floor | 200 | SF | 7 | 10+ years | |
| Classroom #329 (Regular Classroom) | | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 870 | SF | 6 | 10+ years | Mortar crack |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 870 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 14 | EA | 6 | 6-10 years | |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,062 | SF | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 20 | SF | 6 | 10+ years | |
| Classroom #330 (Regular Classroom) | | | | | | | |
| | Ceiling - Lay-in | 3rd Floor | 841 | SF | 6 | 10+ years | |
| | Doors - Wood Doors inclu hw | 3rd Floor | 1 | EA | 6 | 10+ years | |
| | Floor - Tile | 3rd Floor | 841 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 13 | EA | 7 | 6-10 years | |
| | Marker Board | 3rd Floor | 8 | LF | 7 | 6-10 years | |
| | Walls - Concrete Block | 3rd Floor | 1,050 | SF | 6 | 10+ years | |

Category : Interior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------|--------------------------------------|-----------|----------|-----|------|-----------------------|--|
| Corridor | | | | | | | |
| | Ceiling - Plaster/Drywall | 1st Floor | 312 | SF | 6 | 10+ years | Cracked and worn tiles |
| | Doors - Steel Doors incl hw | 1st Floor | 2 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 304 | SF | 7 | 10+ years | |
| | Floor - Tile/Sheet | 1st Floor | 8 | SF | 4 | 0-1 year | |
| | Lighting - Lay-in | 1st Floor | 4 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 1st Floor | 832 | SF | 6 | 10+ years | Tile chipped and it looks like asbestos tile is exposed. |
| | Ceiling - Lay-in | 2nd Floor | 2,508 | SF | 6 | 10+ years | |
| | Drinking Fountains - Single Fountain | 2nd Floor | 4 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 2nd Floor | 2,507 | SF | 7 | 6-10 years | |
| | Floor - Tile/Sheet | 2nd Floor | 1 | SF | 4 | 0-1 year | |

Category : Interior
Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|--------|--------------------------------------|----------------------------|----------|-----|------|-----------------------|--|
| | Lighting - Lay-in | 2nd Floor | 29 | EA | 7 | 6-10 years | |
| | Walls - Concrete Block | 2nd Floor | 4,390 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | 3rd Floor | 2,938 | SF | 6 | 10+ years | |
| | Drinking Fountains - Single Fountain | 3rd Floor | 3 | EA | 7 | 10+ years | |
| | Floor - Tile/Sheet | 3rd Floor | 2,938 | SF | 7 | 6-10 years | |
| | Lighting - Lay-in | 3rd Floor | 34 | EA | 7 | 6-10 years | |
| | Student Lockers - Two Tiers | 3rd Floor | 80 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | 3rd Floor | 4,808 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | Elevator lobby/office area | 542 | SF | 6 | 10+ years | |
| | Doors - Steel Doors incl hw | Elevator lobby/office area | 1 | EA | 7 | 10+ years | |
| | Floor - Tile Quarry | Elevator lobby/office area | 80 | SF | 6 | 10+ years | |
| | Floor - Tile/Sheet | Elevator lobby/office area | 467 | SF | 5 | 10+ years | |
| | Lighting - Lay-in | Elevator lobby/office area | 4 | EA | 6 | 10+ years | |
| | Lighting - Pendent/Surface | Elevator lobby/office area | 2 | EA | 7 | 10+ years | |
| | Walls - Concrete Block | Elevator lobby/office area | 1,314 | SF | 6 | 10+ years | |
| <hr/> | | | | | | | |
| Safety | | | | | | | |
| | Camera Viewing Station | 1st Floor | 1 | EA | 7 | 10+ years | |
| | Metal Detector | 1st Floor | 1 | EA | 7 | 6-10 years | |
| | Security Cameras | 1st Floor | 6 | EA | 7 | 6-10 years | Not previously assessed |
| | Security Cameras | 1st Floor | 4 | EA | 7 | 10+ years | |
| <hr/> | | | | | | | |
| Stairs | | | | | | | |
| | Ceiling - Lay-in | North | 350 | SF | 7 | 10+ years | Rank updated to match current observations |
| | Ceiling - Plaster/Drywall | North | 525 | SF | 6 | 10+ years | |
| | Floor - Concrete | North | 280 | SF | 5 | 10+ years | |
| | Floor - Tile | North | 448 | SF | 6 | 10+ years | |
| | Handrails | North | 115 | LF | 5 | 10+ years | |
| | Lighting - Pendent/Surface | North | 10 | EA | 7 | 10+ years | |
| | Stairs - Concrete | North | 322 | LF | 6 | 10+ years | |
| | Walls - Concrete Block | North | 2,808 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | South East | 350 | SF | 7 | 10+ years | Rank changed to match current observations |
| | Ceiling - Plaster/Drywall | South East | 525 | SF | 6 | 10+ years | |
| | Floor - Concrete | South East | 280 | SF | 7 | 10+ years | |
| | Floor - Tile | South East | 448 | SF | 6 | 10+ years | |
| | Handrails | South East | 115 | LF | 5 | 10+ years | |
| | Lighting - Pendent/Surface | South East | 10 | EA | 7 | 10+ years | |
| | Stairs - Concrete | South East | 322 | LF | 7 | 10+ years | |
| | Walls - Concrete Block | South East | 2,808 | SF | 6 | 10+ years | |
| | Ceiling - Lay-in | South West | 366 | SF | 7 | 10+ years | Rank updated to match current observations |
| | Ceiling - Plaster/Drywall | South West | 509 | SF | 6 | 10+ years | |

Category : Interior

Building : Main

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-------|----------------------------|------------|----------|-----|------|-----------------------|----------|
| | Floor - Concrete | South West | 280 | SF | 5 | 10+ years | |
| | Floor - Tile | South West | 448 | SF | 6 | 10+ years | |
| | Handrails | South West | 115 | LF | 5 | 10+ years | |
| | Lighting - Pendent/Surface | South West | 10 | EA | 7 | 10+ years | |
| | Stairs - Concrete | South West | 322 | LF | 6 | 10+ years | |
| | Walls - Concrete Block | South West | 2,808 | SF | 5 | 10+ years | |

Vertical Conveyance

| | | | | | |
|-------------------------------|-----------------|---|----|---|-----------|
| Elevator - Elevator- Traction | Entire building | 1 | EA | 7 | 10+ years |
|-------------------------------|-----------------|---|----|---|-----------|

Category : Site
Building : Site

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|-----------------------|-----------------------------------|-------------------------|----------|-----|------|-----------------------|-------------------------------------|
| Athletic | | | | | | | |
| | Surface - Synthetic | East | 9,600 | SF | 7 | 10+ years | |
| | Surface - Asphalt | East | 1,750 | SF | 7 | 10+ years | |
| Civil/Drainage | | | | | | | |
| | Civil/ Drainage - Catch Basin | Entire Site | 2 | EA | 7 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 2 | EA | 7 | 10+ years | |
| | Civil/ Drainage - Site Manhole | Entire Site | 1 | EA | 6 | 10+ years | |
| Fencing | | | | | | | |
| | Fencing - Chain Link | Entire Site | 1,558 | LF | 6 | 10+ years | |
| | Fencing - Chain Link | Entire Site | 125 | LF | 5 | 0-1 year | Corroding, bent out of shape |
| | Fencing - Guard Rail | Entire Site | 245 | LF | 6 | 10+ years | |
| | Fencing - New Standard Ornamental | Entire Site | 280 | LF | 6 | 10+ years | |
| Landscape | | | | | | | |
| | Benches | Entire Site | 2 | EA | 7 | 10+ years | |
| | Landscape - Grass | Entire Site | 39,937 | SF | 7 | 10+ years | |
| | Landscape - Grass | Entire Site | 2,000 | SF | 5 | 1-2 years | Bare soil |
| | Parkway trees | Entire Site | 8 | EA | 7 | 10+ years | |
| | Play Area - Hardscape- Asphalt | Entire Site | 3,312 | SF | 7 | 10+ years | |
| Parking Lot | | | | | | | |
| | Concrete Curbs | Parking Lot- South | 95 | LF | 7 | 10+ years | |
| | Concrete Curbs | Parking Lot- South | 5 | LF | 4 | 1-2 years | Broken curb at entry to parking lot |
| | Surface - Asphalt | Parking Lot- South | 12,800 | SF | 6 | 6-10 years | |
| | Surface - Concrete | Parking Lot- South | 1,700 | SF | 7 | 10+ years | |
| | Trash Enclosure - Chain Links | Parking Lot- South | 900 | SF | 7 | 10+ years | |
| | Surface - Asphalt | West - off alley | 13,000 | SF | 5 | 6-10 years | Verified in fair to good condition |
| | Surface - Asphalt | West - off alley | 100 | SF | 4 | 0-1 year | Potholes |
| Playground | | | | | | | |
| | Equipment - Pre K 3-5 | East | 1 | EA | 7 | 10+ years | |
| | Equipment - School Age 5-12 | East | 1 | EA | 7 | 10+ years | |
| | Surface - Poured Surface | East | 1,275 | SF | 7 | 10+ years | |
| | Surface - Poured Surface | East | 400 | SF | 7 | 10+ years | |
| | Surface - Poured Surface | East | 25 | SF | 5 | 1-2 years | Hole near swing |
| Sidewalks | | | | | | | |
| | Sidewalks - Internal Walks | North, East, South Site | 276 | LF | 6 | 10+ years | |
| | Sidewalks - Perimeter Sidewalks | North, East, South Site | 10,252 | SF | 6 | 10+ years | |

Category : Site

Building : Site

| Group | Item - Type | Location | Quantity | UOM | Rank | Recommend Replacement | Comments |
|----------------|---|-------------------------|----------|-----|------|-----------------------|---|
| | Sidewalks - Perimeter Sidewalks | North, East, South Site | 1,700 | SF | 5 | 1-2 years | Broken, cracked, upheaved. Verified dimension |
| Signage | | | | | | | |
| | Flag Pole - Flag Pole | Entire Site | 1 | EA | 7 | 10+ years | |
| | Marquee - Free Standing Back lighted w/ LED | Entire Site | 1 | EA | 7 | 10+ years | |
| | Monument - Building Mounted Cut Letter Sign | Entire Site | 2 | EA | 7 | 10+ years | |

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- **Quantity** means, for each item, the total number (or amount) of that item that exists and was evaluated
- **Unit** means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Classroom Summary

| Current Usage | Intended Usage | Room Location | Room Number | Floor Plan Room Number | Area (SF) | Glazed Window Area | Operable Window Area | Window Stop | Smart-Board |
|------------------------|-------------------|---------------|---------------|------------------------|-----------|--------------------|----------------------|-------------|-------------|
| Building : Main | | | | | | | | | |
| Art Room | Regular Classroom | 3rd Floor | 305 | 305 | 870 | 112 | 34 | Y | Y |
| Computer Lab | Library | 2nd Floor | 2nd Floor Lab | | 1,100 | 213 | 0 | N | N |
| Computer Lab | Regular Classroom | 3rd Floor | 314 | 314 | 1,314 | 149 | 46 | Y | Y |
| Faculty Lounge | Office | 3rd Floor | 306 | 306 | 841 | 112 | 34 | Y | N |
| Multi Purpose Room | Faculty Lounge | 1st Floor | 101 | N/A | 1,110 | 24 | 8 | | |
| Multi Purpose Room | Regular Classroom | 3rd Floor | 313 | 313 | 1,011 | 196 | 60 | Y | Y |
| Play Room | Regular Classroom | 3rd Floor | 307 | 307 | 841 | 112 | 34 | Y | Y |
| Play Room | Regular Classroom | 3rd Floor | 314A | | 937 | 75 | 23 | Y | N |
| Pre School | Kindergarten | 1st Floor | 103 | 103 | 550 | 150 | 45 | Y | Y |
| Pre School | Kindergarten | 1st Floor | 105 | 105 | 550 | 75 | 23 | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 200 | N/A | 841 | 112 | 34 | N | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 201 | N/A | 841 | 112 | 34 | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 205 | N/A | 870 | 112 | 34 | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 206 | N/A | 841 | 112 | 34 | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 207 | N/A | 841 | 112 | 34 | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 208 | N/A | 870 | 112 | 34 | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 212 | N/A | 1,050 | 196 | 60 | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 222 | N/A | 1,010 | 196 | 60 | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 223 | N/A | 841 | 112 | 34 | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 225 | N/A | 870 | 112 | 34 | Y | Y |
| Regular Classroom | Regular Classroom | 2nd Floor | 226 | N/A | 841 | 112 | 34 | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 300 | 300 | 841 | 112 | 34 | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 301 | 301 | 841 | 112 | 34 | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 308 | 308 | 870 | 112 | 34 | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 329 | 329 | 870 | 90 | 25 | Y | Y |
| Regular Classroom | Regular Classroom | 3rd Floor | 330 | 330 | 841 | 112 | 34 | Y | Y |
| Science Classroom | Regular Classroom | 2nd Floor | 211 | N/A | 841 | 112 | 34 | Y | Y |
| Science Classroom | Science Classroom | 3rd Floor | 325 | 325 | 1,011 | 196 | 60 | Y | Y |
| Science Classroom | Science Classroom | 3rd Floor | 326 | 326 | 841 | 112 | 34 | Y | Y |
| Special Program | Regular Classroom | 3rd Floor | 302 | 302 | 667 | 84 | 26 | Y | Y |
| Store Room | Regular Classroom | 2nd Floor | 202 | N/A | 667 | 84 | 26 | Y | N |
| Store Room | Regular Classroom | 3rd Floor | 312 | 312 | 841 | 112 | 34 | Y | N |