

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1907	3	77,140
Campus Total			77,140

Category : Exterior Building : Main

	.y . =Atonie.			<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance)		_			·	
	Exterior Doors - Exterior Steel Door	1 - N	2	EA	4	1-2 years	Corroded door and frame
	Exterior Doors - Transom Lite	1 - N	1	EA	6	10+ years	
	Exterior Stairs - Concrete	1 - N	7	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	1A - N Boiler Room	1	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	1A - N Boiler Room	1	EA	6	6-10 years	
	Exterior Doors - Overhead Rolling/ Garage	1B - N Outside Yard Storage	1	EA	5	6-10 years	
	Door						
	Exterior Doors - Exterior Steel Door	2 - W	2	EA	5	2-5 years	
	Exterior Stairs - Concrete	2 - W	6	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	3 - SW	2	EA	5	2-5 years	
	Exterior Doors - Side lite	3 - SW	2	EA	5	2-5 years	
	Exterior Doors - Transom Lite	3 - SW	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	3 - SW	15	LF	6	10+ years	
	Entrance Control - Audio and Video	4 - S Main	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	4 - S Main	3	EA	4	0-1 year	Corroded doors
	Exterior Doors - Transom Lite	4 - S Main	4	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	5 - SE	2	EA	6	10+ years	
	Exterior Doors - Side lite	5 - SE	2	EA	5	2-5 years	
	Exterior Doors - Transom Lite	5 - SE	4	EA	6	6-10 years	
	Exterior Stairs - Concrete	5 - SE	15	LF	5	2-5 years	
	Entrance Control - Audio and Video	6 - NE	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	6 - NE	2	EA	7	10+ years	
	Power Door Operator and Controls	6 - NE	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	6 - NE	100	LF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ramps - Concrete	6 - NE	55	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	7 - Auditorium East	2	EA	6	6-10 years	
	Exterior Stairs - Concrete	7 - Auditorium East	6	LF	5	6-10 years	
	Exterior Doors - Exterior Steel Door	8 - Auditorium West	2	EA	6	10+ years	
	Exterior Stairs - Concrete	8 - Auditorium West	6	LF	6	6-10 years	
Fire Esca	ana						
	Exterior Doors - Exterior Steel Door	Auditorium - West	2	EA	6	10+ years	
	Fire Escape	Auditorium - West	18	LF	4	0-1 year	Leaning stair due to corroded stringer
	Paints	Auditorium - West	18	LF	5	2-5 years	Learning stail due to corroded stringer
	Exterior Doors - Exterior Steel Door	Auditorium East	2	EA	6	-	
						10+ years	
	Fire Escape	Auditorium East	14	LF	5	2-5 years	0
	Fire Escape	Auditorium East	4	LF	4	0-1 year	Corroded steel beam, bent treads
	Paints	Auditorium East	18	LF	5	2-5 years	
_Foundati	on						
	Foundation - Masonry	Entire Building	820	LF	7	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	77,140	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	13	EA	6	10+ years	
Roof Sys	tem						
_ KOOL Oys	Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 1	70	LF	6	10+ years	
	Liner	11001 1	70		O	101 years	
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 1	10	LF	5	10+ years	
	Liner	10011	10		J	101 years	
	Coping - Clay Tile	Roof 1	242	LF	6	10+ years	
	Coping - Clay Tile	Roof 1	16	LF	5	10+ years	
	Coping - Terra Cotta	Roof 1	410	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	170	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 1	5	LF	4	0-1 year	Leaking downspout
	Downspouts - Interior Downspouts	Roof 1	266	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 1	595	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 1	175	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 1	50	LF	5	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 1	12,475	SF	7	6-10 years	
	Roof - Asphalt Gravel Ballast	Roof 1	335	SF	5	6-10 years	Repaired
	Roof - Modified Bitumen	Roof 1	100	SF	6	6-10 years	
	Roof Hatch - Metal	Roof 1	1	EA	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	Roof 1	12,910	SF	7	10+ years	
	Chimney - Metal Flue	Roof 2	6	LF	6	6-10 years	
			Ü		ŭ	o .o youro	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Clay Tile	Roof 2	48	LF	6	10+ years	
	Coping - Clay Tile	Roof 2	4	LF	5	10+ years	
	Coping - Metal	Roof 2	100	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Roof 2	110	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 2	6,310	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 2	6,310	SF	7	10+ years	
	Coping - Clay Tile	Roof 3 - N. Lower Roof	88	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 3 - N. Lower Roof	38	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 3 - N. Lower Roof	6	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 3 - N. Lower Roof	88	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 3 - N. Lower Roof	1,783	SF	6	6-10 years	Small area of vegetation growth
	Roof Structure - Steel with Clay Tile Arch	Roof 3 - N. Lower Roof	1,783	SF	7	10+ years	
	Coping - Clay Tile	Roof 4 - N. Lower Roofs	88	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 4 - N. Lower Roofs	38	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 4 - N. Lower Roofs	6	LF 	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 4 - N. Lower Roofs	88	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	Roof 4 - N. Lower Roofs	1,783	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Roof 4 - N. Lower Roofs	1,783	SF	7	10+ years	
_Walls							
- VV GIIO	Cornice - Terra Cotta	Entire Building	735	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	28,650	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	50	SF	4	0-1 year	Cracks, open joints
	Exterior Walls - Prefabricated Metal Panel	Entire Building	945	SF	6	10+ years	
	Wall	3			-	, , , , , ,	
	Exterior Walls - Stone-Cast	Entire Building	200	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	400	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	1,320	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	100	SF	5	10+ years	
\^ <i>(</i> :==d=							
_Windows		Entire Building	945	SF	6	6 10 years	
	Clerestory - Glass Single-Pane Guard - Guards perforated	Entire Building Entire Building	945 1,177	SF SF	6 6	6-10 years 6-10 years	
	Guard - Guards periorated Guard - Guards wire guard	Entire Building Entire Building	570	SF	6	6-10 years	
	Lintels - Brick	Entire Building Entire Building	312	LF	6	10+ years	
	Lintels - Brick	Entire Building Entire Building	20	LF	4	0-1 year	Loose brick door 7
	Lintels - Blick Lintels - Steel	Entire Building Entire Building	610	LF	6	10+ years	Loose blick dool 1
	Lintels - Stone	Entire Building Entire Building	165	LF	6	10+ years	
	Windows - Louver	Entire Building Entire Building	103	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building Entire Building	8,475	SF	6	10+ years	
	Windows - Sash Adminian Double-pane Windows - Sash Lexan/ Glass Double-pane	Entire Building Entire Building	158	SF	6	6-10 years	
	Windows - Wood- Single-pane	Entire Building Entire Building	54	SF	6	6-10 years	
	Tilliaotto Titoda Olligio pario	Entire Daliding	34	O.	O	o io youis	



Catego	ry : Electrical		В	uilding	: Main		7040 S Green STREET, Chicago, IL 00020
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerger	ncy System Automatic Transfer Switch	Electrical Room	1	EA	4	2-5 years	Reason and Priority Rep adjusted as the unit is approx. 50 years old, emits an audible "hum" indicating low-level age-related wear, and has reached the end of its anticipated service life.
	Security System - CCTV	Entire Building	77,140	SF	6	6-10 years	·
	Security System - Intrusion Detection	Entire Building	77,140	SF	6	6-10 years	Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer that the system has been upgraded since previous assessment.
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,714	SF	6	6-10 years	Priority Rep adjusted based on current observations and to align with Rank and Reason. Location changed for clarification as the auditorium occupies space on multiple floors. No aisle lighting present.
	Emergency A/C Power - Corridors and Stairs	Entire Building	11,049	SF	6	6-10 years	Priority Rep adjusted based on current observations and to align with Rank and Reason.
	Emergency A/C Power - Gym	Entire Building	3,879	SF	6	6-10 years	Priority Rep adjusted based on current observations and to align with Rank and Reason.
	Emergency A/C Power - Lunchrooms	Entire Building	1,105	SF	6	6-10 years	Priority Rep adjusted based on current observations and to align with Rank and Reason.
	Exit Signs - Auditoium	Entire Building	9	EA	2	0-1 year	Location changed for clarification as the auditorium occupies space on multiple floors. Quantity changed to match current observations. Some signs are damaged, and all signs have no backup batteries and the school has no emergency generator.
	Exit Signs - Corridors and Stairs	Entire Building	16	EA	2	0-1 year	Location and Quantity changed to match current observations. Some sign faces are partially damaged; all signs have no backup batteries and the school has no emergency generator.
	Exit Signs - Gym	Entire Building	2	EA	2	0-1 year	Sign faces are partially damaged; both signs have no backup batteries and the school has no emergency

Campus Name: Oglesby Page : 4 of 29 Assessment Date: 04/25/2024



atego	ry : Electrical		В	uilding	: Main		
			.			Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exit Signs - Lunchroom	Entire Building	3	EA	2	0-1 year	generator. Signs have no backup batteries and the school has no emergency generator.
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	4	EA	7	10+ years	Location changed for clarification a the auditorium occupies space on multiple floors. Quantity changed a total has been divided/aggregated.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	7	EA	6	6-10 years	Rank, Reason and Priority Rep changed to match current observations.
	Emergency Battery Packs - Lunchrooms	Entire Building	1	EA	7	10+ years	
ain Se	rvice						
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	4	0-1 year	Reason and Priority Rep changed a an opening in the front of the panel unreliably covered with duct tape at otherwise exposes live conductors inside the panel presenting an acut live front condition.
	PA System	Entire Building	77,140	SF	6	6-10 years	
ower D	vistribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Quantity changed to match current observations.
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Open fuse receptacles and an opening in the interior cover plate expose live conductors presenting live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	16	EA	6	6-10 years	Quantity changed as total has been divided/aggregated. Some panels the building are secured shut for security reasons; condition verified Building Engineer.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slots expose live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slots are unreliably covered with tape and expose live conductors presenting a live front

Campus Name: Oglesby Page : 5 of 29 Assessment Date: 04/25/2024



Richard J Oglesby Elementary School

7646 S Green STREET, Chicago, IL 60620

Category : Electrical Building : Main

Group Item - Type Location Quantity UOM Rank Replacement Comments condition.

Category : Fire Protection Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Fire Alar	rm						
	Fire ALarm Anunciator	Entire Building	1	EA	7	10+ years	No CPS Asset Tag present.
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Rank, Reason and Priority Rep changed as the fire alarm system was replaced since previous assessment. Location changed for clarification.
	Fire Alarm Strobe Lights	Entire Building	77,140	SF	7	10+ years	Rank, Reason and Priority Rep changed as the fire alarm system was replaced since previous assessment.
	Fire Alarm_System	Entire Building	77,140	SF	7	10+ years	Rank, Reason and Priority Rep changed as the fire alarm system was replaced since previous assessment.

Category : Mechanical Building : Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Air Hand	Iling Systems					•	
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 15000 - 30000 cfm	Mech. Room - AHU-1	1	EA	6	6-10 years	AHU-1, serves east, central, and west sections of Main.
	Air Intake	Mech. Room - AHU-1	2	EA	7	6-10 years	
	Auxiliaries - 15000 - 30000 cfm	Mech. Room - AHU-1	1	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mech. Room - AHU-1	200	LF	6	10+ years	
	Zone Dampers	Mech. Room - AHU-1	28	EA	7	6-10 years	Located in the east and west plenums.
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Mech. Room - AHU-2	1	EA	6	6-10 years	AHU-2, serves auditorium and gym. Rank adjusted based on coil repairs completed since previous assessment.
	Air Intake	Mech. Room - AHU-2	1	EA	7	6-10 years	
	Auxiliaries - 8001 - 15000 cfm	Mech. Room - AHU-2	1	EA	6	10+ years	Rank adjusted based on coil repairs completed since previous assessment.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mech. Room - AHU-2	100	LF	6	10+ years	
	Zone Dampers	Mech. Room - AHU-2	5	EA	7	10+ years	Quantity changed to match current observations.

Campus Name: Oglesby Page: 6 of 29 Assessment Date: 04/25/2024



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Boiler S	vstems						
,	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that the combustion dampers are both fully operational as intended.
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	Priority Rep adjusted based on current observations and per review with Building Engineer that repairs were completed since previous assessment.
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that the feed wate tank and pump system is fully operational as intended despite its age; the tank and all piping and pumps are intact and leak-free.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	6-10 years	B-1. Rank changed based on curre observations and per review with Building Engineer that repairs were completed since previous assessment.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	6-10 years	B-2. Rank changed based on curre observations and per review with Building Engineer that repairs were completed since previous assessment.
	Piping - Condensate Pipe- Steel	Boiler Room	300	LF	6	6-10 years	Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that the condensate piping is fully operationa as intended despite its age; all pipinthroughout the building is intact and leak-free with no known pipe clamps in the system. Many runs of condensate return piping are not

Campus Name: Oglesby Page: 7 of 29 Assessment Date: 04/25/2024



Catego	ry : Mechanical		В	uilding	: Main		· ·
	_		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							labeled. Location changed for
	Piping - Steam Pipe- Steel	Boiler Room	300	LF	6	6-10 years	clarification. Rank, Reason and Priority Rep
	Fipling - Steam Fipe- Steel	Boiler Room	300	LF	O	0-10 years	changed based on current
							observations and per review with
							Building Engineer that the steam
							piping is fully operational as intended
							despite its age; all piping throughout
							the building is intact and leak-free
							with no known pipe clamps in the
							system. Many runs of steam supply
							piping are not labeled. Location
	Steam Traps	Boiler Room	18	EA	6	6-10 years	changed for clarification. Location changed for clarification.
	Steam Traps	Doller Room	10	LA	O	0-10 years	Location changed for claimcation.
_Heating							
	Unit Heater - Electric	Basement	1	EA EA	7 7	10+ years	Overtity sharped as total has been
	Unit Heater - Electric	Basement	Į	EA	1	10+ years	Quantity changed as total has been divided/aggregated. Location
							changed for clarification.
	Unit Heater - Gas	Basement	1	EA	7	6-10 years	changed for clarification.
	Wall Heater - Electric	Entire Building	5	EA	7	10+ years	Location changed for clarification.
		3				,	Quantity changed as total has been
							divided/aggregated.
	Fin Tube - Electric	Entire Building	45	LF	6	6-10 years	Location changed for clarification as
							units are located on multiple floors.
							Rank, Reason and Priority Rep
							changed per review with Building Engineer based on repairs completed
							since previous assessment.
							Since previous assessment.
_Temper	ature Control	Forting Dutilation				0.40	
	Electric Thermostat Pneumatic System	Entire Building Entire Building	1 77,140	EA SF	7 7	6-10 years	
	Thermostats - Pneumatic	Entire Building Entire Building	77,140 46	Sr EA	7 7	10+ years 10+ years	Quantity changed as total has been
	memostats - medinatic	Entire Building	40	LA	,	10+ years	divided/aggregated.
Ventilati	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	1	EA	7	10+ years	-
	CFM				_		
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	1	EA	7	10+ years	Location changed for clarification.
	CFM						Quantity changed as total has been



Richard J Oglesby Elementary School

100	Schools						7646 S Green STREET, Chicago, IL 6062
Catego	ry : Mechanical		В	uilding	: Main		
2roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	item - Type	Location	Qualitity	UOIVI	Kalik	Replacement	divided/aggregated.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Not directly accessible in a safe manner at the time of assessment due to unreliable climbing means. Condition verified by Building Engineer.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Location changed for clarification. Not directly accessible in a safe manner at the time of assessment due to unreliable climbing means. Condition verified by Building Engineer.
Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	77,140	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	77,140	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	77,140	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	77,140	SF	6	6-10 years	
	Sanitary Piping	Entire Building	77,140	SF	6	6-10 years	
	Storm Piping	Entire Building	77,140	SF	6	6-10 years	
	Vent Piping	Entire Building	77,140	SF	6	6-10 years	
umps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	7	10+ years	Rank, Reason and Priority Rep changed as the unit has been replaced since previous assessmer No CPS Asset Tag present.
Catego	ry : Room		В	uilding	: Main	_	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Administ	rative Suites/Offices						

Campus Name: Oglesby Page : 9 of 29 Assessment Date: 04/25/2024



Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Exposed	001	600	SF	6	10+ years	
	Doors - Wood Doors inclu hw	001	1	EA	6	10+ years	
	Floor - Tile	001	600	SF	6	10+ years	
	Lighting - Pendent/Surface	001	10	EA	6	10+ years	
	Power Distribution	001	8	EA	6	10+ years	
	Walls - Plaster/Drywall	001	1,306	SF	6	10+ years	
	Ceiling - Exposed	001A Teacher Lounge	420	SF	6	10+ years	
	Doors - Wood Doors inclu hw	001A Teacher Lounge	1	EA	6	10+ years	
	Floor - Tile	001A Teacher Lounge	420	SF	6	10+ years	
	Lighting - Wall Mounted	001A Teacher Lounge	4	EA	6	6-10 years	
	Power Distribution	001A Teacher Lounge	10	EA	7	10+ years	
	Walls - Masonry	001A Teacher Lounge	504	SF	6	10+ years	
	Walls - Plaster/Drywall	001A Teacher Lounge	150	SF	6	10+ years	
	Ceiling - Plaster/Drywall	007A Office	326	SF	6	10+ years	
	Doors - Wood Doors inclu hw	007A Office	1	ĒA	6	10+ years	
	Floor - Tile	007A Office	326	SF	6	10+ years	
	Lighting - Pendent/Surface	007A Office	4	ĒΑ	7	6-10 years	
	Power Distribution	007A Office	8	ΕA	7	10+ years	
	Walls - Masonry	007A Office	565	SF	6	10+ years	
	Walls - Plaster/Drywall	007A Office	250	SF	6	10+ years	
	Work Sink	007A Office	1	EA	7	10+ years	
	AC Unit	103 Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	103 Main Office	640	SF	6	10+ years	
	Doors - Transom Window	103 Main Office	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	103 Main Office	1	EA	6	10+ years	
	Floor - Tile	103 Main Office	640	SF	6	10+ years	
	Lighting - Pendent/Surface	103 Main Office	7	EA	7	6-10 years	
	Power Distribution	103 Main Office	10	EA	7	10+ years	
	Walls - Plaster/Drywall	103 Main Office	1,520	SF	6	10+ years	
	AC Unit	103A Principal's Office	1,320	EA	7	6-10 years	
	Ceiling - Lay-in	103A Principal's Office	235	SF	6	10+ years	
	Doors - Steel Doors incl hw	103A Principal's Office	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	103A Principal's Office	2	EA	6	10+ years	
	Floor - Tile	103A Principal's Office	235	SF	6	10+ years	
	Lighting - Pendent/Surface	103A Principal's Office	233	EA	7	6-10 years	
	Power Distribution	103A Principal's Office	10	EA	7	10+ years	
	Storage/ Closet	103A Principal's Office	50	SF	5	10+ years	
	Walls - Plaster/Drywall	103A Principal's Office	490	SF	6		
	AC Unit	103A Principal's Office	490	Sr EA	7	10+ years 6-10 years	
	Ceiling - Plaster/Drywall	103B Adj. Office	430	SF	6	•	
	Doors - Wood Doors inclu hw	103B Adj. Office	430	Sr EA	6	10+ years	
	Floor - Tile			SF		10+ years	
	Lighting - Pendent/Surface	103B Adj. Office 103B Adj. Office	430 6	SF EA	6 6	10+ years	
	Power Distribution	103B Adj. Office	12	EA	7	6-10 years	
	FOWEI DISHIBUTION	1036 Auj. Office	12	EA	,	10+ years	



or	y : Room		В	uilding	: Main	_	
	W		0 111		D	Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	103B Adj. Office	40	SF	5	10+ years	
	Walls - Plaster/Drywall	103B Adj. Office	840	SF	6	10+ years	
	AC Unit	2nd for Conference room. Next to room 203	1	EA	7	6-10 years	
	Ceiling - Lay-in	2nd for Conference room. Next to room 203	410	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd for Conference room. Next to room 203	37	SF	6	10+ years	
	Doors - Transom Window	2nd for Conference room. Next to room 203	7	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd for Conference room. Next to room 203	1	EA	6	10+ years	
	Floor - Carpet	2nd for Conference room. Next to room 203	285	SF	6	6-10 years	
	Floor - Carpet	2nd for Conference room. Next to room 203	10	SF	4	0-1 year	Floor uneven and damaged
	Floor - Wood	2nd for Conference room. Next to room 203	147	SF	6	10+ years	
	Floor - Wood	2nd for Conference room. Next to room 203	5	SF	4	0-1 year	Damaged
	Lighting - Lay-in	2nd for Conference room. Next to room 203	7	EA	7	6-10 years	
	Power Distribution	2nd for Conference room. Next to room 203	18	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd for Conference room. Next to room 203	1,332	SF	6	10+ years	
	Work SInk	2nd for Conference room. Next to room 203	1	EA	7	6-10 years	
	Ceiling - Lay-in	Basement, Engineer's Office	8	SF	7	6-10 years	
	Ceiling - Lay-in	Basement, Engineer's Office	247	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement, Engineer's Office	2	EA	6	10+ years	
	Floor - Tile	Basement, Engineer's Office	255	SF	6	10+ years	
	Lighting - Lay-in	Basement, Engineer's Office	2	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	Basement, Engineer's Office	2	EA	7	6-10 years	
	Walls - Masonry	Basement, Engineer's Office	280	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement, Engineer's Office	280	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Security Office in main office	116	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Security Office in main office	3	EA	6	•	
	Floor - Tile			SF	6	10+ years	
		Security Office in main office	116	_	-	10+ years	
	Lighting - Pendent/Surface	Security Office in main office	2	EΑ	6	6-10 years	
	Power Distribution	Security Office in main office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	Security Office in main office	430	SF	6	10+ years	

Campus Name: Oglesby Page : 11 of 29 Assessment Date: 04/25/2024



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Balcony Seating	1st Floor	40	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3,699	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	15	SF	4	0-1 year	Water damage
	Doors - Wood Doors inclu hw	1st Floor	6	EA	6	10+ years	
	Floor - Carpet	1st Floor	2,754	SF	6	6-10 years	
	Floor - Tile	1st Floor	960	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	10	EΑ	6	6-10 years	
	Main Floor Seating	1st Floor	200	EA	7	10+ years	
	Sound System	1st Floor	1	EΑ	7	6-10 years	
	Stage	1st Floor	835	SF	6	10+ years	
	Stage Curtain	1st Floor	2	EA	7	6-10 years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	14	LF	6	10+ years	
	Stairs - Wood	1st Floor	14	LF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	7,680	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	4	0-1 year	Water damage
_							
_Gymnas							
	Ceiling - Plaster/Drywall	3rd Floor	3,879	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Tile	3rd Floor	3,804	SF	6	10+ years	
	Floor - Tile	3rd Floor	75	SF	4	0-1 year	Chipped crack
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	6	EΑ	7	6-10 years	D 11 1
	Lighting - Metal Halide/Sodium Vapor	3rd Floor	13	EA	5	0-1 year	Don't work
	Scoreboards	3rd Floor	1	EΑ	7	6-10 years	
	Sound System	3rd Floor	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	5,150	SF	6	10+ years	
_Kitchen							
	Ceiling - Plaster/Drywall	Basement	720	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	ĒΑ	6	10+ years	
	Floor - Tile	Basement	720	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	12	ĒΑ	6	6-10 years	
	Serving Line	Basement	10	LF	6	10+ years	
	Storage/ Closet	Basement	57	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement	1,000	SF	6	10+ years	
	-		,			-	
Library							
	AC Unit	Basement	1	EA	7	6-10 years	
	Casework	Basement	120	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	1,245	SF	6	10+ years	



Catego	ory : Room		R	uilding	· Main		7040 C CICCH CTREET, Chicago, 12 00020
Catego	ny . Room			ananig	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
O. Gup	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	1,245	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	21	EA	6	6-10 years	
	Walls - Plaster/Drywall	Basement	1,640	SF	6	10+ years	
	valie i lactor/brywan	Bacomoni	1,010	O.	Ü	101 youro	
_Lunch &	Multipurpose Room						
	Ceiling - Exposed	Basement	1,105	SF	6	10+ years	
	Drinking Fountains - Single Water Cooler	Basement	2	EA	7	6-10 years	
	Floor - Tile	Basement	1,095	SF	6	10+ years	
	Floor - Tile	Basement	10	SF	4	1-2 years	Chipped and cracked
	Lighting - Pendent/Surface	Basement	16	EA	6	6-10 years	
	Market Board	Basement	10	LF	6	6-10 years	
	Serving Line	Basement	10	LF	6	10+ years	
	Walls - Masonry	Basement	2,722	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Basement	40	SF	6	10+ years	
						, , , , , , , , , , , , , , , , , , , ,	
_MDF_ID							
	Doors - Store Front	MDF/IDF room in room 200	2	EA	6	10+ years	
	Finishes	MDF/IDF room in room 200	250	SF	7	10+ years	
	Window AC Unit	MDF/IDF room in room 200	1	EA	7	6-10 years	
Mochan	ical/ Service Rooms						
_иеспап	Janitor's Closet	1st Floor	15	SF	5	10+ years	
	Storage Room	1st Floor	120	SF	7	10+ years	
	Vaults	1st Floor	40	SF	7	10+ years	
	Janitor's Closet	2nd Floor	15	SF	5	,	
				SF SF		10+ years	
	Janitor's Closet	3rd Floor	15	SF SF	7	10+ years	
	Air Intake Plenums	Basement	826		5	10+ years	
	Air Tunnel	Basement	3,610	SF	5	10+ years	
	Boiler Room	Basement	3,208	SF	5	10+ years	
	Coal Room	Basement	1,150	SF	5	10+ years	
	Janitor's Closet	Basement	629	SF	5	10+ years	
	Mechanical/ Service Rooms	Basement	1,156	SF	5	10+ years	
	Storage Room	Basement	927	SF	5	10+ years	
Restroo	m						
	Accessories	3rd floor Girls restroom	250	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor Girls restroom	250	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd floor Girls restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor Girls restroom	250	SF	6	10+ years	
	Floor Drain	3rd floor Girls restroom	1	EA	7	10+ years	
	Hand Dryer	3rd floor Girls restroom	1	EA	7	6-10 years	
	Lavatory	3rd floor Girls restroom	2	EA	6	10+ years	
	Lavaiory	ora moor dina restructii	2	ĽA	U	10+ years	



Catego	ry : Room		Building : Main							
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Pendent/Surface	3rd floor Girls restroom	4	EA	6	6-10 years				
	Partitions	3rd floor Girls restroom	5	EA	5	10+ years				
	Walls - Plaster/Drywall	3rd floor Girls restroom	256	SF	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	3rd floor Girls restroom	513	SF	7	10+ years				
	Water Closet	3rd floor Girls restroom	5	EA	7	10+ years				
	Accessories	3rd floor boys restroom	250	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	3rd floor boys restroom	250	SF	6	10+ years				
	Doors - Wood Doors inclu hw	3rd floor boys restroom	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	3rd floor boys restroom	250	SF	7	10+ years				
	Floor Drain	3rd floor boys restroom	1	EA	7	10+ years				
	Hand Dryer	3rd floor boys restroom	1	EA	7	6-10 years				
	Lavatory	3rd floor boys restroom	2	EA	7	10+ years				
	Lighting - Pendent/Surface	3rd floor boys restroom	4	EA	7	10+ years				
	Partitions	3rd floor boys restroom	2	EA	7	10+ years				
	Urinals	3rd floor boys restroom	3	EA	6	10+ years				
	Walls - Plaster/Drywall	3rd floor boys restroom	256	SF	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	3rd floor boys restroom	513	SF	7	10+ years				
	Water Closet	3rd floor boys restroom	2	EA	7	10+ years				
	Accessories	All Gender staff restroom, 2nd Floor	120	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	All Gender staff restroom, 2nd Floor	120	SF	7	10+ years				
	Ceiling - Plaster/Drywall	All Gender staff restroom, 2nd Floor	3	SF	7	10+ years				
	Doors - Wood Doors inclu hw	All Gender staff restroom, 2nd Floor	1	ĒΑ	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	All Gender staff restroom, 2nd Floor	120	SF	7	10+ years				
	Hand Dryer	All Gender staff restroom, 2nd Floor	1	ĒΑ	7	6-10 years				
	Lavatory	All Gender staff restroom, 2nd Floor	1	EA	7	10+ years				
	Lighting - Pendent/Surface	All Gender staff restroom, 2nd Floor	1	EA	7	6-10 years				
	Walls - Plaster/Drywall	All Gender staff restroom, 2nd Floor	45	SF	7	10+ years				
	Walls - Tile Ceramic/ Porcelain	All Gender staff restroom, 2nd Floor	300	SF	7	10+ years				
	Water Closet	All Gender staff restroom, 2nd Floor	1	ĒΑ	7	10+ years				
	Accessories	Boy's Toilet in Basement	950	SF	5	6-10 years				
	Ceiling - Plaster/Drywall	Boy's Toilet in Basement	950	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Boy's Toilet in Basement	2	ĒΑ	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Boy's Toilet in Basement	950	SF	6	10+ years				
	Floor Drain	Boy's Toilet in Basement	3	EA	7	10+ years				
	Lavatory	Boy's Toilet in Basement	2	EΑ	6	10+ years				
	Lighting - Pendent/Surface	Boy's Toilet in Basement	9	EΑ	7	6-10 years				
	Partitions	Boy's Toilet in Basement	3	EΑ	5	10+ years				
	Partitions	Boy's Toilet in Basement	1	EA	4	0-1 year	Missing portions			
	Urinals	Boy's Toilet in Basement	8	EA	6	10+ years	missing politorio			
	Walls - Tile Ceramic/ Porcelain	Boy's Toilet in Basement	2,349	SF	6	10+ years				
	Walls - Tile Ceramic/ Porcelain	Boy's Toilet in Basement	2,349	SF	4	0-1 year	Stepping cracks			
	Water Closet	Boy's Toilet in Basement	4	EA	6	10+ years	Otepping Clacks			
	Accessories	Girl's Toilet in Basement next to	768	SF	5	6-10 years				
	VOCESSOLIES	Lunchroom	100	SI-	5	o-10 years				
		LUIICIIIOOIII								



Catego	ry : Room		B	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	Girl's Toilet in Basement next to Lunchroom	768	SF	6	10+ years	
	Doors - Steel Doors incl hw	Girl's Toilet in Basement next to Lunchroom	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Girl's Toilet in Basement next to Lunchroom	768	SF	6	10+ years	
	Floor Drain	Girl's Toilet in Basement next to Lunchroom	2	EA	7	10+ years	
	Lavatory	Girl's Toilet in Basement next to Lunchroom	2	EA	6	10+ years	
	Lighting - Pendent/Surface	Girl's Toilet in Basement next to Lunchroom	9	EA	7	6-10 years	
	Partitions	Girl's Toilet in Basement next to Lunchroom	11	EA	5	10+ years	
	Partitions	Girl's Toilet in Basement next to Lunchroom	1	EA	4	1-2 years	Broken accessories
	Walls - Tile Ceramic/ Porcelain	Girl's Toilet in Basement next to Lunchroom	1,920	SF	6	10+ years	
	Water Closet	Girl's Toilet in Basement next to Lunchroom	12	EA	6	10+ years	
	Accessories	Restroom in 107	48	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in 107	48	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom in 107	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Restroom in 107	48	SF	6	10+ years	
	Lavatory	Restroom in 107	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Restroom in 107	1	EA	7	6-10 years	
	Partitions	Restroom in 107	1	EA	5	10+ years	
	Walls - Tile Ceramic/ Porcelain	Restroom in 107	255	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Restroom in 107	25	SF	4	0-1 year	Loose tile
	Water Closet	Restroom in 107	1	EA	6	10+ years	2000 1110
	Accessories	Restroom in Principals Office	40	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	Restroom in Principals Office	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom in Principals Office	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Restroom in Principals Office	40	SF	6	•	
		Restroom in Principals Office	40	Sr EA		10+ years	
	Lavatory Lighting - Pendent/Surface	Restroom in Principals Office	1	EA	6 7	10+ years	
	• •			SF		6-10 years	
	Walls - Tile Ceramic/ Porcelain	Restroom in Principals Office	260		7	10+ years	
	Water Closet	Restroom in Principals Office	1	EA	6	10+ years	
	Accessories	Restroom in boiler room	27	SF	5	6-10 years	
	Ceiling - Exposed	Restroom in boiler room	27	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom in boiler room	1	EA	6	10+ years	
	Floor - Tile	Restroom in boiler room	27	SF	5	10+ years	
	Lavatory	Restroom in boiler room	1	EA	6	10+ years	
	Lighting - Wall Mounted	Restroom in boiler room	1	EA	7	6-10 years	



Richard J Oglesby Elementary School

7646 S Green STREET, Chicago, IL 60620

Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Restroom in boiler room	220	SF	6	10+ years	
	Water Closet	Restroom in boiler room	1	EA	6	10+ years	
	Accessories	Restroom in room 201	56	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Restroom in room 201	56	SF	7	10+ years	
	Doors - Transom Window	Restroom in room 201	15	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Restroom in room 201	1	EA	6	10+ years	
	Floor - Tile	Restroom in room 201	56	SF	6	6-10 years	
	Lavatory	Restroom in room 201	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Restroom in room 201	1	EA	6	6-10 years	
	Partitions	Restroom in room 201	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Restroom in room 201	209	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Restroom in room 201	140	SF	6	10+ years	
	Water Closet	Restroom in room 201	1	EA	6	10+ years	
	Accessories	Restroom inside 101 classroom	48	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Restroom inside 101 classroom	48	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Restroom inside 101 classroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Restroom inside 101 classroom	48	SF	7	10+ years	
	Floor Drain	Restroom inside 101 classroom	1	EA	7	10+ years	
	Lavatory	Restroom inside 101 classroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Restroom inside 101 classroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	Restroom inside 101 classroom	120	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	Restroom inside 101 classroom	160	SF	7	10+ years	
	Water Closet	Restroom inside 101 classroom	1	EA	7	10+ years	

Category: Classroom

Building: Main Recommend Location Group Item - Type Quantity **UOM** Rank Replacement Comments Classroom #003 (Store Room) AC Units Basement 1 EΑ 5 6-10 years LF Casework Basement 30 6 10+ years Ceiling - Plaster/Drywall 870 SF 10+ years Basement 6 Chalk Board **Basement** 70 LF 4 2-5 years Doors - Wood Doors inclu hw **Basement** EΑ 6 10+ years 1 10+ years Floor - Tile SF 6 Basement 862 Floor - Tile Basement 8 SF 1-2 years Cracked Lighting - Pendent/Surface **Basement** 14 EΑ 7 6-10 years Marker Board LF 6-10 years Basement 10 6 SF Storage/ Closet Basement 193 5 10+ years Walls - Plaster/Drywall SF Basement 1,130 6 10+ years Classroom #005 (Store Room) **AC Units** Basement 1 EΑ 7 6-10 years LF Casework **Basement** 30 6 10+ years Ceiling - Plaster/Drywall SF Basement 590 6 10+ years

Campus Name: Oglesby Page: 16 of 29 Assessment Date: 04/25/2024



Catego	ry : Classroom		В	uilding	: Main		
_				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	Basement	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Tile	Basement	580	SF	6	10+ years	
	Floor - Tile	Basement	10	SF	4	0-1 year	Broken and chipped
	Lighting - Pendent/Surface	Basement	10	EA	7	6-10 years	
	Marker Board	Basement	10	LF	6	6-10 years	
	Walls - Masonry	Basement	600	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	600	SF	6	10+ years	
Classroo	om #005A (Other Instructional Use)						
	AC Units	Basement	1	EA	7	6-10 years	
	Casework	Basement	30	LF	6	10+ years	
	Ceiling - Plaster/Drywall	Basement	590	SF	6	10+ years	
	Chalk Board	Basement	70	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	Basement	1	EΑ	6	10+ years	
	Floor - Tile	Basement	9	SF	7	10+ years	
	Floor - Tile	Basement	581	SF	6	10+ years	
	Lighting - Pendent/Surface	Basement	8	EA	7	6-10 years	
	Walls - Masonry	Basement	200	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	760	SF	6	10+ years	
Classroo	om #007 (Art Room)						
	AC Units	Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement	903	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Basement	1	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Basement	903	SF	7	10+ years	
	Lighting - Pendent/Surface	Basement	14	EA	6	6-10 years	
	Storage/ Closet	Basement	217	SF	5	10+ years	
	Walls - Plaster/Drywall	Basement	2,257	SF	6	10+ years	
Classroo	om #100 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,115	SF	6	10+ years	
	Chalk Board	1st Floor	70	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,105	SF	7	10+ years	
	Floor - Tile	1st Floor	10	SF	4	0-1 year	Chipped
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	•
	Marker Board	1st Floor	10	LF	6	6-10 years	
	Storage/ Closet	1st Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,645	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main				
Croun	Itam Tuna	Location	Quantity	UOM	Rank	Recommend	Comments		
Group	Item - Type	Location	Quantity	UOW	Kalik	Replacement	Comments		
Classroc	m #101 (Pre School)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	80	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	1,115	SF	6	10+ years			
	Doors - Transom Window	1st Floor	8	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	1,115	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	14	EA	6	6-10 years			
	Storage/ Closet	1st Floor	217	SF	5	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,620	SF	6	10+ years			
	Work Sink	1st Floor	3	EA	7	6-10 years			
Classroo	m #102 (Kindergarten)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	30	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	1,115	SF	6	10+ years			
	Chalk Board	1st Floor	70	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	8	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	1,095	SF	7	10+ years			
	Floor - Tile	1st Floor	20	SF	4	0-1 year	Cracked		
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years			
	Marker Board	1st Floor	20	LF	6	6-10 years			
	Storage/ Closet	1st Floor	217	SF	5	2-5 years			
	Walls - Plaster/Drywall	1st Floor	1,720	SF	6	10+ years			
Classroo	m #104 (Music Room)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	30	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	1,115	SF	6	10+ years			
	Chalk Board	1st Floor	70	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years			
	Floor - Tile	1st Floor	1,105	SF	7	10+ years			
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Cracked		
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years			
	Marker Board	1st Floor	8	LF	6	6-10 years			
	Storage/ Closet	1st Floor	217	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,720	SF	6	10+ years			
Classroo	m #105 (Office)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	30	LF	6	10+ years			
	Cacamoni	1001	00		Ü	ioi youis			



	Catego	ry : Classroom		В	uilding	: Main		
Celling - Plaster/Dywall								
Chaik Board	Group			Quantity		Rank		Comments
Doors - Transom Window		Ceiling - Plaster/Drywall		1,115		6		
Doors - Wood Doors inclu hw				70		4	2-5 years	
Floor - Tile		Doors - Transom Window	1st Floor	9	SF	6	10+ years	
Lighting - Pendent/Surface		Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Lighting - Pendent/Surface		Floor - Tile	1st Floor	1,115	SF	7	10+ years	
Marker Board		Lighting - Pendent/Surface	1st Floor	14	EA	6	-	
Storage/ Closet 1st Floor 217 SF 5 10+ ýears			1st Floor	20	LF	6	6-10 years	
Section Sect		Storage/ Closet			SF	5		
AC Units		Walls - Plaster/Drywall					•	
Casework	Classroc	om #106 (Regular Classroom)						
Casework		AC Units	1st Floor	2		7	6-10 years	
Ceiling - Plaster/Drywall						6		
Ceiling - Plaster/Drywall		Ceiling - Plaster/Drywall	1st Floor	1,110	SF	6		
Chalk Board 1st Floor 70 LF 4 2-5 years Doors - Transom Window 1st Floor 9 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Tile 1st Floor 75 SF 4 0-1 years Hissing Lighting - Pendent/Surface 1st Floor 10 LF 6 6-10 years Marker Board 1st Floor 10 LF 6 6-10 years Storage/ Closet 1st Floor 11 EA 7 6-10 years Walls - Plaster/Drywall 1st Floor 16-10 Years Doors - Transom Window 1st Floor 16-10 Years Doors - Transom Window 1st Floor 19-10 Years Doors - Tile 1st Floor 19-10 Years Doors - Tile 1st Floor 19-10 Years Doors - Tile 1st Floor 19-10 Years Floor 19-10 Years Doors - Tile 1st Floor 19-10 Years Doors - Tile 1st Floor 19-10 Years Floor 19-10 Years Floor 19-10 Years Floor Tile 1st Floor 19-10 Years Floor 19-10 Years Floor Tile 1st Floor 19-10 Years Floor 19-10 Years Floor Tile 1st Floor 19-10 Years Floor 19-10 Years Floor Tile 1st Floor 19-10 Years Storage/ Closet 1st Floor 10-10 Years Storage/ Closet 1st Floor 11-10 Years Year Year Year Year Year Year Year Year			1st Floor		SF	5		Cracked
Doors - Transom Window				70	LF	4		
Doors - Wood Doors inclu hw								
Floor - Tile						-		
Floor - Tile							•	
Lighting - Pendent/Surface 1st Floor 14 EA 7 6-10 years Marker Board 1st Floor 10 LF 6 6-10 years Storage/ Closet 1st Floor 217 SF 5 10+ years Walls - Plaster/Drywall 1st Floor 1,695 SF 6 10+ years AC Units Casework 1st Floor 2 EA 7 6-10 years Ceiling - Plaster/Drywall 1st Floor 30 LF 6 10+ years Coiling - Plaster/Drywall 1st Floor 1,115 SF 6 10+ years Doors - Transom Window 1st Floor 1 EA 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Tile 1st Floor 1,105 SF 7 10+ years Floor - Tile 1st Floor 10 SF 4 1-2 years Chipped Lighting - Pendent/Surface 1st Floor 14 EA 6 6-10 years Storage/ Closet 1st Floor 167 SF 5 10+ years Walls - Plaster/Drywall 1st Floor 1 EA 7 6-10 years AC Units 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 1 EA 7 6-10 years Ceiling - Plaster/Drywall 2nd Floor 1 EA 7 6-10 years Ceiling - Plaster/Drywall								Missing
Marker Board								wildering
Storage Closet 1st Floor 217 SF 5 10+ years								
Section #107 (Other Instructional Use)								
AC Units							•	
Casework 1st Floor 30 LF 6 10+ years Ceiling - Plaster/Drywall 1st Floor 1,115 SF 6 10+ years Doors - Transom Window 1st Floor 8 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Tile 1st Floor 1,105 SF 7 10+ years Floor - Tile 1st Floor 10 SF 4 1-2 years Chipped Lighting - Pendent/Surface 1st Floor 14 EA 6 6-10 years Chipped Lighting - Pendent/Surface 1st Floor 167 SF 5 10+ years Chipped Lighting - Pendent/Surface 1st Floor 167 SF 5 10+ years Chipped Walls - Plaster/Drywall 1st Floor 1 EA 7 6-10 years A 10+ years AC Units 2nd Floor 1 EA 7 6-10 years A 10+ years Casework 2nd Floor 8 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 876 SF 6 10+ years Doors - Transom Window 2nd Floor 9 SF 6 10+ years </td <td>Classroo</td> <td>om #107 (Other Instructional Use)</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td>	Classroo	om #107 (Other Instructional Use)						
Casework 1st Floor 30 LF 6 10+ years Ceiling - Plaster/Drywall 1st Floor 1,115 SF 6 10+ years Doors - Transom Window 1st Floor 8 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Tile 1st Floor 1,105 SF 7 10+ years Floor - Tile 1st Floor 10 SF 4 1-2 years Chipped Lighting - Pendent/Surface 1st Floor 14 EA 6 6-10 years Chipped Lighting - Pendent/Surface 1st Floor 167 SF 5 10+ years Chipped Lighting - Pendent/Surface 1st Floor 167 SF 5 10+ years Chipped Walls - Plaster/Drywall 1st Floor 1 EA 7 6-10 years A 10+ years AC Units 2nd Floor 1 EA 7 6-10 years A 10+ years Casework 2nd Floor 8 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 876 SF 6 10+ years Doors - Transom Window 2nd Floor 9 SF 6 10+ years </td <td></td> <td>AC Units</td> <td>1st Floor</td> <td>2</td> <td>EA</td> <td>7</td> <td>6-10 years</td> <td></td>		AC Units	1st Floor	2	EA	7	6-10 years	
Ceiling - Plaster/Drywall 1st Floor 1,115 SF 6 10+ years Doors - Transom Window 1st Floor 8 SF 6 10+ years Doors - Wood Doors inclu hw 1st Floor 1 EA 6 10+ years Floor - Tile 1st Floor 1,105 SF 7 10+ years Floor - Tile 1st Floor 10 SF 4 1-2 years Chipped Lighting - Pendent/Surface 1st Floor 14 EA 6 6-10 years Storage/ Closet 1st Floor 167 SF 5 10+ years Walls - Plaster/Drywall 1st Floor 1,620 SF 6 10+ years assroom #200 (Regular Classroom) AC Units 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 8 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 876 SF 6 10+ years Doors - Transom Window 2nd Floor		Casework						
Doors - Transom Window		Ceiling - Plaster/Drywall					•	
Doors - Wood Doors inclu hw		,				6	,	
Floor - Tile							,	
Floor - Tile				1.105				
Lighting - Pendent/Surface 1st Floor 14 EA 6 6-10 years Storage/ Closet 1st Floor 167 SF 5 10+ years Walls - Plaster/Drywall 1st Floor 1,620 SF 6 10+ years assroom #200 (Regular Classroom) AC Units 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 8 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 876 SF 6 10+ years Doors - Transom Window 2nd Floor 9 SF 6 10+ years				,	_		-	Chipped
Storage/ Closet 1st Floor 167 SF 5 10+ years Walls - Plaster/Drywall 1st Floor 1,620 SF 6 10+ years assroom #200 (Regular Classroom) AC Units 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 8 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 876 SF 6 10+ years Doors - Transom Window 2nd Floor 9 SF 6 10+ years								opp ou
Walls - Plaster/Drywall 1st Floor 1,620 SF 6 10+ years assroom #200 (Regular Classroom) AC Units 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 8 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 876 SF 6 10+ years Doors - Transom Window 2nd Floor 9 SF 6 10+ years								
AC Units 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 8 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 876 SF 6 10+ years Doors - Transom Window 2nd Floor 9 SF 6 10+ years					_	_	-	
AC Units 2nd Floor 1 EA 7 6-10 years Casework 2nd Floor 8 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 876 SF 6 10+ years Doors - Transom Window 2nd Floor 9 SF 6 10+ years	Classroc	om #200 (Regular Classroom)						
Casework2nd Floor8 LF6 10+ yearsCeiling - Plaster/Drywall2nd Floor876 SF6 10+ yearsDoors - Transom Window2nd Floor9 SF6 10+ years			2nd Floor	1	EA	7	6-10 years	
Ceiling - Plaster/Drywall 2nd Floor 876 SF 6 10+ years Doors - Transom Window 2nd Floor 9 SF 6 10+ years				· · · · · · · · · · · · · · · · · · ·				
Doors - Transom Window 2nd Floor 9 SF 6 10+ years						-		
,		Doors - Transom Window						
2 EA TOT YEARS							•	
				•	_, .	Ŭ	.c. youro	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	846	SF	7	10+ years	
	Floor - Tile	2nd Floor	30	SF	4	0-1 year	Cracked
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	96	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,160	SF	6	10+ years	
Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	1,231	SF	6	10+ years	
				SF	6		
	Doors - Transom Window	2nd Floor	9			10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,181	SF	7	10+ years	
	Floor - Tile	2nd Floor	50	SF	4	0-1 year	Cracked
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	219	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,100	SF	6	10+ years	
Classroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,086	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,086	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	215	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,517	SF	6	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	1,153	SF	6	10+ years	
	Chalk Board	2nd Floor	54	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor 2nd Floor	21	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	•	
				SF		10+ years	
	Floor - Wood	2nd Floor	1,153		6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	217	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,562	SF	6	10+ years	



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,086	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,086	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,570	SF	6	10+ years	
	walls - Plaster/Drywall	2110 F1001	1,570	SF	О	10+ years	
Classroc	om #205 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,150	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	1,150	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	6	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor		SF			
	vvalis - Plaster/Drywali	2nd Floor	2,504	SF	6	10+ years	
Classroo	om #206 (Store Room)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,220	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	1,100	SF	6	6-10 years	
	Floor - Tile	2nd Floor	120	SF	4	0-1 year	Chipped
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	Chippod
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,412	SF	6	10+ years	
	Walls - Plaster/Drywall Walls - Plaster/Drywall	2nd Floor	2,412	SF SF	5	0-1 year	Water damage
			10	SF	5 5		
	Walls - Plaster/Drywall	2nd Floor	1	5F	5	0-1 year	Hole
Classroo	om #207 (Vacant)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	6	10+ years	
			· ·		-	- ,	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	1,220	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,204	SF	6	10+ years	
	Floor - Tile	2nd Floor	16	SF	4	0-1 year	Chipped and cracked
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	217	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,423	SF	6	10+ years	
Classroo	om #300 (Other Instructional Use)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,245	SF	6	10+ years	
	Chalk Board	3rd Floor	48	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,245	SF	6	10+ years	
		3rd Floor			7	•	
	Lighting - Pendent/Surface		16	EA		6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	217	SF	5	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	2,533	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	4	1-2 years	Cracked
Classroo	om #301 (Other Instructional Use)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,231	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,231	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,442	SF	6	10+ years	
Classroo	om #302 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,086	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	DOOLS - MOOR DOOLS HICK LIM	SIU FIOOI	2	ĽA	O	io+ years	



Catego	ry : Classroom		В	uilding	: Main		
					Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	3rd Floor	1,086	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	217	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,513	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4	SF	4	1-2 years	Cracked
Classroo	om #303 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,163	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,159	SF	7	10+ years	
	Floor - Wood	3rd Floor	4	SF	5	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	Chipped
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	217	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,562	SF	6	10+ years	
	walls - Flastel/Drywall	Sid Floor	2,502	SI	O	10+ years	
lassroo	om #304 (Regular Classroom)	0.15				0.40	
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,140	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	0-1 year	Water damage
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	1,100	SF	6	10+ years	
	Floor - Tile	3rd Floor	50	SF	5	0-1 year	Chipped
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	40	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	217	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,435	SF	6	10+ years	
lassroo	om #305 (Other Instructional Use)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,150	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Wood	3rd Floor	1,150	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	30	LF	7	6-10 years	
						J 10 , Julio	



Catego	ry : Classroom		В	uilding	: Main		-
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	3rd Floor	217	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,509	SF	6	10+ years	
Classroo	om #306 (Regular Classroom)						
	AC Units	3rd Floor	2	EΑ	7	6-10 years	
	Casework	3rd Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	1,220	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	1,220	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	6-10 years	
				SF			
	Floor - Wood	3rd Floor	1,220		6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	0-1 year	In storage room
	Marker Board	3rd Floor	36	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	5	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,640	SF	6	10+ years	
Classroc	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,217	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	3	SF	5	0-1 year	Peeling
	Doors - Transom Window	3rd Floor	9	SF	6	10+ years	i ceiling
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	•	
				SF		10+ years	
	Floor - Wood	3rd Floor	1,220		7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	217	SF	5	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	2,423	SF	6	10+ years	
Catego	ry : Interior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor_	· ·	200000	Quantity		- Collit	. topia on in on	
	Ceiling - Lay-in	1st Floor	2,613	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	14	SF	4	0-1 year	Broken
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,627	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	20	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	4,290	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	2,437	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor		EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,437	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	18	EA	7	6-10 years	



Catego	Category : Interior		В	-			
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	4,050	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	2,433	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	4	SF	4	0-1 year	Broken
	Drinking Fountains - Single Fountain	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2,427	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	10	SF	4	1-2 years	Cracked
	Lighting - Lay-in	3rd Floor	33	EA	7	6-10 years	
	Student Lockers - Three Tiers	3rd Floor	72	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4,050	SF	6	10+ years	
	Ceiling - Exposed	Basement	2,682	SF	5	10+ years	
	Drinking Fountains - Single Fountain	Basement	2	EA	7	10+ years	
	Floor - Asphalt Floor	Basement	2,600	SF	5	10+ years	
	Floor - Tile/Sheet	Basement	82	SF	5	6-10 years	
	Lighting - Pendent/Surface	Basement	40	EA	6	6-10 years	
	Student Lockers - One Tier	Basement	14	EA	6	10+ years	
	Walls - Masonry	Basement	6,705	SF	6	10+ years	
Safety							
	Camera Viewing Station	1st Floor	4	EA	7	6-10 years	
	Security Cameras	1st Floor	10	EA	7	6-10 years	
	Security Cameras	1st Floor	2	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	East	2,290	SF	7	10+ years	
	Floor - Tile	East	1,056	SF	7	10+ years	
	Handrails	East	380	LF	7	10+ years	
	Lighting - Pendent/Surface	East	12	EA	7	10+ years	
	Lighting - Wall Mounted	East	4	EA	7	10+ years	
	Stairs - Asphalt	East	190	LF	7	10+ years	
	Walls - Plaster/Drywall	East	8,056	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Middle stair	450	SF	7	10+ years	
	Floor - Tile	Middle stair	450	SF	7	10+ years	
	Handrails	Middle stair	120	LF	7	10+ years	
	Lighting - Pendent/Surface	Middle stair	4	EA	7	10+ years	
	Stairs - Asphalt	Middle stair	280	LF	7	10+ years	
	Walls - Plaster/Drywall	Middle stair	850	SF	7	10+ years	
	Ceiling - Plaster/Drywall	West	2,290	SF	6	10+ years	
	Floor - Tile	West	1,056	SF	6	10+ years	
	Handrails	West	380	LF	5	10+ years	
	Lighting - Pendent/Surface	West	12	EA	7	6-10 years	
	Lighting - Wall Mounted	West	4	EA	7	6-10 years	
	Stairs - Asphalt	West	190	LF	6	10+ years	
	Walls - Plaster/Drywall	West	8,056	SF	6	10+ years	



Category : Interior	Building : Main							
Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
Vertical Conveyance								
Wheelchair Lift - Platform Lift	1st Floor	1	EA	7	10+ years			

Campus Name: Oglesby Page : 26 of 29 Assessment Date: 04/25/2024



Category : Site	Building : Site

Calego	ry . Site		В	unung			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	13	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	5	10+ years	
	C					j	
Fencing							
·	Fencing - New Standard Ornamental	Entire Site	1,485	LF	6	10+ years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	155	LF	6	6-10 years	
_Landsca	•						
	Benches	Entire Site	2	EA	7	10+ years	
	Landscape - Grass	Entire Site	20,420	SF	6	10+ years	
	Landscape - Grass	Entire Site	2,000	SF	5	2-5 years	
	Lighting - Pole Mounted	Entire Site	2	EΑ	7	10+ years	
	Parkway trees	Entire Site	34	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	3,825	SF	6	10+ years	
	Play Area - Hardscape- Concrete	Entire Site	6,760	SF	7	10+ years	
	Play Area - Synthetic Turf	Entire Site	9,850	SF	7	10+ years	
	Trash Receptacles	Entire Site	3	EA	6	6-10 years	
Parking	Lot						
arking_	Concrete Curbs	NE	680	LF	6	10+ years	
	Interior Plantings	NE	1,399	LF	6	10+ years	
	Interior Plantings	NE	1,399	LF	4	0-1 year	Missing tree
	Surface - Asphalt	NE	23,500	SF	6	6-10 years	wissing tree
	Surface - Asphalt	NE	500	SF	4	0-10 years 0-1 year	Holes, spalling
	Trash Enclosure - Masonry	NE	1,185	SF	5	2-5 years	rioles, spailing
	Vehicular Screening	NE	80	LF	6	10+ years	
	Vernicular Screening	INL	80	LI	U	10+ years	
Playgrou	und						
	Equipment - School Age 5-12	SE	1	EA	7	10+ years	
	Surface - Poured Surface	SE	1,975	SF	7	10+ years	
			·			j	
Sidewall							
	Sidewalks - Internal Walks	Entire Site	675	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	16,724	SF	6	10+ years	
0:							
Signage		F :: 0::				40	
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back lighted w/	Entire Site	1	EA	6	10+ years	
	LED						



Building: Site Category: Site

						Recommena	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Monument - Building Mounted Cut Letter	Entire Site	2	EA	7	10+ years	
	Sign						

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Oglesby Page: 28 of 29 Assessment Date: 04/25/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Art Room	Basement	007	007	903	144	60	Y	N
Kindergarten	Regular Classroom	1st Floor	100	100	1,115	175	88	N	Υ
Kindergarten	Regular Classroom	1st Floor	102	102	1,115	100	50	N	Υ
Music Room	Regular Classroom	1st Floor	104	104	1,115	100	75	N	Υ
Office	Regular Classroom	1st Floor	105	105	1,115	150	75	N	Υ
Other Instructional Use	Kindergarten	1st Floor	107	107	1,115	200	100	N	N
Other Instructional Use	Regular Classroom	3rd Floor	300	300	1,245	175	60	N	Υ
Other Instructional Use	Regular Classroom	3rd Floor	301	301	1,231	205	75	N	Y
Other Instructional Use	Regular Classroom	3rd Floor	305	305	1,150	175	70	N	Y
Other Instructional Use	Regular Classroom	Basement	005A	005A	590	40	30	N	N
Pre School	Kindergarten	1st Floor	101	101	1,115	200	88	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	1,115	125	63	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	876	120	30	N	Y
Regular Classroom	Regular Classroom	2nd Floor	201	201	1,231	205	75	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	1,086	135	40	N	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	1,153	175	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	1,086	66	30	N	N
Regular Classroom	Regular Classroom	2nd Floor	205	205	1,150	175	70	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	302	302	1,086	135	30	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	303	303	1,163	175	70	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	1,150	135	30	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	306	306	1,220	135	30	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	307	307	1,220	225	75	N	Υ
Store Room	Regular Classroom	2nd Floor	206	206	1,220	135	30	N	Υ
Store Room	Regular Classroom	Basement	003	003	870	80	40	N	Υ
Store Room	Regular Classroom	Basement	005	005	590	60	30	N	N
Vacant	Office	2nd Floor	207	207	1,220	130	60	N	Υ