

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1913	3	62,706
Campus Total			62,706

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Cell Equ	ipment						
	Cell Equipment - Antenna	Entire Building	6	EA	7	10+ years	
	Cell Equipment - Cabinets	Entire Building	2	EA	7	10+ years	
	Cell Equipment - Generator	Entire Building	1	EA	7	10+ years	
_Entrance							
	Entrance Control - Audio and Video	1 - Main	1	EA	6	10+ years	
	Exterior Doors - Store Front	1 - Main	4	EA	6	6-10 years	Verified that paint is peeled off. Wood is in fair condition, and it is only the trim.
	Exterior Doors - Transom Lite	1 - Main	8	EA	7	10+ years	
	Exterior Stairs - Concrete	1 - Main	16	LF	5	1-2 years	Cracked step and landing
	Power Door Operator and Controls	1 - Main	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	1 - Main	50	LF	5	6-10 years	
	Ramps - Concrete	1 - Main	24	LF	5	1-2 years	Cracked concrete, corroding rail posts are cracking concrete
	Stair Handrail - Steel_Stair Handrail	1 - Main	15	LF	6	10+ years	1
	Entrance Control - Audio and Video	2	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	2	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	2	3	EA	6	10+ years	
	Exterior Stairs - Concrete	2	24	LF	6	10+ years	
	Power Door Operator and Controls	2	1	EA	4	0-1 year	Not working
	Entrance Control - Audio and Video	3	1	EA	6	10+ years	-
	Exterior Doors - Exterior Steel Door	3	3	EA	5	1-2 years	Corroding door and frame
	Exterior Doors - Transom Lite	3	3	EA	6	10+ years	-



7037 S Rhodes AVENUE, Chicago, IL 60637 **Category : Exterior Building : Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Exterior Stairs - Concrete 3 36 LF 6 10+ vears Ramp Handrail - Steel Ramp Handrail 3 20 LF 7 10+ years Ramps - Concrete 3 25 LF 7 10+ years Stair Handrail - Steel Stair Handrail 3 6 LF 7 10+ years 5 Exterior Doors - Exterior Wood Door 4 EΑ 4 0-1 year Rotting doors and frames 5 6 Exterior Doors - Transom Lite 4 EΑ 10+ years **Exterior Stairs - Concrete** 4 120 LF 5 0-1 year Cracked, broken, chips at nosing Exterior Doors - Exterior Steel Door 5 1 ΕA 6 10+ years Ramps - Concrete 5 3 LF 5 0-1 year Slope outside of door damaged. Foundation Foundation - Masonry Entire Building 817 LF 7 10+ years Superstructure - Steel with Clay Tile Arch SF 7 Entire Building 62,706 10+ years Liahtina Exterior Lighting - Wall Mounted Entire Building 6 ΕA 6 10+ years Exterior Lighting - Wall Mounted Entire Building 3 ΕA 6 10+ years Roof System Access Ladder - Metal А 1 ΕA 7 10+ years Access Ladder - Metal A 1 EΑ 4 0-1 year Not attached LF A 5 Coping - Metal 594 1-2 years Corroded LF 6 10+ years Downspouts - Interior Downspouts А 348 LF 7 Parapet - 16" - 30" Height А 102 10+ years LF Parapet - 16" - 30" Height А 20 5 1-2 years Open Joyce, loose brick, spalling, crumbling wall. Interior and exterior of parapet. LF Parapet - Parapet > 30" А 372 7 10+ vears Parapet - Parapet > 30" A 100 LF 6 10+ years Roof - Asphalt Gravel Ballast SF A 50,388 6 10+ years Roof Hatch - Metal ΕA 7 10+ years A 2 SF 7 Roof Structure - Steel with Clay Tile Arch A 50,388 10+ years Access Ladder - Metal В FΑ 7 1 10+ years В LF Coping - Metal 60 6 10+ years В LF Coping - Stone 208 6 10+ years LF Downspouts - Interior Downspouts В 52 6 10+ vears Parapet - 16" - 30" Height В 218 LF 7 10+ years Parapet - Parapet < 16" Height В 50 LF 7 10+ years Roof - Asphalt Gravel Ballast В SF 8.178 6 10+ years Roof Structure - Steel with Clay Tile Arch В SF 7 10+ years 8,178 Chimney - Brick Chimney- Concrete/ Mortar С LF 50 6 10+ years Liner Chimney - Brick Chimney- Concrete/ Mortar С 50 LF 5 1-2 years Open joints



7037 S Rhodes AVENUE, Chicago, IL 60637 **Category : Exterior Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Liner С LF 203 6 10+ vears Coping - Metal **Downspouts - Interior Downspouts** С 54 LF 6 10+ years Parapet - 16" - 30" Height С LF 7 84 10+ years С 1 F Parapet - Parapet < 16" Height 19 7 10+ years С LF Parapet - Parapet > 30" 7 100 10+ years Roof - Asphalt Gravel Ballast С 4,120 SF 10+ years 6 С SF Roof - Asphalt Gravel Ballast 20 3 1-2 years Leak at downspout Roof Structure - Steel with Clay Tile Arch С 4.140 SF 7 10+ vears Walls Canopy - Concrete/ Stucco Entire Building 36 SF 5 10+ years Cheek-Wall - Stone Entire Building SF 6 10+ vears 135 LF Cornice - Cast Stone Entire Building 225 5 10+ years Cornice - Masonry Projecting Limestone 794 LF 6 Entire Building 10+ vears Cornice - Metal Projecting Entire Building 600 LF 5 0-1 year Corroding SF 7 Exterior Walls - Brick Entire Building 35.382 10+ years SF Exterior Walls - Brick Entire Building 505 5 10+ years SF Exterior Walls - Brick Entire Building 200 4 1-2 years Open joints, cracked brick 3.268 SF 6 Exterior Walls - Stone-Cast Entire Building 10+ years Windows SF Guard - Guards perforated Entire Building 20 6 10+ years SF Guard - Guards perforated Entire Building 1.671 6 10+ years Guard - Guards wire guard Entire Building 21 SF 6 10+ years 300 LF 7 Lintels - Steel Entire Building 10+ vears LF Lintels - Steel Entire Building 427 6 10+ years SF Storefront Windows Entire Building 81 6 10+ years Windows - Louver Entire Building 99 SF 6 10+ years SF Windows - Louver Entire Building 15 4 1-2 years Corroded SF 6 Windows - Sash Aluminum Double-pane Entire Building 5,789 10+ years **Category : Electrical Building : Main** Recommend Replacement Item - Type Location Quantity UOM Comments Group Rank Emergency System Security System - CCTV Boiler Room SF 7 62,706 6-10 years New devices present Security System - Intrusion Detection Boiler Room 62.706 SF 6-10 years 6 Emergency A/C Power - Corridors and Entire Building 11.464 SF 6 10+ years Stairs Emergency A/C Power - Gym Entire Building 5.611 SF 6 10+ years Exit Signs - Auditoium FΑ Entire Building 5 6 6-10 years

Quantity updated to observed conditions



7037 S Rhodes AVENUE, Chicago, IL 60637 **Category : Electrical Building : Main** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Exit Signs - Corridors and Stairs Entire Building 12 ΕA 6 6-10 vears Exit Signs - Gvm ΕA Entire Building 1 6 6-10 years Quantity updated to reflect observed conditions 2 ΕA 6 Exit Signs - Lunchroom Entire Building 6-10 years **Emergency Battery Packs - Corridors and** Entire Building 8 FA 4 0-1 year Vintage Stairs Emergency Battery Packs - Gym 3 ΕA 4 0-1 year Vintage units Entire Building **Emergency Generator- Indoor- Natural Gas** Generator Room 1 ΕA 6 10+ years - Below 60 KW Automatic Transfer Switch Mechanical Room 3 FΑ 6 Quantity updated to reflect observed 10+ years conditions Main Service SF PA System 1st Floor 62.706 4 2-5 years Replacement needed, no control over which rooms receive announcements. System is antiquated, obsolete. Independent Electrical Service for Basement 1 FΑ 6 10+ years emergency power Main Electrical Service - 1200 A Electrical Room 1 EΑ 4 1-2 years Some corrosion - older unit. 120/208/3PH Power Distribution Lighting and Power Panels - 100 A Entire Building 2 EΑ 6 10+ years Lighting and Power Panels - 100 A 2 ΕA Entire Building 6 10+ years Quantity change to match current observation Lighting and Power Panels - 100 A Entire Building 1 ΕA 4 0-1 year Missing breaker presents live front condition ΕA Lighting and Power Panels - Above 100 A 6 7 Quantity change to match current Entire Building 10+ years observation Lighting and Power Panels - Above 100 A Entire Building 1 FΑ 7 10+ years Gym teacher office Lighting and Power Panels - Above 100 A 5 ΕA Entire Building 6 10+ years Lighting and Power Panels - Above 100 A Entire Building 1 ΕA 6 10+ years Main Distribution Panels - 400 - 600 amp Entire Building ΕA 1 4 0-1 year Older panel. Main Distribution Panels - Greater than 600 **Entire Building** 1 EΑ 7 10+ years amp

Category : Fire Protection		B	uilding	: Main		
Group Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alarm						
Fire ALarm Anunciator	Entire Building	1	EA	7	10+ years	
Fire Alarm Panel	Entire Building	1	EA	7	10+ years	
Fire Alarm Strobe Lights	Entire Building	62,706	SF	7	10+ years	New devices on all three floors



7037 S Rhodes AVENUE, Chicago, IL 60637 **Category : Fire Protection Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments SF Fire Alarm_System Entire Building 62.706 7 10+ vears **Category : Mechanical Building : Main** Recommend Location Item - Type Quantity UOM Rank Replacement **Comments** Group Air Handling Systems FΑ Air Handling Unit- Built Up- Multi Zone- Hot Mechanical Room - AHU-S1 and 1 5 AHU-S1, serves gym and auditorium 6-10 years Water Coils - 25001 - 35000 cfm AHU-S2 and some classrooms north side. Air Handling Unit- Built Up- Multi Zone- Hot Mechanical Room - AHU-S1 and 1 EΑ 5 6-10 years AHU-S2 serves classrooms, corridors Water Coils - Greater than 35000 cfm AHU-S2 and toilets. Air Intake Mechanical Room - AHU-S1 and 2 ΕA 6 6-10 years AHU-S2 Auxiliaries - 25001 - 35000 cfm Mechanical Room - AHU-S1 and FΑ 1 5 10+ years AHU-S2 Mechanical Room - AHU-S1 and Auxiliaries - Greater than 35000 cfm 1 FΑ 6 10+ years New motor AHU-S2 Return Duct Work - Indoor- Vertical Shaft Mechanical Room - AHU-S1 and 60 LF 6 10+ years AHU-S2 and Ducts Zone Dampers Mechanical Room - AHU-S1 and 32 EΑ 5 10+ years Manual control, many damper AHU-S2 actuator arms disconnected. Outdoor Return Fans- Air Handling Unit Roof 2 FΑ 6 Return fans serving air handlers 10+ years Type - Greater than 20000 CFM Outdoor Return Fans- Air Handling Unit Roof EΑ 6 1 10+ vears Type - Greater than 20000 CFM Boiler Systems Boiler Auxiliary- Scotch Marine- Hot Water **Boiler Room** 2 ΕA 6 10+ years Boiler - 2001 - 3000 MBH **Chemical Pot Feeder** Boiler Room ΕA 5 1 6-10 years **Combustion Dampers** Boiler Room 2 EΑ 6 10+ years 2 Non Condensing- Scotch Marine- Hot Water Boiler Room ΕA 6 10+ years Boiler - 2001 - 3000 MBH Water Fill System **Boiler Room** 1 EΑ 6 10+ years Gas Booster Gas Booster Mechanical Room 3 ΕA 5 2-5 years Older, corroded Heating Devices Unit Heater - Electric Boiler Room 1 ΕA 5 2-5 vears Older unit. corroded Unit Heater - Gas Boiler Room 1 ΕA 7 10+ vears Replaced new in 2021 34 LF 6 10+ years Fin Tube - Electric **Entire Building** ΕA 6 Wall Heater - Electric Entire Building 11 10+ years ΕA 2 Wall Heater - Electric Entire Building 0-1 year 1 Non-functional



Building : Main Category : Mechanical Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Group Mechanical Plumbing Hydronic Supply and Return - Steel Entire Building 300 LF 6 10+ years Hot Water Pump - 10 - 20 HP ΕA 7 Mechanical Room 1 10+ years HWP-4 new in 2021 Hot Water Pump - 10 - 20 HP ΕA 6 Mechanical Room 10+ years HWP-3 new in 2021 Overheats 1 frequently Hot Water Pump - Less than 10 Mechanical Room FΑ 6 6-10 years AHU 2S coil pump 1 Hot Water Pump - Less than 10 Mechanical Room 1 FΑ 6 6-10 years HWP-1 Hot Water Pump - Less than 10 Mechanical Room EΑ 6 6-10 years AHU 1S coil pump 1 Hot Water Pump - Less than 10 Mechanical Room 1 EΑ 6 6-10 years HWP-2 Temperature Control SF DDC System Entire Building 62.706 6 Software has been upgraded, and 6-10 years temperature sensors are reporting back, but engineer has very little control over our temperature via damper actuators Electric Thermostat Entire Building EΑ 5 6-10 years 1 Thermostats - DDC 30 FΑ 6 Entire Building 6-10 years Ventilation Exhaust Fans- Indoor - 500 - 1500 CFM Entire Building 6 1 EΑ 6-10 years Exhaust Fans- Indoor - Less than 500 CFM 2 ΕA 6 Serves pre-K bathroom and first floor Entire Building 10+ years staff toilet Not included in previous assessment Exhaust Fans- Roof Mounted - 500 - 1500 2 EΑ Entire Building 6 10+ years CFM Exhaust Fans- Roof Mounted - Less than Entire Building 1 FΑ 6 2-5 years 500 CFM Exhaust Fans- Roof Mounted - Less than Entire Building 1 ΕA 5 0-1 year Nonfunctional 500 CFM Roof Mounted Duct Work Entire Building 203 LF 7 10+ years **Category : Plumbing Building : Main** Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Hot Water ΕA Gas Heater - 150000 - 300000 BTU/HR Boiler Room 1 6 2-5 years Hot Water Storage Tank_Gas - Less than Boiler Room 1 EΑ 5 6-10 vears 200 Gallons Piping **Domestic Piping-Hot Water Return Lines** SF Entire Building 62.706 6 6-10 years



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water Return Risers	Entire Building	62,706	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	62,706	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	62,706	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	62,706	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	62,706	SF	6	6-10 years	
	Sanitary Piping	Entire Building	62,706	SF	6	10+ years	
	Storm Piping	Entire Building	62,706	SF	6	10+ years	
	Vent Piping	Entire Building	62,706	SF	6	10+ years	
Pumps							
-	Pumps - Domestic Booster Pump-Simplex	Pump Room off the Boiler Room	1	EA	6	10+ years	Installed new in 2020

Catego	ry : Room		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	1st Floor gym office off stage	284	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor gym office off stage	2	EA	6	10+ years	
	Floor - Tile	1st Floor gym office off stage	284	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor gym office off stage	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor gym office off stage	703	SF	6	6-10 years	Deficiency included in rank
	Ceiling - Plaster/Drywall	Custodian office outside gym	242	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Custodian office outside gym	60	SF	5	1-2 years	Damaged
	Doors - Steel Doors incl hw	Custodian office outside gym	1	EA	6	10+ years	
	Floor - Tile	Custodian office outside gym	302	SF	6	10+ years	
	Lighting - Pendent/Surface	Custodian office outside gym	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	Custodian office outside gym	863	SF	6	10+ years	
	Walls - Plaster/Drywall	Custodian office outside gym	20	SF	5	1-2 years	Cracked wall
	Ceiling - Plaster/Drywall	Engineer's office	203	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's office	1	EA	6	10+ years	
	Floor - Concrete	Engineer's office	203	SF	5	2-5 years	
	Lighting - Pendent/Surface	Engineer's office	5	EA	6	6-10 years	
	Walls - Masonry	Engineer's office	500	SF	6	10+ years	
	Walls - Plaster/Drywall	Engineer's office	294	SF	6	10+ years	
	Work SInk	Engineer's office	1	EA	7	10+ years	
	Ceiling - Lay-in	Lunchroom office	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Lunchroom office	1	EA	6	10+ years	
	Floor - Terrazzo	Lunchroom office	40	SF	6	10+ years	
	Lighting - Lay-in	Lunchroom office	2	EA	6	6-10 years	
	Walls - Plaster/Drywall	Lunchroom office	71	SF	6	10+ years	



Category : Room **Building : Main** Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments AC Unit Main office 114 ΕA 6-10 years 7 1 Main office 114 486 SF Ceiling - Plaster/Drywall 6 10+ vears Doors - Wood Doors inclu hw Main office 114 FΑ 6 10+ years 1 Floor - Tile SF 6 Main office 114 486 10+ years Lighting - Pendent/Surface Main office 114 7 EΑ 6 10+ years Storage/ Closet 57 SF 7 Main office 114 10+ years Walls - Plaster/Drywall Main office 114 830 SF 10+ years 6 Ceiling - Plaster/Drywall SF Office 211, 2nd Floor 338 6 10+ years Doors - Wood Doors inclu hw Office 211, 2nd Floor 1 EΑ 6 10+ years SF Floor - Epoxy/ Painted Office 211, 2nd Floor 338 4 0-1 vear Epoxy worn Lighting - Pendent/Surface Office 211, 2nd Floor 2 ΕA 7 6-10 vears Walls - Plaster/Drywall Office 211, 2nd Floor 930 SF 6 10+ years AC Unit Office 300, Floor 3.5b ΕA 7 1 10+ years Updated quantity SF Ceiling - Plaster/Drywall Office 300, Floor 3.5b 260 6 10+ years Doors - Transom Window Office 300, Floor 3.5b SF 7 70 10+ years Doors - Wood Doors inclu hw FΑ Office 300, Floor 3.5b 1 6 10+ years SF 5 Floor - Wood Office 300, Floor 3.5b 260 6-10 years Lighting - Pendent/Surface Office 300, Floor 3.5b 3 EΑ 7 10+ years Walls - Plaster/Drvwall SF Office 300, Floor 3.5b 591 6 10+ vears Ceiling - Plaster/Drywall SF Office 311, Floor 3 340 6 2-5 years Doors - Wood Doors inclu hw Office 311, Floor 3 ΕA 6 10+ years 1 Floor - Epoxy/ Painted SF 7 10+ years Office 311, Floor 3 340 Lighting - Pendent/Surface ΕA 7 Office 311, Floor 3 1 10+ years Lighting - Pendent/Surface Office 311, Floor 3 1 FΑ 5 0-1 year Does not work. Walls - Plaster/Drywall Office 311, Floor 3 SF 6 885 10+ years AC Unit Office 312 1 ΕA 7 10+ vears Updated quantity Ceiling - Plaster/Drywall SF Office 312 270 7 10+ years Doors - Wood Doors inclu hw Office 312 ΕA 7 6-10 years Updated to match current 1 observations Floor - Tile Office 312 270 SF 6 10+ years Lighting - Pendent/Surface Office 312 3 ΕA 7 10+ vears Power Distribution Office 312 4 ΕA 7 10+ vears SF 10+ years Walls - Plaster/Drvwall Office 312 572 6 Need paint around windows. Work SInk Office 312 FΑ 7 10+ years 1 232 SF Ceiling - Plaster/Drywall Principal's office 112 6 10+ years Doors - Wood Doors inclu hw ΕA 6 Principal's office 112 2 10+ years SF Floor - Tile Principal's office 112 232 6 10+ years Lighting - Pendent/Surface Principal's office 112 ΕA 7 6-10 years 4 Walls - Plaster/Drywall Principal's office 112 718 SF 6 10+ years Gymnasia Ceiling - Plaster/Drywall SF 1st Floor 5,354 6 10+ years Doors - Wood Doors inclu hw 1st Floor 9 ΕA 6 10+ years Floor - Tile 1st Floor 5,154 SF 6 10+ years



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Floor - Tile 1st Floor 200 SF 4 1-2 years Damaged and missing tiles Lighting - Pendent/Surface 1st Floor ΕA 7 6-10 vears 50 Main Floor Seating 1st Floor 367 FΑ 7 10+ years Scoreboards 7 6-10 years 1st Floor 1 EΑ 1,374 SF Stage 1st Floor 6 10+ years 7 Stage Curtain 1st Floor EΑ 10+ years 3 Stage Lighting System 1st Floor 1 ΕA 7 10+ years LF Stage-Stairs - Asphalt 1st Floor 42 6 10+ years SF Storage/ Closet 1st Floor 136 7 10+ years Walls - Plaster/Drywall SF 1st Floor 5.756 6 10+ years Kitchen Ceiling - Lay-in 1st Floor 472 SF 6 10+ years Floor - Tile Quarry SF 1st Floor 472 6 10+ years Lighting - Lay-in 1st Floor ΕA 6 6-10 years 7 Lighting - Pendent/Surface 1st Floor 7 FΑ 7 10+ years Walls - Concrete Block SF 1st Floor 50 6 10+ years SF Walls - Plaster/Drywall 1st Floor 407 6 10+ years Library AC Unit 206 1 ΕA 7 6-10 years AC Unit 206 1 ΕA 7 6-10 years LF Casework 206 72 6 10+ years Ceiling - Plaster/Drywall 206 1.663 SF 10+ years 6 Doors - Wood Doors inclu hw 206 2 EΑ 7 10+ years Floor - Tile 206 SF 1.651 6 10+ years SF Floor - Tile 206 12 4 1-2 years Hole through tile 206 29 ΕA 6 Lighting - Pendent/Surface 10+ years Student Lockers - One Tier 206 6 FΑ 7 10+ years SF Walls - Plaster/Drywall 206 1.910 6 10+ years Lunch & Multipurpose Room AC Unit 1st Floor 2 ΕA 7 6-10 years SF Ceiling - Lay-in 1st Floor 1.720 6 10+ years Doors - Wood Doors inclu hw 1st Floor EΑ 6 10+ years 3 Floor - Tile 1st Floor 1.720 SF 6 10+ vears Lighting - Lay-in 1st Floor 25 EA 6 10+ years Serving Line 1st Floor 20 LF 6 10+ years Storage/ Closet SF 7 1st Floor 135 10+ years Walls - Plaster/Drywall SF 6 1st Floor 1,341 10+ years MDF IDF Doors - Wood Doors inclu hw 7 206B inside Room 206 1 ΕA 10+ years



atego	ry : Room		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Finishes	206B inside Room 206	100	SF	5	10+ years	Baseboard missing, plaster walls crumbling on south edge
	Window AC Unit	206B inside Room 206	1	EA	7	6-10 years	
echani	cal/ Service Rooms						
	Boiler Room	1st Floor	1,325	SF	7	10+ years	
	Janitor's Closet	1st Floor	30	SF	5	10+ years	
	Janitor's Closet	1st Floor	11	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	124	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	331	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	750	SF	7	6-10 years	
	Mechanical/ Service Rooms	1st Floor	677	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	550	SF	5	10+ years	Quantity updated to match curren observations
	Storage Room	1st Floor	64	SF	5	10+ years	
	Storage Room	1st Floor	120	SF	5	6-10 years	
	Janitor's Closet	2nd Floor	15	SF	7	10+ years	
	Janitor's Closet	2nd Floor	57	SF	5	6-10 years	
	Janitor's Closet	3rd Floor	18	SF	5	6-10 years	Broken ceiling plaster around ver
stroor	n Accessories	107a	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	107a	45 45	SF	7	10+ years	Rank changed to match current
			-				observations
	Doors - Wood Doors inclu hw	107a	1	EA	7	10+ years	Rank changed to match current observations
	Floor - Tile Ceramic/ Porcelain	107a	45	SF	7	10+ years	Rank changed to match current observations
	Lavatory	107a	1	EA	7	10+ years	Rank changed to match current observations
	Lighting - Pendent/Surface	107a	1	EA	7	6-10 years	Rank changed to match current observations
	Walls - Plaster/Drywall	107a	47	SF	7	10+ years	Rank changed to match current observations
	Walls - Tile Ceramic/ Porcelain	107a	47	SF	7	10+ years	Rank changed to match current observations
	Water Closet	107a	1	EA	7	10+ years	Rank changed to match current observations
	Accessories	109a	38	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	109a	38	SF	7	10+ years	Rank changed to match current observations
	Doors - Wood Doors inclu hw	109a	1	EA	7	10+ years	Rank changed to match current observations
	Floor - Tile Ceramic/ Porcelain	109a	38	SF	7	10+ years	Rank changed to match current



Park Manor Elementary School 7037 S Rhodes AVENUE, Chicago, IL 60637

Catego	ry : Room		R	uilding	: Main		ST S Kildes AVENCE, Chicago, le 00037
oalogo				unung	. mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oroup			Quantity				observations
	Lavatory	109a	1	EA	7	10+ years	Rank changed to match current
						, e , j e e	observations
	Lighting - Pendent/Surface	109a	1	EA	7	10+ years	Rank changed to match current
						-	observations
	Walls - Plaster/Drywall	109a	40	SF	7	10+ years	Rank changed to match current
							observations
	Walls - Structural Glazed Tile	109a	40	SF	7	10+ years	Updated to reflect current
					_		observations
	Water Closet	109a	1	EA	7	10+ years	
	Accessories	1st Floor North (by gym/auditorium)	204	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor North (by gym/auditorium)	204	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor North (by gym/auditorium)	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor North (by gym/auditorium)	204	SF	7	10+ years	
	Floor Drain		204	EA	7		
		1st Floor North (by gym/auditorium)	-			10+ years	
	Hand Dryer	1st Floor North (by gym/auditorium)	1	EA	7	10+ years	
	Lavatory	1st Floor North (by gym/auditorium)	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor North (by gym/auditorium)	4	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor North (by gym/auditorium)	324	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor North (by gym/auditorium)	191	SF	7	10+ years	
	Water Closet	1st Floor North (by gym/auditorium)	1	EA	7	10+ years	
	Accessories	1st Floor boys	341	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor boys	341	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor boys	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor boys	341	SF	6	10+ years	
	Floor Drain	1st Floor boys	2	EA	7	10+ years	
	Hand Dryer	1st Floor boys	1	EA	7	6-10 years	
	Lavatory	1st Floor boys	1	EA	6	10+ years	
			-				
	Lighting - Pendent/Surface	1st Floor boys	9	EA	6	6-10 years	
	Partitions	1st Floor boys	6	EA	7	10+ years	
	Urinals	1st Floor boys	10	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor boys	477	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor boys	477	SF	6	10+ years	
	Water Closet	1st Floor boys	6	EA	6	10+ years	
	Accessories	1st Floor girls	336	SF	7	6-10 years	
							Deals show and to meet show any
	Ceiling - Plaster/Drywall	1st Floor girls	336	SF	7	10+ years	Rank changed to match current
					_		observations
	Floor - Tile Ceramic/ Porcelain	1st Floor girls	336	SF	7	10+ years	Rank changed to match current
							observations
	Floor Drain	1st Floor girls	1	EA	7	10+ years	
	Hand Dryer	1st Floor girls	2	EA	7	6-10 years	Rank and quantity changed to match
	,	5				,	current observations
	Lavatory	1st Floor girls	3	EA	7	10+ years	Rank and quantity changed to match
	Lavatory		5		'	ior years	current observations



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Lighting - Pendent/Surface 1st Floor girls 9 FΑ 7 6-10 years Rank changed to match current observations Partitions 1st Floor girls 9 FΑ 7 10+ years Walls - Plaster/Drywall 509 SF 7 1st Floor girls 10+ years Rank changed to match current observations SF Walls - Tile Ceramic/ Porcelain 1st Floor girls 509 7 Rank changed to match current 10+ years observations Water Closet 1st Floor girls 9 ΕA 7 10+ years Rank and quantity changed to match current observations SF 2nd Floor boys 424 7 6-10 vears Accessories SF Ceiling - Plaster/Drvwall 2nd Floor boys 424 6 10+ vears Doors - Wood Doors inclu hw 2nd Floor boys 2 ΕA 6 10+ years Floor - Tile Ceramic/ Porcelain 2nd Floor boys 424 SF 6 10+ years 7 ΕA Floor Drain 2nd Floor boys 2 10+ years Hand Dryer 7 2nd Floor boys 1 ΕA 6-10 years FΑ Lavatory 2nd Floor boys 1 6 10+ years Lighting - Pendent/Surface 9 2nd Floor boys FΑ 6 6-10 years 6 Partitions 2nd Floor boys ΕA 7 10+ years 9 Urinals 2nd Floor boys ΕA 6 10+ vears Urinals 2nd Floor boys 1 EΑ 5 1-2 years Disconnected Walls - Plaster/Drywall 2nd Floor boys 515 SF 6 10+ years Walls - Structural Glazed Tile SF 6 2nd Floor boys 513 10+ years SF 5 2 Walls - Structural Glazed Tile 2nd Floor boys 1-2 years Broken tile 6 Water Closet 2nd Floor boys 6 FΑ 10+ years Accessories 2nd Floor girls 316 SF 7 6-10 years SF Ceiling - Plaster/Drvwall 2nd Floor airls 316 6 10+ vears Doors - Wood Doors inclu hw 2nd Floor girls 3 EΑ 6 10+ years Floor - Epoxy/ Painted 2nd Floor girls 316 SF 7 10+ years Floor Drain ΕA 2nd Floor girls 1 7 10+ years Hand Drver 2nd Floor girls 1 ΕA 7 6-10 years 2nd Floor girls 1 FΑ 6 10+ vears Lavatory Lavatorv 2nd Floor airls 1 ΕA 5 1-2 vears Missing hardware Lighting - Pendent/Surface 5 2nd Floor airls FΑ 6 6-10 years Partitions 2nd Floor airls 9 FΑ 7 6-10 years Partitions 2nd Floor girls 1 EΑ 4 0-1 year Missing door SF 6 Walls - Plaster/Drywall 2nd Floor girls 408 10+ years SF Walls - Structural Glazed Tile 2nd Floor girls 408 6 10+ years Water Closet ΕA 6 2nd Floor girls 10 10+ years SF Accessories 3rd Floor Unisex. North 90 7 6-10 years SF Ceiling - Plaster/Drvwall 3rd Floor Unisex. North 90 6 10+ vears Doors - Wood Doors inclu hw 3rd Floor Unisex. North 1 ΕA 7 10+ years Floor - Tile Ceramic/ Porcelain 90 SF 3rd Floor Unisex. North 6 10+ vears Floor Drain 3rd Floor Unisex, North 1 ΕA 7 10+ years 7 Hand Dryer 3rd Floor Unisex, North 1 EA 10+ years



Catego	ory : Room		В	uilding	: Main		
				5		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	3rd Floor Unisex, North	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor Unisex, North	1	EA	5	1-2 years	Cover missing
	Walls - Plaster/Drywall	3rd Floor Unisex, North	155	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor Unisex, North	25	SF	6	10+ years	
	Water Closet	3rd Floor Unisex, North	1	EA	7	10+ years	
	Accessories	3rd Floor boys	426	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor boys	426	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor boys	4	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor boys	426	SF	6	10+ years	
	Floor Drain	3rd Floor boys	2	EA	7	10+ years	
	Hand Dryer	3rd Floor boys	1	EA	7	6-10 years	
	Lavatory	3rd Floor boys	6	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor boys	9	EA	6	6-10 years	
	Partitions	3rd Floor boys	4	EA	7	10+ years	
	Partitions	3rd Floor boys	2	EA	5	0-1 year	Door missing
	Urinals	3rd Floor boys	3	EA	6	10+ years	č
	Urinals	3rd Floor boys	5	EA	5	1-2 years	Out of order
	Walls - Plaster/Drywall	3rd Floor boys	496	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor boys	502	SF	6	10+ years	
	Water Closet	3rd Floor boys	5	EA	6	10+ years	
	Water Closet	3rd Floor boys	1	EA	4	1-2 years	Out of order
	Accessories	3rd Floor girls	316	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor girls	316	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor girls	4	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	3rd Floor girls	316	SF	6	10+ years	
	Floor Drain	3rd Floor girls	1	EA	7	10+ years	
	Hand Dryer	3rd Floor girls	1	EA	7	6-10 years	
	Lavatory	3rd Floor girls	2	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor girls	5	EA	6	6-10 years	
	Partitions	3rd Floor girls	10	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor girls	328	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor girls	328	SF	6	10+ years	
	Water Closet	3rd Floor girls	10	EA	6	10+ years	
	Accessories	Kitchen Toilet	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Kitchen Toilet	25	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Kitchen Toilet	1	EA	6	10+ years	
	Floor - Tile	Kitchen Toilet	25	SF	6	10+ years	
	Lavatory	Kitchen Toilet	1	EA	6	10+ years	
	Lighting - Wall Mounted	Kitchen Toilet	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Toilet	30	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Kitchen Toilet	30	SF	6	10+ years	
	Water Closet	Kitchen Toilet	50 1	EA	7	10+ years	
	Accessories	Main office toilet room	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main office toilet room	52	SF	6	10+ years	
	Coming Tradicity Drywaii		52	0	U	ior years	



Building : Main Category : Room Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Doors - Wood Doors inclu hw Main office toilet room ΕA 6 10+ years 1 Floor - Tile Ceramic/ Porcelain Main office toilet room 52 SF 6 10+ years Lavatorv Main office toilet room 1 FΑ 6 10+ years Lighting - Wall Mounted 1 ΕA 6 Main office toilet room 10+ years 7 Partitions Main office toilet room 1 ΕA 10+ years SF Walls - Plaster/Drywall Main office toilet room 109 6 10+ years Water Closet Main office toilet room ΕA 7 10+ years 1 SF Accessories Principal's toilet 98 7 6-10 years SF Ceiling - Plaster/Drywall Principal's toilet 98 6 10+ years Doors - Wood Doors inclu hw ΕA Principal's toilet 1 6 10+ years Floor - Tile Ceramic/ Porcelain Principal's toilet 98 SF 6 10+ vears Lavatory Principal's toilet 1 ΕA 6 10+ years Principal's toilet Lighting - Pendent/Surface 1 ΕA 7 10+ years SF Walls - Plaster/Drywall Principal's toilet 243 6 10+ years Water Closet Principal's toilet ΕA 7 1 10+ years 14 SF 7 Accessories boiler room toilet 6-10 years Ceiling - Plaster/Drywall SF boiler room toilet 14 6 10+ years Doors - Steel Doors incl hw boiler room toilet 1 EΑ 6 10+ years Floor - Concrete 14 SF boiler room toilet 7 10+ vears Lighting - Pendent/Surface 6-10 years boiler room toilet 1 EΑ 6 Walls - Masonry boiler room toilet 29 SF 5 0-1 year Spalling Water Closet ΕA 6 boiler room toilet 1 10+ years

Category : Classroom

Oulogo	/ y . 01035100111		Banang . Man						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
_	om #106 (Faculty Lounge)	Looaton	quantity	00111	i tuint	Ropidoomont	Commente		
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	4	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	804	SF	6	10+ years			
	Doors - Side-lite	1st Floor	9	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years			
	Doors - Transom Window	1st Floor	6	SF	7	10+ years			
	Floor - Tile	1st Floor	804	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years			
	Marker Board	1st Floor	40	LF	6	6-10 years			
	Storage/ Closet	1st Floor	54	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,385	SF	6	10+ years			
Classroo	om #107 (Pre School)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	12	LF	7	10+ years			
	Ceiling - Lay-in	1st Floor	918	SF	6	10+ years			
	Doors - Side-lite	1st Floor	9	SF	6	10+ years			

Building : Main



Building : Main Category : Classroom Recommend Location **Replacement** Comments Group Item - Type Quantity UOM Rank Doors - Transom Window SF 1st Floor 6 6 10+ vears Doors - Wood Doors inclu hw 1st Floor ΕA 6 10+ years 1 Floor - Tile 1st Floor 918 SF 6 10+ years Lighting - Pendent/Surface ΕA 6 1st Floor 14 6-10 years SF 7 Storage/ Closet 1st Floor 162 10+ years SF Walls - Plaster/Drywall 1st Floor 1.174 6 10+ years Work Sink ΕA 7 1st Floor 1 10+ years Classroom #108 (Other Instructional Use) AC Units 1st Floor 1 ΕA 7 6-10 years 1st Floor 4 LF Casework 6 10+ years Ceiling - Plaster/Drywall 1st Floor 816 SF 6 6-10 years Deficiency included in rank, changed to match current observations SF 10+ years Doors - Side-lite 1st Floor 9 7 Doors - Transom Window 6 SF 7 1st Floor 10+ years Doors - Wood Doors inclu hw 1st Floor 1 FΑ 6 10+ years SF Floor - Tile 1st Floor 796 6 10+ years SF Cracking flooring, uneven Floor - Tile 1st Floor 30 4 1-2 years Lighting - Pendent/Surface ΕA 7 1st Floor 14 10+ years Marker Board 1st Floor 34 LF 6 6-10 years SF Storage/ Closet 1st Floor 54 7 10+ years Walls - Plaster/Drvwall 1st Floor 1.349 SF 6 10+ vears Walls - Plaster/Drywall SF 1st Floor 50 5 1-2 years Bubbling wall Classroom #109 (Pre School) AC Units 1st Floor 2 ΕA 7 6-10 years LF Casework 1st Floor 16 6 10+ years Ceiling - Plaster/Drywall 972 SF 6 1st Floor 10+ years Doors - Transom Window 1st Floor 10 SF 7 10+ years FΑ Doors - Wood Doors inclu hw 1st Floor 1 6 10+ years Floor - Tile 972 SF 6 1st Floor 10+ years Lighting - Pendent/Surface 1st Floor 14 EA 6 10+ years Marker Board 1st Floor 13 LF 6 6-10 years Storage/ Closet 1st Floor 73 SF 7 10+ years Walls - Plaster/Drvwall 1st Floor 1.440 SF 6 10+ vears Work Sink FΑ 7 6-10 years 1st Floor 1 Classroom #201 (Regular Classroom) 2nd Floor AC Units 1 7 EΑ 6-10 years Casework 2nd Floor 6 LF 6 10+ years 2nd Floor 836 SF 6 Ceiling - Plaster/Drywall 10+ years Doors - Transom Window 2nd Floor 10 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 FΑ 6 10+ years



Building : Main Category : Classroom Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Floor - Tile 2nd Floor 826 SF 6 10+ vears Floor - Tile 2nd Floor SF 1-2 vears 10 4 Cracking tiles Lighting - Pendent/Surface 2nd Floor 14 FΑ 7 6-10 years Marker Board 2nd Floor 12 LF 6-10 years 6 SF Storage/ Closet 2nd Floor 54 7 10+ years SF Walls - Plaster/Drywall 2nd Floor 1,422 6 10+ years Classroom #202 (Regular Classroom) 2nd Floor AC Units 2 ΕA 7 6-10 years 6 LF Casework 2nd Floor 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 816 SF 6 10+ years Doors - Transom Window 2nd Floor 10 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor ΕA 10+ years 1 6 SF Floor - Tile 2nd Floor 816 4 0-1 year Bubbling tiles 2nd Floor ΕA 7 Lighting - Pendent/Surface 14 10+ years Marker Board 2nd Floor 34 LF 6 6-10 years SF Storage/ Closet 2nd Floor 54 7 10+ years Walls - Plaster/Drywall 1,446 SF 2nd Floor 6 10+ years Classroom #203 (Regular Classroom) AC Units 2nd Floor 1 ΕA 7 6-10 years LF Casework 2nd Floor 6 6 10+ years SF Ceiling - Plaster/Drywall 2nd Floor 828 6 10+ years Doors - Transom Window 2nd Floor SF 6 10 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 6 10+ years Floor - Tile 2nd Floor 828 SF 6 10+ years Lighting - Pendent/Surface 2nd Floor 14 ΕA 7 6-10 years Storage/ Closet 2nd Floor SF 5 24 10+ years Plaster cracking Walls - Plaster/Drvwall 2nd Floor 1.387 SF 6 10+ years Classroom #204 (Regular Classroom) 2 AC Units 2nd Floor 7 EΑ 6-10 years Casework 2nd Floor 6 LF 6 10+ years SF Ceiling - Plaster/Drywall 2nd Floor 804 6 10+ years SF 7 Doors - Transom Window 2nd Floor 10 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 ΕA 7 10+ vears Floor - Tile 800 SF 2nd Floor 6 10+ years Floor - Tile 2nd Floor 4 SF 4 1-2 years Chipping tiles Lighting - Pendent/Surface 2nd Floor ΕA 7 10+ years 14 Marker Board 2nd Floor 36 LF 6 6-10 years 2nd Floor SF 7 Storage/ Closet 54 10+ years Walls - Plaster/Drywall 2nd Floor 1.389 SF 6 10+ years



Building : Main Category : Classroom Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Classroom #205 (Regular Classroom) AC Units 2nd Floor 1 ΕA 7 6-10 years Casework 2nd Floor 6 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor 816 SF 6 10+ years Doors - Transom Window SF 6 10+ years 2nd Floor 10 Doors - Wood Doors inclu hw FΑ 2nd Floor 6 10+ years 1 Floor - Tile 2nd Floor 808 SF 6 10+ years Floor - Tile SF 2nd Floor 8 4 1-2 years Chipping tiles Lighting - Pendent/Surface ΕA 7 2nd Floor 14 6-10 years Marker Board LF 2nd Floor 26 6 6-10 years Storage/ Closet 2nd Floor SF 7 24 10+ years Walls - Plaster/Drywall 2nd Floor 1,394 SF 6 10+ years SF Walls - Plaster/Drywall 2nd Floor 5 5 1-2 years Holes through plaster from previous installations Classroom #207 (Regular Classroom) AC Units 2nd Floor ΕA 7 1 6-10 years Casework 2nd Floor 6 LF 6 10+ years Ceiling - Plaster/Drywall 2nd Floor SF 816 6 10+ years Doors - Transom Window 2nd Floor 10 SF 7 10+ years Doors - Wood Doors inclu hw 2nd Floor 1 EΑ 6 10+ years SF Floor - Tile 2nd Floor 816 6 10+ years Lighting - Pendent/Surface 2nd Floor 14 EΑ 7 6-10 years Marker Board 2nd Floor 26 LF 6-10 years 6 Storage/ Closet 2nd Floor 54 SF 7 10+ years Walls - Plaster/Drywall 2nd Floor SF 1.399 6 10+ years Classroom #209 (Regular Classroom) AC Units 2nd Floor 1 ΕA 7 6-10 years Casework 2nd Floor 6 LF 6 10+ years Ceiling - Plaster/Drywall SF 6 10+ years 2nd Floor 816 SF Doors - Transom Window 2nd Floor 10 6 10+ years Doors - Wood Doors inclu hw 2nd Floor EΑ 6 10+ years 1 Floor - Tile SF 2nd Floor 813 6 10+ years SF Floor - Tile 2nd Floor 4 0-1 year Bubbling up, taped down, broken tile 3 Lighting - Pendent/Surface 2nd Floor 14 EΑ 7 6-10 vears Marker Board LF 6-10 years 2nd Floor 40 7 Storage/ Closet 2nd Floor 54 SF 7 10+ years Walls - Plaster/Drywall SF 2nd Floor 1.399 6 10+ years Classroom #210 (Office) AC Units 2nd Floor 2 ΕA 7 6-10 years 2nd Floor LF Casework 6 6 6-10 years



Category : Classroom

Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Ceiling - Plaster/Drywall 2nd Floor 864 SF 6 10+ vears Doors - Transom Window 2nd Floor SF 7 10 10+ years Doors - Wood Doors inclu hw 2nd Floor FΑ 6 10+ years 1 Floor - Tile 2nd Floor SF 6 564 10+ years SF Floor - Tile 2nd Floor 300 4 1-2 years Chipping tiles Lighting - Pendent/Surface ΕA 7 2nd Floor 14 10+ years Marker Board 2nd Floor 36 LF 6 6-10 years SF Storage/ Closet 2nd Floor 54 7 10+ years Walls - Plaster/Drywall 2nd Floor 1.436 SF 6 10+ years SF Walls - Plaster/Drywall 2nd Floor 10 4 1-2 years Water damage, cracking plaster Classroom #301 (Regular Classroom) AC Units 3rd Floor 1 ΕA 7 6-10 years LF Casework 3rd Floor 6 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 838 SF 6 10+ years Doors - Transom Window 3rd Floor 10 SF 6 10+ years Doors - Wood Doors inclu hw FΑ 3rd Floor 1 6 10+ years SF Floor - Tile 3rd Floor 834 6 10+ years SF Floor - Tile 3rd Floor 4 4 1-2 years Corners chipping, edges bubbling Lighting - Pendent/Surface 3rd Floor 14 ΕA 7 6-10 years Storage/ Closet SF 3rd Floor 54 7 10+ years 1,338 Walls - Plaster/Drywall 3rd Floor SF 6 10+ vears Classroom #302 (Regular Classroom) AC Units 3rd Floor 2 EΑ 7 6-10 years Casework 3rd Floor 6 LF 10+ years 6 SF Ceiling - Plaster/Drywall 3rd Floor 878 6 10+ years Doors - Transom Window SF 7 3rd Floor 10 10+ years Doors - Wood Doors inclu hw 3rd Floor FΑ 6 10+ years 1 Floor - Tile SF 3rd Floor 875 6 10+ years Floor - Tile SF 3rd Floor 3 4 1-2 years Broken Lighting - Pendent/Surface 7 3rd Floor 14 EΑ 10+ years Marker Board 3rd Floor 16 LF 6-10 years 6 Storage/ Closet 3rd Floor 54 SF 7 10+ years 1,350 Walls - Plaster/Drvwall 3rd Floor SF 6 10+ vears Classroom #303 (Store Room) AC Units 3rd Floor 1 ΕA 7 6-10 years Casework 3rd Floor 12 LF 10+ years 6 Ceiling - Plaster/Drywall 3rd Floor SF 6 10+ years 816 Doors - Transom Window SF 7 3rd Floor 10 10+ years Doors - Wood Doors inclu hw 3rd Floor FΑ 6 10+ years 1 SF Floor - Tile 3rd Floor 816 6 10+ years

Building : Main



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	28	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,341	SF	6	10+ years	
lassroc	m #304 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	810	SF	6	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	807	SF	6	10+ years	
	Floor - Tile	3rd Floor	3	SF	4	1-2 years	Corners breaking
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	Comers breaking
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,334	SF	6		
	Walls - Plastel/Drywall	310 11001	1,334	Эг	0	10+ years	
lassroc	m #305 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	38	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	814	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	2	SF	5	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	810	SF	6	10+ years	
	Floor - Tile	3rd Floor	6	SF	4	1-2 years	Broken tiles and subfloor exposed
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	8	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,325	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	4	SF	4	1-2 years	Water damage
	Work Sink	3rd Floor	4	EA	7	10+ years	Water damage
lassror	m #306 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	- 6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	810	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	6	10+ years	
	Floor - Tile	3rd Floor	810	SF	6	10+ years	
				EA	6 7	-	
	Lighting - Pendent/Surface	3rd Floor	14	EA	1	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	1	EA	5	1-2 years	Light switch panel sunken behind face plate
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,334	SF	6	10+ years	
Classroo	om #307 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	824	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	824	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	30	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	5	10+ years	Cracking and falling ceiling plaste
	Walls - Plaster/Drywall	3rd Floor	1,350	SF	6	10+ years	3
Classroo	om #308 (Regular Classroom)				-	0.40	
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	816	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	808	SF	6	10+ years	Destrue and establish titles and flags
	Floor - Tile	3rd Floor	8	SF	4	0-1 year	Broken and missing tiles, subfloor exposed
	Lighting - Pendent/Surface	3rd Floor	17	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	4	EA	5	1-2 years	Missing covers
	Marker Board	3rd Floor	16	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,341	SF	6	10+ years	
Classroo	om #309 (Computer Lab)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	918	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	914	SF	6	10+ years	
	Floor - Tile	3rd Floor	4	SF	4	1-2 years	Missing tiles
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	50	LF	6	6-10 years	
	Storage/ Closet	3rd Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,394	SF	6	10+ years	



Group

Group Corridor

7037 S Rhodes AVENUE, Chicago, IL 60637 **Building : Main Category : Classroom** Recommend Item - Type Location Quantity UOM Rank **Replacement** Comments Classroom #310 (Regular Classroom) 6-10 years AC Units 3rd Floor 2 ΕA 7 LF Casework 3rd Floor 15 6 10+ years Ceiling - Plaster/Drywall 3rd Floor 828 SF 6 10+ years Doors - Transom Window 3rd Floor SF 7 10 10+ years Doors - Wood Doors inclu hw 3rd Floor 1 ΕA 6 10+ years Floor - Tile SF 828 3rd Floor 6 10+ years Lighting - Pendent/Surface ΕA 7 3rd Floor 14 10+ years LF Marker Board 20 3rd Floor 7 6-10 years Storage/ Closet 3rd Floor 54 SF 7 10+ years Walls - Plaster/Drywall 3rd Floor 1,354 SF 6 10+ years **Category : Interior Building : Main** Recommend Item - Type Location Quantity UOM Rank Replacement Comments Ceiling - Plaster/Drywall 1st Floor 3.946 SF 6 10+ years

		0,0.0	•.	•		
Doors - Steel Doors incl hw	1st Floor	10	EA	6	10+ years	
Doors - Wood Doors include hw	1st Floor	10	EA	6	10+ years	
Drinking Fountains - Double Fountain	1st Floor	1	EA	7	10+ years	
Drinking Fountains - Single Fountain	1st Floor	3	EA	7	10+ years	
Floor - Tile/Sheet	1st Floor	30	SF	7	10+ years	
Floor - Tile/Sheet	1st Floor	3,896	SF	7	10+ years	
Floor - Tile/Sheet	1st Floor	20	SF	4	1-2 years	Damaged tiles
Lighting - Pendent/Surface	1st Floor	33	EA	7	10+ years	-
Walls - Plaster/Drywall	1st Floor	5,412	SF	6	10+ years	
Walls - Structural Glazed Tile	1st Floor	75	SF	6	10+ years	
Ceiling - Lay-in	2nd Floor	926	SF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	1,781	SF	6	10+ years	
Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years	
Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
Floor - Tile/Sheet	2nd Floor	2,707	SF	7	10+ years	
Lighting - Lay-in	2nd Floor	6	EA	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	14	EA	6	10+ years	
Walls - Plaster/Drywall	2nd Floor	5,242	SF	6	10+ years	
Ceiling - Lay-in	3rd Floor	144	SF	6	10+ years	
Ceiling - Plaster/Drywall	3rd Floor	2,563	SF	6	10+ years	
Drinking Fountains - Double Fountain	3rd Floor	1	EA	7	10+ years	
Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	
Floor - Tile/Sheet	3rd Floor	2,700	SF	7	10+ years	
Floor - Tile/Sheet	3rd Floor	7	SF	4	1-2 years	Missing tile
Lighting - Lay-in	3rd Floor	1	EA	7	10+ years	
Lighting - Pendent/Surface	3rd Floor	20	EA	7	10+ years	



Category : Interior			В	uilding	: Main					
			Recom				nd			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Pendent/Surface	3rd Floor	2	EA	6	6-10 years				
	Student Lockers - One Tier	3rd Floor	153	EA	6	10+ years				
	Walls - Plaster/Drywall	3rd Floor	5,242	SF	6	10+ years				
	Ceiling - Plaster/Drywall	Auditorium Vestibule	257	SF	6	10+ years				
	Doors - Steel Doors incl hw	Auditorium Vestibule	5	EA	6	10+ years				
	Floor - Asphalt Floor	Auditorium Vestibule	257	SF	5	10+ years				
	Lighting - Pendent/Surface	Auditorium Vestibule	5	EA	6	6-10 years				
	Stairs - Concrete Stairs	Auditorium Vestibule	92	LF	6	10+ years				
	Walls - Structural Glazed Tile	Auditorium Vestibule	482	SF	6	10+ years				
Safety										
	Camera Viewing Station	1st Floor	1	EA	7	6-10 years				
	Security Cameras	1st Floor	15	EA	7	6-10 years	Quantity changed to match current			
							observations			
Stairs										
	Ceiling - Plaster/Drywall	North (Stair 2)	1,035	SF	6	10+ years				
	Floor - Tile/Sheet	North (Stair 2)	958	SF	6	10+ years				
	Handrails	North (Stair 2)	172	LF	7	10+ years				
	Lighting - Lay-in	North (Stair 2)	1	EA	6	10+ years				
	Lighting - Pendent/Surface	North (Stair 2)	8	EA	7	10+ years				
	Stairs - Asphalt	North (Stair 2)	390	LF	6	10+ years				
	Walls - Plaster/Drywall	North (Stair 2)	2,129	SF	6	10+ years				
	Ceiling - Plaster/Drywall	South (Stair 1)	1,035	SF	6	10+ years				
	Floor - Tile/Sheet	South (Stair 1)	958	SF	6	10+ years				
	Handrails	South (Stair 1)	172	LF	7	6-10 years				
	Lighting - Lay-in	South (Stair 1)	1	EA	6	10+ years				
	Lighting - Pendent/Surface	South (Stair 1)	8	EA	6	10+ years				
	Stairs - Asphalt	South (Stair 1)	390	LF	6	10+ years				
	Walls - Plaster/Drywall	South (Stair 1)	2,129	SF	6	10+ years				



Category : Site Building : Site Recommend Item - Type Location Quantity UOM Replacement **Comments** Group Rank Civil/Drainage Civil/ Drainage - Catch Basin 3 ΕA 6 Entire Site 10+ years 3 FΑ Civil/ Drainage - Site Manhole Entire Site 6 10+ years Fencina LF 7 Fencing - Chain Link Entire Site 64 10+ years Converted amount to linear feet Entire Site 145 LF Fencing - New Standard Ornamental 7 10+ years New LF Fencing - New Standard Ornamental Entire Site 452 6 10+ years LF Fencing - New Standard Ornamental Entire Site 490 6 2-5 years LF Fencing - New Standard Ornamental **Entire Site** 30 Fence struck out of plumb 4 1-2 years LF Fencing - Wood Fencing w/ Steel Frame Entire Site 64 4 1-2 years Rotting wood with missing sections Landscape Benches Entire Site 1 ΕA 6 6-10 vears Landscape - Grass Entire Site 2,483 SF 6 10+ years SF Landscape - Grass Entire Site 300 5 1-2 years Bare soil Landscape - Hardscape- Asphalt Entire Site 3,000 SF 4 0-1 year Damaged. SF Landscape - Hardscape- Concrete Entire Site 300 7 10+ years Lighting - Pole Mounted Entire Site 4 FΑ 7 10+ years 32 Parkway trees **Entire Site** FΑ 7 10+ years Planting Beds/ Area **Entire Site** 3.318 SF 6 10+ years Play Area - Synthetic Turf **Entire Site** 10.165 SF 6 10+ years Trash Receptacles 3 ΕA 7 Entire Site 10+ years Parking Lot **Concrete Curbs** North 473 LF 6 10+ years LF **Concrete Curbs** North 20 4 0-1 year Damaged. LF Interior Plantings North 330 6 10+ vears SF Surface - Asphalt North 15.540 6 10+ years Surface - Asphalt 500 SF 4 1-2 years Potholes and cracks. North Trash Enclosure - Chain Links North 1,450 SF 5 10+ years Vehicular Screening LF 7 North 268 10+ years SF Surface - Asphalt South 2.000 7 10+ years New Playground Equipment - Pre K 3-5 South 1 EΑ 7 10+ years Equipment - School Age 5-12 South ΕA 7 10+ years 1 Surface - Poured Surface SF 3.800 7 10+ years South Sidewalks Sidewalks - Perimeter Sidewalks Entire Site SF 7 50 10+ years



7037 S Rhodes AVENUE, Chicago, IL 60637 **Category : Site Building : Site** Recommend Quantity Group Item - Type Location UOM Rank Replacement Comments Sidewalks - Perimeter Sidewalks Entire Site 15,009 SF 10+ years 6 Sidewalks - Perimeter Sidewalks Entire Site 200 SF 4 1-2 years Upheaved, shattered Signage Flag Pole - Flag Pole Entire Site ΕA 6 10+ years 1 Entire Site ΕA 7 Marguee - Building Mounted Back Lighted 10+ years 1 w/ LED

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Computer Lab	Regular Classroom	3rd Floor	309	309	918	150	60	N	Y
Faculty Lounge	Regular Classroom	1st Floor	106	106	804	160	60	N	Y
Office	Regular Classroom	2nd Floor	210	210	864	150	60	N	Y
Other Instructional Use	Regular Classroom	1st Floor	108	108	816	160	60	N	N
Pre School	Kindergarten	1st Floor	109	109	972	160	60	N	N
Pre School	Pre School	1st Floor	107	107	918	120	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	836	165	75	N	Y
Regular Classroom	Regular Classroom	2nd Floor	202	202	816	150	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	203	203	828	165	45	N	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	804	150	60	N	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	816	165	45	N	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	816	165	75	N	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	816	165	75	N	Y
Regular Classroom	Regular Classroom	3rd Floor	301	301	838	165	75	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	302	878	150	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	304	304	810	150	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	306	306	810	150	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	307	307	824	165	75	N	Y
Regular Classroom	Regular Classroom	3rd Floor	308	308	816	150	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	310	310	828	150	60	N	Y
Science Classroom	Regular Classroom	3rd Floor	305	305	816	165	75	N	Y
Store Room	Regular Classroom	3rd Floor	303	303	816	165	75	N	Y