

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1962	1	43,063
Modular 1 (4-Classroom)	2003	1	4,947
Campus Total			48,010

Category : Exterior Building : Main

	.y . =xtorio.			uug		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ntrance	•					<u>.</u>	
	Entrance Control - Audio and Video	#1 - Main - S	1	EA	7	6-10 years	Newly replaced
	Exterior Doors - Side lite	#1 - Main - S	6	EA	6	10+ years	•
	Exterior Doors - Store Front	#1 - Main - S	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 - Main - S	4	EA	6	10+ years	
	Power Door Operator and Controls	#1 - Main - S	1	EA	7	6-10 years	
	Exterior Doors - Store Front	#11 - Courtyard North	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#11 - Courtyard North	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#11 - Courtyard North	3	LF	5	10+ years	
	Exterior Doors - Store Front	#12 - courtyard, S door	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#12 - courtyard, S door	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#12 - courtyard, S door	3	LF	5	10+ years	
	Exterior Doors - Exterior FRP Door	#2 - SE	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 - SE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#2 - SE	4	LF	5	10+ years	
	Exterior Doors - Exterior FRP Door	#3 - E	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 - E	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#3 - E	4	LF	5	10+ years	
	Exterior Doors - Exterior FRP Door	#4 - NE	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	#4 - NE	1	EA	6	10+ years	
	Ramps - Concrete	#4 - NE	3	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	#5 - NE	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#5 - NE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#5 - NE	6	LF	5	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Entrance Control - Audio and Video	#6 - NE	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#6 - NE	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	#6 - NE	1	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	#6 - NE	6	LF	6	10+ years	Quantity changed to match current observations
	Ramps - Steel or Aluminum	#6 - NE	5	LF	6	2-5 years	
	Entrance Control - Audio and Video	#7 - SW	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#7 - SW	2	EA	6	10+ years	
	Exterior Doors - Side lite	#7 - SW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#7 - SW	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#7 - SW	8	LF	5	10+ years	
	Entrance Control - Audio and Video	#8 - NW	1	EA	7	6-10 years	
	Exterior Doors - Exterior FRP Door	#8 - NW	2	EΑ	6	10+ years	
	Exterior Doors - Side lite	#8 - NW	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#8 - NW	_ 1	EA	6	10+ years	
	Exterior Stairs - Concrete	#8 - NW	8	LF	6	10+ years	
	Exterior Granto Gerroretto	<i>"</i> "	· ·		Ü	io: youro	
Foundati							
	Foundation - Concrete	Entire Building	1,039	LF	7	10+ years	
	Foundation - Concrete	Entire Building	16	LF	6	1-2 years	Cracking in room 108 floor slab
	Foundation - Concrete	Entire Building	4	LF	5	0-1 year	Broken edge
	Superstructure - Steel	Entire Building	43,063	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	17	EA	6	10+ years	
Roof Sys	stem						
,	Access Ladder - Metal	Main Roof	1	EA	7	10+ years	
	Chimney - Metal Flue	Main Roof	18	LF	6	10+ years	
	Coping - Metal	Main Roof	729	LF	6	10+ years	
	Downspouts - Interior Downspouts	Main Roof	131	LF	6	10+ years	
	Roof - Modified Bitumen	Main Roof	27,947	SF	4	1-2 years	Bubbling/cracking/open seems throughout.
	Roof Hatch - Metal	Main Roof	1	EA	5	6-10 years	
	Roof Structure - Steel / Metal Deck/	Main Roof	27,947	SF	7	10+ years	
	Concrete Topping	Maii i tooi	21,041	0.	•	ioi youio	
	Coping - Metal	South Courtyard	56	LF	6	6-10 years	
	Downspouts - Interior Downspouts	South Courtyard	15	LF	6	6-10 years	
	Roof - Modified Bitumen	South Courtyard	784	SF	4	1-2 years	Bubbling/cracking/open seems
	Roof Structure - Steel / Metal Deck/	South Courtyard	784	SF	7	6-10 years	throughout.
	Concrete Topping Access Ladder - Metal	Upper E roof	1	EA	7	10+ years	



Emergency System

Emergency Battery Packs - Corridors and Stairs

1st Floor

John T Pirie Fine Arts & Academic Center ES

650 E 85th STREET, Chicago, IL 60619

Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Access Ladder - Metal	Upper E roof	1	EA	3	0-1 year	Missing bolts/sprinkler system pipe in the way.
	Chimney - Metal Flue	Upper E roof	31	LF	6	10+ years	
	Chimney - Metal Flue	Upper E roof	28	LF	6	10+ years	
	Chimney - Metal Flue	Upper E roof	31	LF	6	10+ years	
	Coping - Metal	Upper E roof	729	LF	6	10+ years	
	Downspouts - Interior Downspouts	Upper E roof	72	LF	6	10+ years	
	Roof - Modified Bitumen	Upper E roof	8,244	SF	4	1-2 years	Bubbling/cracking/open seems throughout.
	Roof Hatch - Metal	Upper E roof	1	EA	3	0-1 year	Not accessible.
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Upper E roof	8,244	SF	7	10+ years	
	Coping - Metal	Upper W roof	339	LF	6	10+ years	
	Downspouts - Interior Downspouts	Upper W roof	40	LF	6	10+ years	
	Roof - Modified Bitumen	Upper W roof	6,872	SF	4	1-2 years	Bubbling/cracking/open seems throughout.
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Upper W roof	6,872	SF	7	10+ years	amoag. loat.
Walls							
	Cornice - Metal Projecting	Entire Building	2,252	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	13,883	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	105	SF	5	2-5 years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	238	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	238	SF	5	10+ years	
_Windows	3						
	Clerestory - Glass Double-Pane	Entire Building	850	SF	6	10+ years	
	Curtain wall - Glazed Double Pane	Entire Building	456	SF	6	6-10 years	
	Curtain wall - Insulated Panel	Entire Building	1,035	SF	6	6-10 years	
	Curtain wall - Louver	Entire Building	42	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	1,228	SF	6	10+ years	
	Windows - Casement Aluminum Double- pane	Entire Building	2,952	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	-					•	

Campus Name: Pirie Page : 3 of 28 Assessment Date: 02/14/2024

13

EΑ

6

6-10 years



650 E 85th STREET, Chicago, IL 60619

Catego	ry : Electrical		В	uilding	: Main		050 E 65111 STREET, CHICAGO, IL 60019
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency Battery Packs - Gym	1st Floor	4	EΑ	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	1st Floor	2	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	1st Floor	12	EΑ	2	0-1 year	Low battery AC generator
	Exit Signs - Gym	1st Floor	4	EΑ	2	0-1 year	No battery or AC generator
	Exit Signs - Lunchroom	1st Floor	2	EΑ	2	0-1 year	No battery or AC generator
	Automatic Transfer Switch	Boiler Room	1	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,046	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	4,352	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	2,200	SF	6	6-10 years	
	Security System - CCTV	Entire Building	43,063	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	43,063	SF	6	6-10 years	
Main Se	rvice						
	PA System	1st Floor	43,063	SF	6	6-10 years	Connected to modular building
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	-
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EΑ	7	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EΑ	7	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire ALarm Anunciator	Boiler Room and Entire Building	1	EA	7	10+ years	
	Fire Alarm Panel	Boiler Room and Entire Building	1	EA	7	10+ years	New fire and system installed in 2022
	Fire Alarm Strobe Lights	Boiler Room and Entire Building	43,063	SF	6	6-10 years	•
	Fire Alarm_System	Boiler Room and Entire Building	43,063	SF	7	10+ years	
	Fire Pump Controller	Boiler Room and Entire Building	1	EA	5	2-5 years	Functional, but very old
Pump R	oom Assembly						
	Fire Pump - Less than 25hp	Boiler Room	1	EA	6	6-10 years	
	Jockey Pump	Boiler Room	1	EA	6	6-10 years	
Sprinkle	r System						
	Sprinkler Heads	Entire Building	43,063	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	43,063	SF	7	6-10 years	
O	Nama: Diria	Pogo: 4	-1.00				Aggggment Date: 02/44/200

Campus Name: Pirie Page : 4 of 28 Assessment Date: 02/14/2024



650 E 85th STREET, Chicago, IL 60619

Catego	ry : Fire Protection		В	uilding	: Main		050 E 05111 51 REE1, CHICAGO, IL 00019
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Wet Sprinkler System	Entire Building	43,063	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond	<u> </u>						
	Chemical Pot Feeder	Boiler Room and Roof	1	EA	7	6-10 years	
	Chiller-Water Cooled- Cetrifugal - Less than	Boiler Room and Roof	1	EA	6	6-10 years	
	100 tons	D.1. D LD. (4	_ ^	•	0.40	
	Chiller-Water Cooled- Cetrifugal - Less than	Boiler Room and Roof	1	EA	6	6-10 years	
	100 tons Chiller-Water Cooled- Cetrifugal - Less than	Boiler Room and Roof	1	EA	6	6-10 years	Chillers are planned to be removed
	100 tons	Boller Room and Room	'	LA	U	0-10 years	along with cooling tower and replaced
	100 10113						with rooftop chiller unit.
	Chiller-Water Cooled- Cetrifugal - Less than	Boiler Room and Roof	1	EA	6	6-10 years	with roomop orimor drint.
	100 tons					,	
	Cooling Tower - Closed Cell	Boiler Room and Roof	1	EA	6	6-10 years	
	Glycol Feed	Boiler Room and Roof	1	EA	6	6-10 years	
	Pipes - Dual Temperature Pipe- Steel	Boiler Room and Roof	300	LF	6	6-10 years	
	Pressure Fill System	Boiler Room and Roof	1	EA	6	6-10 years	
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	6-10 years	Serves MDF room.
	than 5 tons						
_Air Hand	Iling Systems						
	Air Handling Unit- Package Single Zone-	Boiler Room	1	EA	6	6-10 years	Serves lunchroom area, in mezzanine
	Indoor- Dual Temperature Coils - 6000-					,	area of boiler room. Difficult to
	10000 cfm						access.
	Air Intake	Boiler Room	1	EA	6	6-10 years	
Doilor C	votomo						
Boiler S	Boiler Auxiliary- Non Condensing Hot Water	Boiler Room	2	EA	6	6-10 years	
	- 2001 - 3000 MBH	Donor Room	2		U	o To years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years	Glycol is manually fed into the
							system. No current leaking observed.
	Non Condensing- Water Tube- Flexible	Boiler Room	1	EA	6	6-10 years	
	Tube- Force Draft- Hot Water Boiler - 2001						
	- 3000 MBH	Dallan Danna	4	_^	0	0.40	
	Non Condensing- Water Tube- Flexible	Boiler Room	1	EA	6	6-10 years	
	Tube- Force Draft- Hot Water Boiler - 2001						
	- 3000 MBH Piping - Dual Temperature Pipes- Steel	Boiler Room	250	LF	6	6-10 years	
	i iping - Duai Temperature Fipes- Steel	Poliet Koolii	250	LF	U	0-10 years	
	Maria Bida		- F-(00				A 1 D - 1 - 00/44/0004

Campus Name: Pirie Page : 5 of 28 Assessment Date: 02/14/2024



	ry : Mechanical		В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Fill System	Boiler Room	1	EA	6	6-10 years	Pressure fill system. Boilers are fed off hot water pumps.
Heating [Devices						
	Fin Tube - Hot Water	1st Floor	15	LF	6	6-10 years	
	Unit Heater - Hot Water	Boiler Room	1	EA	6	6-10 years	
	Unit Heater - Hot Water	Boiler Room	2	EA	6	6-10 years	
	Wall Heater - Electric	Electrical Room	2	EA	6	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	16	EA	6	6-10 years	
Mechanio	cal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	
	Condenser Pump - 10 - 20 HP	Boiler Room	1	EA	5	6-10 years	
	Condenser Pump - 10 - 20 HP	Boiler Room	1	EA	5	6-10 years	
	Dual Temperature Pump - 10 - 20 HP	Boiler Room	1	EA	5	6-10 years	
	Dual Temperature Pump - 10 - 20 HP	Boiler Room	1	EA	5	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	500	LF	6	6-10 years	
Tempera	ture Control						
•	DDC System	Entire Building	43,063	SF	6	6-10 years	
	Electric Thermostat	Entire Building	5	EA	5	6-10 years	
	Thermostats - DDC	Entire Building	31	EA	6	6-10 years	
Unit Vent	ilation						
	Unit Ventilators- Floor Mounted- Dual	Entire Building	21	EA	6	6-10 years	
	Temperature Coils (Hot/Chilled) Water	Fatina Buildian	40	_^	0	0.40	Manual alia a Illa a Abancabant
	Unit Ventilators- Ceiling Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	10	EA	6	6-10 years	Mounted in ceilings, throughout building, underneath tiles
	remperature cons (not/crimed) water						building, underneath tiles
Ventilatio							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof & 1st floor	6	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof & 1st floor	7	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Roof & 1st floor	1	EA	2	0-1 year	No fire suppression system. Water only.
	Type II Exhaust Hood- Warming Kitchen	Roof & 1st floor	1	EA	5	6-10 years	Only 1 secondary hood



650 E 85th STREET, Chicago, IL 60619

Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 300001 - 600000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	43,063	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	43,063	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	43,063	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	43,063	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	43,063	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	43,063	SF	6	6-10 years	
	Sanitary Piping	Entire Building	43,063	SF	6	6-10 years	
	Storm Piping	Entire Building	43,063	SF	6	6-10 years	
	Vent Piping	Entire Building	43,063	SF	6	6-10 years	
	_		_				

Category : Room Building : Main

	. ,						
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•	rative Suites/Offices	Location	Quantity	OOW	Italik	Replacement	Comments
	Ceiling - Splined	1st flr east of kitchen, teacher's lounge	1,055	SF	6	10+ years	
	Ceiling - Splined	1st flr east of kitchen, teacher's lounge	2	SF	4	0-1 year	Water damage
	Ceiling - Splined	1st flr east of kitchen, teacher's lounge	5	SF	4	0-1 year	Damaged and loose tiles
	Doors - Wood Doors inclu hw	1st flr east of kitchen, teacher's lounge	1	EA	6	10+ years	
	Floor - Tile	1st flr east of kitchen, teacher's lounge	1,032	SF	7	10+ years	
	Floor - Tile	1st flr east of kitchen, teacher's lounge	30	SF	4	1-2 years	Damaged and missing tiles
	Lighting - Lay-in	1st flr east of kitchen, teacher's lounge	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st flr east of kitchen, teacher's lounge	12	EA	7	6-10 years	
	Power Distribution	1st flr east of kitchen, teacher's lounge	8	EA	7	10+ years	
	Walls - Concrete Block	1st flr east of kitchen, teacher's lounge	1,141	SF	7	10+ years	
	Ceiling - Splined	1st flr main office	1,023	SF	6	10+ years	





Torugh No. Topic Location Quantity UoM Replacement Comments	Catego	ry : Room		В	uilding	: Main		
Doors - Side-lite								
Doors - Transom Window	Group	• •					<u>-</u>	Comments
Doors - Wood Doors inclut hw								
Floor - Tile								
Lighting - Pendent/Surface 1st fir main office 24							10+ years	
Power Distribution			1st flr main office					
Storage Closet 1st fir main office 240 SF 7 10 + years Walls - Concrete Block 1st fir main office 2,794 SF 7 10 + years Work SInk 1st fir main office 31 EA 7 10 + years 10 +			1st flr main office				6-10 years	
Walls - Concrete Block			1st flr main office				10+ years	
Work Sink			1st flr main office				10+ years	
Ceiling - Splined		Walls - Concrete Block	1st flr main office	2,794		7	10+ years	
Doors - Transom Window Assistant principals Doors - Wood Doors inclu hw Assistant principals Floor - Tile Assistant principals Lighting - Pendent/Surface Assistant principals Assistant principals Lighting - Pendent/Surface Assistant principals Assistant principals Borrage Closet Assistant principals Assistant principals Assistant principals Assistant principals Assistant principals Assistant principals Borrage Closet Assistant principals Assistant principals Assistant principals Assistant principals Borrage Closet Borra		Work SInk	1st flr main office				10+ years	
Doors - Wood Doors inclu hw Assistant principals 2 EA 7 10+ years		Ceiling - Splined	Assistant principals	391			10+ years	
Floor - Tile		Doors - Transom Window	Assistant principals	6	SF	7	6-10 years	
Lighting - Pendent/Surface Assistant principals 6 EA 7 6-10 years Power Distribution Assistant principals 25 SF 7 10+ years Storage/ Closet Assistant principals 25 SF 7 10+ years Walls - Concrete Block Assistant principals 540 SF 7 10+ years Work SInk Assistant principals 1 EA 7 10+ years Work SInk Assistant principals 1 EA 7 10+ years Work SInk Assistant principals 1 EA 7 10+ years Ceiling - Splined Case manager office 270 SF 7 6-10 years Power Distribution Case manager office 2 EA 7 10+ years Power Distribution Power Steel Doors incl hw Case manager office 2 EA 7 10+ years Power Distribution Power Steel Doors incl hw Case manager office 2 EA 7 10+ years Power Distribution Power Steel Doors Steel Doors Incl hw Case manager office 4 EA 7 6-10 years Power Distribution Power Steel Doors Power Doors Doors Doors Doors Power Doors Doors Doors Power Doors Doors Power Doors Doors Doors Doors Doors Power Doors Do		Doors - Wood Doors inclu hw	Assistant principals	2		7	10+ years	
Power Distribution		Floor - Tile	Assistant principals	391	SF	7	10+ years	
Power Distribution		Lighting - Pendent/Surface		6	EΑ	7		
Storage/ Closet		Power Distribution		4	EA	7	10+ years	
Walls - Concrete Block Work Slnk Assistant principals Ceiling - Splined Case manager office Doors - Steel Doors inch w Case manager office Case ma		Storage/ Closet		25	SF	7	•	
Work Slnk Ceiling - Splined Case manager office Doors - Steel Doors incl hw Case manager office Case manager office Doors - Steel Doors incl hw Case manager office Ca					SF	7	10+ years	
Ceiling - Splined Case manager office 270 SF 7 6-10 years Floor - Tile Case manager office 2 EA 7 10+ years Floor - Tile Case manager office 270 SF 7 6-10 years Lighting - Pendent/Surface Case manager office 4 EA 7 6-10 years Walls - Concrete Block Case manager office 666 SF 7 10+ years Ceiling - Splined Counselor office 120 SF 7 10+ years Doors - Side-lite Counselor office 27 SF 7 10+ years Doors - Transom Window Counselor office 27 SF 7 10+ years Doors - Wood Doors inclu hw Counselor office 2 EA 7 10+ years Doors - Wood Doors inclu hw Counselor office 2 EA 7 10+ years Doors - Wood Doors inclu hw Counselor office 2 EA 7 10+ years Doors - Wood Doors inclu hw Counselor office 2 EA 7 6-10 years Walls - Concrete Block Counselor office 2 EA 7 6-10 years Walls - Concrete Block Counselor office 396 SF 7 10+ years Ceiling - Splined Engineer's Office 38 SF 7 10+ years Doors - Steel Doors incl hw Engineer's Office 1 EA 6 10+ years Floor - Concrete Engineer's Office 1 EA 6 10+ years Floor - Concrete Engineer's Office 1 EA 7 6-10 years Floor - Concrete Engineer's Office 1 EA 7 6-10 years Power Distribution Engineer's Office 2 EA 7 10+ years Power Distribution Engineer's Office 1 EA 7 10+ years Doors - Steel Doors incl hw Janitor's Lounge 97 SF 7 10+ years Doors - Steel Doors incl hw Janitor's Lounge 97 SF 7 10+ years Power Distribution Janitor's Lounge 97 SF 7 10+ years Power Distribution Janitor's Lounge 97 SF 7 10+ years Power Distribution Janitor's Lounge 97 SF 4 1-2 years Worn through. Lighting - Pendent/Surface Janitor's Lounge 97 SF 4 1-2 years Power Distribution Janitor's Lounge 97 SF 4 1-2 years Worn through. Ceiling - Exposed Nurse Office 400 SF 7 10+ years Power Distribution Janitor's Lounge 146 SF 7 10+ years Power Distribution Janitor's Lounge 146 SF 7 10+ years Power Distribution Janitor's Lounge 146 SF 7 10+ years Power Distribution Janitor's Lounge 146 SF 7 10+ years Power Distribution Janitor's Lounge 146 SF 7 10+ years Power Distribution Janitor's Lounge 146 SF 7 10+ years Power Distribution Power Defice		Work Sink		1	EA	7	10+ years	
Doors - Steel Doors incl hw Case manager office 2 EA 7 10+ years Floor - Tile Case manager office 270 SF 7 6-10 years Lighting - Pendent/Surface Case manager office 4 EA 7 6-10 years Walls - Concrete Block Case manager office 666 SF 7 10+ years Ceiling - Splined Counselor office 120 SF 7 10+ years Doors - Side-lite Counselor office 27 SF 7 10+ years Doors - Wood Doors inclu hw Counselor office 6 SF 7 10+ years Ploor - Tile Counselor office 120 SF 7 6-10 years Lighting - Pendent/Surface Counselor office 2 EA 7 6-10 years Walls - Concrete Block Counselor office 396 SF 7 10+ years Ceiling - Splined Engineer's Office 58 SF 7 10+ years Lighting - Pendent/Surface Engineer'		Ceiling - Splined		270	SF			
Floor - Tile Lighting - Pendent/Surface Case manager office Case Tase Tob years Case Tase Tase Tase Tob years Case Tase Tase Tase Tase Tase Tase Tase T								
Lighting - Pendent/Surface Case manager office 4 EA 7 6-10 years Walls - Concrete Block Case manager office 666 SF 7 10+ years Ceiling - Splined Counselor office 120 SF 7 10+ years Doors - Side-lite Counselor office 27 SF 7 10+ years Doors - Wood Doors inclu hw Counselor office 6 SF 7 10+ years Doors - Wood Doors inclu hw Counselor office 2 EA 7 10+ years Floor - Tile Counselor office 120 SF 7 6-10 years Lighting - Pendent/Surface Counselor office 2 EA 7 6-10 years Lighting - Pendent/Surface Counselor office 396 SF 7 10+ years Ceiling - Splined Engineer's Office 396 SF 7 10+ years Ceiling - Splined Engineer's Office 58 SF 7 10+ years Lighting - Pendent/Surface Engineer's Office 1 EA 6 10+ years Lighting - Pendent/Surface Engineer's Office 58 SF 7 10+ years Lighting - Pendent/Surface Engineer's Office 58 SF 7 10+ years Lighting - Pendent/Surface Engineer's Office 1 EA 7 6-10 years Lighting - Pendent/Surface Engineer's Office 1 EA 7 6-10 years Power Distribution Engineer's Office 2 EA 7 10+ years Ceiling - Exposed Janitor's Lounge 97 SF 7 10+ years Lighting - Pendent/Surface Janitor's Lounge 97 SF 7 10+ years Lighting - Pendent/Surface Janitor's Lounge 97 SF 4 1-2 years Worn through. Lighting - Pendent/Surface Janitor's Lounge 2 EA 7 6-10 years Power Distribution Janitor's Lounge 97 SF 4 1-2 years Worn through. Lighting - Pendent/Surface Janitor's Lounge 6 EA 7 10+ years Power Distribution Janitor's Lounge 146 SF 7 10+ years Power Distribution Janitor's Lounge 6 EA 7 10+ years Power Distribution Janitor's Lounge 7 EA 7 10+ years Power Distribution Janitor's Lounge 8 EA 7 10+ years Power Distribution Janitor's Lounge 97 SF 7 10+ years Power Distribution Janitor's Lounge 146 SF 7 10+ years Ceiling - Exposed Nurse Office 400 SF 7 10+ years		Floor - Tile		270	SF	7		
Walls - Concrete Block Ceiling - Splined Doors - Side-liteCase manager office Counselor office666 120 27 27 27 27 27 27 27 28 27 29 29 20 								
Ceiling - Splined Doors - Side-lite Doors - Transom Window Doors - Transom Window Counselor office Doors - Wood Doors inclu hw Counselor office Doors - Wood Doors inclu hw Counselor office Doors - Wood Doors inclu hw Counselor office Doors - Tile Doors - Tile Counselor office Doors - Tile Doors - Splined Doors - Steel Doors incl hw Engineer's Office Doors - Steel Doors incl hw Engineer's Office Engineer's Office Doors - Steel Doors incl hw Door							•	
Doors - Side-liteCounselor office27SF710+ yearsDoors - Transom WindowCounselor office6SF710+ yearsDoors - Wood Doors inclu hwCounselor office2EA710+ yearsFloor - TileCounselor office120SF76-10 yearsLighting - Pendent/SurfaceCounselor office2EA76-10 yearsWalls - Concrete BlockCounselor office396SF710+ yearsCeiling - SplinedEngineer's Office58SF710+ yearsDoors - Steel Doors incl hwEngineer's Office58SF710+ yearsFloor - ConcreteEngineer's Office58SF710+ yearsPower DistributionEngineer's Office1EA76-10 yearsPower DistributionEngineer's Office1EA76-10 yearsWalls - Concrete BlockEngineer's Office126SF710+ yearsWalls - Concrete BlockEngineer's Office126SF710+ yearsDoors - Steel Doors incl hwJanitor's Lounge97SF710+ yearsFloor - Epoxyl PaintedJanitor's Lounge97SF41-2 yearsPower DistributionJanitor's Lounge2EA76-10 yearsPower DistributionJanitor's Lounge2EA76-10 yearsPower DistributionJanitor's Lounge6EA710+ y							,	
Doors - Transom Window Doors - Wood Doors inclu hwCounselor office6SF710+ yearsFloor - Tile Lighting - Pendent/SurfaceCounselor office120SF76-10 yearsLighting - Pendent/SurfaceCounselor office2EA76-10 yearsWalls - Concrete BlockCounselor office396SF710+ yearsCeiling - SplinedEngineer's Office58SF710+ yearsDoors - Steel Doors incl hwEngineer's Office1EA610+ yearsFloor - ConcreteEngineer's Office58SF710+ yearsLighting - Pendent/SurfaceEngineer's Office1EA76-10 yearsPower DistributionEngineer's Office2EA710+ yearsWalls - Concrete BlockEngineer's Office126SF710+ yearsCeiling - ExposedJanitor's Lounge97SF710+ yearsPoors - Steel Doors incl hwJanitor's Lounge2EA66-10 yearsFloor - Epoxy/ PaintedJanitor's Lounge97SF41-2 yearsWorn through.Lighting - Pendent/SurfaceJanitor's Lounge2EA76-10 yearsPower DistributionJanitor's Lounge6EA710+ yearsWalls - Concrete BlockJanitor's Lounge6EA710+ yearsWalls - Concrete BlockJanitor's Lounge6EA710+ years <td></td> <td>• •</td> <td>Counselor office</td> <td>27</td> <td>SF</td> <td></td> <td>,</td> <td></td>		• •	Counselor office	27	SF		,	
Doors - Wood Doors inclu hw Floor - Tile Counselor office Lighting - Pendent/Surface Walls - Concrete Block Counselor office Engineer's Office Counselor office Engineer's Off		Doors - Transom Window	Counselor office	6	SF			
Floor - Tile Counselor office 120 SF 7 6-10 years Lighting - Pendent/Surface Counselor office 2 EA 7 6-10 years Walls - Concrete Block Counselor office 396 SF 7 10+ years Ceiling - Splined Engineer's Office 58 SF 7 10+ years Doors - Steel Doors incl hw Engineer's Office 1 EA 6 10+ years Floor - Concrete Engineer's Office 58 SF 7 10+ years Lighting - Pendent/Surface Engineer's Office 1 EA 7 6-10 years Power Distribution Engineer's Office 1 EA 7 10+ years Walls - Concrete Block Engineer's Office 12 EA 7 10+ years Ceiling - Exposed Janitor's Lounge 97 SF 7 10+ years Floor - Epoxy/ Painted Janitor's Lounge 97 SF 4 1-2 years Worn through. Lighting - Pendent/Surface Janitor's Lounge 6 EA 7 10+ years Power Distribution Janitor's Lounge 146 SF 7 10+ years Ceiling - Exposed Nurse Office 146 SF 7 10+ years Floor - Epoxyl Painted Janitor's Lounge 146 SF 7 10+ years Walls - Concrete Block Janitor's Lounge 146 SF 7 10+ years Ceiling - Exposed Nurse Office 400 SF 7 10+ years		Doors - Wood Doors inclu hw	Counselor office	2				
Lighting - Pendent/Surface Walls - Concrete Block Counselor office Colling - Splined Colling - Splined Engineer's Office Doors - Steel Doors incl hw Engineer's Office Enginer		Floor - Tile	Counselor office		SF			
Walls - Concrete Block Ceiling - Splined Engineer's Office Doors - Steel Doors incl hw Engineer's Office Engineer's Offi		Lighting - Pendent/Surface				7		
Ceiling - SplinedEngineer's Office58SF710+ yearsDoors - Steel Doors incl hwEngineer's Office1EA610+ yearsFloor - ConcreteEngineer's Office58SF710+ yearsLighting - Pendent/SurfaceEngineer's Office1EA76-10 yearsPower DistributionEngineer's Office2EA710+ yearsWalls - Concrete BlockEngineer's Office126SF710+ yearsCeiling - ExposedJanitor's Lounge97SF710+ yearsDoors - Steel Doors incl hwJanitor's Lounge2EA66-10 yearsFloor - Epoxy/ PaintedJanitor's Lounge97SF41-2 yearsWorn through.Lighting - Pendent/SurfaceJanitor's Lounge2EA76-10 yearsPower DistributionJanitor's Lounge2EA76-10 yearsWalls - Concrete BlockJanitor's Lounge146SF710+ yearsCeiling - ExposedNurse Office400SF710+ years							•	
Doors - Steel Doors incl hwEngineer's Office1EA610+ yearsFloor - ConcreteEngineer's Office58SF710+ yearsLighting - Pendent/SurfaceEngineer's Office1EA76-10 yearsPower DistributionEngineer's Office2EA710+ yearsWalls - Concrete BlockEngineer's Office126SF710+ yearsCeiling - ExposedJanitor's Lounge97SF710+ yearsDoors - Steel Doors incl hwJanitor's Lounge2EA66-10 yearsFloor - Epoxy/ PaintedJanitor's Lounge97SF41-2 yearsWorn through.Lighting - Pendent/SurfaceJanitor's Lounge2EA76-10 yearsPower DistributionJanitor's Lounge2EA76-10 yearsWalls - Concrete BlockJanitor's Lounge6EA710+ yearsCeiling - ExposedNurse Office400SF710+ years							,	
Floor - Concrete Engineer's Office 58 SF 7 10+ years Lighting - Pendent/Surface Engineer's Office 1 EA 7 6-10 years Power Distribution Engineer's Office 2 EA 7 10+ years Walls - Concrete Block Engineer's Office 126 SF 7 10+ years Ceiling - Exposed Janitor's Lounge 97 SF 7 10+ years Doors - Steel Doors incl hw Janitor's Lounge 2 EA 6 6-10 years Floor - Epoxy/ Painted Janitor's Lounge 97 SF 4 1-2 years Worn through. Lighting - Pendent/Surface Janitor's Lounge 2 EA 7 6-10 years Power Distribution Janitor's Lounge 6 EA 7 10+ years Walls - Concrete Block Janitor's Lounge 146 SF 7 10+ years Ceiling - Exposed Nurse Office 400 SF 7 10+ years							,	
Lighting - Pendent/Surface Engineer's Office 1 EA 7 6-10 years Power Distribution Engineer's Office 2 EA 7 10+ years Walls - Concrete Block Engineer's Office 126 SF 7 10+ years Ceiling - Exposed Janitor's Lounge 97 SF 7 10+ years Doors - Steel Doors incl hw Janitor's Lounge 2 EA 6 6-10 years Floor - Epoxy/ Painted Janitor's Lounge 97 SF 4 1-2 years Worn through. Lighting - Pendent/Surface Janitor's Lounge 2 EA 7 6-10 years Power Distribution Janitor's Lounge 2 EA 7 6-10 years Walls - Concrete Block Janitor's Lounge 6 EA 7 10+ years Walls - Concrete Block Janitor's Lounge 146 SF 7 10+ years Ceiling - Exposed Nurse Office 400 SF 7 10+ years				58				
Power Distribution Engineer's Office 2 EA 7 10+ years Walls - Concrete Block Engineer's Office 126 SF 7 10+ years Ceiling - Exposed Janitor's Lounge Doors - Steel Doors incl hw Janitor's Lounge Floor - Epoxy/ Painted Janitor's Lounge Janitor's Lounge Power Distribution Janitor's Lounge Janitor's Lounge Power Distribution Janitor's Lounge Janitor's Lounge Power Distribution Janitor's Lounge Power Distribution Janitor's Lounge Floor - Epoxy/ Painted Janitor's Lounge Power Distribution Janitor's Lounge Floor - Epoxy/ Painted Floor - Epoxy/ Pain		Lighting - Pendent/Surface				7	•	
Walls - Concrete Block Ceiling - Exposed Janitor's Lounge Doors - Steel Doors incl hw Janitor's Lounge Floor - Epoxy/ Painted Janitor's Lounge Bower Distribution Janitor's Lounge Janitor's Loun			•					
Ceiling - Exposed Janitor's Lounge 97 SF 7 10+ years Doors - Steel Doors incl hw Janitor's Lounge 2 EA 6 6-10 years Floor - Epoxy/ Painted Janitor's Lounge 97 SF 4 1-2 years Worn through. Lighting - Pendent/Surface Janitor's Lounge 2 EA 7 6-10 years Power Distribution Janitor's Lounge 6 EA 7 10+ years Walls - Concrete Block Janitor's Lounge 146 SF 7 10+ years Ceiling - Exposed Nurse Office 400 SF 7 10+ years		Walls - Concrete Block	•		SF	7	-	
Doors - Steel Doors incl hwJanitor's Lounge2EA66-10 yearsFloor - Epoxy/ PaintedJanitor's Lounge97SF41-2 yearsWorn through.Lighting - Pendent/SurfaceJanitor's Lounge2EA76-10 yearsPower DistributionJanitor's Lounge6EA710+ yearsWalls - Concrete BlockJanitor's Lounge146SF710+ yearsCeiling - ExposedNurse Office400SF710+ years			S .				,	
Floor - Epoxy/ Painted Janitor's Lounge 97 SF 4 1-2 years Worn through. Lighting - Pendent/Surface Janitor's Lounge 2 EA 7 6-10 years Power Distribution Janitor's Lounge 6 EA 7 10+ years Walls - Concrete Block Janitor's Lounge 146 SF 7 10+ years Ceiling - Exposed Nurse Office 400 SF 7 10+ years		• .	•					
Lighting - Pendent/Surface Janitor's Lounge 2 EA 7 6-10 years Power Distribution Janitor's Lounge 6 EA 7 10+ years Walls - Concrete Block Janitor's Lounge 146 SF 7 10+ years Ceiling - Exposed Nurse Office 400 SF 7 10+ years								Worn through.
Power DistributionJanitor's Lounge6EA710+ yearsWalls - Concrete BlockJanitor's Lounge146SF710+ yearsCeiling - ExposedNurse Office400SF710+ years					_			.
Walls - Concrete Block Janitor's Lounge 146 SF 7 10+ years Ceiling - Exposed Nurse Office 400 SF 7 10+ years								
Ceiling - Exposed Nurse Office 400 SF 7 10+ years							•	
200.0								
				Ŭ	٥.	•	, Jours	



Catego	ry : Room		В	uilding	: Main		<u> </u>
_				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Nurse Office	3	EA	7	10+ years	
	Floor - Carpet	Nurse Office	395	SF	7	10+ years	
	Floor - Carpet	Nurse Office	5	SF	4	1-2 years	Worn threshold
	Lighting - Pendent/Surface	Nurse Office	7	EΑ	7	6-10 years	
	Power Distribution	Nurse Office	6	EA	7	10+ years	
	Storage/ Closet	Nurse Office	30	SF	7	10+ years	
	Walls - Concrete Block	Nurse Office	896	SF	7	10+ years	
	Work SInk	Nurse Office	1	EA	7	10+ years	
	Ceiling - Splined	Principal Office	231	SF	7	10+ years	
	Doors - Transom Window	Principal Office	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal Office	2	EA	7	10+ years	
	Floor - Tile	Principal Office	231	SF	7	10+ years	
	Lighting - Pendent/Surface	Principal Office	4	EA	7	6-10 years	
	Power Distribution	Principal Office	10	EA	7	10+ years	
	Storage/ Closet	Principal Office	30	SF	7	10+ years	
	Walls - Concrete Block	Principal Office	344	SF	7	10+ years	
_Gvmnas	ia						
	Ceiling - Exposed	1st Floor	4,352	SF	7	10+ years	No occupancy signage
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	. to occupancy eignage
	Floor - Tile	1st Floor	400	SF	7	10+ years	
	Floor - Wood	1st Floor	3,952	SF	7	10+ years	
	Lighting - Metal Halide/Sodium Vapor	1st Floor	12	ĒΑ	7	6-10 years	
	Scoreboards	1st Floor	1	EA	7	10+ years	
	Sound System	1st Floor	1	EΑ	7	10+ years	
	Stage	1st Floor	481	SF	7	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	i 1	EΑ	7	6-10 years	
	Storage/ Closet	1st Floor	304	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	2,981	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,981	SF	7	10+ years	
1.00							
<u>Kitchen</u>	0.11.	4 . 5					
	Ceiling - Splined	1st Floor	1,016	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Tile	1st Floor	1,016	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Serving Line	1st Floor	25	LF	7	10+ years	
	Storage/ Closet	1st Floor	102	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,074	SF	7	10+ years	



650 E 85th STREET, Chicago, IL 60619

Catego	Category : Room			uilding	: Main		
_						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Locker/S	hower Room						
	Accessories	1st flr NE corner	152	SF	7	6-10 years	
	Ceiling - Splined (Moister Resistance)	1st flr NE corner	152	SF	6	10+ years	
	Doors - Transom Window	1st flr NE corner	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st flr NE corner	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr NE corner	152	SF	6	10+ years	
	Lavatory	1st flr NE corner	1	EA	7	10+ years	
	Lighting - Lay-in	1st flr NE corner	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st flr NE corner	1	EA	7	6-10 years	
	Partitions	1st flr NE corner	1	EA	7	10+ years	
	Student Lockers - One Tier	1st flr NE corner	5	EA	6	6-10 years	
	Walls - Structural Glazed Tile	1st flr NE corner	326	SF	7	10+ years	
	Water Closet	1st flr NE corner	1	EA	7	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Splined	1st Floor	1,850	SF	7	10+ years	
	Chalk Board	1st Floor	6	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,850	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	43	EA	7	6-10 years	
	Storage/ Closet	1st Floor	236	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	551	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,653	SF	7	10+ years	
_MDF_ID	E						
_	Doors - Steel Doors incl hw	1st floor south of kitchen	1	EA	7	10+ years	
	Finishes	1st floor south of kitchen	143	SF	7	10+ years	
	Other Cooling Unit	1st floor south of kitchen	1	EA	7	10+ years	Ductless split system.
_Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	1,394	SF	5	10+ years	
	Janitor's Closet	1st Floor	138	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	320	SF	7	10+ years	
	Storage Room	1st Floor	592	SF	7	10+ years	
	Mechanical/ Service Rooms	Chiller Room	165	SF	7	10+ years	
_Restroor	n						
	Accessories	1st flr inside principal's office	22	SF	7	6-10 years	
	Ceiling - Splined	1st flr inside principal's office	22	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside principal's office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr inside principal's office	22	SF	7	10+ years	

Campus Name: Pirie Page : 10 of 28 Assessment Date: 02/14/2024



Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1st flr inside principal's office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st flr inside principal's office	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st flr inside principal's office	60	SF	7	10+ years	
	Water Closet	1st flr inside principal's office	1	EA	7	10+ years	
	Accessories	1st flr inside teacher's lounge	29	SF	7	6-10 years	
	Ceiling - Splined	1st flr inside teacher's lounge	29	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st flr inside teacher's lounge	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st flr inside teacher's lounge	29	SF	7	10+ years	
	Lavatory	1st flr inside teacher's lounge	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st flr inside teacher's lounge	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st flr inside teacher's lounge	76	SF	7	10+ years	
	Water Closet	1st flr inside teacher's lounge	1	EA	7	10+ years	
	Accessories	All Gender near Faculty Lounge	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	All Gender near Faculty Lounge	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	All Gender near Faculty Lounge	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	All Gender near Faculty Lounge	70	SF	7	10+ years	
	Floor Drain	All Gender near Faculty Lounge	1	ĒΑ	7	10+ years	
	Hand Dryer	All Gender near Faculty Lounge	1	EA	7	10+ years	
	Lavatory	All Gender near Faculty Lounge	1	EA	7	10+ years	
	Lighting - Pendent/Surface	All Gender near Faculty Lounge	1	ĒΑ	7	6-10 years	
	Walls - Concrete Block	All Gender near Faculty Lounge	96	SF	7	10+ years	
	Walls - Plaster/Drywall	All Gender near Faculty Lounge	30	SF	7	10+ years	
	Walls - Structural Glazed Tile	All Gender near Faculty Lounge	124	SF	7	10+ years	
	Water Closet	All Gender near Faculty Lounge	1	ĒΑ	7	10+ years	
	Accessories	In Room 115, Library	21	SF	7	6-10 years	
	Ceiling - Splined	In Room 115, Library	21	SF	7	10+ years	
	Doors - Transom Window	In Room 115, Library	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 115, Library	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Room 115, Library	21	SF	7	10+ years	
	Lavatory	In Room 115, Library	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	In Room 115, Library	1	ĒΑ	7	6-10 years	
	Walls - Structural Glazed Tile	In Room 115, Library	71	SF	6	10+ years	
	Walls - Structural Glazed Tile	In Room 115, Library	10	SF	4	0-1 year	Portions of wall displaced
	Water Closet	In Room 115, Library	1	ĒΑ	7	10+ years	γ
	Accessories	In Room 116	21	SF	7	6-10 years	
	Ceiling - Splined	In Room 116	21	SF	7	10+ years	
	Doors - Transom Window	In Room 116	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Room 116	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	In Room 116	21	SF	7	10+ years	
	Lavatory	In Room 116	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Room 116	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	In Room 116	81	SF	7	10+ years	
	Water Closet	In Room 116	1	EA	7	10+ years	
	Accessories	Inside Assistant Principals office	21	SF	7	6-10 years	
					•	3 .0 ,00.0	



Catego	ry : Room		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Splined	Inside Assistant Principals office	21	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Inside Assistant Principals office	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Inside Assistant Principals office	21	SF	7	10+ years	
	Lighting - Pendent/Surface	Inside Assistant Principals office	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	Inside Assistant Principals office	60	SF	7	10+ years	
	Water Closet	Inside Assistant Principals office	1	EA	7	10+ years	
	Accessories	Janitor's Area	88	SF	7	6-10 years	
	Ceiling - Splined	Janitor's Area	88	SF	7	10+ years	
	Doors - Steel Doors incl hw	Janitor's Area	1	EA	7	10+ years	
	Floor - Epoxy/ Painted	Janitor's Area	88	SF	4	1-2 years	Worn finish
	Floor Drain	Janitor's Area	1	EA	7	10+ years	
	Lavatory	Janitor's Area	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Janitor's Area	2	EA	7	6-10 years	
	Partitions	Janitor's Area	1	EA	7	10+ years	
	Showers	Janitor's Area	1	EA	4	1-2 years	Not functioning
	Walls - Structural Glazed Tile	Janitor's Area	166	SF	6	10+ years	3
	Water Closet	Janitor's Area	1	EA	7	10+ years	
	Accessories	North	267	SF	5	2-5 years	
	Ceiling - Splined	North	267	SF	7	10+ years	
	Doors - Wood Doors inclu hw	North	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	North	267	SF	7	10+ years	
	Floor Drain	North	1	EA	7	10+ years	
	Lavatory	North	3	EA	7	10+ years	
	Lighting - Pendent/Surface	North	6	EA	7	6-10 years	
	Partitions	North	4	EA	7	10+ years	
	Urinals	North	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	North	586	SF	7	10+ years	
	Water Closet	North	4	EA	7	10+ years	
	Accessories	North	267	SF	7	6-10 years	
	Ceiling - Splined	North	267	SF	7	10+ years	
	Doors - Wood Doors inclu hw	North	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	North	267	SF	7	10+ years	
	Floor Drain	North	1	EA	7	10+ years	
	Lavatory	North	3	EA	7	10+ years	
	Lighting - Pendent/Surface	North	7	EA	7	6-10 years	
	Partitions	North	8	EA	7	10+ years	
	Walls - Structural Glazed Tile	North	586	SF	7	10+ years	
	Water Closet	North	8	ĒΑ	7	10+ years	
	Accessories	South	267	SF	7	6-10 years	
	Ceiling - Splined	South	267	SF	7	10+ years	
	Doors - Wood Doors inclu hw	South	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	South	267	SF	7	10+ years	
	Floor Drain	South	1	EA	7	10+ years	
	Hand Dryer	South	1	EΑ	7	6-10 years	
	,		·		•	, ,	



650 E 85th STREET, Chicago, IL 60619

Catego	ry : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	South	3	EΑ	7	10+ years	
	Lighting - Lay-in	South	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	South	6	EA	7	6-10 years	
	Partitions	South	1	EA	7	10+ years	
	Urinals	South	4	EΑ	7	10+ years	
	Walls - Structural Glazed Tile	South	586	SF	7	10+ years	
	Water Closet	South	1	EA	7	10+ years	
	Accessories	South	267	SF	7	6-10 years	
	Ceiling - Splined	South	267	SF	7	10+ years	
	Doors - Wood Doors inclu hw	South	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	South	267	SF	7	10+ years	
	Floor Drain	South	1	EΑ	7	10+ years	
	Hand Dryer	South	1	EΑ	7	6-10 years	
	Lavatory	South	3	EA	7	10+ years	
	Lighting - Pendent/Surface	South	7	EA	7	6-10 years	
	Partitions	South	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	South	586	SF	7	10+ years	
	Water Closet	South	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	South		SF	7 7 7	10+ years	

Category : Classroom Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Regular Classroom)						
	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Water damaged
	Ceiling - Splined	1st Floor	758	SF	6	10+ years	-
	Ceiling - Splined	1st Floor	15	SF	4	1-2 years	Water damage or missing tile
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	864	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	288	SF	7	10+ years	
Classroo	om #102 (Regular Classroom)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	773	SF	6	10+ years	
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	-

Campus Name: Pirie Page : 13 of 28 Assessment Date: 02/14/2024



650 E 85th STREET, Chicago, IL 60619

Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	652	SF	6	10+ years	
	Walls - Metal Panel	1st Floor	500	SF	6	10+ years	
lassroc	om #103 (Regular Classroom)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	783	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	ĒΑ	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	652	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	500	SF	7	10+ years	
						,	
Classroc	m #104 (Regular Classroom)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	2	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	10+ years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,152	SF	7	10+ years	
Classroc	m #105 (Store Room)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Chalk Board	1st Floor	18	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EΑ	6	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	864	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	288	SF	5	10+ years	
	Trails Motal Lation	1001 1001	200	01	3	ioi youis	
lassroc	om #106 (Faculty Lounge)						

Campus Name: Pirie Page : 14 of 28 Assessment Date: 02/14/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Chalk Board	1st Floor	18	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EΑ	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	864	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	288	SF	5	10+ years	
Classroo	om #107 (Science Classroom)						
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	200	SF	7	10+ years	
	Ceiling - Splined	1st Floor	604	SF	7	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	804	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	6-10 years	
Classroo	om #108 (Regular Classroom)						
	Casework	1st Floor	8	LF	7	10+ years	
	Ceiling - Splined	1st Floor	804	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	704	SF	7	10+ years	
	Floor - Tile	1st Floor	100	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	zamagea mee
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	5	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #109 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Splined	1st Floor	804	SF	6	10+ years	
	Chalk Board	1st Floor	22	LF	4	2-5 years	
	200.0		<i></i>		•	_ 0 ,00.0	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	789	SF	7	10+ years	
	Floor - Tile	1st Floor	15	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	5	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #110 (Office)						
	Casework	1st Floor	8	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	201	SF	6	10+ years	
	Ceiling - Splined	1st Floor	603	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	784	SF	7	10+ years	
	Floor - Tile	1st Floor	20	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	8	EA	7	6-10 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	5	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #111 (Computer Lab)						
Olabbioc	Ceiling - Plaster/Drywall	1st Floor	201	SF	6	10+ years	
	Ceiling - Flaster/Brywaii Ceiling - Splined	1st Floor	603	SF	6	10+ years	
	Chalk Board	1st Floor	22	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	8	SF	7	,	
	Doors - Side-life Doors - Wood Doors inclu hw	1st Floor	0	EA	6	10+ years	
	Floor - Carpet	1st Floor	804	SF	7	10+ years 2-5 years	
		1st Floor		EA	7		
	Lighting - Pendent/Surface		9	SF		6-10 years	
	Storage/ Closet	1st Floor	9		7	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	5	10+ years	
	Wireless System	1st Floor	1	EA	7	6-10 years	
Classroo	om #112 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	134	SF	6	10+ years	
	Ceiling - Splined	1st Floor	670	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		650 E 65111 STREET, CHICAGO, IL 60619
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	804	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	Locked
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	6	10+ years	Quality adjusted
	Work Sink	1st Floor	1	EA	7	6-10 years	addiny dajustod
Classroo	om #113 (Regular Classroom)						
Oldooroe	Casework	1st Floor	8	LF	4	1-2 years	Damaged casework
	Ceiling - Plaster/Drywall	1st Floor	134	SF	6	10+ years	Damaged casework
	Ceiling - Flaster/Drywaii Ceiling - Splined	1st Floor	665	SF	6	10+ years	
	Ceiling - Splined Ceiling - Splined	1st Floor	5	SF	4	1-2 years	Missing tiles
	Doors - Side-lite			SF			Missing tiles
		1st Floor	8		7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	704	SF	7	10+ years	
	Floor - Tile	1st Floor	100	SF	4	1-2 years	Large cracks
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	Quality adjusted
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	6	10+ years	Quality adjusted
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	om #114 (Regular Classroom)						
	Casework	1st Floor	8	LF	6	6-10 years	Casework covered
	Ceiling - Plaster/Drywall	1st Floor	201	SF	6	10+ years	
	Ceiling - Splined	1st Floor	595	SF	6	10+ years	
	Ceiling - Splined	1st Floor	8	SF	4	1-2 years	Missing and damaged tiles
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	794	SF	7	10+ years	
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Chipping tiles
	Lighting - Pendent/Surface	1st Floor	9	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	590	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	590	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
Classroo	nm #115 (Library)						
	Ceiling - Plaster/Drywall	1st Floor	100	SF	7	6-10 years	
	Ceiling - Flaster/Drywaii Ceiling - Splined	1st Floor	1,093	SF	6	10+ years	
	Gening - Opinieu	13(1100)	1,093	JI.	U	10+ years	



atego	ry : Classroom		В	uilding	: Main		
						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Splined	1st Floor	10	SF	4	0-1 year	Water damage
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,203	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,072	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	358	SF	6	10+ years	
assroc	om #116 (Other Instructional Use)						
	Casework	1st Floor	24	LF	4	1-2 years	Damaged and missing doors
	Ceiling - Plaster/Drywall	1st Floor	100	SF	7	6-10 years	- aagoa a.ia iiioonig aooio
	Ceiling - Flaster/Drywaii Ceiling - Splined	1st Floor	1,093	SF	6	10+ years	
	Ceiling - Splined	1st Floor	10	SF	4	0-1 year	Water damage
	Doors - Side-lite	1st Floor	7	SF	7		Water damage
				SF SF		10+ years	
	Doors - Transom Window	1st Floor	8		7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,193	SF	7	10+ years	
	Floor - Tile	1st Floor	10	SF	4	0-1 year	Missing tiles
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	Qty adjusted to match observed
	Walls - Concrete Block	1st Floor	1,072	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	358	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
ssroc	om #117 (Music Room)						
	Ceiling - Splined	1st Floor	773	SF	6	10+ years	
	Ceiling - Splined	1st Floor	10	SF	4	0-1 year	Water damage
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	-
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	763	SF	7	10+ years	
	Floor - Tile	1st Floor	20	SF	4	0-1 year	Damaged.
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Storage/ Closet	1st Floor	100	SF	7	10+ years	Sq footage updated
	Walls - Concrete Block	1st Floor	864	SF	7	10+ years	54 lookago apaaloa
	Walls - Metal Panel	1st Floor	288	SF	6	10+ years	
ssroc	om #118 (Regular Classroom)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Doors - Side-lite	1st Floor	7 7	SF	7	10+ years	
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Halisolli Williauw	131 1 1001	0	J.	,	TOT years	



650 E 85th STREET, Chicago, IL 60619

Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	Locked
	Walls - Concrete Block	1st Floor	864	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	288	SF	6	10+ years	
Classroc	om #119 (Regular Classroom)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Chalk Board	1st Floor	21	LF	4	2-5 years	Removed
	Doors - Side-lite	1st Floor	7	SF	7	10+ years	rtomovou
	Doors - Transom Window	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	763	SF	7	10+ years	
	Floor - Tile	1st Floor	20	SF	5	1-2 years	Cracks and chipping
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	Cracks and emphing
	Walls - Concrete Block	1st Floor	894	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	288	SF	6	10+ years	
		1001	200	O.	Ū	101 youro	
Classroc	om #120 (Regular Classroom)						
	Ceiling - Splined	1st Floor	778	SF	6	10+ years	
	Ceiling - Splined	1st Floor	3	SF	4	0-1 year	Missing tiles
	Ceiling - Splined	1st Floor	2	SF	4	0-1 year	Water damage
	Doors - Side-lite	1st Floor	14	SF	7	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	Locked
	Walls - Concrete Block	1st Floor	894	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	288	SF	6	10+ years	
Classroc	om #121 (Regular Classroom)						
	Ceiling - Splined	1st Floor	783	SF	6	10+ years	
	Doors - Side-lite	1st Floor	14	SF	7	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	894	SF	7	10+ years	
	Walls - Concrete Block Walls - Metal Panel	1st Floor	89 4 288	SF SF	<i>7</i> 6	•	
	vvalis - ivietai Pariel	ISL FIOOF	288	or.	О	10+ years	

Campus Name: Pirie Page : 19 of 28 Assessment Date: 02/14/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #122 (Regular Classroom)						
	Ceiling - Splined	1st Floor	773	SF	6	10+ years	
	Ceiling - Splined	1st Floor	3	SF	4	0-1 year	Water damage
	Ceiling - Splined	1st Floor	7	SF	4	0-1 year	Damaged tiles
	Doors - Side-lite	1st Floor	14	SF	7	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	783	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	894	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	288	SF	6	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
Corridor	Ceiling - Lay-in	1st Floor	7,046	SF	7	10+ years	
Corridor	Ceiling - Lay-in Doors - Side-lite	1st Floor 1st Floor	7,046 16	SF SF	7 7	10+ years 10+ years	
Corridor							
Corridor	Doors - Side-lite	1st Floor	16	SF	7	10+ years	
Corridor	Doors - Side-lite Doors - Steel Doors incl hw	1st Floor 1st Floor	16 4	SF EA	7 7	10+ years 10+ years	
Corridor	Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain	1st Floor 1st Floor 1st Floor	16 4 12	SF EA SF EA EA	7 7 7	10+ years 10+ years 10+ years	
Corridor	Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window	1st Floor 1st Floor 1st Floor 1st Floor	16 4 12	SF EA SF EA	7 7 7 7	10+ years 10+ years 10+ years 6-10 years	
Corridor	Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	16 4 12 2 1	SF EA SF EA EA	7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 6-10 years	
Corridor	Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	16 4 12 2 1 7,046	SF EA SF EA SF EA	7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
Corridor	Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in	1st Floor	16 4 12 2 1 7,046 64	SF EA SF EA SF EA SF	7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 6-10 years	
Corridor	Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers	1st Floor	16 4 12 2 1 7,046 64 180	SF EA SF EA SF EA	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years	
	Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block	1st Floor	16 4 12 2 1 7,046 64 180 9,167	SF EA SF EA SF EA SF	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years	
Safety	Doors - Side-lite Doors - Steel Doors incl hw Doors - Transom Window Drinking Fountains - Double Fountain Drinking Fountains - Single Fountain Floor - Tile/Sheet Lighting - Lay-in Student Lockers - Two Tiers Walls - Concrete Block	1st Floor	16 4 12 2 1 7,046 64 180 9,167	SF EA SF EA SF EA SF	7 7 7 7 7 7 7	10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years 10+ years 10+ years	





Category: Exterior Building: Modular 1 (4-Classroom) Recommend Location Replacement Item - Type Quantity **UOM** Rank Comments Group Entrance Exterior Doors - Exterior FRP Door #10 - W 2 FΑ 7 10+ years Newly replaced #9 - E EΑ 7 Entrance Control - Audio and Video 1 6-10 years 2 Exterior Doors - Exterior FRP Door #9 - E EΑ 10+ years New doors _Foundation Foundation - Masonry LF 7 **Entire Building** 280 10+ years SF Superstructure - Steel **Entire Building** 4.947 7 10+ years Lighting 7 Exterior Lighting - Wall Mounted **Entire Building** 8 EΑ 10+ years New Roof System Coping - Metal Main Roof LF 280 6 10+ years **Downspouts - Exterior Downspouts** Main Roof LF 6 10+ years 44 Roof - Modified Bitumen Main Roof SF 4,947 6 10+ years Brand new roof. Signs of standing water. Roof Structure - Steel / Metal Deck/ Main Roof 4.947 SF 7 10+ years Concrete Topping Walls Exterior Walls - Hardie Board **Entire Building** 2,055 SF 7 10+ years Newly replaced.\nQuantity changed to match current observations. Exterior Walls - Prefabricated Metal Panel SF 7 Newly replaced. Quantity changed to **Entire Building** 1.027 10+ years Wall match current observations. Windows Guard - Guards perforated **Entire Building** 256 SF 7 10+ years Newly replaced. SF Windows - Sash Aluminum Double-pane **Entire Building** 256 7 10+ years Newly replaced. Category: Electrical Building: Modular 1 (4-Classroom) Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Emergency System SF Security System - Intrusion Detection 1st Floor 4.947 6 6-10 years Emergency Battery Packs - Corridors and EΑ **Entire Building** 6 6 6-10 years Stairs Exit Signs - Corridors and Stairs **Entire Building** EΑ 6-10 years Main Service



650 E 85th STREET, Chicago, IL 60619

Catego	ry : Electrical		В	uilding	: Modul	ar 1 (4-Classro	om)
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	PA System	1st Floor	4,200	SF	7	6-10 years	PA system in the main building services modular also
	Main Electrical Service - 1000 A 120/208/3PH	Site - East	1	EA	6	10+ years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Mechanical Room	2	EA	7	6-10 years	
Catego	ry : Fire Protection		В	uilding	: Modul	ar 1 (4-Classro	om)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire ALarm Anunciator	1st Floor	1	EA	7	10+ years	
	Fire Alarm Panel	1st Floor	1	EA	7	10+ years	
	Fire Alarm Strobe Lights	1st Floor	4,947	SF	7	10+ years	
	Fire Alarm_System	1st Floor	4,947	SF	7	10+ years	
Sprinkle	r System						
•	Sprinkler Heads	Entire Building	4,947	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	4,947	SF	7	6-10 years	
	Wet Sprinkler System	Entire Building	4,947	SF	7	6-10 years	
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (4-Classro	om)
						Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u> Tempera</u>	ature Control						
	Electric Thermostat	Entire Building	4	EA	7	10+ years	Serves four exterior univent.
Jnit Ven	tilation						
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	4	EA	7	6-10 years	
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	2	EA	6	6-10 years	

Campus Name: Pirie Page : 22 of 28 Assessment Date: 02/14/2024



Category : Plumbing			Building : Modular 1 (4-Classroom)					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
lot Wate								
	Electric Heater - Less than 20 KW	Mechanical Room	1	EA	6	6-10 years		
Piping								
	Domestic Piping-Hot Water Return Lines	Entire Building	4,947	SF	6	6-10 years		
	Domestic Piping-Hot/Cold Water Supply	Entire Building	4,947	SF	6	10+ years		
	(Horizontal Lines)	9	.,.	-	•	, , , , , , , , , , , , , , , , , , , ,		
	Sanitary Piping	Entire Building	4,947	SF	6	6-10 years		
	Storm Piping	Entire Building	4,947	SF	6	6-10 years		
	Vent Piping	Entire Building	4,947	SF	6	6-10 years		
		9	,,,	-		,		
Catego	ry : Classroom		В	uilding	: Modul	ar 1 (4-Classro	om)	
	•					Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroc	om #201 (Pre School)							
	Ceiling - Lay-in	1st Floor	875	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	875	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years		
	Storage/ Closet	1st Floor	65	SF	7	10+ years		
	Walls - Metal Panel	1st Floor	1,095	SF	7	10+ years		
Classroo	om #202 (Pre School)							
Classiuc	Ceiling - Lay-in	1st Floor	897	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	897	SF	7	10+ years		
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years		
	Lighting - Lay-in Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years		
	Storage/ Closet	1st Floor	87	SF	7	10+ years		
	Walls - Metal Panel	1st Floor	1,143	SF	7	10+ years		
	Walls - Wetai i allei	13(1100)	1,140	OI	,	10+ years		
Classroo	om #203 (Pre School)							
	Ceiling - Lay-in	1st Floor	875	SF	7	10+ years		
	Chalk Board	1st Floor	12	LF	4	2-5 years		
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years		
	Floor - Tile	1st Floor	875	SF	6	10+ years		
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years		
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years		
	Storage/ Closet	1st Floor	65	SF	7	10+ years		
	Walls - Metal Panel	1st Floor	1,095	SF	7	10+ years		



Catego	ry : Classroom		В	uilding	: Modul	ar 1 (4-Classro	oom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #204 (Kindergarten)						
	Ceiling - Lay-in	1st Floor	897	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	897	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	16	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EΑ	7	6-10 years	
	Storage/ Closet	1st Floor	87	SF	7	10+ years	
	Walls - Metal Panel	1st Floor	1,143	SF	7	10+ years	
	vvalis - Metai i aliei	13(1100)	1,140	OI	,	10+ years	
Catego	ry : Room		В	uilding	: Modul	ar 1 (4-Classro	oom)
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Mechani	ical/ Service Rooms						
	Mechanical/ Service Rooms	1st Floor	52	SF	5	10+ years	
						•	
Restroor		4 of Floor	455		7	C 40	
	Accessories	1st Floor	155	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	155	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	_ 1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	155	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EΑ	7	6-10 years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	2	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	336	SF	7	10+ years	
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	1st Floor	176	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	176	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile/Sheet	1st Floor	176	SF	7	10+ years	
	Floor Drain	1st Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	2	EΑ	7	6-10 years	
	Partitions	1st Floor	4	EA	7	10+ years	
	Walls - Vinyl Coated Gypsum Panel	1st Floor	470	SF	7	10+ years	
	Water Closet	1st Floor	3	EA	7	10+ years	
	Water Closet	1st Floor	1	EA	4	0-1 year	Out of otder
			·			-	
Catego	ry : Interior		В			ar 1 (4-Classro	oom)
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments



					Replacement
Corridor					
Ceiling - Lay-in	1st Floor	544	SF	7	10+ years
Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years
Drinking Fountains - Single Fountain	1st Floor	1	EΑ	7	6-10 years
Drinking Fountains - Single Water Cooler	1st Floor	1	EA	7	6-10 years
Floor - Tile/Sheet	1st Floor	544	SF	7	10+ years
Lighting - Lay-in	1st Floor	7	EΑ	7	6-10 years
Walls - Vinyl Coated Gypsum Panel	1st Floor	1,472	SF	7	10+ years





Category : Site Building : Site

tego	ry : Site		В				
oup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
		Location	Qualitity	UOIVI	Kalik	Replacement	Comments
vil/Dra		F :: 0::				40	
	Civil/ Drainage - Catch Basin	Entire Site	5	EΑ	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	6	10+ years	
encina							
J	Fencing - Chain Link	Entire Site	158	LF	6	10+ years	
	Fencing - Chain Link	Entire Site	60	LF	5	2-5 years	
	Fencing - New Standard Ornamental	Entire Site	1,149	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	24	LF	4	1-2 years	Bending
andsca	pe						
	Benches	Entire Site	2	EA	6	6-10 years	
	Benches	Entire Site	1	EA	5	2-5 years	
	Benches	Entire Site	1	EA	4	1-2 years	Deteriorating
	Landscape - Grass	Entire Site	38,787	SF	6	10+ years	•
	Landscape - Hardscape- Concrete	Entire Site	710	SF	4	1-2 years	Cracking/deteriorating
	Landscape - Hardscape- Pavers	Entire Site	32	SF	6	10+ years	9
	Landscape - Mulch	Entire Site	200	SF	6	6-10 years	
	Parkway trees	Entire Site	24	ĒΑ	6	10+ years	
	Planting Beds/ Area	Entire Site	10,064	SF	6	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	11,557	SF	5	2-5 years	
	Play Area - Hardscape- Asphalt	Entire Site	1,050	SF	4	1-2 years	Cracking
	Play Area - Hardscape- Asphalt	Entire Site	1,050	SF	4	0-1 year	Tree root damage
	Trash Receptacles	Entire Site	5	ĒΑ	6	10+ years	3.
	Walking Path - Hardscape- Asphalt	Entire Site	544	SF	6	6-10 years	Changed to match current
							observations
arking							
	Concrete Curbs	Parking Lot- East	73	LF	6	10+ years	
	Concrete Curbs	Parking Lot- East	7	LF	4	0-1 year	Broken
	Interior Plantings	Parking Lot- East	30	LF	6	6-10 years	
	Surface - Asphalt	Parking Lot- East	1,880	SF	7	10+ years	Newly replaced
	Surface - Asphalt	Parking Lot- East	5,387	SF	4	1-2 years	Cracking/potholes
	Surface - Concrete	Parking Lot- East	255	SF	6	10+ years	Changed to match current observations
	Trash Enclosure - Chain Links	Parking Lot- East	566	SF	5	2-5 years	0.000.700.010
	Vehicular Screening	Parking Lot- East	151	LF	6	10+ years	Changed to match current observations
	Vehicular Screening	Parking Lot- East	20	LF	5	2-5 years	Damage listed under fencing
	Vehicular Screening	Parking Lot- East	20	LF	5	2-5 years	Damage listed under fencing

Campus Name: Pirie Page : 26 of 28 Assessment Date: 02/14/2024



650 E 85th STREET, Chicago, IL 60619

Catego	Category : Site			uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Equipment - School Age 5-12	West	1	EA	5	2-5 years	
	Surface - Square Rubber Mats	West	2,397	SF	4	0-1 year	Buckling/loose
_Sidewall	KS.						
	Sidewalks - Internal Walks	Entire Site	486	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	50	LF	4	0-1 year	Extensive cracking
	Sidewalks - Internal Walks	Entire Site	20	LF	4	0-1 year	Buckling/missing
	Sidewalks - Perimeter Sidewalks	Entire Site	3,000	SF	7	10+ years	Replaced
	Sidewalks - Perimeter Sidewalks	Entire Site	4,675	SF	6	10+ years	•
Signage							
0 0	Flag Pole - Flag Pole	SE site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/ LED	SE site	1	EA	6	10+ years	Changed to match current observations

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Pirie Page: 27 of 28 Assessment Date: 02/14/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

75

875

37

Ν



Pre School

Kindergarten

Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	(0-)		1 11 2 21	0.00	
Computer Lab	Regular Classroom	1st Floor	111	115	804	147	0	N	N
Faculty Lounge	Regular Classroom	1st Floor	106	106	783	45	13	N	N
Library	Kindergarten	1st Floor	115	111	1,203	140	96	N	Υ
Music Room	Regular Classroom	1st Floor	117	117	783	45	13	N	Υ
Office	Regular Classroom	1st Floor	110	116	804	147	0	N	N
Other Instructional Use	Kindergarten	1st Floor	116	112	1,203	157	96	Υ	N
Regular Classroom	Regular Classroom	1st Floor	101	101	783	45	13	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	783	30	9	N	Υ
Regular Classroom	Regular Classroom	1st Floor	103	103	783	30	9	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	783	30	9	N	Υ
Regular Classroom	Regular Classroom	1st Floor	108	110	804	75	0	N	N
Regular Classroom	Regular Classroom	1st Floor	109	113	804	75	0	N	N
Regular Classroom	Regular Classroom	1st Floor	112	114	804	72	0	N	Υ
Regular Classroom	Regular Classroom	1st Floor	113	109	804	75	0	N	Υ
Regular Classroom	Regular Classroom	1st Floor	114	108	804	147	0	N	Υ
Regular Classroom	Regular Classroom	1st Floor	118	118	783	30	9	N	Υ
Regular Classroom	Regular Classroom	1st Floor	119	119	783	30	9	N	Υ
Regular Classroom	Regular Classroom	1st Floor	120	120	783	30	9	N	Υ
Regular Classroom	Regular Classroom	1st Floor	121	121	783	30	9	N	Υ
Regular Classroom	Regular Classroom	1st Floor	122	122	783	45	13	N	N
Science Classroom	Regular Classroom	1st Floor	107	107	804	147	0	N	Υ
Store Room	Regular Classroom	1st Floor	105	105	783	30	9	N	N
Building : Modular 1 (4-Cla	ssroom)								
Kindergarten	Regular Classroom	1st Floor	204	204	897	75	37	N	Υ
Pre School	Kindergarten	1st Floor	201	201	875	75	37	N	Υ
Pre School	Kindergarten	1st Floor	202	202	897	75	37	N	Υ
	141 1							t	— . .

Campus Name: Pirie	Page : 28 of 28	Assessment Date: 02/14/2024
--------------------	-----------------	-----------------------------

203

203

1st Floor