

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a

recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1913	4	251,299
Addition (Telpochcalli)	1921	2	40,822
Campus Total			292,121

Category : Exterior Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1 - Main	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	1 - Main	9	EA	6	10+ years	
	Exterior Doors - Transom Lite	1 - Main	9	EA	6	10+ years	
	Exterior Stairs - Concrete	1 - Main	408	LF	7	10+ years	Repaired
	Stair Handrail - Steel_Stair Handrail	1 - Main	24	LF	6	10+ years	·
	Exterior Doors - Exterior Steel Door	15 - E	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	15 - E	3	EA	6	10+ years	
	Exterior Stairs - Concrete	15 - E	36	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	15 - E	4	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	15 - S	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	15 - S	3	EA	6	10+ years	
	Exterior Stairs - Concrete	15 - S	36	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	15 - S	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	16 - East Vault Door 1	2	EA	5	2-5 years	
	Exterior Doors - Transom Lite	16 - East Vault Door 1	2	EA	5	2-5 years	
	Exterior Stairs - Concrete	16 - East Vault Door 1	36	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	17 - East Vault Door 2	1	EA	5	2-5 years	
	Exterior Doors - Transom Lite	17 - East Vault Door 2	1	EA	5	2-5 years	
	Exterior Stairs - Concrete	17 - East Vault Door 2	20	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	2 - S	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	2 - S	3	EA	6	10+ years	
	Exterior Stairs - Concrete	2 - S	52	LF	6	10+ years	Repaired
	Stair Handrail - Steel_Stair Handrail	2 - S	3	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Exterior Steel Door	2 - W	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	2 - W	3	EA	6	10+ years	
	Exterior Stairs - Concrete	2 - W	56	LF	6	10+ years	Repaired
	Stair Handrail - Steel_Stair Handrail	2 - W	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	3 - NW	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	3 - NW	3	EA	6	10+ years	
	Exterior Stairs - Concrete	3 - NW	60	LF	6	10+ years	Patched
	Stair Handrail - Steel_Stair Handrail	3 - NW	3	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	4 - NW	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	4 - NW	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	5 - N	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	6 - N	2	EA	6	10+ years	
Foundati	on						
	Foundation - Masonry	Entire Building	1,305	LF	6	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	251,299	SF	7	10+ years	
Lighting							
	Exterior Lighting - Wall Mounted	Entire Building	13	EA	7	6-10 years	
Roof Sys	stem						
	Access Ladder - Metal	A - Main Roof	3	EA	7	10+ years	
	Access Ladder - Metal	A - Main Roof	3	EA	3	0-1 year	Not used
	Chimney - Brick Chimney- Concrete/ Mortar	A - Main Roof	20	LF	7	10+ years	1101 0000
	Liner	, t			•	.o. youro	
	Coping - Stone	A - Main Roof	1,502	LF	7	10+ years	
	Coping - Stone	A - Main Roof	30	LF	4	0-1 year	Strapped section, cracking
	Downspouts - Exterior Downspouts	A - Main Roof	1,200	LF	7	10+ years	on appear seemen, enderming
	Downspouts - Interior Downspouts	A - Main Roof	140	LF	7	10+ years	
	Parapet - 16" - 30" Height	A - Main Roof	896	LF	7	10+ years	
	Parapet - Parapet > 30"	A - Main Roof	636	LF	7	10+ years	
	Roof - Asphalt Shingle	A - Main Roof	2,200	SF	7	10+ years	
	Roof - Metal	A - Main Roof	50	SF	6	10+ years	
	Roof - Modified Bitumen	A - Main Roof	54.108	SF	7	10+ years	
	Roof - Modified Bitumen	A - Main Roof	100	SF	4	1-2 years	Water under membrane, bubbling
	Roof Hatch - Metal	A - Main Roof	1	ĒΑ	7	10+ years	
	Roof Hatch - Metal	A - Main Roof	3	EA	3	0-1 year	Corroded, unsafe location on edge of
	Doof Chryster Charlesith Clay Tile Arel	A Main Doof	FO 450	C.E.	7	40	roof
	Roof Structure - Steel with Clay Tile Arch	A - Main Roof	56,458	SF	7	10+ years	
	Access Ladder - Metal	B - Upper Sloped	1	EA	7	10+ years	
	Coping - Stone	B - Upper Sloped	188	LF	7	10+ years	
	Coping - Stone	B - Upper Sloped	20	LF	4	0-1 year	Cracked, displaced at corners
	Downspouts - Exterior Downspouts	B - Upper Sloped	50	LF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	B - Upper Sloped	188	LF	7	10+ years	
	Roof - Asphalt Shingle	B - Upper Sloped	5,310	SF	7	10+ years	
	Roof - Asphalt Shingle	B - Upper Sloped	500	SF	4	0-1 year	Leaks, interior damage
	Roof Structure - Steel with Clay Tile Arch	B - Upper Sloped	5,810	SF	7	10+ years	
	Downspouts - Exterior Downspouts	C - Center Sloped	195	LF	7	10+ years	
	Roof - Metal	C - Center Sloped	6,006	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	C - Center Sloped	6,006	SF	7	10+ years	
	Access Ladder - Metal	D - Center Low	1	EA	7	10+ years	
	Coping - Metal	D - Center Low	328	LF	7	10+ years	
	Downspouts - Exterior Downspouts	D - Center Low	50	LF	7	10+ years	
	Parapet - 16" - 30" Height	D - Center Low	328	LF	7	10+ years	
	Roof - Modified Bitumen	D - Center Low	4,992	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	D - Center Low	4,992	SF	7	10+ years	
	Coping - Clay Tile	E - East Center	63	ĹF	7	10+ years	
	Downspouts - Exterior Downspouts	E - East Center	150	LF	7	10+ years	
	Parapet - 16" - 30" Height	E - East Center	63	LF	7	10+ years	
	Roof - Metal	E - East Center	275	SF	7	10+ years	
	Roof - Modified Bitumen	E - East Center	5,859	SF	7	10+ years	Combined roofs
	Roof Structure - Steel with Clay Tile Arch	E - East Center	6,134	SF	7	10+ years	Combined 10013
	Downspouts - Exterior Downspouts	F - North Center	100	LF	7	10+ years	
	Roof - Modified Bitumen	F - North Center	780	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	F - North Center	780	SF	7	10+ years	
	Access Ladder - Metal	G - NE Center	1	EA	7	10+ years	
	Coping - Clay Tile	G - NE Center	39	LF	7	10+ years	
	Downspouts - Exterior Downspouts	G - NE Center	95	LF	7	10+ years	
		G - NE Center	39	LF			
	Parapet - 16" - 30" Height Roof - Modified Bitumen	G - NE Center		SF	7	10+ years	
			2,854		7	10+ years	Departies a
	Roof - Modified Bitumen	G - NE Center	500	SF	5	0-1 year	Ponding
	Roof Structure - Steel with Clay Tile Arch	G - NE Center	3,354	SF	7	10+ years	
	Downspouts - Exterior Downspouts	H	45	LF	7	10+ years	
	Roof - Modified Bitumen	H	280	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	H	280	SF	7	10+ years	
	Coping - Clay Tile	I - West Center	79	LF . –	7	10+ years	
	Downspouts - Exterior Downspouts	I - West Center	120	LF	7	10+ years	
	Parapet - 16" - 30" Height	I - West Center	79	LF	7	10+ years	
	Roof - Modified Bitumen	I - West Center	5,135	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	I - West Center	5,135	SF	7	10+ years	
	Downspouts - Exterior Downspouts	J - Southwest Center	75	LF	7	10+ years	
	Downspouts - Interior Downspouts	J - Southwest Center	75	LF	7	10+ years	
	Roof - Modified Bitumen	J - Southwest Center	3,638	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	J - Southwest Center	3,638	SF	7	10+ years	
	Access Ladder - Metal	K - NW Center	1	EA	7	10+ years	
	Coping - Clay Tile	K - NW Center	20	LF	7	10+ years	
	Downspouts - Interior Downspouts	K - NW Center	25	LF	7	10+ years	

Page : 3 of 80 Campus Name: Saucedo Assessment Date: 06/04/2024



Catego	ry : Exterior		R	uilding	· Main		O W 24th BOOLE VAIND, Officago, IE 00020
Guiogo	Ty Lization			unung	· Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Parapet - 16" - 30" Height	K - NW Center	20	LF	7	10+ years	
	Roof - Modified Bitumen	K - NW Center	650	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	K - NW Center	650	SF	7	10+ years	
	Coping - Clay Tile	L - N Center	20	LF	7	10+ years	
	Downspouts - Interior Downspouts	L - N Center	40	LF	7	10+ years	
	Roof - Modified Bitumen	L - N Center	1,833	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	L - N Center	1,833	SF	7	10+ years	
	Coping - Clay Tile	M	17	LF	7	10+ years	
	Downspouts - Exterior Downspouts	M	50	LF	7	10+ years	
	Parapet - 16" - 30" Height	M	17	LF	7	10+ years	
	Roof - Modified Bitumen	M	772	SF	7	10+ years	
	Roof - Modified Bitumen	M	10	SF	4	0-1 year	Loose flashing
	Roof Structure - Steel with Clay Tile Arch	M	782	SF	7	10+ years	Loose hashing
	Downspouts - Exterior Downspouts	N - Center Low	40	LF	7	10+ years	
	Roof - Modified Bitumen	N - Center Low	2,707	SF	7	10+ years	
	Roof Structure - Steel with Clay Tile Arch	N - Center Low N - Center Low	2,707	SF	7	10+ years	
	Coping - Clay Tile	O - Center Low	2,707	LF	7	10+ years	
	Downspouts - Exterior Downspouts	O - Center Low	13	LF	7	10+ years	
	Downspouts - Interior Downspouts	O - Center Low	50	LF	7	10+ years	
	Roof - Modified Bitumen	O - Center Low	836	SF	7	,	
	Roof - Modified Bitumen	O - Center Low		SF	4	10+ years 0-1 year	Danding plant growth
			100	SF	7	•	Ponding, plant growth
	Roof Structure - Steel with Clay Tile Arch	O - Center Low	936	SF	,	10+ years	
_Walls							
_vvalis	Cheek-Wall - Stone	Entire Building	360	SF	7	10+ years	
	Cornice - Masonry Projecting Limestone	Entire Building	1,541	LF	7	10+ years	
	Exterior Walls - Brick	Entire Building	78,370	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	400	SF	4	,	Cracking displaced brick porth
		· ·				0-1 year	Cracking, displaced brick north courtyard
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	2,436	SF	7	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	60	SF	5	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	19,555	SF	7	10+ years	
	Exterior Walls - Stucco	Entire Building	850	SF	7	10+ years	
		J				,	
_Windows							
	Guard - Guards perforated	Entire Building	7,752	SF	7	10+ years	
	Lintels - Brick	Entire Building	24	LF	7	10+ years	
	Lintels - Steel	Entire Building	2,460	LF	7	10+ years	
	Skylite - Glass Double-Pane	Entire Building	1,375	SF	7	10+ years	
	Windows - Decorative	Entire Building	288	SF	7	10+ years	
	Windows - Louver	Entire Building	144	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	28,664	SF	6	6-10 years	
		-				•	



	ory : Exterior		В	uilding	: Main	200	0 W 24111 BOOLE VARD, Cliicago, iL 60623
		Landin	Over the	11014	Danila	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerge	ncy System	EL .: 15					0 14 1 16
	Automatic Transfer Switch Exit Signs - Auditoium	Electrical Room Entire Building	3 16	EA EA	6 6	10+ years 6-10 years	Serve Main and Addition. Location changed for clarification as the auditorium occupies space on multiple floors. Quantity changed to match current observations and as the total has been divided/aggregated.
	Exit Signs - Corridors and Stairs	Entire Building	54	EA	6	6-10 years	
	Exit Signs - Gym	Entire Building	8	EA	6	6-10 years	Quantity changed to match current observations.
	Exit Signs - Gym	Entire Building	3	EA	6	6-10 years	Gym 2. Quantity changed to match current observations.
	Exit Signs - Lunchroom	Entire Building	4	EA	6	6-10 years	
	Exit Signs - Pool	Entire Building	4	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	8,576	SF	6	10+ years	Location changed for clarification as the auditorium occupies space on multiple floors.
	Emergency A/C Power - Corridors and Stairs	Entire Building	43,017	SF	6	10+ years	·
	Emergency A/C Power - Gym	Entire Building	16,083	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	12,000	SF	6	10+ years	
	Emergency A/C Power - Multipurpose Room	Entire Building	3,199	SF	6	10+ years	
	Emergency A/C Power - Pool	Entire Building	3,613	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	4,850	SF	6	10+ years	
	Security System - CCTV	Entire Building	251,299	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	251,299	SF	6	6-10 years	
	Emergency Battery Packs - Pool	Entire Building	2	EA	6	6-10 years	
	Emergency Generator- Outdoor- Natural Gas - 151 - 200 KW	Site - East	1	EA	6	6-10 years	Serves EM circuits in Main and Addition.
_Main Se							
	Main Electrical Service - 2000 A 120/240/3PH	Electrical Room	1	EA	6	6-10 years	
	Main Electrical Service - Greater than 3000 A 120/240/3PH	Electrical Room	1	EA	6	6-10 years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	PA System	Entire Building	251,299	SF	4	2-5 years	Serves Main. Generally operational
	Nama: Causada		Daga : E of 90				Accessment Date: 06/04/2024

Campus Name: Saucedo Page : 5 of 80 Assessment Date: 06/04/2024



Catego	ry : Electrical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	with occasional audible static/interference. Reason and Priority Rep changed to reflect that it is an older system requiring frequent maintenance and is at the end of its anticipated service life.
Power D	istribution Lighting and Power Panels - 100 A	Entire Building	18	EA	7	10+ years	Some panels secured shut for security purposes with condition
							verified by Building Engineer.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EΑ	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slots with electrical tape exposes live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	Location changed for clarification.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Vintage live front fuse panel.
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	4	0-1 year	Quantity and location changed to match current observations. Vintage live front fuse panels.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	3	0-1 year	Missing interior cover plate exposes live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	3	0-1 year	Vintage live front fuse panel.
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	3	0-1 year	Quantity changed as total has been divided/aggregated. Vintage live fron fuse panels with damaged door latches.
	Main Distribution Panels - 400 - 600 amp	Entire Building	5	EA	7	6-10 years	Quantity changed to match current observations.
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	3	0-1 year	Missing switch actuator exposes live conductors presenting a live front condition.
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	4	0-1 year	Open fuse receptacles expose live conductors presenting a live front condition.
	Main Distribution Panels - Less than 400 amp	Entire Building	3	EA	6	6-10 years	

Campus Name: Saucedo Page : 6 of 80 Assessment Date: 06/04/2024



Maria Saucedo STEAM Magnet Academy

changed as the system has been replaced since previous assessment.

XIII.	Schools					285	50 W 24th BOULEVARD, Chicago, IL 60623
Catego	ry : Electrical		E	Building	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	6-10 years	Located in AHU-1 Fan Room
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	4	0-1 year	Open breaker slots expose live conductors presenting a live front condition.
	Transformers - 120/240 - 120/208	Entire Building	1	EA	4	2-5 years	Reason and Priority Rep adjusted based on current observations that the transformer operates warm and noisy, consistent with age-related degradation, and has reached the end of its anticipated service life.
	Transformers - 277/480 - 120/240	Entire Building	1	EA	6	6-10 years	Misidentified in previous assessmen Reason and Priority Rep adjusted based on current observations and talign with Rank.
Catego	ry : Fire Protection		E	Building	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar	m Fire ALarm Anunciator	Entire Building	1	EA	7	10+ years	No CPS Asset Tag present.
	Fire Alarm Panel	Entire Building	1	EA	7	10+ years	Rank, Reason and Priority Rep changed as the panel has been replaced since previous assessmen
	Fire Alarm Strobe Lights	Entire Building	251,299	SF	7	10+ years	·
	Fire Alarm_System	Entire Building	251,299	SF	7	10+ years	Rank, Reason and Priority Rep

Category : Mechanical Building : Main

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond	itioning						
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	10+ years	Serves Room 144.
	than 5 tons	5 (•	4.0	0 5 444
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	10+ years	Serves Room 144.
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	10+ years	Serves Room 143.
	than 5 tons						
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	6	10+ years	Serves Room 143.
	than 5 tons						

Air Handling Systems



Catego	ry : Mechanical		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	1	EA	6	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	1	EA	6	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	1	EA	6	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	1	EA	6	6-10 years	
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	1st Floor - AHU-1 (SE)	1	EA	5	6-10 years	Located in SE mechanical room. Location changed for clarification.
	Air Intake	1st Floor - AHU-1 (SE)	1	EA	5	6-10 years	OA dampers are fully operational but require manual adjustment in the absence of a functional temperature control system. Not fully visible at the time of assessment due to space constraints and unsafe ladder access.
	Auxiliaries - 30001 - 45000 cfm	1st Floor - AHU-1 (SE)	1	EA	5	6-10 years	Located in SW mechanical room. Location changed for clarification. Air filters actively in the process of scheduled replacement on the day of assessment.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	1st Floor - AHU-1 (SE)	100	LF	6	10+ years	
	Zone Dampers	1st Floor - AHU-1 (SE)	23	EA	5	6-10 years	Zone dampers are fully operational but require manual adjustment in the absence of a functional temperature control system.
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	1st Floor - AHU-2 (SW)	1	EA	5	6-10 years	Located in SW mechanical room. Location changed for clarification. AHU-2
	Air Intake	1st Floor - AHU-2 (SW)	1	EA	5	6-10 years	OA dampers are fully operational but require manual adjustment in the absence of a functional temperature control system. Not fully visible at the time of assessment due to space constraints and unsafe ladder access.
	Auxiliaries - 30001 - 45000 cfm	1st Floor - AHU-2 (SW)	1	EA	5	6-10 years	Located in SW mechanical room. Location changed for clarification. Air filters actively in the process of scheduled replacement on the day of assessment.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	1st Floor - AHU-2 (SW)	100	LF	6	10+ years	accommit.
	Zone Dampers	1st Floor - AHU-2 (SW)	24	EA	5	6-10 years	Zone dampers are fully operational but require manual adjustment in the absence of a functional temperature control system.

Campus Name: Saucedo Page: 8 of 80 Assessment Date: 06/04/2024



Catego	ry : Mechanical		В	uilding	: Main		· · ·
0	Hom. Tuno	Lagation	Overetite	ПОМ	Donk	Recommend	Commonto
Group	Item - Type Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	Location 1st Floor - AHU-3 (NW)	Quantity 1	UOM EA	Rank 5	Replacement 6-10 years	Comments AHU-3 Located in NW mechanical room. Location changed for clarification.
	Air Intake	1st Floor - AHU-3 (NW)	1	EA	5	6-10 years	OA dampers are fully operational but require manual adjustment in the absence of a functional temperature control system. Not fully visible at the time of assessment due to space constraints and unsafe ladder access.
	Auxiliaries - 30001 - 45000 cfm	1st Floor - AHU-3 (NW)	1	EA	5	6-10 years	Located in SW mechanical room. Location changed for clarification. Air filters actively in the process of scheduled replacement on the day of assessment.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	1st Floor - AHU-3 (NW)	100	LF	6	10+ years	
	Zone Dampers	1st Floor - AHU-3 (NW)	27	EA	5	6-10 years	Zone dampers are fully operational but require manual adjustment in the absence of a functional temperature control system.
	Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm	1st Floor - AHU-4 (NE)	1	EA	5	6-10 years	AHU-4 Located in NE mechanical room. Location changed for clarification.
	Air Intake	1st Floor - AHU-4 (NE)	1	EA	5	6-10 years	OA dampers are fully operational but require manual adjustment in the absence of a functional temperature control system. Not fully visible at the time of assessment due to space constraints and unsafe ladder access.
	Auxiliaries - 30001 - 45000 cfm	1st Floor - AHU-4 (NE)	1	EA	5	6-10 years	Located in SW mechanical room. Location changed for clarification. Air filters actively in the process of scheduled replacement on the day of assessment.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	1st Floor - AHU-4 (NE)	100	LF	6	10+ years	
	Zone Dampers	1st Floor - AHU-4 (NE)	25	EA	5	6-10 years	Zone dampers are fully operational but require manual adjustment in the absence of a functional temperature control system.
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Attic	1	EA	5	2-5 years	Located in the NW attic space. Vintage equipment that is operational but Reason and Priority Rep adjusted based on current observations that

Campus Name: Saucedo Page : 9 of 80 Assessment Date: 06/04/2024



or	y : Mechanical		В	uilding	: Main	_	
			•			Recommend	
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							the unit is approaching the end anticipated service life.
	Air Intake	Attic	1	EA	4	0-1 year	OA dampers are fixed partially and are inoperable.
	Indoor Return Fans- Centrifugal Squirrel Cage - Less than 5000 CFM	Attic	1	EA	5	6-10 years	Located in the west attic space Serves Gym 2.
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons	Lower Roof	1	EA	6	10+ years	West unit serving Room 400.
	Roof Top Unit-Single Zone-Roof Mounted- DX Cooling Only with Self Contained Compressor - 5 - 10 tons	Lower Roof	1	EA	6	10+ years	East unit serving Room 400.
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mezzanine - AHU-5	1	EA	5	6-10 years	AHU-5, serves north 1st floor s
	Air Intake	Mezzanine - AHU-5	1	EA	5	6-10 years	Manual adjustment required in absence of a functional temper control system system.
	Auxiliaries - 15001 - 25000 cfm	Mezzanine - AHU-5	1	EA	5	6-10 years	,
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mezzanine - AHU-5	1	LF	6	10+ years	
	Zone Dampers	Mezzanine - AHU-5	9	EA	5	6-10 years	Manual adjustment required in absence of a functional temper control system system.
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mezzanine - AHU-6	1	EA	5	6-10 years	AHU-6, serves north 1st floor s
	Air Intake	Mezzanine - AHU-6	1	EA	5	6-10 years	Manual adjustment required in absence of a functional temper control system system.
	Auxiliaries - 15001 - 25000 cfm	Mezzanine - AHU-6	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mezzanine - AHU-6	1	LF	6	10+ years	
	Zone Dampers	Mezzanine - AHU-6	9	EA	5	6-10 years	Manual adjustment required in absence of a functional temper control system system.
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 25001 - 35000 cfm	Mezzanine - AHU-7	1	EA	5	6-10 years	AHU-7, serves auditorium.
	Air Intake	Mezzanine - AHU-7	1	EA	5	6-10 years	Manual adjustment required in absence of a functional temper control system system.
	Auxiliaries - 25001 - 35000 cfm	Mezzanine - AHU-7	1	EA	5	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mezzanine - AHU-7	100	LF	6	10+ years	

Campus Name: Saucedo Page : 10 of 80 Assessment Date: 06/04/2024



Catego	ry : Mechanical		В	uilding	: Main		· • • • • • • • • • • • • • • • • • • •
_				_		Recommend	
Group	Item - Type Condensate Pump	Location Entire Building	Quantity 1	EA	Rank 6	Replacement 2-5 years	Reason and Priority Rep adjusted to reflect that the equipment is functional and leak-free but approaching the end of its anticipated service life. Rank changed based on current observations and per review with Building Engineer with repairs completed since previous
	Condensate Pump	Entire Building	1	EA	6	6-10 years	assessment. No CPS Asset Tag present. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer with repairs completed since previous assessment; the equipment is fully operational and leak-free.
	Condensate Pump	Entire Building	1	EA	6	6-10 years	No CPS Asset Tag present. No CPS Asset Tag present. Rank changed based on current observations and per review with Building Engineer with repairs completed since previous assessment; the equipment is fully operational and leak-free.
	Condensate Pump	Entire Building	1	EA	6	6-10 years	No CPS Asset Tag present. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer with repairs completed since previous assessment; the equipment is fully operational and leak-free.
	Piping - Condensate Pipe- Steel	Entire Building	1,500	LF	3	0-1 year	Condensate piping in Main is returned back to Addition. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that faulty piping has been replaced since previous assessment. There are still
	Piping - Steam Pipe- Steel	Entire Building	1,500	LF	5	2-5 years	issues with the piping in general. Steam is piped to Main from Addition. Reason and Priority Rep changed to reflect that the piping is vintage material and is approaching the end of its anticipated service life.
	Steam Traps	Entire Building	160	EA	5	6-10 years	,

Campus Name: Saucedo Page : 11 of 80 Assessment Date: 06/04/2024



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Heating	Devices						
	Unit Heater - Steam	1st Floor	5	EA	6	6-10 years	Located in gym storage, Room 143, Room 144, and two in Gym 1.
	Fin Tube - Steam	Entire Building	22	LF	5	6-10 years	
	Radiators - Steam	Entire Building	4	EA	5	6-10 years	
	Radiators - Steam	Entire Building	2	EA	5	6-10 years	One each located in office and
	radiatoro Giodini	Little Dallaling	_		O	o ro youro	restroom.
	Wall Heater - Electric	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Wall Heater - Electric	Entire Building	1	EA	6	6-10 years	Location changes for dameation.
	Wall Heater - Electric	Entire Building	3	EA	6	6-10 years	Quantity changed as total has been
	Wall Fleater - Liectric	Littile Building	3	LA	U	0-10 years	divided/aggregated.
	Wall Heater - Electric	Entire Building	1	EA	4	0-1 year	Missing cover exposes hot parts and moving parts presenting a risk of personal injury.
	Wall Heater - Electric	Entire Building	1	EA	4	0-1 year	Missing cover exposes live electrical conductors presenting a live front condition.
	Wall Heater - Electric	Entire Building	1	EA	2	0-1 year	Missing cover exposes live electrical conductors presenting a live front condition.
	Wall Heater - Electric	Entire Building	1	EA	2	0-1 year	Location changed for clarification. Missing cover exposes live electrical conductors presenting a live front condition.
	Wall Heater - Electric	Entire Building	1	EA	2	0-1 year	Unit is in a breakdown condition following a severe electrical failure and has been taken out of service.
Tempera	ture Control						
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	
	Electric Thermostat	Entire Building	4	EA	6	6-10 years	
	Pneumatic System	Entire Building	251,299	SF	3	0-1 year	Served by Main. System is failed and inoperable. Temperatures in all spaces throughout the building are manually controlled by the Building
	Thermostats - Pneumatic	Entire Building	121	EA	4	0-1 year	Engineer. Thermostats are inoperative, contaminated with oil, and irreparable.
_Ventilatio	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	5	6-10 years	

Campus Name: Saucedo Page : 12 of 80 Assessment Date: 06/04/2024



of its anticipated service life.

XII N	Schools					285	0 W 24th BOULEVARD, Chicago, IL 6062
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
огоар	Exhaust Fans- Indoor - 500 - 1500 CFM Exhaust Fans- Indoor - Greater than 8000 CFM	Entire Building Entire Building	1 1	EA EA	6 5	6-10 years 6-10 years	Serves boys locker room Priority Rep adjusted based on current observations and on the ago of the equipment.
	Exhaust Fans- Indoor - Less than 500 CFM Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building Entire Building	2 5	EA EA	6 6	6-10 years 6-10 years	Restroom exhaust fans. Quantity changed to match current observations. Not directly accessib at the time of assessment due to no safe
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	4	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	4	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	Rank changed based on current observations and per review with Building Engineer on repairs completed since previous assessment.
	Roof Mounted Duct Work	Entire Building	50	LF	6	6-10 years	Quantity confirmed by physical measurement at the time of assessment.
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	2	0-1 year	No fire suppression system preser
atego	ry : Plumbing		В	uilding	: Main		
oup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
ot Wate	er						
	Electric Heater - Less than 20 KW	1st Floor	1	EA	6	10+ years	Dataplate inaccessible in a safe manner at the time of assessment due to unreliable ladder arrangement
	Electric Heater - Less than 20 KW	1st Floor	1	EA	6	10+ years	Located in a closet; serves Rooms 143 and 144 and associated stude restrooms.
ping							
	Domestic Piping-Hot Water Return Lines	Entire Building	251,299	SF	4	2-5 years	Leak-free at the time of assessmer Reason and Priority Rep adjusted reflect that most piping is original to the building and has reached the e

Campus Name: Saucedo Page: 13 of 80 Assessment Date: 06/04/2024



Catego	ry : Plumbing		B	uilding	: Main	200	O W 24th BOOLE VARB, Officago, IE 00020
Guiogo	. ,		_	uug		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	251,299	SF	4	2-5 years	Leak-free at the time of assessment. Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end of its anticipated service life.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	251,299	SF	4	2-5 years	Leak-free at the time of assessment. Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end of its anticipated service life.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	251,299	SF	4	2-5 years	Leak-free at the time of assessment. Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end of its anticipated service life.
	Sanitary Piping	Entire Building	251,299	SF	5	2-5 years	Leak-free at the time of assessment. Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end of its anticipated service life.
	Storm Piping	Entire Building	251,299	SF	5	2-5 years	Leak-free at the time of assessment. Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end of its anticipated service life.
	Vent Piping	Entire Building	251,299	SF	5	2-5 years	Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end of its anticipated service life.
Pool Sys	stems						
	Pool Drain Piping	1st Floor	200	LF	4	2-5 years	Older steel material with considerable visible deterioration. Reason and Priority Rep adjusted to reflect that it has reached the end of its anticipated service life.
	Pool Filtration System including Pump	1st Floor	1	EA	4	2-5 years	Significantly deteriorated older equipment that remains operational through ongoing maintenance. Reason and Priority Rep adjusted to reflect that it has reached the end of its anticipated service life.
	Pool Hot Water Heater - Steam Heat Exchanger	1st Floor	1	EA	5	2-5 years	Significantly deteriorated older equipment that remains operational

Campus Name: Saucedo Page : 14 of 80 Assessment Date: 06/04/2024



Catego	Category : Plumbing				Building : Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Pool Supply and Return Piping	1st Floor	200	LF	4	2-5 years	through ongoing maintenance. Reason and Priority Rep adjusted to reflect that it has reached the end of its anticipated service life.\n Older steel material with considerable visible deterioration. Reason and Priority Rep adjusted to reflect that it has reached the end of its anticipated service life.		
Pumps									
	Pumps - Sump-Duplex	Entire Building	1	EA	6	6-10 years	No CPS Asset Tag present.		
	Pumps - Sump-Simplex	Entire Building	1	EA	6	6-10 years	Located in the elevator room; serves the elevator pit.		

Category: Room **Building: Main**

				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	AC Unit	102 - Office Ass't Principal	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	102 - Office Ass't Principal	195	SF	6	10+ years	
	Doors - Transom Window	102 - Office Ass't Principal	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	102 - Office Ass't Principal	2	EA	7	10+ years	
	Floor - Tile	102 - Office Ass't Principal	195	SF	6	10+ years	
	Lighting - Pendent/Surface	102 - Office Ass't Principal	4	EA	6	6-10 years	
	Power Distribution	102 - Office Ass't Principal	2	EA	7	10+ years	
	Walls - Plaster/Drywall	102 - Office Ass't Principal	380	SF	6	10+ years	
	AC Unit	107- Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	107- Principal's Office	415	SF	6	10+ years	
	Doors - Steel Doors incl hw	107- Principal's Office	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	107- Principal's Office	2	EA	7	10+ years	
	Floor - Carpet	107- Principal's Office	415	SF	6	6-10 years	
	Lighting - Pendent/Surface	107- Principal's Office	5	EA	6	6-10 years	
	Power Distribution	107- Principal's Office	6	EA	7	10+ years	
	Storage/ Closet	107- Principal's Office	72	SF	4	1-2 years	Significant cracks in wall of closet
	Walls - Plaster/Drywall	107- Principal's Office	830	SF	6	10+ years	
	Ceiling - Plaster/Drywall	109-Open Office	375	SF	6	10+ years	
	Doors - Transom Window	109-Open Office	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	109-Open Office	1	EA	6	10+ years	
	Floor - Tile	109-Open Office	375	SF	6	6-10 years	
	Lighting - Pendent/Surface	109-Open Office	7	EA	6	6-10 years	
	Power Distribution	109-Open Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	109-Open Office	859	SF	6	10+ years	
	Ceiling - Plaster/Drywall	109A - East Office	87	SF	6	10+ years	

Campus Name: Saucedo Page : 15 of 80 Assessment Date: 06/04/2024



Category : Room		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	109A - East Office	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109A - East Office	1	EA	7	10+ years	
	Floor - Tile	109A - East Office	87	SF	6	6-10 years	
	Lighting - Pendent/Surface	109A - East Office	2	EA	6	6-10 years	
	Power Distribution	109A - East Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	109A - East Office	161	SF	6	10+ years	
	Ceiling - Plaster/Drywall	109B - Middle office	87	SF	6	10+ years	
	Doors - Side-lite	109B - Middle office	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109B - Middle office	1	EA	7	10+ years	
	Floor - Tile	109B - Middle office	87	SF	6	6-10 years	
	Lighting - Pendent/Surface	109B - Middle office	2	EΑ	6	6-10 years	
	Power Distribution	109B - Middle office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	109B - Middle office	161	SF	6	10+ years	
	Ceiling - Plaster/Drywall	109C-West Office	87	SF	6	10+ years	
	Doors - Transom Window	109C-West Office	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109C-West Office	1	EA	7	10+ years	
	Floor - Tile	109C-West Office	87	SF	6	6-10 years	
	Lighting - Pendent/Surface	109C-West Office	2	EA	6	6-10 years	
	Power Distribution	109C-West Office	2	EA	7	10+ years	
	Storage/ Closet	109C-West Office	4	SF	7	10+ years	
	Walls - Plaster/Drywall	109C-West Office	152	SF	6	10+ years	
	Ceiling - Splined	117 - Office	650	SF	6	10+ years	
	Ceiling - Splined	117 - Office	20	SF	4	1-2 years	Damaged ceiling
	Doors - Side-lite	117 - Office	96	SF	7	10+ years	Damaged Celling
	Doors - Transom Window	117 - Office	90	SF	7	•	
		117 - Office	7	EA		10+ years	
	Doors - Wood Doors inclu hw Floor - Tile	117 - Office	670	SF	7 6	10+ years	
						6-10 years	
	Lighting - Pendent/Surface	117 - Office	12	EΑ	6	6-10 years	
	Power Distribution	117 - Office	14	EA	7	10+ years	
	Walls - Plaster/Drywall	117 - Office	709	SF	6	10+ years	
	Ceiling - Plaster/Drywall	121 - Conf Room	329	SF	6	10+ years	
	Doors - Transom Window	121 - Conf Room	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	121 - Conf Room	1	EA	7	10+ years	
	Floor - Tile	121 - Conf Room	327	SF	6	6-10 years	Danie and Hear
	Floor - Tile	121 - Conf Room	2	SF	4	1-2 years	Damaged floor
	Lighting - Pendent/Surface	121 - Conf Room	5	EA	6	6-10 years	
	Power Distribution	121 - Conf Room	4	EA	7	10+ years	
	Walls - Plaster/Drywall	121 - Conf Room	709	SF	6	10+ years	
	Ceiling - Plaster/Drywall	121A	250	SF	7	10+ years	
	Doors - Wood Doors inclu hw	121A	1	EA	7	10+ years	
	Floor - Tile	121A	246	SF	7	10+ years	
	Floor - Tile	121A	4	SF	4	1-2 years	Cracked and damaged floor
	Lighting - Pendent/Surface	121A	5	EA	7	10+ years	
	Power Distribution	121A	4	EA	7	10+ years	

Campus Name: Saucedo Page : 16 of 80 Assessment Date: 06/04/2024



Catego	Category : Room		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	121A	400	SF	7	10+ years			
	Ceiling - Plaster/Drywall	124 - Teachers Lounge/Office	336	SF	6	10+ years			
	Doors - Transom Window	124 - Teachers Lounge/Office	10	SF	7	10+ years			
	Doors - Wood Doors inclu hw	124 - Teachers Lounge/Office	3	EA	7	10+ years			
	Floor - Wood	124 - Teachers Lounge/Office	336	SF	6	10+ years			
	Lighting - Pendent/Surface	124 - Teachers Lounge/Office	6	EA	6	6-10 years			
	Power Distribution	124 - Teachers Lounge/Office	6	EA	7	10+ years			
	Walls - Plaster/Drywall	124 - Teachers Lounge/Office	672	SF	6	10+ years			
	Work SInk	124 - Teachers Lounge/Office	1	EA	7	10+ years			
	Ceiling - Plaster/Drywall	128 new office	202	SF	7	10+ years			
	Doors - Wood Doors inclu hw	128 new office	1	EA	7	10+ years			
	Floor - Tile	128 new office	202	SF	7	10+ years			
	Lighting - Pendent/Surface	128 new office	4	EA	7	10+ years			
	Power Distribution	128 new office	2	EA	7	10+ years			
	Walls - Plaster/Drywall	128 new office	350	SF	7	10+ years			
	Ceiling - Plaster/Drywall	128B - Office	242	SF	7	10+ years			
	Doors - Wood Doors inclu hw	128B - Office	3	EA	7	10+ years			
	Floor - Tile	128B - Office	242	SF	6	10+ years			
	Lighting - Pendent/Surface	128B - Office	5	EA	6	6-10 years			
	Power Distribution	128B - Office	4	EA	7	10+ years			
	Storage/ Closet	128B - Office	6	SF	7	10+ years			
	Walls - Plaster/Drywall	128B - Office	576	SF	6	10+ years			
	AC Unit	1st Flr - Main Office Reception	2	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Flr - Main Office Reception	701	SF	7	10+ years			
	Doors - Transom Window	1st Flr - Main Office Reception	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st FIr - Main Office Reception	2	EA	7	10+ years			
	Floor - Carpet	1st FIr - Main Office Reception	401	SF	6	6-10 years			
	Floor - Tile	1st FIr - Main Office Reception	300	SF	6	10+ years			
	Lighting - Pendent/Surface	1st FIr - Main Office Reception	18	EA	6	6-10 years			
	Power Distribution	1st FIr - Main Office Reception	6	EΑ	7	10+ years			
	Walls - Plaster/Drywall	1st Flr - Main Office Reception	1,012	SF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Flr - Main Office Work Room	144	SF	7	10+ years			
	Doors - Side-lite	1st Flr - Main Office Work Room	36	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Flr - Main Office Work Room	1	ĒΑ	7	10+ years			
	Floor - Carpet	1st Flr - Main Office Work Room	144	SF	6	6-10 years			
	Lighting - Pendent/Surface	1st Flr - Main Office Work Room	4	EA	6	6-10 years			
	Power Distribution	1st Flr - Main Office Work Room	4	EA	7	10+ years			
	Walls - Plaster/Drywall	1st Flr - Main Office Work Room	285	SF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Flr - Pool Office	241	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Flr - Pool Office	1	EA	7	10+ years			
	Doors - Wood Doors inclu hw	1st Fir - Pool Office	2	EΑ	7	10+ years			
	Floor - Terrazzo	1st Fir - Pool Office	241	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Fir - Pool Office	3	EA	6	6-10 years			
	Power Distribution	1st Fir - Pool Office	4	EΑ	7	10+ years			
	. C. C. Diotribution	.3(1111 1 001 011100			•	10. 300.0			



Catego	Category : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Flr - Pool Office	482	SF	6	10+ years	
	Ceiling - Plaster/Drywall	231	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	231	1	EA	7	10+ years	
	Floor - Wood	231	120	SF	7	10+ years	
	Lighting - Pendent/Surface	231	2	EΑ	7	10+ years	
	Power Distribution	231	4	EΑ	7	10+ years	
	Walls - Plaster/Drywall	231	250	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	123	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Tile	2nd Floor	123	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	10+ years	
	Power Distribution	2nd Floor	4	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	225	SF	7	10+ years	
	Ceiling - Splined	2nd Floor Kitchen Office	79	SF	6	10+ years	
	Ceiling - Splined	2nd Floor Kitchen Office	3	SF	4	1-2 years	Missing tile
	Doors - Wood Doors inclu hw	2nd Floor Kitchen Office	1	EA	7	10+ years	Wildeling and
	Floor - Tile	2nd Floor Kitchen Office	82	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor Kitchen Office	2	EA	6	6-10 years	
	Power Distribution	2nd Floor Kitchen Office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Kitchen Office	164	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor Library Office	199	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Library Office	193	EA	7	10+ years	
	Floor - Tile	2nd Floor Library Office	189	SF	6	6-10 years	
	Floor - Tile	2nd Floor Library Office	109	SF	4	1-2 years	Cracked and damaged floor
	Lighting - Pendent/Surface	2nd Floor Library Office	4	EA	6	6-10 years	Cracked and damaged noor
	Power Distribution	2nd Floor Library Office	4	EA	7	10+ years	
	Storage/ Closet	2nd Floor Library Office	100	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Library Office	398	SF	6	10+ years	
	Work Sink	2nd Floor Library Office	390	EA		,	Hot water side not
			225	SF	7	2-5 years	not water side not
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	Main Gym Office Main Gym Office	225	SF EA	6	10+ years	
				SF	7	10+ years	
	Floor - Wood	Main Gym Office	225		6	10+ years	
	Lighting - Pendent/Surface	Main Gym Office	4	EA	6	6-10 years	
	Power Distribution	Main Gym Office	8	EA	7	10+ years	
	Walls - Concrete Block	Main Gym Office	40	SF SF	6	10+ years	
	Walls - Plaster/Drywall	Main Gym Office	500		6	10+ years	
	Ceiling - Plaster/Drywall	Next to 102 office, former storage	135	SF	7	10+ years	
	D W 1D : 11	room	4	_ ^	-	40	
	Doors - Wood Doors inclu hw	Next to 102 office, former storage	1	EA	7	10+ years	
		room	405	0=	_	4.0	
	Floor - Wood	Next to 102 office, former storage	135	SF	7	10+ years	
		room	=		_	4.0	
	Lighting - Pendent/Surface	Next to 102 office, former storage	3	EA	7	10+ years	
		room					



Catego	ory : Room		В	uilding	: Main		
	_					Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	Next to 102 office, former storage	2	EA	7	10+ years	
		room					
	Walls - Plaster/Drywall	Next to 102 office, former storage	160	SF	7	10+ years	
		room					
	Ceiling - Exposed	Office in 130	90	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office in 130	1	EA	7	10+ years	
	Floor - Tile	Office in 130	90	SF	7	10+ years	
	Lighting - Pendent/Surface	Office in 130	2	EA	7	10+ years	
	Power Distribution	Office in 130	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Office in 130	160	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Records Room	240	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Records Room	2	EA	7	10+ years	
	Floor - Tile	Records Room	235	SF	6	10+ years	
	Floor - Tile	Records Room	5	SF	4	1-2 years	Damaged flooring
	Lighting - Pendent/Surface	Records Room	4	EA	6	6-10 years	
	Power Distribution	Records Room	6	EA	7	10+ years	
	Storage/ Closet	Records Room	20	SF	7	10+ years	
	Walls - Plaster/Drywall	Records Room	440	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Second floor gym office	110	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Second floor gym office	1	EA	7	10+ years	
	Floor - Wood	Second floor gym office	110	SF	7	10+ years	
	Lighting - Pendent/Surface	Second floor gym office	2	EA	7	10+ years	
	Lighting - Pendent/Surface	Second floor gym office	1	EA	5	0-1 year	Not working
	Power Distribution	Second floor gym office	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Second floor gym office	200	SF	7	10+ years	
Auditori	um & Theater						
	Balcony Seating	1st Floor	506	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	8,576	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	22	EA	7	10+ years	
	Floor - Carpet	1st Floor	6,375	SF	6	6-10 years	
	Floor - Carpet	1st Floor	200	SF	4	1-2 years	Torn damaged carpet
	Floor - Wood	1st Floor	2,001	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	35	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	39	EA	6	6-10 years	
	Main Floor Seating	1st Floor	1,062	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	1,462	SF	7	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Wood	1st Floor	120	LF	6	10+ years	
	Stairs - Asphalt	1st Floor	40	LF	6	10+ years	
	Storage/ Closet	1st Floor	350 3,912	SF SF	7	10+ years	



Catego	ry : Room		В	uilding	: Main		-
			0			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Gymnasi	ja						
	Ceiling - Plaster/Drywall	2nd Floor Girls Gym	4,983	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Girls Gym	7	EA	7	10+ years	
	Floor - Wood	2nd Floor Girls Gym	4,983	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Girls Gym	23	ĒΑ	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor Girls Gym	1	EA	5	0-1 year	Not working
	Storage/ Closet	2nd Floor Girls Gym	301	SF	7	10+ years	
	Walls - Masonry	2nd Floor Girls Gym	3,900	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd Floor Girls Gym	2,121	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Main Gym	9,072	SF	7	10+ years	
	Doors - Steel Doors incl hw	Main Gym	9,072	EA	7	-	
	Doors - Wood Doors inclu hw	Main Gym	9	EA	7	10+ years	
				SF		10+ years	
	Floor - Tile	Main Gym	3,000	_	6	10+ years	
	Floor - Wood	Main Gym	6,072	SF	6	10+ years	
	Lighting - Metal Halide/ High Pressure Sodium	Main Gym	26	EA	6	6-10 years	
	Lighting - Metal Halide/Sodium Vapor	Main Gym	3	EA	5	0-1 year	Not working
	Lighting - Pendent/Surface	Main Gym	11	EA	6	6-10 years	
	Lighting - Wall Mounted	Main Gym	21	EA	6	6-10 years	
	Scoreboards	Main Gym	1	EA	7	6-10 years	
	Storage/ Closet	Main Gym	360	SF	7	10+ years	
	Walls - Concrete Block	Main Gym	830	SF	6	10+ years	
	Walls - Masonry	Main Gym	2,500	SF	6	10+ years	
	Walls - Plaster/Drywall	Main Gym	4,200	SF	6	10+ years	
Kitchen							
	Ceiling - Splined	2nd Floor	1,300	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years	
	Floor - Tile Quarry	2nd Floor	1,300	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	19	ĒΑ	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	310	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,212	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Flr - Kitchen storage @ Lune	,	SF	6	10+ years	
	,	Room				,	
	Doors - Transom Window	2nd Flr - Kitchen storage @ Lune	ch 18	SF	7	10+ years	
		Room					
	Doors - Wood Doors inclu hw	2nd Flr - Kitchen storage @ Lune	ch 2	EA	7	10+ years	
	Floor - Tile Quarry	Room 2nd Flr - Kitchen storage @ Lune	ch 466	SF	6	6-10 years	
	1 1001 - THE QUAITY	Room	UII 400	ЗF	U	0-10 years	
	Lighting Dandont/Curfage		oh O	ГΛ	6	6.10 years	
	Lighting - Pendent/Surface	2nd Flr - Kitchen storage @ Lune	ch 9	EA	6	6-10 years	
	Walls - Plaster/Drywall	Room	ch 022	℃ E	6	10 L VOORO	
	vvalis - riastei/Drywali	2nd Flr - Kitchen storage @ Lune	ch 933	SF	6	10+ years	

Campus Name: Saucedo Page : 20 of 80 Assessment Date: 06/04/2024



Catego	Category : Room		В	uilding	: Main		
0	Hans Toma	Lagathan	0	LIOM	Danila	Recommend	0
Group	Item - Type	Location Room	Quantity	UOM	Rank	Replacement	Comments
		Room					
Library							
	AC Unit	201	2	EA	7	6-10 years	
	Casework	201	687	LF	7	10+ years	
	Ceiling - Lay-in	201	3,978	SF	6	10+ years	
	Doors - Wood Doors inclu hw	201	7	EA	7	10+ years	
	Floor - Tile	201	3,948	SF	6	6-10 years	
	Floor - Tile	201	30	SF	4	1-2 years	Cracked tile
	Lighting - Pendent/Surface	201	62	ĒΑ	6	10+ years	
	Storage/ Closet	201	24	SF	7	10+ years	
	Walls - Plaster/Drywall	201	2,967	SF	6	10+ years	
	•		,			,	
Locker/S	hower Room						
	Accessories	1st Flr Boys @ Gym (NOT USED)	1,574	SF	7	6-10 years	
	Benches, ped mounted	1st Flr Boys @ Gym (NOT USED)	138	LF	7	10+ years	
	Ceiling - Exposed	1st Flr Boys @ Gym (NOT USED)	400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Flr Boys @ Gym (NOT USED)	1,174	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Flr Boys @ Gym (NOT USED)	4	EA	6	10+ years	
	Doors - Wood Doors inclu hw	1st Flr Boys @ Gym (NOT USED)	2	EA	6	10+ years	
	Floor - Concrete	1st Flr Boys @ Gym (NOT USED)	1,486	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Fir Boys @ Gym (NOT USED)	88	SF	6	10+ years	
	Floor Drain	1st Fir Boys @ Gym (NOT USED)	8	ĒΑ	7	10+ years	
	Lavatory	1st Flr Boys @ Gym (NOT USED)	1	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	1st Flr Boys @ Gym (NOT USED)	46	EΑ	6	6-10 years	
	Partitions	1st Fir Boys @ Gym (NOT USED)	2	EA	7	10+ years	
	Student Lockers - Two Tier	1st Fir Boys @ Gym (NOT USED)	16	EA	5	2-5 years	Do not exist
	Student Lockers - Two Tier	1st Fir Boys @ Gym (NOT USED)	110	EA	5	1-2 years	Do not exist
	Urinals	1st Fir Boys @ Gym (NOT USED)	3	EA	7	10+ years	DO HOL EXIST
	Walls - Concrete Block	1st Fir Boys @ Gym (NOT USED)	250	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Fir Boys @ Gym (NOT USED)	2,740	SF	6	10+ years	
	Water Closet	1st Fir Boys @ Gym (NOT USED)	2,740	EA	6	-	
		1st Fir Boys @ Gyrii (NOT 03ED)		SF	7	10+ years	
	Accessories		617 20	LF	7	6-10 years	
	Benches, ped mounted	1st Fir Boys' @ Pool				10+ years	
	Ceiling - Plaster/Drywall	1st Fir Boys' @ Pool	607	SF SF	6	10+ years	Damagad aciling
	Ceiling - Plaster/Drywall	1st Fir Boys' @ Pool	10		4	1-2 years	Damaged ceiling
	Doors - Steel Doors incl hw	1st Fir Boys' @ Pool	1	EA	7	10+ years	
	Floor - Terrazzo	1st Fir Boys' @ Pool	292	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Fir Boys' @ Pool	325	SF	6	10+ years	
	Floor Drain	1st Flr Boys' @ Pool	4	EΑ	7	10+ years	
	Hand Dryer	1st Flr Boys' @ Pool	1	EA	7	6-10 years	
	Lavatory	1st Flr Boys' @ Pool	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Flr Boys' @ Pool	10	EA	6	6-10 years	
	Partitions	1st Flr Boys' @ Pool	1	EA	7	10+ years	



Catego	ry : Room		В	uilding	: Main	200	, , , , , , , , , , , , , , , , , , , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Showers	1st Flr Boys' @ Pool	8	EA	7	10+ years	
	Student Lockers - Two Tier	1st Flr Boys' @ Pool	74	EA	7	10+ years	
	Urinals	1st Flr Boys' @ Pool	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Flr Boys' @ Pool	885	SF	6	10+ years	
	Water Closet	1st FIr Boys' @ Pool	1	EA	7	10+ years	
	Accessories	1st Flr Girls @ Pool	3,002	SF	7	6-10 years	
	Benches, ped mounted	1st Flr Girls @ Pool	132	LF	7	10+ years	
	Ceiling - Exposed	1st FIr Girls @ Pool	3,002	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Flr Girls @ Pool	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Flr Girls @ Pool	4	EA	7	10+ years	
	Floor - Concrete	1st Flr Girls @ Pool	3,002	SF	5	10+ years	
	Floor Drain	1st Flr Girls @ Pool	10	ĒΑ	7	10+ years	
	Hand Dryer	1st Flr Girls @ Pool	24	EA	7	6-10 years	
	Lavatory	1st Flr Girls @ Pool	2	EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Flr Girls @ Pool	37	EΑ	6	2-5 years	Not working
	Lighting - Pendent/Surface	1st Fir Girls @ Pool	28	EA	6	6-10 years	Not working
	Partitions	1st FIr Girls @ Pool	29	EA	7	10+ years	
	Showers	1st Flr Girls @ Pool	24	EA	5	2-5 years	
	Storage/ Closet	1st FIr Girls @ Pool	54	SF	7	10+ years	
	Student Lockers - One Tier	1st Fir Girls @ Pool	760	EA	5	10+ years	
	Student Lockers - One Her Student Lockers - Two Tier	1st Fir Girls @ Pool	1,000	EA	5	-	
		1st Fir Girls @ Pool		SF	5 6	10+ years	
	Walls - Plaster/Drywall		2,688	SF EA	7	10+ years	
	Water Closet	1st Flr Girls @ Pool	5	EA	,	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Lay-in	2nd Floor Student Dining Area	11,000	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor Student Dining Area	426	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Student Dining Area	8	EA	7	10+ years	
	Floor - Tile	2nd Floor Student Dining Area	11,426	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Student Dining Area	355	EA	6	6-10 years	
	Serving Line	2nd Floor Student Dining Area	180	LF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor Student Dining Area	5,449	SF	6	10+ years	
	AC Unit	2nd Floor Teachers Lunchroom	1	EA	7	6-10 years	
	Ceiling - Splined	2nd Floor Teachers Lunchroom	674	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Teachers Lunchroom	1	EA	7	10+ years	
	Floor - Tile	2nd Floor Teachers Lunchroom	669	SF	6	10+ years	
	Floor - Tile	2nd Floor Teachers Lunchroom	5	SF	4	1-2 years	Cracked and damaged tile
	Lighting - Pendent/Surface	2nd Floor Teachers Lunchroom	12	ĒΑ	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor Teachers Lunchroom	1,215	SF	6	10+ years	
	Ceiling - Lay-in	3rd flr, Rm 300	1,785	SF	7	10+ years	
	Doors - Transom Window	3rd flr, Rm 300	48	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd flr, Rm 300	4	EA	7	10+ years	
	Floor - Tile	3rd flr, Rm 300	1,000	SF	6	10+ years	
	Floor - Wood	3rd flr, Rm 300	785	SF	6	10+ years	
	11001 11000	ord III, IXIII 000	700	01	J	ioi yeais	

Campus Name: Saucedo Page : 22 of 80 Assessment Date: 06/04/2024



Catego	Category : Room		В	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd flr, Rm 300	24	EΑ	6	6-10 years	
	Market Board	3rd flr, Rm 300	14	LF	7	6-10 years	
	Storage/ Closet	3rd flr, Rm 300	60	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd flr, Rm 300	2,297	SF	6	10+ years	
MDF ID	F						
_	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	243	SF	7	10+ years	
	Window AC Unit	2nd Floor	1	EA	7	6-10 years	
_Mechani	cal/ Service Rooms						
	Mechanical/ Service Rooms	1st Floor - East half	53	SF	5	10+ years	
	Mechanical/ Service Rooms	1st FIr-Freight Elevator & Lobby	319	SF	5	10+ years	
	Janitor's Closet	2nd Floor	15	SF	7	2-5 years	
	Janitor's Closet	2nd Floor	15	SF	5	2-5 years	
	Mechanical/ Service Rooms	2nd Floor	28	SF	7	10+ years	
	Storage Room	2nd Floor	80	SF	5	10+ years	Damaged ceiling
	Janitor's Closet	3rd Floor Janitor Closet @ Student Toilet Rooms	50	SF	5	10+ years	Damagoa coming
	Janitor's Closet	3rd Floor Janitor Closet @ Student Toilet Rooms	42	SF	5	10+ years	
	Storage Room	North end	4,500	SF	7	10+ years	
Pool & N	latatorium						
	Bleachers Seating/Plank Seating	1st Floor	175	EA	7	10+ years	
	Ceiling - Exposed	1st Floor	3,613	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	5	ĒΑ	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	3,613	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	ĒΑ	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EΑ	5	0-1 year	Not working
	Pool Basin	1st Floor	1,496	SF	7	10+ years	Tiot Working
	Pool Deck	1st Floor	2,117	SF	7	10+ years	
	Pool Deck Drains	1st Floor	2,117	EA	7	10+ years	
	Storage/ Closet	1st Floor	54	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,694	SF	6	10+ years	
	Walls - Flaster/Drywaii Walls - Structural Glazed Tile	1st Floor	1,952	SF	6	10+ years	
			, -			,	
Prep Ro	om Casework	216A - Science Prep/Storage Room	26	LF	7	10 L VOORO	
		with Vault NA with 220	_			10+ years	
	Ceiling - Plaster/Drywall	216A - Science Prep/Storage Room with Vault NA with 220	183	SF	6	10+ years	
	Doors - Wood Doors inclu hw	216A - Science Prep/Storage Room	4	EA	7	10+ years	

Campus Name: Saucedo Page : 23 of 80 Assessment Date: 06/04/2024



Floor - Tile	
Floor - Tile	
Floor - Tile	
Lighting - Lay-in 216A - Science PrepyStorage Room with Wault NA with 220 216A - Science PrepyStorage Room 2 EA 6 6-10 years with Wault NA with 220 216A - Science PrepyStorage Room 376 SF 6 10+ years with Wault NA with 220 216A - Science PrepyStorage Room 376 SF 6 10+ years with Wault NA with 220 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science PrepyStorage Room 376 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Science Prep With Yault 216 SF 6 10+ years 216A - Scien	
Lighting - Lay-in with Yault NA with 220	
With Vault NA with 220	
Lighting - Pendent/Surface 216A - Science Prepr/Storage Room with Vault NA with 220 216A - Science Prepr/Storage Room with Vault NA with 220 216A - Science Prepr/Storage Room with Vault NA with 220 216A - Science Prepr/Storage Room with Vault NA with 220 220A - Science Prepreprepreprepreprepreprepreprepreprepr	
Walls - Plaster/Drywall 216A - Science Prep/Storage Room 376 SF 6 10+ years Casework 220A - Science Prep 28 LF 7 10+ years Celling - Plaster/Drywall 220A - Science Prep 159 SF 6 10+ years Doors - Side-lite 220A - Science Prep 28 SF 7 10+ years Doors - Wood Doors inclu hw 220A - Science Prep 2 EA 7 10+ years Floor - Carpet 220A - Science Prep 159 SF 6 6-10 years Lighting - Pendent/Surface 220A - Science Prep 2 EA 6 6-10 years Walls - Plaster/Drywall 220A - Science Prep 318 SF 6 10+ years Work Sink 220A - Science Prep with Vault 26 LF 7 10+ years Celling - Plaster/Drywall 222 - Science Prep with Vault 18 SF 6 10+ years Casework 221 - Science Prep with Vault 154 A 7 10+ years Floor - Ti	
Walls - Plaster/Drywall	
With Vault NA with ½20	
Casework	
Ceiling - Plaster/Drywall 220A - Science Prep 28	
Doors - Wood Doors inclu hw 220A - Science Prep 2	
Doors - Wood Doors inclu hw 220A - Science Prep 2	
Floor - Carpet	
Lighting - Pendent/Surface 220A - Science Prep 3 EA 6 6-10 years Walls - Plaster/Drywall 220A - Science Prep 318 SF 6 10+ years Work Sink 220A - Science Prep 1 EA 7 6-10 years Casework 222 - Science Prep with Vault 26 LF 7 10+ years Ceiling - Plaster/Drywall 222 - Science Prep with Vault 1 EA 7 10+ years Floor - Carpet 222 - Science Prep with Vault 1 EA 7 10+ years Floor - Tile 222 - Science Prep with Vault 108 SF 6 6-10 years Lighting - Lay-in 222 - Science Prep with Vault 1 EA 6 6-10 years Lighting - Pendent/Surface 222 - Science Prep with Vault 2 EA 6 6-10 years Work Sink 222 - Science Prep with Vault 2 EA 6 6-10 years Casework 224A - In Science Class Room 224 28 LF 7 10+ years Ce	
Walls - Plaster/Drywall 220A - Science Prep 318 SF 6 10+ ýears Work Sink 220A - Science Prep 1 EA 7 6-10 years Casework 222 - Science Prep with Vault 26 LF 7 10+ years Ceiling - Plaster/Drywall 222 - Science Prep with Vault 183 SF 6 10+ years Doors - Wood Doors inclu hw 222 - Science Prep with Vault 1 EA 7 10+ years Floor - Carpet 222 - Science Prep with Vault 1 EA 7 10+ years Floor - Tile 222 - Science Prep with Vault 108 SF 6 6-10 years Lighting - Lay-in 222 - Science Prep with Vault 1 EA 6 6-10 years Lighting - Pendent/Surface 222 - Science Prep with Vault 1 EA 6 6-10 years Work Sink 222 - Science Prep with Vault 2 1 EA 6 6-10 years Work Sink 222 - Science Prep with Vault 1 EA 7 6-10 years	
Work Sink 220A - Science Prep 1 EA 7 6-10 years Casework 222 - Science Prep with Vault 26 LF 7 10+ years Ceiling - Plaster/Drywall 222 - Science Prep with Vault 183 SF 6 10+ years Doors - Wood Doors inclu hw 222 - Science Prep with Vault 1 EA 7 10+ years Floor - Carpet 222 - Science Prep with Vault 1 EA 7 10+ years Floor - Tile 222 - Science Prep with Vault 108 SF 6 6-10 years Lighting - Lay-in 222 - Science Prep with Vault 1 EA 6 6-10 years Lighting - Pendent/Surface 222 - Science Prep with Vault 2 EA 6 6-10 years Work Sink 222 - Science Prep with Vault 1 EA 7 6-10 years Casework 224A - In Science Class Room 224 28 LF 7 10+ years Cailing - Plaster/Drywall 224A - In Science Class Room 224 28 SF 7 10+ years <td></td>	
Casework 222 - Science Prep with Vault 26 LF 7 10+ years Ceiling - Plaster/Drywall 222 - Science Prep with Vault 183 SF 6 10+ years Doors - Wood Doors inclu hw 222 - Science Prep with Vault 1 EA 7 10+ years Floor - Carpet 222 - Science Prep with Vault 75 SF 6 6-10 years Floor - Tile 222 - Science Prep with Vault 108 SF 6 6-10 years Lighting - Lay-in 222 - Science Prep with Vault 1 EA 6 6-10 years Lighting - Pendent/Surface 222 - Science Prep with Vault 2 EA 6 6-10 years Walls - Plaster/Drywall 222 - Science Prep with Vault 216 SF 6 10+ years Work Sink 222 - Science Prep with Vault 1 EA 7 6-10 years Ceiling - Plaster/Drywall 224A - In Science Class Room 224 28 LF 7 10+ years Doors - Wood Doors inclu hw 224A - In Science Class Room 224 28 SF 7	
Ceiling - Plaster/Drywall 222 - Science Prep with Vault 183 SF 6 10+ years Doors - Wood Doors inclu hw 222 - Science Prep with Vault 1 EA 7 10+ years Floor - Carpet 222 - Science Prep with Vault 75 SF 6 6-10 years Floor - Tile 222 - Science Prep with Vault 108 SF 6 6-10 years Lighting - Lay-in 222 - Science Prep with Vault 1 EA 6 6-10 years Lighting - Pendent/Surface 222 - Science Prep with Vault 2 EA 6 6-10 years Walls - Plaster/Drywall 222 - Science Prep with Vault 2 EA 6 6-10 years Work Sink 222 - Science Prep with Vault 21 EA 7 6-10 years Casework 224A - In Science Class Room 224 28 LF 7 10+ years Ceiling - Plaster/Drywall 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Wood Doors inclu hw 224A - In Science Class Room 224 2 EA	
Doors - Wood Doors inclu hw 222 - Science Prep with Vault 1	
Floor - Carpet Floor - Tile 222 - Science Prep with Vault Floor - Tile 222 - Science Prep with Vault Floor - Tile 222 - Science Prep with Vault Floor - Tile 222 - Science Prep with Vault Floor - Tile 108 SF 6 6-10 years Floor - Carpet Floor - Car	
Floor - Tile 222 - Science Prep with Vault 108 SF 6 6-10 years	
Lighting - Lay-in Lighting - Pendent/Surface 222 - Science Prep with Vault 2 EA 6 6-10 years Walls - Plaster/Drywall 222 - Science Prep with Vault 2 EA 6 6-10 years Walls - Plaster/Drywall 222 - Science Prep with Vault 216 SF 6 10+ years Work Sink 222 - Science Prep with Vault 1 EA 7 6-10 years Casework 224A - In Science Class Room 224 28 LF 7 10+ years Ceiling - Plaster/Drywall 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Side-lite 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Wood Doors inclu hw 224A - In Science Class Room 224 2 EA 7 10+ years Floor - Carpet 224A - In Science Class Room 224 2 EA 7 10+ years Floor - Carpet 224A - In Science Class Room 224 2 EA 6 6-10 years Lighting - Pendent/Surface 224A - In Science Class Room 224 2 EA 6 6-10 years Walls - Plaster/Drywall 224A - In Science Class Room 224 2 EA 6 6-10 years Walls - Plaster/Drywall 224A - In Science Class Room 224 318 SF 6 10+ years Work Sink 224A - In Science Class Room 224 318 SF 6 10+ years Casework 3rd fir between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd fir between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd fir between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd fir between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd fir between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd fir between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd fir between CR 304 & 302	
Lighting - Pendent/Surface Walls - Plaster/Drywall 222 - Science Prep with Vault 216 SF 6 10+ years Work Sink 222 - Science Prep with Vault 1 EA 7 6-10 years Casework 224A - In Science Class Room 224 28 LF 7 10+ years Ceiling - Plaster/Drywall 224A - In Science Class Room 224 159 SF 6 2-5 years Doors - Side-lite 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Wood Doors inclu hw 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Wood Doors inclu hw 224A - In Science Class Room 224 2 EA 7 10+ years Floor - Carpet 224A - In Science Class Room 224 159 SF 6 6-10 years Lighting - Pendent/Surface 224A - In Science Class Room 224 2 EA 6 6-10 years Walls - Plaster/Drywall 224A - In Science Class Room 224 2 EA 6 6-10 years Work Sink 224A - In Science Class Room 224 1 EA 7 6-10 years Work Sink 224A - In Science Class Room 224 1 EA 7 6-10 years Casework 3rd fir between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd fir between CR 304 & 302 266 SF 6 10+ years Doors - Steel Doors incl hw 3rd fir between CR 304 & 302 2 EA 7 10+ years Doors - Wood Doors inclu hw 3rd fir between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd fir between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd fir between CR 304 & 302 2 EA 7 10+ years	
Walls - Plaster/Drywall 222 - Science Prep with Vault 216 SF 6 10+ years Work Sink 222 - Science Prep with Vault 1 EA 7 6-10 years Casework 224A - In Science Class Room 224 28 LF 7 10+ years Ceiling - Plaster/Drywall 224A - In Science Class Room 224 28 SF 6 2-5 years Doors - Side-lite 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Wood Doors inclu hw 224A - In Science Class Room 224 2 EA 7 10+ years Floor - Carpet 224A - In Science Class Room 224 159 SF 6 6-10 years Lighting - Pendent/Surface 224A - In Science Class Room 224 2 EA 6 6-10 years Walls - Plaster/Drywall 224A - In Science Class Room 224 318 SF 6 10+ years Work Sink 224A - In Science Class Room 224 1 EA 7 6-10 years Casework 3rd fir between CR 304 & 302 36 LF 7 </td <td></td>	
Work Sink Casework Casework Ceiling - Plaster/Drywall 224A - In Science Class Room 224 28 LF 7 10+ years Ceiling - Plaster/Drywall 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Side-lite 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Wood Doors inclu hw 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Wood Doors inclu hw 224A - In Science Class Room 224 2 EA 7 10+ years Floor - Carpet 224A - In Science Class Room 224 2 EA 6 6-10 years Lighting - Pendent/Surface 224A - In Science Class Room 224 2 EA 6 6-10 years Walls - Plaster/Drywall 224A - In Science Class Room 224 318 SF 6 10+ years Work Sink 224A - In Science Class Room 224 318 SF 6 10+ years Casework 3rd fir between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd fir between CR 304 & 302 36 LF 7 10+ years Doors - Steel Doors incl hw 3rd fir between CR 304 & 302 36 LF 7 10+ years Doors - Wood Doors inclu hw 3rd fir between CR 304 & 302 3 EA 7 10+ years Doors - Wood Doors inclu hw 3rd fir between CR 304 & 302 3 EA 7 10+ years Doors - Wood Doors inclu hw 3rd fir between CR 304 & 302 3 EA 7 10+ years Doors - Tile 3rd fir between CR 304 & 302 3 EA 7 10+ years Floor - Tile	
Casework Ceiling - Plaster/Drywall 224A - In Science Class Room 224 159 SF 6 2-5 years Doors - Side-lite 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Wood Doors inclu hw 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Wood Doors inclu hw 224A - In Science Class Room 224 2 EA 7 10+ years Floor - Carpet 224A - In Science Class Room 224 159 SF 6 6-10 years Lighting - Pendent/Surface 224A - In Science Class Room 224 2 EA 6 6-10 years Walls - Plaster/Drywall 224A - In Science Class Room 224 318 SF 6 10+ years Work Sink 224A - In Science Class Room 224 318 SF 6 10+ years Casework 3rd fir between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd fir between CR 304 & 302 266 SF 6 10+ years Doors - Steel Doors incl hw 3rd fir between CR 304 & 302 3rd fir between CR 304 & 302 2 EA 7 10+ years Doors - Wood Doors inclu hw 3rd fir between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd fir between CR 304 & 302 2 EA 7 10+ years	
Ceiling - Plaster/Drywall 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Side-lite 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Wood Doors inclu hw 224A - In Science Class Room 224 2 EA 7 10+ years Floor - Carpet 224A - In Science Class Room 224 159 SF 6 6-10 years Lighting - Pendent/Surface 224A - In Science Class Room 224 2 EA 6 6-10 years Walls - Plaster/Drywall 224A - In Science Class Room 224 318 SF 6 10+ years Work Sink 224A - In Science Class Room 224 1 EA 7 6-10 years Casework Casework 3rd flr between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd flr between CR 304 & 302 36 LF 7 10+ years Doors - Steel Doors incl hw 3rd flr between CR 304 & 302 1 EA 7 10+ years Doors - Wood Doors inclu hw 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile	
Doors - Side-lite 224A - In Science Class Room 224 28 SF 7 10+ years Doors - Wood Doors inclu hw 224A - In Science Class Room 224 2 EA 7 10+ years Floor - Carpet 224A - In Science Class Room 224 159 SF 6 6-10 years Lighting - Pendent/Surface 224A - In Science Class Room 224 2 EA 6 6-10 years Walls - Plaster/Drywall 224A - In Science Class Room 224 318 SF 6 10+ years Work Sink 224A - In Science Class Room 224 1 EA 7 6-10 years Casework 3rd flr between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd flr between CR 304 & 302 266 SF 6 10+ years Doors - Steel Doors incl hw 3rd flr between CR 304 & 302 1 EA 7 10+ years Doors - Wood Doors inclu hw 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd flr between CR 304 & 302 266 SF 6 6-10 years	
Doors - Wood Doors inclu hw 224A - In Science Class Room 224 2 EA 7 10+ years Floor - Carpet 224A - In Science Class Room 224 Lighting - Pendent/Surface 224A - In Science Class Room 224 2 EA 6 6-10 years Walls - Plaster/Drywall 224A - In Science Class Room 224 318 SF 6 10+ years Work Sink 224A - In Science Class Room 224 1 EA 7 6-10 years Casework 3rd flr between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd flr between CR 304 & 302 266 SF 6 10+ years Doors - Steel Doors incl hw 3rd flr between CR 304 & 302 1 EA 7 10+ years Doors - Wood Doors inclu hw 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd flr between CR 304 & 302 2 EA 7 10+ years Ceiling - Plaster/Drywall 3rd flr between CR 304 & 302 2 EA 7 10+ years Ceiling - Tile 3rd flr between CR 304 & 302 2 EA 7 10+ years Ceiling - Tile	
Floor - Carpet Lighting - Pendent/Surface 224A - In Science Class Room 224 2 EA 6 6-10 years Walls - Plaster/Drywall 224A - In Science Class Room 224 318 SF 6 10+ years Work Sink 224A - In Science Class Room 224 318 SF 6 10+ years Casework 3rd flr between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd flr between CR 304 & 302 266 SF 6 10+ years Doors - Steel Doors incl hw 3rd flr between CR 304 & 302 1 EA 7 10+ years Doors - Wood Doors inclu hw 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd flr between CR 304 & 302 2 66 SF 6 6-10 years	
Lighting - Pendent/Surface 224A - In Science Class Room 224 2 EA 6 6-10 years Walls - Plaster/Drywall 224A - In Science Class Room 224 318 SF 6 10+ years Work Sink 224A - In Science Class Room 224 1 EA 7 6-10 years Casework 3rd flr between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd flr between CR 304 & 302 266 SF 6 10+ years Doors - Steel Doors incl hw 3rd flr between CR 304 & 302 1 EA 7 10+ years Doors - Wood Doors inclu hw 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd flr between CR 304 & 302 266 SF 6 6-10 years	
Walls - Plaster/Drywall 224A - In Science Class Room 224 318 SF 6 10+ years Work Sink 224A - In Science Class Room 224 1 EA 7 6-10 years Casework Casework 3rd flr between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd flr between CR 304 & 302 266 SF 6 10+ years Doors - Steel Doors incl hw 3rd flr between CR 304 & 302 1 EA 7 10+ years Doors - Wood Doors inclu hw 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd flr between CR 304 & 302 2 66 SF 6 6-10 years	
Walls - Plaster/Drywall 224A - In Science Class Room 224 318 SF 6 10+ years Work Sink 224A - In Science Class Room 224 1 EA 7 6-10 years Casework 3rd flr between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd flr between CR 304 & 302 266 SF 6 10+ years Doors - Steel Doors incl hw 3rd flr between CR 304 & 302 1 EA 7 10+ years Doors - Wood Doors inclu hw 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd flr between CR 304 & 302 266 SF 6 6-10 years	
Work Sink 224A - In Science Class Room 224 1 EA 7 6-10 years Casework 3rd flr between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd flr between CR 304 & 302 266 SF 6 10+ years Doors - Steel Doors incl hw 3rd flr between CR 304 & 302 1 EA 7 10+ years Doors - Wood Doors inclu hw 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd flr between CR 304 & 302 266 SF 6 6-10 years	
Casework 3rd flr between CR 304 & 302 36 LF 7 10+ years Ceiling - Plaster/Drywall 3rd flr between CR 304 & 302 266 SF 6 10+ years Doors - Steel Doors incl hw 3rd flr between CR 304 & 302 1 EA 7 10+ years Doors - Wood Doors inclu hw 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd flr between CR 304 & 302 266 SF 6 6-10 years	
Ceiling - Plaster/Drywall 3rd flr between CR 304 & 302 266 SF 6 10+ years Doors - Steel Doors incl hw 3rd flr between CR 304 & 302 1 EA 7 10+ years Doors - Wood Doors inclu hw 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd flr between CR 304 & 302 266 SF 6 6-10 years	
Doors - Steel Doors incl hw 3rd flr between CR 304 & 302 1 EA 7 10+ years Doors - Wood Doors inclu hw 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd flr between CR 304 & 302 266 SF 6 6-10 years	
Doors - Wood Doors inclu hw 3rd flr between CR 304 & 302 2 EA 7 10+ years Floor - Tile 3rd flr between CR 304 & 302 266 SF 6 6-10 years	
Floor - Tile 3rd flr between CR 304 & 302 266 SF 6 6-10 years	
Lighting - Pendent/Surface 3rd flr between CR 304 & 302 3 EA 6 6-10 years	
Walls - Plaster/Drywall 3rd flr between CR 304 & 302 532 SF 6 10+ years	
Work Sink 3rd flr between CR 304 & 302 1 EA 7 6-10 years	
Casework 3rd fir between CR 305 & 309 36 LF 7 10+ years	
Ceiling - Plaster/Drywall 3rd flr between CR 305 & 309 266 SF 6 10+ years	
Coming Flactor, Drywaii Ord iii between er coo d ood 2000 200 Oi O 10+ yedis	



Catego	ry : Room		Building : Main							
_				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Doors - Steel Doors incl hw	3rd flr between CR 305 & 309	1	EA	7	10+ years				
	Doors - Wood Doors inclu hw	3rd flr between CR 305 & 309	1	EA	7	10+ years				
	Doors - Wood Doors inclu hw	3rd flr between CR 305 & 309	1	EA	7	10+ years				
	Floor - Tile	3rd flr between CR 305 & 309	266	SF	6	10+ years				
	Lighting - Pendent/Surface	3rd flr between CR 305 & 309	3	EA	6	6-10 years				
	Walls - Plaster/Drywall	3rd flr between CR 305 & 309	432	SF	6	10+ years				
	Work Sink	3rd flr between CR 305 & 309	1	EA	7	10+ years				
Restrooi	n									
	Accessories	102	72	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	102	72	SF	6	10+ years				
	Doors - Wood Doors inclu hw			EA	7	•				
		102	1			10+ years				
	Floor - Concrete	102	72	SF	7	10+ years				
	Lavatory	102	1	EΑ	7	10+ years				
	Lighting - Pendent/Surface	102	1	EA	6	6-10 years				
	Partitions	102	1	EA	7	10+ years				
	Walls - Plaster/Drywall	102	140	SF	6	10+ years				
	Water Closet	102	1	EA	7	10+ years				
	Accessories	116 Pre-K Unisex	33	SF	7	6-10 years				
	Ceiling - Lay-in	116 Pre-K Unisex	33	SF	6	10+ years				
	Doors - Wood Doors inclu hw	116 Pre-K Unisex	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	116 Pre-K Unisex	33	SF	6	6-10 years				
	Lavatory	116 Pre-K Unisex	1	EA	7	10+ years				
	Lighting - Pendent/Surface	116 Pre-K Unisex	1	EA	6	6-10 years				
	Walls - Plaster/Drywall	116 Pre-K Unisex	32	SF	6	10+ years				
	Walls - Tile Ceramic/ Porcelain	116 Pre-K Unisex	36	SF	6	10+ years				
	Water Closet	116 Pre-K Unisex	1	ĒΑ	7	10+ years				
	Accessories	128 Staff	72	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	128 Staff	72	SF	6	10+ years				
	Doors - Steel Doors incl hw	128 Staff	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	128 Staff	72	SF	7	•				
	Floor Drain	128 Staff	1	EA	7	10+ years				
			1	EA EA	7 7	10+ years				
	Hand Dryer	128 Staff	1			10+ years				
	Lavatory	128 Staff	1	EA	7	10+ years				
	Lighting - Wall Mounted	128 Staff	2	EA	6	6-10 years				
	Walls - Plaster/Drywall	128 Staff	160	SF	6	10+ years				
	Water Closet	128 Staff	1	EA	7	10+ years				
	Accessories	130 Pre-K Unisex	30	SF	7	6-10 years				
	Ceiling - Lay-in	130 Pre-K Unisex	30	SF	6	10+ years				
	Doors - Wood Doors inclu hw	130 Pre-K Unisex	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	130 Pre-K Unisex	30	SF	6	6-10 years				
	Lavatory	130 Pre-K Unisex	1	EA	7	10+ years				
	Lighting - Pendent/Surface	130 Pre-K Unisex	1	EA	6	6-10 years				
	Walls - Plaster/Drywall	130 Pre-K Unisex	70	SF	6	10+ years				



Category : Room			Building : Main						
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Water Closet	130 Pre-K Unisex	1	EA	7	10+ years			
	Accessories	143 Unisex Toilet	54	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	143 Unisex Toilet	54	SF	6	10+ years			
	Doors - Wood Doors inclu hw	143 Unisex Toilet	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	143 Unisex Toilet	54	SF	6	6-10 years			
	Floor Drain	143 Unisex Toilet	1	EA	7	10+ years			
	Hand Dryer	143 Unisex Toilet	1	EA	7	6-10 years			
	Lavatory	143 Unisex Toilet	1	EA	7	10+ years			
	Lighting - Pendent/Surface	143 Unisex Toilet	1	EA	6	6-10 years			
	Walls - Plaster/Drywall	143 Unisex Toilet	75	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	143 Unisex Toilet	89	SF	6	10+ years			
	Water Closet	143 Unisex Toilet	1	EA	7	10+ years			
	Accessories	144 Unisex Toilet	54	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	144 Unisex Toilet	54	SF	6	10+ years			
	Doors - Wood Doors inclu hw	144 Unisex Toilet	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	144 Unisex Toilet	54	SF	6	10+ years			
	Floor Drain	144 Unisex Toilet	1	EA	7	10+ years			
	Hand Dryer	144 Unisex Toilet	1	EA	7	6-10 years			
	Lavatory	144 Unisex Toilet	1	EA	7	10+ years			
	Lighting - Pendent/Surface	144 Unisex Toilet	1	EA	6	6-10 years			
	Walls - Plaster/Drywall	144 Unisex Toilet	75	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	144 Unisex Toilet	89	SF	6	10+ years			
	Water Closet	144 Unisex Toilet	1	EA	7	10+ years			
	Accessories	1st Floor NE Girls (Boys on plan)	331	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor NE Girls (Boys on plan)	331	SF	6	10+ years			
	Floor - Concrete Epoxy/ Painted	1st Floor NE Girls (Boys on plan)	331	SF	7	10+ years			
	Floor Drain	1st Floor NE Girls (Boys on plan)	1	ĒΑ	7	10+ years			
	Hand Dryer	1st Floor NE Girls (Boys on plan)	2	EA	7	10+ years			
	Lavatory	1st Floor NE Girls (Boys on plan)	2	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor NE Girls (Boys on plan)	8	EA	6	6-10 years			
	Partitions	1st Floor NE Girls (Boys on plan)	9	ΕA	7	10+ years			
	Walls - Concrete Block	1st Floor NE Girls (Boys on plan)	144	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor NE Girls (Boys on plan)	136	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor NE Girls (Boys on plan)	8	SF	5	1-2 years	Damaged wall		
	Walls - Tile Ceramic/ Porcelain	1st Floor NE Girls (Boys on plan)	288	SF	6	10+ years	zamagou wan		
	Water Closet	1st Floor NE Girls (Boys on plan)	8	ĒΑ	7	10+ years			
	Water Closet	1st Floor NE Girls (Boys on plan)	1	EA	4	1-2 years	Not in service		
	Accessories	1st Floor NW Girls (Boys on plan)	331	SF	7	6-10 years	1101 111 0011100		
	Ceiling - Plaster/Drywall	1st Floor NW Girls (Boys on plan)	331	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor NW Girls (Boys on plan)	331	SF	7	10+ years			
	Floor Drain	1st Floor NW Girls (Boys on plan)	1	EA	7	10+ years			
	Hand Dryer	1st Floor NW Girls (Boys on plan)	2	EA	7	10+ years			
	Lavatory	1st Floor NW Girls (Boys on plan)	2	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor NW Girls (Boys on plan)	8	EA	6	6-10 years			
		. st. i issi i i i i sins (Baya an plan)	O .	_, .	·	3 10 ,00.0			



Catego	ry : Room		Building : Main							
				_		Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Partitions	1st Floor NW Girls (Boys on plan)	8	EA	7	10+ years				
	Walls - Concrete Block	1st Floor NW Girls (Boys on plan)	144	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor NW Girls (Boys on plan)	144	SF	6	10+ years				
	Walls - Tile Ceramic/ Porcelain	1st Floor NW Girls (Boys on plan)	288	SF	6	6-10 years				
	Water Closet	1st Floor NW Girls (Boys on plan)	8	EA	7	10+ years				
	Accessories	1st Floor SE Boys (Girls on plan)	349	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor SE Boys (Girls on plan)	349	SF	6	10+ years				
	Floor - Concrete Epoxy/ Painted	1st Floor SE Boys (Girls on plan)	349	SF	7	10+ years				
	Floor Drain	1st Floor SE Boys (Girls on plan)	1	EA	7	10+ years				
	Hand Dryer	1st Floor SE Boys (Girls on plan)	2	EA	7	10+ years				
	Lavatory	1st Floor SE Boys (Girls on plan)	2	EA	7	10+ years				
	Lighting - Pendent/Surface	1st Floor SE Boys (Girls on plan)	8	EA	6	6-10 years				
	Partitions	1st Floor SE Boys (Girls on plan)	2	EA	7	10+ years				
	Urinals	1st Floor SE Boys (Girls on plan)	6	EA	7	10+ years				
	Urinals	1st Floor SE Boys (Girls on plan)	1	EΑ	5	1-2 years	Not in service			
	Walls - Concrete Block	1st Floor SE Boys (Girls on plan)	144	SF	6	10+ years	1401 111 001 1100			
	Walls - Plaster/Drywall	1st Floor SE Boys (Girls on plan)	144	SF	6	10+ years				
	Walls - Tile Ceramic/ Porcelain	1st Floor SE Boys (Girls on plan)	278	SF	6	10+ years				
	Walls - Tile Ceramic/ Porcelain	1st Floor SE Boys (Girls on plan)	10	SF	4	1-2 years	Missing tiles			
	Water Closet	1st Floor SE Boys (Girls on plan)	2	EA	7	10+ years	Wilson'ly tiles			
	Accessories	1st Floor SW Boys (Girls on plan)	349	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor SW Boys (Girls on plan)	349	SF	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor SW Boys (Girls on plan)	349	SF	6	10+ years				
	Floor Drain	1st Floor SW Boys (Girls on plan)	1	EA	7	10+ years				
	Hand Dryer	1st Floor SW Boys (Girls on plan)	2	EA	7	10+ years				
	Lavatory	1st Floor SW Boys (Girls on plan)	2	EA	7	10+ years				
	Lighting - Pendent/Surface	1st Floor SW Boys (Girls on plan)	8	EA	6	6-10 years				
	Partitions		2	EA	7	•				
	Urinals	1st Floor SW Boys (Girls on plan)		EA		10+ years				
	Walls - Concrete Block	1st Floor SW Boys (Girls on plan)	7 144	SF	7	10+ years				
		1st Floor SW Boys (Girls on plan) 1st Floor SW Boys (Girls on plan)		SF SF	6	10+ years				
	Walls - Plaster/Drywall Walls - Tile Ceramic/ Porcelain		144 288	SF SF	6	10+ years				
		1st Floor SW Boys (Girls on plan)			6	10+ years				
	Water Closet	1st Floor SW Boys (Girls on plan)	2	EA SF	7	10+ years				
	Accessories	2nd Floor Gym Office/219.5A Toilet room in Office/Storage	100	51	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor Gym Office/219.5A Toilet room in Office/Storage	100	SF	6	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor Gym Office/219.5A Toilet room in Office/Storage	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor Gym Office/219.5A Toilet room in Office/Storage	100	SF	6	10+ years				
	Lavatory	2nd Floor Gym Office/219.5A Toilet room in Office/Storage	1	EA	7	10+ years				
	Lighting - Pendent/Surface	2nd Floor Gym Office/219.5A Toilet	1	EA	7	10+ years				



Catego	ry : Room	Building : Main								
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	11.12	room in Office/Storage	_		_	40				
	Lighting - Wall Mounted	2nd Floor Gym Office/219.5A Toilet	1	EA	7	10+ years				
	Destitions	room in Office/Storage	4	_^	7	40				
	Partitions	2nd Floor Gym Office/219.5A Toilet	1	EA	7	10+ years				
	Showers	room in Office/Storage 2nd Floor Gym Office/219.5A Toilet	1	EA	4	1.0	Out of comics			
	Snowers	room in Office/Storage	1	EA	4	1-2 years	Out of service			
	Walls - Plaster/Drywall	2nd Floor Gym Office/219.5A Toilet	200	SF	6	6-10 years				
	vvalis - i lastei/Drywali	room in Office/Storage	200	OI.	U	0-10 years				
	Water Closet	2nd Floor Gym Office/219.5A Toilet	1	EA	7	10+ years				
	Water Gloset	room in Office/Storage		LA	,	10+ years				
	Accessories	2nd Floor NE Girls (Boys on plan)	331	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor NE Girls (Boys on plan)	331	SF	6	10+ years				
	Floor - Concrete Epoxy/ Painted	2nd Floor NE Girls (Boys on plan)	331	SF	7	10+ years				
	Floor Drain	2nd Floor NE Girls (Boys on plan)	1	ĒΑ	7	10+ years				
	Lavatory	2nd Floor NE Girls (Boys on plan)	2	EA	7	10+ years				
	Lighting - Pendent/Surface	2nd Floor NE Girls (Boys on plan)	8	EA	6	6-10 years				
	Partitions	2nd Floor NE Girls (Boys on plan)	8	EA	7	10+ years				
	Partitions	2nd Floor NE Girls (Boys on plan)	1	EA	4	1-2 years	Damaged door			
	Walls - Concrete Block	2nd Floor NE Girls (Boys on plan)	144	SF	6	10+ years	•			
	Walls - Plaster/Drywall	2nd Floor NE Girls (Boys on plan)	144	SF	6	10+ years				
	Walls - Tile Ceramic/ Porcelain	2nd Floor NE Girls (Boys on plan)	288	SF	6	10+ years				
	Water Closet	2nd Floor NE Girls (Boys on plan)	7	EA	7	10+ years				
	Water Closet	2nd Floor NE Girls (Boys on plan)	2	EA	4	1-2 years	Not in service			
	Accessories	2nd Floor NW (Help Locker Room	214	SF	7	6-10 years				
		on plan)								
	Ceiling - Plaster/Drywall	2nd Floor NW (Help Locker Room	214	SF	6	10+ years				
		on plan)			_					
	Doors - Wood Doors inclu hw	2nd Floor NW (Help Locker Room	1	EA	7	10+ years				
	E. T.	on plan)	0.1.1	0=	•	40				
	Floor - Tile	2nd Floor NW (Help Locker Room	214	SF	6	10+ years				
	Hand Duran	on plan)	4	_^	7	0.40				
	Hand Dryer	2nd Floor NW (Help Locker Room	1	EA	7	6-10 years				
	Loyotony	on plan)	4	EA	7	10				
	Lavatory	2nd Floor NW (Help Locker Room	1	EA	7	10+ years				
	Lighting - Pendent/Surface	on plan) 2nd Floor NW (Help Locker Room	3	EA	6	6-10 years				
	Lighting - Pendent/Surface	· ·	3	EA	O	0-10 years				
	Student Lockers - One Tier	on plan) 2nd Floor NW (Help Locker Room	19	EA	7	10+ years				
	Olddell Lockers - Olie Hel	on plan)	19	LA	,	10+ years				
	Walls - Plaster/Drywall	2nd Floor NW (Help Locker Room	359	SF	6	10+ years				
	Traile Tractor/Dry Wall	on plan)	559	Oi.	J	TOT years				
	Water Closet	2nd Floor NW (Help Locker Room	1	EA	7	6-10 years				
	114.5. 5.0001	on plan)	•	_, .	•	5 To yours				
		··· P·····/								

Campus Name: Saucedo Page : 28 of 80 Assessment Date: 06/04/2024



Catego	ry : Room		Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Accessories	2nd Floor NW Girls (Boys on plan)	331	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor NW Girls (Boys on plan)	331	SF	6	10+ years			
	Floor - Concrete Epoxy/ Painted	2nd Floor NW Girls (Boys on plan)	301	SF	7	10+ years			
	Floor - Concrete Epoxy/ Painted	2nd Floor NW Girls (Boys on plan)	30	SF	4	1-2 years	Damaged finish		
	Floor Drain	2nd Floor NW Girls (Boys on plan)	1	EA	7	10+ years			
	Hand Dryer	2nd Floor NW Girls (Boys on plan)	2	EA	7	10+ years			
	Lavatory	2nd Floor NW Girls (Boys on plan)	2	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor NW Girls (Boys on plan)	8	EA	6	6-10 years			
	Partitions	2nd Floor NW Girls (Boys on plan)	9	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor NW Girls (Boys on plan)	144	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor NW Girls (Boys on plan)	144	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	2nd Floor NW Girls (Boys on plan)	288	SF	6	10+ years			
	Water Closet	2nd Floor NW Girls (Boys on plan)	8	EA	7	10+ years			
	Water Closet	2nd Floor NW Girls (Boys on plan)	1	EA	4	1-2 years	Not in service		
	Accessories	2nd Floor SE Boys (Girls on plan)	349	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor SE Boys (Girls on plan)	349	SF	6	10+ years			
	Floor - Concrete Epoxy/ Painted	2nd Floor SE Boys (Girls on plan)	349	SF	7	10+ years			
	Floor Drain	2nd Floor SE Boys (Girls on plan)	1	EA	7	10+ years			
	Hand Dryer	2nd Floor SE Boys (Girls on plan)	2	EA	7	10+ years			
	Lavatory	2nd Floor SE Boys (Girls on plan)	2	EΑ	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor SE Boys (Girls on plan)	7	EΑ	6	6-10 years			
	Partitions	2nd Floor SE Boys (Girls on plan)	2	EA	7	10+ years			
	Urinals	2nd Floor SE Boys (Girls on plan)	7	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor SE Boys (Girls on plan)	144	SF SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor SE Boys (Girls on plan)	144 288	SF SF	6 6	10+ years			
	Walls - Tile Ceramic/ Porcelain Water Closet	2nd Floor SE Boys (Girls on plan)	288 2	SF EA	6 7	10+ years			
	Accessories	2nd Floor SE Boys (Girls on plan) 2nd Floor SW Boys (Girls on plan)	349	SF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor SW Boys (Girls on plan)	349	SF	6	6-10 years 10+ years			
	Floor - Concrete Epoxy/ Painted	2nd Floor SW Boys (Girls on plan)	349	SF	7	10+ years			
	Floor - Concrete Epoxy/ Painted	2nd Floor SW Boys (Girls on plan)	5 44 5	SF	4	1-2 years	Damaged floor finish		
	Floor Drain	2nd Floor SW Boys (Girls on plan)	1	EA	7	10+ years	Damaged 11001 Illiish		
	Hand Dryer	2nd Floor SW Boys (Girls on plan)	2	EA	7	10+ years			
	Lavatory	2nd Floor SW Boys (Girls on plan)	2	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor SW Boys (Girls on plan)	6	EA	6	6-10 years			
	Partitions	2nd Floor SW Boys (Girls on plan)	2	EA	7	10+ years			
	Urinals	2nd Floor SW Boys (Girls on plan)	7	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor SW Boys (Girls on plan)	144	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor SW Boys (Girls on plan)	129	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	2nd Floor SW Boys (Girls on plan)	288	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	2nd Floor SW Boys (Girls on plan)	15	SF	4	1-2 years	Damaged tile on wall		
	Water Closet	2nd Floor SW Boys (Girls on plan)	2	EA	7	10+ years			
	Accessories	3rd Floor NE Girls (Boys on plan)	331	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor NE Girls (Boys on plan)	331	SF	6	10+ years			
	J	(==,==:::::::::::::::::::::::::::::::::			-	- <i>,</i>			

Campus Name: Saucedo Page : 29 of 80 Assessment Date: 06/04/2024



Catego	Category : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Concrete Epoxy/ Painted	3rd Floor NE Girls (Boys on plan)	331	SF	7	10+ years	
	Floor Drain	3rd Floor NE Girls (Boys on plan)	1	EA	7	6-10 years	
	Hand Dryer	3rd Floor NE Girls (Boys on plan)	2	EA	7	10+ years	
	Lavatory	3rd Floor NE Girls (Boys on plan)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor NE Girls (Boys on plan)	8	EA	6	6-10 years	
	Partitions	3rd Floor NE Girls (Boys on plan)	9	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor NE Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor NE Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor NE Girls (Boys on plan)	288	SF	6	10+ years	
	Water Closet	3rd Floor NE Girls (Boys on plan)	9	EA	7	10+ years	
	Accessories	3rd Floor NW Girls (Boys on plan)	331	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor NW Girls (Boys on plan)	331	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	3rd Floor NW Girls (Boys on plan)	331	SF	7	10+ years	
	Floor Drain	3rd Floor NW Girls (Boys on plan)	1	EA	7	10+ years	
	Hand Dryer	3rd Floor NW Girls (Boys on plan)	2	EA	7	10+ years	
	Lavatory	3rd Floor NW Girls (Boys on plan)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor NW Girls (Boys on plan)	8	EA	6	6-10 years	
	Partitions	3rd Floor NW Girls (Boys on plan)	9	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor NW Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor NW Girls (Boys on plan)	144	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor NW Girls (Boys on plan)	288	SF	6	10+ years	
	Water Closet	3rd Floor NW Girls (Boys on plan)	9	EA	7	10+ years	
	Accessories	3rd Floor SE Boys (Girls on plan)	349	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor SE Boys (Girls on plan)	349	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	3rd Floor SE Boys (Girls on plan)	349	SF	7	10+ years	
	Floor Drain	3rd Floor SE Boys (Girls on plan)	1	EA	7	10+ years	
	Hand Dryer	3rd Floor SE Boys (Girls on plan)	2	EA	7	10+ years	
	Lavatory	3rd Floor SE Boys (Girls on plan)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor SE Boys (Girls on plan)	8	EA	6	6-10 years	
	Partitions	3rd Floor SE Boys (Girls on plan)	2	EA	7	10+ years	
	Urinals	3rd Floor SE Boys (Girls on plan)	7	EA	7	10+ years	
	Walls - Concrete Block	3rd Floor SE Boys (Girls on plan)	144	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor SE Boys (Girls on plan)	144	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor SE Boys (Girls on plan)	288	SF	6	10+ years	
	Water Closet	3rd Floor SE Boys (Girls on plan)	2	ĒΑ	7	10+ years	
	Accessories	3rd Floor SW Boys (Girls on plan)	349	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor SW Boys (Girls on plan)	349	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	3rd Floor SW Boys (Girls on plan)	349	SF	7	10+ years	
	Floor Drain	3rd Floor SW Boys (Girls on plan)	1	EA	7	10+ years	
	Hand Dryer	3rd Floor SW Boys (Girls on plan)	2	EΑ	7	10+ years	
	Lavatory	3rd Floor SW Boys (Girls on plan)	2	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor SW Boys (Girls on plan)	8	EA	6	6-10 years	
	Partitions	3rd Floor SW Boys (Girls on plan)	2	EA	7	10+ years	
	Urinals	3rd Floor SW Boys (Girls on plan)	7	EA	7	10+ years	
	- Cinicio	S.a. Floor CTT Boyo (Cino on plan)	•	_, .	•	ioi youio	



Catego	Category : Room		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	3rd Floor SW Boys (Girls on plan)	144	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor SW Boys (Girls on plan)	144	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor SW Boys (Girls on plan)	287	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	3rd Floor SW Boys (Girls on plan)	1	SF	4	1-2 years	Missing
	Water Closet	3rd Floor SW Boys (Girls on plan)	2	EA	7	10+ years	
	Accessories	Main Gym Office Toilet Room	70	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Gym Office Toilet Room	70	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Main Gym Office Toilet Room	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Main Gym Office Toilet Room	70	SF	6	10+ years	
	Lavatory	Main Gym Office Toilet Room	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Main Gym Office Toilet Room	1	EA	6	6-10 years	
	Partitions	Main Gym Office Toilet Room	1	EA	7	10+ years	
	Showers	Main Gym Office Toilet Room	1	EA	4	1-2 years	Not in use
	Walls - Masonry	Main Gym Office Toilet Room	110	SF	6	10+ years	
	Walls - Plaster/Drywall	Main Gym Office Toilet Room	100	SF	6	10+ years	
	Water Closet	Main Gym Office Toilet Room	1	EA	7	10+ years	
	Accessories	Mens East of Lobby	180	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Mens East of Lobby	180	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Mens East of Lobby	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Mens East of Lobby	179	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Mens East of Lobby	1	SF	4	1-2 years	Damaged floor
	Floor Drain	Mens East of Lobby	1	EA	7	10+ years	3
	Lavatory	Mens East of Lobby	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Mens East of Lobby	4	EA	6	6-10 years	
	Partitions	Mens East of Lobby	1	EA	7	10+ years	
	Urinals	Mens East of Lobby	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Mens East of Lobby	360	SF	6	10+ years	
	Water Closet	Mens East of Lobby	1	EA	7	10+ years	
	Accessories	New in 116	85	SF	7	10+ years	
	Ceiling - Plaster/Drywall	New in 116	85	SF	7	10+ years	
	Doors - Steel Doors incl hw	New in 116	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	New in 116	85	SF	7	10+ years	
	Floor Drain	New in 116	1	ĒΑ	7	10+ years	
	Lavatory	New in 116	1	EA	7	10+ years	
	Lighting - Lay-in	New in 116	1	ΕA	7	10+ years	
	Walls - Plaster/Drywall	New in 116	60	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	New in 116	80	SF	7	10+ years	
	Water Closet	New in 116	1	ĒΑ	7	10+ years	
	Accessories	Second floor staff	110	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Second floor staff	110	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Second floor staff	1	EA	7	10+ years	
	Floor - Tile	Second floor staff	110	SF	7	10+ years	
	Floor Drain	Second floor staff	1	EA	7	10+ years	
	Lavatory	Second floor staff	2	EA	7	10+ years	
	<i>,</i>	essona noor olan	_	_, .	•	10. 300.0	



Catego	ry : Room		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Pendent/Surface	Second floor staff	2	EA	7	10+ years				
	Partitions	Second floor staff	2	EA	7	10+ years				
	Walls - Plaster/Drywall	Second floor staff	220	SF	7	10+ years				
	Water Closet	Second floor staff	2	EA	7	10+ years				
	Accessories	West of front lobby	90	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	West of front lobby	90	SF	6	10+ years				
	Doors - Wood Doors inclu hw	West of front lobby	1	EA	7	10+ years				
	Floor - Tile Ceramic/ Porcelain	West of front lobby	90	SF	6	10+ years				
	Lavatory	West of front lobby	3	EA	7	10+ years				
	Lighting - Pendent/Surface	West of front lobby	3	EA	6	6-10 years				
	Partitions	West of front lobby	2	EA	5	10+ years				
	Walls - Plaster/Drywall	West of front lobby	175	SF	6	10+ years				
	Walls - Plaster/Drywall	West of front lobby	5	SF	5	1-2 years	Damaged wall			
	Water Closet	West of front lobby	2	EA	7	10+ years				
	Accessories	in Office 107 Principal Office	40	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	in Office 107 Principal Office	40	SF	6	10+ years				
	Doors - Wood Doors inclu hw	in Office 107 Principal Office	1	EA	7	10+ years				
	Floor - Tile	in Office 107 Principal Office	40	SF	6	10+ years				
	Lavatory	in Office 107 Principal Office	1	EA	7	10+ years				
	Lighting - Pendent/Surface	in Office 107 Principal Office	1	EA	6	6-10 years				
	Partitions	in Office 107 Principal Office	1	EA	7	10+ years				
	Walls - Plaster/Drywall	in Office 107 Principal Office	80	SF	6	10+ years				
	Water Closet	in Office 107 Principal Office	1	EA	7	10+ years				

Category : Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #104 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	94	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	982	SF	6	10+ years	
	Doors - Transom Window	1st Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	982	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EΑ	6	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,465	SF	6	10+ years	
Classroo	om #106 (Office)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,088	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,088	SF	6	10+ years	

Campus Name: Saucedo Page : 32 of 80 Assessment Date: 06/04/2024



Category : Classroom			В	Building : Main			O W Z-till BOOLE VAILD, Officago, IL 00023
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,570	SF	6	10+ years	
Classro	om #116 combined wi (Pre School)						
	AC Units	1st Floor	4	EA	7	6-10 years	
	Casework	1st Floor	56	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,291	SF	6	10+ years	
	Doors - Transom Window	1st Floor	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	ĒΑ	7	10+ years	
	Floor - Wood	1st Floor	1,291	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	ĒΑ	6	6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,392	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classro	om #119 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	680	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	680	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	12	EA	6	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,120	SF	6	10+ years	
Classro	om #123 (Pre School)						
Classici	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	7	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	673	SF	6	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood Doors Inclu TW	1st Floor	673	SF	6	10+ years	
				EA	_		
	Lighting - Pendent/Surface	1st Floor	12		6	6-10 years	
	Marker Board Walls - Plaster/Drywall	1st Floor 1st Floor	17 1,116	LF SF	7 6	6-10 years 10+ years	
Classic	om #10F (Kindorgorton)						
CidSSiO	om #125 (Kindergarten)	1ot Floor		Γ^	7	6.10	
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	680	SF	6	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	7	10+ years	

Campus Name: Saucedo Page : 33 of 80 Assessment Date: 06/04/2024



Category : Classroom		В	Building : Main			·		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	7	10+ years		
	Floor - Wood	1st Floor	680	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	12	EΑ	6	6-10 years		
	Marker Board	1st Floor	12	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,120	SF	6	10+ years		
Classroo	om #126 (Kindergarten)							
	AC Units	1st Floor	2	EΑ	7	6-10 years		
	Casework	1st Floor	12	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	1,354	SF	6	10+ years		
	Doors - Transom Window	1st Floor	20	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	20	EA	7	10+ years		
	Floor - Wood	1st Floor	1,354	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	1,354	EA	6	6-10 years		
	Marker Board	1st Floor	10	LF	7			
				SF		6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,731		6	10+ years		
	Work Sink	1st Floor	1	EA	7	10+ years		
Classro	om #127 (Kindergarten)							
	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	7	LF	7	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	673	SF	6	10+ years		
	Doors - Transom Window	1st Floor	9	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years		
	Floor - Wood	1st Floor	673	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	12	EΑ	6	6-10 years		
	Marker Board	1st Floor	16	LF	7	6-10 years		
	Walls - Plaster/Drywall	1st Floor	1,116	SF	6	10+ years		
Classro	om #130 (Pre School)							
Sidooro	AC Units	1st Floor	2	EA	7	6-10 years		
	Casework	1st Floor	10	LF	7	10+ years		
	Casework Ceiling - Lay-in	1st Floor	1,644	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	1,044	EA	7	10+ years		
				SF				
	Floor - Tile	1st Floor	1,644		6	6-10 years		
	Lighting - Lay-in	1st Floor	18	EA	6	6-10 years		
	Storage/ Closet	1st Floor	430	SF	7	10+ years		
	Walls - Plaster/Drywall Work Sink	1st Floor 1st Floor	1,227 2	SF EA	6 7	10+ years 10+ years		
						,		
Classro	om #133 (Store Room)							
	Ceiling - Exposed	1st Floor	1,885	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years		
						-		



Category : Classroom			В	Building : Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Concrete	1st Floor	1,885	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	32	EA	6	6-10 years	
	Storage/ Closet	1st Floor	275	SF	7	10+ years	
	Walls - Masonry	1st Floor	2,600	SF	6	10+ years	
Classroo	om #143 (Play Room)						
	Ceiling - Exposed	1st Floor	430	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,200	SF	6	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EΑ	7	10+ years	
	Floor - Tile	1st Floor	1,630	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	44	EA	6	6-10 years	
	Marker Board	1st Floor	6	LF	7	6-10 years	
	Walls - Masonry	1st Floor	2,770	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	230	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #144 (Kindergarten)						
	Casework	1st Floor	52	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	375	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	285	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,000	SF	6	10+ years	
	Doors - Side-lite	1st Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Tile	1st Floor	1,660	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	30	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Masonry	1st Floor	2,100	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	290	SF	6	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	10+ years	
Classroo	om #200 (Other Instructional Use)						
	AC Units	2nd Floor	3	EA	7	10+ years	
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,652	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	4	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	1,612	SF	7	10+ years	
	Floor - Tile	2nd Floor	40	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	2nd Floor	30	ĒΑ	7	10+ years	<u> </u>
	Storage/ Closet	2nd Floor	30	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,500	SF	7	10+ years	



Category : Classroom			Building : Ma				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-		Location	Quantity	UCIVI	Kalik	Replacement	Comments
Classroo	m #202 (Regular Classroom)	0 15				10	
	AC Units	2nd Floor	4	EA	7	10+ years	
	Casework	2nd Floor	44	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,247	SF	6	10+ years	
	Chalk Board	2nd Floor	5	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	1,222	SF	6	10+ years	
	Floor - Tile	2nd Floor	25	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	2nd Floor	36	EA	6	6-10 years	
	Storage/ Closet	2nd Floor	58	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,403	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	m #206 (Regular Classroom)						
	AC Units	2nd Floor	4	EA	7	6-10 years	
	Casework	2nd Floor	38	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,247	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,241	SF	6	6-10 years	
	Floor - Tile	2nd Floor	6	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	2nd Floor	30	EA	6	6-10 years	Damaged the
	Storage/ Closet	2nd Floor	58	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,410	SF	6	10+ years	
	Wireless System	2nd Floor	1,410	EA	7	6-10 years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	m #212 (Other Instructional Use)						
JIASSIUU	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor 2nd Floor	16	LF	7 7		
				SF		10+ years	
	Ceiling - Plaster/Drywall Doors - Transom Window	2nd Floor	673	SF SF	6	10+ years	
		2nd Floor	9		7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	17	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,059	SF	6	10+ years	
Classroo	m #213 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	21	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	6	10+ years	
	Chalk Board	2nd Floor	31	LF	4	2-5 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,146	SF	6	10+ years	
Classroo	om #214 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	6	10+ years	
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	-	
	Doors - Wood Doors inclu hw	2nd Floor 2nd Floor	1	SF EA	7	10+ years	
					=	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,189	SF	6	10+ years	
Classroo	om #215 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	6	10+ years	
	Chalk Board	2nd Floor	31	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,146	SF	6	10+ years	
Classroo	om #216 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Casework	2nd Floor	80	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	1,062	SF	6	10+ years	
	Chalk Board	2nd Floor 2nd Floor	20	SF LF	4		
	Doors - Wood Doors inclu hw		20	EA	7	2-5 years	
		2nd Floor				10+ years	
	Floor - Tile	2nd Floor	1,062	SF	6	10+ years	
	Gas Line	2nd Floor	10	EΑ	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,348	SF	6	10+ years	



Category : Classroom			В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Wireless System	2nd Floor	1	EA	7	6-10 years	
	Work Sink	2nd Floor	2	EA	7	6-10 years	
lassroc	m #217 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	6	10+ years	
	Chalk Board	2nd Floor	9	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	5	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
lassroo	m #219 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	680	SF	6	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	10	EA	7	10+ years	
	Floor - Wood	2nd Floor	680	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	11	EA	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	0-1 year	Not working
	Marker Board	2nd Floor	10	LF	7	6-10 years	Not Working
	Walls - Plaster/Drywall	2nd Floor	1,130	SF	6	10+ years	
lassroo	m #220 (Other Instructional Use)						
idooi oc	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	25	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	602	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	602	SF	6	6-10 years	
		2nd Floor 2nd Floor		EA	_		
	Lighting - Pendent/Surface Marker Board	2nd Floor 2nd Floor	16 10	LF	6 7	6-10 years	
						6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,131	SF	6	10+ years	
lassroc	m #221 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	6	10+ years	
	Chalk Board	2nd Floor	5	LF	4	2-5 years	

Campus Name: Saucedo Page : 38 of 80 Assessment Date: 06/04/2024



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years	
Classroo	om #223 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	680	SF	6	10+ years	
		2nd Floor		LF	4		
	Chalk Board		7			2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	680	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,116	SF	6	6-10 years	
Classroo	om #224 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	121	LF	7	10+ years	
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,062	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	1,062	SF	6	10+ years	
	Gas Line	2nd Floor		EA		-	
			1		7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	28	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,316	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #225 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	680	SF	6	10+ years	
	Chalk Board	2nd Floor	9	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	2nd Floor	680	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Maint Dualu	Z110 1 1001	10	ᆫ	1	u- iu yeais	

Campus Name: Saucedo Page : 39 of 80 Assessment Date: 06/04/2024



Catego	Category : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years			
Classro	om #226 (Regular Classroom)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	7	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	673	SF	6	10+ years			
	Chalk Board	2nd Floor	4	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Wood	2nd Floor	673	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years			
	Marker Board	2nd Floor	16	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,116	SF	6	10+ years			
_Classroo	om #227 (Regular Classroom)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	7	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	680	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Wood	2nd Floor	680	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years			
	Marker Board	2nd Floor	10	LF	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,120	SF	6	10+ years			
_Classroo	om #228 (Regular Classroom)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	42	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	779	SF	6	10+ years			
	Chalk Board	2nd Floor	8	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years			
	Floor - Tile	2nd Floor	779	SF	4	1-2 years	Damaged and cracked throughout		
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	Ç Ç		
	Marker Board	2nd Floor	10	LF	7	6-10 years			
	Storage/ Closet	2nd Floor	175	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,169	SF	6	10+ years			
Classroo	om #302 (Science Classroom)								
	AC Units	3rd Floor	2	EA	7	6-10 years			
	Casework	3rd Floor	_ 84	LF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	985	SF	6	10+ years			
	Chalk Board	3rd Floor	12	LF	4	2-5 years			
						•			



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	971	SF	6	6-10 years	
	Floor - Tile	3rd Floor	14	SF	4	1-2 years	Missing and cracked
	Gas Line	3rd Floor	1	EA	7	10+ years	•
	Lighting - Pendent/Surface	3rd Floor	28	EΑ	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,474	SF	6	10+ years	
	Work Sink	3rd Floor	3	EA	7	6-10 years	
Classroc	om #304 (Science Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	98	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	1,152	SF	6	10+ years	
	Chalk Board	3rd Floor	1,152	SF LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,122	SF	6	10+ years	
	Floor - Tile	3rd Floor	30	SF	4	1-2 years	Chipped and cracked
	Gas Line	3rd Floor	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	27	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,647	SF	6	10+ years	
	Work Sink	3rd Floor	3	EA	7	6-10 years	
`lassror	om #305 (Science Classroom)						
	AC Units	3rd Floor	3	EA	7	6-10 years	
	Casework	3rd Floor	87	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	1,027	SF			
				SF LF	5	10+ years	
	Chalk Board	3rd Floor	12		4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,012	SF	6	10+ years	
	Floor - Tile	3rd Floor	15	SF	4	1-2 years	Chipped
	Gas Line	3rd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	28	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,512	SF	6	10+ years	
	Work Sink	3rd Floor	3	EA	7	6-10 years	
lassroc	om #308 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	703	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF SF	7		
				_		10+ years	
	Doors - Wood Doors inclu hw Floor - Wood	3rd Floor 3rd Floor	1	EA SF	7	10+ years	
	1 100r 1//00d	2rd Floor	703	~L	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		•
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,267	SF	6	10+ years	
_Classroo	om #309 (Science Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	94	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,128	SF	6	10+ years	
	Chalk Board	3rd Floor	, 12	ĹF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,128	SF	6	10+ years	
	Gas Line	3rd Floor	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	27	EA	6	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,621	SF	6	10+ years	
	Work Sink	3rd Floor	3	EΑ	7	6-10 years	
Classroo	om #310 (Regular Classroom)						
Oldssion	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	703	SF	6	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	703	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,225	SF	6	10+ years	
Classroo	om #311 (Regular Classroom)						
_OIGSSI UC	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	703	SF	6	10+ years 10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	12	Sr EA	7	,	
	Doors - Wood Doors Inclu hw Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years 10+ years	
	Floor - Wood Doors Inclu nw	3rd Floor 3rd Floor	703	SF	6	10+ years 10+ years	
		3rd Floor 3rd Floor	14	SF EA	6	6-10 years	
	Lighting - Pendent/Surface Marker Board	3rd Floor		LF	6 7		
	Marker Board Walls - Plaster/Drywall	3rd Floor 3rd Floor	18 1,267	SF	<i>7</i> 6	6-10 years 10+ years	
Cla							
_Classroo	om #312 (Regular Classroom)	0.151					
	AC Units	3rd Floor	2	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor	441	SF	6	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	3	EA	7	10+ years	
	Floor - Wood	3rd Floor	441	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	8	EA	6	6-10 years	
	Marker Board	3rd Floor	6	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	990	SF	6	10+ years	
Classroo	om #313 (Art Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	_ 154	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,143	SF	6	10+ years	
	Chalk Board	3rd Floor	11	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile			SF	_	,	
	Floor - Tile Floor - Tile	3rd Floor	1,128	SF SF	6	6-10 years	Cracked
		3rd Floor	15		4	1-2 years	Cracked
	Lighting - Pendent/Surface	3rd Floor	27	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	22	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,138	SF	6	10+ years	
	Work Sink	3rd Floor	7	EA	7	6-10 years	
Classroo	om #314 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	683	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	663	SF	6	6-10 years	
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	3rd Floor	14	EA	6	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,225	SF	6	10+ years	
Classroc	om #315 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	703	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	703	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	30	SF	7		
	Walls - Plaster/Drywall	3rd Floor 3rd Floor	1,225	SF SF	<i>7</i> 6	10+ years 10+ years	



Category : Classroom		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #316 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	11	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	673	SF	5	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EΑ	7	10+ years	
	Floor - Wood	3rd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	29	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,199	SF	6	10+ years	
Classroo	om #317 (Regular Classroom)						
21400100	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	62	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,140	SF	6	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,120	SF	7	6-10 years	
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Chipped
						•	Chipped
	Lighting - Pendent/Surface Marker Board	3rd Floor 3rd Floor	18 14	EA LF	6 7	6-10 years 6-10 years	
	Walls - Plaster/Drywall			SF		•	
	vvalis - Plaster/Drywali	3rd Floor	1,589	SF	6	10+ years	
Classroo	om #318 (Regular Classroom)						
	AC Units	3rd Floor	2	EΑ	7	6-10 years	
	Casework	3rd Floor	21	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,015	SF	6	10+ years	
	Chalk Board	3rd Floor	3	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,015	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	6-10 years	
	Marker Board	3rd Floor	23	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,498	SF	6	10+ years	
Classroo	om #320 (Regular Classroom)						
CIASSIUC	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	18	LF		•	
				SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	673	SF LF	6	10+ years	
	Chalk Board	3rd Floor	4	LF SF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	5F	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		W 2401 BOOLE VAND, Officago, IE 00020
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,199	SF	6	10+ years	
Classroo	om #321 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	54	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,140	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,120	SF	6	6-10 years	
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	21	EA	6	6-10 years	• •
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,612	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
Classroo	om #322 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	19	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,015	SF	5	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	1,015	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	18	EA	6	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,498	SF	6	10+ years	
Classroo	om #323 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	500	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	500	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	11	EA	5	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	735	SF	6	10+ years	
Classroo	om #326 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	- 32	5.5. · .5 5 .	_	<u></u> ,	•	, oo o	



		Category : Classroom			: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	673	SF	5	10+ years	
	Chalk Board	3rd Floor	34	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	673	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	17	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,199	SF	6	10+ years	
Classroc	m #327 (Science Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	114	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,143	SF	6	10+ years	
	Chalk Board	3rd Floor	9	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,133	SF	6	6-10 years	
	Floor - Tile	3rd Floor	1,133	SF	4		Cracked
			_			1-2 years	Cracked
	Lighting - Pendent/Surface	3rd Floor	19	EA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	45	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,686	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	6-10 years	
lassroc	m #328 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	5	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,279	SF	6	10+ years	
lassroc	m #329 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	23	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	720	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		, 3,
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,275	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	4	SF	5	1-2 years	Hole
Classroo	om #331 (Store Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	648	SF	5	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	648	SF	5	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,171	SF	6	10+ years	
Classroo	om #332 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	109	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,322	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,312	SF	6	6-10 years	
	Floor - Tile	3rd Floor	10	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	3rd Floor	35	EA	6	6-10 years	
	Marker Board	3rd Floor	9	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	22	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,931	SF	6	10+ years	
Classroo	om #333 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	970	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	970	SF	5	10+ years	
	Lighting - Pendent/Surface	3rd Floor	20	EA	6	6-10 years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	56	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,506	SF	6	10+ years	
Classroo	om #334 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	96	LF	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	3rd Floor	1,354	SF	6	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,334	SF	6	10+ years	
	Floor - Tile	3rd Floor	20	SF	4	1-2 years	Chipped
	Lighting - Lay-in	3rd Floor	5	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	29	EA	6	6-10 years	
	Storage/ Closet	3rd Floor	22	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,945	SF	6	10+ years	
Classroo	om #335 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	37	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,026	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,004	SF	6	6-10 years	
	Floor - Tile	3rd Floor	1,004	SF	4	1-2 years	Chipped
		3rd Floor	30	EA	6	•	Chipped
	Lighting - Pendent/Surface				7	6-10 years	
	Marker Board	3rd Floor	12	LF		6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,506	SF	6	10+ years	
Classroc	om #336 (Regular Classroom)						
	AC Units	3rd Floor	3	EA	7	6-10 years	
	Casework	3rd Floor	37	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,026	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	1,021	SF	6	6-10 years	
	Floor - Tile	3rd Floor	5	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	3rd Floor	30	ĒΑ	6	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,506	SF	6	10+ years	
Classroo	om #337 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	704	SF	6	10+ years	
	Chalk Board	3rd Floor	18	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	704	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	Sr EA	6	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,215	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	4	1-2 years	Water damage
Classroo	om #338 (Special Program)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	4	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	360	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	360	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	6	EA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	929	SF	6	10+ years	
Classroo	om #339 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	5	10+ years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	667	SF	6	6-10 years	
	Floor - Tile	3rd Floor	5	SF	4	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	omprou
	Marker Board	3rd Floor	15	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
Classroo	om #340 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	10+ years	
	Chalk Board	3rd Floor	3	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	672	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	19	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
Classroo	om #341 (Regular Classroom)						
Diagonor	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	672	SF	5	10+ years	
	John J. Hactor, Dry Wall	014 1 1001	312	0.	J	ioi youis	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chalk Board	3rd Floor	27	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	672	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EΑ	6	6-10 years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
Classro	om #342 (Regular Classroom)						
Ciassiu	AC Units	3rd Floor	2	EA	7	6-10 years	
		3rd Floor		LF			
	Casework		7		7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	672	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
Classroo	om #343 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	10+ years	
	Chalk Board	3rd Floor	29	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	672	SF	5	10+ years	
		3rd Floor	12	EA	6	6-10 years	
	Lighting - Pendent/Surface			LF		•	
	Marker Board	3rd Floor	8	SF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
Classroo	om #344 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	672	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
	vvalio - r laolol/Di y wali	310 1 1001	1,191	01	U	TOT years	



Category : Classroom			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #346 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	672	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	70	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	672	SF	5	10+ years	
	Lighting - Pendent/Surface	3rd Floor	12	EA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,191	SF	6	10+ years	
Classroo	om #400 (Band Room)						
	Casework	4th Floor	16	LF	7	10+ years	
	Ceiling - Lay-in	4th Floor	2,400	SF	6	10+ years	
	Chalk Board	4th Floor	22	LF	4	2-5 years	
	Doors - Steel Doors incl hw	4th Floor	2	EΑ	7	10+ years	
	Floor - Wood	4th Floor	2,400	SF	6	10+ years	
	Instrument Storage Casework	4th Floor	16	LF	7	10+ years	
	Lighting - Lay-in	4th Floor	36	EA	6	6-10 years	
	Marker Board	4th Floor	22	LF	7	6-10 years	
	Storage/ Closet	4th Floor	28	SF	7	10+ years	
	Storage/ Closet	4th Floor	53	SF	7	10+ years	
	Storage/ Closet	4th Floor	53	SF	7	10+ years	
	Storage/ Closet	4th Floor	28	SF	5	10+ years	
	Walls - Plaster/Drywall	4th Floor	2,986	SF	6	10+ years	

Category : Interior Building: Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	item - Type	Location	Quantity	OCIVI	Naiik	Replacement	Comments
Corridor	0.111						
	Ceiling - Plaster/Drywall	1st Flr BOH (next to 133)	450	SF	6	10+ years	
	Doors - Wood Doors include hw	1st FIr BOH (next to 133)	2	EΑ	7	10+ years	
	Floor - Concrete	1st FIr BOH (next to 133)	450	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Flr BOH (next to 133)	6	EΑ	6	6-10 years	
	Walls - Plaster/Drywall	1st Flr BOH (next to 133)	900	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Flr between Gym + Locker	133	SF	6	10+ years	
	g ,	Room				,	
	Doors - Wood Doors include hw	1st Flr between Gym + Locker	2	EΑ	7	10+ years	
	20010 11000 20010 11101000 1111	Room	_	_, ,	•	. o . y ca. c	
	Floor - Tile/Sheet	1st Flr between Gym + Locker	133	SF	7	10+ years	
	11001 1110/011000	Room	100	O 1	,	ioi youis	
	Lighting Dondont/Surface		2	EA	6	6 10 years	
	Lighting - Pendent/Surface	1st Flr between Gym + Locker	2	EΑ	6	6-10 years	



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Room					
	Student Lockers - One Tier	1st Flr between Gym + Locker	50	EA	6	10+ years	
		Room					
	Walls - Plaster/Drywall	1st Flr between Gym + Locker	450	SF	6	10+ years	
		Room					
	Ceiling - Exposed	1st Flr to Class 130 (each side)	132	SF	6	10+ years	
	Doors - Transom Window	1st FIr to Class 130 (each side)	14	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Flr to Class 130 (each side)	4	EA	7	10+ years	
	Floor - Concrete	1st Flr to Class 130 (each side)	69	SF	7	10+ years	
	Floor - Tile/Sheet	1st Flr to Class 130 (each side)	63	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Flr to Class 130 (each side)	3	EA	6	6-10 years	
	Stairs - Concrete Stairs	1st Flr to Class 130 (each side)	60	LF	7	10+ years	
	Walls - Masonry	1st Flr to Class 130 (each side)	388	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Flr @ Kitchen "Passage"	219	SF	6	10+ years	
	Doors - Wood Doors include hw	2nd Flr @ Kitchen "Passage"	1	EA	7	10+ years	
	Floor - Concrete	2nd Flr @ Kitchen "Passage"	219	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Flr @ Kitchen "Passage"	3	EA	6	6-10 years	
	Walls - Metal Panel	2nd Flr @ Kitchen "Passage"	315	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Flr @ Kitchen "Passage"	715	SF	6	10+ years	
	Ceiling - Exposed	First Floor Corridors	1,600	SF	6	10+ years	
	Ceiling - Plaster/Drywall	First Floor Corridors	19,241	SF	6	10+ years	
	Doors - Steel Doors incl hw	First Floor Corridors	3	EΑ	7	10+ years	
	Doors - Transom Window	First Floor Corridors	72	SF	7	10+ years	
	Doors - Wood Doors include hw	First Floor Corridors	8	EΑ	7	10+ years	
	Drinking Fountains - Single Fountain	First Floor Corridors	12	EA	7	6-10 years	
	Floor - Terrazzo	First Floor Corridors	4,731	SF	7	10+ years	
	Floor - Terrazzo	First Floor Corridors	10	SF	4	1-2 years	Floor sinking
	Floor - Tile/Sheet	First Floor Corridors	16,100	SF	7	10+ years	•
	Lighting - Pendent/Surface	First Floor Corridors	200	EA	6	6-10 years	
	Student Lockers - One Tier	First Floor Corridors	745	EA	7	10+ years	
	Walls - Plaster/Drywall	First Floor Corridors	25,635	SF	6	10+ years	
	Ceiling - Plaster/Drywall	First Floor Main Entry Vestibule	260	SF	6	10+ years	
	Doors - Transom Window	First Floor Main Entry Vestibule	81	SF	7	10+ years	
	Doors - Wood Doors include hw	First Floor Main Entry Vestibule	9	EA	7	10+ years	
	Floor - Terrazzo	First Floor Main Entry Vestibule	200	SF	7	10+ years	
	Floor - Tile/Sheet	First Floor Main Entry Vestibule	60	SF	7	10+ years	
	Lighting - Pendent/Surface	First Floor Main Entry Vestibule	6	EA	6	6-10 years	
	Walls - Plaster/Drywall	First Floor Main Entry Vestibule	390	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Second Floor Corridors	10,464	SF	6	10+ years	
	Doors - Transom Window	Second Floor Corridors	72	SF	7	10+ years	
	Doors - Wood Doors include hw	Second Floor Corridors	8	EA	7	10+ years	
	Drinking Fountains - Single Fountain	Second Floor Corridors	4	EΑ	7	6-10 years	
	Floor - Tile/Sheet	Second Floor Corridors	10,464	SF	7	10+ years	
	Lighting - Pendent/Surface	Second Floor Corridors	119	EA	6	6-10 years	
			710	_, .	Ü	3 10 ,0010	



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	Second Floor Corridors	551	EA	7	10+ years	
	Walls - Plaster/Drywall	Second Floor Corridors	16,999	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Third Floor Corridors	12,163	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Third Floor Corridors	25	SF	5	0-1 year	Water damage
	Doors - Wood Doors include hw	Third Floor Corridors	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	Third Floor Corridors	4	EA	7	6-10 years	
	Floor - Tile/Sheet	Third Floor Corridors	3,456	SF	7	10+ years	
	Floor - Tile/Sheet	Third Floor Corridors	8,732	SF	7	10+ years	
	Lighting - Pendent/Surface	Third Floor Corridors	158	EA	6	6-10 years	
	Student Lockers - One Tier	Third Floor Corridors	647	EA	7	10+ years	
	Student Lockers - One Tier	Third Floor Corridors	1	EA	5	1-2 years	
	Walls - Plaster/Drywall	Third Floor Corridors	21,251	SF	6	10+ years	
Safety							
-	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Security Cameras	Entire Building	2	EA	7	6-10 years	
	Security Cameras	Entire Building	11	EA	7	6-10 years	
	Security Cameras	Entire Building	3	EA	7	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	Girls Gym - NE Stairway	350	SF	6	10+ years	
	Floor - Terrazzo	Girls Gym - NE Stairway	375	SF	6	10+ years	
	Handrails	Girls Gym - NE Stairway	64	LF	7	10+ years	
	Lighting - Pendent/Surface	Girls Gym - NE Stairway	3	EA	6	6-10 years	
	Lighting - Wall Mounted	Girls Gym - NE Stairway	1	EA	6	6-10 years	
	Stairs - Terrazzo	Girls Gym - NE Stairway	128	LF	6	10+ years	
	Walls - Plaster/Drywall	Girls Gym - NE Stairway	687	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Girls gym-SW	270	SF	6	10+ years	
	Floor - Terrazzo	Girls gym-SW	210	SF	6	10+ years	
	Handrails	Girls gym-SW	64	LF	7	10+ years	
	Lighting - Pendent/Surface	Girls gym-SW	3	EA	6	6-10 years	
	Lighting - Wall Mounted	Girls gym-SW	1	EA	6	6-10 years	
	Stairs - Terrazzo	Girls gym-SW	149	LF	6	10+ years	
	Walls - Plaster/Drywall	Girls gym-SW	595	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Main Entry Stairs (East)	756	SF	6	10+ years	
	Floor - Asphalt	Main Entry Stairs (East)	54	SF	6	10+ years	
	Floor - Tile	Main Entry Stairs (East)	547	SF	6	10+ years	
	Handrails	Main Entry Stairs (East)	581	LF	7	10+ years	
	Lighting - Pendent/Surface	Main Entry Stairs (East)	8	ĒΑ	6	6-10 years	
	Lighting - Wall Mounted	Main Entry Stairs (East)	4	EΑ	6	6-10 years	
	Stairs - Asphalt	Main Entry Stairs (East)	448	LF	6	10+ years	
	Walls - Plaster/Drywall	Main Entry Stairs (East)	2,216	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Main Entry Stairs (West)	756	SF	6	10+ years	
	Floor - Asphalt	Main Entry Stairs (West)	54	SF	6	10+ years	
						•	

Campus Name: Saucedo Page : 53 of 80 Assessment Date: 06/04/2024



Catego	ry : Interior		В	uilding	: Main		-
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Main Entry Stairs (West)	547	SF	6	10+ years	
	Handrails	Main Entry Stairs (West)	581	LF	7	10+ years	
	Lighting - Pendent/Surface	Main Entry Stairs (West)	8	EA	6	6-10 years	
	Lighting - Wall Mounted	Main Entry Stairs (West)	5	EA	6	6-10 years	
	Stairs - Asphalt	Main Entry Stairs (West)	448	LF	6	10+ years	
	Walls - Plaster/Drywall	Main Entry Stairs (West)	2,216	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Northeast Stairwell	728	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Northeast Stairwell	140	SF	7	10+ years	
	Floor - Tile	Northeast Stairwell	672	SF	6	10+ years	
	Handrails	Northeast Stairwell	175	LF	7	10+ years	
	Lighting - Pendent/Surface	Northeast Stairwell	6	EΑ	6	6-10 years	
	Lighting - Wall Mounted	Northeast Stairwell	5	EΑ	6	6-10 years	
	Stairs - Asphalt	Northeast Stairwell	429	LF	6	10+ years	
	Walls - Plaster/Drywall	Northeast Stairwell	2,666	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Northwest Stairwell	728	SF	6	10+ years	
	Floor - Concrete Epoxy/ Painted	Northwest Stairwell	140	SF	7	10+ years	
	Floor - Tile	Northwest Stairwell	672	SF	6	10+ years	
	Handrails	Northwest Stairwell	175	LF	7	10+ years	
	Lighting - Pendent/Surface	Northwest Stairwell	6	EA	6	6-10 years	
	Lighting - Wall Mounted	Northwest Stairwell	5	EA	6	6-10 years	
	Stairs - Asphalt	Northwest Stairwell	429	LF	6	10+ years	
	Walls - Metal Panel	Northwest Stairwell	80	SF	6	10+ years	
	Walls - Plaster/Drywall	Northwest Stairwell	2,266	SF	6	10+ years	
	Ceiling - Exposed	South East	2,200 875	SF	6	10+ years	
	Ceiling - Exposed Ceiling - Plaster/Drywall	South East	800	SF	6		
	Floor - Concrete Epoxy/ Painted	South East	340	SF	7	10+ years	
	Floor - Tile	South East	16	SF	6	10+ years 10+ years	
	Floor - Tile	South East	900	SF	6	10+ years	
	Handrails	South East	286	LF	7	,	
			200 144	LF LF		10+ years	
	Handrails Lighting - Wall Mounted	South East	144	EA	5	6-10 years	
		South East	560	LF	6	6-10 years	
	Stairs - Asphalt	South East		LF LF	6	10+ years	
	Stairs - Concrete	South East	50		7	10+ years	
	Walls - Plaster/Drywall	South Mont	1,800	SF	6	10+ years	
	Ceiling - Exposed	South West	875	SF SF	6	10+ years	
	Ceiling - Plaster/Drywall	South West	800		6	10+ years	
	Floor - Concrete Epoxy/ Painted	South West	340	SF	7	10+ years	
	Floor - Tile	South West	116	SF	6	10+ years	
	Floor - Tile	South West	800	SF	6	10+ years	
	Handrails	South West	286	LF	7	10+ years	
	Handrails	South West	144	LF	5	6-10 years	
	Lighting - Wall Mounted	South West	14	EA	6	6-10 years	
	Stairs - Asphalt	South West	560	LF	6	10+ years	
	Stairs - Concrete	South West	50	LF	7	10+ years	



Catego	ry : Interior		В				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Walls - Plaster/Drywall	South West	1,800	SF	6	10+ years	
_Vertical (Convevance						
	Elevator - Freight Elevator	1st to 3rd floors	1	EA	6	10+ years	

Campus Name: Saucedo Page : 55 of 80 Assessment Date: 06/04/2024





Category : Exterior **Building: Addition (Telpochcalli)**

gory : Exterior		Recommend						
p Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
nce								
Exterior Doors - Overhead Rolling/ Garage	10 - OVH	1	EA	7	10+ years			
Door	10 - 0 111	1	LA	,	10+ years			
Exterior Stairs - Concrete	10 - OVH	16	LF	5	2-5 years			
Exterior Doors - Exterior Steel Door	11 north	1	EA	7	10+ years			
Exterior Stairs - Concrete	11 north	12	LF	7	10+ years	Replaced		
Exterior Doors - Exterior Steel Door	12 south	3	EA	6	10+ years	rtopiacou		
Exterior Doors - Transom Lite	12 south	3	EA	6	10+ years			
Exterior Stairs - Concrete	12 south	8	LF	7	10+ years			
Exterior Stairs - Concrete	12 south	1	LF	4	0-1 year	Cracked, missing		
Exterior Doors - Exterior Steel Door	12.5 FE	1	ĒΑ	6	6-10 years	eveneus, meening		
Exterior Doors - Transom Lite	12.5 FE	1	ĒΑ	6	10+ years			
Exterior Stairs - Concrete	12.5 FE	3	LF	6	10+ years			
Entrance Control - Audio and Video	13 south	1	ĒΑ	6	10+ years			
Exterior Doors - Exterior Steel Door	13 south	2	ΕA	6	10+ years			
Exterior Doors - Side lite	13 south	<u></u>	ĒΑ	6	10+ years			
Exterior Doors - Transom Lite	13 south	1	EΑ	6	10+ years			
Exterior Stairs - Concrete	13 south	7	LF	7	10+ years			
Exterior Stairs - Concrete	13 south	2	LF	4	0-1 year	Cracked		
Entrance Control - Audio and Video	14 south	1	ĒΑ	6	6-10 years			
Exterior Doors - Exterior Steel Door	14 south	2	EΑ	6	10+ years			
Exterior Doors - Side lite	14 south	2	EΑ	6	10+ years			
Exterior Doors - Transom Lite	14 south	3	EΑ	6	10+ years			
Exterior Doors - Exterior Steel Door	7 north	3	EΑ	6	10+ years			
Exterior Doors - Transom Lite	7 north	3	EA	6	10+ years			
Exterior Stairs - Concrete	7 north	21	LF	6	10+ years			
Exterior Doors - Exterior Steel Door	8 - N	3	EA	6	10+ years			
Exterior Stairs - Concrete	8 - N	16	LF	6	10+ years			
Exterior Stairs - Concrete	8 - N	2	LF	4	0-1 year	Chipped		
Exterior Doors - Overhead Rolling/ Garage	9 - OVH	1	EA	6	10+ years			
Door					•			
Ramps - Concrete	9 - OVH	6	LF	7	10+ years			
cape								
Exterior Doors - Exterior Steel Door	South Façade	1	EA	6	10+ years			
Exterior Doors - Transom Lite	South Façade	1	EA	6	10+ years			
Fire Escape	South Façade	50	LF	5	2-5 years			
Paints	South Façade	50	LF	5	2-5 years			
		00	 -	J	_ 0 ,00.0			
ation								
Foundation - Concrete	Entire Building	775	LF	7	10+ years			
Superstructure - Concrete	Entire Building	40,822	SF	7	10+ years			

Campus Name: Saucedo Page : 56 of 80 Assessment Date: 06/04/2024



Categor	y : Exterior		В	Building : Addition (Telpochcalli)						
						Recommend				
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
abtina										
ghting_	Exterior Lighting - Wall Mounted	Entire Building	7	EA	7	10+ years				
	Extends Eighting Train Mounted	Littii o Dananig	•	_, ,	•	ioi youro				
oof Syst	em									
	Access Ladder - Metal	P - Main	1	EA	4	0-1 year	Over 20 feet without cage			
	Access Ladder - Metal	P - Main	1	EA	3	0-1 year	Not used			
	Chimney - Brick Chimney- Concrete/ Mortar	P - Main	80	LF	7	10+ years				
	Liner					, , , , , , , , , , , , , , , , , , , ,				
	Chimney - Metal Flue	P - Main	24	LF	6	10+ years				
	Coping - Stone	P - Main	938	LF	7	10+ years				
	Downspouts - Interior Downspouts	P - Main	200	LF	7	10+ years				
	Parapet - 16" - 30" Height	P - Main	262	LF	7	10+ years				
	Parapet - Parapet > 30"	P - Main	676	LF	7	10+ years				
	Roof - Modified Bitumen	P - Main	20,411	SF	6	10+ years				
	Roof Hatch - Metal	P - Main	2	EA	4	0-1 year	Corroded, difficult to open			
	Roof Structure - Concrete	P - Main	20,411	SF	7	10+ years				
alls										
<u>uno</u>	Cornice - Cast Stone	Entire Building	938	LF	7	10+ years				
	Exterior Walls - Brick	Entire Building	10,677	SF	7	10+ years				
	Exterior Walls - Brick	Entire Building	30	SF	4	0-1 year	Cracks, displacement			
	Exterior Walls - Stone-Cast	Entire Building	7,655	SF	7	10+ years	Oracks, displacement			
		· ·		SF			Chinned areals			
	Exterior Walls - Stone-Cast	Entire Building	5		4	0-1 year	Chipped, cracks			
	Exterior Walls - Stucco	Entire Building	180	SF	7	10+ years				
indows										
	Guard - Guards perforated	Entire Building	2,970	SF	6	10+ years				
	Lintels - Steel	Entire Building	759	LF	6	10+ years				
	Windows - Louver	Entire Building	108	SF	6	10+ years				
	Windows - Sash Aluminum Double-pane	Entire Building	10,530	SF	6	10+ years				
ategor	y : Electrical		В	uildina	· Additio	on (Telpochcal	li)			
ulogo.	y . <u> </u>		_	u	. , (Recommend	,			
	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
mergeno	cy System									
	Exit Signs - Corridors and Stairs	Entire Building	17	EA	6	6-10 years	Quantity changed as total has bee divided/aggregated.			
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years				
	Security System - CCTV	Entire Building	40,822	SF	5	6-10 years				
		Entire Building	40,822	SF	6	6-10 years				
	Security System - Intrusion Detection Emergency A/C Power - Corridors and	Entire Building	8,141	SF	6	10+ years				

Campus Name: Saucedo Page : 57 of 80 Assessment Date: 06/04/2024



Maria Saucedo STEAM Magnet Academy

Catego	ry : Electrical		Building : Addition (Telpochcalli)						
.	Ham. Toma	Lacation	O. antitu	ПОМ	Donk	Recommend	Community		
Froup	Item - Type Stairs	Location	Quantity	UOM	Rank	Replacement	Comments		
	Emergency A/C Power - Students Toilets	Entire Building	955	SF	6	10+ years			
		·				•			
∕lain Se	rvice								
	PA System	Entire Building	40,822	SF	7	6-10 years	Serves Addition. Rank changed as new system was installed since previous assessment.		
Power D	istribution								
	Lighting and Power Panels - 100 A	Entire Building	10	EA	7	10+ years	Quantity changed based on current observations. Some panels secured shut for security purposes with condition verified by Building Engineer.		
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	6-10 years	Quantity changed as total has been divided/aggregated. Location changed for clarification.		
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	2	0-1 year	Vintage live front fuse panel with damaged door latch.		
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Quantity changed as total has been divided/aggregated. Location changed for clarification.		
:ateno	ry : Fire Protection		R	uildina	· Additio	on (Telpochcal	lli)		
Julogo				unung	. Additi	Recommend	,		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
ire Alar	m								
	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	40,822 40,822	SF SF	7 7	10+ years 10+ years	FACP is in Main. Rank, Reason an Priority Rep adjusted as the system was replaced since previous assessment.		
Catego	ry : Mechanical		В	uilding	: Additio	on (Telpochcal	lli)		
.	Ham. Toma	Lacation	O. antitu	ПОМ	Donk	Recommend	Community		
Froup Air Cond	Item - Type litioning	Location	Quantity	UOM	Rank	Replacement	Comments		
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years			
	Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years			



Catego	ry : Mechanical		Building : Addition (Telpochcalli)							
			•			Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
Air Hand	ling Systems									
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	1	EA	6	6-10 years	CPS Asset Tag not safely accessible due to height.			
	Fan Coil Unit- Celing Mounted - Electric	Entire Building	1	EA	6	6-10 years	CPS Asset Tag not safely accessible due to height.			
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Mezzanine - AHU-10	1	EA	5	6-10 years	AHU-10, serves Rooms 254-260.			
	Air Intake	Mezzanine - AHU-10	1	EA	6	6-10 years	Manual adjustment required in the absence of a functional temperature control system system.			
	Auxiliaries - 8001 - 15000 cfm	Mezzanine - AHU-10	1	EΑ	6	6-10 years	•			
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mezzanine - AHU-10	100	LF	6	10+ years				
	Zone Dampers	Mezzanine - AHU-10	7	EA	5	6-10 years	Manual adjustment required in the absence of a functional temperature control system system.			
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Mezzanine - AHU-8	1	EA	5	6-10 years	AHU-8, serves Rooms 151, 251, 152, 252, 162 and 262. No CPS Asset Tag present.			
	Air Intake	Mezzanine - AHU-8	1	EA	6	6-10 years	Manual adjustment required in the absence of a functional temperature control system system.			
	Auxiliaries - 8001 - 15000 cfm	Mezzanine - AHU-8	1	EA	6	6-10 years				
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mezzanine - AHU-8	100	LF	6	10+ years				
	Zone Dampers	Mezzanine - AHU-8	6	EA	5	6-10 years	Manual adjustment required in the absence of a functional temperature control system system.			
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 8001 - 15000 cfm	Mezzanine - AHU-9	1	EA	5	6-10 years	AHU-9, serves Rooms 154, 155A, 155B, 159, 253, 262 and 264.			
	Air Intake	Mezzanine - AHU-9	1	EA	6	6-10 years	Manual adjustment required in the absence of a functional temperature control system system.			
	Auxiliaries - 8001 - 15000 cfm	Mezzanine - AHU-9	1	EA	6	6-10 years				
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mezzanine - AHU-9	100	LF	6	10+ years				
	Zone Dampers	Mezzanine - AHU-9	7	EA	5	6-10 years	Manual adjustment required in the absence of a functional temperature control system system.			
Boiler S	stems									
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - Greater than 300 HP	Boiler Room	2	EA	5	6-10 years	B-2 and B-3			
	Boiler Auxiliary- Scotch Marine- Steam Low	Boiler Room	1	EA	3	0-1 year	B-1, out of service			

Campus Name: Saucedo Page : 59 of 80 Assessment Date: 06/04/2024



Catego	Category : Mechanical				Building : Addition (Telpochcalli) Recommend					
			0	•						
Group	Item - Type Pressure Boiler - Greater than 300 HP	Location	Quantity	UOM	Rank	Replacement	Comments			
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years				
	Combustion Dampers	Boiler Room	3	EA	6	6-10 years				
	Feed Water Pumps and Tank	Boiler Room	1	EΑ	4	1-2 years	System is operational but B-1 pumps			
	·					·	are generally not functional. Significant corrosion noted on fluid-handling components.			
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Greater than 300 HP	Boiler Room	1	EA	6	10+ years	B-3			
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Greater than 300 HP	Boiler Room	1	EA	6	10+ years	B-2			
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - Greater than 300 HP	Boiler Room	1	EA	2	0-1 year	B-1. Nonfunctional and out of service for approximately 10 years pending approval of repairs.			
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	6	6-10 years	Leak-free system at the time of assessment. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that faulty piping has been replaced since previous assessment.			
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	4	2-5 years	Reason and Priority Rep changed to reflect that the piping is vintage material and is approaching the end of its anticipated service life. Rank adjusted based on current observations and per review with Building Engineer that repairs to the system since previous assessment presents a leak-free condition.			
	Steam Traps	Boiler Room	25	EA	5	6-10 years	procents a loak not containen.			
Lloatic -	Vacuum Pump	Boiler Room	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer that repairs have been completed since previous assessment.			
Heating	Devices Fin Tube - Electric	1st Floor	48	LF	6	6-10 years	Located in office spaces and			
	i iii i ube - Electric	13(1100)	40	LF	O	o- io yeais	classrooms. Quantity changed to match current observations.			

Page : 60 of 80 Campus Name: Saucedo Assessment Date: 06/04/2024



Catego	ry : Mechanical	Building : Addition (Telpochcalli)						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Radiators - Steam	Entire Building	7	EA	5	6-10 years		
	Unit Heater - Gas	Entire Building	1	EΑ	6	6-10 years		
	Wall Heater - Electric	Entire Building	1	EA	6	6-10 years		
	Wall Heater - Electric	Entire Building	1	EA	6	6-10 years		
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years	Misidentified in previous assessment. Older equipment that is fully intact and operational. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer.	
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.	
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years	Rank, Reason and Priority Rep changed based on current observations that all covers are in place at the time of assessment.	
	Wall Heater - Electric	Entire Building	1	EΑ	6	6-10 years		
	Wall Heater - Electric	Entire Building	1	EA	6	6-10 years	Misidentified in previous assessment. Older equipment that is fully intact and operational. Rank, Reason and Priority Rep changed based on current observations and per review with Building Engineer.	
	Wall Heater - Electric	Entire Building	1	EA	5	0-1 year	Missing cover exposes moving parts and heat-producing parts presenting a risk of personal injury and exposes live electrical conductors presenting a live front condition.	
	Wall Heater - Electric	Entire Building	2	EA	4	0-1 year	Missing covers expose moving parts and heat-producing parts presenting a risk of personal injury.	
_Tempera	ature Control							
	Electric Thermostat	Entire Building	2	EA	7	6-10 years		
	Electric Thermostat	Entire Building	1	EA	7	6-10 years		
	Electric Thermostat	Entire Building	1	EΑ	6	6-10 years		
	Pneumatic System	Entire Building	40,722	SF	3	0-1 year	Serves Main and Addition. System is failed and inoperable. Temperatures in all spaces throughout the building are manually controlled by the Building Engineer.	
	Thermostats - Pneumatic	Entire Building	23	EA	4	0-1 year	Thermostats are inoperative, contaminated with oil, and irreparable.	

Campus Name: Saucedo Page : 61 of 80 Assessment Date: 06/04/2024



Category : Mechanical

Maria Saucedo STEAM Magnet Academy 2850 W 24th BOULEVARD, Chicago, IL 60623

2850 W 24th BOULEVARD, Chicago, IL 60623 **Building : Addition (Telpochcalli)**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Ventilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building Entire Building	1	EA EA	6 6	6-10 years 6-10 years	
Catego	ry : Plumbing		В	uilding	: Additio	on (Telpochcal	li)
0	Wa T	Laartian	0	HOM	D I.	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	Gas Heater - Greater than 600000 BTU/HR	Boiler Room	1	EA	6	10+ years	
	Gas Heater - Greater than 600000 BTU/HR	Boiler Room	1	EA	6	10+ years	
	Hot Water Storage Tank_Gas - 501 - 1000 Gallons	Boiler Room	2	EA	5	6-10 years	
_Piping							
Fiping	Domestic Piping-Hot Water Return Lines	Entire Building	40,822	SF	4	2-5 years	Leak-free at the time of assessment. Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end
	Domestic Piping-Hot Water Return Risers	Entire Building	40,822	SF	4	2-5 years	of its anticipated service life. Leak-free at the time of assessment. Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	40,822	SF	4	2-5 years	of its anticipated service life. Leak-free at the time of assessment. Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	40,822	SF	4	2-5 years	of its anticipated service life. Leak-free at the time of assessment. Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	40,822	SF	4	2-5 years	of its anticipated service life. Leak-free at the time of assessment. Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	40,822	SF	4	2-5 years	of its anticipated service life. Leak-free at the time of assessment. Reason and Priority Rep adjusted to

Campus Name: Saucedo Page : 62 of 80 Assessment Date: 06/04/2024



Catego	ry : Plumbing	В	Building : Addition (Telpochcalli)					
	,				Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Sanitary Piping	Entire Building	40,822	SF	5	2-5 years	reflect that most piping is original to the building and has reached the end of its anticipated service life. Leak-free at the time of assessment. Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end	
	Storm Piping	Entire Building	40,822	SF	5	2-5 years	of its anticipated service life. Leak-free at the time of assessment. Reason and Priority Rep adjusted to reflect that most piping is original to	
	Vent Piping	Entire Building	40,822	SF	5	2-5 years	the building and has reached the end of its anticipated service life. Reason and Priority Rep adjusted to reflect that most piping is original to the building and has reached the end of its anticipated service life.	
Pumps								
·	Pumps - Domestic Booster Pump-Duplex	Boiler Room	1	EA	4	2-5 years	Serves Addition and Main. Fully operational and well maintained, although noisy; Reason and Priority Rep changed to document current observations of corrosion and past leaks that the equipment has reached the end of its anticipated service life.	

Category : Room **Building: Addition (Telpochcalli)**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	Ceiling - Splined	159- Office	347	SF	6	10+ years	
	Doors - Wood Doors inclu hw	159- Office	2	EA	7	10+ years	
	Floor - Tile	159- Office	347	SF	6	10+ years	
	Lighting - Pendent/Surface	159- Office	6	EA	6	6-10 years	
	Power Distribution	159- Office	2	EA	7	10+ years	
	Storage/ Closet	159- Office	44	SF	7	10+ years	
	Walls - Plaster/Drywall	159- Office	716	SF	6	10+ years	
	AC Unit	159A - Interior Office	1	EΑ	7	6-10 years	
	Ceiling - Splined	159A - Interior Office	55	SF	6	10+ years	
	Doors - Side-lite	159A - Interior Office	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	159A - Interior Office	1	EΑ	7	10+ years	
	Floor - Tile	159A - Interior Office	55	SF	6	10+ years	
	Lighting - Pendent/Surface	159A - Interior Office	1	EA	6	6-10 years	

Campus Name: Saucedo Page : 63 of 80 Assessment Date: 06/04/2024



Category : Room			Building : Addition (Telpochcalli)					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Power Distribution	159A - Interior Office	2	EA	7	10+ years		
	Walls - Plaster/Drywall	159A - Interior Office	110	SF	6	10+ years		
	AC Unit	159B - Interior Office	1	EA	7	6-10 years		
	Ceiling - Splined	159B - Interior Office	97	SF	6	10+ years		
	Doors - Wood Doors inclu hw	159B - Interior Office	1	EA	7	10+ years		
	Floor - Tile	159B - Interior Office	97	SF	6	10+ years		
	Lighting - Pendent/Surface	159B - Interior Office	2	EA	6	6-10 years		
	Power Distribution	159B - Interior Office	4	EA	7	10+ years		
	Walls - Plaster/Drywall	159B - Interior Office	194	SF	6	10+ years		
	AC Unit	159C-Interior Office	1	EA	7	6-10 years		
	Ceiling - Splined	159C-Interior Office	41	SF	6	10+ years		
	Doors - Side-lite	159C-Interior Office	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	159C-Interior Office	1	EA	7	10+ years		
	Floor - Tile	159C-Interior Office	41	SF	6	10+ years		
	Lighting - Pendent/Surface	159C-Interior Office	1	EA	6	6-10 years		
	Power Distribution	159C-Interior Office	2	EA	7	10+ years		
	Walls - Plaster/Drywall	159C-Interior Office	82	SF	6	10+ years		
	AC Unit	160BCopy/Work Room in Main Office	1	EA	7	6-10 years		
	Ceiling - Splined	160BCopy/Work Room in Main Office	315	SF	6	10+ years		
	Doors - Wood Doors inclu hw	160BCopy/Work Room in Main Office	2	EA	7	10+ years		
	Floor - Tile	160BCopy/Work Room in Main Office	309	SF	6	10+ years		
	Floor - Tile	160BCopy/Work Room in Main Office	6	SF	4	0-1 year	Cracked	
	Lighting - Pendent/Surface	160BCopy/Work Room in Main Office	7	EA	6	6-10 years		
	Power Distribution	160BCopy/Work Room in Main Office	7	EA	7	10+ years		
	Walls - Plaster/Drywall	160BCopy/Work Room in Main Office	598	SF	6	10+ years		
	AC Unit	1st Floor Main Office - Reception Area	1	EA	7	6-10 years		
	Ceiling - Splined	1st Floor Main Office - Reception Area	247	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor Main Office - Reception Area	1	EA	7	10+ years		
	Floor - Tile	1st Floor Main Office - Reception Area	247	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor Main Office - Reception Area	3	EA	6	6-10 years		
	Power Distribution	1st Floor Main Office - Reception	4	EA	7	10+ years		



Catego	ry : Room		Building : Addition (Telpochcalli)							
						Recommend				
€roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
		Area								
	Storage/ Closet	1st Floor Main Office - Reception	15	SF	7	10+ years				
		Area			_					
	Walls - Plaster/Drywall	1st Floor Main Office - Reception	537	SF	6	10+ years				
		Area			_					
	Ceiling - Plaster/Drywall	1st Floor Supervising Engineer 158	115	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor Supervising Engineer 158		EA	7	10+ years				
	Floor - Tile	1st Floor Supervising Engineer 158	115	SF	6	10+ years				
	Lighting - Pendent/Surface	1st Floor Supervising Engineer 158	2	EA	6	6-10 years				
	Power Distribution	1st Floor Supervising Engineer 158	2	EA	7	10+ years				
	Storage/ Closet	1st Floor Supervising Engineer 158	12	SF	7	10+ years				
	Walls - Masonry	1st Floor Supervising Engineer 158	150	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor Supervising Engineer 158	146	SF	6	10+ years				
	AC Unit	267 - Engineer 2 above Boiler Room	1	EA	7	6-10 years				
	Ceiling - Lay-in	267 - Engineer 2 above Boiler Room	291	SF	6	10+ years				
	Ceiling - Lay-in	267 - Engineer 2 above Boiler Room	9	SF	4	0-1 year	Water damage			
	Doors - Wood Doors inclu hw	267 - Engineer 2 above Boiler Room	1	EA	7	10+ years				
	Floor - Tile	267 - Engineer 2 above Boiler Room	300	SF	6	10+ years				
	Lighting - Lay-in	267 - Engineer 2 above Boiler Room	4	EA	6	6-10 years				
	Power Distribution	267 - Engineer 2 above Boiler Room	4	EA	7	10+ years				
	Storage/ Closet	267 - Engineer 2 above Boiler Room	100	SF	7	10+ years				
	Walls - Plaster/Drywall	267 - Engineer 2 above Boiler Room	720	SF	6	10+ years				
	AC Unit	2nd Floor - boiler room (East)	1	EA	7	6-10 years				
		Office/Lounge. 261			_					
	Ceiling - Plaster/Drywall	2nd Floor - boiler room (East)	344	SF	6	10+ years				
		Office/Lounge. 261			_					
	Doors - Wood Doors inclu hw	2nd Floor - boiler room (East)	1	EA	7	10+ years				
		Office/Lounge. 261			_					
	Floor - Tile	2nd Floor - boiler room (East)	344	SF	6	10+ years				
		Office/Lounge. 261	_		_					
	Lighting - Lay-in	2nd Floor - boiler room (East)	8	EA	6	6-10 years				
		Office/Lounge. 261			_					
	Power Distribution	2nd Floor - boiler room (East)	4	EA	7	10+ years				
		Office/Lounge. 261			_					
	Storage/ Closet	2nd Floor - boiler room (East)	180	SF	7	10+ years				
		Office/Lounge. 261			_					
	Walls - Plaster/Drywall	2nd Floor - boiler room (East)	584	SF	6	10+ years				
	Office/Lounge. 261									
	Walls - Plaster/Drywall	2nd Floor - boiler room (East)	10	SF	4	0-1 year	Water damage			
		Office/Lounge. 261			_					
	AC Unit	Chief Engineer's Office 266	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	Chief Engineer's Office 266	224	SF	6	10+ years				
	Doors - Wood Doors inclu hw	Chief Engineer's Office 266	1	EA	7	10+ years				
	Floor - Tile	Chief Engineer's Office 266	224	SF	6	10+ years				



Catego	ategory : Room Building : Addition (Telpochcalli)						
			_			Recommend	<u> </u>
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Chief Engineer's Office 266	5	EA	6	6-10 years	
	Power Distribution	Chief Engineer's Office 266	6	EA	7	10+ years	
	Storage/ Closet	Chief Engineer's Office 266	56	SF	7	10+ years	
	Walls - Plaster/Drywall	Chief Engineer's Office 266	448	SF	6	10+ years	
	AC Unit	Principal's Office in Main Office 161	1	EA	7	6-10 years	
	Ceiling - Lay-in	Principal's Office in Main Office 161	203	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office in Main Office 161	1	EA	7	10+ years	
	Floor - Tile	Principal's Office in Main Office 161	193	SF	6	10+ years	
	Floor - Tile	Principal's Office in Main Office 161	10	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	Principal's Office in Main Office 161	3	EA	6	6-10 years	
	Power Distribution	Principal's Office in Main Office 161	8	EA	7	10+ years	
	Storage/ Closet	Principal's Office in Main Office 161	81	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office in Main Office 161	389	SF	6	10+ years	
	Walls - Plaster/Drywall	Principal's Office in Main Office 161	6	SF	4	1-2 years	Water damage
_MDF_ID	F						
_	Doors - Wood Doors inclu hw	164A- MDF Room	1	EA	7	10+ years	
	Finishes	164A- MDF Room	105	SF	7	10+ years	
	Other Cooling Unit	164A- MDF Room	1	EA	5	6-10 years	
Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	1,200	SF	7	10+ years	
	Janitor's Closet	1st Floor	32	SF	7	10+ years	
	Loading Docks	1st Floor	400	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	1,500	SF	7	10+ years	
	Storage Room	1st Floor	1,500	SF	7	10+ years	
	Janitor's Closet	2nd Floor	20	SF	7	10+ years	
	Storage Room	2nd Floor	25	SF	5	10+ years	
Restroo	m						
	Accessories	1st Floor	440	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	440	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	440	SF	6	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	4	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	6	6-10 years	
	Partitions	1st Floor	9	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	300	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	263	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	105	SF	6	10+ years	
	Water Closet	1st Floor	9	EA	7	10+ years	
	Accessories	1st Floor	30	SF	7	6-10 years	



Category : Room			Building : Addition (Telpochcalli)						
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	1st Floor	30	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	30	SF	6	10+ years			
	Lavatory	1st Floor	1	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years			
	Walls - Vinyl Coated Gypsum Panel	1st Floor	68	SF	6	10+ years			
	Water Closet	1st Floor	1	EA	7	10+ years			
	Accessories	267	105	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	267	105	SF	6	10+ years			
	Doors - Wood Doors inclu hw	267	1	EA	7	10+ years			
	Floor - Tile	267	105	SF	6	10+ years			
	Floor Drain	267	1	EA	7	10+ years			
	Lavatory	267	2	EA	7	10+ years			
	Lighting - Pendent/Surface	267	1	EA	6	6-10 years			
	Lighting - Wall Mounted	267	1	EA	6	6-10 years			
	Partitions	267	1	EA	5	6-10 years			
	Showers	267	1	EA	5	6-10 years			
	Walls - Plaster/Drywall	267	220	SF	6	10+ years			
	Walls - Plaster/Drywall	267	20	SF	5	1-2 years	Water damage		
	Water Closet	267	1	EA	7	10+ years			
	Accessories	2nd Floor	475	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	475	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	3	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	475	SF	6	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Hand Dryer	2nd Floor	2	EA	5	1-2 years	Not working		
	Lavatory	2nd Floor	4	EA	7	10+ years	•		
	Lighting - Pendent/Surface	2nd Floor	11	EA	6	6-10 years			
	Partitions	2nd Floor	2	EA	7	10+ years			
	Urinals	2nd Floor	5	EA	6	10+ years			
	Urinals	2nd Floor	3	EA	5	0-1 year	Not working		
	Walls - Plaster/Drywall	2nd Floor	408	SF	6	10+ years	•		
	Walls - Structural Glazed Tile	2nd Floor	580	SF	6	10+ years			
	Water Closet	2nd Floor	2	EA	7	10+ years			
	Accessories	2nd Floor	22	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	22	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	22	SF	6	10+ years			
	Lavatory	2nd Floor	1	ĒΑ	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	1	EΑ	6	6-10 years			
	Walls - Masonry	2nd Floor	12	SF	7	10+ years			
	Walls - Vinyl Coated Gypsum Panel	2nd Floor	32	SF	6	10+ years			
	Water Closet	2nd Floor	1	EA	7	6-10 years			
	Accessories	2nd Floor Engineer's Lounge	75	SF	5	6-10 years			
	, 10000001100	Zila i looi Eligillooi o Louligo	70	٥.	J	3 10 yours			



Catego	ry : Room	Building : Addition (Telpochcalli)					
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor Engineer's Lounge	75	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor Engineer's Lounge	1	EA	7	10+ years	
	Floor - Tile	2nd Floor Engineer's Lounge	75	SF	6	10+ years	
	Lavatory	2nd Floor Engineer's Lounge	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor Engineer's Lounge	2	EA	6	6-10 years	
	Lighting - Wall Mounted	2nd Floor Engineer's Lounge	1	EA	6	6-10 years	
	Partitions	2nd Floor Engineer's Lounge	1	EA	5	6-10 years	
	Showers	2nd Floor Engineer's Lounge	1	EA	5	6-10 years	
	Walls - Plaster/Drywall	2nd Floor Engineer's Lounge	150	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor Engineer's Lounge	20	SF	5	0-1 year	Water damage
	Water Closet	2nd Floor Engineer's Lounge	1	EA	7	10+ years	
	Accessories	Boiler Room	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boiler Room	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boiler Room	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Boiler Room	40	SF	5	0-1 year	Damaged.
	Lavatory	Boiler Room	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Boiler Room	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	Boiler Room	80	SF	6	10+ years	
	Water Closet	Boiler Room	1	EA	7	10+ years	
	Accessories	Chief Engineer's Office	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Chief Engineer's Office	36	SF	5	0-1 year	Water damage.
	Doors - Wood Doors inclu hw	Chief Engineer's Office	1	EA	7	10+ years	
	Floor - Tile	Chief Engineer's Office	36	SF	6	10+ years	
	Lavatory	Chief Engineer's Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Chief Engineer's Office	1	EA	6	6-10 years	
	Student Lockers - One Tier	Chief Engineer's Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Chief Engineer's Office	72	SF	6	10+ years	
	Water Closet	Chief Engineer's Office	1	EA	7	10+ years	

Category : Classroom **Building: Addition (Telpochcalli)**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Classro	om #151 (Regular Classroom)						
	AC Units	1st Floor	3	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	911	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	911	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	27	EA	6	6-10 years	
	Marker Board	1st Floor	26	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,586	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classro	om #152 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	



Catego	ry : Classroom		Building : Addition (Telpochcalli)				
90	,		_			Recommend	,
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	619	SF	6	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	619	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,279	SF	6	10+ years	
Classroo	om #154 (Regular Classroom)						
	AC Units	1st Floor	3	EA	7	6-10 years	
	Casework	1st Floor	24	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	911	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	911	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	21	EA	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,588	SF	6	10+ years	
	·		.,,000	•	· ·	.o. you.o	
_Classroo	om #155 (Pre School)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	825	SF	6	10+ years	
	Chalk Board	1st Floor	5	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	825	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	6	6-10 years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,512	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #156 (Art Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	18	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	728	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	728	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	ĒΑ	6	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,666	SF	6	10+ years	
Ola	44CO (O#iaa)						
_Classroo	om #160 (Office)	4 . =				0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	



Category : Classroom Building : Addition (Telpochcalli)							lli)
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Splined	1st Floor	596	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	596	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	6	6-10 years	
	Marker Board	1st Floor	5	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	968	SF	6	10+ years	
Classroo	om #162 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	25	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	875	SF	6	10+ years	
	Chalk Board	1st Floor	15	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	13	EA	7	10+ years	
	Floor - Wood Books inclu hw	1st Floor	875	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	22	EA	6	6-10 years	
		1st Floor	15	LF	_	•	
	Marker Board			SF	7	6-10 years	
	Storage/ Closet	1st Floor	72		7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,591	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #164 (Store Room)						
	AC Units	1st Floor	4	EA	7	6-10 years	
	Ceiling - Lay-in	1st Floor	625	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	150	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	775	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	14	EA	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	85	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,029	SF	6	10+ years	
Classroo	om #251 (Regular Classroom)						
	AC Units	2nd Floor	3	EA	7	6-10 years	
	Casework	2nd Floor	25	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	880	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	830	SF	6	10+ years	
	Floor - Tile	2nd Floor	50	SF	4	0-1 year	Chipped cracked
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years	Onipped Glacked
		2nd Floor 2nd Floor	28	LF	7		
	Marker Board			SF		6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,373	2L	6	10+ years	



July	ry : Classroom		Building : Addition (Telpochcalli)					
0	Hann Time	Laastian	Overtitue	HOM	Dank	Recommend	Comments	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroc	om #252 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	6	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	588	SF	6	10+ years		
	Chalk Board	2nd Floor	10	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Wood	2nd Floor	588	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	10	EA	6	6-10 years		
	Marker Board	2nd Floor	20	LF	7	6-10 years		
				SF	6			
	Walls - Plaster/Drywall	2nd Floor	1,001	5F	б	10+ years		
Classroc	om #253 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	6	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	588	SF	6	10+ years		
	Chalk Board	2nd Floor	28	LF	4	2-5 years		
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Wood Boots inclu tiw	2nd Floor	588	SF	6	10+ years		
		2nd Floor		EA		•		
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	10 12	LF	6 7	6-10 years		
	Marker Board			SF		6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	10+ years		
Classroc	om #254 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	6	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	588	SF	6	10+ years		
	Chalk Board	2nd Floor	18	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	3	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Wood	2nd Floor	588	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	10	EA	6			
	• •					6-10 years		
	Marker Board	2nd Floor	18	LF SF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	10+ years		
Classroc	om #255 (Regular Classroom)							
	AC Units	2nd Floor	2	EA	7	6-10 years		
	Casework	2nd Floor	6	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	588	SF	6	10+ years		
				LF		•		
	Chalk Board	2nd Floor	6	LF	4	2-5 years		



Category : Classroom Building : Addition (Telpochcalli)						lli)	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	588	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	10	EA	6	6-10 years	
	Marker Board	2nd Floor	28	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	10+ years	
Classroo	om #256 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	588	SF	6	10+ years	
	Chalk Board	2nd Floor	19	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	568	SF	6	10+ years	
	Floor - Wood	2nd Floor	20	SF	4	0-1 year	Need seal
		2nd Floor 2nd Floor	10	EA			Need Seal
	Lighting - Pendent/Surface Marker Board	2nd Floor 2nd Floor	23	LF	6	6-10 years	
					7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	10+ years	
Classroo	om #257 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	15	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,176	SF	6	10+ years	
	Chalk Board	2nd Floor	16	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Carpet	2nd Floor	1,176	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	23	EA	6	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,056	SF	6	10+ years	
Classroo	om #258 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,028	SF	6	10+ years	
	Chalk Board	2nd Floor	28	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	1,028	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	24	SF	7	•	
	Sicrage/ Cluser	ZIIU FIUUI	24	SF	1	10+ years	



Categoi	ry : Classroom	Building : Addition (Telpochcalli)						
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Plaster/Drywall	2nd Floor	2,000	SF	6	10+ years		
lassroo	m #259 (Regular Classroom)							
	Casework	2nd Floor	6	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	588	SF	6	10+ years		
	Chalk Board	2nd Floor	19	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	3	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Wood	2nd Floor	578	SF	6	10+ years		
	Floor - Wood	2nd Floor	10	SF	4	0-1 year	Need seal	
	Lighting - Pendent/Surface	2nd Floor	10	EA	6	6-10 years		
	Marker Board	2nd Floor	13	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,001	SF	6	10+ years		
lassroo	m #260 (Regular Classroom)							
	AC Units	2nd Floor	3	EA	7	6-10 years		
	Casework	2nd Floor	39	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	864	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	3	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	16	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years		
	Floor - Wood	2nd Floor	864	SF	6	10+ years		
	Lighting - Pendent/Surface	2nd Floor	24	EΑ	5	0-1 vear	Not working.	
	Marker Board	2nd Floor	20	LF	7	6-10 years	Ğ	
	Walls - Plaster/Drywall	2nd Floor	1,124	SF	6	10+ years		
assroo	m #262 (Science Classroom)							
	AC Units	2nd Floor	3	EA	7	6-10 years		
	Casework	2nd Floor	45	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	1,008	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	14	SF	7	10+ years		
	Doors - Transom Window	2nd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years		
	Floor - Tile	2nd Floor	988	SF	6	10+ years		
	Floor - Tile	2nd Floor	20	SF	4	1-2 years	Cracked chipped	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	6	6-10 years		
	Marker Board	2nd Floor	19	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,389	SF	6	10+ years		
	Work Sink	2nd Floor	1	EA	7	6-10 years		
assroo	m #264 (Regular Classroom)							
	AC Units	2nd Floor	3	EA	7	6-10 years		



Catego	ry : Classroom		В	Building : Addition (Telpochcalli)						
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Casework	2nd Floor	12	LF	7	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor	880	SF	6	10+ years				
	Chalk Board	2nd Floor	12	LF	4	2-5 years				
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years				
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years				
	Floor - Wood	2nd Floor	880	SF	6	10+ years				
	Lighting - Pendent/Surface	2nd Floor	18	EA	6	6-10 years				
	Marker Board	2nd Floor	28	LF	7	6-10 years				
	Walls - Plaster/Drywall	2nd Floor	1,373	SF	6	10+ years				

Category : Interior **Building: Addition (Telpochcalli)**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Flr Corridor	2,056	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Flr Corridor	8	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Flr Corridor	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Flr Corridor	2,056	SF	7	10+ years	
	Lighting - Wall Mounted	1st Flr Corridor	15	EA	6	6-10 years	
	Walls - Plaster/Drywall	1st Flr Corridor	4,326	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Second Floor Boiler Room	180	SF	6	10+ years	
	Floor - Tile/Sheet	Second Floor Boiler Room	180	SF	5	10+ years	
	Lighting - Pendent/Surface	Second Floor Boiler Room	3	EA	6	6-10 years	
	Stairs - Concrete Stairs	Second Floor Boiler Room	75	LF	7	10+ years	Steel
	Walls - Masonry	Second Floor Boiler Room	200	SF	6	10+ years	
	Walls - Plaster/Drywall	Second Floor Boiler Room	280	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Second Floor Corridor	2,020	SF	6	10+ years	
	Doors - Steel Doors incl hw	Second Floor Corridor	2	EA	7	10+ years	
	Doors - Wood Doors include hw	Second Floor Corridor	1	EA	6	10+ years	
	Doors - Wood Doors include hw	Second Floor Corridor	1	EA	5	10+ years	
	Drinking Fountains - Single Fountain	Second Floor Corridor	1	EA	7	6-10 years	
	Drinking Fountains - Single Water Cooler	Second Floor Corridor	1	EA	7	6-10 years	
	Floor - Tile/Sheet	Second Floor Corridor	2,020	SF	7	10+ years	
	Lighting - Pendent/Surface	Second Floor Corridor	29	EA	6	6-10 years	
	Lighting - Wall Mounted	Second Floor Corridor	2	EA	6	6-10 years	
	Stairs - Concrete Stairs	Second Floor Corridor	64	LF	7	10+ years	
	Student Lockers - One Tier	Second Floor Corridor	166	EA	7	10+ years	
	Walls - Plaster/Drywall	Second Floor Corridor	4,308	SF	6	10+ years	
Safety							
,	Camera Viewing Station	Exterior	1	EA	7	6-10 years	
	Security Cameras	Exterior	2	EA	7	6-10 years	

Campus Name: Saucedo Page : 74 of 80 Assessment Date: 06/04/2024



Catego	ry : Interior		В	uilding	: Additi	on (Telpochcal	lli)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Stairs							
	Ceiling - Plaster/Drywall	North Stair	497	SF	6	10+ years	
	Floor - Tile	North Stair	364	SF	6	10+ years	
	Handrails	North Stair	68	LF	7	10+ years	
	Lighting - Pendent/Surface	North Stair	2	EA	6	6-10 years	
	Lighting - Wall Mounted	North Stair	2	EA	6	6-10 years	
	Stairs - Asphalt	North Stair	186	LF	6	10+ years	
	Walls - Plaster/Drywall	North Stair	1,094	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South Stair	360	SF	6	10+ years	
	Floor - Tile	South Stair	382	SF	6	10+ years	
	Handrails	South Stair	70	LF	7	10+ years	
	Lighting - Pendent/Surface	South Stair	2	EA	6	6-10 years	
	Lighting - Wall Mounted	South Stair	4	EA	6	6-10 years	
	Stairs - Asphalt	South Stair	168	LF	6	10+ years	
	Walls - Plaster/Drywall	South Stair	424	SF	6	10+ years	



Category : Site	Building : Site
-----------------	-----------------

	y . Site			unung	. 0.10	Decemberd	
	Ham. Time	Location	Otit	ПОМ	Dank	Recommend	Comments
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
thletic							
	Surface - Synthetic	South	6,500	SF	7	10+ years	
Civil/Drai							
	Civil/ Drainage - Catch Basin	Entire Site	9	EA	6	10+ years	Replaced
	Civil/ Drainage - Site Manhole	Entire Site	14	EA	6	10+ years	
Fencina							
	Fencing - Guard Rail	Entire Site	827	LF	6	10+ years	
	Fencing - Guard Rail	Entire Site	40	LF	4	0-1 year	Corroded, bent
	Fencing - New Standard Ornamental	Entire Site	813	LF	7	10+ years	
	Fencing - New Standard Ornamental	Entire Site	10	LF	5	2-5 years	
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	80	LF	6	6-10 years	
						•	
andscap	De Benches	Entire Site	9	EA	7	10+ years	New
		Entire Site	-	EA	6		New
	Benches Benches	Entire Site	7 2	EA	4	10+ years	Warned deterioreted
					-	0-1 year	Warped, deteriorated
	Landscape - Grass	Entire Site	21,234	SF	6	10+ years	Dealered
	Landscape - Hardscape- Concrete	Entire Site	7,934	SF	7	10+ years	Replaced
	Landscape - Hardscape- Concrete	Entire Site	700	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	250	SF	4	0-1 year	Missing, loose
	Parkway trees	Entire Site	80	EA	6	10+ years	
	Parkway trees	Entire Site	_1	EA	4	0-1 year	Dead tree
	Planting Beds/ Area	Entire Site	450	SF	6	10+ years	
	Trash Receptacles	Entire Site	4	EA	6	10+ years	
	Walking Path - Crushed Stone	Entire Site	250	SF	6	10+ years	
Parking L	ot						
-0-	Concrete Curbs	Entire Site	170	LF	6	10+ years	
	Surface - Asphalt	Entire Site	88,635	SF	7	10+ years	Replaced
	Surface - Concrete	Entire Site	1,500	SF	7	10+ years	
	Trash Enclosure - Chain Links	Entire Site	1,280	SF	7	10+ years	
Playgroui	nd						
<u> iaygi dul</u>	Equipment - Combo 3-12	East of Main	1	EA	7	10+ years	
	Surface - Poured Surface	East of Main	3,900	SF	7	10+ years	
a			·			•	
Sidewalk		Entiro Cito	045	1.5	7	101 2000	
	Sidewalks - Internal Walks	Entire Site	245	LF	7	10+ years	
	Sidewalks - Internal Walks	Entire Site	190	LF	6	10+ years	

Campus Name: Saucedo Page : 76 of 80 Assessment Date: 06/04/2024



Catego	ry : Site		В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	33,171	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	2,019	SF	4	0-1 year	Cracks, settling
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	1	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

Campus Name: Saucedo Page: 77 of 80 Assessment Date: 06/04/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				Floor Plan		Clared	Operable		
			Room	Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	intended Osage	Room Location	Nullibel	Number	(SF)	Alea	Alea	Зюр	Doaru
Art Room	Other Instructional Use	3rd Floor	313	313	1,143	240	100	N	N
Band Room	Band Room	4th Floor	400	400	2,400	830	164	N	N
Kindergarten	Laboratory/Shop	1st Floor	144	144	1,660	375	100	N	N
Kindergarten	Office	1st Floor	119	119	680	150	48	N	N
Kindergarten	Regular Classroom	1st Floor	125	125	680	150	48	N	N
Kindergarten	Regular Classroom	1st Floor	126	126	1,354	180	90	IN	IN
Kindergarten	Regular Classroom	1st Floor	127	127	673	200	100	Y	N
	Science Classroom	1st Floor	104	104	982	216	90	N	Y
Kindergarten Office		1st Floor	104	106	1,088	192	80	N	N N
	Science Classroom	2nd Floor	220	220	602	200		Y	N N
Other Instructional Use	Other Instructional Use						100	Y	N
Other Instructional Use	Regular Classroom	2nd Floor	200	200	1,652	300	60		
Other Instructional Use	Regular Classroom	2nd Floor	212	212	673	225	112	Y	N
Play Room	Laboratory/Shop	1st Floor	143	143	1,630	375	100	N	N
Pre School	Laboratory/Shop	1st Floor	130	130	1,644	420	131	N	N
Pre School	Regular Classroom	1st Floor	116	116	1,291	120	50	N	N
			combined						
			wi						
Pre School	Regular Classroom	1st Floor	118 added	118	665	144	60	N	N
			to 11						
Pre School	Regular Classroom	1st Floor	123	123	673	200	150	Y	N
Regular Classroom	Art Room	3rd Floor	332	332	1,322	276	84	N	N
Regular Classroom	Art Room	3rd Floor	334	334	1,354	276	84	N	Υ
Regular Classroom	Office	3rd Floor	312	312	441	96	40	N	N
Regular Classroom	Other Instructional Use	2nd Floor	202	202	1,247	400	200	Y	Υ
Regular Classroom	Other Instructional Use	2nd Floor	206	206	1,247	367	184	Υ	N
Regular Classroom	Other Instructional Use	3rd Floor	314	314	703	144	60	N	N
Regular Classroom	Other Instructional Use	3rd Floor	315	315	703	144	60	N	N
Regular Classroom	Other Instructional Use	3rd Floor	317	317	1,140	253	77	N	N
Regular Classroom	Other Instructional Use	3rd Floor	321	321	1,140	230	70	N	N
Regular Classroom	Other Instructional Use	3rd Floor	323	323	500	115	35	N	N
Regular Classroom	Other Instructional Use	3rd Floor	335	335	1,026	207	63	N	Υ
Regular Classroom	Other Instructional Use	3rd Floor	336	336	1,026	207	63	N	Y
Regular Classroom	Regular Classroom	2nd Floor	213	213	673	150	75	Y	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	673	120	60	Y	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	673	150	75	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	217	217	673	200	100	Y	N
Regular Classroom	Regular Classroom	2nd Floor	219	219	680	150	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	221	221	673	200	100	N	N

Campus Name: Saucedo Page : 78 of 80 Assessment Date: 06/04/2024





Classroom Summary

Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Regular Classroom	Regular Classroom	2nd Floor	223	223	680	150	48	Υ	Y
Regular Classroom	Regular Classroom	2nd Floor	225	225	680	150	48	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	226	226	673	200	100	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	227	227	680	150	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	228	228	779	220	110	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	703	102	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	703	144	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	703	102	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	316	316	673	138	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	318	318	1,015	207	63	N	Y
Regular Classroom	Regular Classroom	3rd Floor	320	320	673	138	42	N	N
Regular Classroom	Regular Classroom	3rd Floor	322	322	1,015	207	63	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	326	326	673	138	42	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	328	328	720	107	33	N	N
Regular Classroom	Regular Classroom	3rd Floor	329	329	720	107	33	N	N
Regular Classroom	Regular Classroom	3rd Floor	333	333	970	207	63	N	N
Regular Classroom	Regular Classroom	3rd Floor	337	337	704	144	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	339	339	672	144	60	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	340	340	672	144	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	341	341	672	144	60	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	342	342	672	144	60	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	343	343	672	144	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	344	344	672	144	60	N	N
Regular Classroom	Regular Classroom	3rd Floor	346	346	672	144	60	N	N
Regular Classroom	Science Lab Level 3	2nd Floor	216	216	1,062	330	165	Y	N
Regular Classroom	Science Lab Level 3	2nd Floor	224	222/224	1,062	225	72	N	N
Science Classroom	Other Instructional Use	3rd Floor	327	327	1,143	207	63	N	N
Science Classroom	Science Lab Level 3	3rd Floor	302	302	985	207	63	N	N
Science Classroom	Science Lab Level 3	3rd Floor	304	306	1,152	207	63	N	N
Science Classroom	Science Lab Level 3	3rd Floor	305	305	1,027	207	63	N	N
Science Classroom	Science Lab Level 3	3rd Floor	309	309	1,128	207	63	N	N
Special Program	Office	3rd Floor	338	338	360	72	30	N	N
Store Room	Laboratory/Shop	1st Floor	133	133	1,885	336	105	N	N
Store Room	Regular Classroom	3rd Floor	331	331	648	138	42	N	N

Building : Addition (Telpochcalli)									
Art Room	Regular Classroom	1st Floor	156	NA (Rec.	728	233	112	Y	Υ
				Room)					
Kindergarten	Pre School	1st Floor	162	162	875	200	100	Y	N
Office	Regular Classroom	1st Floor	160	159	596	200	100	Y	Y
Pre School	Office	1st Floor	155	NA	825	267	133	Υ	Υ

Campus Name: Saucedo Page : 79 of 80 Assessment Date: 06/04/2024



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Music Room	2nd Floor	251	251	880	120	54	N	N
Regular Classroom	Other Instructional Use	1st Floor	151	151	911	300	150	Y	N
Regular Classroom	Other Instructional Use	1st Floor	154	153	911	300	150	Υ	Υ
Regular Classroom	Other Instructional Use	2nd Floor	257	257	1,176	252	63	N	N
Regular Classroom	Regular Classroom	1st Floor	152	NA	619	200	100	Y	N
Regular Classroom	Regular Classroom	2nd Floor	252	252	588	80	38	N	N
Regular Classroom	Regular Classroom	2nd Floor	253	253	588	80	38	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	254	254	588	80	38	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	255	255	588	80	38	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	256	256	588	80	48	N	N
Regular Classroom	Regular Classroom	2nd Floor	259	259	588	80	38	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	260	260	864	120	54	N	N
Regular Classroom	Regular Classroom	2nd Floor	264	264	880	120	54	N	N
Regular Classroom	Science	2nd Floor	258	258	1,028	224	54	N	N
Science Classroom	Science Classroom	2nd Floor	262	262	1,008	120	54	N	N
Store Room	Regular Classroom	1st Floor	164	164	775	267	133	Y	Υ

Campus Name: Saucedo Page : 80 of 80 Assessment Date: 06/04/2024