



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1951	2	32,352
Addition	1955	2	19,885
Campus Total			52,237

Category: Exterior Building: Main

Galego	Category . Exterior		Building . Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Entrance)							
	Entrance Control - Audio and Video	1 - Main	1	EA	7	6-10 years		
	Exterior Doors - Store Front	1 - Main	2	EA	7	10+ years		
	Exterior Doors - Transom Lite	1 - Main	1	EA	6	10+ years		
	Exterior Stairs - Concrete	1 - Main	10	LF	7	10+ years		
	Exterior Stairs - Stone	1 - Main	50	LF	6	10+ years		
	Stair Handrail - Steel_Stair Handrail	1 - Main	16	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	2	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	2	1	EA	6	10+ years		
	Exterior Stairs - Stone	2	150	LF	7	10+ years		
	Exterior Doors - Exterior Steel Door	3.1	1	EA	6	10+ years		
	Exterior Stairs - Concrete	3.1	10	LF	7	10+ years	Repaired	
	Exterior Stairs - Stone	3.1	50	LF	7	10+ years		
	Stair Handrail - Steel_Stair Handrail	3.1	14	LF	5	2-5 years		
	Exterior Doors - Exterior Steel Door	4	2	EA	6	10+ years		
	Exterior Stairs - Concrete	4	56	LF	5	6-10 years		
	Entrance Control - Audio and Video	5	1	EA	7	6-10 years		
	Exterior Doors - Exterior Steel Door	5	2	EA	6	10+ years		
	Exterior Stairs - Concrete	5	72	LF	7	10+ years		
	Power Door Operator and Controls	5	1	EA	7	6-10 years		
	Ramp Handrail - Steel_Ramp Handrail	5	200	LF	7	10+ years		
	Ramps - Concrete	5	100	LF	7	10+ years		
	Stair Handrail - Steel_Stair Handrail	5	67	LF	7	10+ years		



Category : Exterior			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Foundati							
	Foundation - Concrete	Entire Building	585	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	32,352	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	8	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	8	EA	6	2-5 years	
_Roof Sys		_					
	Coping - Stone	A	60	LF	7	10+ years	
	Downspouts - Exterior Downspouts	A	4	LF	7	10+ years	
	Parapet - Parapet < 16" Height	A	60	LF	7	10+ years	
	Roof - Modified Bitumen Roof Structure - Steel with Clay Tile Arch	A	225	SF	7	10+ years	
	Access Ladder - Metal	A B	225 1	SF EA	7 7	10+ years 10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	В	70	LF	7	10+ years	
	Liner	В	70	LI	,	10+ years	
	Coping - Stone	В	278	LF	6	10+ years	
	Downspouts - Interior Downspouts	В	105	LF	7	10+ years	
	Parapet - Parapet < 16" Height	В	278	LF	6	10+ years	
	Roof - Modified Bitumen	В	9,834	SF	7	10+ years	Repaired
	Roof Structure - Steel with Clay Tile Arch	В	9,834	SF	7	10+ years	•
	Coping - Stone	С	60	LF	7	10+ years	
	Downspouts - Exterior Downspouts	С	4	LF	7	10+ years	
	Parapet - Parapet < 16" Height	С	60	LF	7	10+ years	
	Roof - Modified Bitumen	С	225	SF	5	10+ years	
	Roof Structure - Steel with Clay Tile Arch	С	225	SF	7	10+ years	
	Coping - Stone	D	37	LF	5	10+ years	
	Downspouts - Interior Downspouts	D	26	LF	7	10+ years	
	Parapet - Parapet < 16" Height	D	37	LF	5	10+ years	
	Roof - Modified Bitumen	D	336	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	D	336	SF	7	10+ years	
	Concrete Topping Access Ladder - Metal	E	4	EA	7	10+ years	
	Coping - Stone	E	194	LF	7	10+ years 10+ years	
	Downspouts - Interior Downspouts	E	54	LF LF	7	10+ years 10+ years	
	Parapet - 16" - 30" Height	E	194	LF	, 5	10+ years	
	Roof - Modified Bitumen	E	3,654	SF	7	10+ years	Repaired
	Roof Hatch - Metal	Ē	2	EA	7	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	Ē	3,654	SF	7	10+ years	
			-,			,	
Walls							
	Cheek-Wall - Concrete	Entire Building	540	SF	7	10+ years	
		Ç				•	



Catego	ry : Exterior		В	uilding	: Main		
			Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Cheek-Wall - Stone	Entire Building	220	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	15,006	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	294	SF	6	6-10 years	
	Exterior Walls - Stone-Cut	Entire Building	1,860	SF	6	6-10 years	
Windows	3						
	Curtain wall - Louver	Entire Building	18	SF	7	6-10 years	
	Guard - Guards perforated	Entire Building	1,663	SF	6	10+ years	
	Lintels - Concrete	Entire Building	17	LF	6	10+ years	
	Lintels - Steel	Entire Building	260	LF	6	10+ years	
	Lintels - Stone	Entire Building	187	LF	5	6-10 years	
	Skylite - Glass Single-Pane	Entire Building	72	SF	5	10+ years	Repaired
	Windows - Sash Aluminum Double-pane	Entire Building	3,875	SF	6	6-10 years	·
Catego	ry : Electrical		В	uilding	: Main		

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerger	ncy System		•			•	
· ·	Automatic Transfer Switch	Basement	1	EA	6	10+ years	Serves Main and Addition.
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,020	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	2,425	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	10	EA	2	0-1 year	No battery, no AC generator
	Exit Signs - Gym	Entire Building	2	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Exit Signs - Gym	Entire Building	3	EA	2	0-1 year	Quantity changed divided/aggregated to represent observed conditions.
	Security System - CCTV	Entire Building	32,352	SF	6	6-10 years	·
	Security System - Intrusion Detection	Entire Building	32,352	SF	6	6-10 years	
Main Se	rvice						
	Main Electrical Service - 1600 A 120/208/3PH	Basement	1	EA	6	10+ years	
	Independent Electrical Service for emergency power	Entire Building	1	EA	6	10+ years	Serves Main and Addition.
	PA System	Entire Building	32,352	SF	6	6-10 years	
_Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - 100 A	Entire Building	2	EA	4	0-1 year	Quantity changed as total has been divided/aggregated. Missing doors and covers, and open fuse

Campus Name: Sherwood Page: 3 of 30 Assessment Date: 01/09/2024



Catego	ry : Electrical		R	uilding	· Main		, , , , , , , , , , , , , , , , , , , ,
Calcgo	ry . Licetrical			unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Стопр	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	receptacles, expose live conductors presenting a live front condition. Location changed for clarification. EM fuse panel. Rank, Reason and Priority Rep changed as open fuse receptacles expose live conductors
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	presenting a live front condition. Quantity changed based on current observations and as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slots expose live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slot exposes live conductors presenting a live front condition.
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire ALarm Anunciator Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building Entire Building Entire Building	1 1 32,352 32,352	EA EA SF SF	6 6 6	6-10 years 6-10 years 6-10 years 6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
Juligo	. y · moonamoa.		_	ananig	1 1114111	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	lling Systems		•			•	
	Indoor Return Fans- Centrifugal Inline - 5000 - 10000 CFM	Attic	1	EA	5	6-10 years	Unit is operational and was offline awaiting repairs at the time of assessment. Serves AHU-1.
	Air Handling Unit- Package Single Zone- Indoor- Steam Coils - 4000-8000 cfm	Gym	1	EA	5	6-10 years	Serves the gym. Located in mezzanine space adjacent to the gym.
	Air Intake	Gym	1	EA	6	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	AHU-1, serves Main.
	Air Intake	Mechanical Room	1	EA	6	6-10 years	Dampers are operational but adjusted manually due to nonfunctional DDC control.
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	



Catego	Category : Mechanical		В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	6	EA	5	6-10 years	Quantity changed to match current observations.
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room	100	LF	5	6-10 years	
	Zone Dampers	Mechanical Room	17	EA	5	6-10 years	Quantity changed to match current observations. Dampers are operational with many adjusted manually due to nonfunctional DDC control.
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	3	EA 	7	10+ years	Item Type and quantity changed to match current observations. Rank and Priority Rep changed as the boilers were replaced since previous assessment.
	Chemical Feed System	Boiler Room	1	EΑ	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	7	10+ years	Rank and Priority Rep changed as the combustion dampers were replaced since previous assessment.
	Feed Water Pumps and Tank	Boiler Room	1	EΑ	5	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	7	10+ years	B-2. Item Type, Rank and Priority Rep changed as unit was replaced since previous assessment.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	7	10+ years	B-3.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	7	10+ years	B-1. Item Type, Rank and Priority Rep changed as unit was replaced since previous assessment. No CPS Asset Tag present.
	Piping - Condensate Pipe- Steel	Boiler Room	500	LF	5	6-10 years	
	Piping - Steam Pipe- Steel	Boiler Room	500	LF	6	6-10 years	
	Steam Traps	Boiler Room	17	EΑ	5	6-10 years	
	Vacuum Pump	Boiler Room	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed based on repairs completed since previous assessment.
Heating	Devices						
3	Wall Heater - Electric	Entire Building	6	EA	6	6-10 years	Quantity changed to match current observations.
	Wall Heater - Electric	Entire Building	1	EA	6	10+ years	Location changed for clarification.
	Wall Heater - Electric	Entire Building	1	EA	4	0-1 year	Missing cover exposes live conductors presenting a live front

Campus Name: Sherwood Page : 5 of 30 Assessment Date: 01/09/2024



Catego	ry : Mechanical		B	uilding	: Main	-	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	D 1: 4 O1	E (4.4	_ ^	-	0.40	condition.
	Radiators - Steam	Entire Building	11 40	EA LF	5	6-10 years	Overetity above and to reactable assument
	Fin Tube - Steam	Entire Building	40	LF	6	6-10 years	Quantity changed to match current observations. Located in student restrooms.
	Cabinet Heaters - With Steam Coil	Entire Building	5	EA	5	6-10 years	Quantity changed to match current observations.
<u> Fempera</u>	ture Control						
	DDC System	Entire Building	32,352	SF	4	0-1 year	DDC System is well-outdated and incorporates numerous failure points which software upgrading does not resolve. Temperatures in spaces throughout the building are controlled manually by the Building Engineer.
	Thermostats - DDC	Entire Building	29	EA	6	1-2 years	DDC thermostats may be operable but do not communicate with the controls due to failure of the system
/entilatio	on Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	4	1.2 voore	Comice gram Deals Deagen and
	Exhaust Fans- Indoor - 1501 - 6000 Crivi	Entire Building	'	EA	4	1-2 years	Serves gym; Rank, Reason and Priority Rep changed as the unit broke down, was taken out of servic and has not been repaired.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	Gas Heater - 150000 - 300000 BTU/HR	Basement	1	EA	7	10+ years	Rank and Priority Rep adjusted as the unit was replaced since previous assessment.

_Piping Domestic Piping-Hot Water Return Lines **Entire Building** 32,352 SF 6-10 years 6 Domestic Piping-Hot Water Return Risers SF Entire Building 32,352 6-10 years 6 Domestic Piping-Hot Water from Risers to Entire Building SF 6-10 years 32,352 6 **Fixtures** Domestic Piping-Hot/Cold Water Supply **Entire Building** 32,352 SF 6 6-10 years (Horizontal Lines) Domestic Piping-Hot/Cold Water Supply **Entire Building** 32,352 SF 6 6-10 years



Catego	ry : Plumbing		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	(Risers)							
	Domestic Piping-Hot/Cold Water Supply	Entire Building	32,352	SF	6	6-10 years		
	(from Risers to Fixtures)	· ·				•		
	Sanitary Piping	Entire Building	32,352	SF	6	6-10 years		
	Storm Piping	Entire Building	32,352	SF	6	6-10 years		
	Vent Piping	Entire Building	32,352	SF	6	6-10 years		
Pumps								
	Pumps - Sump-Duplex	Basement	1	EA	5	6-10 years		

Category : Poom Building : Main

Category : Room			Building : Main						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments		
•	trative Suites/Offices		, , , , , , , , , , , , , , , , , , , ,						
	AC Unit	101	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	101	299	SF	6	10+ years			
	Doors - Wood Doors inclu hw	101	3	EA	7	10+ years			
	Floor - Tile	101	299	SF	7	10+ years			
	Lighting - Pendent/Surface	101	6	ĒΑ	7	10+ years			
	Power Distribution	101	6	EA	7	10+ years			
	Storage/ Closet	101	10	SF	7	10+ years			
	Walls - Plaster/Drywall	101	864	SF	7	10+ years			
	Ceiling - Plaster/Drywall	103	72	SF	7	10+ years			
	Doors - Transom Window	103	9	SF	7	10+ years			
	Doors - Wood Doors inclu hw	103	1	EA	7	10+ years			
	Floor - Tile	103	72	SF	7	10+ years			
	Lighting - Pendent/Surface	103	1	EA	5	1-2 years	Missing cover		
	Walls - Plaster/Drywall	103	340	SF	6	10+ years	Peeling paint		
	Ceiling - Plaster/Drywall	103A	126	SF	7	10+ years			
	Doors - Transom Window	103A	18	SF	7	10+ years			
	Doors - Wood Doors inclu hw	103A	1	EA	7	10+ years			
	Floor - Tile	103A	126	SF	7	10+ years			
	Lighting - Pendent/Surface	103A	2	EΑ	7	10+ years			
	Power Distribution	103A	2	EΑ	7	10+ years			
	Walls - Plaster/Drywall	103A	252	SF	7	10+ years			
	Walls - Plaster/Drywall	103A	250	SF	6	10+ years	Peeling paint		
	Work SInk	103A	1	EA	7	10+ years			
	Ceiling - Plaster/Drywall	103B	186	SF	7	10+ years			
	Doors - Transom Window	103B	27	SF	7	10+ years			
	Doors - Wood Doors inclu hw	103B	2	EA	7	10+ years			
	Floor - Tile	103B	186	SF	7	10+ years			
	Lighting - Pendent/Surface	103B	3	EA	7	10+ years			
	Power Distribution	103B	4	EA	7	10+ years			
	Walls - Plaster/Drywall	103B	840	SF	6	10+ years			

Campus Name: Sherwood Page : 7 of 30 Assessment Date: 01/09/2024







Catego	ry : Room		R	uilding	· Main		245 W 57111 STREET, Chicago, IL 60621
Catego	ry . Room			unung	. Walli	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
O. Cup	AC Unit	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	154	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	154	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	10+ years	
	Power Distribution	1st Floor	4	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	400	SF	7	10+ years	
	Ceiling - Plaster/Drywall	200 - Special Education	375	SF	7		
	Doors - Transom Window	200 - Special Education	9	SF	7	10+ years 10+ years	
	Doors - Wood Doors inclu hw	•	1	EA	7	,	
		200 - Special Education	-	SF	7	10+ years	
	Floor - Tile	200 - Special Education	367	SF SF		6-10 years	Demond
	Floor - Tile	200 - Special Education	8		4	0-1 year	Damaged
	Lighting - Pendent/Surface	200 - Special Education	4	EΑ	7	6-10 years	
	Power Distribution	200 - Special Education	8	EA	7	10+ years	
	Storage/ Closet	200 - Special Education	4	SF	7	10+ years	
	Walls - Plaster/Drywall	200 - Special Education	984	SF	7	10+ years	
	Ceiling - Plaster/Drywall	202	169	SF	7	10+ years	
	Doors - Transom Window	202	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	202	1	EA	7	10+ years	
	Floor - Tile	202	169	SF	7	6-10 years	
	Lighting - Pendent/Surface	202	2	EA	7	6-10 years	
	Power Distribution	202	2	EA	7	10+ years	
	Walls - Plaster/Drywall	202	324	SF	7	10+ years	
	AC Unit	Engineer's Office - Basement	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's Office - Basement	156	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office - Basement	1	EA	7	10+ years	
	Floor - Carpet	Engineer's Office - Basement	156	SF	7	6-10 years	
	Lighting - Pendent/Surface	Engineer's Office - Basement	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Engineer's Office - Basement	1	EA	4	0-1 year	Missing bulbs, exposed wiring
	Power Distribution	Engineer's Office - Basement	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Engineer's Office - Basement	500	SF	7	10+ years	
_Gvmnas	io						
_GyilliaS	Ceiling - Plaster/Drywall	1st Floor	2,392	SF	6	10+ years	
	Doors - Transom Window	1st Floor	18	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	6	EA	7	10+ years	
	Floor - Wood	1st Floor	2,392	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	600	SF	7	10+ years	
	Stage Curtain	1st Floor	10	EA	7	10+ years	
	Stage Cultain Stage Lighting System	1st Floor	10	EA	7	10+ years	
	Stage-Stairs - Asphalt	1st Floor	20	LF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,760	SF	7	10+ years	
	vvalis - Structural Glazeu Tile	13(1)001	3,700	J.	,	10+ years	

Campus Name: Sherwood Page: 8 of 30 Assessment Date: 01/09/2024



Catego	ry : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_MDF_ID	E						
	Doors - Steel Doors incl hw	202	1	EA	6	10+ years	
	Finishes	202	440	SF	7	10+ years	
	Other Cooling Unit	202	1	EA	7	10+ years	Portable unit
						, , , , , , , , , , , , , , , , , , , ,	
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	18	SF	7	10+ years	
	Janitor's Closet	1st Floor	18	SF	7	10+ years	
	Janitor's Closet	2nd Floor	18	SF	7	10+ years	
	Janitor's Closet	2nd Floor	18	SF	7	10+ years	
	Storage Room	2nd Floor	300	SF	7	10+ years	
	Air Tunnel	Basement	1,836	SF	7	10+ years	
	Boiler Room	Basement	851	SF	5	10+ years	
	Coal Room	Basement	450	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	5,400	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	800	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	191	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	190	SF	5	10+ years	
	Storage Room	Basement	291	SF	7	10+ years	
	Storage Room	Basement	78	SF	7	10+ years	
	Storage Room	Basement	69	SF	5	10+ years	
Restroor	_						
Resilooi	Accessories	102A	93	SF	7	6-10 years	
	Ceiling - Lay-in	102A	93	SF	7	10+ years	
	Doors - Wood Doors inclu hw	102A	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	102A	93	SF	7	10+ years	
	Floor Drain	102A	1	ĒΑ	7	10+ years	
	Hand Dryer	102A	1	EA	7	6-10 years	
	Lavatory	102A	1	EA	7	10+ years	
	Lighting - Lay-in	102A	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	102A	120	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	102A	100	SF	7	10+ years	
	Water Closet	102A	1	ĒΑ	7	10+ years	
	Accessories	103	32	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	103	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	103	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	103	32	SF	7	10+ years	
	Lavatory	103	1	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	103	1	ĒΑ	7	10+ years	
	Walls - Plaster/Drywall	103	192	SF	6	10+ years	
	Water Closet	103	1	ĒΑ	7	10+ years	
						j	







Category: Room **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Accessories 105 36 SF 6-10 years 7 Ceiling - Plaster/Drywall 105 36 SF 7 10+ years Doors - Wood Doors inclu hw 105 1 EΑ 6 10+ years Floor - Tile Ceramic/ Porcelain 105 SF 7 36 10+ years Floor Drain 105 1 EΑ 7 10+ years 7 Lavatory 105 1 EΑ 10+ years Lighting - Pendent/Surface 105 EΑ 7 6-10 years 1 Walls - Plaster/Drywall SF 105 78 7 10+ years Water Closet 105 1 EΑ 7 10+ years SF Accessories 1st Floor 262 7 6-10 years SF Ceiling - Plaster/Drywall 1st Floor 262 7 10+ vears Floor - Tile Ceramic/ Porcelain 1st Floor 262 SF 7 10+ years Floor Drain EΑ 7 10+ years 1st Floor 1 EΑ 7 Lavatory 1st Floor 2 10+ years Lighting - Pendent/Surface 4 7 1st Floor EΑ 10+ years Partitions 2 EΑ 5 1st Floor 6-10 years 2 7 Urinals 1st Floor EΑ 10+ years SF Walls - Concrete Block 1st Floor 108 7 10+ years SF Walls - Structural Glazed Tile 1st Floor 627 7 10+ vears Water Closet 1st Floor 2 EΑ 7 10+ years Accessories 1st Floor 262 SF 7 6-10 years Ceiling - Plaster/Drywall SF 7 1st Floor 262 10+ years Floor - Tile Ceramic/ Porcelain SF 7 1st Floor 262 10+ years Floor Drain 7 1st Floor 1 FΑ 10+ years Hand Dryer EΑ 7 6-10 years 1st Floor 1 Lavatory 1st Floor 2 EΑ 7 10+ vears Lighting - Pendent/Surface 1st Floor 4 EΑ 7 10+ years **Partitions** 4 EΑ 7 6-10 years 1st Floor SF Walls - Concrete Block 1st Floor 108 7 10+ years Walls - Plaster/Drywall 1st Floor 162 SF 7 10+ years Walls - Structural Glazed Tile SF 1st Floor 465 7 10+ vears Water Closet 1st Floor 4 EΑ 7 10+ years SF 7 Accessories 2nd Floor 262 6-10 years Ceiling - Plaster/Drywall 2nd Floor 262 SF 7 10+ years Floor - Tile Ceramic/ Porcelain SF 7 2nd Floor 262 10+ years EΑ 7 Floor Drain 2nd Floor 1 10+ years 2 Hand Dryer 2nd Floor EΑ 7 6-10 years 2 7 Lavatory 2nd Floor EΑ 10+ years Lighting - Pendent/Surface 2nd Floor 4 EΑ 5 6-10 years Missing covers 5 EΑ **Partitions** 2nd Floor 5 6-10 years SF Walls - Concrete Block 2nd Floor 108 7 10+ years 2nd Floor SF 7 Walls - Plaster/Drywall 162 10+ years Walls - Structural Glazed Tile 2nd Floor 465 SF 7 10+ years Water Closet 5 EΑ 2nd Floor 7 10+ years







Building: Main Category: Room Recommend Group Item - Type Location Quantity UOM Rank Replacement **Comments** Accessories 2nd Floor 262 SF 6-10 years 7 Ceiling - Plaster/Drywall 2nd Floor 262 SF 7 10+ years Floor - Tile Ceramic/ Porcelain 2nd Floor 262 SF 7 6-10 years Floor Drain EΑ 7 2nd Floor 1 10+ years 2 Lavatory 2nd Floor EΑ 7 10+ years Lighting - Pendent/Surface 3 7 2nd Floor EΑ 10+ years Lighting - Pendent/Surface 2nd Floor 1 EΑ 5 10+ years Missing cover 2 **Partitions** 2nd Floor EΑ 7 6-10 years Urinals 2nd Floor 4 EΑ 7 10+ years SF Walls - Concrete Block 2nd Floor 108 7 10+ years SF Walls - Structural Glazed Tile 2nd Floor 627 7 10+ years Water Closet 2nd Floor 2 EΑ 7 10+ years Accessories 36 SF 5 6-10 years Basement - Engineer SF 7 Ceiling - Plaster/Drywall Basement - Engineer 36 10+ years Doors - Wood Doors inclu hw Basement - Engineer EΑ 7 1 10+ years Floor - Tile Basement - Engineer 26 SF 6 10+ years Floor - Tile SF Missing/damaged tile Basement - Engineer 10 4 0-1 year Lavatory Basement - Engineer 1 EΑ 6 10+ years Lighting - Pendent/Surface Basement - Engineer 1 EΑ 7 10+ years Walls - Masonry Basement - Engineer SF 40 5 0-1 year Damaged Walls - Plaster/Drywall Basement - Engineer 40 SF 6 10+ years Water Closet Basement - Engineer 7 1 EΑ 10+ years Principal's Office SF 7 Accessories 32 6-10 years 32 SF 7 Ceiling - Plaster/Drywall Principal's Office 10+ years Doors - Wood Doors inclu hw Principal's Office EΑ 7 1 10+ years Floor - Tile SF Principal's Office 32 7 6-10 years Principal's Office Lavatory 1 EΑ 7 10+ years Lighting - Pendent/Surface Principal's Office 1 EΑ 7 10+ years Walls - Plaster/Drywall Principal's Office SF 92 7 10+ years Water Closet Principal's Office 1 EΑ 7 10+ years

Category : Classroom Building : Main

. ,						
Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
om #102 (Pre School)						
AC Units	1st Floor	2	EA	7	6-10 years	
Casework	1st Floor	10	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	992	SF	7	10+ years	
Doors - Transom Window	1st Floor	18	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
Floor - Tile	1st Floor	992	SF	6	10+ years	
Lighting - Pendent/Surface	1st Floor	12	EΑ	7	6-10 years	
Marker Board	1st Floor	10	LF	7	6-10 years	
Storage/ Closet	1st Floor	90	SF	7	10+ years	
	Item - Type om #102 (Pre School) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board	Item - Type Dom #102 (Pre School) AC Units Casework Ceiling - Plaster/Drywall Doors - Transom Window Doors - Wood Doors inclu hw Floor - Tile Lighting - Pendent/Surface Marker Board Location 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	Item - Type Location Quantity om #102 (Pre School) 3 AC Units 1st Floor 2 Casework 1st Floor 10 Ceiling - Plaster/Drywall 1st Floor 992 Doors - Transom Window 1st Floor 18 Doors - Wood Doors inclu hw 1st Floor 2 Floor - Tile 1st Floor 992 Lighting - Pendent/Surface 1st Floor 12 Marker Board 1st Floor 10	Item - Type Location Quantity UOM om #102 (Pre School) 2 EA AC Units 1st Floor 2 EA Casework 1st Floor 10 LF Ceiling - Plaster/Drywall 1st Floor 992 SF Doors - Transom Window 1st Floor 18 SF Doors - Wood Doors inclu hw 1st Floor 2 EA Floor - Tile 1st Floor 992 SF Lighting - Pendent/Surface 1st Floor 12 EA Marker Board 1st Floor 10 LF	Item - Type Location Quantity UOM Rank om #102 (Pre School) AC Units 1st Floor 2 EA 7 Casework 1st Floor 10 LF 6 Ceiling - Plaster/Drywall 1st Floor 992 SF 7 Doors - Transom Window 1st Floor 18 SF 7 Doors - Wood Doors inclu hw 1st Floor 2 EA 6 Floor - Tile 1st Floor 992 SF 6 Lighting - Pendent/Surface 1st Floor 12 EA 7 Marker Board 1st Floor 10 LF 7	Item - Type Location Quantity UOM Rank Recommend Replacement com #102 (Pre School) AC Units 1st Floor 2 EA 7 6-10 years Casework 1st Floor 10 LF 6 10+ years Ceiling - Plaster/Drywall 1st Floor 992 SF 7 10+ years Doors - Transom Window 1st Floor 18 SF 7 10+ years Doors - Wood Doors inclu hw 1st Floor 2 EA 6 10+ years Floor - Tile 1st Floor 992 SF 6 10+ years Lighting - Pendent/Surface 1st Floor 12 EA 7 6-10 years Marker Board 1st Floor 10 LF 7 6-10 years



Catego	ry : Classroom		В	uilding	: Main		•
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,704	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classro	om #104 (Store Room)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	750	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	4	0-1 year	Not working
	Marker Board	1st Floor	40	LF	7	6-10 years	Ğ
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,320	SF	7	10+ years	
Classro	om #105 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	36	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,114	SF	6	10+ years	
	Doors - Transom Window	1st Floor	[′] 18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	1,114	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	35	LF	7	6-10 years	
	Storage/ Closet	1st Floor	70	SF	5	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,936	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classro	om #106 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	750	SF	6	10+ years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,320	SF	6	10+ years	
	Work Sink	1st Floor	1	ĒΑ	7	6-10 years	
Classro	om #107 (Regular Classroom)						
	,						





Catego	ry : Classroom		В	uilding	: Main		243 W 37111 STREET, CHICAGO, IL 60021
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	750	SF	7	10+ years	
	Chalk Board	1st Floor	32	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,320	SF	7	10+ years	
Classroo	om #201 (Computer Lab)						
	AC Units	2nd Floor	4	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	6	10+ years	
	Chalk Board	2nd Floor	34	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	740	SF	7	6-10 years	
	Floor - Tile	2nd Floor	10	SF	4	1-2 years	Damaged tile
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	Ç
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,310	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	4	1-2 years	Big crack
	Wireless System	2nd Floor	1	EA	7	6-10 years	•
_Classroo	om #202 (Science Classroom)						
	AC Units	2nd Floor	2	EΑ	7	6-10 years	
	Casework	2nd Floor	50	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	750	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	7	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	100	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,320	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	6	10+ years	
	Chalk Board	2nd Floor	34	LF	4	2-5 years	
			01		•	,	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	9	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood	2nd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,320	SF	6	10+ years	
_Classroc	om #204 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	740	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	10	SF	4	0-1 year	Damaged
	Chalk Board	2nd Floor	34	LF	4	2-5 years	Damagea
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Wood Books inclu fiw	2nd Floor	746	SF	6	10+ years	
	Floor - Wood Floor - Wood	2nd Floor 2nd Floor	4	SF	4		Prokon
	Lighting - Pendent/Surface	2nd Floor 2nd Floor		EA	7	1-2 years	Broken
	Marker Board	2nd Floor 2nd Floor	14	LF		6-10 years	
			20	SF	7 7	6-10 years	
	Storage/ Closet	2nd Floor	20			6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,300	SF	6	10+ years	Damarad
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	0-1 year	Damaged.
Classroc	om #205 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	6	10+ years	
	Chalk Board	2nd Floor	36	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Wood	2nd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,315	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	4	0-1 year	Big crack
Classroc	om #206 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor	750	SF	7	10+ years	
	Chalk Board	2nd Floor 2nd Floor	34	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor 2nd Floor		SF	6	6-10 years	
		2nd Floor 2nd Floor	9	SF EA	6		
	Doors - Wood Doors inclu hw	ZIIU FI00I	1		О	6-10 years	



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,320	SF	7	10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	750	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Wood	2nd Floor	750	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,320	SF	7	10+ years	

Category : Interior **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	2,128	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	9	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	2	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,116	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	12	SF	4	1-2 years	Cracked and damaged tile
	Lighting - Pendent/Surface	1st Floor	25	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	103	EA	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,275	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,925	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Gym Vestibule	400	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor - Gym Vestibule	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor - Gym Vestibule	400	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Gym Vestibule	3	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor - Gym Vestibule	400	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - Gym Vestibule	400	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - North East Vestibule	252	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor - North East Vestibule	3	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - North East Vestibule	252	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor - North East Vestibule	2	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor - North East Vestibule	20	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor - North East Vestibule	142	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor - North East Vestibule	270	SF	7	10+ years	

Campus Name: Sherwood Page: 15 of 30 Assessment Date: 01/09/2024





Catego	ry : Interior		D	uilding	· Main		245 W 57th STREET, Chicago, IL 60621
Calego	iy . iiiterioi		D	unung	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Oroup	Ceiling - Plaster/Drywall	1st Floor - North West Vestibule	250	SF	7	10+ years	Comments
	Doors - Wood Doors include hw	1st Floor - North West Vestibule	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - North West Vestibule	250	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - North West Vestibule	2	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - North West Vestibule	170	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor - North West Vestibule	260	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - South Vestibule	250	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor - South Vestibule	230	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - South Vestibule	250	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - South Vestibule	230	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - South Vestibule	270	SF	6	,	
	Walls - Flaster/Drywall Walls - Structural Glazed Tile	1st Floor - South Vestibule	160	SF	7	10+ years 10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	2,128	SF	7	,	
			2,120 4		7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	· · · · · · · · · · · · · · · · · · ·	EΑ		10+ years	
	Doors - Wood Doors include hw	2nd Floor	3	EΑ	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EΑ	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	2,108	SF	7	6-10 years	One also della
	Floor - Tile/Sheet	2nd Floor	20	SF	4	1-2 years	Cracked tile
	Lighting - Pendent/Surface	2nd Floor	25	EΑ	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	103	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,275	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,925	SF	7	10+ years	
Safety							
•	Camera Viewing Station	Entire Building	1	EA	7	6-10 years	
	Metal Detector	Entire Building	2	EA	7	10+ years	
	Security Cameras	Entire Building	4	EA	7	6-10 years	
	•	Ğ				•	
Stairs	Cailing Disates/Drawall	Decement	62	SF		10	
	Ceiling - Plaster/Drywall	Basement		SF SF	6	10+ years	Damagad
	Ceiling - Plaster/Drywall	Basement	10	SF SF	4	0-1 year	Damaged
	Floor - Concrete	Basement	20	SF LF	7	10+ years	
	Handrails	Basement	50		7	10+ years	
	Lighting - Pendent/Surface	Basement	1	EA LF	7	10+ years	
	Stairs - Concrete	Basement	68	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement	156		6	10+ years	
	Ceiling - Plaster/Drywall	East	560 510	SF SF	7	10+ years	
	Floor - Terrazzo	East			7	10+ years	
	Handrails	East	35	LF	7	10+ years	
	Lighting - Pendent/Surface	East	6	EA	6	6-10 years	
	Stairs - Terrazzo	East	144	LF	7	10+ years	
	Walls - Plaster/Drywall	East	280	SF	7	10+ years	
	Walls - Structural Glazed Tile	East	1,064	SF	7	10+ years	



Catego	ry : Interior	y : Interior				Building : Main					
						Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
	Ceiling - Plaster/Drywall	Main Entrance	560	SF	7	10+ years					
	Floor - Terrazzo	Main Entrance	510	SF	7	10+ years					
	Handrails	Main Entrance	35	LF	7	10+ years					
	Lighting - Pendent/Surface	Main Entrance	6	EA	7	6-10 years					
	Stairs - Terrazzo	Main Entrance	144	LF	7	10+ years					
	Walls - Plaster/Drywall	Main Entrance	280	SF	7	10+ years					
	Walls - Structural Glazed Tile	Main Entrance	1,064	SF	7	10+ years					

Campus Name: Sherwood Page: 17 of 30 Assessment Date: 01/09/2024



Category : Exterior Building : Addition							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	3	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	3	2	EA	6	10+ years	
	Exterior Stairs - Stone	3	6	LF	6	10+ years	
_Foundati	ion						
	Foundation - Concrete	Entire Building	473	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	19,882	SF	7	10+ years	
	Superstructure - Concrete	Entire Building	3	SF	5	0-1 year	Crack/hole in cmu
Lighting							
-5	Exterior Lighting - Parapet or Roof Mounted	Entire Building	10	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	7	10+ years	
Roof Sys	stem						
•	Access Ladder - Metal	F	2	EA	7	10+ years	
	Coping - Stone	F	380	LF	7	10+ years	
	Downspouts - Interior Downspouts	F	75	LF	7	10+ years	
	Parapet - Parapet < 16" Height	F	380	LF	7	10+ years	
	Roof - Modified Bitumen	F	8,466	SF	7	6-10 years	
	Roof Hatch - Metal	F	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	F	8,466	SF	7	10+ years	
Walls							
	Canopy - Metal	Entire Building	100	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	10,150	SF	6	10+ years	
	Exterior Walls - Stone-Cut	Entire Building	1,700	SF	7	10+ years	
Windows							
	Curtain wall - Insulated Panel	Entire Building	267	SF	7	10+ years	Repaired
	Guard - Guards perforated	Entire Building	980	SF	7	10+ years	
	Lintels - Steel	Entire Building	182	LF	7	10+ years	
	Lintels - Stone	Entire Building	172	LF	7	10+ years	
	Storefront Windows	Entire Building	1,485	SF SF	6 7	6-10 years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,118	51	1	6-10 years	
Catego	ry : Electrical		В	uilding	: Addition		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System						



Catego	ry : Electrical		В	uilding	: Additi	on	·
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Corridors and Stairs	Entire Building	3,127	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	Entire Building	1,716	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	2	0-1 year	Exit signs have no battery backup and the school has no emergency generator. Quantity changed to match current observations.
	Exit Signs - Lunchroom	Entire Building	2	EA	2	0-1 year	Exit signs have no battery backup and the school has no emergency generator. Quantity changed to match current observations.
	Security System - CCTV	Entire Building	19,885	SF	6	6-10 years	Rank changed as the system was upgraded since previous assessment.
	Security System - Intrusion Detection	Entire Building	19,885	SF	6	6-10 years	., 0
Main Se	rvice						
	PA System	Entire Building	19,885	SF	6	6-10 years	Served by Main.
Power D	Distribution						
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slots expose live conductors presenting a live front condition (inadequately covered with electrical tape).

Category: Fire Protection Building: Addition

Group -Fire Ala	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	19,885 19,885	SF SF	6 6	6-10 years 6-10 years	FACP is in Main.

Category : Mechanical **Building: Addition**

Group	Item - Type	Location	Quantity		UOM	Rank	Recommend Replacement	Comments
_Air Con	ditioning							
	Chemical Pot Feeder	Site South	1	l	EA	6	10+ years	
	Chiller-Air Cooled-Screw Type-Ground Mounted - 50 - 100 tons	Site South	1		EA	7	10+ years	Item Type, Rank, Reason and Priority Rep changed as the chiller was replaced since previous assessment.
	Glycol Feed	Site South	1		EA	6	6-10 years	

Campus Name: Sherwood Page: 19 of 30 Assessment Date: 01/09/2024



Catego	ry : Mechanical		В	uilding	: Additi	on	245 W 57th STREET, Chicago, IL 60621
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pipes - Chilled Water Pipe- Steel	Site South	100	LF	6	10+ years	
Air Hand	lling Systems						
_All Hall	Indoor Return Fans- Centrifugal Inline -	Attic	1	EA	6	6-10 years	Serves AHU-2. Rank adjusted based
	10001 - 20000 CFM	Attic	I	EA	б	6-10 years	on repairs completed since previous assessment.
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Hot Water Coils - 8001 - 15000 cfm	Basement	1	EA	5	6-10 years	AHU-2, serves Addition.
	Air Intake	Basement	1	EA	5	6-10 years	Dampers are operational but adjusted manually due to nonfunctional DDC control.
	Auxiliaries - 8001 - 15000 cfm	Basement	1	EA	5	6-10 years	oontroi.
	Reheat Boxes - Reheat Boxes with Steam	Basement	7	EA	5	6-10 years	
	Coil	5	40	^	-	0.40	0 17 1 17 11
	Zone Dampers	Basement	19	EA	5	6-10 years	Quantity changed to match current observations. Dampers are operational with many adjusted manually due to nonfunctional DDC control.
	Fan Coil Unit- Floor Mounted - Hot Water and Chilled Water	Entire Building	17	EA	6	6-10 years	Located in closets throughout the building.
Boiler S	vstems						
	Piping - Condensate Pipe- Steel	Basement	400	LF	6	6-10 years	
	Piping - Steam Pipe- Steel	Basement	400	LF	6	6-10 years	
	Steam Traps	Basement	12	EA	5	6-10 years	
	Vacuum Pump	Basement	1	EA	6	6-10 years	
Heat Ex	changers						
	Heat Exchanger - Steam to Hot Water Shell Type	Basement	1	EA	5	6-10 years	
	1,750						
_Heating							
	Wall Heater - Electric	Entire Building	4	EA	5	6-10 years	
	Radiators - Steam	Entire Building	2	EA	5	6-10 years	Located in student restrooms.
	Cabinet Heaters - With Hot Water Coil	Entire Building	1	EA	6	6-10 years	
_Mechan	ical Plumbing						
	Chilled Water Pump - Less than 10	Basement	1	EA	6	6-10 years	Rank adjusted based on repairs completed since previous assessment.
	Chilled Water Pump - Less than 10	Basement	1	EA	6	6-10 years	

Campus Name: Sherwood Page : 20 of 30 Assessment Date: 01/09/2024



Catego	ry : Mechanical	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hot Water Pump - Less than 10	Basement	1	EA	6	6-10 years	
	Hot Water Pump - Less than 10	Basement	1	EA	6	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	200	LF	6	10+ years	
_Tempera	ature Control						
•	DDC System	Entire Building	19,885	SF	4	1-2 years	DDC System is well-outdated and incorporates numerous failure points which software upgrading does not resolve. Temperatures in spaces throughout the building are controlled manually by the Building Engineer.
	Electric Thermostat	Entire Building	17	EA	6	6-10 years	Temperature control for the 17 fan coil units in Addition.
	Thermostats - DDC	Entire Building	22	EA	6	1-2 years	DDC thermostats may be operable but do not communicate with the controls due to failure of the system.
_Ventilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	5	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	

Category : Plumbing **Building: Addition**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er .		•			•	
	Electric Heater - Less than 20 KW	1st Floor	1	EA	6	6-10 years	Serves kitchen (only).
Piping							
. 0	Domestic Piping-Hot Water Return Lines	Entire Building	19,885	SF	6	6-10 years	Domestic hot and cold water is supplied from Main.
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	19,885	SF	6	6-10 years	Domestic hot and cold water is supplied from Main.
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	19,885	SF	6	6-10 years	Domestic hot and cold water is supplied from Main.
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	19,885	SF	6	6-10 years	Domestic hot and cold water is supplied from Main.
	Sanitary Piping	Entire Building	19,885	SF	6	6-10 years	
	Storm Piping	Entire Building	19,885	SF	6	6-10 years	
	Vent Piping	Entire Building	19,885	SF	6	6-10 years	

Page : 21 of 30 Campus Name: Sherwood Assessment Date: 01/09/2024



Category : Plumbing			Building : Addition					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Pumps								
	Pumps - Sump-Simplex	Basement	1	EA	5	6-10 years		

Building : Addition

Catego	ry : Room		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Administ	rative Suites/Offices								
	Ceiling - Plaster/Drywall	1st Floor	323	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years			
	Floor - Tile	1st Floor	323	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	7	EA	5	10+ years	Missing covers		
	Power Distribution	1st Floor	4	EΑ	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	696	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
Kitchen									
	Ceiling - Plaster/Drywall	113	676	SF	7	10+ years			
	Doors - Wood Doors inclu hw	113	1	EA	7	10+ years			
	Floor - Tile	113	676	SF	7	10+ years			
	Lighting - Pendent/Surface	113	7	EΑ	7	10+ years			
	Storage/ Closet	113	100	SF	7	10+ years			
	Walls - Concrete Block	113	936	SF	7	10+ years			
Library									
•	Casework	2nd Floor	50	LF	7	10+ years			
	Ceiling - Splined	2nd Floor	1,084	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	7	10+ years			
	Floor - Carpet	2nd Floor	934	SF	7	6-10 years			
	Floor - Concrete	2nd Floor	150	SF	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor	28	EA	7	10+ years			
	Storage/ Closet	2nd Floor	180	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,650	SF	7	10+ years			
Lunch &	Multipurpose Room								
	Ceiling - Plaster/Drywall	113	1,706	SF	7	10+ years			
	Ceiling - Plaster/Drywall	113	10	SF	6	10+ years			
	Doors - Wood Doors inclu hw	113	3	EA	7	10+ years			
	Floor - Tile	113	1,712	SF	7	10+ years			
	Floor - Tile	113	4	SF	4	1-2 years	Holes in tile		
	Lighting - Pendent/Surface	113	45	EA	7	10+ years			
	Serving Line	113	20	LF	7	10+ years			
	Walls - Plaster/Drywall	113	1,896	SF	7	10+ years			

Campus Name: Sherwood Page : 22 of 30 Assessment Date: 01/09/2024





Category : Room			В	uilding	: Additi	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
echani	cal/ Service Rooms						
	Air Tunnel	Basement	1,800	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	3,600	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	800	SF	7	10+ years	
estroor	n						
CSHOOL	Accessories	1st Floor	140	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	125	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	15	SF	5	1-2 years	Cracked plaster
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	Cracked plaster
	Floor - Tile Ceramic/ Porcelain	1st Floor	135	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	5	SF	4	1-2 years	Missing tile
	Floor Drain	1st Floor	_	EA	7	•	Missing tile
			1		7	10+ years	
	Hand Dryer	1st Floor	2 2	EΑ	7 7	6-10 years	
	Lavatory	1st Floor		EΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EΑ		10+ years	
	Partitions	1st Floor	4	EA	5	6-10 years	
	Walls - Concrete Block	1st Floor	64	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	120	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	178	SF	7	10+ years	
	Water Closet	1st Floor	4	EA	7	10+ years	
	Accessories	2nd Floor	140	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	135	SF	7	10+ years	_
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	0-1 year	Damaged.
	Doors - Wood Doors inclu hw	2nd Floor	4	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	120	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	20	SF	4	1-2 years	Cracked tiles
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	5	0-1 year	Missing cover
	Partitions	2nd Floor	4	EA	5	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	115	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	0-1 year	Damaged.
	Walls - Structural Glazed Tile	2nd Floor	178	SF	7	10+ years	-
	Water Closet	2nd Floor	4	EA	7	10+ years	
	Accessories	2nd Floor	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	45	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	45	SF	4	0-1 year	Old, worn, separating.
	Lavatory	2nd Floor	1	EA	7	10+ years	' · ' · · · · · · · · · · · ·
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years	
	gg	2nd Floor	1	EA	7	o io youro	



Catego	ry : Room		В	uilding	: Additi	on	243 W 37th Office 11, Office 300, 12 00021
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	44	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	4	0-1 year	Damaged
	Water Closet	2nd Floor	1	EA	7	10+ years	
	Accessories	Teacher's Lounge	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Teacher's Lounge	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Teacher's Lounge	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Teacher's Lounge	45	SF	7	10+ years	
	Lavatory	Teacher's Lounge	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	Teacher's Lounge	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	Teacher's Lounge	80	SF	7	10+ years	
	Water Closet	Teacher's Lounge	1	EA	7	10+ years	
		reaction 3 Louringe	'	L/\	,	101 years	
Catego	ry : Classroom		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
-	om #109 (Regular Classroom)		4		- 10		
Oldostor	Casework	1st Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	630	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	150	SF	5	1-2 years	Cracked and bubbling paint
	Chalk Board	1st Floor	40	LF	4	2-5 years	Oracica and bubbling paint
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	6	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,300	SF	7	•	
		1st Floor	1,300	SF	, 5	10+ years	Damagad
	Walls - Plaster/Drywall	1St Floor	08	SF	5	0-1 year	Damaged.
Classroo	om #111 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,318	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	50	SF	6	10+ years	
Classroo	om #116 (Regular Classroom)						
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	7	10+ years	
	Chalk Board	1st Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
			•	_, .	Ŭ	.o. youro	



Catego	Category : Classroom		В	uilding	: Additi	on	243 W 37th 311CE11, Officago, 1E 30321
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	Floor - Tile	1st Floor	780	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	19	EΑ	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EΑ	5	1-2 years	Excessively dim
	Marker Board	1st Floor	20	LF	7	6-10 years	·
	Walls - Plaster/Drywall	1st Floor	1,368	SF	6	10+ years	
Classroo	om #118 (Office)						
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	780	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	776	SF	7	10+ years	
	Floor - Tile	1st Floor	4	SF	4	1-2 years	Missing tile
	Lighting - Pendent/Surface	1st Floor	20	ĒΑ	6	6-10 years	g
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,318	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	50	SF	6	10+ years	Patch and paint
Classroo	om #209 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	778	SF	7	6-10 years	
	Floor - Tile	2nd Floor	2	SF	4	0-1 year	Missing tile
	Lighting - Pendent/Surface	2nd Floor	20	ĒΑ	6	6-10 years	g
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,344	SF	7	10+ years	
Classroo	om #213 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	768	SF	7	6-10 years	
	Floor - Tile	2nd Floor	12	SF	4	1-2 years	Cracked tiles
	Lighting - Pendent/Surface	2nd Floor	20	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,363	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	5	SF	4	0-1 year	Big crack
Classroo	om #215 (Other Instructional Use)						
	Casework	2nd Floor	10	LF	6	10+ years	
	233710111	2.13 . 1001	10		J	.o. youro	



Catego	Category : Classroom		В	uildina	: Additi	240 W 07111 0111 (211, Officago, 12 00021	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	780	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,358	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	4	0-1 year	Big crack
_Classroo	om #216 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	776	SF	7	6-10 years	
	Floor - Tile	2nd Floor	4	SF	4	1-2 years	Chipped tile
	Lighting - Pendent/Surface	2nd Floor	20	ĒΑ	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,364	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	4	SF	5	1-2 years	Cracked
Classroo	om #217 (Regular Classroom)						
Olassioc	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	770	SF	7	6-10 years	
	Floor - Tile	2nd Floor	10	SF	4	0-10 years	Broken tiles
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years	Dioken tiles
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,368	SF	6	10+ years	
Classroo	om #218 (Regular Classroom)						
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	780	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	780	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	20	EA	6	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,368	SF	7	10+ years	
	vvalio - i lastei/Diywali	2110 I 1001	1,300	J.	,	10+ years	





Catego	ry : Interior		В	uilding	: Additi	on	
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	1,368	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	2	EΑ	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	_ 1	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor	1,358	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	10	SF	4	1-2 years	Cracked tile
	Lighting - Pendent/Surface	1st Floor	22	ĒΑ	7	6-10 years	
	Student Lockers - One Tier	1st Floor	79	EΑ	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,200	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,200	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - Vestibule	108	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor - Vestibule	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Vestibule	108	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor - Vestibule	2	EA	5	6-10 years	Missing cover
	Walls - Plaster/Drywall	1st Floor - Vestibule	70	SF	7	10+ years	g 5515.
	Walls - Structural Glazed Tile	1st Floor - Vestibule	120	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,368	SF	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1,000	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,368	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	22	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	79	EΑ	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,200	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,200	SF	7	10+ years	
			-,			, , , , , , , , , , , , , , , , , , , ,	
Safety							
	Security Cameras	Entire Building	3	EA	7	6-10 years	
Stairs	0.11. Di 1.75. II		70			40	
	Ceiling - Plaster/Drywall	Basement	72	SF	6	10+ years	
	Floor - Concrete	Basement	20	SF	7	10+ years	
	Handrails	Basement	50	LF	7	10+ years	
	Lighting - Wall Mounted	Basement	1	EA	6	10+ years	
	Stairs - Concrete	Basement	68	LF	6	10+ years	
	Walls - Concrete Block	Basement	151	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South	348	SF	7	10+ years	
	Floor - Terrazzo	South	263	SF LF	7	10+ years	
	Handrails	South	30		7	10+ years	
	Lighting - Pendent/Surface	South	2	EA	7	6-10 years	
	Stairs - Terrazzo	South	174	LF	7	10+ years	Object of a dec
	Stairs - Terrazzo	South	6	LF	4	1-2 years	Chipped edge
	Walls - Plaster/Drywall	South	510	SF	7	10+ years	
	Walls - Structural Glazed Tile	South	450	SF	7	10+ years	



Category : Site Building : Site

alego	ry : Site			ullaing	. Site		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
hletic							
	Surface - Asphalt	South	3,440	SF	7	10+ years	
	Surface - Asphalt	South	2,000	SF	7	10+ years	
	•		•			·	
vil/Drai	inage						
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	7	10+ years	
	ŭ					·	
encing							
	Fencing - Chain Link	Entire Site	332	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	90	LF	6	10+ years	Trash enclosure.
	Fencing - Chain Link	Entire Site	862	LF	6	6-10 years	
	Fencing - Chain Link	Entire Site	12	LF	4	0-1 year	Fencing curling/bending near we
	3 - 3					, , , , , ,	side of building
	Fencing - Guard Rail	Entire Site	50	LF	6	10+ years	ŭ
	Fencing - New Standard Ornamental	Entire Site	720	LF	6	10+ years	
	-					-	
andsca	pe						
	Benches	Entire Site	3	EA	7	10+ years	
	Landscape - Grass	Entire Site	7,166	SF	7	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	31,400	SF	4	0-1 year	Damaged throughout.
	Landscape - Hardscape- Concrete	Entire Site	4,700	SF	7	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	2,175	SF	4	0-1 year	Cracked/ broken concrete
	Parkway trees	Entire Site	3	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	1,670	SF	7	10+ years	
	Play Area - Hardscape- Asphalt	Entire Site	20,600	SF	7	10+ years	
	Play Area - Synthetic Turf	Entire Site	3,690	SF	7	10+ years	
	Retaining Wall - Concrete	Entire Site	84	SF	7	10+ years	
	Retaining Wall - Concrete	Entire Site	477	SF	7	10+ years	
	Retaining Wall - Concrete	Entire Site	168	SF	7	10+ years	
	Trash Receptacles	Entire Site	4	EA	7	6-10 years	
	Walking Path - Hardscape- Asphalt	Entire Site	935	SF	7	10+ years	
aygrou							
	Equipment - Pre K 3-5	Southeast	1	EA	7	6-10 years	
	Equipment - School Age 5-12	Southeast	1	EA	6	10+ years	
	Equipment - Swingset	Southeast	1	EA	7	10+ years	
	Surface - Poured Surface	Southeast	2,500	SF	6	6-10 years	
المسماا							
dewalk	Sidewalks - Internal Walks	Entire Site	225	LF	4	0-1 year	Cracking concrete
	Siucwaiks - Illiciliai Walks		223	ᆫᄃ	4	u-i yeai	Cracking Concrete



Category : Site			В				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sidewalks - Perimeter Sidewalks	Entire Site	5,516	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	2,240	SF	4	0-1 year	Damaged concrete
_Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EΑ	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	3	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Sherwood Page: 29 of 30 Assessment Date: 01/09/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

Classicom Summary				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Computer Lab	Library	2nd Floor	201	201	750	101	37	Υ	N
Kindergarten	Kindergarten	1st Floor	105	105	1,114	219	83	Υ	Υ
Kindergarten	Regular Classroom	1st Floor	106	106	750	135	59	Υ	Υ
Pre School	Regular Classroom	1st Floor	102	102	992	162	70	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	107	107	750	135	59	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	750	135	59	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	750	135	59	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	750	135	59	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	206	206	750	135	59	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	750	135	59	Y	Y
Science Classroom	Science Classroom	2nd Floor	202	202	750	135	59	Y	Y
Store Room	Regular Classroom	1st Floor	104	104	750	135	59	Υ	N
Building : Addition		T	1	T	1	1			т
Office	Regular Classroom	1st Floor	118	118	780	168	68	Y	N
Other Instructional Use	Regular Classroom	2nd Floor	215	215	780	168	68	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	109	109	780	168	68	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	111	111	780	168	68	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	116	116	780	168	68	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	209	209	780	168	68	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	780	168	68	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	216	216	780	168	68	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	217	217	780	168	68	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	218	218	780	168	68	Υ	Υ