

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1926	2	88,546
Addition	2007	2	36,007
Campus Total			124,553

Category : Exterior Building : Main

	W		0	LIONA		Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Entrance							
	Entrance Control - Audio	Door 10 - Courtyard Southwest	1	EA	4	2-5 years	Corroding
	Exterior Doors - Store Front	Door 10 - Courtyard Southwest	2	EA	5	1-2 years	Corroding frames
	Exterior Doors - Transom Lite	Door 10 - Courtyard Southwest	1	EA	6	6-10 years	
	Exterior Stairs - Stone	Door 10 - Courtyard Southwest	6	LF	7	10+ years	
	Exterior Doors - Store Front	Door 11 - Courtyard Southeast	2	EA	5	1-2 years	Corroding frames
	Exterior Doors - Transom Lite	Door 11 - Courtyard Southeast	1	EA	6	6-10 years	
	Exterior Stairs - Stone	Door 11 - Courtyard Southeast	6	LF	6	10+ years	
	Exterior Doors - Store Front	Door 2 - East	2	EA	5	1-2 years	Corroded door frames
	Exterior Stairs - Stone	Door 2 - East	60	LF	5	10+ years	
	Exterior Doors - Exterior Steel Door	Door 20 - Boiler South	2	EΑ	6	6-10 years	
	Exterior Stairs - Concrete	Door 20 - Boiler South	5	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 21 - Boiler North	1	EΑ	6	6-10 years	
	Exterior Stairs - Stone	Door 21 - Boiler North	5	LF	5	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 3 - Southeast	2	EΑ	6	6-10 years	
	Exterior Doors - Transom Lite	Door 3 - Southeast	1	EA	6	6-10 years	
	Exterior Stairs - Stone	Door 3 - Southeast	20	LF	7	10+ years	Repaired
	Exterior Stairs - Stone	Door 3 - Southeast	40	LF	7	10+ years	Repaired
	Exterior Doors - Store Front	Door 4 - Southeast	2	EΑ	5	1-2 years	Corroded frames
	Exterior Doors - Transom Lite	Door 4 - Southeast	1	EA	5	1-2 years	Corroded
	Exterior Stairs - Stone	Door 4 - Southeast	58	LF	6	6-10 years	Repaired
	Exterior Doors - Store Front	Door 5 - South center	1	EA	5	1-2 years	Corroding frames
	Exterior Doors - Transom Lite	Door 5 - South center	1	EA	7	6-10 years	-
	Exterior Stairs - Stone	Door 5 - South center	4	LF	6	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ramp Handrail - Steel_Ramp Handrail	Door 5 - South center	42	LF	7	10+ years	New
	Ramps - Concrete	Door 5 - South center	21	LF	7	10+ years	New
	Entrance Control - Audio	Door 6 - Southwest	1	EA	6	6-10 years	
	Exterior Doors - Store Front	Door 6 - Southwest	2	EA	5	1-2 years	Corroded doors and frames
	Exterior Doors - Transom Lite	Door 6 - Southwest	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 6 - Southwest	72	LF	7	10+ years	New
	Ramp Handrail - Steel_Ramp Handrail	Door 6 - Southwest	168	LF	7	10+ years	New
	Ramps - Concrete	Door 6 - Southwest	84	LF	7	10+ years	New
	Stair Handrail - Steel_Stair Handrail	Door 6 - Southwest	32	LF	6	6-10 years	New
	Exterior Doors - Store Front	Door 7 - Southwest	2	EA	5	1-2 years	Corroded frame
	Exterior Doors - Transom Lite	Door 7 - Southwest	1	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 7 - Southwest	11	LF	7	10+ years	
	Exterior Stairs - Concrete	Door 7 - Southwest	1	LF	5	1-2 years	Cracked concrete
	Exterior Stairs - Stone	Door 7 - Southwest	54	LF	6	10+ years	
	Exterior Doors - Store Front	Door 8 Northwest	2	ĒΑ	6	6-10 years	
	Exterior Stairs - Stone	Door 8 Northwest	60	LF	6	10+ years	Repaired
	Exterior Doors - Store Front	Door 9 - Courtyard west	2	ĒΑ	6	6-10 years	
	Exterior Doors - Transom Lite	Door 9 - Courtyard west	_ 1	EA	6	6-10 years	
	Exterior Stairs - Concrete	Door 9 - Courtyard west	6	LF	6	10+ years	
Foundati	on Foundation - Concrete	Entire Building	1,463	LF	7	10+ years	
	Foundation - Concrete	Entire Building	30	LF	6	10+ years	Cracked foundation seeping water. Some of the foundation was repaired
							by the engineer. This was done by fixing the exterior stairs that needed sealing. there is still one area near the courtyard that gets leaks. Replaced 80 feet to the general foundation number. Recombined quantities and changed rank based on current conditions
	Superstructure - Concrete	Entire Building	88,346	SF	7	10+ years	
Lighting							
5 -5	Exterior Lighting - Parapet or Roof Mounted	Entire Building	17	EA	7	6-10 years	Refurbished fixture with LED
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	5	1-2 years	Light does not face the landscape. It is facing the roof.
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	7	6-10 years	Refurbished fixture with LED
Roof Sys	stem						
TYOU OVE		D (4	70	LF	7	40	
_ROOL Gys	Coping - Metal	Roof 1	70	ᄕ	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Terra Cotta	Roof 1	13	LF	5	1-2 years	Cracked, broken terra-cotta
	Downspouts - Interior Downspouts	Roof 1	420	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 1	127	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 1	40	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 1	983	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	32,545	SF	6	2-5 years	
	Roof - Modified Bitumen	Roof 1	200	SF	4	1-2 years	Soft spots, blistering, open seams
	Roof Structure - Concrete	Roof 1	32,745	SF	7	10+ years	
	Access Ladder - Metal	Roof 2	1	EA	7	10+ years	
	Coping - Terra Cotta	Roof 2	130	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 2	35	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 2	130	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 2	4,130	SF	6	6-10 years	
	Roof - Modified Bitumen	Roof 2	100	SF	4	0-1 year	Soft spots, open seams, blistering
	Roof Structure - Concrete	Roof 2	4,230	SF	7	10+ years	
	Coping - Terra Cotta	Roof 3	30	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	20	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 3	30	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3	150	SF	6	10+ years	
	Roof Structure - Concrete	Roof 3	150	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 4 - Boiler	20	LF	7	10+ years	Repaired
	Chimney - Metal Flue	Roof 4 - Boiler	18	LF	7	10+ years	Corrected quantity
	Coping - Terra Cotta	Roof 4 - Boiler	205	LF	7	10+ years	,
	Downspouts - Interior Downspouts	Roof 4 - Boiler	25	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 4 - Boiler	105	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof 4 - Boiler	50	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 4 - Boiler	50	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 4 - Boiler	2,667	SF	7	10+ years	
	Roof - Modified Bitumen	Roof 4 - Boiler	25	SF	5	2-5 years	Blistering
	Roof Structure - Concrete	Roof 4 - Boiler	600	SF	7	10+ years	C
	Roof Structure - Concrete	Roof 4 - Boiler	2,092	SF	7	10+ years	
						•	
_Walls							
	Cheek-Wall - Concrete	Entire Building	20	SF	6	10+ years	
	Cheek-Wall - Stone	Entire Building	100	SF	6	10+ years	
	Cornice - Terra Cotta	Entire Building	100	LF	7	10+ years	
	Cornice - Terra Cotta	Entire Building	40	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	92,320	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	10	SF	4	1-2 years	Open joints
	Exterior Walls - Stone-Cut	Entire Building	3,363	SF	6	10+ years	Corrected item type
	Exterior Walls - Stone-Cut	Entire Building	500	SF	5	10+ years	Corrected item type
	Exterior Walls - Stone-Cut	Entire Building	10	SF	3	1-2 years	Broken stone, missing sections. Corrected item type

Campus Name: Shoop Page : 3 of 50 Assessment Date: 01/31/2024



Windows

Category : Exterior

Group Item - Type

Guard - Guards perforated

John D Shoop Math-Science Technical Academy ES 11140 S Bishop STREET, Chicago, IL 60643

Replacement Comments

Recommend

6-10 years

Building: Main

Rank

6

UOM

SF

Quantity

3,564

	Guard - Guards wire guard Lintels - Steel Lintels - Stone Windows - Louver Windows - Sash Aluminum Double-pane Windows - Sash Aluminum Double-pane	Entire Building	216 984 88 25 8,022	SF LF LF SF SF	6 7 7 7 6 3	6-10 years 10+ years 10+ years 10+ years 6-10 years 1-2 years	New Falling off frames
Categor	y : Electrical		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emergen	Cy System	Dailar Daam	4	ΕΛ	7	10	Depositly installed
	Automatic Transfer Switch Emergency A/C Power - Auditoium and	Boiler Room Entire Building	1 3,765	EA SF	7 7	10+ years 6-10 years	Recently installed
	Aisle Lighting Emergency A/C Power - Corridors and Stairs	Entire Building	12,247	SF	7	6-10 years	
	Emergency A/C Power - Gym	Entire Building	2,760	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	1	SF	6	1-2 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	8	ĒA	7	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	52	EA	7	6-10 years	Battery packs replaced last month
	Emergency Battery Packs - Corridors and Stairs	Entire Building	1	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	6	EA	7	6-10 years	Quantity updating to reflect observed conditions.
	Emergency Battery Packs - Students Toilets	Entire Building	8	EA	7	6-10 years	0011011101101
	Exit Signs - Auditoium	Entire Building	8	EA	7	6-10 years	Quantity updated to reflect observed conditions
	Exit Signs - Corridors and Stairs	Entire Building	37	EA	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	5	EA	4	0-1 year	Sign is faded affecting legibility
	Exit Signs - Gym	Entire Building	3	EA	6	6-10 years	Quantity updated to reflect observed conditions.
	Security System - CCTV	Entire Building	88,546	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	88,546	SF	6	6-10 years	
Main Ser	vice						
	Main Electrical Service - 1200 A 120/208/3PH	Boiler Room	1	EA	6	10+ years	
	Main Electrical Service - 1200 A	Boiler Room	1	EA	4	0-1 year	Corroded in room with duplex sump
Campus N	ame: Shoop		Page : 4 of 50				Assessment Date: 01/31/202

Location

Entire Building



Catego	ry : Electrical		B	uilding	: Main		
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	120/208/3PH						pump
	Independent Electrical Service for	Electrical Room	1	EA	7	10+ years	T · · · ·
	emergency power					, , , , , ,	
	PA System	Entire Building	88,546	SF	6	6-10 years	PA system served by main office in
	,	ű	,			,	addition
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	MDF
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Vintage unlabeled, 100A panel
		_				-	outside of room 105
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	6-10 years	Vintage unlabeled panel in boiler
							room behind distribution panel PDP
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	1-2 years	Vintage unlabeled, load center in
							auditorium hall, inaccessible, door
							damaged
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	Unlabeled load center near
							distribution panel BRPP2 is live fror
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	EM-1 is live front
	Lighting and Power Panels - 100 A	Entire Building	1	EA	4	0-1 year	Vintage unlabeled fused 100A pane
							in basement is live front
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	PP-1
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	2-5 years	Vintage panel LP-R2 AC-1
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	Vintage unlabeled panels in hallway
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Vintage unlabeled 200A panel in
							auditorium hall is live front
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	HDP EHP
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	BRPP2 400A
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	10+ years	PDP 1200A
	amp						
	Main Distribution Panels - Less than 400	Entire Building	1	EA	6	6-10 years	Vintage unlabeled 275A, distribution
	amp						panel
`atono	ry : Fire Protection		B	uilding	· Main		
Jaiego	ry . I lie i lotection			unung	. Walli	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ire Alar		Location	quantity	00111	Ram	Ropidoomont	Comments
iie Aidi	Fire ALarm Anunciator	Basement	1	EA	6	10+ years	
	Fire Alarm Panel	Basement	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Basement	88,546	SF	6	6-10 years	
	Fire Alarm_Strobe Lights Fire Alarm_System	Basement	88,546	SF SF	6	6-10 years	
	i iie Alaitti_Systetti	שמשוושווו	00,340	ЭF	O	0-10 years	
	m Maakaniaal		ь	uilding	· Main		
Catego	ry : Mechanical		D	unamq	. IVIAIII		



						Replacement	
Cond	itioning Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	6	6-10 years	
Hand	ling Systems						
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	SF-1
	Air Intake	Mechanical Room	1	EA	2	10+ years	OA dampers are inoperable and clogged with debris from at grade intake
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	5	EA	6	10+ years	Steam trap and condensate valve non-functional
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	200	LF	6	10+ years	
	Zone Dampers	Mechanical Room	12	EA	6	10+ years	Zone, dampers operate via DC control, however, there is no temperature control through stean valve actuators
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	SF-4
	Air Intake	Mechanical Room	1	EA	2	10+ years	Air intake is at grade near, parked cars, and clogged with debris
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	Coil bypass damper actuator in operable
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	6	EA	5	10+ years	Steam valve does not respond to BAS, steam valve is locked open, thermal control.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	200	LF	5	10+ years	
	Zone Dampers	Mechanical Room	18	EA	6	10+ years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	6	10+ years	SF-2
	Air Intake	Mechanical Room	1	EA	2	10+ years	Air intake is at grade near, parked cars, and clogged with debris
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	6	10+ years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	9	EA	5	10+ years	No heat control from BAS, steam valve is locked open
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	250	LF	6	6-10 years	
	Zone Dampers	Mechanical Room	30	EA	6	10+ years	
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	SF-3 Classrooms
	Air Intake	Mechanical Room	1	EA	2	0-1 year	Air intake is at grade near, parked cars, and clogged with debris
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	



	CHOOIS						1140 S Bishop STREET, Chicago, IL 60643
						Replacement	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	100	LF	4	0-1 year	Dampers are rusted closed, Air intake is at grade near, parked cars, and clogged with debris
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	Sf-5 Serves gymnasium
	Air Intake	Mechanical Room	1	EA	2	10+ years	Air intake is at grade near, parked cars, and clogged with debris
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	6	10+ years	care, and enegged min decine
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	200	LF	7	10+ years	
Boiler Sy	stems						
Í	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Feed System	Boiler Room	1	EA	4	10+ years	Old chemical feed, abandoned, new chemical feed installed 2021 per last assessment.
	Chemical Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	7	2-5 years	Installed brand new
	Condensate Pump	Boiler Room	1	EA	6	10+ years	
	Condensate Pump	Boiler Room	1	EA	5	10+ years	Serves steam to hot water heat exchanger
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	2-5 years	Make up water, pressure fill system for hot water loop Not included in previous assessment.
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	10+ years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	7	10+ years	B-1
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	7	10+ years	B-2
	Piping - Condensate Pipe- Steel	Boiler Room	500	LF	5	6-10 years	Very corroded, uninsulated
	Piping - Steam Pipe- Steel	Boiler Room	500	LF	6	10+ years	
	Steam Traps	Boiler Room	50	EA	4	2-5 years	Many nonfunctional, need to be repaired or replaced
Heat Exc	•						
	Heat Exchanger - Steam to Hot Water Shell Type	Boiler Room	1	EA	6	10+ years	Minimal insulation missing
Heating I	Devices						
	Unit Heater - Gas	Boiler Room	1	EA	7	6-10 years	Installed brand new
	Unit Heater - Gas	Boiler Room	1	EA	2	0-1 year	Existing gas fired unit heater abandoned in place. Brand new replacement unit already installed per assessment observation.
							assessifierit observation.

Campus Name: Shoop Page: 7 of 50 Assessment Date: 01/31/2024



						Replacement	
	Wall Heater - Electric	Entire Building	5	EA	2	0-1 year	Nonfunctional
	Radiators - Steam	Entire Building	11	EA	5	2-5 years	
	Radiators - Steam	Entire Building	2	EA	5	2-5 years	
	Fin Tube - Steam	Entire Building	8	LF	6	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	4	EA	6	10+ years	
_Mechanic	al Plumbing						
	Hydronic Supply and Return - Copper	Basement	450	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Basement	150	LF	6	10+ years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	10+ years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	10+ years	
_Temperat	ture Control						
·	DDC System	Entire Building	88,546	SF	6	6-10 years	Reheat box, steam valve, actuator, locked open, no control from BAS. All manual control.
	Electric Thermostat	Entire Building	1	EA	7	6-10 years	
	Thermostats - DDC	Entire Building	59	EA	6	6-10 years	
<u>Ventilatio</u>	n						
	Exhaust Fans- Indoor - Less than 500 CFM	Boiler Room	1	EA	7	6-10 years	Installed brand new
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	4	EA	5	6-10 years	Two exhaust fans, non-operational at time of assessment

Category: Plumbing Building: Main

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	•	Location	Quantity	00111	Rank	Replacement	Comments
_HOL Wall	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	7	10+ years	Replaced new in 2021
Piping							
_, _	Domestic Piping-Hot Water Return Lines	Entire Building	88,546	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	88,546	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	88,546	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	88,546	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	88,546	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	88,546	SF	6	10+ years	
	Sanitary Piping	Entire Building	88,546	SF	6	10+ years	
	Storm Piping	Entire Building	88,546	SF	5	10+ years	
	Vent Piping	Entire Building	88,546	SF	6	10+ years	

Campus Name: Shoop Page : 8 of 50 Assessment Date: 01/31/2024



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Pumps							
	Pumps - Domestic Booster Pump-Simplex	Entire Building	1	EA	2	0-1 year	Booster pump system failed, abandoned in place
	Pumps - Sump-Duplex	Entire Building	1	EA	6	10+ years	Replaced new within the last year
	Pumps - Sump-Duplex	Entire Building	1	EA	5	6-10 years	Located in same service entrance closet room as ATS One pump motor has been recently replaced,
	Pumps - Sump-Simplex	Entire Building	4	EA	7	10+ years	Replaced a year before time of assessment
	Pumps - Sump-Simplex	Entire Building	1	EA	5	10+ years	Residential style pump connected to power via insulated cord.

Category : Room Building : Main							
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	AC Unit	113 Office	1	EA	7	10+ years	Not previously assessed
	Ceiling - Plaster/Drywall	113 Office	257	SF	7	10+ years	Not previously assessed
	Doors - Steel Doors incl hw	113 Office	1	EA	7	10+ years	Not previously assessed
	Floor - Tile	113 Office	257	SF	7	10+ years	Not previously assessed
	Lighting - Pendent/Surface	113 Office	4	EΑ	7	10+ years	Not previously assessed
	Walls - Plaster/Drywall	113 Office	837	SF	7	10+ years	Not previously assessed
	Ceiling - Plaster/Drywall	1st Floor-Classroom 123A Office	125	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor-Classroom 123A Office	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor-Classroom 123A Office	125	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-Classroom 123A Office	2	EA	7	6-10 years	
	Power Distribution	1st Floor-Classroom 123A Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Classroom 123A Office	600	SF	6	10+ years	
	AC Unit	1st Floor-Counselor's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Counselor's Office	345	SF	7	10+ years	
	Doors - Transom Window	1st Floor-Counselor's Office	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Counselor's Office	1	EA	6	10+ years	
	Floor - Carpet	1st Floor-Counselor's Office	345	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Counselor's Office	4	EA	6	6-10 years	
	Power Distribution	1st Floor-Counselor's Office	12	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Counselor's Office	880	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-Counselor's Office	10	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Gym Office Storage	570	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Gym Office Storage	2	EA	6	10+ years	
	Floor - Terrazzo	1st Floor-Gym Office Storage	145	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Gym Office Storage	425	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-Gym Office Storage	5	EA	5	6-10 years	
	Walls - Masonry	1st Floor-Gym Office Storage	450	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-Gym Office Storage	370	SF	6	10+ years	

Campus Name: Shoop Page : 9 of 50 Assessment Date: 01/31/2024



Catego	Category : Room		В	uilding	: Main		· · · · · · · · · · · · · · · · · · ·		
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Work Sink	1st Floor-Gym Office Storage	1	EA	7	2-5 years			
	Ceiling - Plaster/Drywall	222 Adjustment Room	270	SF	6	10+ years			
	Ceiling - Plaster/Drywall	222 Adjustment Room	10	SF	4	0-1 year	Water damage, broken plaster, strong smell		
	Doors - Wood Doors inclu hw	222 Adjustment Room	1	EA	6	10+ years			
	Floor - Terrazzo	222 Adjustment Room	10	SF	6	10+ years			
	Floor - Tile	222 Adjustment Room	280	SF	6	10+ years			
	Lighting - Pendent/Surface	222 Adjustment Room	2	ĒA	7	6-10 years			
	Power Distribution	222 Adjustment Room	6	EA	7	10+ years			
	Walls - Plaster/Drywall	222 Adjustment Room	607	SF	6	10+ years			
	Walls - Plaster/Drywall	222 Adjustment Room	5	SF	4	0-1 year	Water damage causing plaster to sag, strong smell		
	Ceiling - Plaster/Drywall	2nd Floor - Teacher's Lounge	401	SF	7	10+ years	3		
	Doors - Wood Doors inclu hw	2nd Floor - Teacher's Lounge	1	ĒA	6	10+ years			
	Floor - Carpet	2nd Floor - Teacher's Lounge	401	SF	6	6-10 years			
	Lighting - Pendent/Surface	2nd Floor - Teacher's Lounge	5	ĒΑ	7	6-10 years			
	Power Distribution	2nd Floor - Teacher's Lounge	8	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor - Teacher's Lounge	913	SF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor Office inside Adjustment Room	121	SF	6	6-10 years			
	Doors - Side-lite	2nd Floor Office inside Adjustment Room	12	SF	7	10+ years	Not previously assessed		
	Doors - Transom Window	2nd Floor Office inside Adjustment Room	8	SF	6	10+ years			
	Floor - Concrete Epoxy/ Painted	2nd Floor Office inside Adjustment Room	116	SF	7	10+ years			
	Floor - Terrazzo	2nd Floor Office inside Adjustment Room	5	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor Office inside Adjustment Room	1	EA	7	6-10 years			
	Power Distribution	2nd Floor Office inside Adjustment Room	6	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor Office inside Adjustment Room	396	SF	6	10+ years			
	Work Sink	2nd Floor Office inside Adjustment Room	1	EA	7	10+ years			
	Ceiling - Plaster/Drywall	Engineers Office in Boiler Room	71	SF	6	10+ years			
	Ceiling - Plaster/Drywall	Engineers Office in Boiler Room	50	SF	5	1-2 years	Damage		
	Doors - Wood Doors inclu hw	Engineers Office in Boiler Room	2	ĒΑ	6	10+ years	ŭ		
	Floor - Tile	Engineers Office in Boiler Room	121	SF	6	10+ years			
	Lighting - Pendent/Surface	Engineers Office in Boiler Room	3	ĒΑ	7	6-10 years			
	Power Distribution	Engineers Office in Boiler Room	6	EA	7	10+ years			
	Walls - Plaster/Drywall	Engineers Office in Boiler Room	434	SF	6	10+ years			
	Walls - Plaster/Drywall	Engineers Office in Boiler Room	50	SF	5	1-2 years	Damage		

Campus Name: Shoop Page : 10 of 50 Assessment Date: 01/31/2024



Category : Room			В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Work SInk	Engineers Office in Boiler Room	1	EA	7	10+ years		
ditari.	m & Theater							
Auditorit		4-4-51	0.4	Ε.Δ		40		
	Balcony Seating	1st Floor	84	EA	5	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	3,765	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	9	EA	6	10+ years		
	Floor - Carpet	1st Floor	1,150	SF	6	6-10 years		
	Floor - Concrete Epoxy/ Painted	1st Floor	1,805	SF	5	10+ years		
	Floor - Terrazzo	1st Floor	215	SF	6	10+ years		
	Floor - Wood	1st Floor	595	SF	6	10+ years		
	Lighting - Chandelier, Incandescent	1st Floor	6	EA	6	6-10 years		
	Lighting - Lay-in	1st Floor	8	EA	6	6-10 years		
	Lighting - Pendent/Surface	1st Floor	9	EA	6	6-10 years		
	Lighting - Wall Mounted	1st Floor	19	EA	6	6-10 years		
	Main Floor Seating	1st Floor	288	EA	7	10+ years	Quantity updated	
	Sound System	1st Floor	1	EA	7	6-10 years		
	Stage	1st Floor	595	SF	6	10+ years		
	Stage Curtain	1st Floor	6	ĒΑ	7	6-10 years		
	Stage Lighting System	1st Floor	1	EA	7	6-10 years		
	Stage-Stairs - Terrazzo	1st Floor	24	LF	6	10+ years		
	Stage-Stairs - Wood	1st Floor	10	LF	6	10+ years		
	Stairs - Asphalt	1st Floor	58	LF	6	10+ years		
	Storage/ Closet	1st Floor	78	SF	7	10+ years		
	Walls - Metal Panel	1st Floor	590	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	6,895	SF	6	10+ years		
	Walls Tlastel/Blywall	13(1100)	0,000	O.	O	101 years		
Symnas								
	Bleacher Seating	1st Floor	6	EA	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	2,750	SF	6	10+ years		
	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Water damage	
	Doors - Transom Window	1st Floor	24	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years		
	Floor - Wood	1st Floor	2,760	SF	6	10+ years		
	Lighting - Pendent/Surface	1st Floor	32	EA	7	6-10 years		
	Student Lockers - One Tier	1st Floor	12	EA	6	10+ years		
	Walls - Masonry	1st Floor	1,540	SF	6	10+ years		
	Walls - Plaster/Drywall	1st Floor	4,620	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor	20	SF	6	10+ years	Narrow crack and chipping pain	
_	·					•	31	
ibrary	A C I Init	Danim 24.4/04.0			7	0.40		
	AC Unit	Room 214/216	2	EA	7	6-10 years		
	Casework	Room 214/216	70	LF	6	10+ years		
	Ceiling - Plaster/Drywall	Room 214/216	1,454	SF	6	10+ years		



Category : Room		В	uilding	: Main				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Doors - Transom Window	Room 214/216	9	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Room 214/216	2	EA	6	10+ years		
	Floor - Carpet	Room 214/216	1,443	SF	4	1-2 years	Carpet is torn, stained, and bubbling	
	Lighting - Pendent/Surface	Room 214/216	24	EA	7	6-10 years		
	Walls - Plaster/Drywall	Room 214/216	1,859	SF	6	10+ years		
MDF ID	F							
_	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years		
	Finishes	2nd Floor	75	SF	7	10+ years		
	Window AC Unit	2nd Floor	1	EA	7	6-10 years		
Mechani	ical/ Service Rooms							
IIII	Janitor's Closet	1st Floor	15	SF	7	10+ years		
	Janitor's Closet	1st Floor	8	SF	7	10+ years		
	Storage Room	1st Floor	390	SF	7	10+ years		
	Storage Room	1st Floor	50	SF	7	10+ years		
	Janitor's Closet	2nd Floor	40	SF	7	10+ years	No keys, cannot access	
	Janitor's Closet	2nd Floor	40	SF	7	10+ years	No keys, carnot access	
	Air Tunnel	Basement	8,500	SF	7	10+ years	Not previously assessed	
	Auditorium Plenums	Basement	3,765	SF	7	10+ years	Not previously assessed	
	Boiler Room		2,500	SF			Standing water at basement entrance	
		Basement		SF SF	5	10+ years		
	Coal Room	Basement	1,500	SF SF	7	10+ years	Not previously assessed	
	Crawl Space - Unfinished Mechanical/ Service Rooms	Basement Basement	19,700 5,000	SF SF	7 7	10+ years 10+ years	Not previously assessed Not previously assessed	
	Mechanical/ Service Rooms	Dasement	3,000	OI .	,	10+ years	Not previously assessed	
Restroor								
	Accessories	1st Floor-Classroom 118 Restroom	54	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor-Classroom 118 Restroom	54	SF	6	10+ years		
	Doors - Wood Doors inclu hw	1st Floor-Classroom 118 Restroom	2	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor-Classroom 118 Restroom	54	SF	6	10+ years		
	Hand Dryer	1st Floor-Classroom 118 Restroom	1	EA	7	6-10 years		
	Lavatory	1st Floor-Classroom 118 Restroom	1	EA	6	10+ years		
	Lighting - Pendent/Surface	1st Floor-Classroom 118 Restroom	1	EA	6	6-10 years		
	Partitions	1st Floor-Classroom 118 Restroom	1	EA	7	10+ years		
	Walls - Plaster/Drywall	1st Floor-Classroom 118 Restroom	390	SF	6	2-5 years		
	Water Closet	1st Floor-Classroom 118 Restroom	1	EA	6	10+ years		
	Accessories	1st Floor-Counselor's Office Restroom	28	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st Floor-Counselor's Office	28	SF	6	10+ years		
	Doors - Wood Doors inclu hw	Restroom 1st Floor-Counselor's Office	1	EA	6	10+ years		
	Floor - Tile Ceramic/ Porcelain	Restroom 1st Floor-Counselor's Office	28	SF	6	-		
	Floor - The Geramic/ Porcelain	15t Floor-Counselors Office	28	SF	0	10+ years		



Catego	egory : Room			uilding	: Main		. · · · · · · · · · · · · · · · · · · ·		
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_	<u>.</u>	Restroom				<u> </u>			
	Lavatory	1st Floor-Counselor's Office	1	EA	6	10+ years			
	•	Restroom				•			
	Lighting - Wall Mounted	1st Floor-Counselor's Office	1	EA	6	6-10 years	Re-lamp fixture		
		Restroom				•	·		
	Walls - Plaster/Drywall	1st Floor-Counselor's Office	268	SF	6	10+ years			
	•	Restroom				•			
	Water Closet	1st Floor-Counselor's Office	1	EA	6	10+ years			
		Restroom				•			
	Accessories	1st Floor-E Boy's Restroom	389	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor-E Boy's Restroom	389	SF	6	10+ years			
	Doors - Side-lite	1st Floor-E Boy's Restroom	42	SF	6	10+ years			
	Doors - Transom Window	1st Floor-E Boy's Restroom	18	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor-E Boy's Restroom	389	SF	6	10+ years			
	Floor Drain	1st Floor-E Boy's Restroom	1	EA	7	10+ years			
	Hand Dryer	1st Floor-E Boy's Restroom	1	EΑ	7	6-10 years			
	Lavatory	1st Floor-E Boy's Restroom	3	EΑ	6	10+ years			
	Lighting - Pendent/Surface	1st Floor-E Boy's Restroom	5	EΑ	6	6-10 years			
	Partitions	1st Floor-E Boy's Restroom	3	EA	7	10+ years			
	Urinals	1st Floor-E Boy's Restroom	6	EA	6	10+ years			
	Walls - Masonry	1st Floor-E Boy's Restroom	280	SF	6	10+ years			
	Walls - Masority Walls - Plaster/Drywall	1st Floor-E Boy's Restroom	560	SF	6	10+ years			
	Walls - Structural Glazed Tile	1st Floor-E Boy's Restroom	135	SF	6	10+ years			
	Water Closet	1st Floor-E Boy's Restroom	3	EA	6	10+ years			
	Accessories	1st Floor-E Girl's Restroom	356	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor-E Girl's Restroom	340	SF	7	•			
	Ceiling - Plaster/Drywall	1st Floor-E Girl's Restroom	16	SF	6	10+ years	Peeling, bubbling, and chipping paint		
	Doors - Side-lite		21	SF		10+ years	reening, bubbling, and chipping paint		
		1st Floor-E Girl's Restroom	18	SF SF	6 6	10+ years			
	Doors - Transom Window Floor - Tile Ceramic/ Porcelain	1st Floor-E Girl's Restroom	356	SF SF		10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor-E Girl's Restroom 1st Floor-E Girl's Restroom	336	SF EA	6 7	10+ years			
			1			10+ years			
	Hand Dryer	1st Floor-E Girl's Restroom	•	EA	7	6-10 years			
	Lavatory	1st Floor-E Girl's Restroom	3	EA	6	10+ years			
	Lighting - Pendent/Surface	1st Floor-E Girl's Restroom	6	EΑ	6	6-10 years			
	Partitions	1st Floor-E Girl's Restroom	7	EA	7	10+ years			
	Walls - Masonry	1st Floor-E Girl's Restroom	460	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor-E Girl's Restroom	835	SF	6	10+ years			
	Water Closet	1st Floor-E Girl's Restroom	7	EA	6	10+ years			
	Accessories	1st Floor-Men's Auditorium	80	SF	5	2-5 years	Not used		
		Restroom Used as storage							
	Ceiling - Plaster/Drywall	1st Floor-Men's Auditorium	80	SF	5	10+ years			
		Restroom Used as storage							
	Doors - Wood Doors inclu hw	1st Floor-Men's Auditorium	1	EA	6	10+ years			
		Restroom Used as storage							



Categoi	ategory : Room			uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile Ceramic/ Porcelain	1st Floor-Men's Auditorium	80	SF	6	10+ years	
		Restroom Used as storage					
	Lavatory	1st Floor-Men's Auditorium	1	EA	5	2-5 years	Not used
		Restroom Used as storage					
	Lighting - Pendent/Surface	1st Floor-Men's Auditorium	1	EA	6	6-10 years	
		Restroom Used as storage					
	Partitions	1st Floor-Men's Auditorium	1	EA	5	2-5 years	Not used
		Restroom Used as storage				,	
	Walls - Masonry	1st Floor-Men's Auditorium	100	SF	6	10+ years	
	,	Restroom Used as storage			•	, , , , , , , , , , , , , , , , , , , ,	
	Walls - Plaster/Drywall	1st Floor-Men's Auditorium	115	SF	6	10+ years	
	Walls Tlaster/Drywall	Restroom Used as storage	110	Oi.	O	101 years	
	Water Closet	1st Floor-Men's Auditorium	1	EA	6	2-5 years	Not used
	Water Closet	Restroom Used as storage	'	LA	O	2-5 years	Not used
	A		200	C.E.	7	C 40	
	Accessories	1st Floor-W Boy's Restroom	300	SF SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-W Boy's Restroom	270		7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor-W Boy's Restroom	30	SF	6	10+ years	Cracking and chipping paint
	Doors - Steel Doors incl hw	1st Floor-W Boy's Restroom	2	EA	6	10+ years	
	Doors - Transom Window	1st Floor-W Boy's Restroom	18	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-W Boy's Restroom	300	SF	6	10+ years	
	Floor Drain	1st Floor-W Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-W Boy's Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-W Boy's Restroom	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-W Boy's Restroom	5	EA	7	6-10 years	
	Partitions	1st Floor-W Boy's Restroom	2	EA	7	10+ years	
	Urinals	1st Floor-W Boy's Restroom	6	EA	6	10+ years	
	Walls - Masonry	1st Floor-W Boy's Restroom	290	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-W Boy's Restroom	560	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor-W Boy's Restroom	130	SF	6	10+ years	
	Water Closet	1st Floor-W Boy's Restroom	2	EA	6	10+ years	
	Accessories	1st Floor-W Girl's Restroom	205	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-W Girl's Restroom	205	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor-W Girl's Restroom	203	EA	6	-	
						10+ years	
	Doors - Transom Window	1st Floor-W Girl's Restroom	18	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-W Girl's Restroom	205	SF	6	10+ years	
	Floor Drain	1st Floor-W Girl's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-W Girl's Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-W Girl's Restroom	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-W Girl's Restroom	2	EA	7	6-10 years	
	Partitions	1st Floor-W Girl's Restroom	3	EA	7	10+ years	
	Walls - Masonry	1st Floor-W Girl's Restroom	320	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-W Girl's Restroom	455	SF	6	10+ years	
	Water Closet	1st Floor-W Girl's Restroom	3	EA	6	10+ years	
	Accessories	1st Floor-Women's Restroom, in	120	SF	5	2-5 years	Not used

Campus Name: Shoop Page : 14 of 50 Assessment Date: 01/31/2024



Catego	ry : Room	Building : Main								
					_	Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	0 :::	Auditorium Used as storage	400	0.5	-	40				
	Ceiling - Plaster/Drywall	1st Floor-Women's Restroom, in	120	SF	5	10+ years				
	Doors - Wood Doors inclu hw	Auditorium Used as storage	4	_^	0	40				
	Doors - wood Doors Inclu nw	1st Floor-Women's Restroom, in	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	Auditorium Used as storage 1st Floor-Women's Restroom, in	120	SF	6	10 . vooro				
	Floor - The Ceramic/ Porcelain	Auditorium Used as storage	120	SF	O	10+ years				
	Lavatory	1st Floor-Women's Restroom, in	1	EA	6	2-5 years	Not used			
	Lavatory	Auditorium Used as storage	'	LA	O	2-5 years	Not used			
	Lighting - Pendent/Surface	1st Floor-Women's Restroom, in	1	EA	6	6-10 years	Re-lamp fixture			
	Lighting Tendent/Ounded	Auditorium Used as storage	•	L/\	O	o io years	To lamp lixture			
	Partitions	1st Floor-Women's Restroom, in	1	EA	5	2-5 years	Not used			
		Auditorium Used as storage	·		•	_ 0 ,00.0	. 101 4004			
	Walls - Masonry	1st Floor-Women's Restroom, in	100	SF	6	10+ years				
	,	Auditorium Used as storage			_	, , , , , ,				
	Walls - Plaster/Drywall	1st Floor-Women's Restroom, in	275	SF	6	10+ years				
	·	Auditorium Used as storage				·				
	Water Closet	1st Floor-Women's Restroom, in	1	EA	6	2-5 years	Not used			
		Auditorium Used as storage				-				
	Accessories	1st Floor-Women's Staff Restroom	100	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	1st Floor-Women's Staff Restroom	85	SF	6	10+ years				
	Ceiling - Plaster/Drywall	1st Floor-Women's Staff Restroom	15	SF	5	10+ years	Water damage			
	Doors - Transom Window	1st Floor-Women's Staff Restroom	9	SF	6	10+ years				
	Doors - Wood Doors inclu hw	1st Floor-Women's Staff Restroom	1	EA	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	1st Floor-Women's Staff Restroom	100	SF	6	10+ years				
	Lavatory	1st Floor-Women's Staff Restroom	1	EA	6	10+ years				
	Lighting - Pendent/Surface	1st Floor-Women's Staff Restroom	2	EA	6	6-10 years				
	Partitions	1st Floor-Women's Staff Restroom	2	EA	7	10+ years				
	Walls - Masonry	1st Floor-Women's Staff Restroom	270	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor-Women's Staff Restroom	310	SF	6	10+ years				
	Water Closet	1st Floor-Women's Staff Restroom	2	EA	6	10+ years				
	Accessories	2nd Floor - East Boy's Restroom	389	SF	7	6-10 years				
	Ceiling - Plaster/Drywall	2nd Floor - East Boy's Restroom	339	SF	6	10+ years				
	Ceiling - Plaster/Drywall	2nd Floor - East Boy's Restroom	50	SF	4	1-2 years	Water damage, bubbling and			
							crumbling plaster			
	Doors - Side-lite	2nd Floor - East Boy's Restroom	42	SF	6	10+ years				
	Doors - Transom Window	2nd Floor - East Boy's Restroom	18	SF	6	10+ years				
	Floor - Tile Ceramic/ Porcelain	2nd Floor - East Boy's Restroom	389	SF	6	10+ years				
	Floor Drain	2nd Floor - East Boy's Restroom	1	EA	7	10+ years				
	Hand Dryer	2nd Floor - East Boy's Restroom	1	EA	7	6-10 years				
	Lavatory	2nd Floor - East Boy's Restroom	1	EA	6	10+ years				
	Lighting - Pendent/Surface	2nd Floor - East Boy's Restroom	5	EA	7	6-10 years				
	Partitions	2nd Floor - East Boy's Restroom	3	EA	7	6-10 years				
	Urinals	2nd Floor - East Boy's Restroom	5	EA	6	10+ years				

Campus Name: Shoop Page : 15 of 50 Assessment Date: 01/31/2024



Catego	Category: Room			uilding	: Main	-	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor - East Boy's Restroom	544	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - East Boy's Restroom	514	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - East Boy's Restroom	30	SF	5	1-2 years	Water damage, sagging plaster
	Walls - Structural Glazed Tile	2nd Floor - East Boy's Restroom	135	SF	6	10+ years	
	Water Closet	2nd Floor - East Boy's Restroom	3	EA	6	10+ years	
	Accessories	2nd Floor - East Girl's Restroom	307	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - East Girl's Restroom	307	SF	6	10+ years	
	Doors - Side-lite	2nd Floor - East Girl's Restroom	21	SF	6	10+ years	
	Doors - Transom Window	2nd Floor - East Girl's Restroom	18	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - East Girl's Restroom	307	SF	6	10+ years	
	Floor Drain	2nd Floor - East Girl's Restroom	1	EA	7	10+ years	
	Hand Dryer	2nd Floor - East Girl's Restroom	1	EA	7	•	
				EA	6	6-10 years	
	Lavatory	2nd Floor - East Girl's Restroom	3			10+ years	
	Lighting - Pendent/Surface	2nd Floor - East Girl's Restroom	1	EΑ	7	6-10 years	D 1
	Lighting - Pendent/Surface	2nd Floor - East Girl's Restroom	4	EA	6	6-10 years	Relamp
	Partitions	2nd Floor - East Girl's Restroom	7	EA	7	10+ years	
	Walls - Masonry	2nd Floor - East Girl's Restroom	407	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - East Girl's Restroom	407	SF	6	10+ years	
	Water Closet	2nd Floor - East Girl's Restroom	7	EA	6	10+ years	
	Accessories	2nd Floor - East Men's Room	139	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - East Men's Room	129	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor - East Men's Room	10	SF	5	1-2 years	Cracking plaster
	Doors - Transom Window	2nd Floor - East Men's Room	9	SF	6	10+ years	.
	Doors - Wood Doors inclu hw	2nd Floor - East Men's Room	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - East Men's Room	139	SF	6	10+ years	
	Lavatory	2nd Floor - East Men's Room	2	EΑ	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor - East Men's Room	2	EΑ	7	6-10 years	
	Partitions	2nd Floor - East Men's Room	2	EA	7	10+ years	
	Walls - Masonry	2nd Floor - East Men's Room	296	SF	6	10+ years	
	Walls - Masonly Walls - Plaster/Drywall	2nd Floor - East Men's Room	276	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor - East Men's Room	20	SF	5	•	Water damage, cracking
				EA		1-2 years	Water damage, cracking
	Water Closet	2nd Floor - East Men's Room	2		6	10+ years	
	Accessories	2nd Floor - Teacher's Lounge	85	SF	7	6-10 years	
		Restroom			_		
	Ceiling - Plaster/Drywall	2nd Floor - Teacher's Lounge	85	SF	6	10+ years	
		Restroom					
	Doors - Wood Doors inclu hw	2nd Floor - Teacher's Lounge	1	EA	6	10+ years	
		Restroom					
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Teacher's Lounge	85	SF	6	10+ years	
		Restroom				·	
	Lavatory	2nd Floor - Teacher's Lounge	2	EA	6	10+ years	
	• •	Restroom	_		-	- ,	
	Lighting - Pendent/Surface	2nd Floor - Teacher's Lounge	2	EA	5	6-10 years	Missing covers, Relamp
	gg	Restroom	_	_, \	J	o lo youlo	g covere, reduinp
		1.000100111					



atego	ategory : Room			uilding	: Main				
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Partitions	2nd Floor - Teacher's Lounge Restroom	2	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor - Teacher's Lounge Restroom	479	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor - Teacher's Lounge Restroom	5	SF	5	1-2 years	Water damage		
	Water Closet	2nd Floor - Teacher's Lounge Restroom	2	EA	6	10+ years			
	Accessories	2nd Floor - West Boys' Restroom	307	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor - West Boys' Restroom	307	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor - West Boys' Restroom	1	ĒΑ	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor - West Boys' Restroom	307	SF	6	10+ years			
	Floor Drain	2nd Floor - West Boys' Restroom	1	EA	7	10+ years			
	Hand Dryer	2nd Floor - West Boys' Restroom	1	EA	7	6-10 years			
	Lavatory	2nd Floor - West Boys' Restroom	3	EA	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor - West Boys' Restroom	5	EA	7	6-10 years			
						-			
	Partitions	2nd Floor - West Boys' Restroom	2	EΑ	7	10+ years			
	Urinals	2nd Floor - West Boys' Restroom	6	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor - West Boys' Restroom	804	SF	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor - West Boys' Restroom	10	SF	5	1-2 years	Cracking plaster		
	Walls - Structural Glazed Tile	2nd Floor - West Boys' Restroom	407	SF	7	10+ years			
	Water Closet	2nd Floor - West Boys' Restroom	2	EA	7	10+ years			
	Accessories	2nd Floor - West Girls' Restroom	307	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor - West Girls' Restroom	307	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor - West Girls' Restroom	2	EA	7	10+ years			
	Doors - Transom Window	2nd Floor - West Girls' Restroom	13	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor - West Girls' Restroom	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor - West Girls' Restroom	307	SF	6	10+ years			
	Floor Drain	2nd Floor - West Girls' Restroom	1	ĒΑ	7	10+ years			
	Hand Dryer	2nd Floor - West Girls' Restroom	1	EΑ	7	6-10 years			
	Lavatory	2nd Floor - West Girls' Restroom	3	EΑ	7	10+ years			
	Lighting - Pendent/Surface	2nd Floor - West Girls' Restroom	4	EΑ	7	6-10 years			
	Partitions	2nd Floor - West Girls' Restroom	6	EA	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor - West Girls' Restroom	407	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor - West Girls' Restroom	407	SF	7	10+ years			
	Water Closet	2nd Floor - West Girls' Restroom	6	EA	7	10+ years			
	Accessories	Engineer's Office In Boiler House		SF			Missing itoms		
			28		4	0-1 year	Missing items		
	Ceiling - Plaster/Drywall	Engineer's Office In Boiler House	10	SF	6	2-5 years			
	Ceiling - Plaster/Drywall	Engineer's Office In Boiler House	18	SF	5	6-10 years			
	Doors - Wood Doors inclu hw	Engineer's Office In Boiler House	1	EA	5	2-5 years			
	Floor - Tile	Engineer's Office In Boiler House	28	SF	6	2-5 years			
	Lavatory	Engineer's Office In Boiler House	1	EA	6	10+ years			
	Lighting - Pendent/Surface	Engineer's Office In Boiler House	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	Engineer's Office In Boiler House	25	SF	6	1-2 years			



Quantity 1 10 720 34 9 1 720 12 1,430	UOM SF EA Suilding UOM EA LF SF EA SF EA SF	7 6 7 4 6 6 6 7 7	Recommend Replacement 2-5 years 10+ years 10+ years 6-10 years 10+ years	Comments
45 1 EQuantity 1 10 720 34 9 1 720 12 1,430	SF EA SF EA SF EA LF	6 6 8 8 Main 7 6 7 4 6 6 6 6 7 7	2-5 years 10+ years 10+ years Recommend Replacement 6-10 years 10+ years 6-10 years	
1 E Quantity 1 10 720 34 9 1 720 12 1,430	EA Building UOM EA LF SF EA SF EA SF EA LF	6 : Main Rank 7 6 7 4 6 6 6 7 7 7	Recommend Replacement 6-10 years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 10+ years 6-10 years	Comments
Quantity 1 10 720 34 9 1 720 12 1,430	EA LF SF EA SF EA SF	7 6 7 4 6 6 6 7 7 7 6 6	Recommend Replacement 6-10 years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years	Comments
Quantity 1 10 720 34 9 1 720 12 1,430	UOM EA LF SF LF SF EA SF EA SF	7 6 7 4 6 6 6 7 7	6-10 years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years	Comments
1 10 720 34 9 1 720 12 1,430	EA LF SF LF SF EA SF EA SF	7 6 7 4 6 6 6 7 7	6-10 years 10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years	Comments
1 10 720 34 9 1 720 12 1,430	EA LF SF LF SF EA SF EA SF	7 6 7 4 6 6 6 7 7	6-10 years 10+ years 10+ years 2-5 years 10+ years 10+ years 6-10 years	
10 720 34 9 1 720 12 1,430	LF SF LF SF EA SF EA SF	6 7 4 6 6 6 7 7	10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years 6-10 years	
10 720 34 9 1 720 12 1,430	LF SF LF SF EA SF EA SF	6 7 4 6 6 6 7 7	10+ years 10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years 6-10 years	
720 34 9 1 720 12 1,430	SF LF SF EA SF EA SF	7 4 6 6 6 7 7	10+ years 2-5 years 10+ years 10+ years 10+ years 6-10 years 6-10 years	
34 9 1 720 12 1,430	LF SF EA SF EA SF	4 6 6 6 7 7	2-5 years 10+ years 10+ years 10+ years 6-10 years 10+ years	
9 1 720 12 1,430	SF EA SF EA SF	6 6 7 7 7	10+ years 10+ years 10+ years 6-10 years 10+ years	
1 720 12 1,430	EA SF EA SF	6 6 7 7 7	10+ years 10+ years 6-10 years 10+ years 6-10 years	
720 12 1,430 1 1	SF EA SF EA LF	6 7 7 7 6	10+ years 6-10 years 10+ years 6-10 years	
12 1,430 1 1 10	EA SF EA LF	7 7 7 6	6-10 years 10+ years 6-10 years	
1,430 1 1 10	SF EA LF	7 7 6	10+ years 6-10 years	
1 10	EA LF	7 6	6-10 years	
10	LF	6	•	
10	LF	6	•	
_			10+ years	
	O.E.		,	
720		7	10+ years	
34	LF	4	2-5 years	
9	SF	6	10+ years	
1	EΑ	6	10+ years	
720	SF	6	10+ years	
12	EA	7	6-10 years	
1,430	SF	7	10+ years	
1	EA	7	6-10 years	
10	LF	6	10+ years	
690	SF	7	10+ years	
30	SF	5	10+ years	Peeling and cracking paint
34	LF	4	2-5 years	
9	SF	6	10+ years	
1	EA	6	10+ years	
720	SF	6	10+ years	
12	EA	7	6-10 years	
12	SF	6	10+ years	
	ΕΛ	7	6-10 vears	
1,430	EA			
	12 1,430	1,430 SF 1 EA	1,430 SF 6 1 EA 7	1,430 SF 6 10+ years

Campus Name: Shoop Page : 18 of 50 Assessment Date: 01/31/2024



Catego	ry : Classroom		В	uilding	: Main				
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years			
	Chalk Board	1st Floor	34	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	720	SF	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,430	SF	7	10+ years			
Classroo	om #105 (Regular Classroom)								
Oldssion	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	10	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	695	SF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	25	SF	5	10+ years	Peeling and cracking paint		
	Chalk Board	1st Floor	34	LF	4	2-5 years	r eeiing and cracking paint		
	Doors - Transom Window	1st Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Wood	1st Floor	720	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,420	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,420	SF	, 5	10+ years	Cracking and peeling paint		
Classroo	om #107 (Office)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	10	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years			
	Chalk Board	1st Floor	34	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years			
	Floor - Wood	1st Floor	720	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years			
	Lighting - Pendent/Surface	1st Floor	2	EΑ	6	6-10 years	Re-lamp fixture		
	Walls - Plaster/Drywall	1st Floor	1,430	SF	6	10+ years			
Classroo	om #114 (Office)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	54	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years			
	Doors - Transom Window	1st Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EΑ	6	10+ years			
	Floor - Tile	1st Floor	720	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,420	SF	6	10+ years			
	•	-	,		-	,			



Catego	ry : Classroom		В	uilding	: Main		
Croup	Itom Type	Location	Quantity	UOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOW	Rank	Replacement	Comments
Classroc	om #117 (Kindergarten)	=				0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	44	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	770	SF	6	6-10 years	
	Chalk Board	1st Floor	14	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Wood	1st Floor	770	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,460	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroc	om #118 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	18	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,305	SF	6	10+ years	
	Doors - Transom Window	1st Floor	27	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	6	10+ years	
	Floor - Wood	1st Floor	1,305	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	18	EA	7	6-10 years	
	Storage/ Closet	1st Floor	125	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,398	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #119 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	770	SF	6	10+ years	
	Chalk Board	1st Floor	44	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Wood	1st Floor	770	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,445	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	15	SF	5	10+ years	Small damaged area
Classroo	om #122 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	7	10+ years	Additional casework installed as sin
	Ceiling - Plaster/Drywall	1st Floor	1,540	SF	7	10+ years	, tastional basework instance as sin
	Doors - Transom Window	1st Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,540	SF	7	10+ years	
	11001 1116	13011001	1,340	Oi.	'	10+ years	



Catego	ry : Classroom		В	uilding	: Main				
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,762	SF	6	10+ years			
	Work Sink	1st Floor	2	EA	7	10+ years			
Classroo	om #123 (Science Classroom)								
	AC Units	1st Floor	2	EA	7	6-10 years			
	Casework	1st Floor	34	LF	6	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	1,185	SF	7	10+ years			
	Doors - Transom Window	1st Floor	18	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years			
	Eye Wash Station	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	1,185	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	20	ĒΑ	7	6-10 years			
	Marker Board	1st Floor	8	LF	7	6-10 years			
	Storage/ Closet	1st Floor	120	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	1,900	SF	7	10+ years			
	Work Sink	1st Floor	3	EA	7	10+ years	Quantity updated		
			· ·	_, .	•	.o. you.o	Quality appeared		
Classroo	om #124 (Store Room)								
	AC Units	1st Floor	1	EA	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	100	SF	6	10+ years	Peeling and cracking paint		
	Ceiling - Plaster/Drywall	1st Floor	620	SF	6	10+ years			
	Doors - Transom Window	1st Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile	1st Floor	712	SF	6	10+ years			
	Floor - Tile	1st Floor	8	SF	4	1-2 years	Cracked and missing tiles. Quantity updated to match current observations		
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years			
	Marker Board	1st Floor	16	LF	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,430	SF	7	10+ years			
Classroo	om #125 (Regular Classroom)								
JIGGOIGE	AC Units	1st Floor	1	EA	7	6-10 years			
	Casework	1st Floor	10	LF	6	10+ years			
	Casework Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years			
	Chalk Board	1st Floor	25	LF	4	2-5 years			
	Doors - Transom Window	1st Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
			•	SF	-				
	Floor - Tile	1st Floor	720		6	10+ years			
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years			
	Walls - Plaster/Drywall	1st Floor	1,430	SF	7	10+ years			



Catego	ry : Classroom		В	uilding	: Main	<u> </u>	1140 0 Bishop OTTLE 1, Officago, in 00040
J.				9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #126 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years	
	Chalk Board	1st Floor	40	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	717	SF	6	10+ years	
	Floor - Tile	1st Floor	3	SF	5	1-2 years	Chipping tiles
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	•
	Walls - Plaster/Drywall	1st Floor	1,430	SF	7	10+ years	
Classroo	om #127 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Chalk Board	1st Floor	35	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,430	SF	7	10+ years	
Classroo	om #128 (Office)						
	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	7	10+ years	
	Chalk Board	1st Floor	35	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,430	SF	7	10+ years	
_Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	20	SF	6	10+ years	Cracking and falling paint
	Ceiling - Plaster/Drywall	2nd Floor	700	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	710	SF	6	10+ years	

Campus Name: Shoop Page : 22 of 50 Assessment Date: 01/31/2024



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	10	SF	5	1-2 years	Cracking and broken tiles
	Lighting - Pendent/Surface	2nd Floor	12	EΑ	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,330	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	13	SF	5	1-2 years	Crumbling plaster
Classroc	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EΑ	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	6	10+ years	
	Floor - Tile	2nd Floor	710	SF	6	10+ years	
	Floor - Tile	2nd Floor	10	SF	5	1-2 years	Chipping and broken tiles
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	6-10 years	Chipping and broken thes
	Walls - Plaster/Drywall	2nd Floor	1,343	SF	6	10+ years	
	walls - Flastel/Diywall	2110 F1001	1,343	SF	O	10+ years	
lassroc	m #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	705	SF	6	10+ years	
	Floor - Tile	2nd Floor	15	SF	5	1-2 years	Chipping
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,343	SF	6	10+ years	
Classroc	om #204 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor 2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,343	SF	6	10+ years	
laceron	om #205 (Regular Classroom)						
المعادلات	AC Units	2nd Floor	4	ΕΛ	7	6 10 years	
			1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	

Campus Name: Shoop Page : 23 of 50 Assessment Date: 01/31/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	710	SF	6	10+ years	
	Floor - Tile	2nd Floor	10	SF	5	1-2 years	Chipping tiles
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	11 3
	Walls - Plaster/Drywall	2nd Floor	1,343	SF	6	10+ years	
Classroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	18	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Tile	2nd Floor	710	SF	6	10+ years	
	Floor - Tile	2nd Floor	10	SF	5	1-2 years	Cracking
	Lighting - Pendent/Surface					•	Cracking
	Walls Bloots / Drawell	2nd Floor	12	EA SF	7 6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,343	SF	б	10+ years	
Classroc	om #215 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	80	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,333	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	30	SF	5	1-2 years	Water damage
	Wireless System	2nd Floor	1	ĒΑ	7	6-10 years	
Classroo	om #217 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	690	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	30	SF	5	1-2 years	Water damage along edge of
					-	-	windows
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	719	SF	6	10+ years	
	Floor - Tile	2nd Floor	1	SF	4	1-2 years	Broken tile near door
	Lighting - Pendent/Surface	2nd Floor	11	EA	7	6-10 years	

Campus Name: Shoop Page : 24 of 50 Assessment Date: 01/31/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
∃roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	Relamp
	Walls - Plaster/Drywall	2nd Floor	1,333	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	30	SF	5	1-2 years	Water damage, crumbling plaste
Classroo	m #218 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	715	SF	6	10+ years	
	Floor - Tile	2nd Floor	5	SF	4	1-2 years	Cracking tiles
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	Ordoning thos
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,343	SF	6	10+ years	
	walls - Flastel/Drywall	2110 F1001	1,343	SI	O	10+ years	
Classroo	m #219 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	708	SF	6	10+ years	
	Floor - Tile	2nd Floor	12	SF	4	1-2 years	Cracking
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years	g
	Walls - Plaster/Drywall	2nd Floor	1,333	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	30	SF	4	1-2 years	Large pieces of plaster falling ou
Classron	m #220 (Regular Classroom)						
<u> </u>	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	690	SF	7		
					-	10+ years	Decling point
	Ceiling - Plaster/Drywall	2nd Floor	30	SF	6	10+ years	Peeling paint
	Chalk Board	2nd Floor	40	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	710	SF	6	10+ years	
	Floor - Tile	2nd Floor	10	SF	5	1-2 years	Chipping and cracking tiles
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,343	SF	6	10+ years	
Classroo	m #221 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	

Campus Name: Shoop Page : 25 of 50 Assessment Date: 01/31/2024



Category : Classroom			В	uilding	: Main				
						Recommend			
3roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years			
	Chalk Board	2nd Floor	40	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile	2nd Floor	715	SF	6	10+ years			
	Floor - Tile	2nd Floor	5	SF	5	1-2 years	Chipping and cracking tiles		
	Lighting - Pendent/Surface	2nd Floor	12	ĒΑ	7	6-10 years			
	Walls - Plaster/Drywall	2nd Floor	1,343	SF	6	10+ years			
Classroo	om #222 (Computer Lab)								
	AC Units	2nd Floor	2	EA	7	6-10 years			
	Casework	2nd Floor	12	LF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	1,060	SF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	5	SF	5	0-1 year	Water damage		
	Doors - Transom Window			SF	6	-	water damage		
		2nd Floor	18			10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years			
	Floor - Tile	2nd Floor	1,065	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	20	EA	7	6-10 years			
	Storage/ Closet	2nd Floor	20	SF	7	10+ years			
	Storage/ Closet	2nd Floor	8	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	1,452	SF	6	10+ years			
	Wireless System	2nd Floor	1	EA	7	6-10 years			
Classroc	om #223 (Faculty Lounge)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	10	LF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years			
	Chalk Board	2nd Floor	40	LF	4	2-5 years			
	Doors - Transom Window	2nd Floor	1	SF	6	10+ years			
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Floor - Tile	2nd Floor	720	SF	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years			
						•			
	Walls - Plaster/Drywall	2nd Floor	1,338	SF	6	10+ years	0 1: 1 1		
	Walls - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Cracking plaster		
lassroc	om #224 (Regular Classroom)								
	AC Units	2nd Floor	1	EA	7	6-10 years			
	Casework	2nd Floor	12	LF	6	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	15	SF	6	10+ years	Peeling paint		
	Chalk Board	2nd Floor	20	ĹF	4	2-5 years	3.1		
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	2nd Floor	730	SF	6	10+ years	
	Floor - Tile	2nd Floor	5	SF	5	1-2 years	Cracking tiles
	Lighting - Pendent/Surface	2nd Floor	11	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	Relamp
	Marker Board	2nd Floor	12	LF	7	6-10 years	•
	Walls - Plaster/Drywall	2nd Floor	1,348	SF	6	10+ years	
Classroo	om #225 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	735	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	•	
	Floor - Tile	2nd Floor	· · · · · · · · · · · · · · · · · · ·	SF	_	10+ years	
			735		6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,347	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1	SF	5	1-2 years	Hole in plaster
Classroo	nm #226 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	735	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	1	SF	6	10+ years	
	Floor - Tile	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	11	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,348	SF	6	10+ years	
`laceroo	nm #227 (Regular Classroom)						
21453100	AC Units	2nd Floor	2	EA	7	6 10 years	
						6-10 years	
	Casework	2nd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	
	Floor - Tile	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,343	SF	6	10+ years	
Classroo	om #228 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	735	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	9	SF	6	10+ years	

Campus Name: Shoop Page : 27 of 50 Assessment Date: 01/31/2024



Category : Classroom

John D Shoop Math-Science Technical Academy ES 11140 S Bishop STREET, Chicago, IL 60643

Recommend

Building: Main

roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	735	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,346	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2	SF	5	1-2 years	Broken plaster
	·		_			,	
ategor	y : Interior		В	uilding	: Main	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor						<u>-</u>	
	Ceiling - Lay-in	1st Floor	140	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	8,408	SF	6	10+ years	
	Doors - Side-lite	1st Floor	60	SF	6	10+ years	
	Doors - Transom Window	1st Floor	108	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	8	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EA	7	10+ years	Quantity updated
	Drinking Fountains - Single Fountain Drinking Fountains - Single Fountain	1st Floor	2	EA	4	0-1 year	Not working
	Floor - Terrazzo	1st Floor	2,192	SF	6		Not working
				SF		10+ years	
	Floor - Tile/Sheet	1st Floor	6,693		7	10+ years	Overalized and bulkbling tiles is set to
	Floor - Tile/Sheet	1st Floor	10	SF	4	0-1 year	Cracked and bubbling tiles next to entrance to addition
	Lighting - Pendent/Surface	1st Floor	114	EA	6	6-10 years	
	Lighting - Wall Mounted	1st Floor	2	EA	6	6-10 years	
	Stairs - Terrazzo	1st Floor	6	LF	6	10+ years	
	Student Lockers - One Tier	1st Floor	394	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	525	SF	6	10+ years	
	Walls - Masonry	1st Floor	1,630	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	19,867	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	3,108	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	12	SF	4	1-2 years	Cracking tiles
	Drinking Fountains - Single Fountain	2nd Floor	6	EA	7	10+ years	Ordoning thes
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	5	1-2 years	Non functional per engineer
	Floor - Tile/Sheet	2nd Floor	3,090	SF	7		Non functional per engineer
	Floor - Tile/Sheet	2nd Floor		SF		10+ years	Chinning
			30		4	1-2 years	Chipping
	Lighting - Pendent/Surface	2nd Floor	56	EΑ	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	202	EΑ	6	10+ years	
	Student Lockers - One Tier	2nd Floor	2	EA	5	1-2 years	Metal bent outward
	Walls - Plaster/Drywall	2nd Floor	31,290	SF	6	10+ years	10/
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Water damage under drinking fountains
ety							
	Metal Detector	1st Floor	1	EA	7	6-10 years	
	Security Cameras	1st Floor	2	EA	7	6-10 years	

Campus Name: Shoop Page : 28 of 50 Assessment Date: 01/31/2024



Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security Cameras	1st Floor	5	EA	7	6-10 years	
Stairs							
	Ceiling - Lay-in	East (by Door 2)	227	SF	7	10+ years	
	Floor - Terrazzo	East (by Door 2)	115	SF	6	10+ years	
	Handrails	East (by Door 2)	80	LF	7	10+ years	
	Lighting - Pendent/Surface	East (by Door 2)	2	EA	7	6-10 years	
	Stairs - Terrazzo	East (by Door 2)	180	LF	6	10+ years	Corrected quantity
	Walls - Plaster/Drywall	East (by Door 2)	315	SF	6	10+ years	
	Walls - Plaster/Drywall	East (by Door 2)	20	SF	5	1-2 years	Plaster damaged near hand rail
	Ceiling - Lay-in	North (by Door 9)	227	SF	7	10+ years	· ·
	Floor - Terrazzo	North (by Door 9)	115	SF	6	10+ years	
	Handrails	North (by Door 9)	80	LF	7	10+ years	
	Lighting - Pendent/Surface	North (by Door 9)	2	EA	7	6-10 years	
	Stairs - Terrazzo	North (by Door 9)	180	LF	6	10+ years	Corrected quantity
	Walls - Plaster/Drywall	North (by Door 9)	325	SF	6	10+ years	
	Ceiling - Lay-in	North East (by Door 11)	227	SF	7	10+ years	
	Floor - Terrazzo	North East (by Door 11)	115	SF	6	10+ years	
	Handrails	North East (by Door 11)	80	ĹF	7	10+ years	
	Lighting - Pendent/Surface	North East (by Door 11)	4	EA	7	6-10 years	recombined quantities
	Stairs - Terrazzo	North East (by Door 11)	180	LF	6	10+ years	Corrected quantity
	Walls - Plaster/Drywall	North East (by Door 11)	335	SF	6	10+ years	4
	Ceiling - Lay-in	North West (by Door 10)	227	SF	7	10+ years	
	Floor - Terrazzo	North West (by Door 10)	115	SF	6	10+ years	
	Handrails	North West (by Door 10)	80	LF	7	10+ years	
	Lighting - Pendent/Surface	North West (by Door 10)	2	EA	7	6-10 years	
	Lighting - Wall Mounted	North West (by Door 10)	2	EA	7	6-10 years	
	Stairs - Terrazzo	North West (by Door 10)	180	LF	6	10+ years	Corrected quantity
	Walls - Plaster/Drywall	North West (by Door 10)	360	SF	6	10+ years	23.700.00 quality
	Ceiling - Lay-in	West (by Door 8)	227	SF	7	10+ years	
	Floor - Terrazzo	West (by Door 8)	115	SF	6	10+ years	
	Handrails	West (by Door 8)	80	LF	7	10+ years	
	Lighting - Pendent/Surface	West (by Door 8)	2	EA	7	6-10 years	
	Stairs - Terrazzo	West (by Door 8)	180	LF	6	10+ years	Corrected quantity
	Walls - Plaster/Drywall	West (by Door 8)	310	SF	6	10+ years	Corrected quartity
	Walls - Plaster/Drywall	West (by Door 8)	25	SF	5	1-2 years	Water damage
	vvalis - i lastei/Diywali	West (by Door o)	25	OI	3	1-2 years	vvater darriage



Building: Addition Category: Exterior

Categor	y : Exterior		<u> </u>	unung	: Additio		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	Door 1 - Southeast	1	EA	6	6-10 years	
	Exterior Doors - Store Front	Door 1 - Southeast	2	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	Door 1 - Southeast	2	EA	7	10+ years	
	Power Door Operator and Controls	Door 1 - Southeast	1	EA	7	10+ years	
	Exterior Doors - Store Front	Door 12 - Courtyard southeast	2	EA	6	10+ years	
	Exterior Doors - Store Front	Door 13 - Courtyard southeast	2	EA	6	6-10 years	
	Exterior Doors - Store Front Exterior Doors - Exterior Steel Door	Door 13.5 - Courtyard southeast	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Door 13.5 - Courtyard southeast	2	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 13.5 - Courtyard southeast Door 13.5 - Courtyard southeast	6	LF	7	10+ years	
	Exterior Doors - Store Front		1	EA	6		
		Door 14 - Courtyard east center	1		7	6-10 years	
	Exterior Doors - Transom Lite	Door 14 - Courtyard east center	•	EA LF		10+ years	Composted accountity
	Exterior Stairs - Concrete	Door 14 - Courtyard east center	3		7	10+ years	Corrected quantity
	Exterior Doors - Store Front	Door 15 - Courtyard East center	2	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Door 15 - Courtyard East center	2	EA	7	6-10 years	
	Exterior Stairs - Concrete	Door 15 - Courtyard East center	6	LF	7	10+ years	
	Exterior Doors - Store Front	Door 16 - northwest	1	EA	6	6-10 years	
	Exterior Doors - Transom Lite	Door 16 - northwest	1	EA	7	10+ years	
	Exterior Stairs - Concrete	Door 16 - northwest	3	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 16.5 - North center	2	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 17 - North center	1	EA	5	1-2 years	Corroded frames
	Exterior Doors - Store Front	Door 18 - North	2	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 18.5 - East center	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 19 - East	2	EA	5	1-2 years	Corroding frames
oundatio	on						
	Foundation - Concrete	Entire Building	640	LF	7	10+ years	
	Superstructure - Steel	Entire Building	36,007	SF	7	10+ years	
	·	5	,			,	
ighting	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	5	1-2 years	Not working according to engineer
	Exterior Lighting - Wall Mounted	Entire Building	16	EA	6	6-10 years	Not working according to engineer
	Exterior Lighting - waii wounted	Entire Building	10	LA	O	0-10 years	
Roof Sys							
	Chimney - Metal Flue	Roof 1	4	LF	7	6-10 years	
	Coping - Metal	Roof 1	20	LF	6	10+ years	
	Coping - Stone	Roof 1	560	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 1	350	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 1	560	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 1	20	LF	7	10+ years	
			4 4 0 0 0	0-	^	0.40	
	Roof - Modified Bitumen	Roof 1	14,960	SF	6	6-10 years	



	ry : Exterior		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Roof Structure - Steel / Metal Deck/	Roof 1	15,460	SF	7	10+ years	
	Concrete Topping						
	Coping - Stone	Roof 2	190	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 2	90	LF	6	6-10 years	
	Parapet - 16" - 30" Height	Roof 2	190	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 2	4,260	SF	6	6-10 years	
	Roof - Modified Bitumen	Roof 2	50	SF	4	1-2 years	blistering,
	Roof Structure - Steel / Metal Deck/	Roof 2	4,310	SF	7	10+ years	3,
	Concrete Topping		,			,	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	255	SF	7	10+ years	Corrected item type
	Exterior Walls - Brick	Entire Building	20,338	SF	6	10+ years	• •
	Exterior Walls - Stone-Cast	Entire Building	1,920	SF	5	10+ years	
Window:	s Curtain wall - Glazed Double Pane	Entire Building	552	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	2,322	SF	6	6-10 years	
	Lintels - Steel	Entire Building	450	LF	7	10+ years	
	Windows - Louver	Entire Building	110	SF	7	10+ years	Not previously assessed
	Windows - Sash Aluminum Double-pane	Entire Building	3,655	SF	6	10+ years	140t providuoly addeddda
		Entire Ballaning	·			,	
Catego	ry : Electrical		В	uilding	: Addition	on Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
•	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	ncy System		•			Replacement	Comments
•	ncy System Emergency A/C Power - Corridors and	Location Entire Building	Quantity 7,501	UOM SF	Rank 6		Comments
•	ncy System Emergency A/C Power - Corridors and Stairs	Entire Building	7,501	SF	6	Replacement 10+ years	Comments
	ncy System Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms	Entire Building Entire Building	7,501 4,190	SF SF	6	10+ years 6-10 years	Comments
	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets	Entire Building Entire Building Entire Building	7,501 4,190 1,293	SF SF SF	6 6 7	10+ years 6-10 years 6-10 years	
•	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and	Entire Building Entire Building	7,501 4,190	SF SF	6	10+ years 6-10 years	
•	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building	7,501 4,190 1,293 23	SF SF SF EA	6 6 7 7	10+ years 6-10 years 6-10 years 6-10 years 6-10 years	Batteries replaced in the last 30 day
	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms	Entire Building Entire Building Entire Building Entire Building Entire Building	7,501 4,190 1,293 23	SF SF SF EA	6 6 7 7	10+ years 6-10 years 6-10 years 6-10 years 6-10 years	Batteries replaced in the last 30 day Batteries replaced in the last 30 day
	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets	Entire Building	7,501 4,190 1,293 23 9 4	SF SF SF EA EA	6 6 7 7 7	10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Batteries replaced in the last 30 day Batteries replaced in the last 30 day
•	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs	Entire Building	7,501 4,190 1,293 23 9 4 22	SF SF SF EA EA EA	6 6 7 7 7 7	10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 2-5 years	Batteries replaced in the last 30 day Batteries replaced in the last 30 day Batteries replaced in the last 30 day
•	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Lunchroom	Entire Building	7,501 4,190 1,293 23 9 4 22 6	SF SF SF EA EA EA EA	6 6 7 7 7 7 7	10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 2-5 years 2-5 years	Batteries replaced in the last 30 day
Group Emergei	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Lunchroom Exit Signs - Lunchroom	Entire Building	7,501 4,190 1,293 23 9 4 22 6 2	SF SF SF EA EA EA EA EA	6 6 7 7 7 7 7 7 7	Replacement 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 2-5 years 2-5 years 0-1 year	Batteries replaced in the last 30 day Batteries replaced in the last 30 day Batteries replaced in the last 30 day
•	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Lunchroom Exit Signs - Lunchroom Security System - CCTV	Entire Building	7,501 4,190 1,293 23 9 4 22 6 2 36,007	SF SF SF EA EA EA EA EA SF	6 6 7 7 7 7 7 7 6 6	Replacement 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 2-5 years 2-5 years 0-1 year 6-10 years	Batteries replaced in the last 30 day
	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Lunchroom Exit Signs - Lunchroom	Entire Building	7,501 4,190 1,293 23 9 4 22 6 2	SF SF SF EA EA EA EA EA	6 6 7 7 7 7 7 7 7	Replacement 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 2-5 years 2-5 years 0-1 year	Batteries replaced in the last 30 day
Emergei	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Lunchroom Exit Signs - Lunchroom Security System - CCTV Security System - Intrusion Detection	Entire Building	7,501 4,190 1,293 23 9 4 22 6 2 36,007 36,007	SF SF EA EA EA EA EA SF SF	6 6 7 7 7 7 7 7 6 6 6	10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 2-5 years 2-5 years 0-1 year 6-10 years 6-10 years	Batteries replaced in the last 30 day
•	Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Lunchrooms Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Lunchrooms Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs Exit Signs - Lunchroom Exit Signs - Lunchroom Security System - CCTV Security System - Intrusion Detection	Entire Building	7,501 4,190 1,293 23 9 4 22 6 2 36,007	SF SF SF EA EA EA EA EA SF	6 6 7 7 7 7 7 7 6 6	Replacement 10+ years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 2-5 years 2-5 years 0-1 year 6-10 years	Batteries replaced in the last 30 day



Catego	ry : Electrical		В	uilding	: Addition	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	PA System	Entire Building	36,007	SF	6	6-10 years	Repaired in 2021
_							
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	PP-2C
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	7	EA	7	10+ years	LP-1 PP-1A PP-1B PP-1C KP1 KP KP3
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	7	10+ years	PP-2A PP-2B
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	DP-1A
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	DP-1B
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years	T-2
	Transformers - 277/480 - 120/208	Entire Building	1	EA	7	10+ years	T-1
`atogo	ry : Fire Protection		D	uildina	: Additio	an.	
catego	ry . File Frotection		D	unung	. Additio	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar			4			nto più do dino ini	
IIE Alai	Fire ALarm Anunciator	Electrical Room	1	EA	7	6-10 years	
	Fire Alarm Panel	Electrical Room	1	EA	6	6-10 years	
			=	SF			
	Fire Alarm Strobe Lights	Electrical Room	36,007		7	6-10 years	
	Fire Alarm_System	Electrical Room	36,007	SF	6	6-10 years	
	Fire Pump Controller	Electrical Room	1	EA	7	6-10 years	
Pump Re	oom Assembly						
	Fire Pump - 51-75hp	1st Floor	1	EA	7	10+ years	
	Jockey Pump	1st Floor	1	EΑ	7	10+ years	
	, ,					•	
Sprinkle	r System						
	Sprinkler Heads	Entire Building	36,007	SF	7	10+ years	
	Sprinkler Piping	Entire Building	36,007	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	36,007	SF	7	10+ years	
Catego	ry · Mechanical		R	uildina	· Additio	on	
Catego	ry : Mechanical		В	uilding	: Additio		
_	ry : Mechanical Item - Type	Location	B Quantity	uilding UOM	: Addition	Recommend Replacement	Comments
Group	Item - Type	Location				Recommend	Comments
_	Item - Type litioning			UOM	Rank	Recommend Replacement	Comments
Group	Item - Type litioning Chemical Pot Feeder Chiller-Air Cooled-Screw Type-Roof	Location Roof Roof	Quantity			Recommend	Comments Not working
Group	Item - Type litioning Chemical Pot Feeder	Roof	Quantity 1	UOM	Rank 6	Recommend Replacement 10+ years	



Catego	ry : Mechanical		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Pressure Fill System	Roof	1	EA	6	10+ years	
	Condensing Unit- Roof Mounted - Less	Roof	1	EA	4	2-5 years	Serves MDF room
	than 5 tons						
Air Hand	Iling Systems						
	Fan Power Box - Fan Power Box with Hot Water Coil	Entire Building	19	EA	6	10+ years	Most of the FCUs are above ceilings
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room	1	EA	6	10+ years	
	Air Intake	Mechanical Room	1	EA	7	10+ years	
	VAV Box	Mechanical Room	13	EA	6	10+ years	Inaccessible above ceilings
	Air Handling Unit-Package Single Zone-	Mechanical Room	1	EA	6	10+ years	
	Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm					•	
	Air Intake	Mechanical Room	1	EA	7	10+ years	
	VAV Box	Mechanical Room	1	EA	6	10+ years	Inaccessible above ceilings
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	1	EA	6	10+ years	
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years	
Gas Boo	oster						
	Gas Booster	1st Floor	1	EA	6	10+ years	Not included in previous assessment
Heating	Devices						
J	Cabinet Heaters - With Hot Water Coil	Entire Building	9	EA	6	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	3	EA	5	10+ years	
	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years	
	Unit Heater - Hot Water	Entire Building	1	EA	6	6-10 years	Fire pump room
	Unit Heater - Hot Water	Entire Building	2	EA	6	6-10 years	- 1 · 1 · 1
Mechani	ical Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	150	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	50	LF	6	10+ years	
	Chilled Water Pump - Less than 10	Mechanical Room	1	EA	6	10+ years	
	Chilled Water Pump - Less than 10	Mechanical Room	1	ΕA	6	10+ years	
	Hot Water Pump - Less than 10	Mechanical Room	1	EΑ	6	10+ years	Serves AHU1
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	10+ years	Serves AHU2
Tempera	ature Control						
	DDC System	Entire Building	36,007	SF	6	6-10 years	
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	
		9	'		J	3 10 ,0010	

Campus Name: Shoop Page : 33 of 50 Assessment Date: 01/31/2024



Category : Mechanical			Building : Addition					
	,		Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Thermostats - DDC	Entire Building	49	EA	6	6-10 years		
_Ventilatio	n .							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Mechanical Room, roof, kitchen	2	EA	6	10+ years	Electrical Vault 2nd floor mech room	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Mechanical Room, roof, kitchen	1	EA	6	10+ years		
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Mechanical Room, roof, kitchen	3	EA	6	10+ years		
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Mechanical Room, roof, kitchen	1	EA	5	0-1 year	Not functional at time of observation	
	Type I Exhaust Hood- Kitchen Type II Exhaust Hood- Warming Kitchen	Mechanical Room, roof, kitchen Mechanical Room, roof, kitchen	1	EA EA	7 7	10+ years 10+ years		
	Type II Extraust 11000- Warming Kitchen	Mechanica Room, 1001, Richen	ı	LA	,	10+ years		
Category : Plumbing			Building : Addition					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
_Hot Wate								
	Gas Heater - 300001 - 600000 BTU/HR	1st Floor	2	EA	6	6-10 years		
_Piping								
	Domestic Piping-Hot Water Return Lines	Entire Building	36,007	SF	7	10+ years		
	Domestic Piping-Hot Water Return Risers	Entire Building	36,007	SF	7	10+ years		
	Domestic Piping-Hot Water from Risers to	Entire Building	36,007	SF	7	10+ years		
	Fixtures	Fortion Dudlelling	00.007	0.5	7	40		
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	36,007	SF	7	10+ years		
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	36,007	SF	7	10+ years		
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	36,007	SF	7	10+ years		
	Sanitary Piping	Entire Building	36,007	SF	7	10+ years		
	Storm Piping	Entire Building	36,007	SF	7	10+ years		
	Vent Piping	Entire Building	36,007	SF	7	10+ years		
Pumps								
	Pumps - Domestic Booster Pump-Duplex	1st Floor	1	EA	6	10+ years		
	Pumps - Sump-Simplex	1st Floor	1	EA	6	10+ years	Elevator pit sump in accessible at time of assessment	



Category : Room			Building : Addition					
			Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Administ	rative Suites/Offices							
	Ceiling - Lay-in	1st Floor-168 Main Office	1,312	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor-168 Main Office	8	SF	5	0-1 year	Water damage in corridor by staff restroom	
	Doors - Side-lite	1st Floor-168 Main Office	32	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor-168 Main Office	1	EA	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor-168 Main Office	1	EA	7	10+ years		
	Floor - Carpet	1st Floor-168 Main Office	1,320	SF	6	6-10 years		
	Lighting - Lay-in	1st Floor-168 Main Office	15	EA	7	6-10 years		
	Power Distribution	1st Floor-168 Main Office	20	EA	7	10+ years		
	Storage/ Closet	1st Floor-168 Main Office	124	SF	7	10+ years		
	Storage/ Closet	1st Floor-168 Main Office	22	SF	7	10+ years		
	Walls - Concrete Block	1st Floor-168 Main Office	1,200	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor-168 Main Office	740	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor-169 Assistant Principal's Office	160	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor-169 Assistant Principal's Office	1	EA	7	10+ years		
	Floor - Carpet	1st Floor-169 Assistant Principal's Office	160	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor-169 Assistant Principal's Office	3	EA	7	6-10 years		
	Power Distribution	1st Floor-169 Assistant Principal's Office	12	EA	7	10+ years		
	Walls - Concrete Block	1st Floor-169 Assistant Principal's Office	360	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor-169 Assistant Principal's Office	225	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor-170 Workroom	226	SF	7	10+ years		
	Doors - Steel Doors incl hw	1st Floor-170 Workroom	1	EA	7	10+ years		
	Floor - Tile	1st Floor-170 Workroom	226	SF	7	10+ years		
	Lighting - Lay-in	1st Floor-170 Workroom	5	EA	7	6-10 years		
	Power Distribution	1st Floor-170 Workroom	12	EA	7	10+ years		
	Walls - Concrete Block	1st Floor-170 Workroom	650	SF	7	10+ years		
	Work SInk	1st Floor-170 Workroom	1	EA	7	10+ years		
	Ceiling - Lay-in	1st Floor-171 Conference Room	243	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor-171 Conference Room	1	EA	7	10+ years		
	Floor - Carpet	1st Floor-171 Conference Room	243	SF	7	6-10 years		
	Lighting - Lay-in	1st Floor-171 Conference Room	4	EA	7	6-10 years		
	Power Distribution	1st Floor-171 Conference Room	10	EA	7	10+ years		
	Walls - Concrete Block	1st Floor-171 Conference Room	265	SF	7	10+ years		
	Walls - Plaster/Drywall	1st Floor-171 Conference Room	504	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor-175 Principal's Office	286	SF	7	10+ years		
	Doors - Wood Doors inclu hw	1st Floor-175 Principal's Office	1	ĒΑ	7	10+ years		

Campus Name: Shoop Page : 35 of 50 Assessment Date: 01/31/2024



Category : Room		Building : Addition				· · · · · · · · · · · · · · · · · · ·	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Carpet	1st Floor-175 Principal's Office	286	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor-175 Principal's Office	3	EA	7	10+ years	
	Power Distribution	1st Floor-175 Principal's Office	12	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-175 Principal's Office	390	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-175 Principal's Office	390	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor-176 Student Services Office	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-176 Student Services Office	1	EA	7	10+ years	
	Floor - Carpet	1st Floor-176 Student Services Office	120	SF	7	6-10 years	
	Lighting - Lay-in	1st Floor-176 Student Services Office	2	EA	7	6-10 years	
	Lighting - Lay-in	1st Floor-176 Student Services Office	1	EA	6	6-10 years	Re-lamp fixture
	Power Distribution	1st Floor-176 Student Services Office	12	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-176 Student Services Office	290	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor-176 Student Services Office	290	SF	7	10+ years	
	Work Slnk	1st Floor-176 Student Services Office	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor-187D Kitchen Office	68	SF	7	10+ years	
	Doors - Side-lite	1st Floor-187D Kitchen Office	16	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor-187D Kitchen Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor-187D Kitchen Office	68	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-187D Kitchen Office	1	EΑ	7	6-10 years	
	Power Distribution	1st Floor-187D Kitchen Office	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-187D Kitchen Office	405	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor-194 Nurse's Office	395	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-194 Nurse's Office	1	EΑ	6	10+ years	
	Floor - Tile	1st Floor-194 Nurse's Office	395	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-194 Nurse's Office	6	EA	7	6-10 years	
	Power Distribution	1st Floor-194 Nurse's Office	10	ΕA	7	10+ years	
	Storage/ Closet	1st Floor-194 Nurse's Office	90	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-194 Nurse's Office	920	SF	6	10+ years	
	Work Sink	1st Floor-194 Nurse's Office	1	EA	7	10+ years	
	Ceiling - Lay-in	1st Floor-195 Cath/Cot Room	88	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor-195 Cath/Cot Room	6	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	1st Floor-195 Cath/Cot Room	1	EA	6	10+ years	
	Floor - Tile	1st Floor-195 Cath/Cot Room	94	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-195 Cath/Cot Room	2	EA	6	2-5 years	
	Power Distribution	1st Floor-195 Cath/Cot Room	6	EA	7	10+ years	



ategory : Room		D	uilding	: Additio	on		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank		Comments
	Walls - Concrete Block	1st Floor-195 Cath/Cot Room	440	SF	7	10+ years	
itchen							
Itorion	Ceiling - Lay-in	1st Floor-187 Kitchen	1,260	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor-187 Kitchen	1,200	EA	6	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor-187 Kitchen	1,260	SF	7	10+ years	
	Lighting - Lay-in	1st Floor-187 Kitchen	14	EA	7	10+ years	
	Storage/ Closet	1st Floor-187 Kitchen	110	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-187 Kitchen	2,400	SF	6	10+ years	
unch &	Multipurpose Room	4 . El	1.100	05		40	
	Ceiling - Lay-in	1st Floor-188 Dining	4,190	SF	7	10+ years	
	Floor - Terrazzo	1st Floor-188 Dining	4,190	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-188 Dining	96	EA	7	6-10 years	-
	Lighting - Lay-in	1st Floor-188 Dining	2	EA	6	6-10 years	Re-lamp fixture
	Storage/ Closet	1st Floor-188 Dining	140	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-188 Dining	3,900	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor-189 Servery/190 Dishwash Room	1,180	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor-189 Servery/190 Dishwash Room	5	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor-189 Servery/190 Dishwash Room	205	SF	7	10+ years	
	Floor - Terrazzo	1st Floor-189 Servery/190 Dishwash Room	975	SF	6	10+ years	
	Lighting - Lay-in	1st Floor-189 Servery/190 Dishwash Room	18	EA	7	6-10 years	
	Serving Line	1st Floor-189 Servery/190 Dishwash Room	44	LF	7	10+ years	
	Walls - Concrete Block	1st Floor-189 Servery/190 Dishwash Room	700	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor-189 Servery/190 Dishwash Room	1,360	SF	7	10+ years	
IDF_IDI	F						
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	40	SF	7	10+ years	
	Other Cooling Unit	2nd Floor	1	EA	7	10+ years	Fan coil unit
lechani	cal/ Service Rooms						
iconanii	Janitor's Closet	1st Floor	42	SF	7	10+ years	
	Janitor's Closet	1st Floor	20	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	75	SF	7	10+ years	
	IVIOGRAFIIGAL GOLVIOG ROOMIS	1001	7.5	01	,	ioi youis	



itego	ry : Room		В	uilding	: Additi	on	
_						Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Mechanical/ Service Rooms	1st Floor	530	SF	7	10+ years	
	Janitor's Closet	2nd Floor	40	SF	7	10+ years	
	Mechanical/ Service Rooms	2nd Floor	1,816	SF	7	10+ years	
stroor	n						
	Accessories	1st Floor	58	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	58	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	58	SF	7	10+ years	
	Floor Drain	1st Floor	1	ĒΑ	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	160	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	190	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	1st Floor-168 Main Office Restroom	75	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-168 Main Office Restroom	75 75	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-168 Main Office Restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-168 Main Office Restroom	75	SF	7	10+ years	
	Floor Drain	1st Floor-168 Main Office Restroom	1	EA	7	10+ years	
	Lavatory	1st Floor-168 Main Office Restroom	1	EA	7	10+ years	
		1st Floor-168 Main Office Restroom	1	EA	7		
	Lighting - Lay-in Walls - Concrete Block		185	SF	7	6-10 years	
		1st Floor-168 Main Office Restroom				10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor-168 Main Office Restroom	225	SF	7	10+ years	
	Water Closet	1st Floor-168 Main Office Restroom	1	EA	7	10+ years	
	Accessories	1st Floor-194 Nurse's Office Restroom	100	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor-194 Nurse's Office	96	SF	7	10+ years	
	20g 23,	Restroom		О.	•	.o. youro	
	Ceiling - Lay-in	1st Floor-194 Nurse's Office	4	SF	5	1-2 years	Water damage
	coming Lay in	Restroom	•	O.	Ū	. <i>-</i> youro	Trator damage
	Doors - Wood Doors inclu hw	1st Floor-194 Nurse's Office	2	EA	7	10+ years	
	Doors Wood Doors Incid IIW	Restroom	_	L/ \	,	101 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-194 Nurse's Office	100	SF	7	10+ years	
	ricor The Geranno, Forcelan	Restroom	100	O.	,	101 years	
	Floor Drain	1st Floor-194 Nurse's Office	3	EA	7	10+ years	
	1 IOOI DIAIII	Restroom	3	LA	'	10+ years	
	Lavatory	1st Floor-194 Nurse's Office	1	EA	7	10+ years	
	Lavalory	Restroom	1	LA	′	10+ years	
	Lighting Lovin		2	Ε.Λ	7	6.10 , , , , , , , ,	
	Lighting - Lay-in	1st Floor-194 Nurse's Office	2	EA	7	6-10 years	
	Chausara	Restroom		г^	7	40	
	Showers	1st Floor-194 Nurse's Office	1	EA	7	10+ years	
	W II O	Restroom		6-	_	40	
	Walls - Concrete Block	1st Floor-194 Nurse's Office	275	SF	7	10+ years	



Catego	ategory : Room			uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		Restroom					
	Walls - Plaster/Drywall	1st Floor-194 Nurse's Office	28	SF	7	10+ years	
		Restroom					
	Walls - Tile Ceramic/ Porcelain	1st Floor-194 Nurse's Office	355	SF	7	10+ years	
		Restroom					
	Water Closet	1st Floor-194 Nurse's Office	1	EA	7	10+ years	
		Restroom					
	Accessories	1st Floor-Boy's Restroom	322	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Boy's Restroom	322	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Boy's Restroom	322	SF	7	10+ years	
	Floor Drain	1st Floor-Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Boy's Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Boy's Restroom	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Boy's Restroom	5	EA	7	6-10 years	
	Partitions	1st Floor-Boy's Restroom	2	EA	7	10+ years	
	Urinals	1st Floor-Boy's Restroom	2	EA	7	10+ years	
	Urinals	1st Floor-Boy's Restroom	1	EA	5	1-2 years	
	Walls - Structural Glazed Tile	1st Floor-Boy's Restroom	1,060	SF	7	10+ years	
	Water Closet	1st Floor-Boy's Restroom	2	EA	7	10+ years	
	Accessories	1st Floor-Girl's Restroom	322	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Girl's Restroom	322	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Girl's Restroom	322	SF	6	10+ years	
	Floor Drain	1st Floor-Girl's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Girl's Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Girl's Restroom	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Girl's Restroom	5	EA	7	6-10 years	
	Partitions	1st Floor-Girl's Restroom	5	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor-Girl's Restroom	1,060	SF	7	10+ years	
	Water Closet	1st Floor-Girl's Restroom	4	EA	7	10+ years	
	Water Closet	1st Floor-Girl's Restroom	1	EA	4	1-2 years	Out of order
	Accessories	1st Floor-Unisex Restroom 1, in Kitchen	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Unisex Restroom 1, in Kitchen	60	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor-Unisex Restroom 1, in	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Kitchen 1st Floor-Unisex Restroom 1, in Kitchen	60	SF	7	10+ years	
	Floor Drain	1st Floor-Unisex Restroom 1, in Kitchen	1	EA	7	10+ years	
	Lavatory	1st Floor-Unisex Restroom 1, in Kitchen	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Unisex Restroom 1, in Kitchen	1	EA	7	6-10 years	



Catego	ategory : Room			uilding	: Additi	on	<u>, , , , , , , , , , , , , , , , , , , </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	1st Floor-Unisex Restroom 1, in Kitchen	375	SF	7	10+ years	
	Water Closet	1st Floor-Unisex Restroom 1, in Kitchen	1	EA	7	10+ years	
	Accessories	1st Floor-Unisex Restroom 2, in Kitchen	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Unisex Restroom 2, in Kitchen	60	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor-Unisex Restroom 2, in Kitchen	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor-Unisex Restroom 2, in Kitchen	60	SF	7	10+ years	
	Floor Drain	1st Floor-Unisex Restroom 2, in Kitchen	1	EA	7	10+ years	
	Lavatory	1st Floor-Unisex Restroom 2, in Kitchen	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor-Unisex Restroom 2, in Kitchen	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor-Unisex Restroom 2, in Kitchen	375	SF	7	10+ years	
	Water Closet	1st Floor-Unisex Restroom 2, in Kitchen	1	EA	7	10+ years	
	Accessories	2nd Floor	58	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	58	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	58	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor	1	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	167	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	167	SF	7	10+ years	
	Water Closet	2nd Floor	1	EΑ	7	10+ years	
	Accessories	2nd Floor - Boy's Restroom	242	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Boy's Restroom	242	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Boy's Restroom 2nd Floor - Boy's Restroom	242	SF	6	10+ years	
	Floor Drain	2nd Floor - Boy's Restroom 2nd Floor - Boy's Restroom	1	EA	7	10+ years	
				EA			
	Hand Dryer	2nd Floor - Boy's Restroom	1		7	6-10 years	
	Lavatory	2nd Floor - Boy's Restroom	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor - Boy's Restroom	6	EA	7	6-10 years	
	Partitions	2nd Floor - Boy's Restroom	2	EA	7	10+ years	
	Urinals	2nd Floor - Boy's Restroom	3	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor - Boy's Restroom	643	SF	7	10+ years	
	Water Closet	2nd Floor - Boy's Restroom	2	EA	7	10+ years	Updated to match current observations



Catego	ry : Room		В	uildina	: Additi		1140 S Bishop STREET, Chicago, IL 60643
20.090	.,				Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Accessories	2nd Floor - Girl's Restroom	307	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor - Girl's Restroom	307	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor - Girl's Restroom	307	SF	7	10+ years	
	Floor Drain	2nd Floor - Girl's Restroom	1	ĒΑ	7	10+ years	
	Hand Dryer	2nd Floor - Girl's Restroom	1	EA	7	6-10 years	
	Lavatory	2nd Floor - Girl's Restroom	3	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor - Girl's Restroom	6	EA	7	6-10 years	
	Partitions	2nd Floor - Girl's Restroom	4	EΑ	7	10+ years	
	Partitions	2nd Floor - Girl's Restroom	1	EΑ	5	1-2 years	Missing door
	Walls - Structural Glazed Tile	2nd Floor - Girl's Restroom	645	SF	7	10+ years	Wilcolling door
	Water Closet	2nd Floor - Girl's Restroom	5	EA	7	10+ years	
Catogo	ry : Classroom		B		: Additi	j	
Calego	Ty . Classicolli		<u> </u>	unung	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #183 (Office)						
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	860	SF	7	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	860	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	13	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,450	SF	7	10+ years	
Classroo	om #198 (Regular Classroom)						
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	886	SF	7	10+ years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	886	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,450	SF	7	10+ years	
Classroo	om #252 (Regular Classroom)						
	Casework	2nd Floor	47	LF	7	10+ years	
	Casework	2nd Floor	3	LF	5	0-1 year	Counter edge chipping, drawer front missing, handle loose
	Ceiling - Lay-in	2nd Floor	913	SF	7	10+ years	mooning, mandio 10000
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	913	SF	6	10+ years	



Catego	ry : Classroom	В	uilding				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	903	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	375	SF	6	10+ years	
Classroc	om #253 (Regular Classroom)						
	Casework	2nd Floor	50	LF	5	1-2 years	Counter edge chipped away
	Ceiling - Lay-in	2nd Floor	913	SF	7	10+ years	111 11 11 11 11 11
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	913	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	903	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	375	SF	6	10+ years	
	walls - Flastel/Drywall	Ziiu Fiooi	373	SI	Ü	10+ years	
Classroc	m #254 (Regular Classroom)						
	Casework	2nd Floor	24	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	542	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	16	SF	5	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	558	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	602	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	285	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #255 (Regular Classroom)						
	Casework	2nd Floor	24	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	558	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	558	SF	7	10+ years	
		2nd Floor	9	EA	7	6-10 years	
	Lighting - Lay-in Marker Board	2nd Floor 2nd Floor	24	LF	7		
				SF	-	6-10 years	
	Walls - Concrete Block	2nd Floor	602		7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	285	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroc	om #260 (Regular Classroom)						
	Casework	2nd Floor	50	LF	6	10+ years	



atego	ry : Classroom		В	uilding	: Addition		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	2nd Floor	860	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	860	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	ĒA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	602	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	285	SF	7	10+ years	
loooroo	om #262 (Regular Classroom)						
Jassioc	,	0-15				40	
	Casework	2nd Floor	50	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	941	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	941	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor	15	EA	7	6-10 years	
	Lighting - Lay-in	2nd Floor	1	EA	4	0-1 year	Switch, cover, missing, switches,
	Marker Board	2nd Floor	20	LF	7	6-10 years	damaged
	Walls - Concrete Block	2nd Floor	880	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	305	SF	7	10+ years	
lassroc	om #263 (Regular Classroom)						
	Casework	2nd Floor	50	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	908	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	898	SF	6	10+ years	
	Floor - Tile	2nd Floor	10	SF	5	1-2 years	Chipping tiles
		2nd Floor	15	EA	7		Chipping tiles
	Lighting - Lay-in		_	LF		6-10 years	
	Marker Board	2nd Floor	20		7	6-10 years	
	Walls - Concrete Block	2nd Floor	922	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	305	SF	7	10+ years	
lassroc	om #265 (Art Room)						
	Casework	2nd Floor	25	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,162	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	2nd Floor	1,162	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	75	SF	7	10+ years	
	JUIAYE/ GIUSEL	ZHU FIOOI	75	JΓ	1	IUT VEAIS	



XII N	Schools		11140 S Bishop STREET, Chicago, IL 60643								
Catego	ry : Classroom		В	uilding	: Additi	on					
_				_		Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
	Walls - Concrete Block	2nd Floor	1,435	SF	7	10+ years					
	Work Sink	2nd Floor	1	EA	7	10+ years	Updated quantity				
Catego	ry : Interior		В	uilding	: Additi						
			0	11014		Recommend					
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments				
_Corridor											
	Ceiling - Lay-in	1st Floor	3,577	SF	7	10+ years					
	Ceiling - Plaster/Drywall	1st Floor	565	SF	7	10+ years					
	Doors - Steel Doors incl hw	1st Floor	10	EA	7	10+ years					
	Doors - Store Front	1st Floor	2	EA	7	10+ years					
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	10+ years					
	Drinking Fountains - Single Fountain	1st Floor	2	EA	5	6-10 years	2 not working according to engineer				
	Floor - Terrazzo	1st Floor	4,232	SF	7	10+ years					
	Lighting - Lay-in	1st Floor	60	EA	7	6-10 years					
	Rescue Panel	1st Floor	1	EA	7	10+ years					
	Stairs - Terrazzo	1st Floor	4	LF	7	10+ years					
	Walls - Structural Glazed Tile	1st Floor	8,675	SF	7	10+ years					
	Ceiling - Lay-in	2nd Floor	2,755	SF	7	10+ years					
	Drinking Fountains - Single Fountain	2nd Floor	1	ĒΑ	7	10+ years					
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	5	1-2 years	Out of order				
	Floor - Terrazzo	2nd Floor	2,755	SF	7	10+ years					
	Lighting - Lay-in	2nd Floor	44	EΑ	7	6-10 years					
	Student Lockers - One Tier	2nd Floor	180	ΕA	7	10+ years					
	Walls - Structural Glazed Tile	2nd Floor	4,101	SF	7	10+ years					
_Safetv											
Salety	Camera Viewing Station	1st Floor	2	EA	7	6-10 years					
	Metal Detector	1st Floor	1	EA	7	6-10 years					
	Security Cameras	1st Floor	10	EA	7	6-10 years					
	Security Cameras Security Cameras	1st Floor	4	EA	7	6-10 years					
	cooming cameras	10111001	·	_, .	•	0 10 900.0					
Stairs											
	Ceiling - Lay-in	North East (by Door 18)	257	SF	7	10+ years					
	Floor - Terrazzo	North East (by Door 18)	257	SF	7	10+ years					
	Handrails	North East (by Door 18)	56	LF	7	10+ years					
	Lighting - Wall Mounted	North East (by Door 18)	2	EA	7	6-10 years					
	Rescue Panel	North East (by Door 18)	1	EA	7	10+ years					
	Stairs - Terrazzo	North East (by Door 18)	180	LF	7	10+ years	Corrected quantity				
	Walls - Structural Glazed Tile	North East (by Door 18)	1,445	SF	7	10+ years					
	Ceiling - Lay-in	South West (by Door 12)	257	SF	7	10+ years					
	Floor - Terrazzo	South West (by Door 12)	257	SF	7	10+ years					
	Handrails	South West (by Door 12)	56	LF	7	10+ years					



Catego	ry : Interior		Building : Addition							
			Recommend							
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Lighting - Wall Mounted	South West (by Door 12)	2	EA	7	6-10 years				
	Rescue Panel	South West (by Door 12)	1	EA	7	10+ years				
	Stairs - Terrazzo	South West (by Door 12)	180	LF	7	10+ years	Corrected quantity			
	Walls - Structural Glazed Tile	South West (by Door 12)	1,445	SF	7	10+ years	•			
<u>Vertical</u>	Conveyance									
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years				



Category : Site **Building: Site**

Catego	ry . Site		B	unung	. Site	_	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Lighting	North	4	EA	6	6-10 years	
	Surface - Asphalt	North	3,572	SF	6	6-10 years	
	Surface - Asphalt	North	10,000	SF	6	6-10 years	Recalculated quantity
	Surface - Aspiran	North	10,000	Oi	O	0-10 years	recalculated quantity
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	7	10+ years	repaired
	Civil/ Drainage - Catch Basin	Entire Site	33	EA	6	10+ years	•
	Civil/ Drainage - Catch Basin	Entire Site	2	ΕA	4	0-1 year	Collapsing
	Civil/ Drainage - Site Manhole	Entire Site	8	EΑ	6	10+ years	Conaponing
	Civil/ Drainage - Site Manhole	Entire Site	1	EA	4	1-2 years	Cracked cover
	Civili Dialilage - Site Marifiole	Littile Site	'	LA	7	1-2 years	Clacked cover
Fencing							
·	Fencing - Chain Link	Entire Site	236	LF	6	6-10 years	Recombined quantities
	Fencing - Chain Link	Entire Site	150	LF	4	2-5 years	Corroded fence
	Fencing - Guard Rail	Entire Site	150	LF	4	1-2 years	Corroded fence, damaged, and
	g					,	missing sections
	Fencing - New Standard Ornamental	Entire Site	1,694	LF	6	10+ years	Recombined quantities
	Fencing - New Standard Ornamental	Entire Site	590	LF	4	1-2 years	Corroded fence
	r ending - New Standard Smanlental	Littile Oite	550	L	7	1-2 years	Confoded ferrice
Landsca	pe						
	Benches	Entire Site	8	EA	6	10+ years	
	Landscape - Grass	Entire Site	30,371	SF	6	10+ years	
	Landscape - Grass	Entire Site	4,700	SF	5	2-5 years	
	Landscape - Grass	Entire Site	500	SF	4	1-2 years	Bare soil
	Landscape - Hardscape- Asphalt	Entire Site	26,317	SF	6	6-10 years	Dai o con
	Landscape - Hardscape- Asphalt	Entire Site	3,500	SF	5	1-2 years	Alligatored, cracks, potholes
				SF	7		Headed 1000 ft.² for new concrete
	Landscape - Hardscape- Concrete	Entire Site	1,450	SF	,	10+ years	near North playground
	Landscape - Hardscape- Concrete	Entire Site	300	SF	5	1-2 years	Broken, cracked concrete
	Lighting - Pole Mounted	Entire Site	24	ĒΑ	6	6-10 years	, , , , , , , , , , , , , , , , , , , ,
	Parkway trees	Entire Site	5	EΑ	7	10+ years	New
	Parkway trees	Entire Site	32	EA	6	10+ years	IACW
		Entire Site	6,750	SF	6		
	Planting Beds/ Area				-	10+ years	
	Retaining Wall - Concrete	Entire Site	1,841	SF	6	10+ years	0 1
	Retaining Wall - Concrete	Entire Site	24	SF	5	1-2 years	Cracks, seepage
	Trash Receptacles	Entire Site	6	EA	6	6-10 years	
Parking	Lot						
g	Concrete Curbs	North	673	LF	6	10+ years	
	Concrete Curbs	North	4	LF	5	1-2 years	Broken concrete
	Interior Plantings	North	120	LF	6	10+ years	Corrected quantity
	interior i fantings	140101	120	LI	U	10+ years	Concoled quantity



Catego	ry : Site	Building : Site					
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pole Mounted	North	4	EA	7	6-10 years	
	Surface - Asphalt	North	10,480	SF	6	6-10 years	
	Surface - Asphalt	North	2,500	SF	5	1-2 years	Alligatored, cracks, potholes
	Trash Compactor	North	1	EA	6	10+ years	
	Trash Enclosure - Masonry	North	910	SF	6	10+ years	
	Vehicular Screening	North	167	LF	6	10+ years	
	Concrete Curbs	South	390	LF	6	10+ years	
	Interior Plantings	South	40	LF	6	10+ years	
	Lighting - Pole Mounted	South	2	EA	6	10+ years	
	Surface - Asphalt	South	5,080	SF	6	6-10 years	
	Surface - Asphalt	South	8,000	SF	5	1-2 years	Alligatored, cracks, potholes
	Vehicular Screening	South	370	LF	6	10+ years	
_Playgrou	und						
,,,	Equipment - School Age 5-12	East	1	EA	6	6-10 years	
	Equipment - Swingset	East	1	EA	7	6-10 years	
	Surface - Poured Surface	East	2,960	SF	6	6-10 years	
	Surface - Poured Surface	East	40	SF	5	1-2 years	Torn, pulled away from edges
	Equipment - School Age 5-12	North	1	EA	5	10+ years	
	Equipment - Swingset	North	1	EA	6	10+ years	
	Surface - Poured Surface	North	3,600	SF	7	10+ years	
	Equipment - School Age 5-12	West	1	EA	4	2-5 years	Corroding equipment
	Surface - Poured Surface	West	1,100	SF	6	2-5 years	-
	Surface - Poured Surface	West	100	SF	4	0-1 year	Torn , corrected quantities
Sidewalk	KS .						
	Sidewalks - Internal Walks	Entire Site	10,470	LF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	17,271	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	1,000	SF	4	1-2 years	Upheaved, broken, shattered concrete
Signage							
-5 5	Flag Pole - Flag Pole	south and east	1	EA	7	10+ years	
	Flag Pole - Flag Pole	south and east	1	EA	6	6-10 years	
	Marquee - Free Standing Back lighted w/ LED	south and east	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	south and east	1	EA	6	10+ years	

Campus Name: Shoop Page: 47 of 50 Assessment Date: 01/31/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Shoop Page: 48 of 50 Assessment Date: 01/31/2024



Classroom Summary

Classroom Summary			_	Floor Plan	_	Glazed	Operable		_
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main					,				
Computer Lab	Regular Classroom	2nd Floor	215	215	720	132	30	N	Υ
Computer Lab	Regular Classroom	2nd Floor	222	222	1,065	243	65	N	N
Faculty Lounge	Regular Classroom	2nd Floor	223	223	720	165	50	N	N
Kindergarten	Kindergarten	1st Floor	117	117	770	165	50	N	Υ
Kindergarten	Kindergarten	1st Floor	118	118	1,305	345	172	N	Υ
Kindergarten	Regular Classroom	1st Floor	119	119	770	165	50	N	Υ
Office	Regular Classroom	1st Floor	107	107	720	165	50	N	N
Office	Regular Classroom	1st Floor	114	114	720	165	50	N	N
Office	Regular Classroom	1st Floor	128	128	720	165	50	N	Υ
Play Room	Regular Classroom	1st Floor	103	103	720	165	50	N	N
Pre School	Regular Classroom	1st Floor	122	122 & 120	1,540	165	50	N	Υ
Regular Classroom	Regular Classroom	1st Floor	101	101	720	165	50	N	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	720	165	50	N	Υ
Regular Classroom	Regular Classroom	1st Floor	104	104	720	165	50	N	Υ
Regular Classroom	Regular Classroom	1st Floor	105	105	720	165	50	N	Υ
Regular Classroom	Regular Classroom	1st Floor	125	125	720	165	50	N	Υ
Regular Classroom	Regular Classroom	1st Floor	126	126	720	165	50	N	Υ
Regular Classroom	Regular Classroom	1st Floor	127	127	720	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	201	201	720	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	202	202	720	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	720	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	205	205	720	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	207	207	720	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	217	217	720	165	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	218	218	720	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	219	219	720	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	220	220	720	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	221	221	720	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	224	224	735	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	225	225	735	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	226	226	735	165	50	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	227	227	720	132	30	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	228	228	735	165	50	N	Υ
Science Classroom	Science Classroom	1st Floor	123	123	1,185	280	140	N	Υ
Store Room	Regular Classroom	1st Floor	124	124	720	165	50	N	N
Store Room	Regular Classroom	2nd Floor	204	204	720	165	50	N	N

Building : Addition

Campus Name: Shoop Page: 49 of 50 Assessment Date: 01/31/2024



Classroom Summary

·			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Art Room	Music Room	2nd Floor	265	265	1,162	210	30	Υ	Υ
Office	Regular Classroom	1st Floor	183	163	860	210	30	Y	N
Regular Classroom	Regular Classroom	1st Floor	198	198	886	210	30	Y	N
Regular Classroom	Regular Classroom	2nd Floor	252	252	913	210	30	Y	N
Regular Classroom	Regular Classroom	2nd Floor	253	253	913	210	30	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	254	254	558	84	12	Y	N
Regular Classroom	Regular Classroom	2nd Floor	255	255	558	84	12	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	260	260	860	210	30	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	262	262	941	210	30	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	263	263	908	168	24	Υ	Υ