

6206 N Hamlin AVENUE, Chicago, IL 60659

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1953	1	18,083
Addition	1956	1	22,250
Campus Total			40,333

Category : Exterior Building : Main

July	I Y . Exterior			unung			
0	Wa T	Lagation	O	LIOM	Danila	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	1						
	Entrance Control - Audio and Video	Entrance 1 - SE	1	EA	6	6-10 years	
	Exterior Doors - Exterior Wood Door	Entrance 1 - SE	2	EA	6	6-10 years	
	Exterior Doors - Side lite	Entrance 1 - SE	4	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 1 - SE	3	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 1 - SE	36	LF	6	10+ years	
	Exterior Stairs - Concrete	Entrance 1 - SE	4	LF	5	1-2 years	Spalled
	Power Door Operator and Controls	Entrance 1 - SE	1	EA	4	0-1 year	Disconnected/not functional
	Ramp Handrail - Steel_Ramp Handrail	Entrance 1 - SE	35	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	Entrance 1 - SE	1	LF	7	10+ years	
	Ramps - Concrete	Entrance 1 - SE	30	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Entrance 2 - East	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Entrance 2 - East	9	LF	6	10+ years	
	Exterior Stairs - Concrete	Entrance 2 - East	3	LF	5	1-2 years	Chipped
	Stair Handrail - Steel_Stair Handrail	Entrance 2 - East	4	LF	6	10+ years	
	Exterior Doors - Exterior Wood Door	Entrance 3 - North	2	EA	6	2-5 years	
	Exterior Doors - Side lite	Entrance 3 - North	2	EA	6	2-5 years	
	Exterior Doors - Transom Lite	Entrance 3 - North	3	EA	6	2-5 years	
	Exterior Stairs - Concrete	Entrance 3 - North	30	LF	6	10+ years	Changed to match current observations
	Exterior Stairs - Concrete	Entrance 3 - North	3	LF	5	1-2 years	Cracking/chipping
	Ramp Handrail - Steel_Ramp Handrail	Entrance 3 - North	68	LF	7	6-10 years	Changed to match current observations
	Ramp Handrail - Steel_Ramp Handrail	Entrance 3 - North	2	LF	4	0-1 year	Corroded



Catego	ry : Exterior		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ramps - Concrete	Entrance 3 - North	35	LF	5	1-2 years	Cracking/chipping at the railing base
	Stair Handrail - Steel_Stair Handrail	Entrance 3 - North	36	LF	3	1-2 years	Broken at the bottom base/corroded. Not secured
	Exterior Doors - Exterior Stainless Steel Door	Entrance 8 - NE - Boiler room	1	EA	6	6-10 years	Changed to match current observations
Foundat	on						
	Foundation - Concrete	Entire Building	628	LF	7	10+ years	
	Foundation - Concrete	Entire Building	4	LF	5	1-2 years	Cracking
	Superstructure - Steel	Entire Building	18,083	SF	7	10+ years	
Lighting							
919	Exterior Lighting - Wall Mounted	Entire Building	9	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	4	0-1 year	Not functional
Roof Sys	stem						
,	Coping - Stone	Roof 4	12	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 4	13	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 4	12	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 4	144	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 4	144	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 5	20	LF	6	10+ years	
	Coping - Stone	Roof 5	87	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 5	87	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 5	20	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 5	1,295	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 5	1,295	SF	7	10+ years	
	Concrete Topping	11001 3	1,233	Oi	,	10+ years	
	Coping - Metal	Roof 6	250	LF	6	10+ years	
	Coping - Stone	Roof 6	258	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 6	310	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 6	52	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 6	16	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof 6	186	LF	6	10+ years	
	Parapet - Parapet > 30"	Roof 6	7	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 6	49	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 6	10,511	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	Roof 6	10,511	SF	7	10+ years	
	Concrete Topping		,			-	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 7	28	LF	7	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Chimney - Brick Chimney- Concrete/ Mortar	Roof 7	28	LF	7	10+ years	
	Liner						
	Coping - Stone	Roof 7	82	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof 7	13	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 7	78	LF	7	10+ years	
	Parapet - Parapet > 30"	Roof 7	4	LF	7	10+ years	
	Roof - Modified Bitumen	Roof 7	1,406	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	Roof 7	1,406	SF	6	10+ years	
	Concrete Topping						
	Coping - Stone	Roof 8	165	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 8	26	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 8	165	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 8	2,552	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 8	2,552	SF	7	10+ years	
	Concrete Topping					•	
	Coping - Stone	Roof 9	12	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 9	1	LF	7	10+ years	Changed to match current
	·					,	observations
	Parapet - 16" - 30" Height	Roof 9	12	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 9	32	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof 9	32	SF	7	10+ years	
	Concrete Topping					,	
	5						
Valls							
	Canopy - Concrete/ Stucco	Entire Building	130	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	4,870	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	468	SF	6	10+ years	
		3				, , , , , ,	
Vindows	3						
	Guard - Guards perforated	Entire Building	2,453	SF	6	10+ years	
	Lintels - Steel	Entire Building	360	LF	6	10+ years	
	Storefront Windows	Entire Building	110	SF	6	10+ years	
	Windows - Decorative	Entire Building	4	SF	6	10+ years	
	Windows - Louver	Entire Building	92	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	2,447	SF	6	10+ years	
	-		_				
atego	ry : Electrical		В	uilding	: Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	ncy System						
-5	Emergency A/C Power - Corridors and Stairs	1st Floor	3,200	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and	1st Floor	6	EA	6	2-5 years	



						206 N Hamlin AVENUE, Chicago, IL 60659
ry : Electrical		В	uilding	: Main		
Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Stairs				_		
					•	
					,	
Security System - Intrusion Detection	Entire Building	18,803	SF	6	6-10 years	
rvice						
PA System	Entire Building	18,083	SF	6	6-10 years	Served from addition
istribution						
Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	10+ years	
ry : Fire Protection		В	uilding	: Main		
			_		Recommend	
Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
m						
		1				
						Serves main & addition
Fire Alarm_System	Entire Building	18,083	SF	7	6-10 years	
ry : Mechanical		В	uilding	: Main		
		•			Recommend	
	Location	Quantity	UOM	Rank	Replacement	Comments
Chiller-Air Cooled-Scroll Type-Ground Mounted - 50 - 100 tons	Site North	1	EA	7	10+ years	New install in 2024. In the process o install.
Glycol Feed	Site North	1	EA	7	6-10 years	Glycol is manually fed into the system
Pipes - Dual Temperature Pipe- Galvanized	Site North	700	LF	7	10+ years	
Pressure Fill System	Site North	1	EA	7	6-10 years	Pressure fill system via the dual temperature pumps
ling Systems						
Fan Coil Unit- Floor Mounted - Hot Water-	1st Floor	1	EA	6	6-10 years	
3	1st Floor	4	⊏^	6	6 10 4000	
Heating	151 F1001	1	EA	Ö	o-10 years	
Fan Coil Unit- Floor Mounted - Hot Water-	1st Floor	1	EA	6	6 10 years	
	15t E1001	1	ĽΑ	6	6-10 years	
Heating Fan Coil Unit- Floor Mounted - Hot Water-	1st Floor					
	Stairs Exit Signs - Corridors and Stairs Security System - CCTV Security System - Intrusion Detection PA System istribution Lighting and Power Panels - Above 100 A ry: Fire Protection Item - Type M Fire ALarm Anunciator Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm_System ry: Mechanical Item - Type itioning Chemical Pot Feeder Chiller-Air Cooled-Scroll Type-Ground Mounted - 50 - 100 tons Glycol Feed Pipes - Dual Temperature Pipe- Galvanized Pressure Fill System Fan Coil Unit- Floor Mounted - Hot Water- Heating Fan Coil Unit- Floor Mounted - Hot Water-	Stairs Exit Signs - Corridors and Stairs Security System - CCTV Security System - Intrusion Detection Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building Entire B	Stairs Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Security System - CCTV Security System - Intrusion Detection Entire Building 18,803 Extribution Lighting and Power Panels - Above 100 A Entire Building 3 Fire Protection Entire Building 1 Fire Alarm Anunciator Fire Alarm Panel Entire Building 1 Fire Alarm Strobe Lights Fire Alarm_System Entire Building 18,803 Fire Alarm_System Entire Building 18,003 Fire A	Stairs Exit Signs - Corridors and Stairs Exit Signs - Corridors and Stairs Security System - CCTV Entire Building 18,803 SF Security System - Intrusion Detection Entire Building 18,803 SF Notice PA System Entire Building 18,083 SF Intrice PA System Entire Building 18,083 SF Intrice PA System Entire Building 18,083 SF Intrice Protection Building Item - Type Location Quantity UOM Intrice Alarm Anunciator Fire Alarm Panel Fire Alarm Strobe Lights Fire Alarm System Entire Building 18,083 SF Fire Alarm_System Entire Building 18,083 SF Fire System Entire Building Item - Type Location Quantity UOM Intrication Item - Type Location Quantity UOM Intrication Item - Type Intrication Interication Int	Stairs Exit Signs - Corridors and Stairs Exit Signs - CCTV Entire Building 18,803 SF 6 Security System - Intrusion Detection Entire Building 18,803 SF 6 Extrice PA System Entire Building 18,083 SF 6 Extrice PA System Entire Building 18,083 SF 6 Extrice Extribution Lighting and Power Panels - Above 100 A Entire Building 3 EA 6 Extrice PA System Entire Building 1 EA 7 Fire Alarm Anunciator Fire Alarm Panel Entire Building 1 EA 7 Fire Alarm Strobe Lights Entire Building 1 1 EA 7 Fire Alarm_System Entire Building 1 1 EA 7 Extrice Building	Stairs Exit Signs - Corridors and Stairs 1st Floor 4 EA 6 6-10 years Security System - CCTV Entire Building 18,803 SF 6 6-10 years Security System - Intrusion Detection Entire Building 18,803 SF 6 6-10 years Security System - Intrusion Detection Entire Building 18,803 SF 6 6-10 years Security System - Intrusion Detection Interior Detection Detection Detection Intrusion Detection Interior Detection Detection Detection Detection Intrusion Detection Detection Intrusion Detection Intrusion Detection Detecti



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Sy							
	Boiler Auxiliary- Scotch Marine- Hot Water Boiler - 1000 - 2000 MBH	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	3	EA	6	10+ years	
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years	Glycol is manually fed into the system
	Non Condensing- Scotch Marine- Hot Water Boiler - 1000 - 2000 MBH	Boiler Room	2	EA	3	10+ years	Broken tubes, leaking in both boiler. Lower tubes. Work Order in for repair, per engineer.
	Piping - Dual Temperature Pipes- Galvanized	Boiler Room	300	LF	6	10+ years	par anginari
	Water Fill System	Boiler Room	1	EA	6	6-10 years	Pressure fill system off the dual temperature pumps
Heating							
	Unit Heater - Hot Water	Boiler Room	1	EA	6	6-10 years	
_Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	HWP-2
	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	HWP-1
	Dual Temperature Pump - 10 - 20 HP	Boiler Room	1	EA	6	6-10 years	HWP-3
	Dual Temperature Pump - 10 - 20 HP	Boiler Room	1	EA	6	6-10 years	HWP-4
_Tempera	ature Control						
	DDC System	Entire Building	15,940	SF	5	0-1 year	Per engineer, DDC/BAS system is not working
	Electric Thermostat	Entire Building	12	EA	6	6-10 years	G
	Thermostats - DDC	Entire Building	3	EA	4	0-1 year	Sensors hooked into failing BAS
_Unit Ven							
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	1st Floor	4	EA	7	10+ years	105, 103a,b,c
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	1st Floor	10	EA	4	0-1 year	Per engineer, fans are blowing, but dampers do not modulate, and the water valve doesn't work. Due to BAS failure.
_Ventilatio							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	

Campus Name: Solomon Page : 5 of 26 Assessment Date: 07/18/2024



Ontario S				*I -F*	84.1	Ь	206 N Hamlin AVENUE, Chicago, IL 60659
Catego	ry : Mechanical		E	Building	: Main	_	
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Catagra	m Dlumbina		-	ب ما الماني	. Mair		
Catego	ry : Plumbing			uilding	: wain	Decemmend	
Craun	Itam Tuna	Location	Ougatitu	UOM	Rank	Recommend	Comments
Group	Item - Type	Location	Quantity	UCIVI	Kalik	Replacement	Comments
Hot Wate							
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
_Piping					_		
	Domestic Piping-Hot Water Return Lines	Entire Building	15,940	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	15,940	SF	6	10+ years	
	(Horizontal Lines)	Fatire Duilding	45.040	C.E.	•	0.40	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	15,940	SF	6	6-10 years	
	(from Risers to Fixtures) Sanitary Piping	Entire Building	15,940	SF	6	10+ years	
	Storm Piping	Entire Building	15,940	SF	6	6-10 years	
	Vent Piping	Entire Building	15,940	SF	6	10+ years	
	vent i iping	Littile Ballaling	13,940	OI.	O	10+ years	
Pumps							
ипро	Pumps - Sump-Simplex	Basement	1	EA	7	10+ years	2021 install, not previously assessed
	Pumps - Sump-Simplex	Basement	1	EA	7	10+ years	2023
	Pumps - Sump-Simplex	Basement	1	EΑ	6	6-10 years	Not previously assessed
	Tampa Samp Sampan		·		•	,	p y accessor
Catego	ry : Room		E	Building	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Splined	103A	338	SF	7	10+ years	
	Doors - Steel Doors incl hw	103A	1	EA	7	10+ years	
	Floor - Tile	103A	338	SF	7	10+ years	
	Lighting - Pendent/Surface	103A	10	EA	7	6-10 years	
	Power Distribution	103A	5	EA	7	10+ years	
	Walls - Concrete Block	103A	310	SF	7	10+ years	
	Walls - Plaster/Drywall	103A	189	SF	7	10+ years	
	Ceiling - Splined	103B	350	SF	7	10+ years	
	Doors - Steel Doors incl hw	103B	1	EA	7	10+ years	
	Floor - Tile	103B	350	SF	7	10+ years	
	Lighting - Pendent/Surface	103B	10	EA	7	6-10 years	
	Power Distribution	103B	8	EA	7	10+ years	
	Walls - Concrete Block	103B	120	SF	7	10+ years	
	Walls - Plaster/Drywall	103B	410	SF	7	10+ years	
	Work Sink	103B	1	EA	7	10+ years	
	Ceiling - Splined	103C	391	SF	7	6-10 years	
	Doors - Steel Doors incl hw	103C	1	EA	7	10+ years	
	Jama: Colomon		Dogo : 6 of 26				Accomment Date: 07/49/2024



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	103C	391	SF	7	10+ years	
	Lighting - Pendent/Surface	103C	9	EA	7	6-10 years	
	Power Distribution	103C	6	EA	7	10+ years	
	Walls - Concrete Block	103C	340	SF	7	10+ years	
	Walls - Plaster/Drywall	103C	510	SF	7	10+ years	
	Work SInk	103C	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	Engineer's Office in Boiler Room	85	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Office in Boiler Room	1	EA	6	10+ years	
	Floor - Concrete	Engineer's Office in Boiler Room	85	SF	7	10+ years	
	Lighting - Pendent/Surface	Engineer's Office in Boiler Room	1	EA	5	6-10 years	Missing cover
	Power Distribution	Engineer's Office in Boiler Room	6	EA	6	10+ years	
	Walls - Concrete Block	Engineer's Office in Boiler Room	210	SF	6	10+ years	
	Walls - Masonry	Engineer's Office in Boiler Room	210	SF	6	10+ years	
	Ceiling - Splined	Room 103 lobby	105	SF	7	10+ years	
	Floor - Tile	Room 103 lobby	105	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 103 lobby	2	EA	7	6-10 years	
	Walls - Concrete Block	Room 103 lobby	120	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 103 lobby	168	SF	7	10+ years	
	Ceiling - Splined	Speech Room	195	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	Speech Room	1	EΑ	7	10+ years	
	Floor - Tile	Speech Room	185	SF	7	6-10 years	
	Floor - Tile	Speech Room	10	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	Speech Room	1	EΑ	7	6-10 years	
	Lighting - Pendent/Surface	Speech Room	1	EΑ	5	6-10 years	
	Walls - Concrete Block	Speech Room	630	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Splined	Recreation room	810	SF	7	6-10 years	
	Floor - Tile	Recreation room	810	SF	7	6-10 years	
	Lighting - Pendent/Surface	Recreation room	13	EA	7	6-10 years	
	Lighting - Pendent/Surface	Recreation room	1	EA	5	6-10 years	
	Walls - Masonry	Recreation room	800	SF	7	10+ years	
Mechani	cal/ Service Rooms						
	Boiler Room	Main floor and basement	1,260	SF	7	10+ years	
	Janitor's Closet	Main floor and basement	60	SF	7	10+ years	
	Storage Room	Main floor and basement	35	SF	7	10+ years	
	Storage Room	Main floor and basement	115	SF	7	10+ years	
	Storage Room	Main floor and basement	75	SF	7	10+ years	
Restroor	n						
	Accessories	103	20	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	103	20	SF	6	10+ years	
			_0	٥.	ŭ	121) 505	



Catego	ategory : Room Building : Main						
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	103	1	EA	7	10+ years	
	Floor - Tile	103	20	SF	7	10+ years	
	Lighting - Pendent/Surface	103	1	EA	7	10+ years	
	Walls - Concrete Block	103	50	SF	7	10+ years	
	Walls - Structural Glazed Tile	103	100	SF	7	10+ years	
	Water Closet	103	1	EA	7	10+ years	
	Accessories	104	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	104	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	104	1	ĒA	7	10+ years	
	Floor - Tile	104	30	SF	6	10+ years	
	Lavatory	104	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	104	1	ĒΑ	7	10+ years	
	Walls - Concrete Block	104	55	SF	7	10+ years	
	Walls - Structural Glazed Tile	104	105	SF	7	10+ years	
	Water Closet	104	103	EA	7	10+ years	
	Accessories	105	20	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	105	20	SF	7	10+ years	
	Doors - Wood Doors inclu hw	105	1	EA	7	10+ years	
	Floor - Tile	105	20	SF	6	10+ years	
	Lighting - Pendent/Surface	105	1	EA	6		
	Walls - Concrete Block	105	50	SF		10+ years	
				SF SF	7	10+ years	
	Walls - Structural Glazed Tile	105	100		7	10+ years	
	Water Closet	105	1	EA	7	10+ years	
	Accessories	106	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	106	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	106	1	EA	7	10+ years	
	Floor - Tile	106	30	SF	7	10+ years	
	Lavatory	106	1	EA	7	10+ years	
	Lighting - Pendent/Surface	106	1	EA	7	10+ years	
	Walls - Concrete Block	106	55	SF	7	10+ years	
	Walls - Structural Glazed Tile	106	105	SF	7	10+ years	
	Water Closet	106	1	EA	7	10+ years	
	Accessories	108	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	108	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	108	1	EA	7	10+ years	
	Floor - Tile	108	30	SF	7	10+ years	
	Lavatory	108	1	EA	7	10+ years	
	Lighting - Pendent/Surface	108	1	EA	6	10+ years	
	Walls - Concrete Block	108	55	SF	7	10+ years	
	Walls - Structural Glazed Tile	108	105	SF	7	10+ years	
	Water Closet	108	1	EA	7	10+ years	
	Accessories	In Boiler Room	53	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Boiler Room	53	SF	6	10+ years	
	Doors - Wood Doors inclu hw	In Boiler Room	1	EA	7	10+ years	
						,	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	In Boiler Room	53	SF	6	10+ years	
	Lavatory	In Boiler Room	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In Boiler Room	1	EA	7	6-10 years	
	Partitions	In Boiler Room	1	EA	7	10+ years	
	Walls - Concrete Block	In Boiler Room	226	SF	7	10+ years	
	Water Closet	In Boiler Room	1	EA	7	10+ years	
	Accessories	Northeast Boys'	170	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Northeast Boys'	165	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Northeast Boys'	5	SF	5	2-5 years	
	Doors - Wood Doors inclu hw	Northeast Boys'	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Northeast Boys'	170	SF	6	10+ years	
	Floor Drain	Northeast Boys'	1	EΑ	4	10+ years	Missing Drain grate
	Lavatory	Northeast Boys'	1	EΑ	7	10+ years	
	Lighting - Lay-in	Northeast Boys'	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Northeast Boys'	1	EA	7	10+ years	
	Partitions	Northeast Boys'	1	EA	7	10+ years	
	Urinals	Northeast Boys'	1	EA	7	10+ years	
	Walls - Concrete Block	Northeast Boys'	460	SF	7	10+ years	
	Walls - Structural Glazed Tile	Northeast Boys'	460	SF	6	10+ years	
	Water Closet	Northeast Boys'	1	EΑ	7	10+ years	
	Accessories	Northeast Girls'	170	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Northeast Girls'	170	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Northeast Girls'	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Northeast Girls'	170	SF	7	10+ years	
	Floor Drain	Northeast Girls'	1	EA	7	10+ years	
	Lavatory	Northeast Girls'	1	EA	7	10+ years	
	Lighting - Lay-in	Northeast Girls'	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Northeast Girls'	1	EA	7	10+ years	
	Partitions	Northeast Girls'	2	EA	7	6-10 years	
	Walls - Concrete Block	Northeast Girls'	460	SF	7	10+ years	
	Walls - Structural Glazed Tile	Northeast Girls'	460	SF	7	10+ years	
	Water Closet	Northeast Girls'	2	EA	7	10+ years	
	Accessories	Speech Room	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Speech Room	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Speech Room	1	EA	7	10+ years	
	Floor - Tile	Speech Room	30	SF	6	10+ years	
	Lavatory	Speech Room	1	EA	6	10+ years	
	Lighting - Pendent/Surface	Speech Room	1	EA	7	2-5 years	
	Partitions	Speech Room	1	EA	7	6-10 years	
	Walls - Concrete Block	Speech Room	55	SF	7	10+ years	
	Walls - Structural Glazed Tile	Speech Room	105	SF	7	10+ years	
	Water Closet	Speech Room	1	EA	7	10+ years	



Catego	ry : Classroom		В	uilding	: Main		200 N Hallilli AVENUE, Chicago, IL 60639
3	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #101 (Music Room)						
	Casework	1st Floor	55	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,005	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor		EA	7	10+ years	
	Floor - Tile	1st Floor	1,005	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	25	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	25	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,165	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #102 (Regular Classroom)						
	Casework	1st Floor	55	LF	6	10+ years	
	Ceiling - Splined	1st Floor	10	SF	6	6-10 years	
	Ceiling - Splined	1st Floor	995	SF	6	6-10 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,005	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	25	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,190	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #104 (Pre School)						
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Splined	1st Floor	990	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	990	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	23	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Student Lockers - One Tier	1st Floor	24	EA	6	10+ years	
	Walls - Concrete Block	1st Floor	1,640	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroc	m #105 (Kindergarten)						
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,220	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,220	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	28	ĒΑ	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	-					-	

Campus Name: Solomon Page : 10 of 26 Assessment Date: 07/18/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	1st Floor	1,515	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #106 (Kindergarten)						
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Splined	1st Floor	990	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	990	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	23	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,640	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #107 (Regular Classroom)						
	Casework	1st Floor	60	LF	7	10+ years	
	Ceiling - Splined	1st Floor	1,005	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1,000	EA	7	10+ years	
	Floor - Tile	1st Floor	1,005	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	24	EA	7	10+ years	
	Marker Board	1st Floor	5	LF	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,165	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #108 (Pre School)						
01000100	Casework	1st Floor	50	LF	6	10+ years	
	Ceiling - Splined	1st Floor	990	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	990	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	23	EA	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	20	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,640	SF	7	10+ years	
	Work Sink	1st Floor	1,040	EA	7	10+ years 10+ years	
	WOIR SIIIK	191 11001	•			10+ years	
Catego	ry : Interior		В	uilding	: Main	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	354	SF	6	10+ years	
	Ceiling - Splined	1st Floor	4,382	SF	6	10+ years	
	Doors - Wood Doors include hw	1st Floor	4	ĒΑ	7	10+ years	



Catego	ry : Interior		В	uilding	: Main	•	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	289	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	4,447	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	35	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	5	6-10 years	Missing cover
	Walls - Concrete Block	1st Floor	3,902	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,272	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,386	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,636	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor	1,500	SF	7	10+ years	
Safety							
•	Camera Viewing Station	1st Floor	2	EA	7	10+ years	
	Security Cameras	1st Floor	1	EA	7	6-10 years	4 outside cameras total
Stairs							
	Handrails	Basement	18	LF	5	10+ years	
	Stairs - Concrete	Basement	18	LF	6	10+ years	





Category : Exterior **Building: Addition**

	•			J	. , (aa	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Exterior Doors - Exterior Wood Door	Entrance 5 - SW	2	EA	6	10+ years	
	Exterior Doors - Side lite	Entrance 5 - SW	8	EA	6	10+ years	
	Exterior Doors - Transom Lite	Entrance 5 - SW	3	EΑ	6	10+ years	
	Exterior Stairs - Concrete	Entrance 5 - SW	18	LF	6	10+ years	Changed to match current
	Extend dans concrete	Emiliano o ov	10		O	101 youro	observations
	Ramp Handrail - Steel_Ramp Handrail	Entrance 5 - SW	38	LF	6	10+ years	obool valions
	Ramp Handrail - Steel_Ramp Handrail	Entrance 5 - SW	2	LF	5	1-2 years	Corroded at the base of the railing
	Ramps - Concrete	Entrance 5 - SW	18	LF	6	10+ years	
	Ramps - Concrete	Entrance 5 - SW	2	LF	5	1-2 years	Cracking
	Exterior Doors - Exterior Steel Door	Entrance 6 - North	2	EA	6	10+ years	Changed to match current
			_		•	. o . y ca. c	observations
	Exterior Stairs - Concrete	Entrance 6 - North	20	LF	6	10+ years	
	Exterior Stairs - Concrete	Entrance 6 - North	5	LF	5	1-2 years	Cracking/chipping
	Ramp Handrail - Steel_Ramp Handrail	Entrance 6 - North	40	LF	7	10+ years	Changed to match current
					-	, , , , , , , , , , , , , , , , , , , ,	observations
	Ramps - Concrete	Entrance 6 - North	14	LF	6	10+ years	
	Ramps - Concrete	Entrance 6 - North	6	LF	5	1-2 years	Cracking/chipping
	Stair Handrail - Steel_Stair Handrail	Entrance 6 - North	20	LF	7	10+ years	Changed to match current
	_					,	observations
	Stair Handrail - Steel_Stair Handrail	Entrance 6 - North	3	LF	3	0-1 year	Missing the middle rails
	Exterior Doors - Exterior Steel Door	Entrance 7 - SE	1	EΑ	6	10+ years	-
	Exterior Stairs - Concrete	Entrance 7 - SE	4	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 4 - South	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Exit 4 - South	12	LF	5	1-2 years	Cracking/spalling
	Exterior Stairs - Stone	Exit 4 - South	4	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	Exit 4 - South	8	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	Exit 4A - SE	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Exit 4A - SE	12	LF	4	1-2 years	Crumbling
	Exterior Stairs - Stone	Exit 4A - SE	4	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Exit 4A - SE	8	LF	6	10+ years	
_Foundati	on.						
_roundall	Foundation - Concrete	Entire Building	847	LF	7	10+ years	
	Foundation - Concrete	Entire Building	3	LF	6	0-1 year	Cracking/seeping water
	Foundation - Concrete	Entire Building Entire Building	40	LF	6	1-2 years	Cracking/seeping water Cracking/seeping water
	Superstructure - Concrete	Entire Building Entire Building	22,250	SF	7	10+ years	Cracking/seeping water
	Superstructure - Concrete	Entire Building	22,250	SF	,	10+ years	
Lighting							
- 3	Exterior Lighting - Wall Mounted	Entire Building	7	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	5	2-5 years	
		-				•	



Catego	ry : Exterior		В	uilding	: Additi		200 14 Hammi 74 E140E, Officago, IE 00000
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Roof Sys	stem						
_	Access Ladder - Metal	Roof 1	1	EA	7	10+ years	
	Coping - Metal	Roof 1	455	LF	6	10+ years	
	Coping - Stone	Roof 1	244	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof 1	180	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 1	244	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	18,860	SF	6	10+ years	
	Roof - Modified Bitumen	Roof 1	60	SF	4	1-2 years	Ponding/soft spots. Quantity changed to match current observations
	Roof Hatch - Metal	Roof 1	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 1	18,920	SF	7	10+ years	
	Access Ladder - Metal	Roof 2 - Gym	1	EA	7	10+ years	
	Coping - Stone	Roof 2 - Gym	92	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 2 - Gym	150	LF	6	10+ years	
	Parapet - 16" - 30" Height	Roof 2 - Gym	92	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 2 - Gym	3,150	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 2 - Gym	3,150	SF	7	10+ years	
	Coping - Stone	Roof 3	28	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Roof 3	12	LF	6	10+ years	
	Parapet - Parapet < 16" Height	Roof 3	28	LF	6	10+ years	
	Roof - Modified Bitumen	Roof 3	180	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof 3	180	SF	7	10+ years	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	185	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	8,433	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	335	SF	6	10+ years	
Windows	3						
	Clerestory - Glass Single-Pane	Entire Building	81	SF	5	6-10 years	
	Guard - Guards perforated	Entire Building	3,098	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	981	SF	6	10+ years	
	Lintels - Steel	Entire Building	430	LF	6	10+ years	
	Lintels - Stone	Entire Building	84	LF	6	10+ years	
	Windows - Louver	Entire Building	127	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,134	SF	6	10+ years	

Campus Name: Solomon Page : 14 of 26 Assessment Date: 07/18/2024



Catego	ry : Electrical		В	uilding	: Addition	on	
_			• 44			Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>-</u> merger	ncy System						
	Emergency A/C Power - Corridors and Stairs	1st Floor	4,200	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	1st Floor	4	EA	6	6-10 years	
	Exit Signs - Lunchroom	1st Floor	2	EΑ	6	6-10 years	
	Exit Signs - Multipurpose Room	1st Floor	5	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	1st Floor	6	EA	6	6-10 years	
	Emergency Battery Packs - Multipurpose Room	1st Floor	5	EA	6	6-10 years	
	Security System - CCTV	1st Floor	22,250	SF	6	6-10 years	
	Security System - Intrusion Detection	1st Floor	22,250	SF	6	6-10 years	
	Automatic Transfer Switch	Basement	1	EA	6	6-10 years	
	UPS - 30 - 60 KW	Electrical Room	1	EA	2	0-1 year	No battery, decommissioned. Abandoned in place.
<u>Main Se</u>							
	PA System Main Electrical Service - 2000 A 120/208/3PH	1st Floor Electrical Room	18,803 1	SF EA	6 6	6-10 years 6-10 years	Serves main building Serves main and addition
Power D	tistribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	1	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	6	10+ years	
Catego	ry : Fire Protection		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire Alarm Strobe Lights	Entire Building	22,250	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	22,250	SF	6	6-10 years	Served from main
Catego	ry : Mechanical		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Hand	lling Systems						
	Fan Coil Unit- Floor Mounted - Hot Water	1st Floor	1	EA	6	6-10 years	

Campus Name: Solomon Page : 15 of 26 Assessment Date: 07/18/2024



Catego	ry : Mechanical		В	uilding	: Additi		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	and Chilled Water Fan Coil Unit- Floor Mounted - Hot Water	1st Floor	1	EA	6	6-10 years	
	and Chilled Water Fan Coil Unit- Floor Mounted - Hot Water and Chilled Water	1st Floor	1	EA	6	6-10 years	
	Fan Coil Unit- Floor Mounted - Hot Water and Chilled Water	1st Floor	1	EA	6	6-10 years	
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	1	EA	5	0-1 year	MDF. Not previously assessed, Not tagged.
	Indoor Return Fans- Centrifugal Squirrel Cage - Less than 5000 CFM	Basement	1	EA	5	0-1 year	Return fan unit is old but operational, however, fan motor replaced with the wrong size motor, work order currently in for correct parts
	Air Handling Unit-Package Single Zone- Indoor- Hot Water Coils - 4000-8000 cfm	Mechanical Room	1	EA	5	0-1 year	Actuators not operating properly, due to BAS failure.
	Air Intake	Mechanical Room	1	EA	6	6-10 years	
Boiler S	vstems						
	Piping - Dual Temperature Pipes- Galvanized	Entire Building	400	LF	6	10+ years	Served from main building
Heating	Devices						
	Cabinet Heaters - With Hot Water Coil Unit Heater - Electric	1st Floor Electrical Room	7 1	EA EA	6 7	6-10 years 10+ years	
Tempera	ature Control						
	Electric Thermostat	1st Floor	7	EA	7	6-10 years	
	Thermostats - DDC	1st Floor	10	EA	7	6-10 years	
Unit Ven							
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	1st Floor	14	EA	4	0-1 year	Per engineer, fans are blowing, but dampers do not modulate, and the water valve doesn't work. Due to BAS failure.
Ventilation							
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	4	0-1 year	Fan not operating, due to being off via the nonworking BAS system
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	4	0-1 year	Fan not operating, due to being off via the nonworking BAS system

Campus Name: Solomon Page : 16 of 26 Assessment Date: 07/18/2024



Catego	ory : Mechanical		В	uilding	: Addition		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	4	0-1 year	Fan not operating, due to being o via the nonworking BAS system
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	6-10 years	
Catego	ory : Plumbing		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wat	er						
	Electric Heater - Less than 20 KW	1st Floor	1	EA	5	2-5 years	Serves kitchen only. Older model
Piping	B. C. B. C. HAWA BALL	F.C. D.11	00.050	05		40	
	Domestic Piping-Hot Water Return Lines	Entire Building	22,250	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	22,250	SF	6	10+ years	
	Sanitary Piping	Entire Building	22,250	SF	6	10+ years	
	Storm Piping	Entire Building	22,250	SF	6	10+ years	
	Vent Piping	Entire Building	22,250	SF	6	10+ years	
Pumps							
•	Pumps - Sump-Duplex	Basement	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	
Catego	ory : Room		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	trative Suites/Offices						
	AC Unit	Main Office	2	EA	7	6-10 years	
		Main Office	364	SF	6	6-10 years	
	Ceiling - Splined		304		_		
	Doors - Wood Doors inclu hw	Main Office	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw Floor - Carpet	Main Office Main Office		EA SF		10+ years 10+ years	
	Doors - Wood Doors inclu hw Floor - Carpet Lighting - Pendent/Surface	Main Office	1	EA	6		
	Doors - Wood Doors inclu hw Floor - Carpet Lighting - Pendent/Surface Power Distribution	Main Office Main Office Main Office Main Office	1 364 6 16	EA SF EA EA	6 6 7 6	10+ years 10+ years 10+ years	
	Doors - Wood Doors inclu hw Floor - Carpet Lighting - Pendent/Surface Power Distribution Walls - Concrete Block	Main Office Main Office Main Office Main Office Main Office	1 364 6	EA SF EA	6 6 7	10+ years 10+ years 10+ years 10+ years	
	Doors - Wood Doors inclu hw Floor - Carpet Lighting - Pendent/Surface Power Distribution Walls - Concrete Block AC Unit	Main Office Main Office Main Office Main Office	1 364 6 16	EA SF EA SF EA	6 6 7 6	10+ years 10+ years 10+ years	
	Doors - Wood Doors inclu hw Floor - Carpet Lighting - Pendent/Surface Power Distribution Walls - Concrete Block AC Unit Ceiling - Splined	Main Office Main Office Main Office Main Office Main Office	1 364 6 16 608	EA SF EA EA SF EA SF	6 6 7 6	10+ years 10+ years 10+ years 10+ years	
	Doors - Wood Doors inclu hw Floor - Carpet Lighting - Pendent/Surface Power Distribution Walls - Concrete Block AC Unit	Main Office Main Office Main Office Main Office Main Office Principal's Office	1 364 6 16 608 1	EA SF EA SF EA SF EA	6 6 7 6 6 7	10+ years 10+ years 10+ years 10+ years 6-10 years	
	Doors - Wood Doors inclu hw Floor - Carpet Lighting - Pendent/Surface Power Distribution Walls - Concrete Block AC Unit Ceiling - Splined	Main Office Main Office Main Office Main Office Main Office Main Office Principal's Office Principal's Office Principal's Office Principal's Office Principal's Office	1 364 6 16 608 1 182	EA SF EA EA SF EA SF	6 6 7 6 6 7 6	10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years	
	Doors - Wood Doors inclu hw Floor - Carpet Lighting - Pendent/Surface Power Distribution Walls - Concrete Block AC Unit Ceiling - Splined Doors - Wood Doors inclu hw Floor - Carpet	Main Office Main Office Main Office Main Office Main Office Main Office Principal's Office Principal's Office Principal's Office Principal's Office Principal's Office	1 364 6 16 608 1 182	EA SF EA SF EA SF EA	6 7 6 6 7 6	10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	
	Doors - Wood Doors inclu hw Floor - Carpet Lighting - Pendent/Surface Power Distribution Walls - Concrete Block AC Unit Ceiling - Splined Doors - Wood Doors inclu hw	Main Office Main Office Main Office Main Office Main Office Main Office Principal's Office Principal's Office Principal's Office	1 364 6 16 608 1 182 1	EA SF EA SF EA SF EA SF	6 6 7 6 7 6 6 7	10+ years 10+ years 10+ years 10+ years 6-10 years 6-10 years 10+ years	

Campus Name: Solomon Page : 17 of 26 Assessment Date: 07/18/2024



Catego	ry : Room		В	uilding	: Additi		200 N Hammi Avenue, Onleago, 12 00000
J				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor	2,274	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Wood	1st Floor	1,140	SF	6	10+ years	
	Floor - Wood	1st Floor	1,134	SF	6	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	10+ years	
	Sound System	1st Floor	1	EA	7	10+ years	
	Stage	1st Floor	280	SF	6	10+ years	
	Stage Curtain	1st Floor	8	ĒΑ	7	10+ years	
	Stage Lift	1st Floor	1	EA	7	10+ years	
	Stage Lighting System	1st Floor	1	EA	7	10+ years	
	Stage-Stairs - Wood	1st Floor	8	LF	6	10+ years	
	Storage/ Closet	1st Floor	90	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	6,950	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,053	SF	6	10+ years	
	Walls - Structural Glazed Tile	151 11001	1,000	SI	O	10+ years	
Library							
-	AC Unit	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	80	LF	6	10+ years	
	Ceiling - Splined	1st Floor	1,065	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	5	SF	6	6-10 years	
	Floor - Tile	1st Floor	1,060	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor	21	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	6	6-10 years	
	Walls - Concrete Block	1st Floor	1,536	SF	6	10+ years	
Lunch 8	Multipurpose Room						
LUHCH &	AC Unit	111	1	EA	7	10+ years	No occupancy signage
	Ceiling - Splined	111	302	SF	6	6-10 years	No occupancy signage
	Doors - Wood Doors inclu hw	111	1	EA	6	10+ years	No occupancy signage
	Floor - Tile	111	296	SF	6	10+ years	No occupancy signage
	Lighting - Pendent/Surface	111		EA	7	10+ years	No occupancy signage
			6	LF		•	
	Serving Line	111	10		6	10+ years	No occupancy signage
	Walls - Concrete Block	111	408	SF	6	10+ years	No occupancy signage
_MDF_ID	F						
_	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Finishes	1st Floor	125	SF	7	10+ years	
	Other Cooling Unit	1st Floor	1	EA	7	10+ years	
Machan	ical/ Service Rooms						
_wechall		1st Floor	26	SF	7	10+ vears	
_Mechan	ical/ Service Rooms Janitor's Closet	1st Floor	26	SF	7	10+ years	

Campus Name: Solomon Page : 18 of 26 Assessment Date: 07/18/2024



Catego	ry : Room		В	uilding	: Addition	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Mechanical/ Service Rooms	1st Floor	160	SF	7	10+ years	
	Storage Room	1st Floor	120	SF	7	10+ years	
	Vaults	1st Floor	108	SF	7	10+ years	
Restroor	n						
CSHOOL	Accessories	Main Office	10	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office	108	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	100	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	Main Office	108	SF	6	10+ years	
	Lavatory	Main Office	100	EA	6	10+ years	
	Lighting - Pendent/Surface	Main Office	1	EA	7	10+ years	
	Walls - Concrete Block	Main Office	320	SF	6	-	
				EA		10+ years	
	Water Closet	Main Office	1 25	SF	6 7	10+ years	
	Accessories	North		SF SF		10+ years	
	Ceiling - Plaster/Drywall	North	182		6	10+ years	
	Doors - Wood Doors inclu hw	North	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	North	182	SF	6	10+ years	
	Floor Drain	North	1	EΑ	7	10+ years	
	Lavatory	North	2	EA	6	10+ years	
	Lighting - Lay-in	North	1	EA	7	10+ years	
	Lighting - Pendent/Surface	North	2	EA	7	10+ years	
	Partitions	North	4	EA	4	0-1 year	Rust and corrosion
	Walls - Concrete Block	North	104	SF	6	10+ years	
	Walls - Structural Glazed Tile	North	312	SF	6	10+ years	
	Water Closet	North	4	EA	6	10+ years	
	Accessories	North	25	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North	182	SF	6	10+ years	
	Doors - Wood Doors inclu hw	North	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	North	182	SF	6	10+ years	
	Floor Drain	North	1	EA	7	10+ years	
	Lavatory	North	1	EA	6	10+ years	
	Lighting - Lay-in	North	4	EA	7	10+ years	
	Lighting - Pendent/Surface	North	2	EA	7	10+ years	
	Partitions	North	1	EA	7	10+ years	
	Urinals	North	3	EA	6	10+ years	
	Walls - Concrete Block	North	104	SF	7	10+ years	
	Walls - Structural Glazed Tile	North	312	SF	6	10+ years	
	Water Closet	North	1	EA	6	10+ years	
	Accessories	South men's	25	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	South men's	104	SF	6	10+ years	
	Doors - Wood Doors inclu hw	South men's	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	South men's	104	SF	6	10+ years	
	Lavatory	South men's	1	ĒΑ	6	10+ years	
	Lighting - Pendent/Surface	South men's	2	EA	7	10+ years	



Catego	ry : Room		В	uildina	: Addition		2200 N Hamiin AVENOE, Chicago, iz 00039
			_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Partitions	South men's	1	EA	7	10+ years	
	Urinals	South men's	2	EA	6	10+ years	
	Walls - Concrete Block	South men's	70	SF	6	10+ years	
	Walls - Structural Glazed Tile	South men's	240	SF	6	10+ years	
	Water Closet	South men's	1	EA	6	10+ years	
	Accessories	South women's	25	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South women's	104	SF	6	10+ years	
	Doors - Wood Doors inclu hw	South women's	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	South women's	101	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	South women's	3	SF	5	1-2 years	Damaged tiles
	Lavatory	South women's	2	EA	6	10+ years	•
	Lighting - Pendent/Surface	South women's	2	EA	7	10+ years	
	Partitions	South women's	2	EA	7	10+ years	
	Walls - Plaster/Drywall	South women's	70	SF	6	10+ years	
	Walls - Structural Glazed Tile	South women's	240	SF	6	10+ years	
	Water Closet	South women's	2	EA	6	10+ years	
Catego	ry : Classroom		В	uildina	: Additio	on	
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #110 (Art Room)		·			·	
	Casework	1st Floor	28	LF	6	6-10 years	
	Ceiling - Splined	1st Floor	740	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	740	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	778	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	86	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	Repaired
Classroo	om #112 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	10+ years	_
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Splined	1st Floor	740	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	778	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	68	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
		1001	· ·	_, .	•	10. 300.0	



Catego	ry : Classroom		В	uildina	: Additi		200 N Hallilli AVENUE, Chicago, ic 60659
2 2			_	9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #113 (Office)		·			-	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Splined	1st Floor	370	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	1st Floor	370	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	10+ years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	389	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	34	SF	6	10+ years	
_Classroo	om #114 (Regular Classroom)						
	Casework	1st Floor	6	LF	6	6-10 years	Veneer damaged
	Casework	1st Floor	30	LF	6	10+ years	.
	Ceiling - Splined	1st Floor	765	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	6	10+ years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	778	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	86	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	Repaired
Classroo	om #115 (Regular Classroom)						
	Casework	1st Floor	38	LF	6	10+ years	
	Ceiling - Splined	1st Floor	740	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	760	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	30	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	803	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	68	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	om #116 (Regular Classroom)						
	Casework	1st Floor	28	LF	7	10+ years	
	Ceiling - Splined	1st Floor	740	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	778	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	68	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Addition		
_			_			Recommend	
∃roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Work Sink	1st Floor	1	EA	7	6-10 years	
`lassroo	m #117 (Regular Classroom)						
21000100	Casework	1st Floor	28	LF	6	10+ years	
	Casework	1st Floor	6	LF	4	1-2 years	Veneer peeling
	Casework Ceiling - Splined	1st Floor	740	SF	6	10+ years	verieer peeling
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	740	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	-	
	Marker Board	1st Floor	36	LF	7	10+ years 6-10 years	
	Walls - Concrete Block	1st Floor	778	SF	6	10+ years	
		1st Floor		SF	_	•	
	Walls - Structural Glazed Tile Work Sink	1st Floor	68 1	SF EA	6 7	10+ years	
	WOIK SIIIK	181 11001	1	EA	/	6-10 years	
Classroo	m #118 (Regular Classroom)						
	Casework	1st Floor	46	LF	6	10+ years	
	Ceiling - Splined	1st Floor	740	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	730	SF	6	10+ years	
	Floor - Tile	1st Floor	10	SF	5	1-2 years	Cracking
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	.
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	778	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	68	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
laceroo	m #119 (Regular Classroom)						
Jiassiuu	AC Units	1st Floor	4	ГΛ	7	6.10 veers	
	Casework	1st Floor	1 34	EA LF	6	6-10 years 10+ years	
	Casework Ceiling - Splined	1st Floor	740	SF	6	,	
	Doors - Wood Doors inclu hw	1st Floor	140	SF EA	6	10+ years	
	Floor - Tile	1st Floor	740	SF	6	10+ years	
		1st Floor	740 16	SF EA	6 7	10+ years	
	Lighting - Pendent/Surface	1st Floor	-		7	10+ years	
	Marker Board		36	LF		6-10 years	
	Walls - Concrete Block	1st Floor	778	SF SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	68		6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #120 (Regular Classroom)						
	Casework	1st Floor	28	LF	6	10+ years	
	Ceiling - Splined	1st Floor	740	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	740	SF	6	10+ years	



atego	ry : Classroom		В	uilding	: Additi	on	
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	6-10 years	
	Marker Board	1st Floor	36	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	778	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	86	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
assroc	om #122 (Regular Classroom)						
	Casework	1st Floor	28	LF	6	10+ years	
	Ceiling - Splined	1st Floor	740	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	735	SF	6	10+ years	
	Floor - Tile	1st Floor	5	SF	5	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	18	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	778	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	86	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
			•				
atego	ry : Interior		В	uilding	: Additi	on Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	· ·					-	
<u>rridor</u>							
rridor	Ceiling - Plaster/Drywall	1st Floor	120	SF	7	10+ years	
rridor	Ceiling - Plaster/Drywall Ceiling - Splined	1st Floor 1st Floor	120 3.344	SF SF	7 7	10+ years 10+ years	
ridor	Ceiling - Splined	1st Floor	120 3,344 4	SF	7	10+ years	
rridor	Ceiling - Splined Doors - Steel Doors incl hw	1st Floor 1st Floor	3,344 4	SF EA	7 6	10+ years 10+ years	
rridor	Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors include hw	1st Floor 1st Floor 1st Floor	3,344	SF EA EA	7 6 6	10+ years 10+ years 10+ years	
rridor	Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler	1st Floor 1st Floor 1st Floor 1st Floor	3,344 4 2 4	SF EA EA	7 6 6 7	10+ years 10+ years 10+ years 10+ years	
rridor	Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain	1st Floor 1st Floor 1st Floor 1st Floor 1st Floor	3,344 4 2 4 120	SF EA EA EA SF	7 6 6 7 7	10+ years 10+ years 10+ years 10+ years 10+ years	
rridor	Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet	1st Floor	3,344 4 2 4 120 3,334	SF EA EA SF SF	7 6 6 7 7 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years	Chipped and cracked tiles
rridor	Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet	1st Floor	3,344 4 2 4 120 3,334 10	SF EA EA SF SF SF	7 6 6 7 7 7 5	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 1-2 years	Chipped and cracked tiles
rridor	Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface	1st Floor	3,344 4 2 4 120 3,334 10 34	SF EA EA SF SF SF EA	7 6 6 7 7 7 5	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 1-2 years 10+ years	
rridor	Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Lighting - Pendent/Surface	1st Floor	3,344 4 2 4 120 3,334 10 34	SF EA EA SF SF SF EA EA	7 6 6 7 7 7 5 7	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 1-2 years 1-2 years	Chipped and cracked tiles Missing lens cover
rridor	Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Lighting - Pendent/Surface Student Lockers - One Tier	1st Floor	3,344 4 2 4 120 3,334 10 34 1	SF EA EA SF SF EA EA	7 6 6 7 7 5 7 5	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 1-2 years 1-2 years 10+ years	• •
rridor	Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Lighting - Pendent/Surface Student Lockers - One Tier Walls - Concrete Block	1st Floor	3,344 4 2 4 120 3,334 10 34 1 211 844	SF EA EA SF SF EA EA SF	7 6 6 7 7 5 7 5 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 1-2 years 10+ years 1-2 years 10+ years 10+ years	
orndor	Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Lighting - Pendent/Surface Student Lockers - One Tier Walls - Concrete Block Walls - Masonry	1st Floor	3,344 4 2 4 120 3,334 10 34 1 211 844 80	SF EA EA SF SF EA EA SF SF	7 6 6 7 7 5 7 5 6 6	10+ years 1-2 years 10+ years 10+ years 10+ years	
rridor	Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Lighting - Pendent/Surface Student Lockers - One Tier Walls - Concrete Block	1st Floor	3,344 4 2 4 120 3,334 10 34 1 211 844	SF EA EA SF SF EA EA SF	7 6 6 7 7 5 7 5 6 6	10+ years 10+ years 10+ years 10+ years 10+ years 10+ years 1-2 years 10+ years 1-2 years 10+ years 10+ years	• •
afety	Ceiling - Splined Doors - Steel Doors incl hw Doors - Wood Doors include hw Drinking Fountains - Single Water Cooler Floor - Tile Ceramic/ Porcelain Floor - Tile/Sheet Floor - Tile/Sheet Lighting - Pendent/Surface Lighting - Pendent/Surface Student Lockers - One Tier Walls - Concrete Block Walls - Masonry	1st Floor	3,344 4 2 4 120 3,334 10 34 1 211 844 80	SF EA EA SF SF EA EA SF SF	7 6 6 7 7 5 7 5 6 6	10+ years 1-2 years 10+ years 10+ years 10+ years	• •





Category: Site **Building: Site**

Catego	ry : Site		В	ullaing			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Athletic							
	Surface - Asphalt	North	8,610	SF	5	6-10 years	Quantity changed to match current
	·		,			,	observations
	Surface - Asphalt	North	3,400	SF	6	10+ years	
	Surface - Synthetic	North	6,600	SF	6	2-5 years	
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	1	EA	7	10+ years	
	Civil/ Drainage - Catch Basin	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	5	EA	6	10+ years	
encing							
· ·	Fencing - Chain Link	North	180	LF	7	10+ years	
	Fencing - Chain Link	North	36	LF	6	6-10 years	
	Fencing - Chain Link	North	846	LF	6	6-10 years	
	Fencing - Chain Link	North	20	LF	5	1-2 years	Broken top railing
	Fencing - New Standard Ornamental	North	60	LF	7	10+ years	
_andsca	pe						
	Benches	Entire Site	6	EA	7	10+ years	
	Benches	Entire Site	2	EA	6	2-5 years	
	Landscape - Grass	Entire Site	21,020	SF	6	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	7,452	SF	6	6-10 years	
	Landscape - Hardscape- Asphalt	Entire Site	900	SF	5	1-2 years	Cracking
	Landscape - Hardscape- Concrete	Entire Site	708	SF	6	10+ years	0 1:
	Landscape - Hardscape- Concrete	Entire Site	150	SF	4	1-2 years	Cracking
	Parkway trees	Entire Site	2	EΑ	7	10+ years	
	Parkway trees	Entire Site	44	EA	6	10+ years	
	Planting Beds/ Area	Entire Site	5,863	SF	6	10+ years	B 1 1
	Play Area - Hardscape- Asphalt	Entire Site	2,000	SF	7	10+ years	Replaced
	Play Area - Hardscape- Asphalt	Entire Site	42,160	SF	6	6-10 years	Quantity adjusted
	Retaining Wall - Masonry	Entire Site	120	SF	6	10+ years	
	Trash Receptacles	Entire Site	14	EA	6	6-10 years	
Parking I	ot						
	Surface - Asphalt	North	12,640	SF	6	6-10 years	Quantity changed to match current observations
	Surface - Asphalt	North	600	SF	4	1-2 years	Cracking/potholes
	Surface - Aspiralit Surface - Concrete	North	648	SF	7	10+ years	Oracking/pouroies
	Trash Enclosure - Chain Links	North	612	SF	7	10+ years	
	Hash Endosule - Chain Ellins	NOILII	012	JI	,	10+ years	



Category : Site			Building : Site				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	7 1	Location	Quantity	CON	Italik	Replacement	Comments
_Playgrou							
	Equipment - Pre K 3-5	North	1	EA	7	10+ years	Newly replaced
	Equipment - School Age 5-12	North	1	EΑ	7	10+ years	
	Surface - Poured Surface	North	5,720	SF	7	6-10 years	New
Sidewalk	KS.						
	Sidewalks - Internal Walks	Entire Site	500	LF	6	10+ years	
	Sidewalks - Internal Walks	Entire Site	60	LF	5	1-2 years	Cracking
	Sidewalks - Perimeter Sidewalks	Entire Site	13,151	SF	6	10+ years	Ç
	Sidewalks - Perimeter Sidewalks	Entire Site	80	SF	5	1-2 years	Cracking apron
Signage							
0 0	Flag Pole - Flag Pole	South	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	South	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	South	1	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Solomon Page: 25 of 26 Assessment Date: 07/18/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Kindergarten	Kindergarten	1st Floor	105	105	1,220	225	112	N	Y
Kindergarten	Regular Classroom	1st Floor	106	106	990	225	112	N	Y
Music Room	Regular Classroom	1st Floor	101	101	1,005	250	125	N	N
Pre School	Regular Classroom	1st Floor	104	104	990	225	112	N	N
Pre School	Regular Classroom	1st Floor	108	108	990	225	112	N	Y
Regular Classroom	Regular Classroom	1st Floor	102	102	1,005	225	112	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	1,005	250	125	N	Y
Building : Addition									
Art Room	Regular Classroom	1st Floor	110	110	740	138	49	N	Y
Lunch Room	Regular Classroom	1st Floor	121	121	1,088	138	49	N	N
Office	Regular Classroom	1st Floor	113	113	370	69	25	N	N
Regular Classroom	Regular Classroom	1st Floor	112	112	740	138	49	N	Υ
Regular Classroom	Regular Classroom	1st Floor	114	114	740	138	49	N	Υ
Regular Classroom	Regular Classroom	1st Floor	115	115	740	138	49	N	N
Regular Classroom	Regular Classroom	1st Floor	116	116	740	138	49	N	N
Regular Classroom	Regular Classroom	1st Floor	117	117	740	138	49	N	N
Regular Classroom	Regular Classroom	1st Floor	118	118	740	138	49	N	Y
Regular Classroom	Regular Classroom	1st Floor	119	119	740	138	49	N	Υ
Regular Classroom	Regular Classroom	1st Floor	120	120	740	138	49	N	Υ
Regular Classroom	Regular Classroom	1st Floor	122	122	740	138	49	N	Y