

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition<sup>1</sup>. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1914	3	66,708
Addition 1	1998	3	42,691
Campus Total			109,399

Catego	ry : Exterior		В	uilding	: Main		
		1	0			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Cell Equ	ipment						
	Cell Equipment - Antenna	Main Roof	1	EA	7	10+ years	
	Cell Equipment - Cabinets	Main Roof	1	EA	7	10+ years	
	9						
	Entrance Control - Audio and Video	1	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	1	6	EA	6	10+ years	
	Exterior Doors - Transom Lite	1	6	EA	6	10+ years	
	Exterior Stairs - Concrete	1	48	LF	5	2-5 years	
	Ramp Handrail - Steel_Ramp Handrail	1	42	LF	5	6-10 years	
	Ramps - Concrete	1	21	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	10	1	EA	5	1-2 years	Door does not close properly
	Exterior Doors - Transom Lite	10	1	EA	6	10+ years	
	Exterior Stairs - Concrete	10	3	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	11	1	EA	5	1-2 years	Door does not close/lock properly
	Exterior Doors - Transom Lite	11	1	EA	6	10+ years	
	Exterior Stairs - Concrete	11	3	LF	5	2-5 years	
	Exterior Doors - Exterior Steel Door	12	1	EA	5	6-10 years	
	Exterior Doors - Transom Lite	12	1	EA	4	1-2 years	Rust/corrosion- deterioration of asset
	Entrance Control - Audio and Video	13	1	EA	6	6-10 years	
	Exterior Doors - Exterior Steel Door	13	4	EA	7	6-10 years	Repaired
	Exterior Stairs - Concrete	13	40	LF	7	10+ years	Repaired
	Ramp Handrail - Steel_Ramp Handrail	13	42	LF	7	6-10 years	Repaired
	Ramps - Concrete	13	21	LF	7	6-10 years	Repaired



Catego	ry : Exterior		B	uilding	: Main		
5						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
oreup	Stair Handrail - Steel_Stair Handrail	13	20	LF	7	6-10 years	Repaired
	Exterior Doors - Exterior Steel Door	9		EA	6	10+ years	Ropanoa
	Exterior Stairs - Concrete	9	20	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	9	20	LF	6	6-10 years	
		0	20	<b>_</b> .	Ũ		
oundati							
	Foundation - Concrete	Entire Building	888	LF SF	6	10+ years	
	Superstructure - Steel with Clay Tile Arch	Entire Building	66,708	SF	7	10+ years	
ighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	1	EA	7	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	6	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	5	2-5 years	Repaired
Roof Sys	stem						
	Access Ladder - Metal	Main Roof	2	EA	7	10+ years	
	Access Ladder - Metal	Main Roof	2	EA	7	10+ years	Ladder is not properly secured. Unsafe conditions to access.
	Coping - Stone	Main Roof	922	LF	5	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	280	LF	6	10+ years	
	Parapet - 16" - 30" Height	Main Roof	461	LF	5	10+ years	
	Parapet - Parapet > 30"	Main Roof	461	LF	5	10+ years	
	Roof - Asphalt Gravel Ballast	Main Roof	22,592	SF	6	6-10 years	
	Roof Hatch - Metal	Main Roof	2	EA	5	2-5 years	
	Roof Structure - Steel with Clay Tile Arch	Main Roof	22,592	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	NW Low Roof	15	LF	6	10+ years	
	Liner				Ū.	let yeare	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	NW Low Roof	48	LF	6	10+ years	
	Coping - Clay Tile	NW Low Roof	36	LF	6	6-10 years	
	Coping - Stone	NW Low Roof	140	LF	6	6-10 years	
	Downspouts - Exterior Downspouts	NW Low Roof	60	LF	6	10+ years	
	Parapet - 16" - 30" Height	NW Low Roof	140	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	NW Low Roof	6,073	SF	6	6-10 years	
	Roof Structure - Steel with Clay Tile Arch	NW Low Roof	6,073	SF	7	10+ years	
	Coping - Stone	NW Lower Roof	9	LF	7	6-10 years	
	Downspouts - Interior Downspouts	NW Lower Roof	9 12	LF	6	6-10 years	
	Parapet - Parapet > 30"	NW Lower Roof	9	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	NW Lower Roof	9 450	SF	4	1-2 years	Organic/vegetative growth coverin
					-	-	roof
	Roof Structure - Steel with Clay Tile Arch	NW Lower Roof	450	SF	7	10+ years	
	Coping - Clay Tile	SW Low Roof	40	LF	5	2-5 years	
	Coping - Stone	SW Low Roof	167	LF	5	10+ years	



					84.1	590	00 N Winthrop AVENUE, Chicago, IL 60660
Catego	ry : Exterior		B	uilding	: Main	_	
<b>A</b>	Hanna Tama	Leasting	0		Daula	Recommend	0
Group	Item - Type		Quantity	UOM LF	Rank	Replacement	Comments
	Downspouts - Exterior Downspouts	SW Low Roof	60 167		6	10+ years 2-5 years	
	Parapet - Parapet < 16" Height Roof - Asphalt Gravel Ballast	SW Low Roof	167	LF SF	5		
	Roof Structure - Steel with Clay Tile Arch	SW Low Roof SW Low Roof	4,862 4,862	SF	6 7	6-10 years 10+ years	
	Coping - Stone	SW Low Roof	4,002	LF	7		
	Downspouts - Interior Downspouts	SW Lower Roof	15	LF	6	6-10 years 6-10 years	
	Parapet - Parapet > 30"	SW Lower Roof	6	LF	7	10+ years	
	Roof - Asphalt Gravel Ballast	SW Lower Roof	354	SF	5	0-1 year	Vegetation growth and missing grav
	Rool - Aspilait Glavel Ballast	SW Lower Roor		0	5	0-1 year	throughout.
	Roof Structure - Steel with Clay Tile Arch	SW Lower Roof	354	SF	7	10+ years	throughout.
Nalls							
	Exterior Walls - Brick	Entire Building	22,300	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	23,128	SF	5	10+ years	
	Exterior Walls - Prefabricated Metal Panel Wall	Entire Building	458	SF	6	10+ years	
	Exterior Walls - Stone-Cast	Entire Building	2,052	SF	6	10+ years	
Nindows	S						
	Guard - Guards wire guard	Entire Building	974	SF	6	6-10 years	
	Lintels - Steel	Entire Building	840	LF	6	10+ years	
	Lintels - Steel	Entire Building	93	LF	5	6-10 years	
	Skylite - Glass Single-Pane	Entire Building	146	SF	5	2-5 years	
	Windows - Sash Aluminum Double-pane	Entire Building	9,393	SF	6	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Emerger	ncy System						
	UPS - 30 - 60 KW	Electrical Room	1	EA	5	6-10 years	Functional but not in use at the time of assessment.
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Automatic Transfer Switch	Electrical Room	1	EA	4	2-5 years	Switch is 50 years old and has exceeded its anticipated service life
	Security System - CCTV	Entire Building	66,708	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	66,708	SF	6	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	3	EA	2	2-5 years	Location changed for clarification as the Auditorium occupies space on multiple floors. Quantity (3) change to match current observations.
	Emergency Battery Packs - Pool	Entire Building	2	EA	6	6-10 years	Quantity changed to match current observations.
	Exit Signs - Auditoium	Entire Building	9	EA	7	6-10 years	Location changed for clarification as



Catego	ry : Electrical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
							the Auditorium occupies space on multiple floors.
	Exit Signs - Corridors and Stairs	Entire Building	21	EA	7	6-10 years	
	Exit Signs - Gym	Entire Building	1	EA	7	6-10 years	
	Exit Signs - Gym	Entire Building	1	EA	2	0-1 year	Sign has no backup battery and the
	0	C C					school has no emergency generator.
	Exit Signs - Pool	Entire Building	2	EA	7	6-10 years	Quantity changed to match current observations as there are two means of egress in the pool.
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	3,813	SF	6	6-10 years	Location changed for clarification as the Auditorium occupies space on multiple floors.
	Emergency A/C Power - Corridors and Stairs	Entire Building	12,500	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	6,200	SF	6	6-10 years	
	Emergency A/C Power - Pool	Entire Building	2,625	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	Entire Building	,	SF	6	6-10 years	
	Emergency A/C Power - Students Tollets	Entire Building	3,200	ЪГ	0	6-10 years	
Main Se							
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	6	6-10 years	Serves Main.
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Serves Main.
	PA System	Entire Building	66,708	SF	5	6-10 years	Serves Main and Addition.
Power D	listribution						
	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	Quantity changed as total has been divided/aggregated. Location changed for clarification.
	Lighting and Power Panels - Above 100 A	Entire Building	12	EA	7	10+ years	Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Open breaker slot exposes live conductors presenting a live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	Quantity changed to match current observations.
	Transformers - 120/240 - 120/208	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
Crour	Hom Tuno	Leastion	Quartity		Donk	Recommend	Commente
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar							
	Fire ALarm Anunciator	Mechanical Room	1	EA	6	6-10 years	



Catego	ry : Fire Protection		В	uilding	: Main		
_						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Fire Alarm Panel	Mechanical Room	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Mechanical Room	66,708	SF	6	6-10 years	
	Fire Alarm_System	Mechanical Room	66,708	SF	6	6-10 years	
`atoro	ry : Mechanical		B	uilding	• Main		
catego	ry . Mechanical			unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems						
	Dehumidification Unit-Outdoor- Gas Heating- DX Cooling with Self Contained Compressor - 4001 - 8000 cfm	Lower Roof	1	EA	6	10+ years	Serves pool area. No CPS Asset Ta present.
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 25001 - 35000 cfm	Mechanical Room	1	EA	6	10+ years	Serves south sections of Main.
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Auxiliaries - 25001 - 35000 cfm	Mechanical Room	1	EA	6	10+ years	
	Return Duct Work - Masonry and Ducts-	Mechanical Room	100	LF	6	10+ years	
	Missing or Existing Shaft						
	Zone Dampers	Mechanical Room	18	EA	6	10+ years	
	Air Handling Unit- Built Up-Multi Zone- Steam Coils - 15001 - 25000 cfm	Mechanical Room - AHU-1	1	EA	6	10+ years	No CPS Asset Tag present. AHU-1 Serves main building.
	Air Intake	Mechanical Room - AHU-1	1	EA	6	10+ years	5
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room - AHU-1	1	EA	6	10+ years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Mechanical Room - AHU-1	100	LF	6	10+ years	
	Zone Dampers	Mechanical Room - AHU-1	11	EA	6	10+ years	
Boiler Sy	atoma						
boller Sy	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Feed System	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	2	EA	6	10+ years	
	Condensate Pump	Boiler Room	2	EA	5	6-10 years	Priority Rep adjusted based on
	Condensate Fump	Boller Room	I	LA	5	0-10 years	current observations.
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	10+ years	
	Non Condensing- Fire Tube- Scotch Marine-	Boiler Room	1	EA	6	10+ years	B-2, serves Main.
	Steam- Low Pressure Boiler - 101 - 150 HP					,	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	6	10+ years	B-1, serves Main.
	Piping - Condensate Pipe- Steel	Boiler Room	400	LF	5	6-10 years	Priority Rep adjusted based on current observations.
	Piping - Steam Pipe- Steel	Boiler Room	400	LF	5	6-10 years	Priority Rep adjusted based on current observations.
	Steam Traps	Boiler Room	25	EA	5	6-10 years	Traps are well-maintained with no signs of leakage at the time of



Catego	ry : Mechanical		В	uilding	: Main	-	
Crown	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
Group	item - Type	Location	Quantity		Kalik	Replacement	assessment.
Heating I							
	Unit Heater - Gas	Boiler Room	1	EA	5	6-10 years	Unit has integral temperature control.
	Wall Heater - Electric	Entire Building	14	EA	5	6-10 years	Quantity changed as total has been divided/aggregated.
	Wall Heater - Electric	Entire Building	2	EA	4	0-1 year	Quantity changed to match current observations. Reason and Priority Rep changed as units are missing front cover which exposes live conductors presenting a live front condition.
Tempera	ture Control						
ľ	Electric Thermostat	Entire Building	1	EA	5	6-10 years	Location changed for clarification. Serves the vent damper assembly in the Electrical Room.
	Pneumatic System	Entire Building	66,708	SF	5	6-10 years	Priority Rep adjusted based on current observations.
	Thermostats - Pneumatic	Entire Building	29	EA	6	10+ years	Quantity changed as total has been divided/aggregated.
Ventilatic	on						
	Roof Mounted Duct Work	Entire Building	30	LF	6	10+ years	Associated with the pool area air handler. Quantity changed to match current observations as the lineal footage was confirmed by physical measurement performed at the time of assessment.
Catego	ry : Plumbing		B	uilding	• Main		
Guicgo	y : r ramoing			unung	. mani	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Serves Main.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	66,708	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	66,708	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	66,708	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	66,708	SF	6	10+ years	



Catego	ry : Plumbing		B	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	66,708	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	66,708	SF	6	10+ years	
	Sanitary Piping	Entire Building	66,708	SF	6	10+ years	
	Storm Piping	Entire Building	66,708	SF	6	10+ years	
	Vent Piping	Entire Building	66,708	SF	6	10+ years	
Pool Sys	tems						
	Pool Drain Piping	Mechanical Room	400	LF	6	10+ years	
	Pool Filtration System including Pump	Mechanical Room	1	EA	6	6-10 years	
	Pool Hot Water Heater - Gas Fired	Mechanical Room	1	EA	6	6-10 years	
	Pool Supply and Return Piping	Mechanical Room	850	LF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	2	0-1 year	No CPS Asset Tag present. Not in service and not needed to maintain adequate water pressure. Reason and Priority Rep adjusted as the equipment has s been deemed to be obsolete and has been abandoned in place.

#### Category : Room

Ū				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	003/007	150	SF	7	10+ years	
	Doors - Wood Doors inclu hw	003/007	3	EA	7	10+ years	
	Floor - Carpet	003/007	150	SF	7	6-10 years	
	Lighting - Pendent/Surface	003/007	3	EA	6	10+ years	
	Power Distribution	003/007	6	EA	7	10+ years	
	Walls - Plaster/Drywall	003/007	400	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st floor inside swimming pool	41	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor inside swimming pool	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor inside swimming pool	41	SF	7	10+ years	
	Lighting - Lay-in	1st floor inside swimming pool	1	EA	7	6-10 years	
	Power Distribution	1st floor inside swimming pool	4	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st floor inside swimming pool	84	SF	7	10+ years	
	AC Unit	Basement-Engineers Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement-Engineers Office	72	SF	5	0-1 year	Minor damage throughout.
	Doors - Wood Doors inclu hw	Basement-Engineers Office	1	EA	6	10+ years	- •
	Floor - Concrete Epoxy/ Painted	Basement-Engineers Office	72	SF	5	10+ years	

**Building : Main** 



Catego	ry : Room		R	uilding	: Main	000	
Calogo						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	Basement-Engineers Office	2	EA	7	6-10 years	
	Power Distribution	Basement-Engineers Office	4	EA	7	10+ years	
	Walls - Masonry	Basement-Engineers Office	92	SF	6	10+ years	
	Walls - Plaster/Drywall	Basement-Engineers Office	56	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Copy room north end next to 301	95	SF	6	10+ years	
	Doors - Transom Window	Copy room north end next to 301	10	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Copy room north end next to 301	1	EA	6	10+ years	
	Floor - Wood	Copy room north end next to 301	95	SF	6	10+ years	
	Lighting - Pendent/Surface	Copy room north end next to 301	2	EA	7	6-10 years	
	Power Distribution	Copy room north end next to 301	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Copy room north end next to 301	198	SF	6	10+ years	
	AC Unit	First floor, main office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor, main office	497	SF	7	10+ years	
	Doors - Transom Window	First floor, main office	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	First floor, main office	1	EA	6	10+ years	
	Floor - Tile	First floor, main office	497	SF	7	10+ years	
	Lighting - Pendent/Surface	First floor, main office	6	EA	7	6-10 years	
	Power Distribution	First floor, main office	10	EA	7	10+ years	
	Walls - Plaster/Drywall	First floor, main office	1,050	SF	7	10+ years	
	AC Unit	First floor, principal office	1	ĒA	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor, principal office	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	First floor, principal office	1	EA	6	10+ years	
	Floor - Tile	First floor, principal office	300	SF	7	10+ years	
	Lighting - Pendent/Surface	First floor, principal office	5	EA	7	6-10 years	
	Power Distribution	First floor, principal office	8	EA	7	10+ years	
	Walls - Plaster/Drywall	First floor, principal office	750	SF	7	10+ years	
	AC Unit	Room 106	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 106	620	SF	7	10+ years	
	Doors - Transom Window	Room 106	10	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 106	1	EA	6	10+ years	
	Floor - Carpet	Room 106	620	SF	6	6-10 years	
	Lighting - Pendent/Surface	Room 106	9	EA	7	6-10 years	
	Power Distribution	Room 106	12	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 106	1,227	SF	7	10+ years	
			1,221	0	,	ior yours	
Auditoriu	ım & Theater						
	Balcony Seating	1st Floor	64	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3,813	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	6	EA	6	10+ years	
	Floor - Carpet	1st Floor	3,613	SF	6	6-10 years	
	Floor - Wood	1st Floor	200	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	29	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	1	EA	6	6-10 years	
	Main Floor Seating	1st Floor	376	EA	7	10+ years	
	Main 1 1001 Ocaling		5/0		'	ior yours	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	739	SF	6	10+ years	
	Stage Curtain	1st Floor	9	EA	7	6-10 years	
	Stage Lighting System	1st Floor	1	EA	7	6-10 years	
	Stage-Stairs - Asphalt	1st Floor	8	LF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	7,400	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	46	SF	6	10+ years	
	,					5	
Gymnas							
	Ceiling - Plaster/Drywall	3rd Floor	4,736	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	20	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	6	10+ years	
	Floor - Wood	3rd Floor	4,736	SF	6	10+ years	
	Floor - Wood	3rd Floor	20	SF	4	1-2 years	Missing
	Lighting - Pendent/Surface	3rd Floor	20	EA	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	6,820	SF	6	10+ years	
		3rd Floor		SF			Water demogra
	Walls - Plaster/Drywall	310 F1001	20	55	4	1-2 years	Water damage
ocker/S	hower Room						
	Accessories	1st floor boy's next to swimming	276	SF	7	6-10 years	
		pool					
	Benches, ped mounted	1st floor boy's next to swimming	6	LF	7	10+ years	
		pool		0-	_	4.0	
	Ceiling - Plaster/Drywall	1st floor boy's next to swimming	276	SF	7	10+ years	
		pool					
	Doors - Steel Doors incl hw	1st floor boy's next to swimming	3	EA	7	10+ years	
		pool				-	
	Floor - Tile Ceramic/ Porcelain	1st floor boy's next to swimming	276	SF	7	10+ years	
		pool		•		, e , j e e	
	Floor Drain	1st floor boy's next to swimming	3	EA	7	10+ years	
		pool	5	LA	'	TOF years	
	Leveter		1	Γ.	7	10	
	Lavatory	1st floor boy's next to swimming	I	EA	7	10+ years	
		pool			_		
	Lighting - Lay-in	1st floor boy's next to swimming	4	EA	7	6-10 years	
		pool					
	Partitions	1st floor boy's next to swimming	1	EA	7	6-10 years	
		pool					
	Showers	1st floor boy's next to swimming	1	EA	7	10+ years	
		pool				2	
	Student Lockers - Two Tier	1st floor boy's next to swimming	14	EA	7	10+ years	
		pool	17	_/ \	•	is: youro	
	Walls - Plaster/Drywall	1st floor boy's next to swimming	<b>DE 4</b>	SF	7	10, 10, 10, 10, 10, 10, 10, 10, 10, 10,	
	waiis - Masiei/Drywaii		254	эг	7	10+ years	
		pool	~~~	07	_	40	
	Walls - Structural Glazed Tile	1st floor boy's next to swimming	308	SF	7	10+ years	



Catego	ory : Room		В	uilding	: Main		
Ŭ				Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•		pool	-			•	
	Water Closet	1st floor boy's next to swimming	1	EA	7	10+ years	
		pool				·	
	Accessories	1st floor girl's next to swimming pool	287	SF	7	6-10 years	
	Benches, ped mounted	1st floor girl's next to swimming pool	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st floor girl's next to swimming pool	287	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st floor girl's next to swimming pool	3	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st floor girl's next to swimming pool	287	SF	7	10+ years	
	Floor Drain	1st floor girl's next to swimming pool	4	EA	7	10+ years	
	Lavatory	1st floor girl's next to swimming pool	1	EA	7	10+ years	
	Lighting - Lay-in	1st floor girl's next to swimming pool	3	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st floor girl's next to swimming pool	1	EA	6	6-10 years	
	Partitions	1st floor girl's next to swimming pool	1	EA	7	10+ years	
	Showers	1st floor girl's next to swimming pool	4	EA	7	10+ years	
	Student Lockers - Two Tier	1st floor girl's next to swimming pool	20	EA	7	10+ years	
	Walls - Plaster/Drywall	1st floor girl's next to swimming pool	287	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st floor girl's next to swimming pool	275	SF	7	10+ years	
	Water Closet	1st floor girl's next to swimming pool	1	EA	6	10+ years	
	-						
MDF_ID		Desement	4		0	10	
	Doors - Wood Doors inclu hw	Basement	1	EA SF	6	10+ years	Material and the second
	Finishes	Basement	248		5 7	1-2 years	Water damage
	Window AC Unit	Basement	1	EA	1	6-10 years	
Mechan	ical/ Service Rooms						
	Boiler Room	1st Floor	1,731	SF	5	10+ years	
	Janitor's Closet	1st Floor	74	SF	7	10+ years	
	Janitor's Closet	1st Floor	74	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	850	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	1,821	SF	7	10+ years	
	Storage Room	1st Floor	56	SF	7	10+ years	
	Storage Room	1st Floor	30	SF	7	10+ years	
	Storage Room	1st Floor	122	SF	7	10+ years	
	Janitor's Closet	2nd Floor	74	SF	5	10+ years	
	Janitor's Closet	2nd Floor	74	SF	5	10+ years	
	Storage Room	2nd Floor	155	SF	5	10+ years	
	Janitor's Closet	3rd Floor	74	SF	5	10+ years	
	Janitor's Closet	3rd Floor	74	SF	5	10+ years	
Dool & N	Natatorium						
	Accessories	1st Floor	2,625	SF	7	6-10 years	
	Bleachers Seating/Plank Seating	1st Floor	2,025	EA	7	10+ years	
	Ceiling - Splined (Moister Resistance)	1st Floor	2,619	SF	7	10+ years	
	Centry - Spinled (Moister Resistance)		2,019	SF	'	iu+ years	



Building : MainRecommendGroupRecommendCeiling - Splined (Moister Resistance)1st FloorRecommendCeiling - Splined (Moister Resistance)1st FloorRecommendDoors - Steel Doors incl hw1st FloorReplacementCommentsDoors - Steel Doors incl hw1st Floor4EA710+ yearsFloor - Tile Ceramic/ Porcelain1st Floor2,625SF610+ yearsPool Basin1st Floor1,665SF710+ yearsPool Deck Drains1st Floor1,665SF710+ yearsPool Deck Drains1st Floor1,860SF710+ yearsWalls - Plaster/Drywall1st Floor1,873SF710+ yearsValueRecommentWalls - Plaster/Drywall1st Floor Laundry Room1RecommentPool Deck1st Floor Laundry Room12SF710+ years <th< th=""></th<>
GroupItem - TypeLocationQuantityUOMRankReplacementCommentsCeiling - Splined (Moister Resistance)1st Floor6SF41-2 yearsBig crackDoors - Steel Doors incl hw1st Floor4EA710+ yearsBig crackFloor - Tile Ceramic/ Porcelain1st Floor2,625SF610+ yearsLighting - Pendent/Surface1st Floor12EA76-10 yearsPool Basin1st Floor1,565SF710+ yearsPool Deck1st Floor1,660SF710+ yearsPool Deck Drains1st Floor8EA710+ yearsPool Deck Drains1st Floor937SF710+ yearsWalls - Plaster/Drywall1st Floor1,873SF710+ yearsWalls - Structural Glazed Tile1st Floor Laundry Room122SF710+ yearsPrep Room1EA710+ years10+ yearsFloor - Tile1st Floor Laundry Room122SF710+ yearsFloor - Tile1st Floor Laundry Room1EA710+ yearsFloor - Tile1st Floor Laundry Room102SF41-2 yearsMissingFloor - Tile1st Floor Laundry Room2SF41-2 yearsFloor - Tile1st Floor Laundry Room2SF41-2 yearsMissingFloor - Tile1st Floor Laundry Room2SF
Ceiling - Splined (Moister Resistance)1st Floor6SF41-2 yearsBig crackDoors - Steel Doors incl hw1st Floor4EA710+ yearsFloor - Tile Ceramic/ Porcelain1st Floor2,625SF610+ yearsLighting - Pendent/Surface1st Floor12EA76-10 yearsPool Basin1st Floor1,565SF710+ yearsPool Deck1st Floor1,565SF710+ yearsPool Deck Drains1st Floor1,660SF710+ yearsWalls - Plaster/Drywall1st Floor8EA710+ yearsWalls - Structural Glazed Tile1st Floor937SF710+ yearsPrep RoomCeiling - Plaster/Drywall1st Floor Laundry Room122SF710+ yearsDoors - Wood Doors inclu hw1st Floor Laundry Room1EA710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsMissingFloor - Tile1st Floor Laundry Room20SF41-2 yearsMissing1st Floor Laundry Room2EA76-10 years
Doors - Steel Doors incl hw1st Floor4EA710+ yearsFloor - Tile Ceramic/ Porcelain1st Floor2,625SF610+ yearsLighting - Pendent/Surface1st Floor12EA76-10 yearsPool Basin1st Floor1,565SF710+ yearsPool Deck1st Floor1,660SF710+ yearsPool Deck Drains1st Floor8EA710+ yearsWalls - Plaster/Drywall1st Floor937SF710+ yearsWalls - Structural Glazed Tile1st Floor1,873SF710+ yearsPrep RoomCeiling - Plaster/Drywall1st Floor Laundry Room122SF710+ yearsPoor - Tile1st Floor Laundry Room122SF710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsKising1st Floor Laundry Room20SF41-2 yearsKising1st Floor Laundry Room2EA76-10 years
Floor - Tile Ceramic/ Porcelain1st Floor2,625SF610+ yearsLighting - Pendent/Surface1st Floor12EA76-10 yearsPool Basin1st Floor1,565SF710+ yearsPool Deck1st Floor1,660SF710+ yearsPool Deck Drains1st Floor8EA710+ yearsWalls - Plaster/Drywall1st Floor937SF710+ yearsWalls - Structural Glazed Tile1st Floor937SF710+ yearsCeiling - Plaster/Drywall1st Floor Laundry Room122SF710+ yearsDoors - Wood Doors inclu hw1st Floor Laundry Room1EA710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsMissing1st Floor Laundry Room2EA76-10 years
Lighting - Pendent/Surface1st Floor12EA76-10 yearsPool Basin1st Floor1,565SF710+ yearsPool Deck1st Floor1,060SF710+ yearsPool Deck Drains1st Floor8EA710+ yearsWalls - Plaster/Drywall1st Floor937SF710+ yearsWalls - Structural Glazed Tile1st Floor937SF710+ yearsPrep RoomCeiling - Plaster/Drywall1st Floor Laundry Room122SF710+ yearsDoors - Wood Doors inclu hw1st Floor Laundry Room1EA710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsLighting - Pendent/Surface1st Floor Laundry Room2EA76-10 years
Pool Basin1st Floor1,565SF710+ yearsPool Deck1st Floor1,060SF710+ yearsPool Deck Drains1st Floor8EA710+ yearsWalls - Plaster/Drywall1st Floor937SF710+ yearsWalls - Structural Glazed Tile1st Floor937SF710+ yearsPrep RoomCeiling - Plaster/Drywall1st Floor Laundry Room122SF710+ yearsDoors - Wood Doors inclu hw1st Floor Laundry Room1EA710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsMissing1st Floor Laundry Room20SF41-2 yearsMissing1st Floor Laundry Room2EA76-10 years
Pool Deck1st Floor1,060SF710+ yearsPool Deck Drains1st Floor8EA710+ yearsWalls - Plaster/Drywall1st Floor937SF710+ yearsWalls - Structural Glazed Tile1st Floor1,873SF710+ yearsPrep RoomCeiling - Plaster/Drywall1st Floor Laundry Room122SF710+ yearsDoors - Wood Doors inclu hw1st Floor Laundry Room1EA710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsMissing1st Floor Laundry Room20SF41-2 yearsLighting - Pendent/Surface1st Floor Laundry Room2EA76-10 years
Pool Deck Drains1st Floor8EA710+ yearsWalls - Plaster/Drywall1st Floor937SF710+ yearsWalls - Structural Glazed Tile1st Floor1,873SF710+ yearsPrep RoomCeiling - Plaster/Drywall1st Floor Laundry Room122SF710+ yearsDoors - Wood Doors inclu hw1st Floor Laundry Room1EA710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsMissingLighting - Pendent/Surface1st Floor Laundry Room2EA76-10 years
Walls - Plaster/Drywall1st Floor937SF710+ yearsWalls - Structural Glazed Tile1st Floor1st Floor1,873SF710+ yearsPrep RoomCeiling - Plaster/Drywall1st Floor Laundry Room122SF710+ yearsDoors - Wood Doors inclu hw1st Floor Laundry Room1EA710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsLighting - Pendent/Surface1st Floor Laundry Room2EA76-10 years
Walls - Structural Glazed Tile1st Floor1st Floor1,873SF710+ yearsPrep RoomCeiling - Plaster/Drywall1st Floor Laundry Room122SF710+ yearsDoors - Wood Doors inclu hw1st Floor Laundry Room1EA710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsLighting - Pendent/Surface1st Floor Laundry Room2EA76-10 years
Ceiling - Plaster/Drywall1st Floor Laundry Room122SF710+ yearsDoors - Wood Doors inclu hw1st Floor Laundry Room1EA710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsLighting - Pendent/Surface1st Floor Laundry Room2EA76-10 years
Ceiling - Plaster/Drywall1st Floor Laundry Room122SF710+ yearsDoors - Wood Doors inclu hw1st Floor Laundry Room1EA710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsLighting - Pendent/Surface1st Floor Laundry Room2EA76-10 years
Doors - Wood Doors inclu hw1st Floor Laundry Room1EA710+ yearsFloor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsMissingLighting - Pendent/Surface1st Floor Laundry Room2EA76-10 years
Floor - Tile1st Floor Laundry Room102SF710+ yearsFloor - Tile1st Floor Laundry Room20SF41-2 yearsMissingLighting - Pendent/Surface1st Floor Laundry Room2EA76-10 years
Floor - Tile       1st Floor Laundry Room       20       SF       4       1-2 years       Missing         Lighting - Pendent/Surface       1st Floor Laundry Room       2       EA       7       6-10 years
Lighting - Pendent/Surface 1st Floor Laundry Room 2 EA 7 6-10 years
Walls - Plaster/Drywall1st Floor Laundry Room240SF710+ years
Restroom
Accessories 1st floor inside room 106 59 SF 7 6-10 years
Ceiling - Plaster/Drywall 1st floor inside room 106 59 SF 7 10+ years
Doors - Wood Doors inclu hw 1st floor inside room 106 1 EA 6 10+ years
Floor - Tile Ceramic/ Porcelain 1st floor inside room 106 59 SF 6 10+ years
Floor Drain 1st floor inside room 106 1 EA 7 10+ years
Lavatory 1st floor inside room 106 1 EA 7 10+ years
Lighting - Pendent/Surface 1st floor inside room 106 1 EA 7 6-10 years
Partitions 1st floor inside room 106 1 EA 7 6-10 years
Walls - Concrete Block 1st floor inside room 106 58 SF 7 10+ years
Walls - Plaster/Drywall 1st floor inside room 106 53 SF 7 10+ years
Water Closet    1st floor inside room 106    1    EA    7    10+ years
Accessories 2nd floor, Girls 336 SF 7 6-10 years
Ceiling - Plaster/Drywall 2nd floor, Girls 336 SF 6 10+ years
Doors - Steel Doors incl hw 2nd floor, Girls 1 EA 7 10+ years
Floor - Tile 2nd floor, Girls 48 SF 6 10+ years
Floor - Tile Ceramic/ Porcelain 2nd floor, Girls 288 SF 6 10+ years
Floor Drain    2nd floor, Girls    1    EA    7    10+ years
Lavatory 2nd floor, Girls 3 EA 6 10+ years
Lighting - Pendent/Surface 2nd floor, Girls 4 EA 7 6-10 years
Partitions 2nd floor, Girls 8 EA 5 1-2 years Damaged
Walls - Concrete Block2nd floor, Girls150SF610+ years
Walls - Plaster/Drywall 2nd floor, Girls 370 SF 6 10+ years
Walls - Plaster/Drywall    2nd floor, Girls    12    SF    5    1-2 years    Cracked
Walls - Structural Glazed Tile    2nd floor, Girls    377    SF    6    10+ years
Walls - Structural Glazed Tile2nd floor, Girls1SF51-2 yearsBroken



Catego	ory : Room		В	uilding	: Main		· · ·
Ŭ	·			Ŭ		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	2nd floor, Girls	8	EA	6	10+ years	
	Accessories	2nd floor, boys	371	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor, boys	351	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd floor, boys	20	SF	5	1-2 years	Damaged
	Doors - Steel Doors incl hw	2nd floor, boys	1	EA	6	10+ years	
	Floor - Tile	2nd floor, boys	48	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor, boys	323	SF	6	10+ years	
	Floor Drain	2nd floor, boys	1	EA	7	10+ years	
	Lavatory	2nd floor, boys	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd floor, boys	5	EA	7	6-10 years	
	Partitions	2nd floor, boys	4	EA	7	10+ years	
	Urinals	2nd floor, boys	6	EA	6	10+ years	
	Urinals	2nd floor, boys	1	EA	4	0-1 year	Missing
	Walls - Concrete Block	2nd floor, boys	171	SF	6	10+ years	-
	Walls - Plaster/Drywall	2nd floor, boys	362	SF	6	10+ years	
	Walls - Structural Glazed Tile	2nd floor, boys	365	SF	6	10+ years	
	Water Closet	2nd floor, boys	4	EA	6	10+ years	
	Accessories	2nd floor, south end, staff toilet	122	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor, south end, staff toilet	117	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd floor, south end, staff toilet	5	SF	5	1-2 years	Chipped
	Doors - Wood Doors inclu hw	2nd floor, south end, staff toilet	1	EA	6	10+ years	
	Floor - Tile	2nd floor, south end, staff toilet	122	SF	4	1-2 years	Cracked
	Lavatory	2nd floor, south end, staff toilet	1	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd floor, south end, staff toilet	3	EA	7	6-10 years	
	Partitions	2nd floor, south end, staff toilet	2	EA	7	10+ years	
	Walls - Concrete Block	2nd floor, south end, staff toilet	185	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd floor, south end, staff toilet	100	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd floor, south end, staff toilet	144	SF	4	1-2 years	Cracked
	Water Closet	2nd floor, south end, staff toilet	2	EA	6	10+ years	
	Accessories	3rd floor Girls	336	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor Girls	336	SF	6	10+ years	
	Doors - Side-lite	3rd floor Girls	12	SF	6	10+ years	
	Floor - Tile	3rd floor Girls	48	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor Girls	288	SF	6	10+ years	
	Floor Drain	3rd floor Girls	1	ĒA	7	10+ years	
	Lavatory	3rd floor Girls	3	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor Girls	4	EA	7	6-10 years	
	Partitions	3rd floor Girls	8	EA	5	10+ years	
	Walls - Concrete Block	3rd floor Girls	151	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd floor Girls	350	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd floor Girls	377	SF	6	10+ years	
	Water Closet	3rd floor Girls	8	EA	6	10+ years	
	Accessories	3rd floor boys	371	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor boys	371	SF	6	10+ years	
	eening Places Digital		5/1	0.	Ŭ	io: jouro	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	3rd floor boys	1	EA	6	10+ years	
	Floor - Tile	3rd floor boys	48	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor boys	323	SF	6	10+ years	
	Floor Drain	3rd floor boys	1	EA	7	10+ years	
	Lavatory	3rd floor boys	3	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor boys	4	EA	7	6-10 years	
	Partitions	3rd floor boys	4	EA	7	10+ years	
	Urinals	3rd floor boys	7	EA	6	10+ years	
	Walls - Concrete Block	3rd floor boys	171	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd floor boys	352	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd floor boys	10	SF	5	1-2 years	Cracked
	Walls - Structural Glazed Tile	3rd floor boys	395	SF	6	10+ years	
	Water Closet	3rd floor boys	4	EA	6	10+ years	
	Accessories	3rd floor, north end, staff toilet	65	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor, north end, staff toilet	65	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd floor, north end, staff toilet	1	EA	6	10+ years	
	Floor - Tile	3rd floor, north end, staff toilet	63	SF	6	6-10 years	
	Floor - Tile	3rd floor, north end, staff toilet	2	SF	4	1-2 years	Damaged
	Lavatory	3rd floor, north end, staff toilet	1	EA	6	10+ years	-
	Lighting - Pendent/Surface	3rd floor, north end, staff toilet	1	EA	7	6-10 years	
	Partitions	3rd floor, north end, staff toilet	1	EA	5	6-10 years	
	Urinals	3rd floor, north end, staff toilet	1	EA	6	10+ years	
	Walls - Plaster/Drywall	3rd floor, north end, staff toilet	100	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd floor, north end, staff toilet	42	SF	6	10+ years	
	Water Closet	3rd floor, north end, staff toilet	1	EA	6	10+ years	
	Accessories	3rd floor, south end, staff toilet	122	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor, south end, staff toilet	118	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd floor, south end, staff toilet	4	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	3rd floor, south end, staff toilet	1	EA	6	10+ years	5
	Floor - Tile	3rd floor, south end, staff toilet	122	SF	4	0-1 year	Cracked
	Lavatory	3rd floor, south end, staff toilet	1	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor, south end, staff toilet	3	EA	7	6-10 years	
	Partitions	3rd floor, south end, staff toilet	2	EA	5	6-10 years	
	Walls - Concrete Block	3rd floor, south end, staff toilet	185	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd floor, south end, staff toilet	240	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd floor, south end, staff toilet	104	SF	5	0-1 year	Damaged.
	Water Closet	3rd floor, south end, staff toilet	2	EA	6	10+ years	0
	Accessories	Boiler Room	60	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Boiler Room	60	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Boiler Room	1	EA	6	10+ years	
	Floor - Concrete	Boiler Room	60	SF	7	10+ years	
	Lavatory	Boiler Room	1	EA	7	10+ years	
	Lighting - Wall Mounted	Boiler Room	1	EA	6	6-10 years	



Catego	ry : Room		В	uilding	: Main		So in winding Avenue, onicago, ie oooo
	<b>,</b>					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	Boiler Room	1	EA	7	10+ years	
	Accessories	First floor, Girls	336	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor, Girls	336	SF	7	10+ years	
	Doors - Wood Doors inclu hw	First floor, Girls	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	First floor, Girls	335	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	First floor, Girls	1	SF	4	1-2 years	Missing
	Floor Drain	First floor, Girls	1	EA	7	10+ years	
	Lavatory	First floor, Girls	3	EA	7	10+ years	
	Lighting - Pendent/Surface	First floor, Girls	4	EA	7	6-10 years	
	Partitions	First floor, Girls	8	EA	7	10+ years	
	Walls - Concrete Block	First floor, Girls	151	SF	6	10+ years	
	Walls - Plaster/Drywall	First floor, Girls	352	SF	7	10+ years	
	Walls - Plaster/Drywall	First floor, Girls	30	SF	6	10+ years	
	Walls - Structural Glazed Tile	First floor, Girls	367	SF	6	10+ years	
	Walls - Structural Glazed Tile	First floor, Girls	10	SF	4	1-2 years	Big crack
	Water Closet	First floor, Girls	8	EA	7	10+ years	-
	Accessories	First floor, boys	371	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor, boys	371	SF	7	10+ years	
	Doors - Wood Doors inclu hw	First floor, boys	2	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	First floor, boys	371	SF	6	10+ years	
	Floor Drain	First floor, boys	1	EA	7	10+ years	
	Lavatory	First floor, boys	3	EA	7	10+ years	
	Lighting - Pendent/Surface	First floor, boys	4	EA	7	6-10 years	
	Partitions	First floor, boys	3	EA	5	0-1 year	Damaged
	Urinals	First floor, boys	7	EA	7	10+ years	-
	Walls - Concrete Block	First floor, boys	171	SF	7	10+ years	
	Walls - Plaster/Drywall	First floor, boys	362	SF	7	10+ years	
	Walls - Plaster/Drywall	First floor, boys	30	SF	6	10+ years	
	Walls - Structural Glazed Tile	First floor, boys	365	SF	6	10+ years	
	Water Closet	First floor, boys	3	EA	7	10+ years	
	Accessories	First floor, principal bathroom	111	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor, principal bathroom	111	SF	7	10+ years	
	Doors - Wood Doors inclu hw	First floor, principal bathroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	First floor, principal bathroom	111	SF	7	10+ years	
	Lavatory	First floor, principal bathroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	First floor, principal bathroom	1	EA	7	6-10 years	
	Partitions	First floor, principal bathroom	1	EA	7	10+ years	
	Walls - Concrete Block	First floor, principal bathroom	112	SF	7	10+ years	
	Walls - Plaster/Drywall	First floor, principal bathroom	130	SF	7	10+ years	
	Walls - Plaster/Drywall	First floor, principal bathroom	4	SF	5	1-2 years	Water damage
	Water Closet	First floor, principal bathroom	1	EA	7	10+ years	Ğ
Catego	ry : Classroom		R	uilding	• Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
Group	nem - Type	Location	Quantity		Nalik	Recommend	Comments

Chicago Public Schools				Geol	ge B Swift Elementary Specialty S 5900 N Winthrop AVENUE, Chicago,	
					Replacement	
ssroom #101 (Office)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	10	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	907	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Wood	1st Floor	907	SF	7	10+ years	
Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
Marker Board	1st Floor	24	LF	7	6-10 years	
Storage/ Closet	1st Floor	10	SF	5	10+ years	
Walls - Plaster/Drywall	1st Floor	1,935	SF	6	10+ years	
ssroom #102 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	7	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	836	SF	7	10+ years	
Doors - Transom Window	1st Floor	10	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	ĒA	6	10+ years	
Floor - Wood	1st Floor	836	SF	7	10+ years	
Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
Marker Board	1st Floor	22	LF	7	6-10 years	
Storage/ Closet	1st Floor	15	SF	5	10+ years	
Walls - Plaster/Drywall	1st Floor	1,930	SF	7	10+ years	
ssroom #103 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	7	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	836	SF	7	10+ years	
Doors - Transom Window	1st Floor	10	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
Floor - Wood	1st Floor	836	SF	7	10+ years	
Lighting - Pendent/Surface	1st Floor	14	ĒA	6	6-10 years	
Marker Board	1st Floor	22	LF	7	6-10 years	
Storage/ Closet	1st Floor	15	SF	7	10+ years	
Walls - Plaster/Drywall	1st Floor	1,930	SF	6	10+ years	
ssroom #107 (Regular Classroom)						
AC Units	1st Floor	1	EA	7	6-10 years	
Casework	1st Floor	3	LF	6	10+ years	
Ceiling - Plaster/Drywall	1st Floor	920	SF	6	10+ years	
Doors - Transom Window	1st Floor	920 10	SF	7	10+ years	
Doors - Wood Doors inclu hw	1st Floor	10	EA	6	10+ years	
Floor - Wood Dools Inclu IIW	1st Floor	920	SF	7	10+ years	
		920		1	IUT YEAIS	
Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	

Chicago Public Schools
------------------------------

15	~-		Replacement	
15	~-			
	SF	7	10+ years	
1,470	SF	6	10+ years	
1	EA	7	6-10 years	
3	LF	6	10+ years	
880	SF	6	10+ years	
10	SF	6	10+ years	
1	EA	7	10+ years	
870	SF	7	10+ years	
10	SF	4	1-2 years	Broken
14	EA	5	6-10 years	
24	LF	7	6-10 years	
20	SF	5	10+ years	
1,420	SF	6	10+ years	
8	SF	6	10+ years	
1	EA	7	6-10 years	
16	LF	6	10+ years	
767	SF	7	10+ years	
10	SF	7	10+ years	
1	EA	7	10+ years	
767	SF	7	10+ years	
4	EA	6	6-10 years	
8	LA	7	6-10 years	
15	SF	5	10+ years	Paint chipping and peeling.
1,270	SF	6	10+ years	r ant chipping and peeling.
1,270	01	0	TOP years	
1	EA	7	6-10 years	
4	LF	6	10+ years	
907	SF	7	10+ years	
13	LF	4	2-5 years	
1	EA	7	10+ years	
1	EA	6	10+ years	
897	SF	6	10+ years	
10	SF	4	1-2 years	Chipped
16	EA	7	6-10 years	
22	LF	7	6-10 years	
50	SF	5	10+ years	
1,935	SF	6	10+ years	
1	FΔ	7	6-10 years	
		50 SF 1,935 SF	50 SF 5 1,935 SF 6	50 SF 5 10+ years 1,935 SF 6 10+ years




Schools					59	00 N Winthrop AVENUE, Chicago, IL 60660
					Replacement	
Casework	2nd Floor	7	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	836	SF	5	10+ years	
Chalk Board	2nd Floor	13	LF	4	2-5 years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Wood	2nd Floor	836	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
Marker Board	2nd Floor	22	LF	7	6-10 years	
Storage/ Closet	2nd Floor	20	SF	5	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,947	SF	6	10+ years	
<u>Classroom #203 (Regular Classroom)</u>						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	7	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	907	SF	5	10+ years	
Chalk Board	2nd Floor	13	LF	4	2-5 years	
Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Wood	2nd Floor	900	SF	6	10+ years	
Floor - Wood	2nd Floor	7	SF	4	1-2 years	Chipped
Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	omppod
Marker Board	2nd Floor	22	LF	7	6-10 years	
Storage/ Closet	2nd Floor	20	SF	5	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,935	SF	6	10+ years	
_Classroom #204 (Regular Classroom)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	7	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	907	SF	5	10+ years	
Chalk Board	2nd Floor	13	LF	4	2-5 years	
Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Wood	2nd Floor	907	SF	6	10+ years	
Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
Marker Board	2nd Floor	22	LF	7	6-10 years	
Storage/ Closet	2nd Floor	20	SF	5	10+ years	
	2nd Floor		SF	6	•	
Walls - Plaster/Drywall	2110 11001	1,935	ЪГ	0	10+ years	
Classroom #205 (Store Room)						
AC Units	2nd Floor	1	EA	7	6-10 years	
Casework	2nd Floor	7	LF	6	10+ years	
Ceiling - Plaster/Drywall	2nd Floor	907	SF	6	10+ years	
Chalk Board	2nd Floor	18	LF	4	2-5 years	
Doors - Transom Window	2nd Floor	10	SF	6	10+ years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
Floor - Tile	2nd Floor	905	SF	7	6-10 years	



X School	OIS					59	00 N Winthrop AVENUE, Chicago, IL 60660
						Replacement	
Flo	oor - Tile	2nd Floor	2	SF	4	1-2 years	Chipped
Lig	hting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	arker Board	2nd Floor	17	LF	7	6-10 years	
Sto	orage/ Closet	2nd Floor	20	SF	5	10+ years	
	alls - Plaster/Drywall	2nd Floor	1,935	SF	6	10+ years	
			1,000	01	Ū	ior youro	
Classroom #2	206 (Regular Classroom)						
	C Units	2nd Floor	1	EA	7	6-10 years	
	asework	2nd Floor	7	LF	6	10+ years	
	eiling - Plaster/Drywall	2nd Floor	907	SF	6	10+ years	
				LF			
-	nalk Board	2nd Floor	13		4	2-5 years	
	oors - Transom Window	2nd Floor	10	SF	6	10+ years	
	oors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	bor - Wood	2nd Floor	907	SF	6	10+ years	
	hting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	arker Board	2nd Floor	22	LF	7	6-10 years	
Sto	orage/ Closet	2nd Floor	20	SF	5	10+ years	
Wa	alls - Plaster/Drywall	2nd Floor	1,930	SF	6	10+ years	
Wa	alls - Plaster/Drywall	2nd Floor	5	SF	5	1-2 years	Cracked
						,	
_Classroom #2	207 (Regular Classroom)						
AC	CUnits	2nd Floor	1	EA	7	6-10 years	
Ca	asework	2nd Floor	7	LF	6	10+ years	
	eiling - Plaster/Drywall	2nd Floor	907	SF	6	10+ years	
	nalk Board	2nd Floor	18	LF	4	2-5 years	
	oors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	ors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	oor - Wood	2nd Floor	907	SF	5	2-5 years	
						•	
	hting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	arker Board	2nd Floor	17	LF	7	6-10 years	
	orage/ Closet	2nd Floor	20	SF	5	10+ years	
Wa	alls - Plaster/Drywall	2nd Floor	1,935	SF	6	10+ years	
_Classroom #2	208 (Regular Classroom)						
	C Units	2nd Floor	1	EA	7	6-10 years	
	asework	2nd Floor	7	LF	6	10+ years	
	eiling - Plaster/Drywall	2nd Floor	836	SF	6	10+ years	
	halk Board	2nd Floor	16	LF	4	2-5 years	
	ors - Transom Window	2nd Floor	10	SF	6	10+ years	
						•	
	oors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	bor - Wood	2nd Floor	829	SF	6	10+ years	
	por - Wood	2nd Floor	7	SF	4	1-2 years	Chipped
	hting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	arker Board	2nd Floor	15	LF	7	6-10 years	
	orage/ Closet	2nd Floor	20	SF	5	10+ years	
Wa	alls - Plaster/Drywall	2nd Floor	1,968	SF	6	10+ years	
						-	




SCHOOIS					59	00 N Winthrop AVENUE, Chicago, IL 606
					Replacement	
Walls - Plaster/Drywall	2nd Floor	10	SF	5	1-2 years	Water damage
· · · · · · · · · · · · · · · · · · ·		-	-	-	<b>j</b>	
Classroom #209 (Computer Lab)						
			<b>F</b> A	7	0.40	
AC Units	2nd Floor	2	EA	7	6-10 years	
Ceiling - Lay-in	2nd Floor	755	SF	7	10+ years	
Ceiling - Lay-in	2nd Floor	34	SF	5	1-2 years	Water damage
Chalk Board	2nd Floor	12	LF	4	2-5 years	
Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
Floor - Tile	2nd Floor	789	SF	6	10+ years	
Lighting - Lay-in	2nd Floor	14	EA	7	6-10 years	
Storage/ Closet	2nd Floor	20	SF	5	10+ years	
Walls - Plaster/Drywall	2nd Floor	1,442	SF	6	10+ years	
Wireless System	2nd Floor	. 1	EA	7	6-10 years	
···· <b>·</b>					- <b>j</b>	
Classroom #301 (Regular Classroom)						
AC Units	3rd Floor	1		7	6 10 years	
			EA	7	6-10 years	
Casework	3rd Floor	4	LF	6	10+ years	
Ceiling - Plaster/Drywall	3rd Floor	964	SF	6	10+ years	
Chalk Board	3rd Floor	13	LF	4	2-5 years	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
Floor - Wood	3rd Floor	964	SF	6	10+ years	
Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
Marker Board	3rd Floor	22	LF	7	6-10 years	
Storage/ Closet	3rd Floor	50	SF	5	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,433	SF	6	10+ years	
Classroom #302 (Regular Classroom)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Casework	3rd Floor	6	LF	6	10+ years	
Ceiling - Plaster/Drywall	3rd Floor	898	SF	6	10+ years	
Chalk Board	3rd Floor	15	LF	4	2-5 years	
Doors - Transom Window	3rd Floor	10	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	3rd Floor	•	SF	-		
Floor - Wood		898		5	2-5 years	
Lighting - Pendent/Surface	3rd Floor	12	EA	7	6-10 years	
Marker Board	3rd Floor	13	LF	7	6-10 years	
Storage/ Closet	3rd Floor	20	SF	5	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,386	SF	6	10+ years	- · ·
Walls - Plaster/Drywall	3rd Floor	20	SF	5	1-2 years	Cracked
Classroom #303 (Regular Classroom)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Casework	3rd Floor	6	LF	6	10+ years	
Ceiling - Plaster/Drywall	3rd Floor	983	SF	6	10+ years	
		366	01	U	ici yourd	



Chicaao



XCR Schools					59	00 N Winthrop AVENUE, Chicago, IL 60660
					Replacement	
Floor - Wood	3rd Floor	12	SF	4	1-2 years	Cracked
Lighting - Pendent/Surface	3rd Floor	7	EA	7	6-10 years	
Lighting - Pendent/Surface	3rd Floor	7	EA	6	6-10 years	
Marker Board	3rd Floor	24	LF	7	6-10 years	
Storage/ Closet	3rd Floor	20	SF	5	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,472	SF	6	10+ years	
Classroom #307 (Regular Classroom)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Casework	3rd Floor	4	LF	6	10+ years	
Ceiling - Plaster/Drywall	3rd Floor	971	SF	6	10+ years	
Ceiling - Plaster/Drywall	3rd Floor	2	SF	4	1-2 years	Water damage
Chalk Board	3rd Floor	13	LF	4	2-5 years	0
Doors - Transom Window	3rd Floor	10	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	6	10+ years	
Floor - Wood	3rd Floor	971	SF	6	10+ years	
Floor - Wood	3rd Floor	2	SF	4	1-2 years	Chipped
Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	ompped
Marker Board	3rd Floor	22	LF	7	6-10 years	
Storage/ Closet	3rd Floor	20	SF	5	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,433	SF	6	10+ years	
Walls Tlaster/Drywall		1,400	01	0	Tor years	
Classroom #308 (Music Room)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Casework	3rd Floor	6	LF	6	•	
Ceiling - Plaster/Drywall	3rd Floor	898	SF	6	10+ years	
Chalk Board	3rd Floor	27	LF	4	10+ years	
			SF		2-5 years	
Doors - Transom Window	3rd Floor	10		6	10+ years	
Doors - Transom Window	3rd Floor	1	SF	6	10+ years	
Floor - Wood	3rd Floor	898	SF	6	10+ years	
Lighting - Metal Halide/Sodium Vapor	3rd Floor	12	EA	7	6-10 years	
Marker Board	3rd Floor	13	LF	6	6-10 years	
Storage/ Closet	3rd Floor	20	SF	5	10+ years	
Walls - Plaster/Drywall	3rd Floor	1,396	SF	6	10+ years	
Walls - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Cracked
Classroom #309 (Music Room)						
AC Units	3rd Floor	1	EA	7	6-10 years	
Ceiling - Lay-in	3rd Floor		SF	7	10+ years	
Ceiling - Lay-in	3rd Floor	4	SF	4	1-2 years	Water damage
Chalk Board	3rd Floor	29	LF	4	2-5 years	
Doors - Side-lite	3rd Floor	23	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd Floor	0	EA	6	10+ years	
Floor - Tile	3rd Floor	851	SF	6	10+ years	
Lighting - Lay-in	3rd Floor	12	EA	7		
Storage/ Closet	3rd Floor	30	SF	5	6-10 years	
Sluraye/ Glusel		30	SF	Э	10+ years	



Chicago

#### **George B Swift Elementary Specialty School**



### George B Swift Elementary Specialty School

	Schools	5900 N Winthrop AVENUE, Chicago, IL 6						
atego	ry : Interior		В	uilding	: Main			
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Stairs								
	Ceiling - Plaster/Drywall	Stair 1	256	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Stair 1	50	SF	7	10+ years		
	Floor - Epoxy/ Painted	Stair 1	306	SF	7	10+ years		
	Handrails	Stair 1	120	LF	7	10+ years		
	Lighting - Pendent/Surface	Stair 1	6	EA	7	6-10 years		
	Stairs - Rubber	Stair 1	60	LF	7	10+ years		
	Walls - Plaster/Drywall	Stair 1	660	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Stair 2	258	SF	7	10+ years		
	Floor - Concrete Epoxy/ Painted	Stair 2	258	SF	7	10+ years		
	Handrails	Stair 2	120	LF	7	10+ years		
	Lighting - Pendent/Surface	Stair 2	6	EA	7	6-10 years		
	Stairs - Rubber	Stair 2	60	LF	7	10+ years		
	Walls - Plaster/Drywall	Stair 2	650	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Stair 3	306	SF	7	10+ years		
	Floor - Epoxy/ Painted	Stair 3	306	SF	7	10+ years		
	Handrails	Stair 3	120	LF	7	10+ years		
	Lighting - Pendent/Surface	Stair 3	6	EA	7	6-10 years		
	Stairs - Rubber	Stair 3	60	LF	7	10+ years		
	Walls - Plaster/Drywall	Stair 3	650	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Stair 4	206	SF	7	10+ years		
	Ceiling - Plaster/Drywall	Stair 4	100	SF	7	10+ years		
	Floor - Epoxy/ Painted	Stair 4	306	SF	7	10+ years		
	Handrails	Stair 4	120	LF	7	10+ years		
	Lighting - Pendent/Surface	Stair 4	5	EA	7	6-10 years		
	Lighting - Pendent/Surface	Stair 4	1	EA	7	6-10 years		
	Stairs - Rubber	Stair 4	60	LF	7	10+ years		
	Malla Diastar/Drawall	Ctair 4	000	0	7	10		

Stair 4

Stair 4

200

660

SF

SF

7

6

10+ years 10+ years

Walls - Plaster/Drywall Walls - Plaster/Drywall



Category : Exterior			В	Building : Addition 1					
					Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Entrance	2								
	Entrance Control - Audio and Video	2	1	EA	6	6-10 years			
	Exterior Doors - Store Front	2	4	EA	7	10+ years			
	Exterior Doors - Transom Lite	2	4	EA	7	10+ years			
	Exterior Stairs - Concrete	2	60	LF	6	10+ years			
	Ramps - Concrete	2	27	LF	6	10+ years			
	Stair Handrail - Steel_Stair Handrail	2	40	LF	7	10+ years			
	Exterior Doors - Store Front	3	2	EA	7	10+ years			
	Exterior Stairs - Concrete	3	36	LF	5	10+ years			
	Ramps - Concrete	3	27	LF	6	10+ years			
	Stair Handrail - Steel_Stair Handrail	3	20	LF	7	10+ years			
	Exterior Doors - Exterior Steel Door	4 Exit	2	EA	6	6-10 years			
	Exterior Doors - Exterior Steel Door	5 Exit	2	EA	6	10+ years			
	Exterior Doors - Exterior Steel Door	6	- 1	EA	6	10+ years			
	Entrance Control - Audio and Video	7	1	EA	6	6-10 years			
	Exterior Doors - Exterior Steel Door	7	2	EA	7	10+ years			
	Ramp Handrail - Steel_Ramp Handrail	7	20	LF	6	10+ years			
	Ramps - Concrete	7	10	LF	6	10+ years			
	Entrance Control - Audio and Video	8	1	EA	6	2-5 years			
	Exterior Doors - Store Front	8	4	EA	6	10+ years			
	Exterior Doors - Transom Lite	8	4	EA	6	10+ years			
		5		<b>L</b> / (	Ū	ior youro			
_Foundat	ion								
	Foundation - Concrete	Entire Building	636	LF	7	10+ years			
	Superstructure - Steel	Entire Building	42,691	SF	7	10+ years			
		·				·			
Lighting									
	Exterior Lighting - Lighting	Entire Building	2	EA	6	6-10 years			
	Exterior Lighting - Wall Mounted	Entire Building	14	EA	6	6-10 years			
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	4	1-2 years	Wall sconces broken fixtures		
Roof Sy									
	Access Ladder - Metal	Main Roof	1	EA	7	10+ years			
	Coping - Stone	Main Roof	479	LF	6	10+ years			
	Downspouts - Interior Downspouts	Main Roof	312	LF	6	10+ years			
	Parapet - 16" - 30" Height	Main Roof	120	LF	6	10+ years			
	Parapet - Parapet > 30"	Main Roof	359	LF	6	10+ years			
	Roof - Modified Bitumen	Main Roof	11,480	SF	6	6-10 years			
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years			
	Roof Structure - Steel / Metal Deck/	Main Roof	11,480	SF	7	10+ years			
	Concrete Topping								
	Chimney - Metal Flue	South Low Roof	18	LF	6	10+ years			



	ry : Exterior		В	uilding	: Additi	on 1	
e	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Stone	South Low Roof	296	LF	7	10+ years	
	Downspouts - Interior Downspouts	South Low Roof	180	LF	6	10+ years	
	Parapet - 16" - 30" Height	South Low Roof	296	LF	6	10+ years	
	Roof - Modified Bitumen	South Low Roof	7,687	SF	6	6-10 years	
	Roof Structure - Steel / Metal Deck/	South Low Roof	7,687	SF	7	10+ years	
	Concrete Topping					2	
Walls							
	Cornice - Cast Stone	Entire Building	888	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	32,780	SF	6	10+ years	
	Exterior Walls - Prefabricated Metal Panel	Entire Building	620	SF	6	10+ years	
	Wall	5				,	
	Exterior Walls - Stone-Cast	Entire Building	1,272	SF	6	10+ years	
Windows							
	Curtain wall - Louver	Entire Building	185	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	427	SF	6	10+ years	
	Lintels - Steel	Entire Building	433	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,200	SF	6	10+ years	
			0,200	•	Ū	let yeare	
Catego	ry : Electrical		В	uilding	: Additi	on 1	
Ū	,			anang	.,		
Group		Location	Quantity	UOM	Rank	Recommend	Comments
Group	Item - Type	Location					Comments
Group	Item - Type ncy System Automatic Transfer Switch	Location Electrical Room	Quantity 1			Recommend Replacement 0-1 year	Comments Rank, Reason and Priority Rep changed based on current observations that originally the unit was only partially installed.
Group	Item - Type ncy System Automatic Transfer Switch Security System - CCTV	Electrical Room	Quantity 1 42,691	UOM	Rank	Recommend Replacement 0-1 year 6-10 years	Rank, Reason and Priority Rep changed based on current observations that originally the unit
Group	Item - Type hcy System Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection	Electrical Room Entire Building Entire Building	Quantity 1	UOM EA	Rank 2	Recommend Replacement 0-1 year	Rank, Reason and Priority Rep changed based on current observations that originally the unit
Group	Item - Type Docy System Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and	Electrical Room	Quantity 1 42,691	UOM EA SF	Rank 2 6	Recommend Replacement 0-1 year 6-10 years	Rank, Reason and Priority Rep changed based on current observations that originally the unit
Group	Item - Type Docy System Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Multipurpose	Electrical Room Entire Building Entire Building	Quantity 1 42,691 42,691	UOM EA SF SF	<b>Rank</b> 2 6 6	Recommend Replacement 0-1 year 6-10 years 6-10 years	Rank, Reason and Priority Rep changed based on current observations that originally the unit
Group	Item - Type Decy System Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Multipurpose Room	Electrical Room Entire Building Entire Building Entire Building Entire Building	Quantity 1 42,691 42,691 9,482 4,965	UOM EA SF SF SF SF	<b>Rank</b> 2 6 6 6 6	Recommend Replacement 0-1 year 6-10 years 6-10 years 6-10 years 6-10 years	Rank, Reason and Priority Rep changed based on current observations that originally the unit
Group	Item - Type Decy System Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Multipurpose Room Emergency A/C Power - Students Toilets	Electrical Room Entire Building Entire Building Entire Building Entire Building Entire Building	Quantity 1 42,691 42,691 9,482 4,965 1,071	UOM EA SF SF SF SF SF SF	<b>Rank</b> 2 6 6 6 6 6	Recommend Replacement 0-1 year 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Rank, Reason and Priority Rep changed based on current observations that originally the unit was only partially installed.
Group	Item - Type Decy System Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Multipurpose Room	Electrical Room Entire Building Entire Building Entire Building Entire Building	Quantity 1 42,691 42,691 9,482 4,965	UOM EA SF SF SF SF	<b>Rank</b> 2 6 6 6 6	Recommend Replacement 0-1 year 6-10 years 6-10 years 6-10 years 6-10 years	Rank, Reason and Priority Rep changed based on current observations that originally the unit was only partially installed.
Group	Item - Type Decy System Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Multipurpose Room Emergency A/C Power - Students Toilets	Electrical Room Entire Building Entire Building Entire Building Entire Building Entire Building	Quantity 1 42,691 42,691 9,482 4,965 1,071	UOM EA SF SF SF SF SF SF	<b>Rank</b> 2 6 6 6 6 6	Recommend Replacement 0-1 year 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Rank, Reason and Priority Rep changed based on current observations that originally the unit was only partially installed. Quantity changed as total has been divided/aggregated. Quantity changed as total has been
Group	Item - Type Decy System Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Emergency A/C Power - Corridors and Stairs Emergency A/C Power - Multipurpose Room Emergency A/C Power - Students Toilets Exit Signs - Corridors and Stairs	Electrical Room Entire Building Entire Building Entire Building Entire Building Entire Building Entire Building	Quantity 1 42,691 42,691 9,482 4,965 1,071 21	UOM EA SF SF SF SF SF SF EA	<b>Rank</b> 2 6 6 6 6 6 6 6 6	Recommend Replacement 0-1 year 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years 6-10 years	Rank, Reason and Priority Rep changed based on current observations that originally the unit was only partially installed. Quantity changed as total has been divided/aggregated.



Catana			Building : Addition 1					
Catego	ry : Electrical		D	unaing		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Group	Stairs	Location	Quantity		INALIK	Replacement	Comments	
	Emergency Battery Packs - Multipurpose	Entire Building	2	EA	6	6-10 years		
	Room	Entire Duilding	2	LA	0	0-10 years		
	Emergency Battery Packs - Students Toilets	Entire Building	2	EA	6	6-10 years	Location changed for clarification.	
		5			-	<b>,</b>	<u>.</u>	
Main Sei	rvice							
	Main Electrical Service - 2000 A	Electrical Room	1	EA	6	10+ years	Serves Addition	
	120/208/3PH							
	PA System	Entire Building	42,691	SF	5	6-10 years	Served by Main.	
	Independent Electrical Service for	Plumbing Room	1	EA	6	10+ years	Serves fire pump and sprinkler	
	emergency power						system. Location changed for	
							clarification.	
	istribution							
PowerD	Lighting and Power Panels - 100 A	Entire Building	4	EA	7	10+ years		
	Lighting and Power Panels - 100 A	Entire Building	4	EA	4	0-1 year	Open fuse receptacles expose live	
	Lighting and I ower I ariels - 100 A	Entite Building	1	LA	4	0-1 year	conductors presenting a live front	
							condition. Location changed for	
							clarification.	
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	7	10+ years	cianneation.	
			9	EA	7	•	Minidentified in provinue appears	
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	1	10+ years	Misidentified in previous assessme	
							Quantity changed to match current	
							observations.	
Catego	ry : Fire Protection		В	uilding	: Additi	on 1		
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Fire Alar	m							
	Fire Alarm Strobe Lights	Entire Building	42,691	SF	6	2-5 years		
	Fire Alarm_System	Entire Building	42,691	SF	6	2-5 years	FACP is in Main.	
	Fire Pump Controller	Entire Building	1	EA	6	10+ years		
Dump D								
Pump Ro	Dom Assembly	Blumbing Doom	A		6	10, , , , , , , , , , , , , , , , , , ,	Someon Addition No CDC Accest	
	Fire Pump - 25-50 hp	Plumbing Room	1	EA	6	10+ years	Serves Addition. No CPS Asset Ta	
							present. Location changed for	
							clarification.	

Serves Addition. No CPS Asset Tag Jockey Pump Plumbing Room ΕA 10+ years 1 6 present. Location changed for clarification. Sprinkler System SF SF Sprinkler Heads Entire Building 42,691 10+ years 7 Sprinkler Piping Entire Building 42,691 6 10+ years



Catego	ry : Fire Protection		В	uilding	: Additie	on 1	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Wet Sprinkler System	Entire Building	42,691	SF	6	10+ years	
atego	ry : Mechanical		В	uilding	: Additie	on 1	
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
ir Cond							
	Chemical Pot Feeder Chiller-Air Cooled- Recipricating-Roof Mounted - 101 - 200 tons	Entire Building Entire Building	1 1	EA EA	6 2	10+ years 0-1 year	Serves Addition. Rank, Reason an Priority Rep changed to note that th chiller is inoperable as it has been decommissioned and disconnected preparation for replacement in Sprin
	Dines Chilled Water Dine Steel	Entire Duilding	400		0	10	2024. No CPS Asset Tag present.
	Pipes - Chilled Water Pipe- Steel Pressure Fill System	Entire Building Entire Building	400 1	LF EA	6 6	10+ years 10+ years	
	Flessure Fill System		1	LA	0	TOF years	
ir Hand	ling Systems						
	Fan Power Box - Fan Power Box with No Coil	Entire Building	24	EA	6	10+ years	Located throughout the building above the suspended ceiling grid. Quantity changed as total has been divided/aggregated.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - 12001-20000 cfm	Mechanical Room	1	EA	6	6-10 years	AHU-2. Serves multipurpose room kitchen, and associated spaces in Addition. No CPS Asset Tag prese
	Air Intake	Mechanical Room	1	EA	6	10+ years	
	Induction Fan	Mechanical Room	1	EA	6	6-10 years	
	Indoor Return Fans- Centrifugal Inline - 10001 - 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF-2, associated with AHU-2.
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years	RF-1, associated with AHU-1.
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and Chilled Water Coils - Greater than 30,000 cfm	Mechanical Room - AHU-1	1	EA	6	6-10 years	AHU-1. Serves Addition.
	Air Intake	Mechanical Room - AHU-1	1	EA	6	10+ years	
	Induction Fan	Mechanical Room - AHU-1	1	EA	6	6-10 years	
	VAV Box	Mechanical Room - AHU-1	7	EA	6	10+ years	Located throughout the building
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	South Lower Roof	1	EA	5	6-10 years	above the suspended ceiling grid. Original 1998 equipment. Serves kitchen. No CPS Asset Tag prese Location changed for clarification.
oiler Sv	stems						
	Boiler Auxiliary- Non Condensing Hot Water	Mechanical Room	2	EA	5	6-10 years	



Category : Mechanical				Building : Addition 1					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	- 1001 - 2000 MBH								
	Chemical Pot Feeder	Mechanical Room	1	EA	5	10+ years	Quantity changed to match current		
						-	observations.		
	Combustion Dampers	Mechanical Room	1	EA	6	10+ years	Quantity changed to match current		
							observations and per review with		
							Building Engineer.		
	Non Condensing- Flexible Tube-	Mechanical Room	2	EA	5	6-10 years	B-1 and B-2. Well-maintained		
	Atmospheric- Hot Water Boiler - 1001 - 2000						equipment original to the building.		
	MBH								
	Water Fill System	Mechanical Room	1	EA	6	10+ years			
as Boo	ster								
as Duu	Gas Booster	Mechanical Room	1	EA	6	10+ years			
				L/\	U	Tor years			
eating	Devices								
	Cabinet Heaters - With Hot Water Coil	1st Floor	3	EA	6	10+ years	Location changed for clarification.		
	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years			
	Unit Heater - Electric	Entire Building	1	EA	6	6-10 years			
	Radiator Panels - Hot Water	Entire Building	6	EA	6	10+ years	Ceiling mounted in student restrooms,		
ecnani	cal Plumbing	Frating Desilations	700		0	10			
	Hydronic Supply and Return - Steel	Entire Building	700	LF EA	6	10+ years	Deiler numm No CDC Accet Ter		
	Hot Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	10+ years	Boiler pump. No CPS Asset Tag present. Leak-free at the time of		
							assessment with evidence of		
							previous leak repairs.		
	Hot Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	10+ years	Boiler pump. No CPS Asset Tag		
	Hot Water Fullip - 10 - 20 HF		1	EA	0	10+ years	present. Leak-free at the time of		
							assessment with evidence of		
							previous leak repairs.		
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	10+ years	AHU-1 recirculating pump. No CF		
		Mechanical Room	1	LA	0	TOF years	Asset Tag present. Leak-free at th		
							time of assessment with evidence		
							previous leak repairs.		
	Hot Water Pump - Less than 10	Mechanical Room	1	EA	6	10+ years	AHU-2 recirculating pump. No CF		
	The Water Fump - Less than To	Mechanical Room	1	LA	0	TUT years	Asset Tag present. Leak-free at the		
							time of assessment with evidence		
							previous leak repairs.		
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	No CPS Asset Tag present.		
	Chilled Water Pump - 10 - 20 HP	Mechanical Room	1	EA	6	6-10 years	No CPS Asset Tag present.		
			1	L7	0	U- IU years	no or o hoser ray present.		
						-			



Catego	ry : Mechanical		В	uilding	: Additi	on 1	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	DDC System	Entire Building	42,691	SF	4	1-2 years	Software, modem and computer are severely outdated resulting in poor or no communication between controls and equipment, and requiring the Building Engineer to manually control temperatures in spaces throughout the building. Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer.
	Electric Thermostat	Entire Building	6	EA	5	6-10 years	
	Thermostats - DDC	Entire Building	30	EA	6	6-10 years	Quantity changed as total has been divided/aggregated. Thermostats throughout the building are intact and may be presumed to be operational despite the absence of a fully- operational control system.
Ventilatio							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	Quantity changed as total has been divided/aggregated.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	10+ years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	4	1-2 years	Quantity, Rank, Reason and Priority Rep changed as the unit is operational but the cover of the enclosure is missing.
	Type I Exhaust Hood- Kitchen	Entire Building	1	EA	6	10+ years	3
	Type II Exhaust Hood- Warming Kitchen	Entire Building	2	EA	6	10+ years	
Catego	ry : Plumbing		В	uilding	: Additi	on 1	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Hot Wate		MashaniashDaana		<b>F A</b>	0	0.40	
	Gas Heater - Greater than 600000 BTU/HR	Mechanical Room	2	EA	6	6-10 years	Serve Addition.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	42,691	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	42,691	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	42,691	SF	6	10+ years	



Catego	ry : Plumbing	B	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	42,691	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	42,691	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	42,691	SF	6	10+ years	
	Sanitary Piping	Entire Building	42,691	SF	6	10+ years	
	Storm Piping	Entire Building	42,691	SF	6	10+ years	
	Vent Piping	Entire Building	42,691	SF	6	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	10+ years	Serves Addition. Location changed for clarification.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	10+ years	Elevator pit sump pump. Not directly accessible at the time of assessment. CPS Asset Tag not available. Condition verified by the Building Engineer. Location changed for clarification.

Category : Room

**Building : Addition 1** 

					Recommend	
roup Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dministrative Suites/Offices						
Ceiling - Lay-in	110	426	SF	6	10+ years	
Ceiling - Lay-in	110	4	SF	4	1-2 years	Stained tile
Doors - Wood Doors inclu hw	110	1	EA	5	1-2 years	Door loose on frame
Floor - Carpet	110	430	SF	6	2-5 years	
Lighting - Lay-in	110	5	EA	7	6-10 years	
Power Distribution	110	6	EA	7	10+ years	
Walls - Concrete Block	110	978	SF	7	10+ years	
Ceiling - Lay-in	310 A	160	SF	7	10+ years	
Doors - Steel Doors incl hw	310 A	1	EA	7	10+ years	
Floor - Tile	310 A	160	SF	7	10+ years	
Lighting - Lay-in	310 A	2	EA	7	10+ years	
Power Distribution	310 A	4	EA	7	10+ years	
Walls - Concrete Block	310 A	320	SF	7	10+ years	
Ceiling - Lay-in	3rd flr south end of corridor Special Ed.	399	SF	6	10+ years	
Doors - Wood Doors inclu hw	3rd flr south end of corridor Special Ed.	1	EA	7	10+ years	
Floor - Tile	3rd flr south end of corridor Special Ed.	399	SF	7	10+ years	
Lighting - Lay-in	3rd flr south end of corridor Special	3	EA	7	6-10 years	



Category : Room			В	uilding	: Additi	on 1	
J				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•		Ed.				•	
	Power Distribution	3rd flr south end of corridor Special	6	EA	7	10+ years	
		Ed.				-	
	Storage/ Closet	3rd flr south end of corridor Special	17	SF	7	10+ years	
		Ed.					
	Walls - Concrete Block	3rd flr south end of corridor Special	790	SF	7	10+ years	
		Ed.					
	Ceiling - Lay-in	Kitchen Office	56	SF	7	10+ years	
	Doors - Side-lite	Kitchen Office	15	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen Office	1	EA	7	10+ years	
	Floor - Concrete	Kitchen Office	56	SF	7	10+ years	
	Lighting - Lay-in	Kitchen Office	1	EA	7	6-10 years	
	Power Distribution	Kitchen Office	1	EA	7	10+ years	
	Walls - Concrete Block	Kitchen Office	156	SF	7	10+ years	
	Ceiling - Lay-in	Library workroom	220	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Library workroom	1	EA	7	10+ years	
	Floor - Tile	Library workroom	220	SF	7	10+ years	
	Lighting - Lay-in	Library workroom	2	EA	7	6-10 years	
	Power Distribution	Library workroom	6	EA	7	10+ years	
	Storage/ Closet	Library workroom	50	SF	7	10+ years	
	Walls - Concrete Block	Library workroom	200	SF	7	10+ years	
	Walls - Plaster/Drywall	Library workroom	300	SF	7	10+ years	
	Work SInk	Library workroom	1	EA	7	10+ years	
Kitchen			4.0.47	05	-		
	Ceiling - Lay-in	1st Floor	1,647	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	5	SF	4	1-2 years	Ceiling tile missing
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Concrete	1st Floor	1,652	SF	4	1-2 years	Floor rough throughout
	Lighting - Lay-in	1st Floor	18	EA	7	6-10 years	
	Storage/ Closet	1st Floor	120	SF	5	2-5 years	
	Storage/ Closet	1st Floor	200	SF	5	2-5 years	
	Walls - Concrete Block	1st Floor	1,910	SF	7	10+ years	
Library							
,	Casework	2nd Floor	180	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2,826	SF	7	10+ years	
	Doors - Side-lite	2nd Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒA	7	10+ years	
	Floor - Carpet	2nd Floor	2,826	SF	7	6-10 years	
	Lighting - Lay-in	2nd Floor	26	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	1,226	SF	7	10+ years	



Category : Room			В	Building : Addition 1				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Lunch &	Multipurpose Room							
	Ceiling - Exposed	1st Floor	4,065	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	876	SF	7	10+ years		
	Ceiling - Lay-in	1st Floor	24	SF	4	1-2 years	Missing and stained tile	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	7	10+ years	3	
	Floor - Tile/Sheet	1st Floor	4,945	SF	4	0-1 year	Damage from tables throughout	
	Floor - Tile/Sheet	1st Floor	20	SF	4	1-2 years	Missing floor	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	3	
	Lighting - Metal Halide/ High Pressure	1st Floor	5	EA	5	1-2 years	Not working	
	Sodium		C C	_/ \	Ū.	) • • • •		
	Lighting - Metal Halide/Sodium Vapor	1st Floor	5	EA	7	6-10 years		
	Serving Line	1st Floor	54	LF	7	10+ years		
	Walls - Concrete Block	1st Floor	8,450	SF	7	10+ years		
		13(1100)	0,400	01	'	Tor years		
MDF ID	F							
_	Doors - Transom Window	2nd Floor	1	SF	7	10+ years		
	Finishes	2nd Floor	142	SF	7	6-10 years		
Mechani	cal/ Service Rooms							
	Janitor's Closet	1st Floor	33	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	502	SF	7	10+ years		
	Storage Room	1st Floor	248	SF	7	10+ years		
	Janitor's Closet	2nd Floor	33	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	3,349	SF	7	10+ years		
	Mechanical/ Service Rooms	2nd Floor	45	SF	7	10+ years		
	Storage Room	2nd Floor	148	SF	7	10+ years		
	Storage Room	2nd Floor	65	SF	7	10+ years		
	Storage Room	2nd Floor	50	SF	5	1-2 years	Stained ceiling tile and floor	
	Janitor's Closet	3rd Floor	33	SF	5	10+ years	Ũ	
	Mechanical/ Service Rooms	3rd Floor	41	SF	7	10+ years		
	Storage Room	3rd Floor	251	SF	7	10+ years		
Restroor	n Accessories	1st floor boy's	179	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st floor boy's	175	SF	7	10+ years		
	Ceiling - Plaster/Drywall	1st floor boy's	2	SF	5	1-2 years	Cracked drywall	
	Floor - Terrazzo	1st floor boy's	179	SF	7	10+ years		
	Floor Drain	1st floor boy's	1/9	EA	7	10+ years		
	Lavatory	1st floor boy's	3	EA	7	10+ years		
	Lighting - Lay-in	1st floor boy's	5	EA	7	6-10 years		
		1st floor boy's	5		7	-		
	Partitions Urinals			EA		10+ years		
		1st floor boy's	1	EA	7	10+ years		
	Walls - Structural Glazed Tile	1st floor boy's	504	SF	7	10+ years		



Catego	ry : Room		Building : Addition 1						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Water Closet	1st floor boy's	2	EA	7	10+ years			
	Accessories	1st floor girl's	178	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st floor girl's	178	SF	7	10+ years			
	Floor - Terrazzo	1st floor girl's	178	SF	6	2-5 years			
	Floor Drain	1st floor girl's	1	EA	7	10+ years			
	Lavatory	1st floor girl's	3	EA	7	10+ years			
	Lighting - Lay-in	1st floor girl's	5	EA	7	6-10 years			
	Partitions	1st floor girl's	3	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st floor girl's	504	SF	7	10+ years			
	Water Closet	1st floor girl's	3	ĒA	7	10+ years			
	Accessories	1st floor inside Rm #111	37	SF	7	6-10 years			
	Ceiling - Lay-in	1st floor inside Rm #111	37	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st floor inside Rm #111	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st floor inside Rm #111	37	SF	7	10+ years			
	Floor Drain	1st floor inside Rm #111	1	EA	7	10+ years			
	Lavatory	1st floor inside Rm #111	1	EA	7	10+ years			
	Lighting - Lay-in	1st floor inside Rm #111	1	EA	7	6-10 years			
	Walls - Structural Glazed Tile	1st floor inside Rm #111	78	SF	7	10+ years			
	Walls - Structural Glazed The	1st floor inside Rm #111	1	EA	7	10+ years			
	Accessories	1st floor inside Rm #112	37	SF	7				
			37	SF		6-10 years			
	Ceiling - Lay-in	1st floor inside Rm #112			7	10+ years			
	Doors - Wood Doors inclu hw	1st floor inside Rm #112	1	EA	7	10+ years			
	Floor - Tile	1st floor inside Rm #112	33	SF	7	10+ years	<b>-</b>		
	Floor - Tile	1st floor inside Rm #112	4	SF	4	1-2 years	Tile separating		
	Floor Drain	1st floor inside Rm #112	1	EA	7	10+ years			
	Lavatory	1st floor inside Rm #112	1	EA	7	10+ years			
	Lighting - Lay-in	1st floor inside Rm #112	1	EA	7	6-10 years			
	Walls - Structural Glazed Tile	1st floor inside Rm #112	78	SF	7	10+ years			
	Water Closet	1st floor inside Rm #112	1	EA	7	10+ years			
	Accessories	1st floor inside Rm #113	37	SF	7	6-10 years			
	Ceiling - Lay-in	1st floor inside Rm #113	37	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st floor inside Rm #113	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st floor inside Rm #113	37	SF	7	10+ years			
	Floor Drain	1st floor inside Rm #113	1	EA	4	1-2 years	Teacher reports drain has standing water at times		
	Lavatory	1st floor inside Rm #113	1	EA	7	10+ years			
	Lighting - Lay-in	1st floor inside Rm #113	1	EA	7	6-10 years			
	Walls - Structural Glazed Tile	1st floor inside Rm #113	78	SF	7	10+ years			
	Water Closet	1st floor inside Rm #113	1	ĒA	7	10+ years			
	Accessories	1st floor inside Rm #114	37	SF	7	6-10 years			
	Ceiling - Lay-in	1st floor inside Rm #114	37	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st floor inside Rm #114	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st floor inside Rm #114	37	SF	7	10+ years			
	Floor Drain	1st floor inside Rm #114	57 1	EA	7	-			
			I	EA	1	10+ years			



Catego	ry : Room		В	uilding	: Additi	on 1	
				-		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	1st floor inside Rm #114	1	EA	7	10+ years	
	Lighting - Lay-in	1st floor inside Rm #114	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st floor inside Rm #114	78	SF	7	10+ years	
	Water Closet	1st floor inside Rm #114	1	EA	7	10+ years	
	Accessories	1st floor inside kitchen	38	SF	7	6-10 years	
	Ceiling - Lay-in	1st floor inside kitchen	38	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor inside kitchen	1	EA	7	10+ years	
	Floor - Concrete	1st floor inside kitchen	38	SF	4	1-2 years	Rough floor
	Floor Drain	1st floor inside kitchen	1	EA	4	1-2 years	Cover over what might be drain
	Lavatory	1st floor inside kitchen	1	EA	7	10+ years	
	Lighting - Lay-in	1st floor inside kitchen	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st floor inside kitchen	82	SF	7	10+ years	
	Water Closet	1st floor inside kitchen	1	EA	7	10+ years	
	Accessories	1st floor north end of corridor	43	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st floor north end of corridor	43	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st floor north end of corridor	1	EA	7	10+ years	
	Floor - Terrazzo	1st floor north end of corridor	43	SF	7	10+ years	
	Floor Drain	1st floor north end of corridor	1	EA	7	10+ years	
	Lavatory	1st floor north end of corridor	1	EA	7	10+ years	
	Lighting - Lay-in	1st floor north end of corridor	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st floor north end of corridor	88	SF	7	10+ years	
	Water Closet	1st floor north end of corridor	1	ĒA	7	10+ years	
	Accessories	2nd floor boy's	179	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor boy's	179	SF	7	10+ years	
	Floor - Terrazzo	2nd floor boy's	179	SF	7	10+ years	
	Floor Drain	2nd floor boy's	1	ĒA	7	10+ years	
	Lavatory	2nd floor boy's	3	EA	7	10+ years	
	Lighting - Lay-in	2nd floor boy's	4	EA	7	6-10 years	
	Lighting - Lay-in	2nd floor boy's	1	EA	5	1-2 years	Not working
	Partitions	2nd floor boy's	2	EA	7	10+ years	Not working
	Urinals	2nd floor boy's	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd floor boy's	504	SF	6	10+ years	
	Water Closet	2nd floor boy's	2	EA	6	10+ years	
	Accessories	2nd floor girl's	178	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor girl's	178	SF	7	10+ years	
	Floor - Terrazzo	2nd floor girl's	178	SF	7	10+ years	
	Floor Drain	2nd floor girl's	1/0	EA	7	10+ years	
	Lavatory	2nd floor girl's	3	EA	7	10+ years	
	Lighting - Lay-in	2nd floor girl's	5	EA	7	6-10 years	
	Partitions	2nd floor girl's	3	EA	7	•	
	Walls - Structural Glazed Tile	2nd floor girl's	3 504	SF	7	10+ years 10+ years	
	Water Closet	2nd floor girl's	3	EA	7	10+ years	
	Accessories	2nd floor north end of corridor	43	SF SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor north end of corridor	43	55	7	10+ years	



Category : Room **Building : Addition 1** Recommend Location Group Item - Type Quantity UOM Rank Replacement Comments Doors - Transom Window 2nd floor north end of corridor SF 10+ vears 7 1 Floor - Terrazzo 2nd floor north end of corridor 43 SF 7 10+ years Floor Drain 2nd floor north end of corridor 1 FΑ 7 10+ years ΕA 7 Lavatory 2nd floor north end of corridor 1 10+ years 7 Lighting - Chandelier, Incandescent 2nd floor north end of corridor 1 EΑ 6-10 years SF Walls - Structural Glazed Tile 7 2nd floor north end of corridor 88 10+ years Water Closet 2nd floor north end of corridor ΕA 7 10+ years 1 SF Accessories 3rd floor boy's 179 7 6-10 years SF Ceiling - Plaster/Drywall 3rd floor boy's 179 7 10+ years Floor - Terrazzo SF 3rd floor boy's 179 7 10+ years Floor Drain 3rd floor boy's 1 ΕA 7 10+ vears Lavatory 3rd floor boy's 3 EΑ 7 10+ years 3rd floor boy's 5 ΕA 7 6-10 years Lighting - Lay-in 2 ΕA 7 Partitions 3rd floor boy's 10+ years ΕA 7 Urinals 3rd floor boy's 1 10+ years Walls - Structural Glazed Tile SF 7 3rd floor boy's 494 10+ years SF Walls - Tile Ceramic/ Porcelain 3rd floor boy's 10 4 1-2 years Boarded over Water Closet 3rd floor boy's 2 EΑ 7 10+ years SF Accessories 3rd floor airl's 178 7 6-10 vears SF Ceiling - Plaster/Drywall 3rd floor girl's 178 7 10+ years Floor - Terrazzo 3rd floor girl's 178 SF 7 10+ years Floor Drain 7 10+ years 3rd floor girl's 1 EΑ 3 ΕA 7 Lavatory 3rd floor girl's 10+ years 5 7 Lighting - Lay-in 3rd floor girl's FΑ 6-10 years Partitions 3rd floor girl's 3 ΕA 7 10+ years SF Walls - Structural Glazed Tile 3rd floor airl's 504 7 10+ vears ΕA Water Closet 3rd floor girl's 3 7 10+ years Accessories 3rd floor north end of corridor 43 SF 7 6-10 years Ceiling - Plaster/Drywall SF 3rd floor north end of corridor 43 7 10+ years Doors - Wood Doors inclu hw 3rd floor north end of corridor 1 ΕA 7 10+ years Floor - Terrazzo SF 3rd floor north end of corridor 43 7 10+ vears Floor Drain 3rd floor north end of corridor 1 ΕA 7 10+ vears FΑ 7 3rd floor north end of corridor 1 10+ years Lavatory Lighting - Lay-in 3rd floor north end of corridor 1 FΑ 7 6-10 years Walls - Structural Glazed Tile SF 7 3rd floor north end of corridor 88 10+ years ΕA 7 Water Closet 3rd floor north end of corridor 1 10+ years

Category : Classroom	Building : Addition 1						
		Recommend					
Group Item - Type	Location	Quantity UOM Rank Replacement Comments					
Classroom #111 (Pre School)							
Casework	1st Floor	30 LF 6 10+ years					
Ceiling - Lay-in	1st Floor	1,254 SF 6 10+ years					
Chalk Board	1st Floor	12 LF 4 2-5 years					



Catego	ry : Classroom		В	uilding	: Additi		
-						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,254	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,002	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	334	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	m #112 (Kindergarten)						
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,230	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor	24	SF	4	1-2 years	Minor damage to tiles
	Chalk Board	1st Floor	12	LF	4	2-5 years	Willier damage to tiles
	Doors - Side-lite	1st Floor	8	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	1,224	SF	6	10+ years	
	Floor - Tile	1st Floor	30	SF	4	1-2 years	Cracked and damaged tile
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	Clacked and damaged life
		1st Floor		EA	5		Networking
	Lighting - Lay-in		7		-	1-2 years	Not working
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,002	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	334	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
lassroo	m #113 (Pre School)						
	Casework	1st Floor	28	LF	6	10+ years	
	Casework	1st Floor	2	LF	4	1-2 years	Damaged casework
	Ceiling - Lay-in	1st Floor	1,254	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,254	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,002	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	334	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	m #114 (Kindergarten)						
	Casework	1st Floor	30	LF	6	10+ years	
	Ceiling - Lay-in	1st Floor	1,254	SF	6	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
		13(1100)	12		-	2-0 years	



Catego	ory : Classroom		В	uilding	: Additi		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	1st Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	1,254	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	35	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,002	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	334	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
_Classroo	om #210 (Other Instructional Use)						
	Casework	2nd Floor	8	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	480	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	26	SF	4	1-2 years	Stained tile
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	426	SF	7	6-10 years	
	Floor - Tile	2nd Floor	80	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	6	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	956	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
	Work Chink			273	,	ior youro	
Classroo	om #211 (Art Room)						
	Casework	2nd Floor	48	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	925	SF	6	10+ years	
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	925	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	
	Storage/ Closet	2nd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	809	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	270	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #213 (Regular Classroom)						
	Casework	2nd Floor	40	LF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	610	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	2	SF	4	1-2 years	Stained tile
	Chalk Board	2nd Floor	24	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	608	SF	7	10+ years	
		21011001	666	0.		ior yourd	



Catego	ry : Classroom		В	Building : Addition 1				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile	2nd Floor	4	SF	4	1-2 years	Damaged tile	
	Lighting - Lay-in	2nd Floor	8	EA	7	6-10 years		
	Storage/ Closet	2nd Floor	4	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	466	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	466	SF	7	10+ years		
	Work Sink	2nd Floor	1	EA	7	10+ years		
Classroo	om #215 (Regular Classroom)							
	Casework	2nd Floor	40	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	612	SF	6	10+ years		
	Chalk Board	2nd Floor	24	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	607	SF	7	10+ years		
	Floor - Tile	2nd Floor	5	SF	4		Cracked tile	
				EA		1-2 years	Cracked life	
	Lighting - Lay-in	2nd Floor	8		6	6-10 years		
	Storage/ Closet	2nd Floor	4	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	466	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	466	SF	7	10+ years		
Classroo	om #217 (Regular Classroom)							
	Casework	2nd Floor	40	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	612	SF	6	10+ years		
	Chalk Board	2nd Floor	24	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	598	SF	7	10+ years		
	Floor - Tile	2nd Floor	14	SF	4	1-2 years	Several damaged tiles	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years		
	Storage/ Closet	2nd Floor	4	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	233	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	233	SF	7	10+ years		
lassroo	om #310 (Computer Lab)							
	Casework	2nd Floor	3	LF	6	10+ years		
	Ceiling - Lay-in	2nd Floor	1,238	SF	6	10+ years		
	Doors - Side-lite	2nd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	1,238	SF	7	10+ years		
		2nd Floor	,	EA	7			
	Lighting - Lay-in Markar Baard		14			6-10 years		
	Marker Board	2nd Floor	12	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	161	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	1,322	SF	7	10+ years		



atego	ry : Classroom		В	Building : Addition 1				
-						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Walls - Concrete Block	2nd Floor	20	SF	5	1-2 years	Cracks in block	
	Walls - Plaster/Drywall	2nd Floor	271	SF	7	10+ years		
	Wireless System	2nd Floor	1	EA	7	6-10 years		
	-							
assroo	m #311 (Regular Classroom)				-			
	Casework	3rd Floor	36	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	925	SF	6	10+ years		
	Chalk Board	3rd Floor	12	LF	4	2-5 years		
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	925	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years		
	Lighting - Lay-in	3rd Floor	1	EA	5	1-2 years	Not working	
	Marker Board	3rd Floor	12	LF	7	6-10 years	5	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	809	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	20	SF	5	1-2 years	Cracks in clock at corner	
	Walls - Plaster/Drywall	3rd Floor	250	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
ooroo	m #312 (Regular Classroom)							
1222100	Casework	3rd Floor	36	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	920	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	920 5	SF	4	1-2 years	Stained tile	
	Chalk Board	3rd Floor	12	LF			Stamed the	
					4	2-5 years		
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	925	SF	7	10+ years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Storage/ Closet	3rd Floor	4	SF	7	10+ years		
	Walls - Concrete Block	3rd Floor	530	SF	7	10+ years	<b>-</b>	
	Walls - Concrete Block	3rd Floor	10	SF	5	1-2 years	Cracked wall	
	Walls - Plaster/Drywall	3rd Floor	540	SF	7	10+ years		
	Work Sink	3rd Floor	1	EA	7	10+ years		
assroo	m #313 (Regular Classroom)							
	Casework	3rd Floor	36	LF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	921	SF	6	10+ years		
	Ceiling - Lay-in	3rd Floor	4	SF	4	1-2 years	Minor water stain	
	Chalk Board	3rd Floor	24	LF	4	2-5 years		
	Doors - Side-lite		8	SF	7	10+ vears		
		3rd Floor 3rd Floor	8 1	SF EA	7 7	10+ years 10+ years		



atego	ry : Classroom		В	uilding	: Additi	on 1	
-						Recommend	
iroup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor	1	EA	5	1-2 years	Not working
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	530	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	10	SF	5	1-2 years	Cracks in block
	Walls - Plaster/Drywall	3rd Floor	539	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
assroo	m #314 (Regular Classroom)						
	Casework	3rd Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	925	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	925	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	789	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	20	SF	5	1-2 years	Cracked wall
	Walls - Plaster/Drywall	3rd Floor	270	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
assroo	m #315 (Regular Classroom)						
	Casework	3rd Floor	36	LF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	925	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	8	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	5	1-2 years	Crack in wood door
	Floor - Tile	3rd Floor	920	SF	7	10+ years	
	Floor - Tile	3rd Floor	5	SF	4	1-2 years	Cracked and damaged tile
	Lighting - Lay-in	3rd Floor	11	EA	7	6-10 years	-
	Lighting - Lay-in	3rd Floor	1	EA	5	1-2 years	Not working
	Marker Board	3rd Floor	12	LF	7	6-10 years	5
	Storage/ Closet	3rd Floor	4	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	809	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	20	SF	5	1-2 years	Cracked wall
			270	SF			
	Walls - Plaster/Drywall	3rd Floor	270	55	7	10+ years	



Catego	ry : Interior		В	Building : Addition 1					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Lay-in	1st Floor	3,348	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Stained tile		
	Ceiling - Plaster/Drywall	1st Floor	243	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years			
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	6-10 years			
	Floor - Terrazzo	1st Floor	3,599	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	82	EA	7	6-10 years			
	Walls - Concrete Block	1st Floor	5,422	SF	7	10+ years			
	Ceiling - Lay-in	2nd Floor	2,735	SF	6	10+ years			
	Ceiling - Lay-in	2nd Floor	16	SF	4	1-2 years	Stained tiles		
	Ceiling - Plaster/Drywall	2nd Floor	243	SF	6	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	2	EA	7	10+ years			
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	10+ years			
	Floor - Terrazzo	2nd Floor	2,994	SF	7	10+ years			
	Lighting - Lay-in	2nd Floor	73	EA	7	6-10 years			
	Walls - Concrete Block	2nd Floor	4,371	SF	7	10+ years			
	Ceiling - Lay-in	3rd Floor	2,729	SF	6	10+ years			
	Ceiling - Lay-in	3rd Floor	22	SF	4	1-2 years	Stained tile		
	Ceiling - Plaster/Drywall	3rd Floor	243	SF	6	10+ years			
	Doors - Steel Doors incl hw	3rd Floor	2	EA	7	10+ years			
	Drinking Fountains - Double Fountain	3rd Floor	1	EA	7	10+ years			
	Floor - Terrazzo	3rd Floor	2,994	SF	7	10+ years			
	Lighting - Lay-in	3rd Floor	78	EA	7	6-10 years			
	Walls - Concrete Block	3rd Floor	4,371	SF	7	10+ years			
						-			
Safety									
,	Security Cameras	Entire Building	3	EA	7	6-10 years	Only on exterior according to		
		g	-		-		administration		
Stairs									
AGITO	Ceiling - Lay-in	Stair 5	4	SF	4	1-2 years	Stained tile		
	Ceiling - Plaster/Drywall	Stair 5	308	SF	6	10+ years			
	Floor - Terrazzo	Stair 5	312	SF	7	10+ years			
	Handrails	Stair 5	110	LF	7	10+ years			
	Lighting - Pendent/Surface	Stair 5	7	EA	7	6-10 years			
	Stairs - Terrazzo	Stair 5	, 55	LF	6	10+ years			
	Walls - Concrete Block	Stair 5	880	SF	7	10+ years			
	Ceiling - Lay-in	Stair 6	16	SF	4	1-2 years	Stained tile		
	Ceiling - Plaster/Drywall	Stair 6	296	SF	7	10+ years			
	Floor - Terrazzo	Stair 6	312	SF	7	10+ years			
	Handrails	Stair 6	110	LF	7	10+ years			
	Lighting - Lay-in	Stair 6	4	EA	7	6-10 years			
	Lighting - Lay-In	Stall U	4	EA	1	0-10 years			



Catego	ry : Interior		В	Building : Addition 1					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Lay-in	Stair 6	1	EA	5	1-2 years	Not working		
	Lighting - Wall Mounted	Stair 6	4	EA	7	10+ years			
	Stairs - Terrazzo	Stair 6	55	LF	7	10+ years			
	Walls - Concrete Block	Stair 6	880	SF	7	10+ years			
Vertical	Conveyance								
	Elevator - Hydraulic Elevator	1st to 3rd floors	1	EA	6	10+ years	Damaged floor in cab		



Catego	ry : Site	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	3	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	5	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	6	EA	6	10+ years	
	-					-	
encing							
	Fencing - Chain Link	Entire Site	152	LF	4	0-1 year	Missing pieces and leaning.
	Fencing - New Standard Ornamental	Entire Site	728	LF	5	10+ years	
andaaa							
andsca	Benches	Entire Site	19	EA	7	10+ years	Repaired
	Landscape - Hardscape- Concrete	Entire Site	3,761	SF	6	10+ years	Repaired
	Landscape - Hardscape- Concrete Landscape - Hardscape- Pavers	Entire Site	5,878	SF	6	10+ years	
	Landscape - Mulch	Entire Site	150	SF	6	6-10 years	
	Parkway trees	Entire Site	5	EA	7	10+ years	
	Planting Beds/ Area	Entire Site	6,098	SF	6	6-10 years	
	Play Area - Hardscape- Asphalt	Entire Site	760	SF	6	6-10 years	
				SF	6		
	Play Area - Synthetic Turf Retaining Wall - Concrete	Entire Site Entire Site	7,149	SF		2-5 years	
	Trash Receptacles	Entire Site	140 8	EA	6 6	6-10 years 10+ years	
	Trasil Neceptacies		0	LA	0	10+ years	
Parking	Lot						
-	Surface - Asphalt	Parking Lot- North	7,728	SF	7	10+ years	Repaired
	Vehicular Screening	Parking Lot- North	44	LF	5	10+ years	
	Surface - Concrete	West	4,188	SF	5	2-5 years	
	Trash Compactor	West	1	EA	6	6-10 years	
	Trash Enclosure - Chain Links	West	330	SF	6	6-10 years	
	nd						
Playgrou	Equipment - School Age 5-12	North	1	EA	6	6-10 years	
	Surface - Poured Surface	North	2,697	SF	6	6-10 years	
		North	2,007	01	Ū	o roycars	
Sidewalk							
	Sidewalks - Perimeter Sidewalks	Entire Site	11,921	SF	6	10+ years	
Signage							
	Flag Pole - Flag Pole	East	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	East	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter	East	2	EA	7	10+ years	
	Sign		-				



<sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

#### Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



### Classroom Summary

			Deem	Floor Plan	A	Glazed	Operable	Window	Crocost
Current Usage	Intended Usage	Room Location	Room Number	Room Number	Area (SF)	Window Area	Window Area	Window Stop	Smart- Board
Building : Main	Intended Osage	Room Location	Number	Number	(36)	Alea	Alea	Stop	Duaru
Computer Lab	Regular Classroom	2nd Floor	209	201	789	113	48	N	Y
Kindergarten	Kindergarten	1st Floor	109	kindergarten	767	49	25	Y	n N
Music Room	Regular Classroom	3rd Floor	308	302	898	49 98	31	N N	Y
Music Room Music Room	Regular Classroom	3rd Floor	308	302	<u>851</u>	98	31	N	r N
	<u> </u>			109	907	98 170	84	Y	N Y
Office	Regular Classroom	1st Floor	101						-
Other Instructional Use	Regular Classroom	2nd Floor	201	209	907	170	84	N	N Y
Other Instructional Use	Regular Classroom	3rd Floor	305	305	948	123	50	N	
Regular Classroom	Regular Classroom	1st Floor	102	108	836	168	81	Y	Y
Regular Classroom	Regular Classroom	1st Floor	103	107	836	168	81	Y	Y
Regular Classroom	Regular Classroom	1st Floor	107	103	920	123	50	Y	Y
Regular Classroom	Regular Classroom	1st Floor	108	102	880	98	31	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	202	208	836	141	68	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	207	907	170	84	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	206	907	170	84	Y	N
Regular Classroom	Regular Classroom	2nd Floor	206	204	907	170	84	N	Ν
Regular Classroom	Regular Classroom	2nd Floor	207	203	907	170	84	N	Y
Regular Classroom	Regular Classroom	2nd Floor	208	202	836	141	68	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	309	964	123	50	N	N
Regular Classroom	Regular Classroom	3rd Floor	302	308	898	98	31	N	Y
Regular Classroom	Regular Classroom	3rd Floor	303	307	986	123	50	N	N
Regular Classroom	Regular Classroom	3rd Floor	304	306	948	123	50	Y	N
Regular Classroom	Regular Classroom	3rd Floor	306	304	948	123	50	N	Y
Regular Classroom	Regular Classroom	3rd Floor	307	303	973	123	50	N	N
Store Room	Regular Classroom	2nd Floor	205	205	907	170	84	Ν	N
F	0		-	•		•	•	•	
Building : Addition 1									
Art Room	Regular Classroom	2nd Floor	211		925	120	60	Ν	Y
Computer Lab	Computer Lab	2nd Floor	310		1,238	160	80	N	N
Kindergarten	Kindergarten	1st Floor	112	NA	1,254	160	80	N	Y
Kindergarten	Kindergarten	1st Floor	114	NA	1,254	160	80	N	Y
Other Instructional Use	Regular Classroom	2nd Floor	210		506	40	20	N	N
Pre School	Pre School	1st Floor	111	NA	1,254	160	80	N	Y
Pre School	Pre School	1st Floor	113	NA	1,254	160	80	N	Ý
Regular Classroom	Regular Classroom	2nd Floor	213		612	80	40	N	Ý
Regular Classroom	Regular Classroom	2nd Floor	215		612	80	40	N	Ý
Regular Classroom	Regular Classroom	2nd Floor	213	1	612	80	40	N	Y
Regular Classroom	Regular Classroom	3rd Floor	311		925	120	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	312		925	120	60	N	Y



#### **Classroom Summary**

				Floor Plan		Glazed	Operable		
			Room	Room	Area	Window	Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Regular Classroom	Regular Classroom	3rd Floor	313		925	120	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	314		925	120	60	N	Y
Regular Classroom	Regular Classroom	3rd Floor	315		925	120	60	N	Y