

#### **Facility Assessment Report**

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at <a href="http://www.cps.edu/facilityassessment">http://www.cps.edu/facilityassessment</a>.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1923	3	75,318
Annex	1996	1	12,310
Campus Total			87,628

Category : Exterior Building : Main

Calego	I y . Exterior			unung	. IVIAIII		
	<b></b>	1	0	11014		Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance	)						
	Entrance Control - Audio and Video	1	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	1	6	EA	6	2-5 years	Warped doors
	Exterior Doors - Transom Lite	1	6	EΑ	6	10+ years	
	Exterior Stairs - Stone	1	24	LF	6	10+ years	
	Exterior Doors - Exterior Steel Door	2	4	EA	4	1-2 years	Delaminating old doors with corroded frames
	Exterior Doors - Transom Lite	2	4	EΑ	6	10+ years	
	Exterior Stairs - Concrete	2	11	LF	6	10+ years	
	Exterior Stairs - Concrete	2	1	LF	5	1-2 years	Crack in the concrete
	Exterior Doors - Exterior Wood Door	3	4	EΑ	5	1-2 years	Corroded base of frames
	Exterior Doors - Transom Lite	3	4	EA	6	10+ years	
	Exterior Stairs - Concrete	3	12	LF	6	10+ years	
	Exterior Stairs - Concrete	3	1	LF	5	0-1 year	Broken, spalled
	Exterior Doors - Exterior Steel Door	4	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	5	2	EΑ	4	1-2 years	Corroded doors and frame
	Exterior Doors - Exterior Steel Door	6	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	6	1	EA	5	0-1 year	Corroded frame base, missing piece
	Exterior Doors - Transom Lite	6	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	6	1	EA	5	1-2 years	Broken, rotted frame
	Entrance Control - Audio and Video	7	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	7	2	EA	6	2-5 years	Corroding
	Exterior Doors - Transom Lite	7	2	EA	6	10+ years	-
	Exterior Doors - Exterior Wood Door	8	1	EΑ	4	1-2 years	Delaminated door, corroded frame



Calego	ry : Exterior		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Foundati	on						
	Foundation - Concrete Superstructure - Steel with Clay Tile Arch	Entire Building Entire Building	816 73,684	LF SF	7 7	10+ years 10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted Exterior Lighting - Wall Mounted	Entire Building Entire Building	10 7	EA EA	6 6	2-5 years 6-10 years	
Roof Sys	stem						
•	Access Ladder - Metal	Α	1	EA	7	10+ years	No ladder, there is a folding ladder propped against the building
	Coping - Terra Cotta	A	262	LF	6	10+ years	
	Downspouts - Interior Downspouts	A	84	LF	6	10+ years	<b>5</b>
	Parapet - Parapet > 30"	Α	292	LF	5	0-1 year	Parrot wall and very poor condition. Spalling, open joints, cracked brick.
	Roof - Asphalt Gravel Ballast	A	4,320	SF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	A	200	SF	4	0-1 year	Open seams, detached membrane at counter, flashing, deteriorated sealant at counter flashing
	Roof Structure - Steel with Clay Tile Arch	A	4,520	SF	7	10+ years	•
	Access Ladder - Metal	В	3	EA	7	10+ years	
	Access Ladder - Wood	В	2	EA	4	1-2 years	Ladder shakes, flimsy ladder with poor attachment
	Coping - Terra Cotta	В	632	LF	6	10+ years	
	Downspouts - Interior Downspouts	В	246	LF	6	10+ years	
	Parapet - 16" - 30" Height	В	250	LF	6	10+ years	Verified condition
	Parapet - Parapet > 30"	В	332	LF	6	10+ years	
	Parapet - Parapet > 30"	В	50	LF	5	1-2 years	Open joints, cracked, spalling brick
	Roof - Asphalt Gravel Ballast	В	15,764	SF	6	10+ years	
	Roof - Asphalt Gravel Ballast	В	1,600	SF	4	0-1 year	Open seams, damaged, loose membrane at flashing, ponding
	Roof Hatch - Metal	В	2	EA	4	1-2 years	Corroded hatch
	Roof Structure - Steel with Clay Tile Arch	В	17,364	SF	7	10+ years	
	Coping - Terra Cotta	C	30	LF	6	10+ years	
	Downspouts - Exterior Downspouts	C	10	LF	6	10+ years	Commanded decomposit
	Downspouts - Exterior Downspouts	C	6	LF LF	4	1-2 years	Corroded downspout
	Parapet - 16" - 30" Height Roof - Modified Bitumen	C	30	SF	6	2-5 years	No access window balancers
	Rooi - Modilled Bitumen	С	112	SF	6	6-10 years	No access, window balancers damaged, screen locks inoperable.  Need to verify if metal roof
	Roof Structure - Steel with Clay Tile Arch	С	112	SF	7	10+ years	
	Coping - Terra Cotta	D	20	LF	6	10+ years	

Campus Name: Taylor Page : 2 of 38 Assessment Date: 07/25/2024



Catego	ry : Exterior		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Downspouts - Exterior Downspouts	D	10	LF	6	10+ years	
	Parapet - 16" - 30" Height	D	30	LF	6	6-10 years	
	Roof - Metal	D	112	SF	6	6-10 years	No access to verify fully
	Roof Structure - Steel with Clay Tile Arch	D	112	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	E	24	LF	6	10+ years	
	Liner						
	Chimney - Brick Chimney- Concrete/ Mortar	E	36	LF	5	1-2 years	Open joints
	Liner						
	Coping - Terra Cotta	E	113	LF	6	10+ years	
	Coping - Terra Cotta	E	22	LF	6	10+ years	
	Coping - Terra Cotta	E	4	LF	5	1-2 years	Cracked, broken tile
	Downspouts - Exterior Downspouts	E	30	LF	6	10+ years	
	Parapet - Parapet < 16" Height	E	22	LF	6	10+ years	Verified deteriorated mortar
	Parapet - Parapet > 30"	E	113	LF	5	1-2 years	Open joints, spalled, cracked brick
	Roof - Asphalt Gravel Ballast	E	2,430	SF	6	10+ years	
	Roof - Asphalt Gravel Ballast	E	300	SF	5	6-10 years	Growing vegetation, gravel washed
							away by water from drain spout
	Roof Structure - Steel with Clay Tile Arch	E	2,730	SF	7	10+ years	
	Coping - Terra Cotta	F	163	LF	6	10+ years	
	Downspouts - Exterior Downspouts	F	40	LF	6	10+ years	
	Parapet - Parapet < 16" Height	F	143	LF	6	10+ years	Verified condition. No open joints or
							cracked mortar were observed
	Parapet - Parapet > 30"	F	20	LF	6	10+ years	Verified condition. No open joints or
	·					·	cracked mortar were observed
	Roof - Asphalt Gravel Ballast	F	3,010	SF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	F	100	SF	4	0-1 year	Open seams, tears at perimeter
	Roof Structure - Steel with Clay Tile Arch	F	3,110	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar	G	20	LF	6	10+ years	
	Liner					·	
	Coping - Terra Cotta	G	22	LF	6	10+ years	
	Coping - Terra Cotta	G	100	LF	6	10+ years	
	Downspouts - Exterior Downspouts	G	49	LF	6	10+ years	
	Downspouts - Exterior Downspouts	G	6	LF	4	0-1 year	Smashed section of downspout
	Parapet - Parapet < 16" Height	G	22	LF	6	10+ years	Verified condition. No open joints or
						·	cracked mortar were observed
	Parapet - Parapet > 30"	G	70	LF	6	10+ years	
	Parapet - Parapet > 30"	G	30	LF	5	0-1 year	Open joints, spalling, broken brick
	Roof - Asphalt Gravel Ballast	G	1,480	SF	6	10+ years	
	Roof - Asphalt Gravel Ballast	G	200	SF	4	0-1 year	Open seams
	Roof Structure - Steel with Clay Tile Arch	G	1,680	SF	7	10+ years	•
	,		•			,	
Walls							
	Cheek-Wall - Stone	Entire Building	12	SF	7	10+ years	
	Cornice - Terra Cotta	Entire Building	1,701	LF	6	10+ years	
		•	•			Ž	

Campus Name: Taylor Page : 3 of 38 Assessment Date: 07/25/2024



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	30,000	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	2,942	SF	4	1-2 years	Open joints, cracked or broken brick
	Exterior Walls - Stone-Cast	Entire Building	2,935	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	3,233	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	60	SF	5	1-2 years	Vegetation growing on terra-cotta
	Exterior Walls - Terra Cotta	Entire Building	1	SF	3	1-2 years	Broken piece of pilaster cap
Windows	3						
	Curtain wall - Louver	Entire Building	146	SF	6	10+ years	
	Guard - Guards perforated	Entire Building	7,092	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	1,772	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	579	SF	6	10+ years	
	Lintels - Steel	Entire Building	464	LF	6	10+ years	
	Lintels - Terra Cotta	Entire Building	573	LF	6	10+ years	
	Windows - Decorative	Entire Building	192	SF	5	10+ years	Corroding mullions
	Windows - Sash Aluminum Double-pane	Entire Building	8,180	SF	6	10+ years	-
	Windows - Sash Aluminum Double-pane	Entire Building	1,400	SF	5	6-10 years	Many windows with non-functioning ballasts

Category : Electrical **Building: Main** 

						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
mergen	cy System						
	Automatic Transfer Switch	Electrical Room	2	EA	6	10+ years	
	Security System - CCTV	Entire Building	75,318	SF	5	6-10 years	
	Security System - Intrusion Detection	Entire Building	75,318	SF	5	6-10 years	
	Exit Signs - Auditoium	Entire Building	10	EA	5	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	16	EA	5	6-10 years	Some signs in the basement and Plenum space need their bulbs replaced
	Exit Signs - Gym	Entire Building	2	EΑ	5	6-10 years	·
	Exit Signs - Lunchroom	Entire Building	2	EA	5	6-10 years	
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	12	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	16	EA	6	6-10 years	
	Emergency Battery Packs - Gym	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	2	EA	6	6-10 years	
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	6,480	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	16,670	SF	6	6-10 years	
	Emergency A/C Power - Gym	Entire Building	2,790	SF	6	6-10 years	
	Emergency A/C Power - Lunchrooms	Entire Building	3,600	SF	6	6-10 years	

Campus Name: Taylor Page : 4 of 38 Assessment Date: 07/25/2024



XYN S	schools					991:	2 S Avenue H AVENUE, Chicago, IL 60617
Catego	ry : Electrical		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Students Toilets	Entire Building	2,244	SF	6	6-10 years	No emergency back up battery packs observed
Main Se	vice						
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Main electrical service updated and installed in 2003 all switch gear left in place and abandoned
	Main Electrical Service - 2001 to 3000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Installed in 2003
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	6-10 years	
	PA System	Entire Building	87,628	SF	5	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	6-10 years	In electrical room
	Lighting and Power Panels - 100 A	Entire Building	10	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	13	EA	6	10+ years	Most panels located in janitors close
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	,,
	Main Distribution Panels - 400 - 600 amp	Entire Building	3	EA	7	10+ years	Duplicate there are only three main distribution panels 600 A 400 A and 2500 A
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	2-5 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Greater than 600 amp	Entire Building	1	EA	7	10+ years	Duplicate there are only three main distribution panels 600 A 400 A and 2500 A
	Transformers - 120/240 - 120/208	Entire Building	1	EA	5	2-5 years	Non-functional transformer for the solar system on the roof
Catego	ry : Fire Protection		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar		Entire Duilding		ГΛ		6 10 veers	Not appeared before
	Fire ALarm Anunciator Fire Alarm Panel	Entire Building Entire Building	1	EA EA	6 3	6-10 years 0-1 year	Not assessed before Antiquated. Fire panel was tested recently, and it works per engineer
	Fire Alarm_System	Entire Building	75,318	SF	4	0-1 year	Antiquated.
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
•		Location	Qualitity	COM	Nam	Ropiacement	Comments
Air Cond	Condensing Unit- Roof Mounted - Less	Main Roof	1	EA	4	2-5 years	In operative, needs repair

Campus Name: Taylor Page : 5 of 38 Assessment Date: 07/25/2024



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	than 5 tons						
Air Hand	ling Systems						
	Fan Coil Unit- Celing Mounted - Electric	1st Floor	1	EA	5	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Basement	1	EA	5	6-10 years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 25001 - 35000 cfm	Basement	1	EA	5	6-10 years	
	Air Intake	Basement	2	EA	5	6-10 years	
	Auxiliaries - 25001 - 35000 cfm	Basement	2	EA	5	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Basement	13	EA	5	6-10 years	
	Return Duct Work - Masonry and Ducts- Missing or Existing Shaft	Basement	200	LF	5	6-10 years	
	Zone Dampers	Basement	24	EA	5	6-10 years	
	Zone Dampers	Basement	19	EA	4	2-5 years	Included in the reheat boxes
Boiler Sy	vstems						
,	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP	Boiler Room	2	EA	5	6-10 years	
	Chemical Feed System	Boiler Room	2	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	5	6-10 years	
	Condensate Pump	Boiler Room	1	ΕA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	Asset tag for tank missing pump asset tag recorded
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	5	6-10 years	Water valve is leaking and insulation needs to be replaced. Pipes are corroded.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP	Boiler Room	1	EA	5	6-10 years	The gas valves are leaking and needs to be replaced
	Piping - Condensate Pipe- Steel	Boiler Room	500	LF	5	6-10 years	,
	Piping - Steam Pipe- Steel	Boiler Room	500	LF	5	6-10 years	
	Steam Traps	Boiler Room	25	EA	5	6-10 years	
	Steam Traps	Boiler Room	15	ĒĀ	4	2-5 years	With internal leak adjusted steam tra quantity is 40 total
Heating	Devices						
	Radiators - Steam	Entire Building	22	EA	5	6-10 years	
	Radiators - Steam	Entire Building	6	EA	4	2-5 years	All restroom radiators are corroded
	Fin Tube - Electric	Entire Building	35	LF	7	10+ years	Rm 109 and 111
	Fin Tube - Steam	Entire Building	50	LF	5	6-10 years	
	Unit Heater - Electric	Entire Building	1	ĒΑ	6	6-10 years	In boys toilet room



Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Unit Heater - Electric	Entire Building	2	EΑ	6	10+ years	In electricalroom
	Unit Heater - Steam	Entire Building	2	EΑ	5	6-10 years	
	Unit Heater - Steam	Entire Building	1	EA	5	2-5 years	Located on first floor, girls restroon
Tempera	ature Control						
-	Electric Thermostat	Entire Building	1	EA	6	10+ years	Room 102
	Electric Thermostat	Entire Building	2	EA	5	6-10 years	
	Pneumatic System	Entire Building	75,318	SF	5	2-5 years	Actuators are not working most temperature control manually
	Thermostats - Pneumatic	Entire Building	24	EA	6	2-5 years	Actuators are not working most temperature control manually
	Thermostats - Pneumatic	Entire Building	19	EA	4	2-5 years	Actuators are not working most temperature control manually
/entilation	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	4	2-5 years	Noisy ceiling mounted in teachers lounge
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	7	10+ years	3.
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	

**Category: Plumbing Building: Main** 

0		Lagathan	Occamility	ПОМ	Danila	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Hot Wat	er						
	Electric Heater - Less than 20 KW	Basement	1	EA	5	6-10 years	
	Gas Heater - 150000 - 300000 BTU/HR	Mechanical Room	1	EA	7	10+ years	
						,	
Piping							
<del></del>	Domestic Piping-Hot Water Return Lines	Entire Building	75,318	SF	6	2-5 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	75,318	SF	6	2-5 years	
	Domestic Piping-Hot Water from Risers to	Entire Building	75,318	SF	6	2-5 years	
	Fixtures	g	,	-	•	, ,	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	75,318	SF	6	2-5 years	
	(Horizontal Lines)	g	7 0,0 . 0	٠.	•	_ 0 ,00.0	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	75,318	SF	6	2-5 years	
	(Risers)	Zitare Bananig	70,010	O.	·	2 o you.o	
	Domestic Piping-Hot/Cold Water Supply	Entire Building	75,318	SF	6	2-5 years	
	(from Risers to Fixtures)	Litaro Bananing	70,010	51	J	2 o yours	
	(Holli Mocio to Fixtures)						

Campus Name: Taylor Page : 7 of 38 Assessment Date: 07/25/2024



Catego	ry : Plumbing		В	uilding	: Main		
						Recommend	_
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sanitary Piping	Entire Building	75,318	SF	6	6-10 years	
	Storm Piping	Entire Building	75,318	SF	6	6-10 years	
	Vent Piping	Entire Building	75,318	SF	6	6-10 years	
Pumps							
•	Pumps - Domestic Booster Pump-Simplex	Basement	1	EA	5	6-10 years	
	Pumps - Sump-Simplex	Basement	1	EA	6	6-10 years	
	Pumps - Sump-Simplex	Basement	1	EA	2	0-1 year	Near North air handling unit

**Building: Main** Category: Room

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Administ	rative Suites/Offices						
	AC Unit	1st Floor Principal office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Principal office	450	SF	7	10+ years	
	Doors - Side-lite	1st Floor Principal office	100	SF	7	10+ years	
	Doors - Transom Window	1st Floor Principal office	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Principal office	3	EA	7	10+ years	
	Floor - Tile	1st Floor Principal office	100	SF	7	10+ years	
	Floor - Wood	1st Floor Principal office	350	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor Principal office	5	EΑ	7	6-10 years	
	Power Distribution	1st Floor Principal office	8	EΑ	7	10+ years	
	Storage/ Closet	1st Floor Principal office	110	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor Principal office	912	SF	7	10+ years	
	Ceiling - Plaster/Drywall	207b Counseling Office Suite	570	SF	7	10+ years	
	Doors - Transom Window	207b Counseling Office Suite	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	207b Counseling Office Suite	4	EΑ	7	10+ years	
	Floor - Carpet	207b Counseling Office Suite	570	SF	7	6-10 years	
	Floor - Carpet	207b Counseling Office Suite	5	SF	5	1-2 years	Fraying
	Lighting - Pendent/Surface	207b Counseling Office Suite	7	EA	7	10+ years	
	Power Distribution	207b Counseling Office Suite	20	EΑ	7	10+ years	
	Walls - Plaster/Drywall	207b Counseling Office Suite	1,850	SF	7	10+ years	
	Work Sink	207b Counseling Office Suite	1	EΑ	7	10+ years	
	Ceiling - Plaster/Drywall	307 Counseling Room	385	SF	7	10+ years	
	Doors - Transom Window	307 Counseling Room	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	307 Counseling Room	3	EΑ	7	10+ years	
	Floor - Wood	307 Counseling Room	385	SF	7	10+ years	
	Lighting - Pendent/Surface	307 Counseling Room	5	EΑ	7	10+ years	
	Power Distribution	307 Counseling Room	10	EΑ	7	10+ years	
	Storage/ Closet	307 Counseling Room	40	SF	7	10+ years	
	Walls - Plaster/Drywall	307 Counseling Room	1,170	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Building Engineer's Office (104 on plan)	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Building Engineer's Office (104 on	2	EA	7	10+ years	

Campus Name: Taylor Page : 8 of 38 Assessment Date: 07/25/2024



Catego	ry : Room		Building : Main							
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments			
	Floor - Carpet	plan) Building Engineer's Office (104 on	300	SF	7	6-10 years				
	Lighting - Pendent/Surface	plan) Building Engineer's Office (104 on plan)	4	EA	7	10+ years				
	Power Distribution	Building Engineer's Office (104 on plan)	8	EA	7	10+ years				
	Storage/ Closet	Building Engineer's Office (104 on plan)	670	SF	7	10+ years				
	Walls - Plaster/Drywall	Building Engineer's Office (104 on plan)	600	SF	7	10+ years				
	AC Unit	Custodial breakroom next to engineer's office	1	EA	7	6-10 years				
	Ceiling - Lay-in	Custodial breakroom next to engineer's office	600	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Custodial breakroom next to engineer's office	1	EA	7	10+ years				
	Floor - Carpet	Custodial breakroom next to engineer's office	600	SF	7	6-10 years				
	Lighting - Lay-in	Custodial breakroom next to engineer's office	7	EA	7	6-10 years				
	Power Distribution	Custodial breakroom next to engineer's office	8	EA	7	10+ years				
	Walls - Plaster/Drywall	Custodial breakroom next to engineer's office	800	SF	7	10+ years				
	Work SInk	Custodial breakroom next to engineer's office	1	EA	7	6-10 years				
	Ceiling - Plaster/Drywall	Gym Office + Storage (in former Storage 305)	244	SF	7	10+ years	Engineer had no access, previous assessment data used			
	Doors - Wood Doors inclu hw	Gym Office + Storage (in former Storage 305)	2	EA	7	10+ years	Engineer had no access, previous assessment data used			
	Floor - Wood	Gym Office + Storage (in former Storage 305)	244	SF	7	10+ years	Engineer had no access, previous assessment data used			
	Lighting - Pendent/Surface	Gym Office + Storage (in former Storage 305)	1	EA	7	10+ years	Engineer had no access, previous assessment data used			
	Power Distribution	Gym Office + Storage (in former Storage 305)	4	EA	7	10+ years	Engineer had no access, previous assessment data used			
	Walls - Plaster/Drywall	Gym Office + Storage (in former Storage 305)	700	SF	7	10+ years	Engineer had no access, previous assessment data used			
	Ceiling - Plaster/Drywall	Kitchen manager office inside 1st Floor Break Room	130	SF	7	10+ years	Inaccessible due to waxing			
	Doors - Wood Doors inclu hw	Kitchen manager office inside 1st Floor Break Room	2	EA	7	10+ years	Inaccessible due to waxing			
	Floor - Tile	Kitchen manager office inside 1st	130	SF	7	10+ years	Inaccessible due to waxing			



Catego	ry : Room	Building : Main							
						Recommend	_		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	1:1:: 5 1 1/0 (	Floor Break Room		^	-	40			
	Lighting - Pendent/Surface	Kitchen manager office inside 1st Floor Break Room	1	EA	7	10+ years	Inaccessible due to waxing		
	Power Distribution	Kitchen manager office inside 1st Floor Break Room	4	EA	7	10+ years	Inaccessible due to waxing		
	Storage/ Closet	Kitchen manager office inside 1st Floor Break Room	15	SF	7	10+ years	Inaccessible due to waxing		
	Walls - Plaster/Drywall	Kitchen manager office inside 1st Floor Break Room	374	SF	7	10+ years	Inaccessible due to waxing		
	Work Slnk	Kitchen manager office inside 1st Floor Break Room	1	EA	7	10+ years	Inaccessible due to waxing		
	Ceiling - Plaster/Drywall	Library Office	400	SF	7	10+ years	Engineer had no access, previous assessment data used		
	Doors - Wood Doors inclu hw	Library Office	1	EA	7	10+ years	Engineer had no access, previous		
	Floor - Carpet	Library Office	400	SF	7	6-10 years	assessment data used Engineer had no access, previous		
	Lighting - Pendent/Surface	Library Office	6	EA	7	10+ years	assessment data used Engineer had no access, previous		
	Power Distribution	Library Office	6	EA	7	10+ years	assessment data used Engineer had no access, previous		
	Storage/ Closet	Library Office	25	SF	7	10+ years	assessment data used Engineer had no access, previous		
	Walls - Plaster/Drywall	Library Office	840	SF	7	10+ years	assessment data used Engineer had no access, previous assessment data used		
	Ceiling - Plaster/Drywall	Main Office	794	SF	7	10+ years	assessment data used		
	Doors - Side-lite	Main Office	30	SF	7	10+ years			
	Doors - Transom Window	Main Office	70	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Main Office	6	EA	7	10+ years			
	Floor - Tile	Main Office	408	SF	7	10+ years			
	Floor - Wood	Main Office	386	SF	7				
		Main Office		SF EA		10+ years			
	Lighting - Pendent/Surface		9		7	10+ years			
	Power Distribution	Main Office	12	EA	7	10+ years			
	Walls - Plaster/Drywall	Main Office	2,000	SF	7	10+ years			
	Ceiling - Plaster/Drywall	Office in former Book Storage 208 + 210A	230	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Office in former Book Storage 208 + 210A	1	EA	7	10+ years			
	Floor - Wood	Office in former Book Storage 208 + 210A	230	SF	7	10+ years			
	Lighting - Pendent/Surface	Office in former Book Storage 208 + 210A	3	EA	7	10+ years			
	Power Distribution	Office in former Book Storage 208 + 210A	6	EA	7	10+ years			

Campus Name: Taylor Page : 10 of 38 Assessment Date: 07/25/2024



Catego	ory : Room		В	uilding	: Main		•
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	Office in former Book Storage 208 +	900	SF	7	10+ years	
		210A					
_Auditori	um & Theater						
	Balcony Seating	1st Floor	132	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	5,700	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	5	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	14	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	4,080	SF	7	10+ years	
	Floor - Tile	1st Floor	695	SF	7	10+ years	
	Floor - Tile	1st Floor	25	SF	5	2-5 years	
	Floor - Wood	1st Floor	900	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	8	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	9	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	4	EA	7	10+ years	
	Lighting - Wall Mounted	1st Floor	9	EA	7	10+ years	
	Main Floor Seating	1st Floor	286	EA	7	10+ years	
	Main Floor Seating  Main Floor Seating	1st Floor	326	EA	7	,	
					7	10+ years	
	Sound System	1st Floor	1	EA		10+ years	
	Stage	1st Floor	720	SF	7	10+ years	
	Stage Curtain	1st Floor	1	EΑ	7	10+ years	
	Stage-Stairs - Terrazzo	1st Floor	40	LF	7	10+ years	
	Storage/ Closet	1st Floor	300	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	6,200	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,900	SF	7	10+ years	
_Gvmnas	sia						
•	Ceiling - Plaster/Drywall	3rd Floor	2,790	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	4	EA	7	6-10 years	
	Floor - Wood	3rd Floor	2,790	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	ĒΑ	7	10+ years	
	Storage/ Closet	3rd Floor	244	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	3,500	SF	7	10+ years	
Librari							
_Library_	AC Unit	306/308 (306 on plans)	2	EA	7	6-10 years	
				LF	7		
	Casework	306/308 (306 on plans)	112		6	10+ years	
	Ceiling - Plaster/Drywall	306/308 (306 on plans)	1,265	SF	7	10+ years	
	Doors - Wood Doors inclu hw	306/308 (306 on plans)	3	EA	7	10+ years	
	Floor - Tile	306/308 (306 on plans)	1,265	SF	7	10+ years	
	Lighting - Pendent/Surface	306/308 (306 on plans)	20	EA	7	10+ years	
	Storage/ Closet	306/308 (306 on plans)	40	SF	7	10+ years	



Category : Room			Building : Main				
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	306/308 (306 on plans)	1,430	SF	7	10+ years	
cker/S	hower Room						
	Accessories	South Basement	150	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	South Basement	150	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	South Basement	150	SF	7	10+ years	
	Floor Drain	South Basement	1	ĒA	7	10+ years	
	Lavatory	South Basement	1	EA	6	10+ years	
	Lighting - Pendent/Surface	South Basement	1	EΑ	7	10+ years	
	Showers	South Basement	1	EA	7	10+ years	
	Walls - Plaster/Drywall	South Basement	500	SF	7	10+ years	
	Water Closet	South Basement	1	EA	6	6-10 years	
0 مامدس	Multinum and Danie						
IICH &	Multipurpose Room  AC Unit	1st Floor	2	EA	7	10+ years	Not previously assessed
	Ceiling - Plaster/Drywall	1st Floor	1,486	SF	7	10+ years	That providually addedded
	Doors - Transom Window	1st Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	4	EA	6	10+ years	
	Floor - Tile		1,466	SF	7	10+ years 10+ years	
		1st Floor		SF SF			Over the constant of the markets accommon
	Floor - Tile	1st Floor	20	5F	5	1-2 years	Quantity updated to match curren observations
	Lighting - Pendent/Surface	1st Floor	22	EA	7	10+ years	
	Serving Line	1st Floor	8	LF	7	10+ years	
	Storage/ Closet	1st Floor	266	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,850	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor Staff Break Room (112 on	750	SF	7	10+ years	Inaccessible due to waxing
	Doors - Transom Window	plan) 1st Floor Staff Break Room (112 on	14	SF	7	10+ years	Inaccessible due to waxing
	Doord Transom Window	plan)		O.	•	101 youro	maccocolore due to waxing
	Doors - Wood Doors inclu hw	1st Floor Staff Break Room (112 on	2	EA	7	10+ years	Inaccessible due to waxing
	Floor - Terrazzo	plan) 1st Floor Staff Break Room (112 on	30	SF	7	10+ years	Inaccessible due to waxing
		plan)				-	_
	Floor - Tile	1st Floor Staff Break Room (112 on plan)	705	SF	7	10+ years	Inaccessible due to waxing
	Floor - Tile	1st Floor Staff Break Room (112 on	15	SF	5	1-2 years	Inaccessible due to waxing
		plan)					
	Lighting - Pendent/Surface	1st Floor Staff Break Room (112 on plan)	7	EA	7	10+ years	Inaccessible due to waxing
	Storage/ Closet	1st Floor Staff Break Room (112 on	20	SF	7	10+ years	Inaccessible due to waxing
		plan)			_		
	Walls - Plaster/Drywall	1st Floor Staff Break Room (112 on plan)	800	SF	7	10+ years	Inaccessible due to waxing
	Ceiling - Plaster/Drywall	2nd Floor Teachers' Kitchen/Break	380	SF	7	10+ years	

Campus Name: Taylor Page: 12 of 38 Assessment Date: 07/25/2024



Category : Room			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Room (Cafe)	1	Ε.	7	40	
	Doors - wood Doors Inclu nw	2nd Floor Teachers' Kitchen/Break Room (Cafe)	1	EA	7	10+ years	
	Floor - Tile	2nd Floor Teachers' Kitchen/Break	370	SF	7	10+ years	
	11001 1110	Room (Cafe)	370	O.	,	101 years	
	Floor - Tile	2nd Floor Teachers' Kitchen/Break	10	SF	5	1-2 years	Broken and missing tiles
		Room (Cafe)			-	,	3
	Lighting - Pendent/Surface	2nd Floor Teachers' Kitchen/Break	2	EA	7	10+ years	
	Room (Cafe)						
	Walls - Plaster/Drywall	2nd Floor Teachers' Kitchen/Break	1,000	SF	7	10+ years	
		Room (Cafe)					
MDF ID	<b>-</b>						
NIDE_ID	Doors - Wood Doors inclu hw	2nd Floor in former Projection Room	1	EA	7	10+ years	
	Finishes	2nd Floor in former Projection Room	70	SF	7	10+ years	
	T II II OTTO	Zha i looi iir loimei i rejoolion recom	70	O.	•	To Tyouro	
Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	12	SF	7	10+ years	Split up from other janitors's closet
	Janitor's Closet	1st Floor	12	SF	7	10+ years	Quantity updated to match current
							observations
	Janitor's Closet	2nd Floor	30	SF	7	10+ years	
	Janitor's Closet	2nd Floor	30	SF	7	10+ years	
	Janitor's Closet	3rd Floor	30	SF	7	10+ years	D 1
	Janitor's Closet	3rd Floor	30	SF	7	10+ years	Relamp
	Boiler Room	Basement Level - North	1,120	SF SF	7	10+ years	
	Mechanical/ Service Rooms	Basement Level - North	2,150 530	SF SF	7 5	10+ years	
	Storage Room Air Tunnel	Basement Level - North		SF SF	5 7	10+ years	
		Basement Level - South	3,000			10+ years	
	Mechanical/ Service Rooms	Basement Level - South	1,200	SF	7	10+ years	
Restroor	n						
	Accessories	107	40	SF	7	10+ years	
	Ceiling - Plaster/Drywall	107	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	107	1	ĒΑ	7	10+ years	
	Floor - Tile	107	40	SF	4	1-2 years	Broken tiles
	Lavatory	107	1	EA	7	10+ years	
	Lighting - Pendent/Surface	107	1	ĒΑ	7	10+ years	
	Walls - Concrete Block	107	300	SF	7	10+ years	
	Water Closet	107	1	EA	7	10+ years	
	Accessories	109	25	SF	7	10+ years	
	Ceiling - Plaster/Drywall	109	25	SF	7	10+ years	
	Doors - Wood Doors inclu hw	109	1	EA	7	10+ years	
						•	
	Floor - Tile	109	25	SF	7	10+ years	

Campus Name: Taylor Page: 13 of 38 Assessment Date: 07/25/2024





Catego	ry : Room		В	uilding	: Main		2 0 Avenue 11 Avenue, onleage, 12 00011
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	109	1	EA	7	10+ years	
	Lighting - Pendent/Surface	109	1	EA	7	10+ years	
	Walls - Plaster/Drywall	109	250	SF	7	10+ years	
	Water Closet	109	1	EA	7	10+ years	
	Accessories	1st Floor	372	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	372	SF	7	10+ years	
	Doors - Transom Window	1st Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	362	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	10	SF	4	1-2 years	Broken tiles
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	10+ years	
	Partitions	1st Floor	7	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	580	SF	7	10+ years	
	Walls - Masonry	1st Floor	580	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	336	SF	7	10+ years	
	Water Closet	1st Floor	7	EA	7	10+ years	
	Accessories	1st Floor	372	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	372	SF	7	10+ years	
	Doors - Transom Window	1st Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	372	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	10+ years	
	Partitions	1st Floor	3	EA	7	10+ years	
	Urinals	1st Floor	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	580	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	580	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	336	SF	7	10+ years	
	Water Closet	1st Floor	3	ĒΑ	6	10+ years	
	Accessories	1st Floor North - in Boys' restroom	28	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor North - in Boys' restroom	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor North - in Boys' restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor North - in Boys' restroom	28	SF	7	10+ years	
	Lavatory	1st Floor North - in Boys' restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor North - in Boys' restroom	1	EA	7	10+ years	
	Partitions	1st Floor North - in Boys' restroom	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor North - in Boys' restroom	225	SF	7	10+ years	
	Water Closet	1st Floor North - in Boys' restroom	1	EA	6	10+ years	
	Accessories	1st Floor South - in Girls' Restroom	28	SF	7	10+ years	
	/10003301103	13t 1 1001 Oddin - III Ollis 1\estilolii	20	Oi	'	TOT years	



Catego	Category : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor South - in Girls' Restroom	28	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor South - in Girls' Restroom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor South - in Girls' Restroom	28	SF	7	10+ years	
	Lavatory	1st Floor South - in Girls' Restroom	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor South - in Girls' Restroom	1	EA	7	10+ years	
	Partitions	1st Floor South - in Girls' Restroom	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor South - in Girls' Restroom	225	SF	6	10+ years	
	Water Closet	1st Floor South - in Girls' Restroom	1	EA	6	10+ years	
	Accessories	2nd Floor	375	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	375	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	375	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	10+ years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	10+ years	
	Partitions	2nd Floor	2	EA	7	10+ years	
	Partitions	2nd Floor	1	EA	5	1-2 years	Missing door
	Urinals	2nd Floor	6	EA	7	10+ years	•
	Walls - Concrete Block	2nd Floor	595	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	355	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	475	SF	7	10+ years	
	Water Closet	2nd Floor	3	EA	7	10+ years	
	Accessories	2nd Floor	375	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	325	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	50	SF	3	0-1 year	Active leak
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	375	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	2	EA	7	6-10 years	
	Lavatory	2nd Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	10+ years	
	Partitions	2nd Floor	7	EA	7	10+ years	
	Walls - Concrete Block	2nd Floor	595	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	355	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	475	SF	7	10+ years	
	Water Closet	2nd Floor	7	EA	7	10+ years	
	Water Closet	2nd Floor	2	EA	4	1-2 years	Out of order
	Accessories	2nd Floor North	27	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor North	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor North	1	EA	6	10+ years	
	Floor - Terrazzo	2nd Floor North	27	SF	7	10+ years	
	Lavatory	2nd Floor North	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor North	1	EA	7	10+ years	
	5 5 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	<del></del>	·		-	. ,	

Campus Name: Taylor Page: 15 of 38 Assessment Date: 07/25/2024



Catego	Category : Room		Building : Main						
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Partitions	2nd Floor North	1	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor North	155	SF	7	10+ years			
	Water Closet	2nd Floor North	1	EA	7	10+ years			
	Accessories	2nd Floor South	27	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor South	27	SF	7	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor South	1	EA	7	10+ years			
	Floor - Terrazzo	2nd Floor South	22	SF	7	10+ years			
	Floor - Terrazzo	2nd Floor South	5	SF	5	1-2 years	Cracking		
	Lavatory	2nd Floor South	1	EA	7	10+ years	•		
	Lighting - Pendent/Surface	2nd Floor South	1	EA	7	10+ years			
	Partitions	2nd Floor South	1	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor South	155	SF	7	10+ years			
	Water Closet	2nd Floor South	1	EA	7	6-10 years			
	Accessories	3rd Floor	375	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	375	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	375	SF	7	10+ years			
	Floor Drain	3rd Floor	1	ĒΑ	7	10+ years			
	Hand Dryer	3rd Floor	1	EA	7	6-10 years			
	Lavatory	3rd Floor	1	ΕA	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	10+ years			
	Partitions	3rd Floor	7	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor	595	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	355	SF	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor	475	SF	7	10+ years			
	Water Closet	3rd Floor	7	ĒA	7	10+ years			
	Accessories	3rd Floor	375	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	375	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	375	SF	7	10+ years			
	Floor Drain	3rd Floor	1	ĒΑ	7	10+ years			
	Hand Dryer	3rd Floor	2	EA	7	6-10 years			
	Lavatory	3rd Floor	1	EA	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	10+ years			
	Partitions	3rd Floor	3	EA	7	10+ years			
	Urinals	3rd Floor	6	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor	595	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	355	SF	7	10+ years			
	Walls - Structural Glazed Tile	3rd Floor	475	SF	7	10+ years			
	Water Closet	3rd Floor	2	EA	7	10+ years			
	Water Closet	3rd Floor	1	EΑ	4	1-2 years	Out of order		
	Accessories	3rd Floor North	27	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor North	27	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor North	1	EA	7	10+ years			
			·		•	,			

Campus Name: Taylor Page : 16 of 38 Assessment Date: 07/25/2024



Category : Room			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	3rd Floor North	27	SF	7	10+ years	
	Lavatory	3rd Floor North	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor North	1	EA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor North	1	EA	6	6-10 years	Missing switch cover
	Partitions	3rd Floor North	1	EA	7	10+ years	-
	Walls - Plaster/Drywall	3rd Floor North	155	SF	7	10+ years	
	Water Closet	3rd Floor North	1	EA	6	10+ years	
	Accessories	3rd Floor South	27	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor South	27	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor South	1	ĒΑ	7	10+ years	
	Floor - Terrazzo	3rd Floor South	27	SF	7	10+ years	
	Lavatory	3rd Floor South	 1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor South	1	ΕA	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor South	1	EΑ	6	6-10 years	Switch cover missing
	Partitions	3rd Floor South	1	EA	7	10+ years	Cwitch cover missing
	Walls - Plaster/Drywall	3rd Floor South	155	SF	7	10+ years	
	Water Closet	3rd Floor South	1	EA	7	10+ years	
	Accessories	In Principal's Office	100	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In Principal's Office	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In Principal's Office	100	EA	7	10+ years	
	Floor - Terrazzo	In Principal's Office	100	SF	7	10+ years	
		In Principal's Office	100	EA	7	-	
	Lavatory			EA	7	10+ years	
	Lighting - Pendent/Surface	In Principal's Office	1	EA		6-10 years	
	Partitions	In Principal's Office	1		7	6-10 years	
	Walls - Plaster/Drywall	In Principal's Office	380	SF	7	10+ years	One of
	Walls - Plaster/Drywall	In Principal's Office	20	SF	5	1-2 years	Crack
	Water Closet	In Principal's Office	1	EA	7	10+ years	
	Accessories	In engineer's office	130	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	In engineer's office	130	SF	7	10+ years	
	Doors - Wood Doors inclu hw	In engineer's office	1	EA	6	10+ years	
	Floor - Tile	In engineer's office	130	SF	7	10+ years	
	Lavatory	In engineer's office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	In engineer's office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	In engineer's office	284	SF	6	10+ years	Rank changed to match current
							observations
	Water Closet	In engineer's office	1	EA	7	10+ years	
			_				
atego	ry : Classroom		В	uilding	: Main	D	
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	om #101 (Regular Classroom)	Location	Quantity	OOM	Nank	Replacement	Comments
145510C	· · ·	1at Floor	4		7	6 10 2000	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	824	SF	7	10+ years	
	Doors - Transom Window	1st Floor	14	SF	7	10+ years	

Campus Name: Taylor Page: 17 of 38 Assessment Date: 07/25/2024



Catego	Category : Classroom		В	uilding	: Main		-
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	824	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	10+ years	
	Marker Board	1st Floor	30	LF	6	6-10 years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,326	SF	7	10+ years	
Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	824	SF	7	10+ years	
	Chalk Board	1st Floor	52	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood Bools Ilicia IIW	1st Floor	824	SF	7		
	Lighting - Pendent/Surface	1st Floor	14	EA		10+ years	
		1st Floor		SF	7	10+ years	
	Storage/ Closet	1st Floor	60 1,326	SF SF	7 7	10+ years	
	Walls - Plaster/Drywall	151 F1001	1,320	SF	,	10+ years	
Classroo	om #103 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	824	SF	7	10+ years	
	Chalk Board	1st Floor	52	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	824	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	7	EA	6	6-10 years	
	Marker Board	1st Floor	22	LF	7	10+ years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,326	SF	7	10+ years	
Classroo	om #107 (Pre School)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	42	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,325	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	25	SF	7	10+ years	
	Doors - Side-lite	1st Floor	30	SF	7	10+ years	
	Doors - Transom Window	1st Floor	42	SF	7	10+ years	
	Doors - Transom Window  Doors - Transom Window	1st Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Floor - Wood Doors inclu riw	1st Floor	1,350	SF	7	10+ years	
	1 1001 - VV00u	131 1 1001	1,350	SI⁻	,	TOT years	

Campus Name: Taylor Page: 18 of 38 Assessment Date: 07/25/2024



Catego	ory : Classroom		В	uilding	: Main		2 8 Avenue 11 Avenue, omeago, ne oou 17
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	16	EA	7	10+ years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,840	SF	6	10+ years	
Classroo	om #109 (Kindergarten)						
	AC Units	1st Floor	2	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	800	SF	7	10+ years	
	Doors - Transom Window	1st Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Wood	1st Floor	800	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	11	EA	7	10+ years	
	Marker Board	1st Floor	8	LF	7	10+ years	
	Storage/ Closet	1st Floor	84	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,700	SF	7	10+ years	
Classroo	om #111 (Regular Classroom)						
	AC Units	1st Floor	2	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	700	SF	7	10+ years	
	Doors - Transom Window	1st Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	1st Floor	700	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	11	ĒΑ	7	10+ years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Storage/ Closet	1st Floor	200	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,500	SF	7	10+ years	
_Classroo	om #114 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	824	SF	7	10+ years	
	Doors - Transom Window	1st Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	824	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	10+ years	
	Marker Board	1st Floor	24	LF	7	10+ years	
	Storage/ Closet	1st Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,326	SF	7	10+ years	
_Classroo	om #201 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	824	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	

Campus Name: Taylor Page: 19 of 38 Assessment Date: 07/25/2024



Catego	ry : Classroom		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	824	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,326	SF	7	10+ years	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	824	SF	7	10+ years	
	Chalk Board	2nd Floor	100	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw		14	EA	7	-	
	Floor - Wood Doors Inclu riw	2nd Floor 2nd Floor	824	SF	7	10+ years	
			-	_	-	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,326	SF	7	10+ years	
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	824	SF	7	10+ years	
	Chalk Board	2nd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Wood	2nd Floor	824	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	10+ years	
	Marker Board	2nd Floor	24	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,326	SF	7	10+ years	
Classroo	om #204 (Regular Classroom)						
CidaaiUt	AC Units	2nd Floor	2	EA	7	6 10 years	
	Casework		2	LF		6-10 years	
		2nd Floor	6		7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	990	SF	7	10+ years	
	Chalk Board	2nd Floor	5	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	990	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	70	SF	7	10+ years	

Campus Name: Taylor Page : 20 of 38 Assessment Date: 07/25/2024



	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	2nd Floor	1,464	SF	7	10+ years	
_Classroo	m #205 (Special Education)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	764	SF	7	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	28	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	764	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	42	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,240	SF	7	10+ years	
	•						
Classroo	m #207 (Office)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	902	SF	7	10+ years	
	Chalk Board	2nd Floor	48	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	40	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	902	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Storage/ Closet	2nd Floor	48	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,322	SF	7	10+ years	
_Classroo	m #209 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	824	SF	7	10+ years	
	Chalk Board	2nd Floor	52	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	824	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	8	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,306	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	6	10+ years	



Catego	ry : Classroom		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend	Comments
Group		Location	Quantity	UOW	Kank	Replacement	Comments
_Classroc	om #211 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	824	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	824	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,326	SF	7	10+ years	
_Classroc	om #212 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	990	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	990	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	10+ years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,464	SF	7	10+ years	
_Classroo	om #214 (Regular Classroom)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	824	SF	7	10+ years	
	Chalk Board	2nd Floor	25	LF	4	2-5 years	
	Doors - Transom Window	2nd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EΑ	7	10+ years	
	Floor - Wood	2nd Floor	824	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	60	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,326	SF	7	10+ years	
Classroo	om #301 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	848	SF	7	10+ years	
	Chalk Board	3rd Floor 3rd Floor	10	SF LF	4	2-5 years	
	Doors - Transom Window			SF	4 7	•	
	DUUIS - HAIISUIII WIIIUUW	3rd Floor	14	ЭF	1	10+ years	



Catego	ory : Classroom		В	uilding	: Main		. 5 :
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	7	10+ years	
	Floor - Wood	3rd Floor	848	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	14	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,165	SF	7	10+ years	
Classro	om #302 (Play Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	848	SF	7	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood Doors Inclu IIW	3rd Floor	848	SF	7	10+ years	
				EA			
	Lighting - Pendent/Surface	3rd Floor	14		7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,165	SF	7	10+ years	
_Classroo	om #303 (Art Room)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	848	SF	7	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	848	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	10+ years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,165	SF	7	10+ years	
Classro	om #304 (Music Room)						
	AC Units	3rd Floor	2	ГΛ	7	6.10 years	
			2	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	848	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	848	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	22	LF	7	6-10 years	
	Sound Panels	3rd Floor	20	EA	7	6-10 years	

Campus Name: Taylor Page : 23 of 38 Assessment Date: 07/25/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Sound System	3rd Floor	1	EA	7	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,165	SF	7	10+ years	
Classroo	om #309 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	798	SF	7	10+ years	
	Chalk Board	3rd Floor	4	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	3rd Floor	798	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	120	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,228	SF	7	10+ years	
Classroo	nm #310 (Regular Classroom)						
Olassico	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	3rd Floor	848	SF	7	10+ years	
	Chalk Board	3rd Floor	24	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood Bools Inclu IIW	3rd Floor	848	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,165	SF	7	10+ years	
	walls - Flastel/Drywall	314 11001	1,105	SF	,	10+ years	
Classroo	m #311 (Other Instructional Use)	0.15				0.40	
	AC Units	3rd Floor	1	EA	7	6-10 years	•
	AC Units	3rd Floor	1	EA	5	1-2 years	Cover missing
	Ceiling - Plaster/Drywall	3rd Floor	848	SF	7	10+ years	
	Chalk Board	3rd Floor	36	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile	3rd Floor	828	SF	7	10+ years	
	Floor - Tile	3rd Floor	20	SF	5	1-2 years	Cracking nd broken tiles
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	8	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,145	SF	7	10+ years	
	Wireless System	3rd Floor	1	EA	7	6-10 years	

Campus Name: Taylor Page : 24 of 38 Assessment Date: 07/25/2024



Category : Classroom		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
01	#040 /D						
_Classroc	m #312 (Regular Classroom)	0.15		<b>-</b>		0.10	
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	848	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	848	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	10+ years	
	Marker Board	3rd Floor	18	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,165	SF	7	10+ years	
_Classroo	om #314 (Regular Classroom)						
	AC Units	3rd Floor	2	EA	7	6-10 years	
	Casework	3rd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	848	SF	6	10+ years	
	Doors - Transom Window	3rd Floor	14	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Wood	3rd Floor	848	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	10+ years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	70	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,165	SF	7	10+ years	
<u>.</u> .			_			-	
Catego	ry : Interior		В	uilding	: Main	D	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor		Location	Quantity	OCIVI	Ivalik	Replacement	Comments
Comidor	Ceiling - Plaster/Drywall	1st Floor	6,940	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	20	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	20	EA	7	•	
	Floor - Terrazzo		5,600	SF	7	10+ years	
		1st Floor				10+ years	
	Floor - Terrazzo	1st Floor	100	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	1,240	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	63	EA	7	10+ years	
	Stairs - Terrazzo	1st Floor	4	LF	7	10+ years	
	Walls - Masonry	1st Floor	3,300	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	9,480	SF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	4,720	SF	7	10+ years	
	Doors - Wood Doors include hw	2nd Floor	3	EA	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	2	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor	4,600	SF	7	10+ years	



Catego	ry : Interior		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Terrazzo	2nd Floor	120	SF	5	1-2 years	Cracking		
	Lighting - Pendent/Surface	2nd Floor	40	EA	7	10+ years			
	Walls - Masonry	2nd Floor	4,500	SF	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	8,000	SF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	5,010	SF	7	10+ years			
	Doors - Wood Doors include hw	3rd Floor	2	EA	7	10+ years			
	Drinking Fountains - Double Fountain	3rd Floor	2	EA	7	10+ years			
	Floor - Terrazzo	3rd Floor	4,860	SF	7	10+ years			
	Floor - Terrazzo	3rd Floor	150	SF	5	1-2 years	Cracking		
	Lighting - Pendent/Surface	3rd Floor	32	ĒΑ	7	10+ years	3		
	Student Lockers - One Tier	3rd Floor	102	EA	7	10+ years			
	Walls - Masonry	3rd Floor	3,750	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	4,550	SF	7	10+ years			
Safety									
	Camera Viewing Station	1st Floor	2	EA	7	6-10 years			
	Security Cameras	1st Floor	5	EA	7	6-10 years	Quantity updated to match current		
	Coodiny Cameras	16(1166)	Ü		•	o ro youro	observations		
Stairs									
	Handrails	Balcony access (north side)	18	LF	7	10+ years			
	Stairs - Terrazzo	Balcony access (north side)	36	LF	7	10+ years			
	Handrails	Balcony access (south side)	18	LF	7	10+ years			
	Stairs - Terrazzo	Balcony access (south side)	36	LF	7	10+ years			
	Ceiling - Plaster/Drywall	NE Stair (2nd - 3rd Floor only, Stair 3)	180	SF	7	10+ years			
	Floor - Terrazzo	NE Stair (2nd - 3rd Floor only, Stair 3)	75	SF	7	10+ years			
	Handrails	NE Stair (2nd - 3rd Floor only, Stair 3)	66	LF	7	10+ years			
	Lighting - Pendent/Surface	NE Stair (2nd - 3rd Floor only, Stair 3)	2	EA	7	10+ years			
	Stairs - Terrazzo	NE Stair (2nd - 3rd Floor only, Stair	180	LF	7	10+ years			
	Walls - Plaster/Drywall	NE Stair (2nd - 3rd Floor only, Stair 3)	202	SF	7	10+ years			
	Walls - Structural Glazed Tile	NE Stair (2nd - 3rd Floor only, Stair 3)	202	SF	7	10+ years			
	Ceiling - Plaster/Drywall	North (Stair 4)	404	SF	7	10+ years			
	Floor - Terrazzo	North (Stair 4)	100	SF	7	10+ years			
	Handrails	North (Stair 4)	140	LF	7	10+ years			
	Lighting - Pendent/Surface	North (Stair 4)	4	EA	7	10+ years			
	Stairs - Terrazzo	North (Stair 4) North (Stair 4)	404	LF	7	10+ years 10+ years			
	Walls - Plaster/Drywall	North (Stair 4)	404	SF	7	10+ years 10+ years			
	vvalis - i lastel/Drywall	Hottii (Otali 4)	400	SF	,	TOT years			

Campus Name: Taylor Page : 26 of 38 Assessment Date: 07/25/2024



Category : Interior			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	North (Stair 4)	400	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North West (Stair 3)	192	SF	7	10+ years	
	Floor - Terrazzo	North West (Stair 3)	100	SF	7	10+ years	
	Handrails	North West (Stair 3)	84	LF	7	10+ years	
	Lighting - Pendent/Surface	North West (Stair 3)	2	EA	7	10+ years	
	Stairs - Terrazzo	North West (Stair 3)	192	LF	7	10+ years	
	Walls - Plaster/Drywall	North West (Stair 3)	202	SF	7	10+ years	
	Walls - Structural Glazed Tile	North West (Stair 3)	202	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South (Stair 1)	404	SF	7	10+ years	
	Floor - Terrazzo	South (Stair 1)	200	SF	7	10+ years	
	Handrails	South (Stair 1)	140	LF	7	10+ years	
	Lighting - Pendent/Surface	South (Stair 1)	4	EA	7	10+ years	
	Stairs - Terrazzo	South (Stair 1)	404	LF	7	10+ years	
	Walls - Plaster/Drywall	South (Stair 1)	400	SF	7	10+ years	
	Walls - Structural Glazed Tile	South (Stair 1)	400	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South West (Stair 2)	192	SF	7	10+ years	
	Floor - Terrazzo	South West (Stair 2)	80	SF	7	10+ years	
	Floor - Terrazzo	South West (Stair 2)	20	SF	5	1-2 years	Cracking
	Handrails	South West (Stair 2)	84	LF	7	10+ years	-
	Lighting - Pendent/Surface	South West (Stair 2)	2	EA	7	10+ years	
	Stairs - Terrazzo	South West (Stair 2)	192	LF	7	10+ years	
	Walls - Plaster/Drywall	South West (Stair 2)	202	SF	7	10+ years	
	Walls - Plaster/Drywall	South West (Stair 2)	202	SF	7	10+ years	

Campus Name: Taylor Page : 27 of 38 Assessment Date: 07/25/2024



Catego	ry : Exterior		В	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance		Location	Quantity	COM	IXAIIX	Replacement	Comments
	Exterior Doors - Exterior Steel Door	10	2	EA	5	1-2 years	Corroded base of frames
	Exterior Doors - Exterior Steel Door	11	2	EA	6	10+ years	
	Entrance Control - Audio and Video	9	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	9	2	EA	4	1-2 years	Corroding doors and frames
Foundati	ion						
Canaan	Foundation - Concrete	Entire Building	494	LF	7	10+ years	
	Superstructure - Slab on Grade	Entire Building	12,900	SF	7	10+ years	
Lighting							
<u>-igriiiig</u>	Exterior Lighting - Wall Mounted	Entire Building	3	EA	7	6-10 years	
Roof Sys	stem						
,	Chimney - Metal Flue	Н	16	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Н	60	LF	6	10+ years	Growing vegetation
	Downspouts - Exterior Downspouts	Н	3	LF	5	1-2 years	Broken, damage downspouts
	Roof - Metal	Н	12,870	SF	6	10+ years	-
	Roof - Metal	Н	30	SF	4	1-2 years	Damaged, bent fascia and gutter
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Н	12,900	SF	7	10+ years	•
Walls							
	Canopy - Metal	Entire Building	60	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	3,969	SF	7	10+ years	
Windows	3						
	Curtain wall - Louver	East and West	180	SF	6	10+ years	
	Guard - Guards perforated	East and West	1,138	SF	6	10+ years	
	Lintels - Steel	East and West	224	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	East and West	1,138	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	2,014	SF	6	10+ years	
	Emergency Battery Packs - Corridors and	Entire Building	4	EA	6	6-10 years	

Campus Name: Taylor Page : 28 of 38 Assessment Date: 07/25/2024



Catego	ry : Electrical		В	uildina	: Annex		2 S Avenue H AVENUE, Chicago, IL 606
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Exit Signs - Corridors and Stairs	Entire Building	3	EA	5	6-10 years	
	Security System - CCTV	Entire Building	12,310	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	12,310	SF	5	6-10 years	
//ain Se	n do o						
viain se		Floatrical Doors	4	ΓΛ		40	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	6	10+ years	
	Main Electrical Service - 800 A and	Entire Building	1	EA	6	10+ years	
	120/208/3PH	•				•	
	PA System	Entire Building	12,310	SF	5	6-10 years	
Power D	istribution						
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	4	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alar	m						
	Fire ALarm Anunciator	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	12,310	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	12,310	SF	6	6-10 years	
Sprinkler	System						
эршке	Sprinkler Heads	Entire Building	12,310	SF	7	10+ years	
	Sprinkler Piping	Entire Building	12,310	SF	7	10+ years	
	Wet Sprinkler System	9	12,310	SF	7		
	wet Spillikier System	Entire Building	12,310	SF	,	10+ years	
Catego	ry : Mechanical		В	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ling Systems						
w rail	Make Up Air Unit- Indoor Mounted- Hot	Boiler Room	1	EA	5	6-10 years	
	Water Coils - Less than 6000 cfm	Doller Room	ı	LA	3	0-10 years	
Boiler Sy	vstems						
	Boiler Auxiliary- Non Condensing Hot Water	Boiler Room	2	EA	6	6-10 years	
	- 1001 - 2000 MRH						
	- 1001 - 2000 MBH Chemical Pot Feeder	Boiler Room	1	ΕΛ	5	6-10 years	
	- 1001 - 2000 MBH Chemical Pot Feeder Combustion Dampers	Boiler Room Boiler Room	1 3	EA EA	5 6	6-10 years 6-10 years	

Campus Name: Taylor Page : 29 of 38 Assessment Date: 07/25/2024



\_Piping\_

# Douglas Taylor Elementary School 9912 S Avenue H AVENUE, Chicago, IL 60617

Catego	ry : Mechanical		В	uilding	: Annex		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Glycol Feed System	Boiler Room	1	EA	6	6-10 years	Manually fed
	Non Condensing- Flexible Tube-	Boiler Room	2	EA	5	2-5 years	
	Atmospheric- Hot Water Boiler - 1001 - 2000						
	MBH	B 11 B			_	0.40	
	Water Fill System	Boiler Room	1	EA	5	6-10 years	
_Heating_	Devices						
	PTAC - Hot Water Heating and Self	Electrical Room	1	EA	6	6-10 years	
	Contained Cooling		•	`	•	0 .0 ,00.0	
	Cabinet Heaters - With Hot Water Coil	Entire Building	6	EA	6	6-10 years	
	Unit Heater - Hot Water	Mechanical Room	2	EA	5	6-10 years	
						•	
_Mechani	cal Plumbing						
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	6-10 years	
	Hot Water Pump - Less than 10	Boiler Room	1	EA	5	6-10 years	
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	10+ years	
Tempera	ature Control						
	Electric Controls	Entire Building	12,310	SF	6	6-10 years	
	Electric Thermostat	Entire Building	2	EA	6	6-10 years	
		3				, , , , , , ,	
Unit Ven							
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	7	EA	5	6-10 years	
	w/ DX Cooling Coil & w/ Self Contained						
	Compressors						
	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	2	EA	5	6-10 years	
	w/ DX Cooling Coil & w/ Self Contained						
	Compressors						
_Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000	Roof	1	EA	5	6-10 years	
	CFM	<b>D</b> (	_		_	0.40	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	2	EA	5	6-10 years	
	G⊏IVI						
Catego	ry : Plumbing		В	uilding	: Annex		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Hot Wate	er						
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	7	6-10 years	
	Gas Heater - Less than 150000 BTU/HR	Mechanical Room	1	EA	7	6-10 years	

Campus Name: Taylor Page : 30 of 38 Assessment Date: 07/25/2024



Dome Fixtur Dome (Horiz Dome (from Sanita Storm Vent  Category : Ro  Group Item Administrative S  Ceilin Doors Floor Lighti Powe Walls	n - Type nestic Piping-Hot Water from Risers to ures nestic Piping-Hot/Cold Water Supply rizontal Lines) nestic Piping-Hot/Cold Water Supply m Risers to Fixtures) itary Piping m Piping triping triping	Location Entire Building	Quantity 12,310 12,310 12,310 12,310 12,310 12,310	UOM SF SF SF SF SF	Rank 6 6	Recommend Replacement 10+ years 10+ years 10+ years	Comments
Dome Fixtur Dome (Horiz Dome (from Sanita Storm Vent  Category : Ro  Group Item Administrative S  Ceilin Doors Floor Lighti Powe Walls	nestic Piping-Hot Water from Risers to ures nestic Piping-Hot/Cold Water Supply rizontal Lines) nestic Piping-Hot/Cold Water Supply m Risers to Fixtures) itary Piping m Piping t Piping t Piping Room	Entire Building Entire Building Entire Building Entire Building Entire Building	12,310 12,310 12,310 12,310 12,310	SF SF SF	6 6	10+ years 10+ years	Comments
Fixtur Dome (Horiz Dome (from Sanita Storm Vent  Category : Ro  Group Item Administrative S  Ceilin Doors Floor Lighti Powe Walls	ures nestic Piping-Hot/Cold Water Supply rizontal Lines) nestic Piping-Hot/Cold Water Supply m Risers to Fixtures) itary Piping m Piping t Piping Room	Entire Building Entire Building Entire Building Entire Building	12,310 12,310 12,310 12,310	SF SF SF	6	10+ years	
Dome (Horiz Dome (Horiz Dome (From Sanita Storm Vent    Category : Ro  Group Item Administrative S  Ceilin Doors Floor Lighti Powe Walls	nestic Piping-Hot/Cold Water Supply rizontal Lines) nestic Piping-Hot/Cold Water Supply m Risers to Fixtures) itary Piping m Piping t Piping Room	Entire Building Entire Building Entire Building	12,310 12,310 12,310	SF SF		-	
Category: Ro  Group Item Administrative S  Ceilin Doors Floor Lighti Powe Walls	nestic Piping-Hot/Cold Water Supply m Risers to Fixtures) itary Piping rm Piping t Piping Room	Entire Building Entire Building	12,310 12,310	SF	6	10+ years	
Category : Ro  Group Item Administrative S  Ceilin Doors Floor Lighti Powe Walls	itary Piping m Piping t Piping Room	Entire Building	12,310				
Storm Vent  Category: Ro  Group Item Administrative S  Ceilin Doors Floor Lighti Powe Walls	rm Piping It Piping Room	Entire Building	12,310		6	10+ years	
Category : Ro  Group Item Administrative S Ceilin Doors Floor Lighti Powe Walls	t Piping Room	<u> </u>			6	,	
Group Item Administrative S Ceilin Doors Floor Lighti Powe Walls	Room	Littino Ballating	12,010	SF	6	10+ years 10+ years	
Group Item Administrative S Ceilin Doors Floor Lighti Powe Walls				Oi.	O	101 years	
Administrative S Ceilin Doors Floor Lighti Powe Walls			В	uilding	: Annex		
Administrative S Ceilin Doors Floor Lighti Powe Walls	1 - IVDA	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Ceilin Doors Floor Lighti Powe Walls		Locution	Quantity	OOM	Marik	Replacement	Comments
Doors Floor Lighti Powe Walls		1st Floor Office	340	SF	7	10+ years	
Floor Lighti Powe Walls	ing - Lay-in						
Lighti Powe Walls	ors - Steel Doors incl hw	1st Floor Office	1	EA	7	10+ years	
Powe Walls		1st Floor Office	340	SF	7	10+ years	
Walls	nting - Lay-in	1st Floor Office	4	EA	7	10+ years	
	ver Distribution	1st Floor Office	8	EA	7	10+ years	
Walls	ls - Concrete Block	1st Floor Office	270	SF	7	10+ years	
	ls - Plaster/Drywall	1st Floor Office	500	SF	6	10+ years	
MDF_IDF							
Doors	ors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
Finish	shes	1st Floor	180	SF	7	10+ years	
Other	er Cooling Unit	1st Floor	1	EA	4	6-10 years	No cooling unit observed
Mechanical/ Se	ervice Rooms						
	er Room	1st Floor	433	SF	7	10+ years	
	itor's Closet	1st Floor	35	SF	7	10+ years	
	chanical/ Service Rooms	1st Floor	220	SF	7	10+ years	
Restroom							
	essories	1st Floor	580	SF	7	10+ years	
	ing - Plaster/Drywall	1st Floor	568	SF	7	10+ years	
	ing - Plaster/Drywall	1st Floor	12	SF	5	1-2 years	Water damage
	ors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	or - Epoxy/ Painted	1st Floor	580	SF	7	10+ years	
	or Drain	1st Floor	2	EA	7	10+ years	
	d Dryer	1st Floor	2	EA	7	6-10 years	
Lavat		1st Floor	3	EA	7	10+ years	
	atory nting - Lay-in	1st Floor	5	EA	7	10+ years	
	ining Lay-iii	1st Floor	1	EA	7	,	
Lighti	nting - Pendent/Surface					10+ years	

Campus Name: Taylor Page : 31 of 38 Assessment Date: 07/25/2024



Category : Room

#### Douglas Taylor Elementary School 9912 S Avenue H AVENUE, Chicago, IL 60617

Jatego	ry : Room		ь	unamg	: Annex		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Partitions	1st Floor	8	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,610	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Water Closet	1st Floor	7	EA	7	10+ years	
	Accessories	1st Floor	565	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	565	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	6	10+ years	
	Floor - Epoxy/ Painted	1st Floor	565	SF	7	10+ years	
	Floor Drain	1st Floor	2	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	5	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	ΕA	7	10+ years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	6	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	1,530	SF	7	10+ years	
	Water Closet	1st Floor	1,330	EA	7	6-10 years	
				SF	7		
	Accessories	Men's	44			10+ years	
	Ceiling - Plaster/Drywall	Men's	44	SF	7	10+ years	
	Doors - Steel Doors incl hw	Men's	1	EA	7	10+ years	
	Floor - Tile	Men's	44	SF	7	10+ years	
	Floor Drain	Men's	1	EA	7	10+ years	
	Lavatory	Men's	1	EA	7	10+ years	
	Lighting - Lay-in	Men's	1	EA	7	10+ years	
	Walls - Concrete Block	Men's	240	SF	7	10+ years	
	Water Closet	Men's	1	EA	7	10+ years	
	Accessories	Women's	44	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Women's	44	SF	6	10+ years	
	Doors - Steel Doors incl hw	Women's	1	EA	6	10+ years	
	Floor - Tile	Women's	44	SF	6	10+ years	
	Floor Drain	Women's	1	EA	7	10+ years	
	Lavatory	Women's	1	EA	6	10+ years	
	Lighting - Lay-in	Women's	1	EA	6	10+ years	
	Walls - Concrete Block	Women's	240	SF	6	10+ years	
	Water Closet	Women's	1	ĒΑ	6	10+ years	
			·		Ū	. o . y ca. c	
ateno	ry : Classroom		R	uildina	: Annex		
alogo	ry : Glassicom			ananig	· Allion	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	om #MS1 (Computer Lab)	Location	Qualitity	00141	Nuin	Nopidocinient	Commonto
1922100	, ,	2nd Floor	10	ır	7	10 L VOORS	Deficiency fixed
	Casework		18	LF	7	10+ years	Deficiency fixed
	Ceiling - Lay-in	2nd Floor	800	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	

**Building: Annex** 



Category : Classroom			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_	Floor - Tile	2nd Floor	800	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	760	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	250	SF	7	10+ years	
:lassroo	om #MS2 (Regular Classroom)						
1000100	Casework	1st Floor	42	LF	7	6-10 years	
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	800	SF	7	,	
						10+ years	
	Lighting - Lay-in	1st Floor	9	EA LF	7	6-10 years	
	Marker Board	1st Floor	12		7	6-10 years	
	Walls - Concrete Block	1st Floor	760	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	
lassroo	om #MS3 (Regular Classroom)						
	Casework	1st Floor	42	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	800	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	760	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years	
lassroo	om #MS4 (Regular Classroom)						
	Casework	2nd Floor	42	LF	7	10+ years	Deficiency fixed
	Ceiling - Lay-in	2nd Floor	800	SF	7	10+ years	
	Chalk Board	2nd Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	800	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	9	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	•	
		2nd Floor 2nd Floor		SF	7	6-10 years 10+ years	
	Walls - Concrete Block		760	SF SF		•	
	Walls - Plaster/Drywall	2nd Floor	250	51	7	10+ years	
lassroo	om #MS5 (Regular Classroom)						
	Casework	1st Floor	42	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	792	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Water damage tiles

Campus Name: Taylor Page: 33 of 38 Assessment Date: 07/25/2024



Catego	Category : Classroom			Building : Annex			2 0 7 Wellad 117 W EI VOE, Olloago, 12 00017			
						Recommend	Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
-	Chalk Board	1st Floor	12	LF	4	2-5 years				
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years				
	Floor - Tile	1st Floor	800	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years				
	Marker Board	1st Floor	12	LF	6	6-10 years				
	Walls - Concrete Block	1st Floor	660	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	100	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years				
Classroo	om #MS6 (Regular Classroom)									
	Casework	1st Floor	42	LF	7	10+ years				
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years				
	Chalk Board	1st Floor	12	LF	4	2-5 years				
	Doors - Steel Doors incl hw	1st Floor	1	EΑ	7	10+ years				
	Floor - Tile	1st Floor	800	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years				
	Walls - Concrete Block	1st Floor	760	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years				
Classroo	om #MS7 (Regular Classroom)									
	Casework	1st Floor	42	LF	7	10+ years				
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years				
	Chalk Board	1st Floor	12	LF	4	2-5 years				
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years				
	Floor - Tile	1st Floor	780	SF	7	10+ years				
	Floor - Tile	1st Floor	20	SF	5	1-2 years	Broken tiles			
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years				
	Marker Board	1st Floor	12	LF	7	6-10 years				
	Walls - Concrete Block	1st Floor	760	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years				
_Classroo	om #MS8 (Regular Classroom)									
	Casework	1st Floor	42	LF	7	10+ years				
	Ceiling - Lay-in	1st Floor	800	SF	7	10+ years				
	Chalk Board	1st Floor	12	LF	4	2-5 years				
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years				
	Floor - Tile	1st Floor	800	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years				
	Marker Board	1st Floor	12	LF	7	6-10 years				
	Walls - Concrete Block	1st Floor	760	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	250	SF	7	10+ years				

Campus Name: Taylor Page : 34 of 38 Assessment Date: 07/25/2024



Category : Interior			В	Building : Annex					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Corridor									
	Ceiling - Lay-in	1st Floor	1,753	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor	288	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	2	EΑ	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	2	EΑ	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor	6	EA	7	10+ years			
	Drinking Fountains - Single Fountain	1st Floor	2	EA	7	10+ years			
	Floor - Tile Quarry	1st Floor	288	SF	7	10+ years			
	Floor - Tile/Sheet	1st Floor	1,753	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	17	EA	7	10+ years			
	Student Lockers - Two Tiers	1st Floor	180	EA	7	10+ years			
	Walls - Concrete Block	1st Floor	4,900	SF	7	10+ years			
Safety									
<b>,</b>	Camera Viewing Station	1st Floor	1	EA	7	6-10 years			
	Security Cameras	1st Floor	1	EA	7	6-10 years			



- Type  ace - Asphalt  Drainage - Catch Basin Drainage - Site Manhole	Location  Northwest  Entire Site Entire Site	1,720 7 8	UOM SF EA	Rank 6	Recommend Replacement 10+ years	Comments
ace - Asphalt Drainage - Catch Basin Drainage - Site Manhole	Northwest Entire Site	1,720	SF	6	<u> </u>	Comments
Drainage - Catch Basin Drainage - Site Manhole	Entire Site	7			10+ years	
Drainage - Catch Basin Drainage - Site Manhole	Entire Site	7			10+ years	
Drainage - Site Manhole			EA			
Drainage - Site Manhole			EA			
Drainage - Site Manhole			EA			
	Entire Site	8		6	10+ years	
ing Chain Link			EA	6	10+ years	
ing Chain Link						
ang - Chain Link	Entire Site	499	LF	6	10+ years	
						Bent, corroding
		_		-		
ing Iron and Concrete Post						Dent neet and namela
						Bent post and panels
ang - New Standard Omamental	Little Site	410	LF	O	10+ years	
hes	Entire Site	5	EA	6	10+ years	
scape - Grass	Entire Site	4,005	SF	6	10+ years	
scape - Hardscape- Concrete	Entire Site	100		6	10+ years	
	Entire Site	4,603		6	10+ years	
				-		
				-		
Area - Hardscape- Asphalt	Entire Site	4,628	SF	4	1-2 years	Large cracks with growing vegetation, sunken, and upheaved surfaces throughout
ining Wall - Concrete	Entire Site	110	SF	6	10+ years	3
ining Wall - Concrete	Entire Site	140	SF	4	1-2 years	Extremely damaged, broken, spalled, disintegrated and missing sections of retaining wall. Parts of concrete slab above are floating
n Receptacles	Entire Site	1	EA	6	10+ years	S
ace - Asnhalt	North	3 800	SF	6	10± vears	Verified dimension
ace - Asphalt	North	1,000	SF	5	0-1 year	Verified dimensions and condition of asphalt. Alligatored surface, cracks. some repairs
ace - Concrete	North	820	SF	7	10+ years	
n Enclosure - Chain Links	North	244	SF	7	10+ years	
::::::::::::::::::::::::::::::::::::::	scape - Grass scape - Hardscape- Concrete scape - Hardscape- Concrete way trees ting Beds/ Area Area - Hardscape- Asphalt Area - Hardscape- Asphalt ining Wall - Concrete ining Wall - Concrete in Receptacles  ace - Asphalt ace - Asphalt	ing - Guard Rail ing - Iron and Concrete Post ing - New Standard Ornamental  Entire Site Entire Site Entire Site Entire Site Entire Site Escape - Grass Entire Site Escape - Hardscape- Concrete Entire Site Escape - Hardscape- Concrete Entire Site  Entire Site  In Receptacles  Entire Site  Entire	ing - Guard Rail Entire Site 120 ing - Iron and Concrete Post Entire Site 423 ing - Iron and Concrete Post Entire Site 12 ing - New Standard Ornamental Entire Site 1418  Thes Entire Site 5 scape - Grass Entire Site 100 scape - Hardscape- Concrete Entire Site 100 scape - Hardscape- Concrete Entire Site 30 way trees Entire Site 30 way trees Entire Site 30 ing Beds/ Area Entire Site 30 Area - Hardscape- Asphalt Entire Site 4,603 Area - Hardscape- Asphalt Entire Site 4,628  Inining Wall - Concrete Entire Site 4,628  Inining Wall - Concrete Entire Site 110 Inining Wall - Concrete Entire Site 140  In Receptacles Entire Site 140  Area - Asphalt North 3,890 Area - Asphalt North 1,000  In Rece - Asphalt North 1,000  In Rece - Concrete North 820	sing - Guard Rail         Entire Site         120         LF           sing - Iron and Concrete Post         Entire Site         423         LF           sing - Iron and Concrete Post         Entire Site         12         LF           sing - Iron and Concrete Post         Entire Site         12         LF           sing - New Standard Ornamental         Entire Site         418         LF           shes         Entire Site         4         405         SF           scape - Hardscape- Concrete         Entire Site         4,005         SF           scape - Hardscape- Concrete         Entire Site         4,603         SF           way trees         Entire Site         30         EA           sing Beds/ Area         Entire Site         152         SF           Area - Hardscape- Asphalt         Entire Site         4,150         SF           Area - Hardscape- Asphalt         Entire Site         4,628         SF           sining Wall - Concrete         Entire Site         110         SF           sining Wall - Concrete         Entire Site         1         EA           ace - Asphalt         North         3,890         SF           ace - Asphalt         North         1,000	sing - Guard Rail         Entire Site         120         LF         6           sing - Iron and Concrete Post         Entire Site         12         LF         6           sing - Iron and Concrete Post         Entire Site         12         LF         4           sing - Iron and Concrete Post         Entire Site         12         LF         4           sing - Iron and Concrete Post         Entire Site         12         LF         4           sing - Iron and Concrete Post         Entire Site         12         LF         6           sing - Iron and Concrete Post         Entire Site         12         LF         6           sing - Iron and Concrete Post         Entire Site         4         5         EA         6           sing - Iron and Concrete Entire Site         5         EA         6         6           scape - Hardscape Lardscape Entire Site         15         EA         6 <td>ing - Guard Rail         Entire Site         120         LF         6         10+ years           ing - Iron and Concrete Post         Entire Site         423         LF         6         10+ years           ing - Iron and Concrete Post         Entire Site         12         LF         4         0-1 years           ing - New Standard Ornamental         Entire Site         12         LF         4         0-1 years           ches         Entire Site         418         LF         6         10+ years           scape - New Standard Ornamental         Entire Site         400         SF         6         10+ years           scape - Grass         Entire Site         4,005         SF         6         10+ years         100         SF         6         10+ years         100         SF         6         10+ years         100         SF         6         10+ years         10+ years         10         Entire Site         30         EA         6         10+ years         10+ years         152         SF         6         10+ years         10+ years         152         SF         6         10+ years         10+ years</td>	ing - Guard Rail         Entire Site         120         LF         6         10+ years           ing - Iron and Concrete Post         Entire Site         423         LF         6         10+ years           ing - Iron and Concrete Post         Entire Site         12         LF         4         0-1 years           ing - New Standard Ornamental         Entire Site         12         LF         4         0-1 years           ches         Entire Site         418         LF         6         10+ years           scape - New Standard Ornamental         Entire Site         400         SF         6         10+ years           scape - Grass         Entire Site         4,005         SF         6         10+ years         100         SF         6         10+ years         100         SF         6         10+ years         100         SF         6         10+ years         10+ years         10         Entire Site         30         EA         6         10+ years         10+ years         152         SF         6         10+ years         10+ years         152         SF         6         10+ years         10+ years



#### **Douglas Taylor Elementary School**

9912 S Avenue H AVENUE, Chicago, IL 60617

Category : Site			В	uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Playgrou	ınd						
	Equipment - School Age 5-12	North	1	EA	7	10+ years	
	Surface - Poured Surface	North	3,000	SF	7	10+ years	
	Equipment - Combo 3-12	Southeast	1	EA	7	10+ years	Verified condition
	Surface - Poured Surface	Southeast	2,800	SF	7	10+ years	
Sidewalk	KS.						
	Sidewalks - Internal Walks	Entire Site	300	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	15,041	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	200	SF	4	1-2 years	Upheaved, solid numbers
Signage							
0 0	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back lighted w/ LED	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	3	EA	7	10+ years	

#### **Definitions**

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Taylor Page : 37 of 38 Assessment Date: 07/25/2024

<sup>&</sup>lt;sup>1</sup> It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



**Classroom Summary** 

Classroom Summary			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main									
Art Room	Regular Classroom	3rd Floor	303	303	848	216	40	N	Υ
Kindergarten	Office	1st Floor	109	123	800	180	30	N	N
Music Room	Regular Classroom	3rd Floor	304	304	848	216	40	N	N
Office	Regular Classroom	2nd Floor	207	207	902	232	15	N	N
Other Instructional Use	Regular Classroom	3rd Floor	311	313	848	216	40	N	N
Play Room	Regular Classroom	3rd Floor	302	302	848	216	40	N	N
Pre School	Kindergarten	1st Floor	107	121	1,350	145	30	N	N
Pre School	Regular Classroom	1st Floor	103	103	824	216	60	N	N
Regular Classroom	Office	1st Floor	111	133	700	144	40	N	N
Regular Classroom	Regular Classroom	1st Floor	101	101	824	216	60	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	824	216	60	N	N
Regular Classroom	Regular Classroom	1st Floor	114	114	824	216	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	824	216	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	824	216	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	203	203	824	216	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	204	204	990	252	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	824	216	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	824	216	40	N	N
Regular Classroom	Regular Classroom	2nd Floor	212	212	990	252	50	N	N
Regular Classroom	Regular Classroom	2nd Floor	214	214	824	216	40	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	848	216	40	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	309	311	798	216	40	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	848	216	40	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	312	312	848	216	40	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	314	314	848	216	40	N	Υ
Special Education	Regular Classroom	2nd Floor	205	205	764	182	36	N	N
Building : Annex									
Computer Lab	Regular Classroom	2nd Floor	MS1	106	800	108	54	Υ	N
Regular Classroom	Regular Classroom	1st Floor	MS2	107	800	108	54	N	N
Regular Classroom	Regular Classroom	1st Floor	MS3	104	800	108	54	N	N
Regular Classroom	Regular Classroom	1st Floor	MS5	108	800	108	54	N	N
Regular Classroom	Regular Classroom	1st Floor	MS6	102	800	108	54	N	N
Regular Classroom	Regular Classroom	1st Floor	MS7	105	800	108	54	N	N
Regular Classroom	Regular Classroom	1st Floor	MS8	101	800	108	54	N	Y
Regular Classroom	Regular Classroom	2nd Floor	MS4	103	800	108	54	N	N