

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1909	4	77,670
Addition	1971	3	27,218
Campus Total			104,888

Category : Exterior Building : Main

Building : Main					
			Recommend		
Quantity	UOM	Rank	Replacement	Comments	
4	EA	6	1-2 years	Warped, not closing properly, per building engineer	
2	EA	6	1-2 years	Warped, not closing properly, per building engineer	
3	EΑ	6	10+ years		
9	LF	6	10+ years		
1	EA	6	10+ years		
1	EA	6	10+ years		
4	LF	6	10+ years		
1	EΑ	6	10+ years		
1	EA	6	10+ years		
4	LF	6	10+ years		
1	EΑ	6	10+ years		
1	EA	6	10+ years		
4	LF	6	10+ years		
1	EA	6	10+ years		
1	EA	6	10+ years		
4	LF	6	10+ years		
1	EA	6	10+ years	see fire escape section	
3	EA	6	10+ years	•	
1	EA	6	10+ years		
3	LF	6	•		
1	EA	6	10+ years	see fire escape section	
	4 2 3 9 1 1 4 1 1 4 1 1 4 1 1 4 1 1 3 1	4 EA 2 EA 3 EA 9 LF 1 EA	4 EA 6 2 EA 6 3 EA 6 9 LF 6 1 EA 6	Quantity UOM Rank Replacement 4 EA 6 1-2 years 2 EA 6 1-2 years 3 EA 6 10+ years 9 LF 6 10+ years 1 EA 6 10+ years 2 EA 6 10+ years 3 EA 6 10+ years 1 EA 6 10+ years 1 EA	



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Doors - Side lite	18 - Fire Escape	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	18 - Fire Escape	3	EΑ	6	10+ years	
	Exterior Stairs - Concrete	18 - Fire Escape	5	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	19 - Fire Escape	1	EA	6	10+ years	see fire escape section
	Exterior Doors - Side lite	19 - Fire Escape	1	EΑ	6	10+ years	·
	Exterior Doors - Transom Lite	19 - Fire Escape	3	EA	6	10+ years	
	Exterior Stairs - Concrete	19 - Fire Escape	5	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	4 - Boiler Room	1	EA	5	0-1 year	Corroding frame
	Exterior Doors - Exterior FRP Door	5	1	EA	6	10+ years	G
	Exterior Doors - Side lite	5	1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	5	1	EΑ	6	10+ years	
	Exterior Stairs - Concrete	5	5	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	6	1	ĒΑ	6	10+ years	
	Exterior Doors - Transom Lite	6	1	EA	6	10+ years	
	Exterior Stairs - Concrete	6	4	LF	5	6-10 years	
	Exterior Doors - Exterior FRP Door	7	1	ĒΑ	6	10+ years	
	Exterior Doors - Transom Lite	7	1	EA	6	10+ years	
	Exterior Stairs - Concrete	7	4	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	8	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	8	1	EA	6	10+ years	
	Exterior Stairs - Concrete	8	4	LF	6	10+ years	
	Exterior Doors - Exterior FRP Door	9	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	9	1	EA	6	10+ years	
	Exterior Stairs - Concrete	9	4	LF	6	10+ years	
	Exterior Stairs - Concrete	9	4	L	O	10+ years	
_Fire Esca	ane						
	Exterior Doors - Exterior FRP Door	North Façade	3	EA	7	10+ years	
	Exterior Doors - Side lite	North Façade	3	EA	7	10+ years	
	Exterior Doors - Transom Lite	North Façade	18	EA	7	10+ years	
	Fire Escape	North Façade	85	LF	7	10+ years	
	Paints	North Façade	8	LF	7	6-10 years	
	raints	Notti Façade	O	LF	,	0-10 years	
Foundati	ion						
	Foundation - Concrete	Entire Building	624	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	77,670	SF	7	10+ years	
	•	.	,		-	- ,	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	7	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	3	EA	6	10+ years	
Post Sur	ntom						
Roof Sys		۸	4		7	101 2000	Now
	Access Ladder - Metal	A	1	EA	7	10+ years	New
	Access Ladder - Metal	A	1	EA	7	10+ years	New



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Coping - Metal	A	225	LF	7	10+ years	
	Coping - Metal	A	10	LF	5	0-1 year	Damaged coping, missing at terracotta roofs(named slate in assessment detail)
	Coping - Stone	A	160	LF	6	10+ years	
	Coping - Terra Cotta	A	598	LF	6	10+ years	
	Downspouts - Exterior Downspouts	A	10	LF	6	10+ years	
	Downspouts - Interior Downspouts	A	148	LF	6	10+ years	
	Parapet - 16" - 30" Height	A	933	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	A	11,190	SF	6	6-10 years	
	Roof - Asphalt Gravel Ballast	Α	4,200	SF	3	0-1 year	Leaks into rm 400, Deteriorated sealant at counter flashing, ponding
	Roof - Metal	A	50	SF	5	10+ years	Confirm that this is a surface stain. Copper, with patina.
	Roof - Slate Shingle	Α	250	SF	7	10+ years	Repaired
	Roof Hatch - Metal	A	1	EA	7	6-10 years	New
	Roof Structure - Steel with Clay Tile Arch	A	15,690	SF	7	10+ years	
	Downspouts - Exterior Downspouts	В	60	LF	6	10+ years	
	Downspouts - Interior Downspouts	В	100	LF	6	10+ years	
	Downspouts - Interior Downspouts	В	50	LF	6	10+ years	
	Roof - Modified Bitumen	В	1,600	SF	6	10+ years	
	Roof - Tile Shingle	В	2,000	SF	6	10+ years	
	Roof Structure - Concrete	В	3,600	SF	7	10+ years	
	Coping - Terra Cotta	C	124	LF	6	10+ years	
	Downspouts - Exterior Downspouts	C	80	LF	6	10+ years	
	Parapet - 16" - 30" Height	C	124	LF	6	10+ years	
	Roof - Asphalt Gravel Ballast	C	2,691	SF	6	6-10 years	
	Roof Structure - Concrete	С	2,691	SF	7	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	D	72	LF	6	10+ years	
	Coping - Clay Tile	D	20	LF	6	10+ years	
	Coping - Metal	D	103	LF	7	10+ years	
	Downspouts - Exterior Downspouts	D	12	LF	6	10+ years	
	Downspouts - Interior Downspouts	D	12	LF	6	10+ years	
	Parapet - 16" - 30" Height	D	123	LF	6	10+ years	
	Parapet - 16" - 30" Height	D	12	LF	5	1-2 years	Spalled brick, open joints
	Roof - Asphalt Gravel Ballast	D	3,237	SF	5	2-5 years	Blistering throughout, ponding, vegetation, deteriorated sealant at counter flashing
	Roof Structure - Concrete	D	3,237	SF	7	10+ years	g
Walls							
	Cheek-Wall - Stone	Entire Building	48	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	40,065	SF	7	10+ years	

Campus Name: Tilton Page : 3 of 42 Assessment Date: 09/18/2023



Catedo	ry : Exterior		B	uilding	: Main		
	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Exterior Walls - Brick	Entire Building	2,000	SF	5	10+ years	Roof tower walls, deteriorated, morta
	Exterior Walls - Brick	Entire Building	200	SF	4	1-2 years	Open joints
	Exterior Walls - Brick	Entire Building	50	SF	3	0-1 year	Corroded lintel, buckling wall
	Exterior Walls - Prefabricated Metal Panel	Entire Building	30	SF	6	10+ years	Corroaca initer, backing wan
	Wall	Entire Ballating	00	O1	O	101 years	
	Exterior Walls - Stone-Cut	Entire Building	2,645	SF	5	10+ years	
	Exterior Walls - Storie-Cut Exterior Walls - Terra Cotta	Entire Building	210	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Little Ballaling	210	01	U	10+ years	
Windows							
vvii idov.	Guard - Guards perforated	Entire Building	2,554	SF	6	10+ years	
	Lintels - Brick	•	2,334	LF	6		
		Entire Building			_	10+ years	
	Lintels - Steel	Entire Building	182	LF	6	10+ years	Orang de di ete el lietel Well ele conic
	Lintels - Steel	Entire Building	6	LF	4	0-1 year	Corroded, steel lintel. Wall above is
	Lintels - Stone	Entiro Building	100	LF	6	10 Lyone	buckling.
		Entire Building				10+ years	
	Lintels - Terra Cotta	Entire Building	416	LF	6	10+ years	
	Skylite - Lexan	Entire Building	1,004	SF	7	10+ years	
	Windows - Insulated Panel	Entire Building	420	SF	6	10+ years	
	Windows - Louver	Entire Building	96	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	6,276	SF	6	10+ years	
Catego	ry : Electrical		R	uilding	· Main		
				ananig	. IVIAIII		
				ananig	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Item - Type ncy System			_			Comments
	Item - Type	Location 1st Floor		_			Comments Per engineer survey there is ongoing issues.
•	Item - Type ncy System Emergency Generator- Indoor- Natural Gas - 60 - 100 KW Emergency Battery Packs - Auditoium and		Quantity	UOM	Rank	Replacement	Per engineer survey there is ongoing
•	Item - Type ncy System Emergency Generator- Indoor- Natural Gas - 60 - 100 KW Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and	1st Floor	Quantity	UOM	Rank 5	Replacement 1-2 years	Per engineer survey there is ongoing
•	Item - Type ncy System Emergency Generator- Indoor- Natural Gas - 60 - 100 KW Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs	1st Floor 1st Floor 1st Floor	Quantity 1 5	UOM EA EA EA	5 6 6	1-2 years 6-10 years 6-10 years	Per engineer survey there is ongoing
•	Item - Type ncy System Emergency Generator- Indoor- Natural Gas - 60 - 100 KW Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Automatic Transfer Switch	1st Floor 1st Floor 1st Floor Electrical Room	Quantity 1 5 1 3	UOM EA EA EA EA	5 6 6	1-2 years 6-10 years 6-10 years 10+ years	Per engineer survey there is ongoing
	Item - Type ncy System Emergency Generator- Indoor- Natural Gas - 60 - 100 KW Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Automatic Transfer Switch Security System - CCTV	1st Floor 1st Floor 1st Floor Electrical Room Entire Building	Quantity 1 5 1 3 77,670	UOM EA EA EA SF	5 6 6 6 6	1-2 years 6-10 years 6-10 years 10+ years 6-10 years	Per engineer survey there is ongoing
•	Item - Type ncy System Emergency Generator- Indoor- Natural Gas - 60 - 100 KW Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection	1st Floor 1st Floor 1st Floor Electrical Room Entire Building Entire Building	Quantity 1 5 1 3 77,670 77,670	EA EA EA SF SF	5 6 6 6 6 6	1-2 years 6-10 years 6-10 years 10+ years 6-10 years 2-5 years	Per engineer survey there is ongoing issues.
•	Item - Type ncy System Emergency Generator- Indoor- Natural Gas - 60 - 100 KW Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Automatic Transfer Switch Security System - CCTV	1st Floor 1st Floor 1st Floor Electrical Room Entire Building	Quantity 1 5 1 3 77,670	UOM EA EA EA SF	5 6 6 6 6	1-2 years 6-10 years 6-10 years 10+ years 6-10 years	Per engineer survey there is ongoing issues. Over 20 years old with incandescent
•	Item - Type ncy System Emergency Generator- Indoor- Natural Gas - 60 - 100 KW Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection	1st Floor 1st Floor 1st Floor Electrical Room Entire Building Entire Building	Quantity 1 5 1 3 77,670 77,670	EA EA EA SF SF	5 6 6 6 6 6	1-2 years 6-10 years 6-10 years 10+ years 6-10 years 2-5 years	Per engineer survey there is ongoing issues. Over 20 years old with incandescent bulbs Over 20 years old with incandescent
•	Item - Type ncy System Emergency Generator- Indoor- Natural Gas - 60 - 100 KW Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Exit Signs - Auditoium	1st Floor 1st Floor 1st Floor Electrical Room Entire Building Entire Building Entire Building	Quantity 1 5 1 3 77,670 77,670 13	EA EA EA SF SF EA	5 6 6 6 6 6 6 4	1-2 years 6-10 years 6-10 years 10+ years 6-10 years 2-5 years 2-5 years	Per engineer survey there is ongoing issues. Over 20 years old with incandescent bulbs Over 20 years old with incandescent bulbs Over 20 years old with incandescent bulbs Over 20 years old with incandescent
•	Item - Type ncy System Emergency Generator- Indoor- Natural Gas - 60 - 100 KW Emergency Battery Packs - Auditoium and Aisle Lighting Emergency Battery Packs - Corridors and Stairs Automatic Transfer Switch Security System - CCTV Security System - Intrusion Detection Exit Signs - Auditoium Exit Signs - Corridors and Stairs	1st Floor 1st Floor 1st Floor Electrical Room Entire Building Entire Building Entire Building Entire Building	Quantity 1 5 1 3 77,670 77,670 13 38	EA EA EA SF SF EA EA	5 6 6 6 6 6 4 4	1-2 years 6-10 years 6-10 years 10+ years 6-10 years 2-5 years 2-5 years 2-5 years	Per engineer survey there is ongoing issues. Over 20 years old with incandescent bulbs Over 20 years old with incandescent bulbs



Catego	ry : Electrical		В	uilding	: Main		
Calego.	. y . =100111041		_	anding.		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Jioup	Emergency A/C Power - Gym	Entire Building	2,414	SF	6	6-10 years	Comments
			· · · · · · · · · · · · · · · · · · ·		_		
	Emergency A/C Power - Students Toilets	Entire Building	3,101	SF	6	6-10 years	
//ain Ser	vice						
	Main Electrical Service - 2000 A	Electrical Room	1	EA	6	6-10 years	
	120/208/3PH						
	Independent Electrical Service for	Electrical Room	1	EA	6	6-10 years	
	emergency power						
	PA System	Entire Building	77,670	SF	6	2-5 years	
Power D	istribution						
owel D	Lighting and Power Panels - 100 A	Entire Building	2	EA	7	10+ years	
	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A	•	2	EA	6	6-10 years	
		Entire Building				-	
	Lighting and Power Panels - Above 100 A	Entire Building	8	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	10	EA	6	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	2-5 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Greater than 600	Entire Building	1	EA	6	10+ years	
	amp	G				•	
`ateno	ry : Fire Protection		R	uilding	· Main		
Juic go.				anding	. Wall	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Aları	m						
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	77,670	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	77,670	SF	6	6-10 years	
	•	g				,	
Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Air Cond		Location	Quantity	O O III	Italik	Replacement	Comments
VII COLIG	Condensing Unit- Roof Mounted - Less	Lower Roof	1	EA	6	6-10 years	
	· · · · · · · · · · · · · · · · · · ·	Lower Roof	Į	EA	O	0-10 years	
	than 5 tons						
	than 5 tons						
Air Hand	ling Systems						
Air Hand		1st Floor	1	EA	5	2-5 years	Deteriorating walls and peeling pai
Air Hand	ling Systems Air Handling Unit- Built Up-Multi Zone-	1st Floor	1	EA	5	2-5 years	Deteriorating walls and peeling par
Air Hand	ling Systems Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 -	1st Floor	1	EA	5	2-5 years	Deteriorating walls and peeling pa
sir Hand	ling Systems Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm					·	Deteriorating walls and peeling pa
sir Hand	ling Systems Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm Air Intake	1st Floor	2	EA	6	6-10 years	Deteriorating walls and peeling pa
Air Hand	ling Systems Air Handling Unit- Built Up-Multi Zone- Double Delivery- Steam Coils - 30001 - 45000 cfm					·	Deteriorating walls and peeling pa



Recommend Recommend Recommend Response Recommend Replacement	Catego	ry : Mechanical		В	uilding	: Main		223 IN Reelei AVENUE, Chicago, IL 60024
Missing or Existing Shaft Zone Dampers Air Handling Unit- Built Up- Single Zone- Stoam Colls - 8001 - 15000 cfm Air Indake Auxiliaries - 8001 - 15000 cfm Basement Air Indake Auxiliaries - 8001 - 15000 cfm Basement Auxiliaries - 8001 - 15000 cfm Basement Basement Air Indake Auxiliaries - 8001 - 15000 cfm Basement Basement Auxiliaries - 8001 - 15000 cfm Basement	_				_			
Air Handling Unit- Built Up- Single Zone- Basement 1 EA	Group		Location	Quantity	UOM	Rank	Replacement	Comments
Air Handing Unit- Built Up- Single Zone- Steam Coils - 5001 - 15000 cfm Air Intake Auxilianies - 8001 - 15000 cfm Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Air Intake Auxilianies - 8001 - 1500 cfm Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Air Intake Auxilianies - 8001 - 15000 cfm Basement Auxilianies - 8001 - 1500 cfm Basement Auxilianies - 8001 - 1500 cfm Basement Air Intake Auxilianies - 8001 - 1500 cfm Basement Auxilianies - 8001 - 1500 cfm Pressure Boilier - 101 - 150 lPP Boilianies - 8001 - 1500 cfm Basement Auxilianies - 8001 - 1500 cfm Basement Air Intake Basement Basement Air Intake Bas								
Air Handling Unit- Built Up. Single Zone- Steam Coils - 8001 - 15000 cfm Air Intake Auxiliaries - 8001 - 15000 cfm Basement Basement Auxiliaries - 8001 - 15000 cfm Basement		Zone Dampers	1st Floor	30	EA	4	2-5 years	•
Steam Coils - 8001 - 15000 cfm Air Intake Auxillairies - 8001 - 15000 cfm Basement Auxillairies - 8001 - 15000 cfm Basement Ba 6 6-10 years Basement Basement Basement Basement Basement Baseme		Air Llevelling Linit Duilt Lin Cingle Zone	Decement	4	Ε.	4	0.5.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
Air Intake Basement 1 EA 6 6-10 years Shares with main AHU Auxiliaries - 9001 - 15000 cfm Basement 1 EA 5 2-5 years Return Duct Work - Masonry and Ducts-Missing or Existing Shaft **Return Duct Work - Masonry and Ducts-Missing or Existing Shaft **Return Duct Work - Masonry and Ducts-Missing or Existing Shaft **Return Duct Work - Masonry and Ducts-Missing or Existing Shaft **Return Duct Work - Masonry and Ducts-Missing or Existing Shaft **Return Duct Work - Masonry and Ducts-Missing or Existing Shaft **Return Duct Work - Masonry and Ducts-Missing Or Existing Shaft **Return Duct Work - Masonry and Ducts-Missing Shaft **Return Duct Missing Shaft **Return Duct Mis			basement	ı	EA	4	2-5 years	
Ari Intake Auxiliaries - 8001 - 15000 cfm Basement Auxiliaries - 8001 - 15000 cfm Basement Auxiliaries - 8001 - 15000 cfm Basement Basement Auxiliaries - 8001 - 15000 cfm Basement Basement Basement Boiler Auxiliary - Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP Chemical Feed System Combustion Dampers Condensate Pump Entire Building Entire Building Beauting Condensate Pump Entire Building Beauting Condensate Pump Entire Building Beauting Condensate Pump Entire Building Beauting Beaut		Steam Coils - 8001 - 15000 cm						
Auxiliaries - 8001 - 15000 cfm Return Duct Work - Masonny and Ducts- Missing or Existing Shaft Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP Chemical Feed System Entire Building Combustion Dampers Condensate Pump Entire Building Electric Entire Building Electric Entire Building Electric Entire Building E		Air Intake	Rasement	1	FΔ	6	6-10 years	
Return Duct Work - Masonny and Ducts- Missing or Existing Shaft Boiler Auxiliary - Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP Entire Building 2 EA 5 2-5 years				•				Chares with main 7 th 10
Boiler Auxiliary - Scotch Marine - Steam Low Pressure Boiler - 101 - 150 HP Chemical Feed System Entire Building Entire Buildi				100				
Boiler Auxiliary - Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP Chemical Feed System Entire Building 2 EA 6 6-10 years Combustion Dampers Entire Building 2 EA 6 2-5 years Condensate Pump Entire Building 2 EA 6 6-10 years Condensate Pump Entire Building 1 EA 6 6-10 years Condensate Pump Entire Building 1 EA 6 6-10 years Condensate Pump Entire Building 1 EA 4 1-2 years Tank heavily corroded Condensate Pump Entire Building 1 EA 4 1-2 years Tank heavily corroded Condensate Pump Entire Building 1 EA 4 1-2 years Tank heavily corroded Condensate Pump Entire Building 1 EA 4 1-2 years Tank heavily corroded Entire Building 1 EA 4 2-5 years Insulation and piping deteriorating Entire Building 1 EA 5 2-5 years Insulation and piping deteriorating Entire Building 1 EA 5 2-5 years Insulation and piping deteriorating Entire Building 1 EA 4 1-2 years Recently failed inspection however currently being repaired to be ready soon to operate, leaking Steam Low Pressure Boiler - 101 - 150 HP Entire Building 1,000 LF 6 2-5 years Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years A lot are not working properly per engineer Heating Devices Heating Devices Heater - Electric Coil 4th Floor 1 EA 6 6-10 years Clean unit Unit Heater - Gas Entire Building 1 EA 5 2-5 years A lot are not working properly per engineer Heating Devices Entire Building 1 EA 5 6-10 years Clean unit Heater - Steam Entire Building 1 EA 5 6-10 years Clean unit Fin Tube - Steam Entire Building 1 EA 5 6-10 years For unit heaters Perumatic System Entire Building 3 EA 5 2-5 years For unit heaters Perumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to			Basomont	100		Ü	2 o youro	
Boiler Auxiliary - Scotch Marine- Steam Low Pressure Boiler - 101 - 150 HP Chemical Feed System Entire Building 2 EA 6 6-10 years Combustion Dampers Entire Building 2 EA 6 2-5 years Condensate Pump Entire Building 2 EA 6 6-10 years Condensate Pump Entire Building 1 EA 6 6-10 years Condensate Pump Entire Building 1 EA 6 6-10 years Condensate Pump Entire Building 1 EA 4 1-2 years Tank heavily corroded Condensate Pump Entire Building 1 EA 4 1-2 years Tank heavily corroded Condensate Pump Entire Building 1 EA 4 1-2 years Tank heavily corroded Condensate Pump Entire Building 1 EA 4 1-2 years Tank heavily corroded Entire Building 1 EA 4 2-5 years Insulation and piping deteriorating Entire Building 1 EA 5 2-5 years Insulation and piping deteriorating Entire Building 1 EA 5 2-5 years Insulation and piping deteriorating Entire Building 1 EA 4 1-2 years Recently failed inspection however currently being repaired to be ready soon to operate, leaking Steam Low Pressure Boiler - 101 - 150 HP Entire Building 1,000 LF 6 2-5 years Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years A lot are not working properly per engineer Heating Devices Heating Devices Heater - Electric Coil 4th Floor 1 EA 6 6-10 years Clean unit Unit Heater - Gas Entire Building 1 EA 5 2-5 years A lot are not working properly per engineer Heating Devices Entire Building 1 EA 5 6-10 years Clean unit Heater - Steam Entire Building 1 EA 5 6-10 years Clean unit Fin Tube - Steam Entire Building 1 EA 5 6-10 years For unit heaters Perumatic System Entire Building 3 EA 5 2-5 years For unit heaters Perumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to	Poilor C	votomo						
Pressure Boiler - 101 - 150 HP Chemical Feed System Combustion Dampers Combustion Dampers Condensate Pump Entire Building Condensate Pump Entire Building 1 EA 6 6-10 years Condensate Pump Entire Building 1 EA 6 6-10 years Condensate Pump Entire Building 1 EA 6 6-10 years Condensate Pump Entire Building 1 EA 4 1-2 years Condensate Pump Entire Building 1 EA 4 1-2 years Tank heavily corroded Entire Building 1 EA 4 1-2 years Tank heavily corroded Entire Building 1 EA 4 2-5 years Entire Building 1 EA 4 2-5 years Entire Building 1 EA 5 2-5 years Insulation and piping deteriorating Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing-Fire Tube-Scotch Marine- Steam-Low Pressure Boiler - 101 - 150 HP Entire Building 1 EA 6 2-5 years Steam Pipe-Steel Entire Building 1 EA 6 6-10 years Steam-Tow Pressure Boiler - 101 - 150 HP Entire Building 1 EA 6 6-10 years Steam-Tow Pressure Boiler - 101 - 150 HP Heating-Devices Entire Building 1 EA 6 6-10 years Steam-Tow Pressure Boiler - 101 - 150 HP Entire Building 1 EA 6 6-10 years	_bollet_Sy		Entire Building	2	EA	5	2-5 years	
Combustion Dampers Condensate Pump Entire Building Condensing-Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Entire Building Condensate Pipe- Steel Entire Building Condensate Pipe- Steen Entire Building Condensate Pipe			g	_			,	
Condensate Pump Condensate Pump Condensate Pump Condensate Pump Entire Building Condensate Pump Condensate Pump Entire Building Condensate Pump Condensate Pump Entire Building Condensate Pump Entire Building Condensate Pump Entire Building Feed Water Pumps and Tank Entire Building Feed Water Pumps and Tank Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Entire Building Thire Building		Chemical Feed System	Entire Building	1	EA	6	6-10 years	
Condensate Pump Entire Building 1 EA 6 6-10 years Condensate Pump Entire Building 1 EA 4 1-2 years Tank heavily corroded Entire Building 1 EA 4 1-2 years Tank heavily corroded Entire Building 1 EA 4 1-2 years Tank heavily corroded Entire Building 1 EA 4 2-5 years Insulation and piping deteriorating Entire Building 1 EA 5 2-5 years Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine-Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine-Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine-Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine-Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine-Steam- Low Pressure Boiler - 101 - 150 HP Entire Building 1,000 LF 6 2-5 years Piping - Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years Steam Traps Entire Building 1,000 LF 6 2-5 years Steam Traps Entire Building 1,000 LF 6 2-5 years A lot are not working properly per engineer Heating Devices Heating Devices Cabinet Heaters - With Electric Coil 4th Floor 1 EA 6 6-10 years Unit Heater - Steam Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 2-5 years Wall Heater - Steam Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 2 EA 5 6-10 years Fin Tube - Steam Entire Building 3 LF 7 10+ years For unit heaters For unit heaters For unit Pearl Entire Building 3 EA 5 2-5 years For unit heaters For unit pearl Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to		Combustion Dampers	Entire Building	2	EA	6	2-5 years	
Condensate Pump Entire Building 1 EA 4 1-2 years Tank heavily corroded Entire Building 1 EA 4 1-2 years Tank heavily corroded Entire Building 1 EA 4 1-2 years Tank heavily corroded Tank Non Condensing- Fire Tube- Scotch Marine-Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine-Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine-Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine-Steam- Low Pressure Boiler - 101 - 150 HP Entire Building 1 Devices Entire Building 2 De		Condensate Pump	Entire Building	1	EA	6	6-10 years	
Condensate Pump Entire Building 1 EA 4 1-2 years Tank heavily corroded Insulation and piping deteriorating 1 EA 4 2-5 years Steam-Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Poing - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Entire Building 1 EA 4 1-2 years Recently failed inspection however currently being repaired to be ready soon to operate, leaking Piping - Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years Piping - Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years Steam Traps Entire Building 32 EA 4 2-5 years A lot are not working properly per engineer Heating Devices Heating Devices Heater - Gas Entire Building 1 EA 6 6-10 years Unit Heater - Gas Entire Building 1 EA 6 6-10 years Unit Heater - Steam Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 6-10 years Fin Tube - Steam Entire Building 22 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Finance Fine Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to		Condensate Pump	Entire Building	1	EA	6	6-10 years	
Feed Water Pumps and Tank Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Piping - Condensate Pipe- Steel Piping - Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years Piping - Steam Pipe- Steel Entire Building 32 EA 4 2-5 years Steam Traps Entire Building 1,000 LF 6 2-5 years Steam Traps Entire Building 1,000 LF 6 2-5 years Steam Traps Entire Building 1,000 LF 6 2-5 years Steam Traps Entire Building 1,000 LF 6 2-5 years Steam Traps Entire Building 1,000 LF 6 2-5 years Steam Traps Entire Building 1,000 LF 6 2-5 years Entire Buil		Condensate Pump	Entire Building	1	EA	4	1-2 years	Tank heavily corroded
Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Piping - Condensate Pipe- Steel Piping - Steam Piping Piping - Steam Piping Pipi		Condensate Pump	Entire Building	1	EA	4	1-2 years	Tank heavily corroded
Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Piping - Condensate Pipe- Steel Entire Building 1,000 LF 6 2-5 years Piping - Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years Steam Traps Entire Building 32 EA 4 2-5 years A lot are not working properly per engineer Heating Devices Cabinet Heaters - With Electric Coil 4th Floor 1 EA 6 6-10 years Unit Heater - Gas Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 6-10 years Unit Heater - Steam Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to		Feed Water Pumps and Tank	Entire Building	1	EA	4	2-5 years	Insulation and piping deteriorating
Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 101 - 150 HP Piping - Condensate Pipe- Steel Entire Building 1,000 LF 6 2-5 years Piping - Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years Steam Pipe- Steel Entire Building 32 EA 4 2-5 years A lot are not working properly per engineer Heating Devices Heating Devices Cabinet Heaters - With Electric Coil 4th Floor 1 EA 6 6-10 years Unit Heater - Gas Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Fin Tube - Steam Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to			Entire Building	1	EA	5	2-5 years	
Steam- Low Pressure Boiler - 101 - 150 HP Piping - Condensate Pipe- Steel Entire Building 1,000 LF 6 2-5 years Piping - Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years Steam Traps Entire Building 32 EA 4 2-5 years A lot are not working properly per engineer Heating Devices Cabinet Heaters - With Electric Coil 4th Floor 1 EA 6 6-10 years Unit Heater - Electric Entire Building 1 EA 6 6-10 years Unit Heater - Gas Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to								
Piping - Condensate Pipe- Steel Entire Building 1,000 LF 6 2-5 years Steam Piper - Steel Entire Building 1,000 LF 6 2-5 years Steam Piper - Steel Entire Building 1,000 LF 6 2-5 years Steam Traps Entire Building 32 EA 4 2-5 years A lot are not working properly per engineer Heating Devices Cabinet Heaters - With Electric Coil 4th Floor 1 EA 6 6-10 years Unit Heater - Electric Entire Building 1 EA 6 6-10 years Unit Heater - Steam Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to			Entire Building	1	EA	4	1-2 years	
Piping - Condensate Pipe- Steel Entire Building 1,000 LF 6 2-5 years Steam Pipe- Steel Entire Building 1,000 LF 6 2-5 years Steam Pipe- Steel Entire Building 32 EA 4 2-5 years A lot are not working properly per engineer Heating Devices Cabinet Heaters - With Electric Coil 4th Floor 1 EA 6 6-10 years Unit Heater - Electric Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 2-5 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to		Steam- Low Pressure Boiler - 101 - 150 HP						
Piping - Steam Pipe- Steel Steam Traps Entire Building Steam Traps Steam Traps Entire Building Steam Traps Ste								soon to operate, leaking
Steam Traps Entire Building 32 EA 4 2-5 years A lot are not working properly per engineer Heating Devices Cabinet Heaters - With Electric Coil 4th Floor 1 EA 6 6-10 years Unit Heater - Electric Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 2-5 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 22 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to								
Heating Devices Cabinet Heaters - With Electric Coil 4th Floor 1 EA 6 6-10 years Unit Heater - Electric Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 6-10 years Wall Heater - Steam Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 1 EA 5 6-10 years Fin Tube - Steam Entire Building 22 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to								
Heating Devices Cabinet Heaters - With Electric Coil 4th Floor 1 EA 6 6-10 years Unit Heater - Electric Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 6-10 years Unit Heater - Electric Entire Building 1 EA 5 6-10 years Unit Heater - Electric Entire Building 22 EA 5 6-10 years Wall Heater - Electric Entire Building 22 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to		Steam Traps	Entire Building	32	EA	4	2-5 years	
Cabinet Heaters - With Electric Coil 4th Floor 1 EA 6 6-10 years Clean unit Unit Heater - Electric Entire Building 1 EA 5 6-10 years Unit Heater - Gas Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 22 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to								engineer
Unit Heater - Electric Entire Building 1 EA 6 6-10 years Unit Heater - Gas Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 22 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to	_Heating_	Devices						
Unit Heater - Gas Entire Building 1 EA 5 2-5 years Unit Heater - Steam Entire Building 1 EA 5 6-10 years Wall Heater - Electric Entire Building 22 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to		Cabinet Heaters - With Electric Coil	4th Floor	1	EA	6	6-10 years	Clean unit
Unit Heater - Steam Wall Heater - Electric Fin Tube - Steam Entire Building 22 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to		Unit Heater - Electric	Entire Building	1	EA	6	6-10 years	
Wall Heater - Electric Entire Building 22 EA 5 6-10 years Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to		Unit Heater - Gas	Entire Building	1	EA	5	2-5 years	
Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to		Unit Heater - Steam		1	EA			
Fin Tube - Steam Entire Building 30 LF 7 10+ years Temperature Control Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to		Wall Heater - Electric	Entire Building	22		5	6-10 years	
Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to		Fin Tube - Steam	Entire Building	30	LF	7	10+ years	
Electric Thermostat Entire Building 3 EA 5 2-5 years For unit heaters Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to	Tempera	ature Control						
Pneumatic System Entire Building 77,670 SF 3 0-1 year Compressor running a lot due to			Entire Building	3	EA	5	2-5 years	For unit heaters
			•					
		•	3	,,,,,		-	,	leaks in system

Campus Name: Tilton Page : 6 of 42 Assessment Date: 09/18/2023



atego	ry : Mechanical		В	uilding	: Main		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Thermostats - Pneumatic	Entire Building	31	EΑ	4	0-1 year	Non operational
		· ·				·	·
entilatio	on						
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	2	ΕA	6	6-10 years	
	CFM	9			-	,	
	Exhaust Fans- Roof Mounted - 500 - 1500	Entire Building	2	EA	6	6-10 years	
	CFM	· ·				•	
atego	ry : Plumbing		В	uilding	: Main		
alogo.	, ,		_	aag		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lot Wate	· ·						
<u>OL VVAIE</u>	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	6	6-10 years	
	Gue Flouidi 100000 000000 B1 6/1110	Bollot Room	_	_, 、	Ū	o io youio	
iping							
	Domestic Piping-Hot Water Return Lines	Entire Building	77,670	SF	4	2-5 years	A few pipe clamps, deteriorating
	B		 0-0	0=		0.5	insulation in some areas
	Domestic Piping-Hot Water Return Risers	Entire Building	77,670	SF	4	2-5 years	A few pipe clamps, deteriorating
	Domestic Piping-Hot Water from Risers to	Entire Building	77,670	SF	4	2 E vooro	insulation in some areas
	Fixtures	Entire Building	77,070	SF	4	2-5 years	A few pipe clamps, deteriorating insulation in some areas
	Domestic Piping-Hot/Cold Water Supply	Entire Building	77,670	SF	4	2-5 years	A few pipe clamps, deteriorating
	(Horizontal Lines)	Entire Banding	77,070	O.	7	2 0 years	insulation in some areas
	Domestic Piping-Hot/Cold Water Supply	Entire Building	77,670	SF	4	2-5 years	A few pipe clamps, deteriorating
	(Risers)	g	,	•	•	_ 0 ,000	insulation in some areas
	Domestic Piping-Hot/Cold Water Supply	Entire Building	77,670	SF	4	2-5 years	A few pipe clamps, deteriorating
	(from Risers to Fixtures)	3	·			·	insulation in some areas
	Sanitary Piping	Entire Building	77,670	SF	5	2-5 years	
	Storm Piping	Entire Building	77,670	SF	5	2-5 years	
	Vent Piping	Entire Building	77,670	SF	5	2-5 years	
umps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	10+ years	
	Pumps - Sump-Simplex	Entire Building	1	EA	3	0-1 year	Basement floods under heavy rain
ataaa.	ry : Poom		В	uildina	. Main		
alego	ry : Room		В	uilding	. IVIdIII	Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_	rative Suites/Offices						2 2
<u> </u>	AC Unit	101 Counselor's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	101 Counselor's Office	573	SF	6	10+ years	
	Johnsy i laston by wall	TO T COULIDOIDI 3 OIIICE	513	OI.	J	io i years	

Campus Name: Tilton Page: 7 of 42 Assessment Date: 09/18/2023



,	ry : Room			uilding		Recommend	
up	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Doors - Side-lite	101 Counselor's Office	30	SF	6	10+ years	
	Doors - Steel Doors incl hw	101 Counselor's Office	1	EA	6	10+ years	
	Doors - Transom Window	101 Counselor's Office	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	101 Counselor's Office	1	ĒΑ	6	10+ years	
	Floor - Tile	101 Counselor's Office	573	SF	5	1-2 years	Dirty (needs to be cleaned) and chipped tile
	Lighting - Pendent/Surface	101 Counselor's Office	16	EA	7	6-10 years	
	Power Distribution	101 Counselor's Office	8	EA	6	6-10 years	
	Walls - Masonry	101 Counselor's Office	770	SF	6	10+ years	
	Walls - Plaster/Drywall	101 Counselor's Office	311	SF	6	10+ years	
	AC Unit	118 Office	1	ĒΑ	7	6-10 years	
	Ceiling - Plaster/Drywall	118 Office	342	SF	7	10+ years	
	Doors - Side-lite	118 Office	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	118 Office	1	EA	7	10+ years	
	Floor - Tile/Sheet	118 Office	342	SF	7	10+ years	
	Lighting - Pendent/Surface	118 Office	5	EA	7	10+ years	
	Power Distribution	118 Office	6	EA	7	10+ years	
	Walls - Plaster/Drywall	118 Office	880	SF	7		
	AC Unit		1	EA	7	10+ years	
		119 Assistant Principal		SF	7	6-10 years	
	Ceiling - Plaster/Drywall	119 Assistant Principal	342	SF SF		10+ years	
	Doors - Side-lite	119 Assistant Principal	30		7	10+ years	
	Doors - Wood Doors inclu hw	119 Assistant Principal	1	EA	7	10+ years	
	Floor - Tile	119 Assistant Principal	342	SF	7	10+ years	
	Lighting - Pendent/Surface	119 Assistant Principal	5	EA	7	10+ years	
	Power Distribution	119 Assistant Principal	6	EA	7	10+ years	
	Walls - Plaster/Drywall	119 Assistant Principal	880	SF	7	10+ years	
	Ceiling - Plaster/Drywall	131 Engineer's Office	105	SF	6	10+ years	
	Doors - Steel Doors incl hw	131 Engineer's Office	1	EA	6	10+ years	
	Floor - Tile	131 Engineer's Office	105	SF	6	10+ years	
	Lighting - Pendent/Surface	131 Engineer's Office	2	EA	6	6-10 years	
	Power Distribution	131 Engineer's Office	4	EΑ	6	6-10 years	
	Walls - Masonry	131 Engineer's Office	276	SF	5	0-1 year	Water drips, cracking, and holes throughout
	Walls - Plaster/Drywall	131 Engineer's Office	276	SF	6	0-1 year	Holes throughout
	AC Unit	307 Faculty Lounge	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	307 Faculty Lounge	883	SF	6	10+ years	
	Doors - Transom Window	307 Faculty Lounge	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	307 Faculty Lounge	2	EA	6	10+ years	
	Floor - Carpet	307 Faculty Lounge	883	SF	6	6-10 years	
	Lighting - Pendent/Surface	307 Faculty Lounge	18	EA	7	6-10 years	
	Power Distribution	307 Faculty Lounge	7	EA	7	10+ years	
				SF	6		
	Walls - Plaster/Drywall	307 Faculty Lounge	1,354	SF	О	10+ years	

Campus Name: Tilton Page: 8 of 42 Assessment Date: 09/18/2023



Catego	ry : Room		В	uilding	: Main		
	_					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Balcony Seating	1st Floor	286	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	3,429	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	18	EA	6	10+ years	
	Floor - Concrete	1st Floor	1,187	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,242	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	6	EA	6	10+ years	
	Lighting - Wall Mounted	1st Floor	6	EA	6	10+ years	
	Main Floor Seating	1st Floor	272	EA	7	10+ years	
	Sound System	1st Floor	1	EΑ	7	10+ years	
	Stage	1st Floor	1,002	SF	6	10+ years	
	Stage Curtain	1st Floor	8	EA	7	10+ years	
	Stage Lift	1st Floor	1	EA	5	10+ years	
	Stage Lighting System	1st Floor	1	EΑ	7	10+ years	
	Stage-Stairs - Wood	1st Floor	18	LF	6	10+ years	
	Stairs - Wood	1st Floor	120	LF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	2,410	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,108	SF	6	10+ years	
Gymnas	ia						
•	Ceiling - Plaster/Drywall	Room 317 - 3rd Floor	2,414	SF	6	10+ years	No max occupancy sign
	Doors - Wood Doors inclu hw	Room 317 - 3rd Floor	, 4	ĒΑ	6	10+ years	
	Floor - Wood	Room 317 - 3rd Floor	2,414	SF	6	10+ years	
	Lighting - Pendent/Surface	Room 317 - 3rd Floor	[′] 15	ĒΑ	7	10+ years	
	Walls - Plaster/Drywall	Room 317 - 3rd Floor	950	SF	6	10+ years	
	Walls - Plaster/Drywall	Room 317 - 3rd Floor	2,853	SF	6	10+ years	
Library							
,	AC Unit	206	1	EA	7	6-10 years	
	Casework	206	54	LF	6	10+ years	
	Ceiling - Plaster/Drywall	206	939	SF	6	10+ years	
	Doors - Transom Window	206	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	206	2	EA	5	10+ years	
	Floor - Tile	206	939	SF	6	6-10 years	
	Lighting - Pendent/Surface	206	16	ĒΑ	7	10+ years	
	Storage/ Closet	206	122	SF	7	10+ years	
	Walls - Plaster/Drywall	206	1,415	SF	6	10+ years	
MDF ID	F						
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	_
	Doors - Steel Doors incl hw	2nd Floor	1	EA	6	10+ years	
	Finishes	2nd Floor	284	SF	5	1-2 years	Worn floor and chipping and cracking
	Other Cooling Unit	2nd Floor	1	EA	4	1-2 years	paint throughout No cooling unit found
	LITDALL COUNT LIDIT	Zna Floor	1	⊢ Δ	/1	1-7 VA2re	NO COURT UNIT TOURD



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
1bi	cal/ Service Rooms						
viechanii		4 of Elecu	4 204	OF.		10	
	Boiler Room	1st Floor	1,381	SF	5	10+ years	
	Coal Room	1st Floor	386	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	714	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	559	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	346	SF	5	10+ years	
	Mechanical/ Service Rooms	1st Floor	346	SF	5	10+ years	
	Storage Room	1st Floor	493	SF	5	10+ years	Quantity updated to match current observations
	Storage Room	1st Floor	541	SF	5	10+ years	
	Storage Room	203A Storage	120	SF	7	10+ years	Inaccessible the door is blocked
	Storage Room	207A- Storage	130	SF	7	10+ years	No deficiency found
	Janitor's Closet	2nd Floor	10	SF	4	0-1 year	paint is chipped throughout, water damage
	Janitor's Closet	2nd Floor	10	SF	4	1-2 years	Water damage, not in use
	Janitor's Closet	3rd Floor	10	SF	5	1-2 years	Not in use, no access
	Janitor's Closet	3rd Floor	10	SF	5	1-2 years	Water damage
	Janitor's Closet	4th Floor	10	SF	4	•	Water damage to floor and ceiling
	Janitor's Closet	4th Floor	10	SF	4	1-2 years 0-1 year	Repaint, water damage on walls ar
							ceiling
Restroon							
	Accessories	103A	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	103A	45	SF	6	10+ years	
	Doors - Wood Doors inclu hw	103A	1	EA	7	6-10 years	
	Floor - Terrazzo	103A	45	SF	6	10+ years	
	Lavatory	103A	1	EA	6	6-10 years	
	Lighting - Pendent/Surface	103A	1	EA	6	6-10 years	
	Walls - Plaster/Drywall	103A	255	SF	6	10+ years	
	Water Closet	103A	1	EΑ	6	6-10 years	
	Accessories	118A Unisex	26	SF	7	10+ years	
	Ceiling - Plaster/Drywall	118A Unisex	26	SF	7	10+ years	
	Doors - Wood Doors inclu hw	118A Unisex	2	EA	7	10+ years	
	Floor - Terrazzo	118A Unisex	20	SF	7	10+ years	
	Floor - Tile	118A Unisex	6	SF	7	10+ years	
	Lavatory	118A Unisex	1	EA	7	10+ years	
	Lighting - Wall Mounted	118A Unisex	2	EA	7	10+ years	
	Walls - Plaster/Drywall	118A Unisex	101	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	118A Unisex	101	SF	7	10+ years	
	Water Closet	118A Unisex	1	EA	7	10+ years	
	Accessories	119A Unisex	26	SF	7	10+ years	
	Ceiling - Plaster/Drywall	119A Unisex	26	SF	7	10+ years	
	•					•	
	Doors - Wood Doors inclu hw	119A Unisex	2	EA	7	10+ years	

Campus Name: Tilton Page : 10 of 42 Assessment Date: 09/18/2023



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	119A Unisex	20	SF	7	10+ years	
	Floor - Tile	119A Unisex	6	SF	7	10+ years	
	Lavatory	119A Unisex	1	EΑ	7	10+ years	
	Lighting - Wall Mounted Walls - Plaster/Drywall	119A Unisex	2 101	EA SF	7 7	10+ years	
	Walls - Flaster/Drywall Walls - Tile Ceramic/ Porcelain	119A Unisex 119A Unisex	101	SF SF	7	10+ years 10+ years	
	Water Closet	119A Unisex	101	EA	7	10+ years	
	Accessories	210 Unisex - not in use, padlock on	170	SF	7	10+ years	Inaccessible, engineer and staff are
	710003301103	door	170	Oi.	•	101 years	unable to enter
	Ceiling - Plaster/Drywall	210 Unisex - not in use, padlock on	170	SF	6	10+ years	
		door		-	-	, , , , , , , , , , , , , , , , , , , ,	
	Doors - Wood Doors inclu hw	210 Unisex - not in use, padlock on	1	EA	7	10+ years	
		door					
	Floor - Tile Ceramic/ Porcelain	210 Unisex - not in use, padlock on	170	SF	7	10+ years	
		door					
	Hand Dryer	210 Unisex - not in use, padlock on	1	EA	7	10+ years	
		door	_		_		
	Lavatory	210 Unisex - not in use, padlock on	1	EA	6	10+ years	
	Linktin v. Dandant/Ourface	door	0	_^	0	40	
	Lighting - Pendent/Surface	210 Unisex - not in use, padlock on	2	EA	6	10+ years	
	Walls - Plaster/Drywall	door 210 Unisex - not in use, padlock on	313	SF	6	10 Lyong	
	Walls - Plaster/Drywall	door	313	SF	O	10+ years	
	Walls - Tile Ceramic/ Porcelain	210 Unisex - not in use, padlock on	313	SF	6	10+ years	
	vvalis The Ceramic, Ferencialit	door	313	Oi.	U	101 years	
	Water Closet	210 Unisex - not in use, padlock on	1	EA	6	10+ years	
		door			-	, , , , , , , , , , , , , , , , , , , ,	
	Accessories	211 Unisex -Not in Use, Padlock on	170	SF	7	10+ years	
		door					
	Ceiling - Plaster/Drywall	211 Unisex -Not in Use, Padlock on	170	SF	6	10+ years	
		door					
	Doors - Wood Doors inclu hw	211 Unisex -Not in Use, Padlock on	1	EA	7	10+ years	
		door					
	Floor - Tile	211 Unisex -Not in Use, Padlock on	170	SF	6	10+ years	
	Hand Davis	door	4	_^	7	40	
	Hand Dryer	211 Unisex -Not in Use, Padlock on	1	EA	7	10+ years	
	Lavatory	door 211 Unisex -Not in Use, Padlock on	1	EA	6	10+ years	
	Lavatory	door	'	LA	O	10+ years	
	Lighting - Pendent/Surface	211 Unisex -Not in Use, Padlock on	2	EA	7	10+ years	
	Lighting 1 offdorff Outland	door	2	L/\	•	ioi youis	
	Walls - Plaster/Drywall	211 Unisex -Not in Use, Padlock on	626	SF	6	10+ years	
		door	3_0	٥.	•	,	
	Water Closet	211 Unisex -Not in Use, Padlock on	1	EA	6	10+ years	
		·				ĺ	

Campus Name: Tilton Page : 11 of 42 Assessment Date: 09/18/2023



Catego	ry : Room		Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
		door			_				
	Accessories	2nd Floor	535	SF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	535	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Terrazzo	2nd Floor	535	SF	5	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Hand Dryer	2nd Floor	1	EA	7	10+ years			
	Lavatory	2nd Floor	4	EA	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	8	EA	7	10+ years			
	Partitions	2nd Floor	7	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	84	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	1,097	SF	5	10+ years			
	Water Closet	2nd Floor	7	EA	6	10+ years			
	Accessories	2nd Floor	500	SF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	500	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years			
	Floor - Terrazzo	2nd Floor	350	SF	6	10+ years			
	Floor - Terrazzo	2nd Floor	150	SF	4	1-2 years	Large crack		
	Floor Drain	2nd Floor	1	EA	7	10+ years	Large order		
	Hand Dryer	2nd Floor	1	EA	7	10+ years			
	Lavatory	2nd Floor	2	EA	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	8	EA	6	10+ years			
	Partitions	2nd Floor	3	EA	7	10+ years			
	Urinals	2nd Floor	6	EA	6	10+ years			
	Walls - Plaster/Drywall	2nd Floor	491	SF	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor 2nd Floor	491	SF	5		Cracks throughout		
	Water Closet	2nd Floor	3	EA	6	1-2 years 10+ years	Cracks throughout		
	Accessories	310 Unisex	170	SF	7				
	Ceiling - Plaster/Drywall	310 Unisex	170	SF	7	10+ years			
	Doors - Wood Doors inclu hw		170	SF EA	7	10+ years			
		310 Unisex 310 Unisex	170	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain					10+ years			
	Hand Dryer	310 Unisex	1	EΑ	7	10+ years			
	Lavatory	310 Unisex	1	EΑ	6	10+ years			
	Lighting - Pendent/Surface	310 Unisex	2	EA	7	10+ years			
	Walls - Plaster/Drywall	310 Unisex	250	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	310 Unisex	375	SF	6	10+ years			
	Water Closet	310 Unisex	1	EA	6	10+ years			
	Accessories	311 Unisex	173	SF	7	10+ years			
	Ceiling - Plaster/Drywall	311 Unisex	173	SF	6	10+ years			
	Doors - Wood Doors inclu hw	311 Unisex	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	311 Unisex	173	SF	7	10+ years			
	Hand Dryer	311 Unisex	1	EA	7	10+ years			
	Lavatory	311 Unisex	1	EA	6	10+ years			
	Lighting - Pendent/Surface	311 Unisex	2	EA	7	10+ years			



Category : Room			Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Plaster/Drywall	311 Unisex	316	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	311 Unisex	316	SF	6	10+ years			
	Water Closet	311 Unisex	1	EA	6	10+ years			
	Accessories	3rd Floor	500	SF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	500	SF	7	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years			
	Floor - Terrazzo	3rd Floor	500	SF	6	10+ years			
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Hand Dryer	3rd Floor	1	EA	7	10+ years			
	Lavatory	3rd Floor	2	EA	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	8	EA	6	10+ years			
	Partitions	3rd Floor	3	EA	7	10+ years			
	Urinals	3rd Floor	6	EA	6	10+ years			
	Walls - Plaster/Drywall	3rd Floor	491	SF	6	10+ years			
	Walls - Structural Glazed Tile	3rd Floor	491	SF	6	10+ years			
	Water Closet	3rd Floor	3	EA	6	10+ years			
	Accessories	3rd Floor	535	SF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	535	SF	5	1-2 years	Water damage		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	-		
	Floor - Terrazzo	3rd Floor	535	SF	6	10+ years			
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Hand Dryer	3rd Floor	1	EA	7	10+ years			
	Lavatory	3rd Floor	4	EA	6	10+ years			
	Lighting - Pendent/Surface	3rd Floor	8	EA	7	10+ years			
	Partitions	3rd Floor	7	EA	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	84	SF	6	10+ years			
	Walls - Structural Glazed Tile	3rd Floor	1,000	SF	6	10+ years			
	Walls - Structural Glazed Tile	3rd Floor	97	SF	5	1-2 years	Cracking		
	Water Closet	3rd Floor	7	EA	6	10+ years			
	Accessories	409 Unisex	170	SF	7	10+ years			
	Ceiling - Plaster/Drywall	409 Unisex	170	SF	7	10+ years			
	Doors - Wood Doors inclu hw	409 Unisex	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	409 Unisex	170	SF	7	10+ years			
	Hand Dryer	409 Unisex	1	EA	7	10+ years			
	Lavatory	409 Unisex	1	EA	7	10+ years			
	Lighting - Pendent/Surface	409 Unisex	2	EA	7	10+ years			
	Walls - Plaster/Drywall	409 Unisex	331	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	409 Unisex	331	SF	7	10+ years			
	Water Closet	409 Unisex	1	EA	7	10+ years			
	Accessories	410 Unisex	170	SF	7	10+ years			
	Ceiling - Plaster/Drywall	410 Unisex	170	SF	7	10+ years			
	Doors - Wood Doors inclu hw	410 Unisex	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	410 Unisex	170	SF	7	10+ years			
	Hand Dryer	410 Unisex	1	EA	7	10+ years			
	-					•			

Campus Name: Tilton Page: 13 of 42 Assessment Date: 09/18/2023



Catego	ry : Room		B	uilding	: Main		223 N Neclei Avenoe, Officago, le 00024
Guiogo	.,		_	uag		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	410 Unisex	1	EA	7	10+ years	
	Lighting - Pendent/Surface	410 Unisex	2	EA	6	10+ years	
	Walls - Plaster/Drywall	410 Unisex	331	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	410 Unisex	331	SF	7	10+ years	
	Water Closet	410 Unisex	1	ĒΑ	7	10+ years	
	Accessories	4th Floor	531	SF	7	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	531	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	1	ĒΑ	6	10+ years	
	Floor - Terrazzo	4th Floor	531	SF	6	10+ years	
	Floor Drain	4th Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	4th Floor	1	EA	7	10+ years	
	Lavatory	4th Floor	4	ΕA	6	10+ years	
	Lighting - Pendent/Surface	4th Floor	8	EA	7	10+ years	
	Partitions	4th Floor	7	EA	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	491	SF	6	10+ years	
	Walls - Structural Glazed Tile	4th Floor	491	SF	6	10+ years	
	Water Closet	4th Floor	7	ĒΑ	6	10+ years	
	Accessories	4th Floor	500	SF	7	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	500	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	2	ĒΑ	6	10+ years	
	Floor - Terrazzo	4th Floor	500	SF	6	10+ years	
	Floor Drain	4th Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	4th Floor	1	EA	7	10+ years	
	Lavatory	4th Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	4th Floor	8	EA	7	10+ years	
	Partitions	4th Floor	3	EA	7	10+ years	
	Urinals	4th Floor	6	EA	6	10+ years	
	Walls - Plaster/Drywall	4th Floor	466	SF	6	10+ years	
	Walls - Structural Glazed Tile	4th Floor	466	SF	6	10+ years	
	Water Closet	4th Floor	3	EA	6	10+ years	
	Accessories	Engineer's Toilet	49	SF	7	10+ years	
	Ceiling - Exposed	Engineer's Toilet	49	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Engineer's Toilet	1	EA	5	10+ years	
	Floor - Concrete	Engineer's Toilet	49	SF	5	10+ years	
	Lighting - Wall Mounted	Engineer's Toilet	1	EA	6	10+ years	
	Walls - Masonry	Engineer's Toilet	270	SF	5	10+ years	
	Water Closet	Engineer's Toilet	1	EA	6	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	om #100 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	560	SF	7	10+ years	
	Coming Tractor/Diywan	1001 1001	000	0.	•	ioi youis	

Campus Name: Tilton Page : 14 of 42 Assessment Date: 09/18/2023



Catego	Category : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	1st Floor	30	SF	6	10+ years	
	Doors - Transom Window	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	560	SF	5	1-2 years	Sloped floor, the flooring along the
						•	north and south walls are sinking and
							warped
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	•
	Marker Board	1st Floor	40	LF	7	6-10 years	
	Walls - Masonry	1st Floor	704	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	364	SF	7	10+ years	
	Wallo Tlastel/Diywall	13(1100)	004	O.	,	101 years	
Classroc	om #102 (Science Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	987	SF	6	10+ years	
	Doors - Transom Window	1st Floor	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,037	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	1,037	EA	7	6-10 years	
	Marker Board			LF	7	,	
		1st Floor	36			6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,402	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroc	om #103 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	1,003	SF	6	10+ years	
	Doors - Transom Window	1st Floor	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
				SF	6		Oughtity undeted to motely ourrent
	Floor - Wood	1st Floor	1,053	5F	б	10+ years	Quantity updated to match current observations
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,382	SF	7	10+ years	
	Work Sink	1st Floor	1,302	EA	7	10+ years	
	WOIR SIIIK	1St Floor	ı	LA	,	10+ years	
Classroc	om #104 (Store Room)						
	AC Units	1st Floor	1	EA	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	566	SF	7	10+ years	
	Doors - Side-lite	1st Floor	30	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Transom Window	1st Floor	30	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	POOLS - MADOR POOLS ILICIA LIM	121 LIOOI	1	EA	O	io+ years	

Campus Name: Tilton Page : 15 of 42 Assessment Date: 09/18/2023



Catego	Category : Classroom		В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	1st Floor	566	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	20	LF	7	6-10 years	
	Walls - Masonry	1st Floor	711	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	364	SF	7	10+ years	
Classroo	om #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	566	SF	6	10+ years	
	Chalk Board	1st Floor	7	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	561	SF	6	10+ years	
				SF	5		Cracking and chinned tiles
	Floor - Tile	1st Floor	5	Sr EA	-	1-2 years	Cracking, and chipped tiles
	Lighting - Pendent/Surface	1st Floor	12		6	10+ years	
	Marker Board	1st Floor	28	LF	6	6-10 years	
	Walls - Masonry	1st Floor 1st Floor	757 378	SF SF	6 6	10+ years	
	Walls - Plaster/Drywall	13111001	370	OI .	U	10+ years	
_Classroo	om #200 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	847	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	847	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,297	SF	7	10+ years	
_Classroo	om #201 (Store Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	848	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	2nd Floor	848	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	10+ years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,327	SF	6	10+ years	
	idoton b. y wan	2.13 . 1001	1,021	٥.	Ü	.o. youro	



Category : Classroom			В	uilding	: Main		
			•			Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
lassroo	m #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	5	0-1 year	Cabinets are worn
	Ceiling - Plaster/Drywall	2nd Floor	847	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	847	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	10+ years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,289	SF	6	10+ years	
Classroo	m #203 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	6	LF	7	6-10 years	Deficiency fixed
	Ceiling - Plaster/Drywall	2nd Floor	1,137	SF	6	10+ years	•
	Doors - Transom Window	2nd Floor	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	1.137	SF	4	0-1 year	Cracks throughout
	Lighting - Pendent/Surface	2nd Floor	17	EA	7	6-10 years	oraciic un oagiicat
	Marker Board	2nd Floor	20	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	91	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,499	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroo	m #204 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	3	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	847	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	6	10+ years	
	Floor - Wood	2nd Floor	847	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,289	SF	6	10+ years	
lassroo	m #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	533	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	533	SF	4	0-1 year	Worn, separating, and cracking throughout



Catego	ry : Classroom		В	uilding	: Main		•
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	2nd Floor	12	EA	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,104	SF	6	10+ years	
_Classro	om #207 (Play Room)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	8	LF	5	6-10 years	Deficiency fixed
	Ceiling - Plaster/Drywall	2nd Floor	897	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	16	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EΑ	5	6-10 years	Deficiency not found
	Floor - Wood	2nd Floor	897	SF	6	10+ years	•
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	7	10+ years	
	Marker Board	2nd Floor	22	LF	6	6-10 years	
	Storage/ Closet	2nd Floor	91	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	1,349	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	5	2-5 years	
_Classroo	om #300 (Regular Classroom)						
	AC Units	3rd Floor	1	EΑ	7	6-10 years	
	Casework	3rd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	842	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	24	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒΑ	6	10+ years	
	Floor - Wood	3rd Floor	842	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	32	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,321	SF	6	10+ years	
_Classro	om #301 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	848	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years	
	Floor - Wood	3rd Floor	848	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	21	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,301	SF	7	10+ years	
_Classro	om #302 (Science Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
		0.4 1 1001	12		J	.o. youro	



Catego	ory : Classroom		В	uilding	: Main		225 N Nobici AVENOE, Onloago, 12 00024		
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	3rd Floor	843	SF	6	10+ years			
	Doors - Transom Window	3rd Floor	32	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years			
	Floor - Wood	3rd Floor	843	SF	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years			
	Marker Board	3rd Floor	25	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	50	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,314	SF	6	10+ years			
Classroo	om #303 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	6	LF	6	10+ years			
	Casework Ceiling - Plaster/Drywall	3rd Floor	846	SF	6	10+ years			
	Doors - Transom Window	3rd Floor	32	SF	6	10+ years			
			2	EA	6	-			
	Doors - Wood Doors inclu hw	3rd Floor		SF		10+ years			
	Floor - Wood	3rd Floor	846		6	6-10 years			
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years			
	Marker Board	3rd Floor	29	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	50	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,300	SF	7	10+ years			
Classroo	om #304 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	10	LF	7	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	843	SF	6	10+ years			
	Doors - Transom Window	3rd Floor	32	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years			
	Floor - Wood	3rd Floor	843	SF	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years			
	Marker Board	3rd Floor	36	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	50	SF	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	1,314	SF	6	10+ years			
_Classroo	om #305 (Regular Classroom)								
	AC Units	3rd Floor	1	EA	7	6-10 years			
	Casework	3rd Floor	6	LF	6	10+ years			
	Ceiling - Plaster/Drywall	3rd Floor	860	SF	6	10+ years			
	Doors - Transom Window	3rd Floor	32	SF	6	10+ years			
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	6	10+ years			
			860	SF		-			
	Floor - Wood	3rd Floor 3rd Floor	14	SF EA	6	10+ years			
	Lighting - Pendent/Surface				7	6-10 years			
	Marker Board	3rd Floor	22	LF	7	6-10 years			
	Storage/ Closet	3rd Floor	50	SF	7	10+ years			

Campus Name: Tilton Page: 19 of 42 Assessment Date: 09/18/2023



Catego	ory : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	3rd Floor	1,312	SF	7	10+ years	
Classro	om #400 (Laboratory/Shop)						
	AC Units	4th Floor	2	EA	7	6-10 years	
	Casework	4th Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	1,804	SF	5	1-2 years	Water damage
	Doors - Transom Window	4th Floor	56	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	4	EA	6	10+ years	
	Floor - Wood	4th Floor	1,804	SF	6	10+ years	
	Lighting - Pendent/Surface	4th Floor	28	EΑ	7	10+ years	
	Marker Board	4th Floor	40	LF	6	6-10 years	
	Storage/ Closet	4th Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	2,149	SF	6	10+ years	
	Work Sink	4th Floor	2	EA	7	10+ years	
Classro	om #401 (Store Room)						
	AC Units	4th Floor	2	EA	7	6-10 years	
	Casework	4th Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	863	SF	6	10+ years	
	Doors - Steel Doors incl hw	4th Floor	2	EA	6	10+ years	
	Doors - Transom Window	4th Floor	24	SF	6	10+ years	
	Floor - Wood	4th Floor	863	SF	6	10+ years	
	Lighting - Pendent/Surface	4th Floor	14	EA	7	10+ years	
	Marker Board	4th Floor	37	LF	6	10+ years	
	Storage/ Closet	4th Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	1,323	SF	6	10+ years	
Classro	om #403 (Regular Classroom)						
	AC Units	4th Floor	2	EA	7	6-10 years	
	Casework	4th Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	860	SF	6	10+ years	
	Doors - Transom Window	4th Floor	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	6	10+ years	
	Floor - Wood	4th Floor	860	SF	6	10+ years	
	Lighting - Pendent/Surface	4th Floor	14	EA	7	10+ years	
	Marker Board	4th Floor	48	LF	6	6-10 years	
	Storage/ Closet	4th Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	1,312	SF	6	10+ years	
_Classroo	om #404 (Computer Lab)						
	AC Units	4th Floor	2	EA	7	6-10 years	
	Casework	4th Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	927	SF	6	10+ years	



Cotogo				uildise	. Main		223 N Keeler AVENUE, Chicago, IL 6
Category : Classroom			В	uilding	. wain	December	
Graum	Itam Tuna	Logation	Oughtitus	LICAN	Donle	Recommend	Comments
Group	Item - Type Doors - Transom Window	Location 4th Floor	Quantity	UOM SF	Rank 6	Replacement	Comments
			32	_	-	10+ years	
	Doors - Wood Doors inclu hw	4th Floor	2	EA	7	6-10 years	
	Floor - Wood	4th Floor	927	SF	6	10+ years	
	Lighting - Pendent/Surface	4th Floor	14	EA	7	10+ years	
	Marker Board	4th Floor	24	LF	6	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,371	SF	6	10+ years	
	Wireless System	4th Floor	1	EA	7	10+ years	
Classroo	m #405 (Regular Classroom)						
	AC Units	4th Floor	1	EA	7	6-10 years	
	Casework	4th Floor	6	LF	6	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	860	SF	6	10+ years	
	Doors - Transom Window		32	SF	6	•	
		4th Floor 4th Floor				10+ years	
	Doors - Wood Doors inclu hw		2	EA	6	10+ years	
	Floor - Wood	4th Floor	860	SF	6	10+ years	
	Lighting - Pendent/Surface	4th Floor	14	EA	7	10+ years	
	Marker Board	4th Floor	23	LF	6	6-10 years	
	Storage/ Closet	4th Floor	50	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor	1,312	SF	6	10+ years	
Classroo	m #408 (Store Room)						
	AC Units	4th Floor	2	EA	7	6-10 years	
	Casework	4th Floor	5	LF	6	10+ years	
	Ceiling - Plaster/Drywall	4th Floor	1,119	SF	6	10+ years	
	Doors - Steel Doors incl hw	4th Floor	2	EA	6	10+ years	
	Floor - Wood	4th Floor		SF		,	
			1,119		6	10+ years	
	Lighting - Pendent/Surface	4th Floor	18	EA	7	6-10 years	
	Marker Board	4th Floor	49	LF	7	6-10 years	
	Walls - Plaster/Drywall	4th Floor	1,604	SF	6	10+ years	
	Work Sink	4th Floor	1	EA	7	10+ years	
Catego	ry : Interior		В	uilding	: Main		
	Itama Tima	Lagation	Output!ter	HOM	Dowl	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
orridor							
	Ceiling - Lay-in	1st Floor East Corridor	756	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor East Corridor	600	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor East Corridor	2	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor East Corridor	2	EA	6	10+ years	
	Drinking Fountains - Double Fountain	1st Floor East Corridor	1	EΑ	7	6-10 years	
	Floor - Tile/Sheet	1st Floor East Corridor	1,356	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor East Corridor	25	EA	7	6-10 years	
	Walls - Masonry	1st Floor East Corridor	2,233	SF	7	10+ years	
	a massing	. St. 1881 East Collidor	2,200	٥.		.o. youro	



Category : Interior		В	uilding	: Main			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor East Corridor	1,056	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor South Corridor	728	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor South Corridor	4	EA	6	10+ years	
	Doors - Transom Window	1st Floor South Corridor	60	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor South Corridor	6	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor South Corridor	728	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor South Corridor	7	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor South Corridor	513	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor South Corridor	513	SF	6	10+ years	
	Ceiling - Lay-in	1st Floor West Corridor	756	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor West Corridor	600	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor West Corridor	2	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor West Corridor	1,352	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor West Corridor	4	SF	4	1-2 years	Chipping and uneven
	Lighting - Pendent/Surface	1st Floor West Corridor	25	EA	7	6-10 years	
	Walls - Masonry	1st Floor West Corridor	2,233	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor West Corridor	1,056	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor East Corridor	951	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor East Corridor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor East Corridor	941	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor East Corridor	10	SF	4	1-2 years	Missing tiles
	Lighting - Pendent/Surface	2nd Floor East Corridor	19	EA	7	6-10 years	
	Stairs - Concrete Stairs	2nd Floor East Corridor	18	LF	6	10+ years	
	Walls - Masonry	2nd Floor East Corridor	1,157	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor East Corridor	1,157	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor North Corridor	682	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor North Corridor	3	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor North Corridor	682	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor North Corridor	11	EA	6	6-10 years	
	Walls - Masonry	2nd Floor North Corridor	778	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor North Corridor	778	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor West Corridor	951	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor West Corridor	1	EA	6	10+ years	
	Floor - Tile/Sheet	2nd Floor West Corridor	951	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor West Corridor	19	EA	7	6-10 years	
	Stairs - Concrete Stairs	2nd Floor West Corridor	18	LF	6	10+ years	
	Walls - Masonry	2nd Floor West Corridor	1,157	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor West Corridor	857	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor West Corridor	300	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor East Corridor	951	SF	6	10+ years	
	Doors - Steel Doors incl hw	3rd Floor East Corridor	1	ĒΑ	6	10+ years	
	Floor - Tile/Sheet	3rd Floor East Corridor	948	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor East Corridor	3	SF	5	1-2 years	Chipping
	Lighting - Pendent/Surface	3rd Floor East Corridor	19	EA	6	6-10 years	11 9
	g - g		. •		-	3 12 , 22 0	

Campus Name: Tilton Page : 22 of 42 Assessment Date: 09/18/2023



Catego	Category : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs - Concrete Stairs	3rd Floor East Corridor	18	LF	6	10+ years	
	Student Lockers - One Tier	3rd Floor East Corridor	6	EA	6	10+ years	
	Walls - Masonry	3rd Floor East Corridor	1,157	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor East Corridor	1,157	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor North Corridor	682	SF	6	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor North Corridor	3	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor North Corridor	600	SF	7	6-10 years	Updated to match current observations
	Floor - Tile/Sheet	3rd Floor North Corridor	82	SF	5	1-2 years	Missing, cracking and chipped tiles
	Lighting - Pendent/Surface	3rd Floor North Corridor	11	EA	7	10+ years	5· 5 11
	Student Lockers - One Tier	3rd Floor North Corridor	27	EA	6	10+ years	
	Walls - Masonry	3rd Floor North Corridor	758	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor North Corridor	758	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor West Corridor	951	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor West Corridor	1	ĒΑ	6	10+ years	
	Floor - Tile/Sheet	3rd Floor West Corridor	951	SF	7	10+ years	Updated to match current observations
	Lighting - Pendent/Surface	3rd Floor West Corridor	19	EA	7	6-10 years	
	Stairs - Concrete Stairs	3rd Floor West Corridor	18	LF	7	10+ years	
	Walls - Masonry	3rd Floor West Corridor	1,127	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor West Corridor	1,127	SF	7	10+ years	
	Ceiling - Plaster/Drywall	4th Floor East Corridor	951	SF	7	10+ years	
	Doors - Steel Doors incl hw	4th Floor East Corridor	1	EA	6	10+ years	
	Floor - Tile/Sheet	4th Floor East Corridor	951	SF	7	10+ years	
	Lighting - Pendent/Surface	4th Floor East Corridor	19	EA	7	6-10 years	
	Stairs - Concrete Stairs	4th Floor East Corridor	18	LF	7	10+ years	
	Walls - Masonry	4th Floor East Corridor	1,157	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor East Corridor	1,157	SF	7	10+ years	
	Ceiling - Plaster/Drywall	4th Floor North Corridor	810	SF	6	10+ years	
	Drinking Fountains - Single Fountain	4th Floor North Corridor	3	EA	7	10+ years	Updated quantity
	Floor - Tile/Sheet	4th Floor North Corridor	810	SF	7	10+ years	opadica quantity
	Lighting - Pendent/Surface	4th Floor North Corridor	10	EA	6	6-10 years	
	Student Lockers - One Tier	4th Floor North Corridor	47	EA	6	10+ years	
	Walls - Masonry	4th Floor North Corridor	738	SF	7	10+ years	
	Walls - Plaster/Drywall	4th Floor North Corridor	738	SF	7	10+ years	
	Ceiling - Plaster/Drywall	4th Floor West Corridor	901	SF	6	10+ years	
	Ceiling - Plaster/Drywall	4th Floor West Corridor	50	SF	4	1-2 years	Water damage
	Doors - Steel Doors incl hw	4th Floor West Corridor	1	EA	6	10+ years	Trator damage
	Floor - Tile/Sheet	4th Floor West Corridor	940	SF	7	10+ years	
	Floor - Tile/Sheet	4th Floor West Corridor	11	SF	5	1-2 years	Broken tiles
	Lighting - Pendent/Surface	4th Floor West Corridor	19	EA	7	6-10 years	Dionoli moo
	Stairs - Concrete Stairs	4th Floor West Corridor	18	LF	6	10+ years	
	Student Lockers - One Tier	4th Floor West Corridor	3	EA	7	6-10 years	
	Walls - Masonry	4th Floor West Corridor	1,157	SF	6		
	vvalis - iviasurity	411 FIOOI WEST COITION	1,137	ЭГ	U	10+ years	

Campus Name: Tilton Page : 23 of 42 Assessment Date: 09/18/2023



Catego	ry : Interior		В	uilding	: Main		
			_			Recommend	_
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	4th Floor West Corridor	1,107	SF	6	10+ years	Updated to match current observations
Safety							
•	Camera Viewing Station	Throughout Building	1	EA	7	6-10 years	
	Security Cameras	Throughout Building	16	EA	7	6-10 years	
	Security Cameras	Throughout Building	4	EA	5	6-10 years	
Stairs							
	Ceiling - Plaster/Drywall	North East	253	SF	6	10+ years	
	Floor - Epoxy/ Painted	North East	150	SF	7	10+ years	
	Floor - Tile	North East	200	SF	6	10+ years	
	Handrails	North East	216	LF	7	10+ years	
	Stairs - Asphalt	North East	450	LF	6	6-10 years	Chipping top treads
	Walls - Masonry	North East	956	SF	6	10+ years	
	Walls - Plaster/Drywall	North East	956	SF	6	10+ years	
	Ceiling - Plaster/Drywall	North West	253	SF	6	6-10 years	Updated to match current observations
	Floor - Epoxy/ Painted	North West	150	SF	7	10+ years	
	Floor - Tile	North West	200	SF	6	10+ years	
	Handrails	North West	216	LF	7	10+ years	
	Stairs - Asphalt	North West	450	LF	6	10+ years	
	Walls - Masonry	North West	956	SF	6	10+ years	
	Walls - Plaster/Drywall	North West	956	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South East	253	SF	6	10+ years	
	Floor - Epoxy/ Painted	South East	150	SF	7	10+ years	
	Floor - Tile	South East	200	SF	6	10+ years	
	Handrails	South East	216	LF	7	10+ years	
	Stairs - Asphalt	South East	450	LF	6	10+ years	
	Walls - Masonry	South East	956	SF	6	10+ years	
	Walls - Plaster/Drywall	South East	956	SF	6	10+ years	
	Ceiling - Plaster/Drywall	South West	253	SF	6		
				SF	7	10+ years	
	Floor - Epoxy/ Painted	South West	150		-	10+ years	
	Floor - Tile	South West	200	SF	6	10+ years	
	Handrails	South West	216	LF	7	10+ years	
	Stairs - Asphalt	South West	450	LF	6	10+ years	
	Walls - Masonry	South West	956	SF	6	10+ years	
	Walls - Plaster/Drywall	South West	956	SF	6	10+ years	
ertical (Conveyance						
	Elevator - Elevator- Traction	1st Floor	1	EA	7	10+ years	
	Wheelchair Lift - Platform Lift	1st Floor	1	EA	7	6-10 years	

Campus Name: Tilton Page : 24 of 42 Assessment Date: 09/18/2023



Category : Exterior Building : Addition

Catego	ry : Exterior		Building : Addition_						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Entrance									
	Entrance Control - Audio and Video	1	1	EA	7	10+ years			
	Exterior Doors - Exterior FRP Door	1	3	EA	7	10+ years			
	Exterior Doors - Transom Lite	1	3	EA	7	10+ years			
	Exterior Stairs - Concrete	1	17	LF	6	10+ years			
	Exterior Stairs - Concrete	1	10	LF	5	1-2 years	Cracks at landing and at-top step,		
						•	spalled, brokerages		
	Power Door Operator and Controls	1	1	EA	7	10+ years			
	Ramp Handrail - Steel_Ramp Handrail	1	48	LF	6	10+ years			
	Ramps - Concrete	1	24	LF	6	10+ years			
	Stair Handrail - Steel_Stair Handrail	1	10	LF	6	10+ years			
	Entrance Control - Audio and Video	2	1	EA	7	10+ years			
	Exterior Doors - Exterior FRP Door	2	3	EA	7	10+ years			
	Exterior Stairs - Concrete	2	12	LF	7	10+ years			
	Ramp Handrail - Steel_Ramp Handrail	2	35	LF	7	10+ years			
	Ramps - Concrete	2	20	LF	5	1-2 years	Cracks in the concrete ramp		
	Stair Handrail - Steel_Stair Handrail	2	6	LF	7	10+ years			
	Entrance Control - Audio and Video	3	1	EA	7	6-10 years			
	Exterior Doors - Exterior FRP Door	3	2	EA	7	10+ years			
	Exterior Stairs - Concrete	3	6	LF	6	10+ years			
	Exterior Doors - Exterior FRP Door	Yard Storage	1	EA	7	10+ years			
	Exterior Deorg Exterior Fixt Deor	Tara Clorage	·	L/\	'	101 years			
Foundati	on								
ounuau	Foundation - Concrete	Entire Building	459	LF	7	10+ years			
	Foundation - Concrete	Entire Building	15	LF	5	2-5 years	Minor cracks, clean and patch		
				SF	5 7		willor cracks, clean and paten		
	Superstructure - Metal Deck/ Concrete	Entire Building	27,218	SF	1	10+ years			
	Topping								
iahtina									
ighting	Exterior Lighting - Parapet or Roof Mounted	Main Roof	6	EA	6	10. voore			
	Exterior Lighting - Parapet of Roof Mounted Exterior Lighting - Wall Mounted	Main Roof	9	EA	6	10+ years 10+ years			
	Exterior Lighting - Wall Mounted	Main Nooi	9	LA	O	10+ years			
Roof Sys	tem								
Cys	Access Ladder - Metal	E	2	EA	7	10+ years			
	Coping - Metal	E	466	LF	7	10+ years			
	Downspouts - Interior Downspouts	E	74	LF	6	10+ years			
	Parapet - Parapet < 16" Height	E	466	LF	7	10+ years			
	Roof - Modified Bitumen	E	3,458	SF	7	10+ years	New		
		E	3, 4 56	EA			INCW		
	Roof Hatch - Metal		•		7	10+ years	Now		
	Roof Hatch - Metal	E	1	EA SF	7 7	10+ years	New		
	Roof Structure - Steel / Metal Deck/	E	3,458	21	1	10+ years			
	Concrete Topping								



Categoi	ry : Exterior		В	uilding	: Additi	on	
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Access Ladder - Metal	F	1	EA	7	10+ years	
	Coping - Metal	F	44	LF	7	10+ years	
	Downspouts - Exterior Downspouts	F	25	LF	7	10+ years	
	Parapet - Parapet < 16" Height	F	44	LF	7	10+ years	
	Roof - Modified Bitumen	F	121	SF	6	10+ years	
	Roof Structure - Steel / Metal Deck/	F	121	SF	7	10+ years	
	Concrete Topping					·	
	Coping - Metal	G	168	LF	7	10+ years	
	Downspouts - Interior Downspouts	G	24	LF	6	10+ years	
	Parapet - Parapet < 16" Height	G	168	LF	7	10+ years	
	Roof - Modified Bitumen	G	1,900	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Ğ	1,900	SF	7	10+ years	
	Concrete Topping		,			, , , , ,	
Walls							
	Canopy - Concrete/ Stucco	Entire Building	60	SF	6	10+ years	
	Canopy - Concrete/ Stucco	Entire Building	16	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	15,359	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	4	SF	4	0-1 year	Cracked brick
Windows							
	Guard - Guards perforated	Entire Building	1,815	SF	6	10+ years	
	Lintels - Steel	Entire Building	668	LF	6	10+ years	
	Windows - Casement Aluminum Double- pane	Entire Building	33	SF	6	10+ years	
	Windows - Decorative	Entire Building	761	SF	6	10+ years	
	Windows - Insulated Panel	Entire Building	176	SF	6	10+ years	
	Windows - Louver	Entire Building	76	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	3,186	SF	6	10+ years	
Catogo	ry : Electrical	-	B	uildina	: Additi	on	
Categoi	y . Liectricai			unung	. Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank		Comments
Emergen	cy System						
	Exit Signs - Corridors and Stairs	Entire Building	15	EA	4	2-5 years	Over 20 years old with incandescent bulbs
	Exit Signs - Lunchroom	Entire Building	2	EA	4	2-5 years	Over 20 years old with incandescent bulbs
	Emergency A/C Power - Corridors and Stairs	Entire Building	6,856	SF	6	6-10 years	Mild
	Emergency A/C Power - Lunchrooms	Entire Building	2,327	SF	6	6-10 years	
	Security System - CCTV	Entire Building	27,218	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	27,218	SF	6	2-5 years	
		Ÿ				-	



Main Servic F Power Distr L L L	ribution Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building	Quantity 27,218	UOM SF	Rank 6	Recommend Replacement	Comments
Main Servic F Power Distr L L L L	ribution Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building	•				Comments
P <u>ower Distr</u> L L L L	ribution Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building	27,218	SF	6		
Power Distr L L L L	ribution Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building	27,218	SF	6		
Power Distr L L L L	ribution Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building	21,218	5F	ю	O F	
L L L	Lighting and Power Panels - 100 A Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A					2-5 years	
L L	Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A						
L L	Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A		1	EA	7	10+ years	
L	ighting and Power Panels - Above 100 A	Entire Building	2	EΑ	6	2-5 years	
L		Entire Building	2	ΕA	7	10+ years	
2-4	ighting and Power Panels - Above 100 A	Entire Building	5	EA	6	2-5 years	
		· ·	.	!!!!	. A .1.1!4!	-	
ategory	: Fire Protection		В	ullaing	: Additio	n Recommend	
Group It	tem - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alarm							
	Fire Alarm Strobe Lights	Entire Building	27,218	SF	6	6-10 years	
F	Fire Alarm_System	Entire Building	27,218	SF	6	6-10 years	
Category	: Mechanical		В	uildina	: Additio	on	
			_			Recommend	
Group It	tem - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler Syste							
C	Condensate Pump	Entire Building	1	EA	3	0-1 year	Tank and piping heavily corroded pump needs repairs
(Condonanta Dumn	Entire Building	1	EA	2	0.1.400	
(Condensate Pump	Entire Building	ı	EA	3	0-1 year	Tank and piping heavily corroded pump needs repairs
F	Piping - Condensate Pipe- Steel	Entire Building	400	LF	6	2-5 years	pamp needs repaire
	Piping - Steam Pipe- Steel	Entire Building	400	LF	6	2-5 years	
	Steam Traps	Entire Building	45	EA	4	2-5 years	A lot are not working properly per
	Steam Traps	Entire Building	45	LA	4	2-5 years	engineer
\	/acuum Pump	Entire Building	2	EA	3	0-1 year	Tank and piping heavily corroded
v	vacaum i amp	Entire Ballating	2		J	o i yeai	pump needs repairs
							. r
Heating De							
	Fin Tube - Steam	1st Floor	5	LF	5	2-5 years	- ···
_	Cabinet Heaters - With Electric Coil	Entire Building	6	EA	6	6-10 years	Ceiling mounted
_	Cabinet Heaters - With Steam Coil	Entire Building	18	EA	5	2-5 years	
V	Wall Heater - Electric	Entire Building	8	EA	6	6-10 years	
<u> Temperatur</u>	re Control						
	DDC System	Entire Building	27,218	SF	2	0-1 year	Not operational
	Fhermostats - DDC	Entire Building	21	EA	4	0-1 year	Not operational

Campus Name: Tilton Page : 27 of 42 Assessment Date: 09/18/2023



Catego	ry : Mechanical		В	uilding	: Additi	on	223 N Reelel AVENUE, Chicago, IL 0002-
Calogo	, y i moonamoui		_	uag	. ,	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	21	EA	5	2-5 years	
Ventilation	on						
	Exhaust Fans- Indoor - Less than 500 CFM Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building Entire Building	1 3	EA EA	6 6	10+ years 6-10 years	
	CFM Exhaust Fans- Roof Mounted - 1501 - 8000	Entire Building	4	EA	6	6-10 years	
	CFM Exhaust Fans- Roof Mounted - Less than	Entire Building	1	EA	6	6-10 years	
	500 CFM Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	
Catego	ry : Plumbing		В	uilding	: Additi	on	
	•					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	27,218	SF	4	2-5 years	A few pipe clamps, deteriorating insulation in some areas
	Domestic Piping-Hot Water Return Risers	Entire Building	27,218	SF	4	2-5 years	A few pipe clamps, deteriorating insulation in some areas
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	27,218	SF	4	2-5 years	A few pipe clamps, deteriorating insulation in some areas
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	27,218	SF	4	2-5 years	A few pipe clamps, deteriorating insulation in some areas
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	27,218	SF	4	2-5 years	A few pipe clamps, deteriorating insulation in some areas
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	27,218	SF	4	2-5 years	A few pipe clamps, deteriorating insulation in some areas
	Sanitary Piping	Entire Building	27,218	SF	5	2-5 years	
	Storm Piping	Entire Building	27,218	SF	5	2-5 years	
	Vent Piping	Entire Building	27,218	SF	5	2-5 years	
Pumps							
	Pumps - Sump-Duplex	Crawl Space	1	EA	4	1-2 years	Piping corroding and pumps not keeping up with heavy flow
	Pumps - Sump-Simplex	Crawl Space	1	EA	6	2-5 years	

Campus Name: Tilton Page : 28 of 42 Assessment Date: 09/18/2023



Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Froup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
dminist	rative Suites/Offices						
	AC Unit	110 Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	110 Main Office	411	SF	6	10+ years	
	Doors - Side-lite	110 Main Office	50	SF	6	10+ years	
	Doors - Transom Window	110 Main Office	6	SF	6	10+ years	
	Doors - Wood Doors inclu hw	110 Main Office	2	EA	6	10+ years	
	Floor - Tile	110 Main Office	411	SF	6	6-10 years	
	Lighting - Pendent/Surface	110 Main Office	6	EA	7	6-10 years	
	Power Distribution	110 Main Office	8	EA	6	6-10 years	
	Storage/ Closet	110 Main Office	20	SF	7	10+ years	
	Walls - Concrete Block	110 Main Office	632	SF	6	10+ years	
	AC Unit	110A Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	110A Principal's Office	157	SF	6	10+ years	
	Doors - Steel Doors incl hw	110A Principal's Office	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	110A Principal's Office	1	EA	6	10+ years	
	Floor - Tile	110A Principal's Office	157	SF	6	6-10 years	
	Lighting - Pendent/Surface	110A Principal's Office	2	EA	7	6-10 years	
	Power Distribution	110A Principal's Office	4	EA	6	6-10 years	
	Storage/ Closet	110A Principal's Office	6	SF	7	10+ years	
	Walls - Concrete Block	110A Principal's Office	369	SF	6	10+ years	
	AC Unit	110B Assistant Principal's Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	110B Assistant Principal's Office	364	SF	6	10+ years	
	Doors - Wood Doors inclu hw	110B Assistant Principal's Office	1	EA	6	6-10 years	
	Floor - Tile	110B Assistant Principal's Office	364	SF	6	10+ years	
	Lighting - Pendent/Surface	110B Assistant Principal's Office	6	EA	6	6-10 years	
	Power Distribution	110B Assistant Principal's Office	6	EA	6	6-10 years	
	Storage/ Closet	110B Assistant Principal's Office	4	SF	7	10+ years	
	Walls - Concrete Block	110B Assistant Principal's Office	662	SF	7	10+ years	
	AC Unit	114 Administration Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	114 Administration Office	965	SF	7	10+ years	
	Doors - Wood Doors inclu hw	114 Administration Office	2	EA	6	10+ years	
	Floor - Carpet	114 Administration Office	424	SF	6	6-10 years	
	Floor - Tile	114 Administration Office	541	SF	6	6-10 years	
	Lighting - Pendent/Surface	114 Administration Office	23	EA	7	6-10 years	
	Power Distribution	114 Administration Office	44	EA	7	6-10 years	
	Storage/ Closet	114 Administration Office	48	SF	7	10+ years	
	Walls - Concrete Block	114 Administration Office	960	SF	7	10+ years	
	AC Unit	209 Principal's Second Office	1	EA	5	6-10 years	
	Ceiling - Plaster/Drywall	209 Principal's Second Office	306	SF	6	10+ years	
	Doors - Wood Doors inclu hw	209 Principal's Second Office	1	EA	6	10+ years	
	Floor - Tile	209 Principal's Second Office	306	SF	6	10+ years	
	Lighting - Pendent/Surface	209 Principal's Second Office	4	EA	7	6-10 years	
	Power Distribution	209 Principal's Second Office	4	EA	6	6-10 years	
	Walls - Concrete Block	209 Principal's Second Office	598	SF	7	10+ years	

Campus Name: Tilton Page : 29 of 42 Assessment Date: 09/18/2023



Catego	ry : Room		Building : Addition						
	_					Recommend	_		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Ceiling - Plaster/Drywall	215	5	SF	7	10+ years			
	Ceiling - Plaster/Drywall	215	261	SF	6	10+ years			
	Doors - Steel Doors incl hw	215	1	EA	6	10+ years			
	Floor - Tile	215	254	SF	6	10+ years			
	Floor - Tile	215	6	SF	4	0-1 year	Chipped and missing tile		
	Lighting - Pendent/Surface	215	4	EA	7	6-10 years			
	Power Distribution	215	5	EA	6	6-10 years			
	Walls - Concrete Block	215	611	SF	7	10+ years			
	AC Unit	309 Teachers Lounge/Office	1	EA	7	10+ years			
	Ceiling - Plaster/Drywall	309 Teachers Lounge/Office	305	SF	6	10+ years			
	Doors - Wood Doors inclu hw	309 Teachers Lounge/Office	2	EA	6	10+ years			
	Floor - Tile	309 Teachers Lounge/Office	5	SF	6	10+ years			
	Floor - Tile	309 Teachers Lounge/Office	300	SF	6	10+ years			
	Lighting - Pendent/Surface	309 Teachers Lounge/Office	4	ĒA	7	6-10 years			
	Power Distribution	309 Teachers Lounge/Office	4	EA	6	6-10 years			
	Walls - Concrete Block	309 Teachers Lounge/Office	576	SF	7	10+ years			
	7.4 20.10.10.10 2.100.11	555 . 5555 <u>_</u> 5545	0.0	Ο.	-	.o. yea.e			
Kitchen									
	Ceiling - Plaster/Drywall	1st Floor	452	SF	6	10+ years			
	Doors - Steel Doors incl hw	1st Floor	2	EA	6	10+ years			
	Floor - Tile	1st Floor	100	SF	4	0-1 year	Worn and cracking		
	Floor - Tile Quarry	1st Floor	352	SF	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years			
	Serving Line	1st Floor	26	LF	7	10+ years			
	Storage/ Closet	1st Floor	254	SF	7	10+ years			
	Walls - Concrete Block	1st Floor	100	SF	6	10+ years			
	Walls - Structural Glazed Tile	1st Floor	545	SF	6	10+ years			
Lunch &	Multipurpose Room								
	Ceiling - Plaster/Drywall	132	2,327	SF	6	10+ years			
	Doors - Wood Doors inclu hw	132	2,027	EA	6	10+ years			
	Floor - Tile	132	2,281	SF	6	10+ years			
	Floor - Tile	132	46	SF	4	0-1 year	Chipped and cracking throughout.		
	TIOOT - THE	102	40	Oi	7	0-1 year	Quantity updated to match current observations		
	Lighting - Pendent/Surface	132	64	EA	7	10+ years	ODSEI VALIOUS		
	Walls - Concrete Block	132	1,334	SF	7	10+ years 10+ years			
	vvalis - Culicièle Bluck	192	1,334	ЭF	/	10+ years			
Mechani	cal/ Service Rooms								
	Janitor's Closet	1st Floor	37	SF	5	10+ years	Floor missing		
	Vaults	1st Floor	37	SF	5	10+ years	-		
	Janitor's Closet	2nd Floor	38	SF	5	1-2 years	Flooring missing, water damage on		

Campus Name: Tilton Page : 30 of 42 Assessment Date: 09/18/2023



Catego	Category : Room			Building : Addition					
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
•	Janitor's Closet	3rd Floor	38	SF	5	10+ years	Flooring damaged		
	Storage Room	3rd Floor	263	SF	7	10+ years			
estroo	n								
ESI100	Accessories	112A	38	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	112A	38	SF	6	10+ years			
	Doors - Wood Doors inclu hw	112A	1	EA	6	10+ years			
	Floor - Tile	112A	38	SF	7	6-10 years	Deficiency fixed		
	Lavatory	112A	1	EA	6	10+ years	Bonoloney hadd		
	Lighting - Pendent/Surface	112A	i	EA	6	6-10 years			
	Walls - Concrete Block	112A	182	SF	6	10+ years			
	Water Closet	112A 112A	102	EA	7	10+ years			
	Accessories	112A 114A	38	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	114A 114A	38	SF	6	-			
	Doors - Wood Doors inclu hw			EA		10+ years			
		114A	1		6	10+ years			
	Floor - Tile	114A	38	SF	6	10+ years			
	Lavatory	114A	1	EA	6	10+ years			
	Lighting - Pendent/Surface	114A	1	EA	7	6-10 years			
	Walls - Concrete Block	114A	182	SF	7	10+ years			
	Water Closet	114A	1	EA	6	10+ years			
	Accessories	1st Floor	230	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	230	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	230	SF	6	10+ years			
	Floor Drain	1st Floor	1	EA	7	10+ years			
	Hand Dryer	1st Floor	1	EA	7	6-10 years			
	Lavatory	1st Floor	3	EA	6	10+ years			
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years			
	Partitions	1st Floor	3	EA	5	10+ years			
	Walls - Structural Glazed Tile	1st Floor	555	SF	6	10+ years			
	Water Closet	1st Floor	3	EA	7	10+ years			
	Accessories	1st Floor	184	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	184	SF	6	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	184	SF	6	10+ years			
	Floor Drain	1st Floor	1	EΑ	7	10+ years			
	Hand Dryer	1st Floor	1	EA	7	6-10 years			
	Lavatory	1st Floor	2	EΑ	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years			
	Partitions	1st Floor	2	EA	7	10+ years			
	Urinals	1st Floor	1	EA	6	1-2 years	Constantly running		
	Urinals	1st Floor	3	EA	6	10+ years	Constantly running		
	Walls - Structural Glazed Tile			SF	6	•			
		1st Floor	521			10+ years			
	Water Closet	1st Floor	2	EA	6	10+ years			



Catego	ry : Room		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Accessories	1st Floor Kitchen Womens	74	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor Kitchen Womens	74	SF	7	10+ years			
	Doors - Steel Doors incl hw	1st Floor Kitchen Womens	_1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor Kitchen Womens	74	SF	6	10+ years			
	Lavatory	1st Floor Kitchen Womens	1	EA	6	10+ years			
	Lighting - Pendent/Surface	1st Floor Kitchen Womens	1	EA	6	6-10 years			
	Lighting - Wall Mounted	1st Floor Kitchen Womens	1	EA	7	6-10 years			
	Partitions	1st Floor Kitchen Womens	1	EA	5	10+ years			
	Student Lockers - One Tier	1st Floor Kitchen Womens	4	EA	5	6-10 years			
	Walls - Concrete Block	1st Floor Kitchen Womens	327	SF	5	1-2 years	Cracks throughout		
	Water Closet	1st Floor Kitchen Womens	1	EA	6	10+ years			
	Accessories	1st Floor Unisex	37	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor Unisex	37	SF	5	1-2 years	Water damage and cracking paint		
	Doors - Steel Doors incl hw	1st Floor Unisex	1	EA	6	10+ years			
	Floor - Tile	1st Floor Unisex	37	SF	6	10+ years			
	Lavatory	1st Floor Unisex	1	EA	6	10+ years			
	Lighting - Lay-in	1st Floor Unisex	1	EΑ	7	6-10 years			
	Lighting - Wall Mounted	1st Floor Unisex	1	EA	7	6-10 years			
	Walls - Concrete Block	1st Floor Unisex	173	SF	6	10+ years			
	Water Closet	1st Floor Unisex	1	EA	6	10+ years			
	Accessories	209A Principal's Toilet	52	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	209A Principal's Toilet	52	SF	6	10+ years			
	Doors - Wood Doors inclu hw	209A Principal's Toilet	1	EA	6	10+ years			
	Floor - Tile	209A Principal's Toilet	52	SF	6	10+ years			
	Lavatory	209A Principal's Toilet	1	EΑ	6	10+ years			
	Lighting - Lay-in	209A Principal's Toilet	1	EA EA	7 7	6-10 years			
	Lighting - Wall Mounted Partitions	209A Principal's Toilet	1	EA	, 5	6-10 years			
	Walls - Concrete Block	209A Principal's Toilet	206	SF	5 7	10+ years			
	Walls - Concrete Block	209A Principal's Toilet 209A Principal's Toilet		SF SF	4	10+ years	Uele		
	Water Closet	209A Principal's Toilet	3	Sr EA	7	0-1 year	Hole.		
	Accessories	209A Fillicipal's Tollet 2nd Floor	248	SF	7	10+ years 6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	248	SF	6	10+ years			
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	2nd Floor	248	SF	6	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Hand Dryer	2nd Floor	1	EA	7	6-10 years			
	Lavatory	2nd Floor	3	EA	6	10+ years			
	Lighting - Pendent/Surface	2nd Floor	5	EA	7	6-10 years			
	Partitions	2nd Floor	2	EA	7	10+ years			
	Urinals	2nd Floor	3	EA	6	10+ years			
	Walls - Structural Glazed Tile	2nd Floor	588	SF	6	10+ years			
	Water Closet	2nd Floor	2	EA	6	10+ years			
	Accessories	2nd Floor	315	SF	7	6-10 years			
	. 1000001100	2113 1 1501	010	٥.	•	o lo youlo			

Campus Name: Tilton Page : 32 of 42 Assessment Date: 09/18/2023



ategory : Room			В	uilding	: Addition	on	
_				_		Recommend	
up	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	2nd Floor	315	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	315	SF	6	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	1	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years	
	Partitions	2nd Floor	3	EΑ	5	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	667	SF	7	10+ years	
	Water Closet	2nd Floor	3	EA	6	10+ years	
	Accessories	2nd Floor Unisex - inaccessible,	36	SF	7	10+ years	
	Accessories	abatement needed	30	31	,	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor Unisex - inaccessible,	36	SF	6	10 L VOORO	
	Ceiling - Plaster/Drywaii		30	SF	О	10+ years	
	Daniel Ward Danielinekoko	abatement needed	4	^	^	40	
	Doors - Wood Doors inclu hw	2nd Floor Unisex - inaccessible,	1	EA	6	10+ years	
	E. T.	abatement needed		0.5		0.4	
	Floor - Tile	2nd Floor Unisex - inaccessible,	36	SF	4	0-1 year	Missing/damaged flooring, needs
		abatement needed					abatement, no access
	Lavatory	2nd Floor Unisex - inaccessible,	1	EA	6	10+ years	
		abatement needed					
	Lighting - Lay-in	2nd Floor Unisex - inaccessible,	1	EA	7	6-10 years	
		abatement needed					
	Lighting - Wall Mounted	2nd Floor Unisex - inaccessible,	1	EA	7	6-10 years	
		abatement needed					
	Partitions	2nd Floor Unisex - inaccessible,	1	EA	5	10+ years	
		abatement needed				•	
	Walls - Concrete Block	2nd Floor Unisex - inaccessible,	171	SF	7	10+ years	
		abatement needed				,	
	Water Closet	2nd Floor Unisex - inaccessible,	1	EA	4	0-1 year	Out of order
		abatement needed			•	· , , · · ·	
	Accessories	309A Teachers Lounge Toilet	52	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	309A Teachers Lounge Toilet	52	SF	6	10+ years	
	Doors - Wood Doors inclu hw	309A Teachers Lounge Toilet	1	EA	6	10+ years	
	Floor - Tile	309A Teachers Lounge Toilet	52	SF	6	10+ years	
	Lavatory	309A Teachers Lounge Toilet	1	EA	6	10+ years	
	Lighting - Lay-in	309A Teachers Lounge Toilet	1	EA	7	6-10 years	
	Lighting - Wall Mounted	309A Teachers Lounge Toilet	1	EA	7	6-10 years	
	Partitions	309A Teachers Lounge Toilet	1	EA	7	-	Undated to match ourrant
	Partitions	309A Teachers Lounge Tollet	1	EA	1	10+ years	Updated to match current
	Walla Canarata Black	2004 Tacabara Launga Tailat	200	C.E.	6	10	observations
	Walls - Concrete Block	309A Teachers Lounge Toilet	206	SF	6	10+ years	Liele through CMIL equals =
	Walls - Concrete Block	309A Teachers Lounge Toilet	3	SF	4	0-1 year	Hole through CMU, causing
	\\/-t-= Olt	000A T		- ^	^	40	ventilation issues
	Water Closet	309A Teachers Lounge Toilet	1	EA	6	10+ years	
	Accessories	3rd Floor	248	SF	7	6-10 years	

Campus Name: Tilton Page : 33 of 42 Assessment Date: 09/18/2023



ategory : Room		В	uilding	: Additi	on		
						Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Ceiling - Plaster/Drywall	3rd Floor	248	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	248	SF	6	10+ years	
	Floor Drain	3rd Floor	1	EA	7	10+ years	
	Hand Dryer	3rd Floor	1	EA	7	6-10 years	
	Lavatory	3rd Floor	3	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	5	EA	7	6-10 years	
	Partitions	3rd Floor	2	EA	7	10+ years	
	Urinals	3rd Floor	3	EA	6	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	588	SF	6	10+ years	
	Water Closet	3rd Floor	2	EA	6	10+ years	
	Accessories	3rd Floor	315	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	315	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd Floor	315	SF	6	10+ years	
	Floor Drain	3rd Floor	1	ĒΑ	7	10+ years	
	Hand Dryer	3rd Floor	1	EA	7	6-10 years	
	Lavatory	3rd Floor	3	EA	6	10+ years	Updated quantity
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	6-10 years	op and a quantity
	Partitions	3rd Floor	3	ĒΑ	7	10+ years	Updated to match current
		0.0.1.00.	· ·		•	.o. you.o	observations
	Walls - Structural Glazed Tile	3rd Floor	662	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	5	SF	5	1-2 years	Chipping, cracking tiles
	Water Closet	3rd Floor	3	EA	6	10+ years	ompania, ordoning moo
	Accessories	3rd Floor Unisex	36	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor Unisex	36	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor Unisex	1	EA	6	10+ years	
	Floor - Tile	3rd Floor Unisex	36	SF	6	10+ years	
	Lavatory	3rd Floor Unisex	1	EA	6	10+ years	
	Lighting - Lay-in	3rd Floor Unisex	1	EA	7	6-10 years	
	Lighting - Lay-in	3rd Floor Unisex	1	EA	7	6-10 years	
	Partitions	3rd Floor Unisex	1	EA	7	10+ years	Updated to match current
	raittions	Station offisex	ı	LA	,	10+ years	observations
	Walls - Concrete Block	3rd Floor Unisex	171	SF	7	10+ years	ODSCI VALIONS
	Water Closet	3rd Floor Unisex 3rd Floor Unisex	171	Sr EA	6	10+ years 10+ years	
	Accessories	Main Office Toilet	42	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Main Office Toilet	42	SF SF	7	•	
	Doors - Steel Doors incl hw	Main Office Toilet Main Office Toilet		SF EA		10+ years	
	Floor - Tile	Main Office Toilet Main Office Toilet	1 42	SF	6	10+ years	Worn cracking and concreting
					4	0-1 year	Worn, cracking, and separating
	Lavatory	Main Office Toilet	1	EΑ	6	10+ years	
	Lighting - Pendent/Surface	Main Office Toilet	1	EA	7	6-10 years	
	Walls - Concrete Block	Main Office Toilet	186	SF	6	10+ years	
	Water Closet	Main Office Toilet	1	EA	6	10+ years	

Page : 34 of 42 Campus Name: Tilton Assessment Date: 09/18/2023



Catego	ry : Classroom		В	uilding	: Additi	on	223 W Reciei Avenoe, Officago, le 00024
.				9		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #112 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	12	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	965	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	965	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	23	EA	7	6-10 years	
	Marker Board	1st Floor	8	LF	7	6-10 years	
	Storage/ Closet	1st Floor	48	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	960	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
_Classroo	om #208 (Regular Classroom)						
<u> </u>	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	718	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	718	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	890	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #210 (Kindergarten)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	718	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	718	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	890	SF	7	10+ years	
_Classroo	om #211 (Computer Lab)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	726	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	726	SF	6	6-10 years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	36	SF	7	10+ years	

Campus Name: Tilton Page : 35 of 42 Assessment Date: 09/18/2023



Category : Classroom		B	uilding				
				Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Concrete Block	2nd Floor	896	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	10+ years	
Classroo	m #212 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	15	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	6	10+ years	
	Floor - Tile	2nd Floor	720	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	40	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	892	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	m #214 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	720	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	6	10+ years	
	Floor - Tile	2nd Floor	720	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	ĒΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	892	SF	7	10+ years	
Classroo	m #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	12	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	718	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒA	6	10+ years	
	Floor - Tile	3rd Floor	708	SF	6	10+ years	
	Floor - Tile	3rd Floor	10	SF	5	1-2 years	Missing tiles
	Lighting - Pendent/Surface	3rd Floor	16	ĒΑ	7	6-10 years	gg
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	890	SF	7	10+ years	
	Work Sink	3rd Floor	2	EA	7	10+ years	
Classroo	m #310 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	13	LF	6	10+ years	
			10		-		



Catego	Category : Classroom		В	uilding	: Additi	ZZO W NOCIOI WYZINOE, Omougo, iz 66024	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	3rd Floor	1	EΑ	6	10+ years	
	Floor - Tile	3rd Floor	718	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	890	SF	7	10+ years	
_Classroo	om #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	13	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	726	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	720	SF	6	6-10 years	
	Floor - Tile	3rd Floor	6	SF	5	1-2 years	Chipping
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	896	SF	7	10+ years	
_Classroo	om #312 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	716	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	716	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	889	SF	7	10+ years	
	Work Sink	3rd Floor	1	EA	7	10+ years	
_Classroo	om #314 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	13	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	733	SF	6	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	6	10+ years	
	Floor - Tile	3rd Floor	697	SF	6	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	36	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	875	SF	7	10+ years	
	200000000000000000000000000000000000000	0.0	0.0		•	,	

Campus Name: Tilton Page : 37 of 42 Assessment Date: 09/18/2023



Catego	ry : Interior		В	uilding	: Additi	-	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor - East/west	915	SF	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor - East/west	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor - East/west	915	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - East/west	7	EA	7	10+ years	
	Walls - Concrete Block	1st Floor - East/west	1,730	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - North/South	494	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor - North/South	1,857	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor - North/South	11	EA	6	10+ years	
	Doors - Wood Doors include hw	1st Floor - North/South	4	EA	6	10+ years	
	Drinking Fountains - Single Fountain	1st Floor - North/South	2	EA	7	10+ years	
	Floor - Terrazzo	1st Floor - North/South	494	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor - North/South	1,857	SF	7	10+ years	
	Lighting - Lay-in	1st Floor - North/South	8	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor - North/South	21	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor - North/South	885	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor - North/South	2,655	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	1,593	SF	6	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	2	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	121	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,472	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	10+ years	
	Stairs - Terrazzo	2nd Floor	56	LF	6	10+ years	
	Student Lockers - One Tier	2nd Floor	4	EA	6	10+ years	
	Student Lockers - Two Tiers	2nd Floor	34	EA	6	10+ years	
	Walls - Concrete Block	2nd Floor	625	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	1,876	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	121	SF SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	1,472	SF EA	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	2	SF	7	10+ years	
	Floor - Terrazzo Floor - Tile/Sheet	3rd Floor 3rd Floor	121 1,472	SF SF	6 7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	1,472	Sr EA	7 7	10+ years 6-10 years	
	Stairs - Terrazzo	3rd Floor	56	LF	6	•	
	Student Lockers - One Tier	3rd Floor	3	EA	6	10+ years 10+ years	
	Student Lockers - One Tier Student Lockers - Two Tiers	3rd Floor	32	EA	6	10+ years	
	Walls - Concrete Block	3rd Floor	625	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	1,876	SF	6	10+ years	
	Trails Stradiara Siazou Tilo	5.4 (100)	1,070	51	J	ioi youis	
Safety							
	Camera Viewing Station	Throughout Building	1	EA	7	6-10 years	
	Metal Detector	Throughout Building	1	EA	7	10+ years	
	Security Cameras	Throughout Building	5	EA	7	6-10 years	
	-	-				•	

Campus Name: Tilton Page : 38 of 42 Assessment Date: 09/18/2023



Catego	Category : Interior			uilding	, , , , , , , , , , , , , , , , , , , ,		
0	Hann Time	Langtion	Overetter	LIOM	Donk	Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Stairs	0.11. 51. (5. 11.						
	Ceiling - Plaster/Drywall	North	258	SF	7	10+ years	
	Floor - Terrazzo	North	318	SF	6	10+ years	
	Handrails	North	100	LF	7	10+ years	
	Lighting - Pendent/Surface	North	5	EΑ	7	10+ years	
	Lighting - Wall Mounted	North	2	EA	7	10+ years	
	Stairs - Terrazzo	North	189	LF	6	10+ years	
	Walls - Concrete Block	North	630	SF	7	10+ years	
	Walls - Structural Glazed Tile	North	630	SF	7	10+ years	
	Ceiling - Lay-in	West	434	SF	6	10+ years	
	Floor - Terrazzo	West	532	SF	6	10+ years	
	Handrails	West	112	LF	7	10+ years	
	Lighting - Lay-in	West	6	EA	7	10+ years	
	Lighting - Wall Mounted	West	5	EA	7	10+ years	
	Stairs - Terrazzo	West	168	LF	6	10+ years	
	Walls - Concrete Block	West	2,941	SF	6	10+ years	
Vertical	Convevance						
	Elevator - Hydraulic Elevator	1st Floor	1	EA	7	10+ years	

Campus Name: Tilton Page : 39 of 42 Assessment Date: 09/18/2023



Category : Site Building : Site

0							
			0			Recommend	•
•	tem - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Draina							
C	Civil/ Drainage - Catch Basin	Entire Site	3	EA	6	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	14	EA	6	10+ years	
	3					,	
Fencing							
	Fencing - Chain Link	Entire Site	220	LF	7	10 L VOORO	
		Entire Site		LF		10+ years	
	Fencing - Chain Link		52		6	10+ years	Dualiza tan mil
	encing - Chain Link	Entire Site	8	LF	5	1-2 years	Broken top rail
	Fencing - Guard Rail	Entire Site	48	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	770	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	10	LF	6	10+ years	Item Not seen in this visit
F	Fencing - Wood Fencing w/ Steel Frame	Entire Site	70	LF	6	10+ years	
Landagana							
Landscape B	Benches	Entire Site	1	EA	7	10+ years	
	andscape - Grass	Entire Site	6,380	SF	7	10+ years	
	andscape - Hardscape- Asphalt	Entire Site	900	SF	4	2-5 years	Uneven, poor condition
	andscape - Hardscape - Concrete	Entire Site	5,324	SF	6	10+ years	oneven, poor condition
ī	andscape - Hardscape- Concrete	Entire Site	600	SF	4	0-1 year	Broken,cracked concrete
	andscape - Hardscape- Concrete	Entire Site	1,500	SF	7	10+ years	Brokeri, cracked concrete
	Parkway trees	Entire Site	21	EA	7	10+ years	
			21		4		Missing trace, some new
	Parkway trees	Entire Site	1	EA	•	0-1 year	Missing trees, some new
	Planting Beds/ Area	Entire Site	850	SF	7	10+ years	A1 (C. 1.1)
	Play Area - Hardscape- Asphalt	Entire Site	9,450	SF	7	10+ years	New,verified dimension
	Play Area - Synthetic Turf	Entire Site	2,500	SF	7	10+ years	
I	Frash Receptacles	Entire Site	7	EA	7	10+ years	
Parking Lot	•						
Č	Concrete Curbs	North	99	LF	7	10+ years	
S	Surface - Asphalt	North	7,475	SF	4	0-1 year	Alligatored, disintegrated surface, potholes
S	Surface - Concrete	North	11,072	SF	6	6-10 years	•
	Surface - Concrete	North	200	SF	5	1-2 years	Large pothole, disintegrated, spalling
т	Frash Enclosure - Chain Links	North	520	SF	7	10+ years	surface
	/ehicular Screening	North	50	LF	6	10+ years	
V	Tornodial Goreening	140141	30	LI	U	10+ years	
Playground	<u> </u>						
	Equipment - Combo 3-12	North	1	EA	7	10+ years	
S	Surface - Poured Surface	North	2,600	SF	6	10+ years	
	Equipment - Pre K 3-5	South	1	EA	7	10+ years	
	Surface - Poured Surface	South	1,600	SF	7	10+ years	
						•	



Catego	ry : Site	В	uilding				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Sidewall	KS.						
	Sidewalks - Internal Walks	Entire Site	20	LF	5	1-2 years	Broken concrete, large cracks
	Sidewalks - Perimeter Sidewalks	Entire Site	23,039	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	300	SF	4	0-1 year	Upheaved, cracked
Signage							
0 0	Flag Pole - Building Mounted Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Tilton Page: 41 of 42 Assessment Date: 09/18/2023

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.





			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	o		110		(0.)	700	700		
Computer Lab	Regular Classroom	2nd Floor	203	203	1,137	180	90	N	N
Computer Lab	Regular Classroom	4th Floor	404	404	927	150	75	N	Y
Kindergarten	Science Classroom	1st Floor	103	103	1,053	190	90	N	N
Laboratory/Shop	Regular Classroom	4th Floor	400	400	1,854	300	150	Y	Y
Play Room	Other Instructional Use	2nd Floor	207	207	897	150	75	N	N
Regular Classroom	Other Instructional Use	2nd Floor	205	205	533	71	35	Y	N
Regular Classroom	Regular Classroom	1st Floor	100	100	560	60	30	N	N
Regular Classroom	Regular Classroom	2nd Floor	200	200	847	150	75	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	847	150	75	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	204	204	847	150	75	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	300	300	842	150	75	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	301	301	848	150	75	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	303	303	846	150	75	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	304	304	843	150	75	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	305	305	860	150	75	N	N
Regular Classroom	Regular Classroom	4th Floor	403	403	860	150	75	N	Υ
Regular Classroom	Regular Classroom	4th Floor	405	405	860	150	75	N	N
Regular Classroom	Store Room	1st Floor	105	105	566	120	60	N	N
Science Classroom	Regular Classroom	3rd Floor	302	302	843	150	75	N	N
Science Classroom	Science Classroom	1st Floor	102	102	1,037	190	90	N	Υ
Store Room	Regular Classroom	1st Floor	104	104	566	60	30	N	N
Store Room	Regular Classroom	2nd Floor	201	201	848	150	75	N	N
Store Room	Regular Classroom	4th Floor	401	401	863	150	75	N	N
Store Room	Science Classroom	4th Floor	408	408	1,119	160	80	N	N
Building : Addition									
Computer Lab	Regular Classroom	2nd Floor	211	211	762	160	80	N	Υ
Kindergarten	Kindergarten	1st Floor	112	112	1,013	240	120	Y	Υ
Kindergarten	Regular Classroom	2nd Floor	210	210	754	160	80	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	208	208	754	160	80	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	212	212	720	160	80	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	214	214	756	160	80	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	308	308	754	160	80	N	N
Regular Classroom	Regular Classroom	3rd Floor	310	310	754	160	80	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	311	311	762	160	80	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	312	312	752	160	80	N	Υ
Regular Classroom	Regular Classroom	3rd Floor	314	314	733	160	80	N	Υ