



Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1931	3	67,204
Annex	1996	2	17,176
Modular 1 (2-Classroom)	1995	1	2,100
Campus Total			86,480

Category : Exterior Building : Main

Category . Exterior		Building . Main						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
		Location	Quantity	OCIVI	Ivalik	Replacement	Comments	
eli Equ	ipment	Factor Destators	0		7	40		
	Cell Equipment - Antenna	Entire Building	8	EΑ	7	10+ years		
	Cell Equipment - Cabinets	Entire Building	2	EΑ	7	10+ years		
	Cell Equipment - Generator	Entire Building	1	EA	7	10+ years		
ntrance	9							
	Entrance Control - Audio and Video	Door 1 - Northeast	1	EA	6	10+ years		
	Exterior Doors - Exterior Steel Door	Door 1 - Northeast	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	Door 1 - Northeast	2	EA	6	10+ years		
	Exterior Stairs - Stone	Door 1 - Northeast	100	LF	6	10+ years		
	Stair Handrail - Steel_Stair Handrail	Door 1 - Northeast	18	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	Door 1.5 - East center	1	EA	6	10+ years		
	Exterior Doors - Transom Lite	Door 1.5 - East center	2	EA	6	10+ years		
	Exterior Stairs - Stone	Door 1.5 - East center	4	LF	6	10+ years		
	Exterior Doors - Exterior Steel Door	Door 2 - Southeast	2	EA	6	6-10 years		
	Exterior Doors - Transom Lite	Door 2 - Southeast	2	EA	6	10+ years		
	Exterior Stairs - Stone	Door 2 - Southeast	106	LF	4	1-2 years	The stairs have settled and shifte	
	Stair Handrail - Steel_Stair Handrail	Door 2 - Southeast	10	LF	7	10+ years	Repaired	
	Stair Handrail - Steel_Stair Handrail	Door 2 - Southeast	20	LF	6	10+ years	•	
	Exterior Doors - Exterior Steel Door	Door 3 - Southeast	2	EA	6	10+ years		
	Exterior Doors - Transom Lite	Door 3 - Southeast	2	EA	6	10+ years		
	Exterior Stairs - Concrete	Door 3 - Southeast	24	LF	6	10+ years		
	Exterior Stairs - Stone	Door 3 - Southeast	46	LF	6	10+ years		



Catego	ry : Exterior		В	uilding	: Main		430 N AVOIS AVENUE, Officago, IE 00020
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Entrance Control - Audio and Video	Door 4 - Southwest	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 4 - Southwest	2	EA	5	1-2 years	Corroding at doors and frame
	Exterior Doors - Transom Lite	Door 4 - Southwest	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 4 - Southwest	8	LF	6	10+ years	
	Exterior Stairs - Stone	Door 4 - Southwest	38	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 4 - Southwest	8	LF	6	6-10 years	
	Exterior Doors - Exterior Steel Door	Door 4.3 - Boiler South	1	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 4.3 - Boiler South	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 4.3 - Boiler South	4	LF	6	10+ years	
	Exterior Doors - Overhead Rolling/ Garage Door	Door 4.7 - Boiler West	1	EA	6	10+ years	
	Entrance Control - Audio and Video	Door 5 - Northwest	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 5 - Northwest	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	Door 5 - Northwest	2	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 5 - Northwest	72	LF	7	10+ years	Repaired
	Ramp Handrail - Steel_Ramp Handrail	Door 5 - Northwest	120	LF	5	1-2 years	Post are corroding and creating cracks in the concrete
	Ramps - Concrete	Door 5 - Northwest	60	LF	7	10+ years	Repaired
	Stair Handrail - Steel Stair Handrail	Door 5 - Northwest	40	LF	5	1-2 years	Post are corroding
	Exterior Doors - Exterior Steel Door	Door 6 - Northeast	2	ĒΑ	6	10+ years	
	Exterior Doors - Transom Lite	Door 6 - Northeast	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 6 - Northeast	40	LF	5	6-10 years	
	Exterior Stairs - Stone	Door 6 - Northeast	12	LF	5	10+ years	
	Stair Handrail - Steel_Stair Handrail	Door 6 - Northeast	12	LF	6	10+ years	
_Foundati							
	Foundation - Concrete	Entire Building	1,130	LF	7	10+ years	
	Foundation - Concrete	Entire Building	10	LF	6	10+ years	
	Superstructure - Steel	Entire Building	67,204	SF	7	10+ years	
Lighting							
	Exterior Lighting - Parapet or Roof Mounted	Entire Building	11	EA	6	10+ years	
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	6	10+ years	
_Roof Sys							
	Access Ladder - Metal	Roof 1	2	EA	7	10+ years	
	Access Ladder - Metal	Roof 1	2	EA	4	0-1 year	Obsolete ladder is unsecured to the wall, angle support merely rest on clay tile
	Access Ladder - Wood	Roof 1	2	EA	3	0-1 year	Not safe. Loose openings at the top of ladder
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 1	61	LF	6	10+ years	

Campus Name: Volta Page : 2 of 47 Assessment Date: 02/19/2024



Catego	ry : Exterior		В	Building : Main			-	
				_		Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Roof 1	5	LF	3	1-2 years	Large crack	
	Coping - Terra Cotta	Roof 1	460	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof 1	200	LF	6	10+ years		
	Parapet - 16" - 30" Height	Roof 1	270	LF	6	10+ years		
	Parapet - Parapet > 30"	Roof 1	190	LF	6	10+ years		
	Roof - Modified Bitumen	Roof 1	11,170	SF	2	0-1 year	Roof is in very bad condition with soft spots throughout, worn surface, deteriorated sealant and mortar at coping.	
	Roof Hatch - Metal	Roof 1	2	EA	4	1-2 years	Roof hatch is old and obsolete	
	Roof Structure - Steel with Clay Tile Arch	Roof 1	11,170	SF	7	10+ years		
	Coping - Terra Cotta	Roof 2	384	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof 2	180	LF	6	10+ years		
	Parapet - 16" - 30" Height	Roof 2	346	LF	6	10+ years		
	Parapet - Parapet > 30"	Roof 2	38	LF	6	10+ years		
	Roof - Modified Bitumen	Roof 2	7,680	SF	5	0-1 year	Deteriorated roof, open joints and soft spots	
	Roof Structure - Steel with Clay Tile Arch	Roof 2	7,680	SF	7	10+ years	·	
	Coping - Clay Tile	Roof 3	439	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof 3	144	LF	6	10+ years		
	Parapet - 16" - 30" Height	Roof 3	401	LF	6	10+ years		
	Parapet - Parapet > 30"	Roof 3	38	LF	6	10+ years	Repaired	
	Roof - Modified Bitumen	Roof 3	7,307	SF	5	0-1 year	Soft spots, worn out surface	
	Roof Structure - Steel with Clay Tile Arch	Roof 3	7,307	SF	7	10+ years	•	
	Coping - Clay Tile	Roof 4	128	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof 4	40	LF	6	10+ years		
	Parapet - 16" - 30" Height	Roof 4	128	LF	6	10+ years		
	Roof - Modified Bitumen	Roof 4	1,731	SF	5	2-5 years		
	Roof Structure - Steel with Clay Tile Arch	Roof 4	1,731	SF	7	10+ years		
	Coping - Terra Cotta	Roof 5	30	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof 5	30	LF	6	10+ years		
	Parapet - 16" - 30" Height	Roof 5	30	LF	6	10+ years		
	Roof - Modified Bitumen	Roof 5	122	SF	5	2-5 years		
	Roof Structure - Steel with Clay Tile Arch	Roof 5	122	SF	7	10+ years		
	Coping - Terra Cotta	Roof 6	30	LF	6	10+ years		
	Downspouts - Interior Downspouts	Roof 6	30	LF	6	10+ years		
	Parapet - 16" - 30" Height	Roof 6	30	LF	6	10+ years		
	Roof - Modified Bitumen	Roof 6	122	SF	5	0-1 year	Vegetation growth.	
	Roof Structure - Steel with Clay Tile Arch	Roof 6	122	SF	7	10+ years	- •	
	Coping - Metal	Roof 7	22	LF	6	10+ years		
	Roof - Modified Bitumen	Roof 7	250	SF	5	2-5 years		
	Roof Structure - Steel with Clay Tile Arch	Roof 7	250	SF	7	10+ years		

Page : 3 of 47 Campus Name: Volta Assessment Date: 02/19/2024



Catego	ry : Exterior		В	uilding	: Main		4930 IN AVEIS AVEINUE, CHICAGO, IL 60023
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Walls	21.						
	Cheek-Wall - Stone	Entire Building	10	SF	6	10+ years	Repaired
	Cheek-Wall - Stone	Entire Building	60	SF	6	10+ years	rtopanoa
	Cornice - Terra Cotta	Entire Building	30	LF	7	10+ years	Repaired
	Cornice - Terra Cotta	Entire Building	789	LF	5	10+ years	
	Exterior Walls - Brick	Entire Building	20	SF	6	6-10 years	Repaired
	Exterior Walls - Brick	Entire Building	41,357	SF	6	10+ years	•
	Exterior Walls - Stone-Cast	Entire Building	760	SF	6	10+ years	
	Exterior Walls - Terra Cotta	Entire Building	1	SF	5	6-10 years	Repaired
	Exterior Walls - Terra Cotta	Entire Building	3,969	SF	5	10+ years	·
_Windows	S						
	Guard - Guards perforated	Entire Building	2,881	SF	6	10+ years	
	Guard - Guards wire guard	Entire Building	276	SF	6	10+ years	
	Lintels - Steel	Entire Building	1,082	LF	6	10+ years	
	Skylite - Glass Single-Pane	Entire Building	184	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,360	SF	7	6-10 years	Repaired
	Windows - Sash Aluminum Double-pane	Entire Building	8,277	SF	6	10+ years	·
	Windows - Sash Lexan	Entire Building	72	SF	5	6-10 years	
Catego	ry : Electrical		В	uilding	: Main		
				<u> </u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Emerge	ncy System						
	Security System - Intrusion Detection	Entire Building	67,204	SF	6	6-10 years	Priority Rep adjusted based on current observations.
	Exit Signs - Auditoium	Entire Building	6	EA	2	0-1 year	Quantity changed to match current observations. Signs have no backup batteries and the school has no
	Exit Signs - Corridors and Stairs	Entire Building	20	EA	2	0-1 year	emergency generator. Signs have no backup batteries and the school has no emergency generator.
	Exit Signs - Gym	Entire Building	2	EA	2	0-1 year	Signs have no backup batteries and the school has no emergency
	Exit Signs - Lunchroom	Entire Building	2	EA	6	6-10 years	generator.Quantity and Rank changed to match current observations.
	Emergency Battery Packs - Auditoium and Aisle Lighting	Entire Building	4	EA	6	6-10 years	Quantity changed to match current observations. Priority Rep adjusted based on current observations.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years	Priority Rep adjusted based on current observations.
	Staire						current observations



Categor	ry : Electrical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Emergency A/C Power - Auditoium and Aisle Lighting	Entire Building	2,294	SF	6	6-10 years	
	Emergency A/C Power - Corridors and Stairs	Entire Building	13,378	SF	6	6-10 years	
	Automatic Transfer Switch	Mechanical Room	1	EA	4	2-5 years	Equipment is approx. 60 years old and has exceeded its anticipated service life.
Main Ser	vice						
	PA System	Entire Building	67,204	SF	5	6-10 years	Serves Main and Annex.
	Independent Electrical Service for emergency power	Mechanical Room	1	EA	7	6-10 years	
	Main Electrical Service - 2000 A 120/208/3PH	Switchgear Room	1	EA	7	10+ years	
Power Di	stribution						
	Lighting and Power Panels - 100 A	Entire Building	8	EA	6	6-10 years	Quantity changed as total has been divided/aggregated. Condition of panels secured shut for safety reasons verified by Building Engineer
	Lighting and Power Panels - Above 100 A	Entire Building	9	EA	6	6-10 years	Quantity changed as total has been divided/aggregated.
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Location changed for clarification. Rank, Reason and Priority Rep changed as an open breaker slot exposes live conductors presenting live front condition.
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	Location changed for clarification. Quantity changed as total has been divided/aggregated.
Categor	ry : Fire Protection		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Alarr	m Fire ALarm Anunciator	Entire Building	1	EA	3	2-5 years	Rank, Reason and Priority Rep established as the system is 25-plus years old, employs antiquated technology, and has exceeded its anticipated service life. No CPS Asset Tag present.

Campus Name: Volta Page : 5 of 47 Assessment Date: 02/19/2024



Catego	ry : Fire Protection		E	Building	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments the panel is 25-plus years old,
							employs antiquated technology, and has exceeded its anticipated service life.
	Fire Alarm_System	Entire Building	67,204	SF	4	2-5 years	Rank, Reason and Priority Rep adjusted as the system is 25-plus years old, employs antiquated technology, does not include strobe lights, and has exceeded its anticipated service life.
Catego	ry : Mechanical		E	Building	: Main		
o miego	, · ·····			·		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond							
	Condensing Unit- Roof Mounted - Less than 5 tons Condensing Unit- Roof Mounted - Less than 5 tons	Lower Roof Lower Roof	1	EA	6	6-10 years	Not directly accessible at the time of assessment due to unreliable window passage with no immediate way to improve safety to an acceptable condition at the time of assessment. Dataplate and CPS Asset Tag not available. Condition verified by current observations and per review with Building Engineer. Component of a ductless split system serving the MDF Room. Not directly accessible at the time of assessment due to unreliable window passage with no immediate way to improve safety to an acceptable condition at the time of assessment. CPS Asset Tag not available. Condition verified by current observations and per review with Building Engineer. Component of a ductless split system serving the Switchgear Room.
Air Hand	ling Systems	F (-		0.40	ALILLA
	Air Handling Unit- Built Up- Single Zone- Steam Coils - Less than 4000 cfm	Entire Building	1	EA	5	6-10 years	AHU-4, serves gym.
	Air Intake	Entire Building Entire Building	1	EA EA	6 5	10+ years 6-10 years	
	Auxiliaries - Less than 4000 cfm						

Campus Name: Volta Page : 6 of 47 Assessment Date: 02/19/2024



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	and Ducts Indoor Return Fans- Centrifugal Squirrel	Mechanical Room	1	EA	6	6-10 years	
	Cage - 10001 - 20000 CFM Air Handling Unit- Built Up- Single Zone w/	Mechanical Room	1	EA	5	6-10 years	AHU-3, serves south sections of
	Air Tunnel- Steam Coils - 15001 - 25000 cfm						Main.
	Air Intake	Mechanical Room	1	EA	7	10+ years	
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room	1	EA	5	6-10 years	Air filters are installed on the reheat boxes in lieu of a single filter bank.
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room	6	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room	400	LF	7	10+ years	
	Zone Dampers	Mechanical Room	20	EA	5	6-10 years	Priority Rep adjusted based on current observations.
	Air Handling Unit- Built Up- Single Zone- Steam Coils - 8001 - 15000 cfm	Mechanical Room - AHU-1	1	EA	6	6-10 years	AHU-1, serves auditorium.
	Air Intake	Mechanical Room - AHU-1	1	EA	6	10+ years	
	Auxiliaries - 8001 - 15000 cfm	Mechanical Room - AHU-1	1	EΑ	4	1-2 years	Leak in condensate system.
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-1	50	LF	7	10+ years	
	Air Handling Unit- Built Up- Single Zone w/ Air Tunnel- Steam Coils - 15001 - 25000 cfm	Mechanical Room - AHU-2	1	EA	5	6-10 years	AHU-2, serves north sections of Main.
	Air Intake	Mechanical Room - AHU-2	1	EA	6	10+ years	···aiii
	Auxiliaries - 15001 - 25000 cfm	Mechanical Room - AHU-2	1	EA	5	6-10 years	
	Reheat Boxes - Reheat Boxes with Steam Coil	Mechanical Room - AHU-2	6	EA	6	6-10 years	
	Return Duct Work - Indoor- Vertical Shaft and Ducts	Mechanical Room - AHU-2	400	LF	7	10+ years	
	Zone Dampers	Mechanical Room - AHU-2	16	EA	6	6-10 years	
Boiler Sy	vstems						
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 76 - 100 HP	Boiler Room	2	EA	5	6-10 years	Priority Rep adjusted based on current observations.
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	5	6-10 years	Priority Rep adjusted based on current observations.
	Condensate Pump	Boiler Room	1	EA	7	10+ years	Rank, Reason and Priority Rep changed as the entire assembly was replaced since previous assessment. No CPS Asset Tag present.
	Condensate Pump	Boiler Room	1	EA	4	1-2 years	Pump motor replaced in 2023 but system is overflowing. Location changed for clarification.

Campus Name: Volta Page : 7 of 47 Assessment Date: 02/19/2024



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Feed Water Pumps and Tank	Boiler Room	1	EA	5	6-10 years	Priority Rep adjusted based on current observations.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	6-10 years	B-1. Priority Rep adjusted based on current observations.
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 76 - 100 HP	Boiler Room	1	EA	5	6-10 years	B-2. Priority Rep adjusted based on current observations.
	Piping - Condensate Pipe- Steel	Boiler Room	500	LF	6	10+ years	
	Piping - Steam Pipe- Steel	Boiler Room	500	LF	6	10+ years	
	Steam Traps	Boiler Room	91	EA	5	6-10 years	
	Oteam Traps	Bollet Room	31	L/\	J	o to years	
Heating							
	Fin Tube - Steam	1st Floor	4	LF	6	6-10 years	Located in Auditorium restroom. Rank, Reason and Priority Rep adjusted per review with Building Engineer that upgrades have been completed since previous assessment.
	Unit Heater - Gas	Boiler Room, Boiler Room Storage	1	EΑ	6	6-10 years	
	Unit Heater - Gas	Boiler Room, Boiler Room Storage	2	EA	6	6-10 years	
	Radiators - Steam	Entire Building	35	EA	5	10+ years	Paint required.
	Wall Heater - Electric	Entire Building	19	EA	6	6-10 years	Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer that repairs have been completed since previous assessment.
Tempera	ature Control						
	Electric Thermostat	Entire Building	5	EA	6	6-10 years	
	Hybrid Pneumatic/DDC System	Entire Building	67,204	SF	6	6-10 years	
	Thermostats - DDC	Entire Building	39	ĒΑ	6	6-10 years	
		C				•	
Ventilation							
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	Location changed for clarification.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Rank, Reason and Priority Rep adjusted based on current observations and per review with Building Engineer; repairs have been completed since previous assessment.
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	Rank, Reason and Priority Rep adjusted based on current observations and per review with

Campus Name: Volta Page: 8 of 47 Assessment Date: 02/19/2024



Alessandro Volta Elementary School

4950 N Avers AVENUE, Chicago, IL 60625

Building: Main Category : Mechanical

Item - Type Quantity UOM Rank Comments Location Replacement Group

Recommend

Building Engineer; repairs have been completed since previous assessment.

Building: Main Category: Plumbing

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	-	Location	Qualitity	CON	IVALIK	Replacement	Comments
_HOL Wall	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
_Piping							
1 0	Domestic Piping-Hot Water Return Lines	Entire Building	67,204	SF	6	6-10 years	
	Domestic Piping-Hot Water Return Risers	Entire Building	67,204	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	67,204	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	67,204	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	67,204	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	67,204	SF	6	6-10 years	
	Sanitary Piping	Entire Building	67,204	SF	6	6-10 years	
	Storm Piping	Entire Building	67,204	SF	6	6-10 years	
	Vent Piping	Entire Building	67,204	SF	6	6-10 years	
Pumps							
·	Pumps - Domestic Booster Pump-Simplex	Mechanical Room	1	EA	7	10+ years	Newly installed since previous assessment. No CPS Asset Tag present.
	Pumps - Sump-Duplex	Mechanical Room	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed as the equipment has been upgraded since previous assessment and is leak-free.

Category: Room **Building: Main**

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Administ	rative Suites/Offices						
	Ceiling - Plaster/Drywall	1st Floor - Auditorium Vestibule	134	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor - Auditorium Vestibule	1	EA	7	10+ years	
	Floor - Terrazzo	1st Floor - Auditorium Vestibule	134	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Auditorium Vestibule	1	EA	7	10+ years	
	Power Distribution	1st Floor - Auditorium Vestibule	4	EA	7	10+ years	

Campus Name: Volta Page: 9 of 47 Assessment Date: 02/19/2024



Catego	ry : Room		Building : Main							
						Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
	Walls - Plaster/Drywall	1st Floor - Auditorium Vestibule	324	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - Auditorium Vestibule	20	SF	5	0-1 year	Water damage			
	Ceiling - Plaster/Drywall	1st Floor - Janitor Break Room	88	SF	7	10+ years				
	Ceiling - Plaster/Drywall	1st Floor - Janitor Break Room	20	SF	4	1-2 years	Damaged ceiling			
	Doors - Wood Doors inclu hw	1st Floor - Janitor Break Room	1	EA	7	10+ years				
	Floor - Tile	1st Floor - Janitor Break Room	96	SF	7	10+ years				
	Floor - Tile	1st Floor - Janitor Break Room	12	SF	4	1-2 years	Missing tile			
	Lighting - Pendent/Surface	1st Floor - Janitor Break Room	2	EA	7	10+ years				
	Power Distribution	1st Floor - Janitor Break Room	2	EA	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - Janitor Break Room	120	SF	6	10+ years				
	Walls - Plaster/Drywall	1st Floor - Janitor Break Room	170	SF	4	1-2 years	Damaged wall			
	AC Unit	1st Floor - Main Office	1	EA	7	6-10 years				
	Ceiling - Lay-in	1st Floor - Main Office	416	SF	7	10+ years				
	Doors - Transom Window	1st Floor - Main Office	6	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor - Main Office	2	EA	7	10+ years				
	Floor - Carpet	1st Floor - Main Office	260	SF	7	6-10 years				
	Floor - Carpet	1st Floor - Main Office	34	SF	4	1-2 years	Torn carpet			
	Floor - Tile	1st Floor - Main Office	77	SF	7	10+ years	·			
	Floor - Tile	1st Floor - Main Office	45	SF	4	1-2 years	Cracked tile			
	Lighting - Lay-in	1st Floor - Main Office	7	EA	7	10+ years				
	Power Distribution	1st Floor - Main Office	10	EA	7	10+ years				
	Storage/ Closet	1st Floor - Main Office	154	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - Main Office	1,008	SF	7	10+ years				
	AC Unit	1st Floor - Principal		EA	7	6-10 years				
	Ceiling - Lay-in	1st Floor - Principal	137	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor - Principal	12	SF	4	1-2 years	Water damaged tile			
	Doors - Wood Doors inclu hw	1st Floor - Principal	1	ĒΑ	7	10+ years				
	Floor - Carpet	1st Floor - Principal	149	SF	7	6-10 years				
	Lighting - Lay-in	1st Floor - Principal	2	ĒΑ	7	10+ years				
	Power Distribution	1st Floor - Principal	6	EA	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - Principal	381	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor - Principal	15	SF	5	1-2 years	Cracked paint			
	Ceiling - Plaster/Drywall	Across from Lunchroom	74	SF	7	10+ years				
	Doors - Transom Window	Across from Lunchroom	6	SF	7	10+ years				
	Doors - Wood Doors inclu hw	Across from Lunchroom	1	EA	7	10+ years				
	Floor - Carpet	Across from Lunchroom	74	SF	7	6-10 years				
	Lighting - Pendent/Surface	Across from Lunchroom	2	EA	7	10+ years				
	Power Distribution	Across from Lunchroom	2	EA	7	10+ years				
	Walls - Plaster/Drywall	Across from Lunchroom	216	SF	7	10+ years				
	Walls - Plaster/Drywall	Across from Lunchroom	210	SF	5	1-2 years	Minor crack			
	Ceiling - Plaster/Drywall	Auditorium beside toilet old women	120	SF	7	10+ years	WILLOW OTGOR			
	Coming - I laster/Drywan	RR	120	Oi.	,	10+ years				
	Doors - Wood Doors inclu hw	Auditorium beside toilet old women	1	EA	7	10+ years				
	20013 - WOOD 20013 IIIOID IIW	RR	'		,	10+ years				
		IXIX								

Campus Name: Volta Page : 10 of 47 Assessment Date: 02/19/2024



Catego	Category: Room			uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Auditorium beside toilet old women RR	120	SF	7	10+ years	
	Lighting - Pendent/Surface	Auditorium beside toilet old women RR	1	EA	7	10+ years	
	Power Distribution	Auditorium beside toilet old women RR	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Auditorium beside toilet old women RR	300	SF	6	10+ years	
	AC Unit	Basement - Engineer	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Engineer	142	SF	5	1-2 years	Cracking throughout
	Doors - Wood Doors inclu hw	Basement - Engineer	1	EA	7	10+ years	
	Floor - Tile	Basement - Engineer	142	SF	6	2-5 years	
	Lighting - Pendent/Surface	Basement - Engineer	2	EA	7	10+ years	
	Power Distribution	Basement - Engineer	6	EA	7	10+ years	
	Storage/ Closet	Basement - Engineer	189	SF	7	10+ years	
	Walls - Masonry	Basement - Engineer	75	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement - Engineer	207	SF	7	10+ years	
	Walls - Plaster/Drywall	Basement - Engineer	30	SF	5	1-2 years	Cracking walls
	Ceiling - Plaster/Drywall	First floor small office inside room 109	99	SF	6	10+ years	3
	Doors - Transom Window	First floor small office inside room 109	12	SF	6	10+ years	
	Doors - Wood Doors inclu hw	First floor small office inside room 109	2	EA	6	10+ years	
	Floor - Tile	First floor small office inside room 109	99	SF	6	10+ years	
	Lighting - Pendent/Surface	First floor small office inside room 109	1	EA	7	6-10 years	
	Power Distribution	First floor small office inside room 109	6	EA	7	10+ years	
	Walls - Plaster/Drywall	First floor small office inside room 109	178	SF	7	10+ years	
	Walls - Plaster/Drywall	First floor small office inside room 109	30	SF	5	1-2 years	Minor cracking not viewed
	Ceiling - Plaster/Drywall	First floor teachers lounge inside room 109	194	SF	7	10+ years	
	Doors - Transom Window	First floor teachers lounge inside room 109	72	SF	7	10+ years	
	Doors - Wood Doors inclu hw	First floor teachers lounge inside room 109	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	First floor teachers lounge inside room 109	194	SF	7	10+ years	
	Lighting - Pendent/Surface	First floor teachers lounge inside room 109	2	EA	7	6-10 years	



Category : Room			В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Power Distribution	First floor teachers lounge inside	2	EA	7	10+ years	
		room 109			_		
	Storage/ Closet	First floor teachers lounge inside	190	SF	7	10+ years	
	\\\-\\-\\\-\\\-\\\-\\\-\\\\-\\\-\\\\-\\\\	room 109	400	0.5	7	40	
	Walls - Plaster/Drywall	First floor teachers lounge inside	460	SF	7	10+ years	
	Work SInk	room 109 First floor teachers lounge inside	1	EA	7	10	
	WOIR SIIIK	room 109	ı	EA	,	10+ years	
	AC Unit	Room 302	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Room 302	332	SF	6	10+ years	
	Doors - Transom Window	Room 302	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 302	1	EA	6	6-10 years	
	Floor - Wood	Room 302	332	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 302	6	EA	7	6-10 years	
	Power Distribution	Room 302	4	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Room 302	840	SF	7	10+ years	
	Walls - Plaster/Drywall	Room 302	40	SF	5	0-1 year	Big crack
	Ceiling - Plaster/Drywall	Second small office in 109	30	SF	7	10+ years	Dig order
	Doors - Transom Window	Second small office in 109	9	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Second small office in 109	1	EA	7	10+ years	
	Floor - Terrazzo	Second small office in 109	30	SF	7	10+ years	
	Lighting - Pendent/Surface	Second small office in 109	1	ĒΑ	7	10+ years	
	Power Distribution	Second small office in 109	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Second small office in 109	90	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Third office in 109	30	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Third office in 109	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Third office in 109	30	SF	7	10+ years	
	Lighting - Pendent/Surface	Third office in 109	1	EA	7	10+ years	
	Power Distribution	Third office in 109	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Third office in 109	90	SF	7	10+ years	
_Auditoriu	ım & Theater						
	Balcony Seating	1st Floor	100	EA	7	10+ years	
	Ceiling - Lay-in	1st Floor	2,284	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	10	SF	4	1-2 years	Water damage.
	Doors - Wood Doors inclu hw	1st Floor	5	EA	7	10+ years	
	Floor - Carpet	1st Floor	865	SF	7	6-10 years	
	Floor - Carpet	1st Floor	6	SF	4	0-1 year	Damaged.
	Floor - Tile	1st Floor	1,423	SF	7	10+ years	
	Lighting - Chandelier, Incandescent	1st Floor	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	26	EΑ	7	6-10 years	
	Lighting - Wall Mounted	1st Floor	14	EA	7	6-10 years	
	Main Floor Seating	1st Floor	286	EA	7	10+ years	
	Main Floor Seating	1st Floor	2	EA	4	0-1 year	Broken.

Campus Name: Volta Page : 12 of 47 Assessment Date: 02/19/2024



Catego	Category : Room		В	uilding	: Main		4550 N AVEIS AVENUE, Officago, IE 00025		
			_			Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Sound System	1st Floor	1	EΑ	7	10+ years			
	Stage	1st Floor	531	SF	7	10+ years			
	Stage Curtain	1st Floor	4	EA	7	10+ years			
	Stage Lighting System	1st Floor	1	EA	7	10+ years			
	Stage-Stairs - Wood	1st Floor	30	LF	7	10+ years			
	Stairs - Terrazzo	1st Floor	40	LF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	4,800	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	2	SF	6	10+ years			
	Walls - Plaster/Drywall	1st Floor	150	SF	5	0-1 year	Damaged and cracked.		
Gvmnas	ia								
	Ceiling - Plaster/Drywall	1st Floor	2,407	SF	7	10+ years			
	Doors - Transom Window	1st Floor	12	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years			
	Floor - Wood	1st Floor	2,407	SF	7	10+ years			
	Lighting - Metal Halide/Sodium Vapor	1st Floor	8	EA	7	6-10 years			
	Scoreboards	1st Floor	1	EA	7	10+ years			
	Walls - Structural Glazed Tile	1st Floor	4,406	SF	6	10+ years			
Library									
•	AC Unit	208/206	2	EA	7	6-10 years			
	Casework	208/206	46	LF	7	10+ years			
	Ceiling - Lay-in	208/206	1,485	SF	6	10+ years			
	Doors - Transom Window	208/206	24	SF	7	10+ years			
	Doors - Wood Doors inclu hw	208/206	4	EΑ	7	10+ years			
	Floor - Wood	208/206	1,485	SF	7	10+ years			
	Lighting - Lay-in	208/206	24	EΑ	7	6-10 years			
	Walls - Plaster/Drywall	208/206	2,055	SF	7	10+ years			
	Walls - Plaster/Drywall	208/206	10	SF	6	10+ years	Peeling		
Lunch&	Multipurpose Room								
	Ceiling - Plaster/Drywall	1st Floor - 117 and 115	1,482	SF	7	10+ years			
	Ceiling - Plaster/Drywall	1st Floor - 117 and 115	10	SF	5	1-2 years	Water damage.		
	Doors - Transom Window	1st Floor - 117 and 115	18	SF	7	10+ years	3		
	Doors - Wood Doors inclu hw	1st Floor - 117 and 115	3	ĒΑ	7	10+ years			
	Floor - Tile	1st Floor - 117 and 115	1,292	SF	7	10+ years			
	Floor - Tile	1st Floor - 117 and 115	200	SF	4	1-2 years	Cracked tile in several places		
	Lighting - Pendent/Surface	1st Floor - 117 and 115	28	ĒΑ	7	10+ years	•		
	Market Board	1st Floor - 117 and 115	12	LF	7	6-10 years			
	Serving Line	1st Floor - 117 and 115	10	LF	7	10+ years			
	Walls - Metal Panel	1st Floor - 117 and 115	1,147	SF	7	10+ years			
	Walls - Plaster/Drywall	1st Floor - 117 and 115	1,147	SF	7	10+ years			

Campus Name: Volta Page: 13 of 47 Assessment Date: 02/19/2024



Catego	Category : Room		В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_MDF_ID	F						
	Doors - Steel Doors incl hw	Inside 208	1	EA	7	10+ years	
	Finishes	Inside 208	90	SF	5	10+ years	
	Other Cooling Unit	Inside 208	1	EA	7	6-10 years	Split unit.
_Mechani	cal/ Service Rooms						
	Janitor's Closet	1st Floor	60	SF	5	2-5 years	
	Storage Room	1st Floor	90	SF	7	10+ years	
	Storage Room	1st Floor	280	SF	5	10+ years	
	Janitor's Closet	2nd Floor	60	SF	7	10+ years	
	Storage Room	2nd Floor	90	SF	7	10+ years	
	Janitor's Closet	3rd Floor	60	SF	7	10+ years	
	Air Tunnel	Basement	3,800	SF	7	10+ years	
	Boiler Room	Basement	1,590	SF	7	10+ years	
	Coal Room	Basement	465	SF	7	10+ years	
	Crawl Space - Unfinished	Basement	8,100	SF	7	10+ years	
	Loading Docks	Basement	183	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	850	SF	7	10+ years	
	Mechanical/ Service Rooms	Basement	900	SF	7	10+ years	
	Storage Room	Basement	500	SF	7	10+ years	
Restroor	n						
	Accessories	1st Floor	325	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	240	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	85	SF	4	1-2 years	Water damaged ceiling
	Doors - Transom Window	1st Floor	24	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	2-5 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	325	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	2	EA	7	6-10 years	
	Lavatory	1st Floor	3	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	5	EA	7	10+ years	
	Partitions	1st Floor	9	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	728	SF	7	10+ years	
	Water Closet	1st Floor	9	EA	7	10+ years	
	Accessories	1st Floor - Janitor's Break Room	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Janitor's Break Room	30	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor - Janitor's Break Room	1	ĒΑ	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor - Janitor's Break Room	30	SF	7	10+ years	
	Lavatory	1st Floor - Janitor's Break Room	1	ĒΑ	7	10+ years	
	Lighting - Wall Mounted	1st Floor - Janitor's Break Room	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Janitor's Break Room	96	SF	5	1-2 years	Damaged walls throughout
	,				-	,	5 3

Campus Name: Volta Page : 14 of 47 Assessment Date: 02/19/2024



Catego	ry : Room		В	uilding	: Main		·
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Water Closet	1st Floor - Janitor's Break Room	1	EA	7	10+ years	
	Accessories	1st Floor - Principal's Office	24	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor - Principal's Office	24	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	1st Floor - Principal's Office	1	EA	7	10+ years	
	Floor - Tile	1st Floor - Principal's Office	24	SF	7	10+ years	
	Lavatory	1st Floor - Principal's Office	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor - Principal's Office	1	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor - Principal's Office	64	SF	6	2-5 years	
	Water Closet	1st Floor - Principal's Office	1	EA	7	10+ years	
	Accessories	2nd floor women near Room 210	90	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd floor women near Room 210	90	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd floor women near Room 210	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd floor women near Room 210	90	SF	7	10+ years	
	Hand Dryer	2nd floor women near Room 210	1	EA	7	10+ years	
	Lavatory	2nd floor women near Room 210	1	EA	7	10+ years	
	Lighting - Pendent/Surface	2nd floor women near Room 210	2	EA	7	6-10 years	
	Partitions	2nd floor women near Room 210	2	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd floor women near Room 210	200	SF	7	10+ years	
	Water Closet	2nd floor women near Room 210	2	EA	7	10+ years	
	Accessories	3rd floor boys near 304	230	SF	5	2-5 years	
	Ceiling - Plaster/Drywall	3rd floor boys near 304	230	SF	7	10+ years	
	Doors - Transom Window	3rd floor boys near 304	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd floor boys near 304	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor boys near 304	227	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	3rd floor boys near 304	3	SF	4	1-2 years	Missing
	Floor Drain	3rd floor boys near 304	1	EA	7	10+ years	
	Lavatory	3rd floor boys near 304	3	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor boys near 304	3	EA	6	6-10 years	
	Partitions	3rd floor boys near 304	2	EA	7	10+ years	
	Urinals	3rd floor boys near 304	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	3rd floor boys near 304	410	SF	6	10+ years	
	Walls - Structural Glazed Tile	3rd floor boys near 304	4	SF	4	1-2 years	Broken missing
	Walls - Tile Ceramic/ Porcelain	3rd floor boys near 304	100	SF	6	10+ years	
	Water Closet	3rd floor boys near 304	2	EA	6	10+ years	
	Accessories	3rd floor girls' near 310	230	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd floor girls' near 310	230	SF	6	10+ years	
	Doors - Transom Window	3rd floor girls' near 310	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd floor girls' near 310	1	EA	6	10+ years	
	Doors - Wood Doors inclu hw	3rd floor girls' near 310	1	EA	6	2-5 years	
	Floor - Tile Ceramic/ Porcelain	3rd floor girls' near 310	230	SF	6	10+ years	
	Floor Drain	3rd floor girls' near 310	1	EA	7	10+ years	
	Lavatory	3rd floor girls' near 310	2	EA	6	10+ years	
	Lighting - Pendent/Surface	3rd floor girls' near 310	4	EA	7	6-10 years	
	Partitions	3rd floor girls' near 310	7	EA	7	10+ years	
		•				•	

Campus Name: Volta Page : 15 of 47 Assessment Date: 02/19/2024



Category : Room		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Structural Glazed Tile	3rd floor girls' near 310	510	SF	6	10+ years	
	Water Closet	3rd floor girls' near 310	7	EA	6	10+ years	
	Accessories	Auditorium Vestibule - Men	81	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Auditorium Vestibule - Men	81	SF	6	10+ years	
	Doors - Wood Doors inclu hw	Auditorium Vestibule - Men	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Auditorium Vestibule - Men	81	SF	7	10+ years	
	Lavatory	Auditorium Vestibule - Men	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Auditorium Vestibule - Men	1	EA	6	2-5 years	
	Partitions	Auditorium Vestibule - Men	1	EA	7	10+ years	
	Urinals	Auditorium Vestibule - Men	1	EA	7	10+ years	
	Walls - Plaster/Drywall	Auditorium Vestibule - Men	160	SF	7	10+ years	
	Walls - Plaster/Drywall	Auditorium Vestibule - Men	12	SF	5	1-2 years	Big crack
	Water Closet	Auditorium Vestibule - Men	1	EA	7	10+ years	G
	Accessories	Basement - Engineer's Office	30	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Basement - Engineer's Office	30	SF	5	1-2 years	Cracked ceiling throughout
	Doors - Wood Doors inclu hw	Basement - Engineer's Office	1	ĒΑ	7	10+ years	3 · · · · · · · · · · · · · · · · · · ·
	Floor - Tile Ceramic/ Porcelain	Basement - Engineer's Office	30	SF	7	10+ years	
	Lavatory	Basement - Engineer's Office	1	ĒΑ	7	10+ years	
	Lighting - Wall Mounted	Basement - Engineer's Office	1	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Basement - Engineer's Office	96	SF	5	1-2 years	Cracked walks throughout
	Water Closet	Basement - Engineer's Office	1	EΑ	7	10+ years	oracioa mamo unoagnoar
	Accessories	First floor boys near 107	264	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	First floor boys near 107	260	SF	7	10+ years	
	Ceiling - Plaster/Drywall	First floor boys near 107	4	SF	5	1-2 years	Braking ceiling plaster
	Doors - Transom Window	First floor boys near 107	24	SF	7	10+ years	Drawing coming placetor
	Doors - Wood Doors inclu hw	First floor boys near 107	4	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	First floor boys near 107	254	SF	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	First floor boys near 107	10	SF	4	1-2 years	Various spots with damaged missing
		·	10			·	tile
	Floor Drain	First floor boys near 107	1	EA	7	10+ years	
	Hand Dryer	First floor boys near 107	2	EA	7	10+ years	
	Lavatory	First floor boys near 107	3	EA	7	10+ years	
	Lighting - Pendent/Surface	First floor boys near 107	4	EA	7	6-10 years	
	Partitions	First floor boys near 107	2	EA	7	10+ years	
	Urinals	First floor boys near 107	5	EA	7	10+ years	
	Walls - Plaster/Drywall	First floor boys near 107	20	SF	7	10+ years	
	Walls - Structural Glazed Tile	First floor boys near 107	376	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	First floor boys near 107	60	SF	6	10+ years	
	Water Closet	First floor boys near 107	2	EA	7	10+ years	
	Accessories	Near Class 110 - Women	90	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Near Class 110 - Women	90	SF	7	10+ years	
	Doors - Transom Window	Near Class 110 - Women	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Near Class 110 - Women	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	Near Class 110 - Women	90	SF	7	10+ years	

Campus Name: Volta Page : 16 of 47 Assessment Date: 02/19/2024



Category : Room			В	uilding	: Main		-
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hand Dryer	Near Class 110 - Women	1	EA	7	6-10 years	
	Lavatory	Near Class 110 - Women	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Near Class 110 - Women	2	EA	7	10+ years	
	Partitions	Near Class 110 - Women	2	EA	7	10+ years	
	Walls - Plaster/Drywall	Near Class 110 - Women	162	SF	7	10+ years	
	Walls - Plaster/Drywall	Near Class 110 - Women	8	SF	6	2-5 years	
	Walls - Plaster/Drywall	Near Class 110 - Women	30	SF	5	1-2 years	Cracking plaster
	Water Closet	Near Class 110 - Women	2	EA	7	10+ years	
	Accessories	Second floor boys	264	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Second floor boys	264	SF	5	0-1 year	Cracked
	Doors - Transom Window	Second floor boys	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Second floor boys	2	EΑ	5	1-2 years	Damaged door
	Floor - Tile Ceramic/ Porcelain	Second floor boys	263	SF	6	10+ years	-
	Floor - Tile Ceramic/ Porcelain	Second floor boys	1	SF	4	1-2 years	Missing
	Floor Drain	Second floor boys	2	EA	7	10+ years	-
	Hand Dryer	Second floor boys	1	EA	7	10+ years	
	Lavatory	Second floor boys	3	EA	6	10+ years	
	Lighting - Pendent/Surface	Second floor boys	4	EA	6	6-10 years	
	Partitions	Second floor boys	2	EA	7	10+ years	
	Urinals	Second floor boys	5	EA	6	10+ years	
	Walls - Structural Glazed Tile	Second floor boys	376	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	Second floor boys	80	SF	6	10+ years	
	Water Closet	Second floor boys	2	EA	6	10+ years	
	Accessories	Second floor girls near 213	325	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Second floor girls near 213	295	SF	6	10+ years	
	Ceiling - Plaster/Drywall	Second floor girls near 213	30	SF	4	0-1 year	Water damage
	Floor - Tile Ceramic/ Porcelain	Second floor girls near 213	325	SF	6	10+ years	•
	Floor Drain	Second floor girls near 213	1	EA	7	10+ years	
	Hand Dryer	Second floor girls near 213	2	EA	7	10+ years	
	Lavatory	Second floor girls near 213	3	EA	7	10+ years	
	Lighting - Pendent/Surface	Second floor girls near 213	5	EA	7	6-10 years	
	Partitions	Second floor girls near 213	9	EA	7	10+ years	
	Walls - Structural Glazed Tile	Second floor girls near 213	728	SF	7	10+ years	
	Water Closet	Second floor girls near 213	9	EA	7	10+ years	
Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #101 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	698	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	12	SF	6	10+ years	Peeling paint
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	· .
						•	



Catego	ry : Classroom		В	uilding	: Main		· ·
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	1st Floor	9	SF	7	6-10 years	
	Floor - Wood	1st Floor	701	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	42	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,178	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	100	SF	6	1-2 years	Peeling paint
_Classroo	om #102 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	726	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Moisture related stain
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	Worsture related stair
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	736	SF	7	•	
		1st Floor		EA	7	10+ years	
	Lighting - Pendent/Surface		14	LF		6-10 years	
	Marker Board	1st Floor	44		7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,285	SF	7	10+ years	NA
	Walls - Plaster/Drywall	1st Floor	3	SF	5	1-2 years	Water damage
Classroo	om #103 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	22	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	686	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	18	SF	5	1-2 years	Water damage.
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	· ·
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	704	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,276	SF	6	10+ years	Peeling paint throughout
Classroo	om #104 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	700	SF	7	10+ years	
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood Doors Inclu IIW	1st Floor	700	SF	7		
						10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	51	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,246	SF	6	10+ years	5
	Walls - Plaster/Drywall	1st Floor	30	SF	5	1-2 years	Damage.

Campus Name: Volta Page : 18 of 47 Assessment Date: 02/19/2024



Category : Classroom			В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
01	#405 (D Ol)						
Classroo	om #105 (Regular Classroom)	4 - 4 - 51			7	0.40	
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	706	SF	6	10+ years	Damanad
	Ceiling - Plaster/Drywall	1st Floor	35	SF	5	1-2 years	Damaged.
	Doors - Transom Window	1st Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Wood	1st Floor	741	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,283	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	14	SF	5	1-2 years	Damaged.
Classroo	om #107 (Art Room)						
<u> </u>	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	716	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	20	SF	5	1-2 years	Water damage.
	Doors - Transom Window	1st Floor	6	SF	7	•	water damage.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years 10+ years	
	Floor - Tile		•	SF	6	•	
		1st Floor 1st Floor	730	SF SF	4	10+ years	Cracked shifted tile
	Floor - Tile		6			1-2 years	Cracked Shirted tile
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,138	SF	6	10+ years	144.4
	Walls - Plaster/Drywall	1st Floor	150	SF	5	1-2 years	Water damage.
_Classroo	om #108 (Office)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	694	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	28	SF	5	1-2 years	Water damage.
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	•
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Wood	1st Floor	722	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	14	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	44	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,230	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	48	SF	5	1-2 years	Water damage.
Closs	m #100 (Multi Durn and Dages)						
_Ciassroc	om #109 (Multi Purpose Room)	4 -4 Fl.				0.40	
	AC Units	1st Floor	2	EA	7	6-10 years	

Campus Name: Volta Page : 19 of 47 Assessment Date: 02/19/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	20	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,021	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	15	SF	5	1-2 years	Water damage.
	Doors - Transom Window	1st Floor	78	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,024	SF	7	10+ years	
	Floor - Tile	1st Floor	12	SF	4	1-2 years	Cracked and damaged til
	Lighting - Pendent/Surface	1st Floor	18	EA	6	6-10 years	
	Marker Board	1st Floor	29	LF	6	6-10 years	
	Storage/ Closet	1st Floor	257	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,562	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	5	1-2 years	Damaged wall finish
Classroo	om #110 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	738	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	718	SF	7	10+ years	
	Floor - Tile	1st Floor	20	SF	4	1-2 years	Cracked tile
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	Oracked tile
	Marker Board	1st Floor	46	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,276	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	6	6-10 years	
Classro	om #201 (Regular Classroom)						
Classion	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	714	SF	7	10+ years	
	Doors - Hardware	2nd Floor	1	EA	6	6-10 years	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Bools Ilicia IIW	2nd Floor	714	SF	7		
	Lighting - Pendent/Surface	2nd Floor 2nd Floor	14	EA	7	10+ years 6-10 years	
	Marker Board	2nd Floor 2nd Floor	38	LF	7	•	
	Walls - Plaster/Drywall	2nd Floor 2nd Floor	1,205	SF	6	6-10 years 10+ years	
	Walls - Plaster/Drywall Walls - Plaster/Drywall	2nd Floor	75	SF	4	0-1 year	Cracked
	•					,	
Classroo	om #202 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	733	SF	7	10+ years	

Campus Name: Volta Page : 20 of 47 Assessment Date: 02/19/2024



Catego	Category : Classroom		В	uilding	: Main		<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	733	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	1-2 years	Water damage.
Classroo	om #203 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	700	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	700	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	52	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,255	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	25	SF	5	1-2 years	Water damage.
	walls - Flaster/Drywall	2110 1 1001	23	OI .	3	1-2 years	water damage.
_Classroo	om #204 (Regular Classroom)	0.15					
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	7	10+ years	
	Doors - Hardware	2nd Floor	2	EA	6	2-5 years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	725	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,282	SF	5	10+ years	
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Cracked
Classroo	om #205 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	740	SF	7	10+ years	
	Doors - Transom Window	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Wood	1st Floor	730	SF	7	10+ years	
	Floor - Wood	1st Floor	10	SF	4	1-2 years	Damaged
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	~3~~
	Marker Board	1st Floor	44	LF	7	6-10 years	
	marker Board	1001	7-7		•	J 10 yours	

Campus Name: Volta Page : 21 of 47 Assessment Date: 02/19/2024



Catego	ory : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,290	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	10	SF	5	0-1 year	Water damage.
Classro	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	730	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
	Floor - Wood	2nd Floor	680	SF	7	10+ years	
	Floor - Wood	2nd Floor	50	SF	4	1-2 years	Bubbling and damaged
	Lighting - Pendent/Surface	2nd Floor	14	ĒΑ	7	6-10 years	- aramig and daming a
	Marker Board	2nd Floor	22	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,292	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	8	SF	5	1-2 years	Water damage.
Classro	om #209 (Regular Classroom)						
Olassio	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	725	SF	7	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood Bools Inclu IIW	2nd Floor	725	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	48	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	6	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	5	1-2 years	Water damage.
	vvalis i lasten brywan	2110 1 1001	20	Oi.	J	1 Z years	water damage.
_Classro	om #210 (Music Room)	0.15					
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	737	SF	6	10+ years	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Wood	2nd Floor	737	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	32	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,282	SF	7	10+ years	_
	Walls - Plaster/Drywall	2nd Floor	10	SF	5	0-1 year	Damaged.
Classro	om #211 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	9	LF	7	10+ years	
						-	



atego	ry : Classroom		В	uilding	: Main			
						Recommend		
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Plaster/Drywall	2nd Floor	710	SF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	15	SF	4	1-2 years	Water damage	
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Wood	2nd Floor	725	SF	7	10+ years		
	Lighting - Pendent/Surface	2nd Floor	14	EΑ	7	6-10 years		
	Marker Board	2nd Floor	22	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,257	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	35	SF	5	1-2 years	Damaged.	
lassroc	om #213 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor 2nd Floor	9	LF	7			
		2nd Floor 2nd Floor		SF		10+ years		
	Ceiling - Plaster/Drywall		731		5	10+ years		
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Wood	2nd Floor	711	SF	7	10+ years		
	Floor - Wood	2nd Floor	20	SF	4	1-2 years	Damaged.	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years		
	Marker Board	2nd Floor	48	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,282	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	10	SF	4	0-1 year	Water damage	
lassroc	om #215 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	9	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	744	SF	6	10+ years		
	Doors - Transom Window	2nd Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	-		
				SF		10+ years		
	Floor - Wood	2nd Floor	741		7	10+ years	Death is the en	
	Floor - Wood	2nd Floor	3	SF	4	1-2 years	Bubbling	
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years		
	Marker Board	2nd Floor	50	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,285	SF	6	10+ years		
	Walls - Plaster/Drywall	2nd Floor	12	SF	5	1-2 years	Damaged.	
lassroc	om #217 (Regular Classroom)							
	AC Units	2nd Floor	1	EA	7	6-10 years		
	Casework	2nd Floor	9	LF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	723	SF	7	10+ years		
	Ceiling - Plaster/Drywall	2nd Floor	8	SF	4	0-1 year	Water damage	
	Doors - Transom Window	2nd Floor	6	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Poors - Mood Pools lilely lim	ZIIU I IUUI	1	LA	,	TOT years		

Campus Name: Volta Page : 23 of 47 Assessment Date: 02/19/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Wood	2nd Floor	728	SF	7	10+ years	
	Floor - Wood	2nd Floor	3	SF	4	1-2 years	Bubbling
	Lighting - Pendent/Surface	2nd Floor	14	EA	7	6-10 years	
	Marker Board	2nd Floor	48	LF	7	6-10 years	
	Walls - Plaster/Drywall	2nd Floor	1,272	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	20	SF	4	0-1 year	Damaged.
Classroo	m #304 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	700	SF	6	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	30	SF	4	0-1 year	Water damage
	Chalk Board	3rd Floor	12	LF	4	2-5 years	Water damage
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	-	
						10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	50	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,206	SF	6	10+ years	_
	Walls - Plaster/Drywall	3rd Floor	30	SF	5	0-1 year	Damaged.
Classroo	nm #306 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	7	10+ years	
	Doors - Hardware	3rd Floor	1	EA	6	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	730	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,226	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	0-1 year	Big crack
	Work Sink	3rd Floor	10	EA	7	10+ years	Dig crack
Olaa	#207 /Damulay Ol\					•	
Ciassroo	om #307 (Regular Classroom)	0.151				0.40	
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	

Campus Name: Volta Page : 24 of 47 Assessment Date: 02/19/2024



Calego	ry : Classroom		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,236	SF	6	10+ years	
Classroo	om #308 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	12	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	726	SF	6	10+ years	
	Floor - Wood	3rd Floor	4	SF	4	0-1 year	Big crack
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	20	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,236	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Damaged.
Classroo	om #309 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	730	SF	6	10+ years	
	Chalk Board	3rd Floor	32	LF	4	2-5 years	
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	ĒA	7	10+ years	
	Floor - Wood	3rd Floor	730	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	25	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,226	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	0-1 year	Damaged.
Classroo	om #310 (Office)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	3rd Floor	396	SF	7	10+ years	
	Doors - Transom Window	3rd Floor	6	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years	
	Floor - Wood	3rd Floor	396	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	4	ĒΑ	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,035	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	20	SF	5	0-1 year	Big crack
Classroo	om #311 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	



Category : Classroom			В	uilding	: Main		
				_		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	3rd Floor	10	LF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	720	SF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	5	1-2 years	Water damage
	Chalk Board	3rd Floor	30	LF	4	2-5 years	3.1
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood Boors inclu riw	3rd Floor	730	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	•	
				LF		6-10 years	
	Marker Board	3rd Floor	25		7	10+ years	NA
	Walls - Plaster/Drywall	3rd Floor	12	SF	5	1-2 years	Water damage
	Walls - Plaster/Drywall	3rd Floor	1,224	SF	5	10+ years	
lassroc	om #313 (Regular Classroom)						
	AC Units	3rd Floor	1	EA	7	6-10 years	
	Casework	3rd Floor	10	LF	6	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	726	SF	5	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	4	SF	4	1-2 years	Water damage
	Doors - Transom Window	3rd Floor	12	SF	7	10+ years	Water damage
						•	
	Doors - Wood Doors inclu hw	3rd Floor	2	EA	7	10+ years	
	Floor - Wood	3rd Floor	730	SF	6	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Marker Board	3rd Floor	50	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	1,221	SF	6	10+ years	
	Walls - Plaster/Drywall	3rd Floor	10	SF	5	0-1 year	Water damage
lassroc	om #NA (Faculty Lounge)						
	Ceiling - Plaster/Drywall	2nd Floor	100	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor	100	SF	7	10+ years	
	Lighting - Pendent/Surface			EA	7		
		2nd Floor	2			6-10 years	
	Walls - Plaster/Drywall	2nd Floor	192	SF	7	10+ years	Damasad
	Walls - Plaster/Drywall	2nd Floor	8	SF	5	0-1 year	Damaged.
atego	ry : Interior		В	uilding	: Main		
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
orridor	,	Location	Quantity	COIVI	IVALIA	Replacement	Oonillicits
	Ceiling - Plaster/Drywall	1st Floor	5,148	SF	6	10+ years	
	Doors - Transom Window	1st Floor	44	SF	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	8	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	3	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	2,016	SF	6	10+ years	
			2,016 3,097	SF SF	6 7	6-10 years	
	Floor - Tile/Sheet	1st Floor	3.097	ЭF	1	o- io vears	

Campus Name: Volta Page : 26 of 47 Assessment Date: 02/19/2024



Catego	Category : Interior		В	uilding	: Main		, , , , , , , , , , , , , , , , , , , ,
	,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	1st Floor	30	SF	4	1-2 years	Cracked and damaged tile
	Floor - Tile/Sheet	1st Floor	5	SF	4	1-2 years	Damaged 9x9 tile
	Lighting - Pendent/Surface	1st Floor	58	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	149	EA	6	10+ years	
	Student Lockers - One Tier	1st Floor	14	EA	6	1-2 years	Refinish lockers
	Walls - Plaster/Drywall	1st Floor	6,220	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor	5,138	SF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	3,760	SF	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	3	EA	7	10+ years	
	Floor - Terrazzo	2nd Floor	610	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,146	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	, ₄	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	2nd Floor	22	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	185	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	3,730	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	3,605	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	3,750	SF	7	10+ years	
	Ceiling - Plaster/Drywall	3rd Floor	10	SF	4	1-2 years	Peeling
	Drinking Fountains - Single Fountain	3rd Floor	2	ĒΑ	7	10+ years	
	Floor - Terrazzo	3rd Floor	610	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	3,150	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	22	ĒΑ	7	6-10 years	
	Student Lockers - One Tier	3rd Floor	185	EA	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	1,500	SF	7	10+ years	
	Walls - Structural Glazed Tile	3rd Floor	2,120	SF	7	10+ years	
Stairs							
	Ceiling - Plaster/Drywall	Auditorium stairs	30	SF	7	10+ years	
	Floor - Terrazzo	Auditorium stairs	76	SF	7	10+ years	
	Handrails	Auditorium stairs	44	LF	7	10+ years	
	Stairs - Terrazzo	Auditorium stairs	24	LF	7	10+ years	
	Walls - Plaster/Drywall	Auditorium stairs	121	SF	7	10+ years	
	Walls - Plaster/Drywall	Auditorium stairs	6	SF	4	1-2 years	Huge damage
	Ceiling - Plaster/Drywall	North East	263	SF	7	10+ years	. rago damago
	Floor - Terrazzo	North East	523	SF	7	10+ years	
	Handrails	North East	70	LF	7	10+ years	
	Lighting - Pendent/Surface	North East	6	EA	7	6-10 years	
	Stairs - Terrazzo	North East	44	LF	7	10+ years	
	Walls - Plaster/Drywall	North East	876	SF	7	10+ years	
	Walls - Structural Glazed Tile	North East	886	SF	7	10+ years	
	Ceiling - Plaster/Drywall	North West	263	SF	7	10+ years	
	Floor - Terrazzo	North West	794	SF	7	10+ years	
	Handrails	North West	141	LF	7	10+ years	
	Lighting - Pendent/Surface	North West	9	EA	7	6-10 years	
	5g		Ŭ	<u> </u>	•	2 . 2 , 5 5	

Campus Name: Volta Page : 27 of 47 Assessment Date: 02/19/2024



Catego	ry : Interior	·	В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Stairs - Terrazzo	North West	58	LF	7	10+ years	
	Walls - Plaster/Drywall	North West	544	SF	7	10+ years	
	Walls - Structural Glazed Tile	North West	544	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South East	263	SF	7	10+ years	
	Floor - Terrazzo	South East	523	SF	7	10+ years	
	Handrails	South East	70	LF	7	10+ years	
	Lighting - Pendent/Surface	South East	6	EA	7	6-10 years	
	Stairs - Terrazzo	South East	44	LF	7	10+ years	
	Walls - Plaster/Drywall	South East	886	SF	7	10+ years	
	Walls - Structural Glazed Tile	South East	886	SF	7	10+ years	
	Ceiling - Plaster/Drywall	South West	283	SF	7	10+ years	
	Floor - Terrazzo	South West	794	SF	7	10+ years	
	Handrails	South West	141	LF	7	10+ years	
	Lighting - Pendent/Surface	South West	9	EA	7	6-10 years	
	Stairs - Terrazzo	South West	58	LF	7	10+ years	
	Walls - Plaster/Drywall	South West	544	SF	7	10+ years	
	Walls - Structural Glazed Tile	South West	544	SF	7	10+ years	

Campus Name: Volta Page : 28 of 47 Assessment Date: 02/19/2024





Catego	ry : Exterior		В	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Entrance						•	
	Entrance Control - Audio	Door 7 - East	1	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 7 - East	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	Door 7.5 - South	1	EA	6	10+ years	
	Exterior Stairs - Concrete	Door 7.5 - South	4	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	Door 8 - West	2	EA	6	10+ years	
Foundat	ion						
	Foundation - Concrete	Entire Building	614	LF	7	10+ years	
	Superstructure - Slab on Grade	Entire Building	17,176	SF	7	10+ years	
Lighting							
- 0 0	Exterior Lighting - Wall Mounted	Entire Building	7	EA	6	10+ years	
Roof Sys	stem						
	Chimney - Metal Flue	Main Roof	14	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	36	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	30	LF	5	1-2 years	Damaged gutters and disconnected downspouts
	Roof - Metal	Main Roof	19,633	SF	6	10+ years	
	Roof - Metal	Main Roof	200	SF	4	1-2 years	Ice guards have fallen off the roof
	Roof Structure - Heavy Timber	Main Roof	19,833	SF	7	10+ years	
Walls							
	Canopy - Metal	Entire Building	54	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	6,447	SF	6	10+ years	
Windows	3						
	Guard - Guards perforated	Entire Building	1,851	SF	6	10+ years	
	Lintels - Concrete	Entire Building	291	LF	6	10+ years	
	Lintels - Steel	Entire Building	15	LF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,813	SF	6	10+ years	
Catego	ry : Electrical		В	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	ncy System						
	Security System - CCTV	Entire Building	17,176	SF	5	2-5 years	Exterior CCTV only. Reason and Priority Rep adjusted as the system is 25-plus years old and has exceeded its anticipated service life.

Campus Name: Volta Page : 29 of 47 Assessment Date: 02/19/2024



Catego	ry : Electrical		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Security System - Intrusion Detection	Entire Building	17,176	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	2	0-1 year	Signs have no backup batteries and the school has no emergency generator.
	Emergency A/C Power - Corridors and Stairs	Entire Building	2,204	SF	6	6-10 years	
	Automatic Transfer Switch	Entire Building	1	EA	6	6-10 years	
/lain Se	rvice						
	Main Electrical Service - 800 A and 120/208/3PH	Electrical Room	1	EA	7	10+ years	
	Independent Electrical Service for emergency power	Electrical Room	1	EA	7	10+ years	
	PA System	Entire Building	17,176	SF	6	6-10 years	Served by Main.
ower D	istribution						
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	6	10+ years	
	Lighting and Power Panels - 100 A	Electrical Room	1	EA	4	0-1 year	Rank, Reason and Priority Rep changed as open fuse receptacles expose live conductors presenting a live front condition.
	Lighting and Power Panels - Above 100 A	Electrical Room	4	EA	6	10+ years	
	Main Distribution Panels - 400 - 600 amp	Electrical Room	1	EA	6	10+ years	
	Main Distribution Panels - Greater than 600 amp	Electrical Room	1	EA	7	6-10 years	

Category: Fire Protection Building: Annex

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Fire Alar	m Fire Alarm Panel	Entire Building	1	EA	7	6-10 years	Reason and Priority Rep adjusted as the panel is 25-plus years old, employs antiquated technology, and has exceeded its anticipated service life.
	Fire Alarm Strobe Lights	Entire Building	17,176	SF	4	2-5 years	Based on current observations, the Rank, Reason and Priority Rep changed as the system is 25-plus years old and has exceeded its anticipated service life.
	Fire Alarm_System	Entire Building	17,176	SF	4	2-5 years	Reason and Priority Rep adjusted as the system is 25-plus years old and beyond its anticipated service life.

Campus Name: Volta Page : 30 of 47 Assessment Date: 02/19/2024



Catego	ry : Fire Protection		В	uilding	: Annex		<u> </u>
	Ham Time	Location				Recommend	Commonto
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Sprinkler	System						
	Sprinkler Heads	Entire Building	17,176	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	17,176	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	17,176	SF	6	6-10 years	Location changed for clarification.
Catego	ry : Mechanical		R	uildina	: Annex		
Categor	y . Mechanical		<u>_</u>	unung	. Alliex	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Hand	ling Systems		•			•	
	Make Up Air Unit- Indoor Mounted- Hot Water Coils - 6000 - 10,000 cfm	Boiler Room	1	EA	6	6-10 years	
Boiler Sy	stems						
,	Boiler Auxiliary- Non Condensing Hot Water - 1001 - 2000 MBH	Boiler Room	2	EA	6	6-10 years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	2-5 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	Quantity changed to match current observations. There are three damper assemblies but one is a thermostat-controlled boiler room venting damper and not a boiler system combustion damper.
	Non Condensing- Flexible Tube- Atmospheric- Hot Water Boiler - 1001 - 2000 MBH	Boiler Room	2	EA	5	2-5 years	B-1 and B-2. Leak-free at the time of assessment but signs of considerable corrosion and past leaks to the extenthat the boilers have prematurely reached the end of their anticipated service life.
	Water Fill System	Boiler Room	1	EA	6	2-5 years	
Heating I	Devices Unit Heater - Hot Water	Boiler Room, Plumbing Room	2	EA	6	6-10 years	Location changed for clarification.
	Offit Heater - Hot Water	Bollet Room, Plumbing Room	2	EA	б	6-10 years	One each is located in the Boiler Room and the Plumbing Room.
	Cabinet Heaters - With Hot Water Coil	Entire Building	6	EA	6	6-10 years	
Maahasi	cal Plumbing						
wechani	Hot Water Pump - Less than 10	Boiler Room	1	EA	6	6-10 years	Rank, Reason and Priority Rep
			·		Ü	o io youio	adjusted based on current observations that although the pump shows signs of previous leaks, it is operating as intended with no leaks

Campus Name: Volta Page : 31 of 47 Assessment Date: 02/19/2024



Catego	ry : Mechanical		В	uilding	: Annex		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
		D. 1. D.	4	_^		0.40	or undue vibration.
	Hot Water Pump - Less than 10 Hydronic Supply and Return - Copper	Boiler Room	1 800	EA LF	6 6	6-10 years	
	Hydronic Supply and Return - Copper	Entire Building	800	LF	0	10+ years	
Tempera	iture Control						
тотпропо	Electric Controls	Entire Building	500	SF	6	6-10 years	
	Electric Thermostat	Entire Building	3	EA	6	6-10 years	Quantity changed to match current
							observations. Two are located in the
							Boiler Room and one is located in the
							Plumbing Room.
Unit Ven	tilation						
OIII VOII	Unit Ventilators- Floor Mounted- Hot Water	Entire Building	13	EA	5	6-10 years	Priority Rep adjusted based on
	w/ DX Cooling Coil & w/ Self Contained	Ŭ				,	current observations that the
	Compressors						equipment is original to the building
							but well-maintained and fully
							operational at the time of assessment.
							addeddifferit.
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 500 - 1500	Roof	1	EA	6	6-10 years	Not directly accessible in a safe
	CFM						manner at due to sloped roof and
							unreliable climbing means which could not be made safe at the time o
							assessment. Condition verified by
							the Building Engineer.
	Exhaust Fans- Roof Mounted - Greater than	Roof	1	EA	6	6-10 years	Not directly accessible in a safe
	8000 CFM						manner at due to sloped roof and
							unreliable climbing means which could not be made safe at the time o
							assessment. Condition verified by
							the Building Engineer.
	Exhaust Fans- Roof Mounted - Less than	Roof	1	EA	6	6-10 years	Not directly accessible in a safe
	500 CFM						manner at due to sloped roof and
							unreliable climbing means which could not be made safe at the time of
							assessment. Condition verified by
							the Building Engineer.
_			_		_		
Catego	ry : Plumbing		В	uilding	: Annex		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	item - Type	Location	Quantity	OCIVI	Naiik	Replacement	Comments

Campus Name: Volta Page : 32 of 47 Assessment Date: 02/19/2024



Category: Plumbing

Other Cooling Unit

Mechanical/ Service Rooms

Boiler Room

Alessandro Volta Elementary School 4950 N Avers AVENUE, Chicago, IL 60625

0	11 T	1 0	0	11014	D I-	Danisa	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heater - Less than 150000 BTU/HR	Plumbing Room	1	EA	4	2-5 years	Rank, Reason and Priority Rep changed as unit is 25-plus years old and has exceeded its anticipated service life.
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	17,176	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	17,176	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	17,176	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	17,176	SF	6	10+ years	
	Sanitary Piping	Entire Building	17,176	SF	6	10+ years	
	Vent Piping	Entire Building	17,176	SF	6	10+ years	
Catego	ry : Room		В	uilding	: Annex		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	trative Suites/Offices						
	Ceiling - Lay-in	100	360	SF	7	10+ years	
	Doors - Steel Doors incl hw	100	1	EA	7	10+ years	
	Floor - Tile	100	360	SF	7	10+ years	
	Lighting - Lay-in	100	4	EA	7	6-10 years	
	Power Distribution	100	6	EA	7	10+ years	
	Walls - Concrete Block	100	200	SF	7	10+ years	
	Walls - Plaster/Drywall	100	600	SF	7	10+ years	
	Ceiling - Lay-in	Counselor	193	SF	7	10+ years	
	Doors - Steel Doors incl hw	Counselor	1	EΑ	7	10+ years	
	Floor - Tile	Counselor	193	SF	7	10+ years	
	Lighting - Lay-in	Counselor	3	EA	7	6-10 years	
	Power Distribution	Counselor	2	EA	7	10+ years	
	Walls - Concrete Block	Counselor	204	SF	7	10+ years	
	Walls - Plaster/Drywall	Counselor	295	SF	7	10+ years	
MDF_ID	F						
_	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Finishes	1st Floor	85	SF	7	10+ years	
	Other Cooling Unit	1st Floor	1	EA	7	2-5 years	PTAC.
	Other Ceeling Unit	10t Floor	,		-	4 0	Not be use

1st Floor

1st Floor

Building: Annex

Recommend

Campus Name: Volta Page: 33 of 47 Assessment Date: 02/19/2024

EΑ

SF

255

5

7

1-2 years

10+ years

Not in use



Catego	ry : Room		В	Building : Annex			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Janitor's Closet	1st Floor	38	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	65	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	285	SF	7	10+ years	
						, , , , , , , , , , , , , , , , , , , ,	
Restrooi	n						
	Accessories	1st Floor	630	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	630	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	630	SF	7	10+ years	
	Floor Drain	1st Floor	2	EA	7	10+ years	
	Lavatory	1st Floor	4	EA	7	10+ years	
	Lighting - Lay-in	1st Floor	5	EA	7	6-10 years	
	Partitions	1st Floor	3	EA	7	10+ years	
	Urinals	1st Floor	8	EΑ	7	10+ years	
	Walls - Concrete Block	1st Floor	980	SF	7	10+ years	
	Water Closet	1st Floor	3	EA	7	10+ years	
	Accessories	1st Floor	630	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	630	SF	7	10+ years	
	Floor - Concrete Epoxy/ Painted	1st Floor	630	SF	7	,	
	Floor Drain	1st Floor		EA		10+ years	
			2		7	10+ years	
	Lavatory	1st Floor	4	EΑ	7	10+ years	
	Lighting - Lay-in	1st Floor	5	EΑ	7	6-10 years	
	Partitions	1st Floor	11	EA	7	10+ years	
	Walls - Concrete Block	1st Floor	980	SF	7	10+ years	
	Water Closet	1st Floor	11	EA	7	10+ years	
	Accessories	North	44	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	North	44	SF	7	10+ years	
	Doors - Steel Doors incl hw	North	1	EA	7	10+ years	
	Floor - Tile	North	38	SF	7	10+ years	
	Floor - Tile	North	6	SF	4	1-2 years	Cracking tile
	Floor Drain	North	1	EA	7	10+ years	
	Lavatory	North	1	EA	7	10+ years	
	Lighting - Pendent/Surface	North	1	EA	5	1-2 years	Missing cover
	Walls - Concrete Block	North	90	SF	7	10+ years	3
	Water Closet	North	1	ĒΑ	7	10+ years	
	Accessories	South	44	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	South	44	SF	7	10+ years	
	Doors - Wood Doors inclu hw	South	1	EA	7	10+ years	
	Floor - Tile	South	44	SF	4	1-2 years	Damaged tile
	Floor Drain	South	1	EA	7	10+ years	Damagod tilo
	Lavatory	South	1	EA	7	10+ years	
	Lighting - Pendent/Surface	South	1	EA	5	1-2 years	Missing cover
	Walls - Concrete Block		•	SF	5 7	•	wissing cover
		South	90			10+ years	
	Water Closet	South	1	EA	7	10+ years	



Catego	ategory : Classroom		В	Building : Annex			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #120 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	854	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	16	SF	4	1-2 years	Stained tile
	Chalk Board	1st Floor	12	ĹF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	870	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	740	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	300	SF	7	10+ years	
:lassroo	m #121 (Computer Lab)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	864	SF	7	10+ years	
	Ceiling - Lay in	1st Floor	6	SF	4	0-1 year	Missing.
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	Missing.
	Floor - Tile	1st Floor	862	SF	6	2-5 years	
	Floor - Tile	1st Floor	8	SF	4	1-2 years	Cracked tile
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	Cracked tile
	Marker Board	1st Floor	24	LF	7	6-10 years	
			738	SF	7	-	
	Walls - Concrete Block Walls - Concrete Block	1st Floor 1st Floor	736	SF SF	, 5	10+ years	Cracked block
	Walls - Plaster/Drywall	1st Floor	300	SF	7	1-2 years 10+ years	Clacked block
	Wireless System	1st Floor	1	EA	7	10+ years 10+ years	
	Wileless System	150 11001	ı	LA	1	10+ years	
Classroo	m #122 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	870	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	870	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	9	EΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	440	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	600	SF	7	10+ years	
lassroo	m #123 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	870	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	850	SF	7	10+ years	
				SF			

Campus Name: Volta Page : 35 of 47 Assessment Date: 02/19/2024



Catego	ry : Classroom		В	uilding	: Annex		Ţ
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	440	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	600	SF	7	10+ years	
Classroo	om #124 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	870	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	· <u>-</u> 1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	864	SF	7	10+ years	
	Floor - Tile	1st Floor	6	SF	4	1-2 years	Cracked tile
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	5.33Not 110
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	740	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	300	SF	7	10+ years	
	vvalis - Flastei/Drywali	151 -1001	300	Si	,	10+ years	
Classroo	om #125 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	870	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	852	SF	7	10+ years	
	Floor - Tile	1st Floor	18	SF	4	1-2 years	Cracked tiles
	Lighting - Lay-in	1st Floor	9	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	440	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	600	SF	6	10+ years	
Classroo	om #126 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Casework Ceiling - Lay-in	1st Floor	870	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Steel Doors incl hw	1st Floor	12	EA	7	10+ years	
	Floor - Tile	1st Floor	870	SF	7	10+ years 10+ years	
					7		
	Lighting - Lay-in Marker Board	1st Floor 1st Floor	9	EA		6-10 years	
			12	LF CF	7	6-10 years	
	Walls - Concrete Block	1st Floor	440	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	600	SF	7	10+ years	
Classroo	om #127 (Regular Classroom)						
	Casework	1st Floor	20	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	870	SF	7	10+ years	
	3 - 7		5.0	=:-	-	· ,	



Casework 1st Floor 20 LF 7 10+ years Ceiling - Lay-in 1st Floor 870 SF 7 10+ years Chalk Board 1st Floor 12 LF 4 2-5 years Doors - Steel Doors incl hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 870 SF 7 10+ years Lighting - Lay-in 1st Floor 9 EA 7 6-10 years Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 440 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years Classroom #129 (Kindergarten)	
Chalk Board	
Doors - Steel Doors incl hw	
Floor - Tile	
Lighting - Lay-in	
Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 440 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years Classroom #128 (Kindergarten) 20 LF 7 10+ years Casework 1st Floor 870 SF 7 10+ years Ceiling - Lay-in 1st Floor 12 LF 4 2-5 years Doors - Steel Doors incl hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 870 SF 7 10+ years Lighting - Lay-in 1st Floor 9 EA 7 6-10 years Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 440 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years	
Walls - Concrete Block Walls - Plaster/Drywall 1st Floor 440 SF 7 10+ years Classroom #128 (Kindergarten) Casework Sework Ceiling - Lay-in Sework Ser 7 1st Floor Ser 7 10+ years Chalk Board Ser 7 1st Floor Ser 7 10+ years Chalk Board Ser 7 1st Floor Ser 7 10+ years Ser 7 10+ y	
Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years Classroom #128 (Kindergarten) Casework 1st Floor 20 LF 7 10+ years Ceiling - Lay-in 1st Floor 870 SF 7 10+ years Chalk Board 1st Floor 12 LF 4 2-5 years Doors - Steel Doors incl hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 870 SF 7 10+ years Lighting - Lay-in 1st Floor 9 EA 7 6-10 years Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 440 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years	
Classroom #128 (Kindergarten) Casework 1st Floor 20 LF 7 10+ years Ceiling - Lay-in 1st Floor 870 SF 7 10+ years Chalk Board 1st Floor 12 LF 4 2-5 years Doors - Steel Doors incl hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 870 SF 7 10+ years Lighting - Lay-in 1st Floor 9 EA 7 6-10 years Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 440 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years	
Casework 1st Floor 20 LF 7 10+ years Ceiling - Lay-in 1st Floor 870 SF 7 10+ years Chalk Board 1st Floor 12 LF 4 2-5 years Doors - Steel Doors incl hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 870 SF 7 10+ years Lighting - Lay-in 1st Floor 9 EA 7 6-10 years Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 440 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years Classroom #129 (Kindergarten)	
Casework 1st Floor 20 LF 7 10+ years Ceiling - Lay-in 1st Floor 870 SF 7 10+ years Chalk Board 1st Floor 12 LF 4 2-5 years Doors - Steel Doors incl hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 870 SF 7 10+ years Lighting - Lay-in 1st Floor 9 EA 7 6-10 years Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 440 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years	
Ceiling - Lay-in 1st Floor 870 SF 7 10+ years Chalk Board 1st Floor 12 LF 4 2-5 years Doors - Steel Doors incl hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 870 SF 7 10+ years Lighting - Lay-in 1st Floor 9 EA 7 6-10 years Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 440 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years Classroom #129 (Kindergarten)	
Chalk Board 1st Floor 12 LF 4 2-5 years Doors - Steel Doors incl hw 1st Floor 1 EA 7 10+ years Floor - Tile 1st Floor 870 SF 7 10+ years Lighting - Lay-in 1st Floor 9 EA 7 6-10 years Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 440 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years	
Doors - Steel Doors incl hw	
Floor - Tile	
Lighting - Lay-in 1st Floor 9 EA 7 6-10 years Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 440 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years	
Marker Board 1st Floor 12 LF 7 6-10 years Walls - Concrete Block 1st Floor 440 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years Classroom #129 (Kindergarten)	
Walls - Concrete Block 1st Floor 440 SF 7 10+ years Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years Classroom #129 (Kindergarten)	
Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years Classroom #129 (Kindergarten)	
Consularly 10t Electrical 20 LE 7 10 years	
Ceiling - Lay-in 1st Floor 866 SF 7 10+ years	
Ceiling - Lay-in 1st Floor 4 SF 4 1-2 years Stained tile	
Chalk Board 1st Floor 12 LF 4 2-5 years	
Doors - Steel Doors incl hw 1st Floor 1 EA 7 10+ years	
Floor - Tile 1st Floor 857 SF 7 10+ years	
Floor - Tile 1st Floor 13 SF 4 1-2 years Cracking tile	es
Lighting - Lay-in 1st Floor 9 EA 7 6-10 years	
Marker Board 1st Floor 12 LF 7 6-10 years	
Walls - Concrete Block 1st Floor 440 SF 7 10+ years	
Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years	
_Classroom #130 (Kindergarten)	
Casework 1st Floor 20 LF 7 10+ years	
Ceiling - Lay-in 1st Floor 870 SF 7 10+ years	
Doors - Steel Doors incl hw 1st Floor 1 EA 7 10+ years	
Floor - Tile 1st Floor 860 SF 7 10+ years	
Floor - Tile 1st Floor 10 SF 4 1-2 years Cracked tile	es
Lighting - Lay-in 1st Floor 9 EA 7 6-10 years	
Marker Board 1st Floor 12 LF 7 6-10 years	
Walls - Concrete Block 1st Floor 440 SF 7 10+ years	
Walls - Plaster/Drywall 1st Floor 600 SF 7 10+ years	
1. a	



/ l	UOM		Recommend	
/ l	HOM			
	00111	Rank	Replacement	Comments
20	LF	7	10+ years	
' 0	SF	7	10+ years	
1	EA	7	10+ years	
8	SF	7	10+ years	
2	SF	4	1-2 years	Cracked tile
9	EA	7	6-10 years	
2	LF	7	6-10 years	
10	SF	7	10+ years	
00	SF	7	10+ years	
1	20 70 1 58 12 9 12 10	70 SF 1 EA 58 SF 12 SF 9 EA 12 LF	70 SF 7 1 EA 7 58 SF 7 12 SF 4 9 EA 7 12 LF 7	70 SF 7 10+ years 11 EA 7 10+ years 12 SF 4 1-2 years 14 EA 7 6-10 years 15 EA 7 6-10 years 16 SF 7 10+ years 17 EA 7 6-10 years 18 EA 7 6-10 years 19 EA 7 6-10 years 19 EA 7 10+ years

Category : Interior **Building: Annex**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Corridor							
	Ceiling - Lay-in	1st Floor	2,030	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	174	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	9	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	6-10 years	
	Drinking Fountains - Single Fountain	1st Floor	1	EA	7	6-10 years	
	Floor - Tile Quarry	1st Floor	174	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	2,005	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	25	SF	4	1-2 years	Cracked tile
	Lighting - Lay-in	1st Floor	22	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	4,642	SF	7	10+ years	

Campus Name: Volta Page : 38 of 47 Assessment Date: 02/19/2024





Category: Exterior Building: Modular 1 (2-Classroom) Recommend Location Replacement Comments Item - Type Quantity **UOM** Group Rank Entrance FΑ Exterior Doors - Exterior Steel Door Door 10 - Southwest 1 6 10+ years LF 6 Door 10 - Southwest 20 10+ years Exterior Stairs - Wood LF Stair Handrail - Wood Stair Handrail Door 10 - Southwest 20 6 10+ years Entrance Control - Audio and Video Door 11 - North 1 EΑ 7 10+ years Exterior Doors - Exterior Steel Door Door 11 - North 2 EΑ 6 10+ years LF 7 Exterior Stairs - Steel or Aluminum Door 11 - North 36 10+ years LF Ramp Handrail - Steel_Ramp Handrail Door 11 - North 60 7 10+ years Ramps - Steel or Aluminum Door 11 - North 30 LF 7 10+ years LF Stair Handrail - Steel Stair Handrail Door 11 - North 30 7 10+ years Exterior Doors - Exterior Steel Door FΑ Door 9 - Southeast 5 1-2 years 1 Corroded frame Exterior Stairs - Wood Door 9 - Southeast 20 LF 6 10+ years LF Stair Handrail - Wood Stair Handrail Door 9 - Southeast 20 10+ years Foundation LF 7 Foundation - Masonry **Entire Building** 233 10+ years Superstructure - Heavy Timber SF **Entire Building** 3,042 7 10+ years Lighting Exterior Lighting - Wall Mounted 8 FΑ 6 **Entire Building** 10+ years Roof System **Downspouts - Exterior Downspouts** Main Roof LF 248 5 6-10 years Repaired Roof - Metal Main Roof 3,042 SF 7 10+ years New roof SF Roof Structure - Heavy Timber Main Roof 3.042 10+ years Walls Exterior Walls - Wood Siding **Entire Building** SF 7 200 6-10 years Repaired SF Exterior Walls - Wood Siding **Entire Building** 2,272 6 10+ years Windows Guard - Guards perforated SF **Entire Building** 240 6 10+ years Guard - Guards wire guard **Entire Building** 16 SF 5 1-2 years Corroded guard frame Windows - Sash Aluminum Double-pane SF 6 **Entire Building** 240 10+ years Category: Electrical Building: Modular 1 (2-Classroom) Recommend Group Item - Type Location Quantity UOM Rank Replacement Comments Emergency System Security System - Intrusion Detection **Entire Building** 2,100 SF 6 6-10 years Exit Signs - Corridors and Stairs **Entire Building** EΑ 2 0-1 year Quantity changed as there is one 1

Campus Name: Volta Page : 39 of 47 Assessment Date: 02/19/2024



Catego	ry : Electrical		В	uilding	: Modul	ar 1 (2-Classro	oom)
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	comments corridor exit sign, and four of the previously documented exit signs are in classrooms. Sign has no backup battery and the school has no emergency generator.
	Emergency Battery Packs - Corridors and Stairs	Entire Building	2	EA	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	1	EA	2	0-1 year	Battery pack at primary entrance to Modular 1 is nonfunctional and damaged beyond reasonable repair.
Power D	istribution						
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Modul	ar 1 (2-Classro	om)
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar		20041011	Quantity	00	rtaint	rtopiasomont	
	Fire Alarm Panel Fire Alarm_System	Entire Building Entire Building	2,100	EA SF	3	2-5 years 2-5 years	System remains operational and passes inspection, however Reason and Priority Rep adjusted as the system is 25-plus years old, employs antiquated technology, and has exceeded its anticipated service life. Rank, Reason and Priority Rep adjusted as the system is 25-plus years old, does not include any strobe lights, and has exceeded its anticipated service life.
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (2-Classro	om)
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Tempera	Electric Thermostat	Entire Building	4	EA	6	6-10 years	Quantity changed to match current observations.
Unit Ven							
	Unit Ventilators - Vertical Package Electric Heat & Self Contained Cooling	Entire Building	4	EA	4	2-5 years	Rank and Reason adjusted as the units are 25-plus years old and beyond their EUL. Dataplates of the equipment are not present.

Campus Name: Volta Page : 40 of 47 Assessment Date: 02/19/2024



Alessandro Volta Elementary School

	Public Schools						4950 N Avers AVENUE, Chicago, IL 60625
Catego	ry : Mechanical		В	uilding	: Modul	ar 1 (2-Classro	oom)
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Ventilation	on						
	Exhaust Fans- Indoor - Less than 500 CFM	1st Floor	1	EA	6	6-10 years	
			_				
Catego	ry : Plumbing		В	oom)			
0	Name Tame	Laadan	0	LIOM	D I	Recommend	0
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Hot Wate							
	Electric Heater - Less than 20 KW	1st Floor	1	EA	6	6-10 years	Dataplate inaccessible due to the position of the unit. Condition verified by Building Engineer.
_Piping							
. •	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	2,100	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	2,100	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	2,100	SF	6	10+ years	
	Sanitary Piping	Entire Building	2,100	SF	6	10+ years	
	Vent Piping	Entire Building	2,100	SF	6	10+ years	
0-1	D		_	!! -!!	- NAll	4 (0 0)	\
Catego	ry : Room		В	ullaing	: Modul	ar 1 (2-Classro	oom)
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Commonts
•	rative Suites/Offices	Location	Quantity	CON	IVALIK	Replacement	Comments
Administ		1st Floor	120	OE.	7	10 L Vooro	
	Ceiling - Lay-in Ceiling - Lay-in	1st Floor 1st Floor	139 6	SF SF	4	10+ years 1-2 years	Water damage
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	water damage
	Floor - Tile	1st Floor	145	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	1-10	EA	7	6-10 years	
	Power Distribution	1st Floor	1	EA	7	10+ years	
	Walls - Metal Panel	1st Floor	345	SF	7	10+ years	
	Walle Motal Fallor	10111001	0.10	O.	•	To Tyouro	
_Restroor	n						
TYCSHOOL	Accessories	001	33	SF	7	6-10 years	
	Ceiling - Lay-in	001	33	SF	7	10+ years	
	Doors - Wood Doors inclu hw	001	1	EA	7	10+ years	
	Floor - Tile	001	33	SF	7	10+ years	
	Lavatory	001	1	EA	7	10+ years	
	Lighting - Lay-in	001	1	EA	5	1-2 years	Missing cover
	Walls - Metal Panel	001	55	SF	7	10+ years	Wildeling Cover
	Water Closet	001	1	EA	7	10+ years	
			·	_, 、	•	.o. youro	



Catego	ry : Room	В	Building : Modular 1 (2-Classroom)				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	002	33	SF	7	6-10 years	
	Ceiling - Lay-in	002	33	SF	7	10+ years	
	Doors - Wood Doors inclu hw	002	1	EA	7	10+ years	
	Floor - Tile	002	33	SF	7	10+ years	
	Lavatory	002	1	EA	7	10+ years	
	Lighting - Lay-in	002	1	EA	7	6-10 years	
	Walls - Metal Panel	002	55	SF	7	10+ years	
	Water Closet	002	1	EA	7	10+ years	
	Accessories	Office	40	SF	7	6-10 years	
	Ceiling - Lay-in	Office	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Office	1	EA	7	10+ years	
	Floor - Tile	Office	40	SF	7	10+ years	
	Lavatory	Office	1	EA	7	10+ years	
	Lighting - Lay-in	Office	1	EA	7	10+ years	
	Walls - Metal Panel	Office	77	SF	7	10+ years	
	Water Closet	Office	1	EA	7	10+ years	

Category: Classroom Building: Modular 1 (2-Classroom)

Jaicy	Category . Classicom			Building . Modular 1 (2-Classroom)					
			Recommend						
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
_Classro	om #001 (Pre School)								
	Casework	1st Floor	4	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	1,112	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor	8	SF	4	1-2 years	Water damage		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	1,120	SF	6	10+ years			
	Lighting - Lay-in	1st Floor	15	EA	7	10+ years			
	Marker Board	1st Floor	30	LF	7	6-10 years			
	Storage/ Closet	1st Floor	45	SF	7	10+ years			
	Walls - Metal Panel	1st Floor	940	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			
Classro	om #002 (Pre School)								
	Casework	1st Floor	6	LF	6	10+ years			
	Ceiling - Lay-in	1st Floor	1,108	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor	12	SF	4	0-1 year	Water damage		
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years			
	Floor - Tile	1st Floor	1,120	SF	7	10+ years			
	Lighting - Lay-in	1st Floor	15	EA	7	6-10 years			
	Marker Board	1st Floor	30	LF	7	6-10 years			
	Walls - Metal Panel	1st Floor	940	SF	7	10+ years			
	Work Sink	1st Floor	1	EA	7	10+ years			

Campus Name: Volta Page : 42 of 47 Assessment Date: 02/19/2024



Catego	ry : Interior	Building : Modular 1 (2-Classroom)					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor	•	Location	Quantity	OOM	Italik	Replacement	Comments
	Ceiling - Lay-in	Entry Vestibule	60	SF	7	10+ years	
	Doors - Steel Doors incl hw	Entry Vestibule	2	EA	7	10+ years	
	Floor - Tile/Sheet	Entry Vestibule	60	SF	7	10+ years	
	Lighting - Lay-in	Entry Vestibule	1	EA	7	6-10 years	
	Walls - Metal Panel	Entry Vestibule	126	SF	7	10+ years	

Campus Name: Volta Page : 43 of 47 Assessment Date: 02/19/2024





Category : Site **Building: Site**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Drai	71	2004.1011	Quality	00	rtann	rtopiacomont	
CIVII/DIai	•	Entire Site	1	EA	6	10	
	Civil/ Drainage - Site Drain		1		6	10+ years	Damairad
	Civil/ Drainage - Site Drain	Entire Site	1	EΑ	6	10+ years	Repaired
	Civil/ Drainage - Site Drain	Entire Site	1	EA	6	10+ years	
	Civil/ Drainage - Site Drain	Entire Site	1	EA	5	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	10	EA	6	10+ years	
Fencing							
· ·	Fencing - Chain Link	Entire Site	260	LF	4	1-2 years	Badly damaged, corroded fencing
	Fencing - Guard Rail	Entire Site	280	LF	6	10+ years	
	Fencing - New Standard Ornamental	Entire Site	5	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Entire Site	5	LF	6	6-10 years	Repaired
	Fencing - New Standard Ornamental	Entire Site	5	LF	6	6-10 years	Repaired
	Fencing - New Standard Ornamental	Entire Site	968	LF	6	6-10 years	
Landsca	ne						
	Benches	Entire Site	2	EA	7	10+ years	
	Landscape - Grass	Entire Site	30,596	SF	5	10+ years	
	Landscape - Hardscape- Asphalt	Entire Site	28,938	SF	5	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	3,090	SF	6	10+ years	
	Landscape - Mulch	Entire Site	150	SF	6	6-10 years	
	Parkway trees	Entire Site	28	EA	6	10+ years	
	Parkway trees	Entire Site	3	EA	4	1-2 years	Missing tree
	Planting Beds/ Area	Entire Site	1,710	SF	6	10+ years	Missing tree
	Play Area - Hardscape- Asphalt	Entire Site	13,632	SF	6		
		Entire Site		SF SF		10+ years	Damaged curface Dathalas large
	Play Area - Hardscape- Asphalt		4,000		4	0-1 year	Damaged surface. Potholes large cracks, alligatored surface
	Play Area - Synthetic Turf	Entire Site	6,110	SF	7	10+ years	
	Retaining Wall - Concrete	Entire Site	220	SF	6	10+ years	
	Trash Receptacles	Entire Site	2	EA	6	10+ years	
Parking I	ot						
J	Concrete Curbs	Entire Site	669	LF	6	10+ years	
	Concrete Curbs	Entire Site	20	LF	4	1-2 years	Cracked and broken.
	Interior Plantings	Entire Site	60	LF	6	10+ years	
	Interior Plantings	Entire Site	80	LF	4	1-2 years	Missing trees.
	Surface - Asphalt	Entire Site	10,661	SF	6	2-5 years	3
	Surface - Asphalt	Entire Site	6,000	SF	6	6-10 years	
	Surface - Asphalt	Entire Site	5,000	SF	4	1-2 years	Damaged.
	Surface - Asphalt	Entire Site	3,612	SF	4	0-1 year	Broken.
	Trash Enclosure - Chain Links	Entire Site	332	SF	7	10+ years	D. O.C.
	Trash Enclosure - Chain Links	Entire Site	100	SF	4	1-2 years	Damaged fence
	Tradit Endodro Onam Emilo	2.7.110 01.0	100	0.	•	1 2 yours	Damagou forfoo



Alessandro Volta Elementary School

4950 N Avers AVENUE, Chicago, IL 60625

Category : Site			В	uilding			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Vehicular Screening	Entire Site	378	LF	6	10+ years	
_Playgrou	und						
, 0	Equipment - Combo 3-12	West	1	EA	6	2-5 years	
	Surface - Poured Surface	West	1,589	SF	4	0-1 year	Torn surface and holes throughout
_Sidewal	KS						
	Sidewalks - Internal Walks	Entire Site	100	LF	7	10+ years	Repaired
	Sidewalks - Internal Walks	Entire Site	100	LF	7	10+ years	Repaired
	Sidewalks - Internal Walks	Entire Site	78	LF	6	10+ years	·
	Sidewalks - Internal Walks	Entire Site	100	LF	4	0-1 year	Damaged Sidewalk at door 2
	Sidewalks - Perimeter Sidewalks	Entire Site	75	SF	7	10+ years	-
	Sidewalks - Perimeter Sidewalks	Entire Site	75	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	9,914	SF	6	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	75	SF	6	6-10 years	Repaired
_Signage							
5 5	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	6	10+ years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	3	EA	6	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary Current Usage	Intended Usage	Room Location	Room Number	Floor Plan Room Number	Area (SF)	Glazed Window Area	Operable Window Area	Window Stop	Smart- Board
Building : Main		·		•					
Art Room	Regular Classroom	1st Floor	107	107	736	117	60	Υ	N
Faculty Lounge	Faculty Lounge	2nd Floor	NA	2nd FI Teach Rm	100	34	17	N	N
Multi Purpose Room	Regular Classroom	1st Floor	109	109	1,036	180	65	Υ	N
Music Room	Regular Classroom	2nd Floor	210	210	737	117	60	Y	N
Office	Faculty Lounge	3rd Floor	310	Teach Lunch Rm	396	44	22	N	N
Office	Regular Classroom	1st Floor	104	104	700	117	60	Υ	N
Office	Regular Classroom	1st Floor	108	108	722	104	75	Υ	N
Regular Classroom	Kindergarten	1st Floor	103	103	704	117	60	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	101	101	710	117	60	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	102	102	736	117	60	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	105	105	741	117	60	Υ	Υ
Regular Classroom	Regular Classroom	1st Floor	205	205	740	117	60	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	201	201	714	117	60	N	N
Regular Classroom	Regular Classroom	2nd Floor	202	202	733	117	60	Υ	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	203	700	117	60	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	204	209	725	117	60	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	207	207	730	117	60	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	209	209	725	117	60	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	211	211	725	117	60	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	213	213	731	117	60	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	215	215	744	117	60	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	217	217	731	117	60	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	304	304	730	170	85	N	N
Regular Classroom	Regular Classroom	3rd Floor	306	306	730	170	85	N	N
Regular Classroom	Regular Classroom	3rd Floor	307	307	730	170	85	N	N
Regular Classroom	Regular Classroom	3rd Floor	308	308	730	170	85	N	N
Regular Classroom	Regular Classroom	3rd Floor	309	309	730	170	85	N	N
Regular Classroom	Regular Classroom	3rd Floor	311	311	730	170	85	N	N
Regular Classroom	Regular Classroom	3rd Floor	313	313	730	170	85	N	N
Store Room	Regular Classroom	1st Floor	110	110	738	117	60	Υ	N
Building : Annex		1 . =	T	1				1	
Computer Lab	Regular Classroom	1st Floor	121	123	870	150	75	N	Y
Kindergarten	Regular Classroom	1st Floor	128	106	870	150	75	Υ	Υ
Kindergarten	Regular Classroom	1st Floor	129	102	870	150	75	Υ	Y
Kindergarten	Regular Classroom	1st Floor	130	105	870	150	75	Υ	N



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Kindergarten	Regular Classroom	1st Floor	131	131	870	150	75	N	N
Regular Classroom	Regular Classroom	1st Floor	120	124	870	150	75	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	122	122	870	150	75	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	123	121	870	150	75	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	124	108	870	150	75	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	125	104	870	150	75	Υ	N
Regular Classroom	Regular Classroom	1st Floor	126	107	870	150	75	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	127	103	870	150	75	Υ	Y

Building: Modular 1 (2-Classroom)										
Pre School	Regular Classroom	1st Floor	001	•	1,120	200	100	N	N	
Pre School	Regular Classroom	1st Floor	002	•	1,120	200	100	N	N	

Campus Name: Volta Page : 47 of 47 Assessment Date: 02/19/2024