

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1992	3	50,106
Addition	1997	2	23,182
Campus Total			73,288

Category: Exterior **Building: Main** Recommend Group Item - Type Location Quantity **UOM** Rank Replacement Comments Entrance Entrance Control - Audio and Video 1 1 EΑ 7 6-10 years Exterior Doors - Store Front 1 2 FΑ 6 10+ years Exterior Doors - Store Front 10 1 EΑ 1-2 years Corrosion Exterior Doors - Store Front 11 1 EΑ 4 1-2 years Corrosion Exterior Doors - Store Front 12 EΑ 1-2 years Corrosion Exterior Doors - Exterior Steel Door 13 EΑ 4 1-2 years Corroded at base Exterior Stairs - Concrete 13 8 LF 4 1-2 years Cracked and settling LF 6 Stair Handrail - Steel Stair Handrail 13 10 10+ years FΑ 10+ years Exterior Doors - Store Front 14 6 1 Exterior Doors - Store Front 15 1 FΑ 6 10+ years 16 - Roof C Exterior Doors - Exterior Steel Door 1 EΑ 6 10+ years Exterior Doors - Exterior Steel Door 17 - Roof C Entrance 1 EΑ 6 10+ years Exterior Doors - Store Front 1-2 years 2 2 EΑ 4 Corroded 2 1 F Exterior Stairs - Stone 36 5 2-5 years EΑ Exterior Doors - Exterior Steel Door 6 1 6 10+ years Exterior Doors - Exterior Steel Door 7 - Yard Storage FΑ 6 10+ years 2 EΑ Exterior Doors - Exterior Steel Door 4 0-1 year Corrosion, issues closing 9 Exterior Doors - Store Front 2 FΑ 1-2 years Corrosion Foundation 700 LF 7 Foundation - Concrete **Entire Building** 10+ years LF **Entire Building** 0-1 year Settlement issues at gym Foundation - Concrete 120 4 Superstructure - Metal Deck/ Concrete **Entire Building** 50,106 SF 10+ years

Campus Name: Walsh Page : 1 of 41 Assessment Date: 07/17/2024



Catego	y : Exterior		В	uilding	: Main		
	Ham Time	Location	Ourse!!te	HOM	Dowl	Recommend	Comments
Froup	Item - Type Topping	Location	Quantity	UOM	Rank	Replacement	Comments
	торріпд						
iahtina							
	Exterior Lighting - Wall Mounted	Entire Building	30	EA	7	10+ years	
Roof Svs	tem						
,	Access Ladder - Metal	Roof A	1	EA	7	10+ years	
	Coping - Metal	Roof A	395	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof A	152	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof A	395	LF	7	10+ years	
	Roof - Modified Bitumen	Roof A	8,070	SF	7	10+ years	
	Roof Hatch - Metal	Roof A	· 1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof A	8,070	SF	7	10+ years	
	Concrete Topping		2,21	-		, , , , , , , , , , , , , , , , , , , ,	
	Downspouts - Exterior Downspouts	Roof B	12	LF	7	10+ years	
	Roof - Metal	Roof B	1,521	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof B	1,521	SF	7	10+ years	
	Concrete Topping	Nooi B	1,521	Oi	'	10+ years	
	Coping - Metal	Roof C	56	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof C	48	LF	7		
	Parapet - Parapet < 16" Height	Roof C	56	LF	7	10+ years	
						10+ years	
	Roof - Modified Bitumen	Roof C	992	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof C	992	SF	7	10+ years	
	Concrete Topping	D (D		. –	_	4.0	
	Coping - Metal	Roof D	330	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof D	152	LF	7	10+ years	
	Parapet - 16" - 30" Height	Roof D	300	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof D	30	LF	7	10+ years	
	Roof - Modified Bitumen	Roof D	5,814	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof D	5,814	SF	7	10+ years	
	Concrete Topping						
	Access Ladder - Metal	Roof E	1	EA	7	10+ years	
	Coping - Stone	Roof E	50	LF	6	10+ years	
	Downspouts - Interior Downspouts	Roof E	22	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof E	50	LF	7	10+ years	
	Roof - Modified Bitumen	Roof E	308	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof E	308	SF	7	10+ years	
	Concrete Topping					,	
	Coping - Metal	Roof F	72	LF	7	10+ years	
	Downspouts - Interior Downspouts	Roof F	38	LF	7	10+ years	
	Parapet - Parapet < 16" Height	Roof F	72	LF	7	10+ years	
	Roof - Modified Bitumen	Roof F	469	SF	7	10+ years	
	Roof Structure - Steel / Metal Deck/	Roof F	469	SF	7	10+ years	
	Concrete Topping	10011	+03	Oi.	1	TOT years	



Category : Exterior			В	uilding	: Main		2015 S Peoria STREET, Chicago, IL 60608
	.,					Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Walls							
	Exterior Walls - Brick	Entire Building	225	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	15,097	SF	7	10+ years	
	Exterior Walls - Stucco	Entire Building	9,543	SF	6	10+ years	
	Exterior Walls - Stucco	Entire Building	5	SF	4	1-2 years	Cracked stucco, roof door 16
Windows	3						
	Curtain wall - Glazed Double Pane	Entire Building	2,034	SF	6	6-10 years	
	Curtain wall - Glazed Double Pane	Entire Building	30	SF	5	2-5 years	
	Lintels - Steel	Entire Building	576	LF	7	10+ years	
	Storefront Windows	Entire Building	610	SF	6	6-10 years	
	Windows - Decorative	Entire Building	370	SF	6	6-10 years	
	Windows - Louver	Entire Building	324	SF	6	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	1,854	SF	5	2-5 years	Issues opening and closing
Catego	ry : Electrical		В	uilding	: Main		
	.,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Automatic Transfer Switch	Electrical Room	1	EA	6	10+ years	
	Emergency Battery Packs - Corridors and	Entire Building	27	EA	7	6-10 years	
	Stairs						
	Emergency Battery Packs - Gym	Entire Building	5	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	3	EA	7	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	7	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	17	EA	2	0-1 year	Rank, Reason and Priority Rep
							changed as signs have no backup
							batteries and the school has no
							emergency generator.
	Exit Signs - Gym	Entire Building	1	EA	4	0-1 year	Exit Sign fixture is missing its sign
							face; the sign has no backup batter
							and the school has no emergency
							generator.
	Exit Signs - Gym	Entire Building	1	EA	2	0-1 year	generator. Quantity changed as total has beer
	Exit Signs - Gym	Entire Building	1	EA	2	0-1 year	generator. Quantity changed as total has beer divided/aggregated. Rank, Reasor
	Exit Signs - Gym	Entire Building	1	EA	2	0-1 year	generator. Quantity changed as total has beer divided/aggregated. Rank, Reasor and Priority Rep changed as signs
	Exit Signs - Gym	Entire Building	1	EA	2	0-1 year	generator. Quantity changed as total has been divided/aggregated. Rank, Reason and Priority Rep changed as signs have no backup batteries and the
		·	·				generator. Quantity changed as total has beer divided/aggregated. Rank, Reasor and Priority Rep changed as signs have no backup batteries and the school has no emergency generate
	Exit Signs - Gym Exit Signs - Lunchroom	Entire Building Entire Building	1	EA EA	2	0-1 year 0-1 year	generator. Quantity changed as total has beer divided/aggregated. Rank, Reasor and Priority Rep changed as signs have no backup batteries and the school has no emergency generator Rank, Reason and Priority Rep
		·	·				generator. Quantity changed as total has been divided/aggregated. Rank, Reason and Priority Rep changed as signs have no backup batteries and the school has no emergency generate Rank, Reason and Priority Rep changed as signs have no backup
		·	·				generator. Quantity changed as total has beer divided/aggregated. Rank, Reasor and Priority Rep changed as signs have no backup batteries and the school has no emergency generate Rank, Reason and Priority Rep

Campus Name: Walsh Page : 3 of 41 Assessment Date: 07/17/2024



John A Walsh Elementary School

XIII.	Schools						2015 S Peoria STREET, Chicago, IL 60608
Catego	ry : Electrical		В				
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Emergency A/C Power - Corridors and Stairs	Entire Building	5,057	SF	6	10+ years	
	Security System - Intrusion Detection	Entire Building	50,106	SF	6	6-10 years	
Main Se	rvice						
	Main Electrical Service - 1600 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Location changed for clarification.
	PA System	Entire Building	73,288	SF	7	10+ years	Rank, Reason and Priority Rep changed as the system has been replaced since previous assessment.
	Independent Electrical Service for emergency power	Mechanical Room	1	EA	7	10+ years	Serves fire sprinkler system
	Independent Electrical Service for emergency power	Mechanical Room	1	EA	7	10+ years	Serves building EM circuits
Power D	Distribution						
	Lighting and Power Panels - 100 A Lighting and Power Panels - Above 100 A	Entire Building Entire Building	1 8	EA EA	6 6	10+ years 10+ years	EM fuse panel Quantity changed as total has been
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	divided/aggregated. Open breaker slots expose live conductors presenting a live front
	Main Distribution Panels - 400 - 600 amp	Entire Building	2	EA	6	10+ years	condition.
Catego	ry : Fire Protection		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Fire Alar							
	Fire ALarm Anunciator	Entire Building	1	EA	3	2-5 years	No CPS Asset Tag present. Panel is 25-plus years old and passes annual inspection, however the system employs antiquated technology and has reached the end of its anticipated service life.
	Fire Alarm Panel	Entire Building	1	EA	3	2-5 years	No CPS Asset Tag present. Rank, Reason and Priority Rep changed as the panel is 25-plus years old and passes annual inspection, however it employs antiquated technology and has reached the end of its anticipated service life.
	Fire Alarm Strobe Lights Fire Alarm_System	Entire Building Entire Building	50,106 73,288	SF SF	6 4	6-10 years 2-5 years	Rank, Reason and Priority Rep



	crools			ilalia e	. Mein		2015 S Peoria STREET, Chicago, IL 60608
Catego	ry : Fire Protection		В	uilding	: Main	_	
			•			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	changed as the system is 25-plus years old and passes annual inspection, however it employs antiquated technology and has reached the end of its anticipated service life.
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	
Duman Da	Anna Anna ambili						
Pump Ro	oom Assembly Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	6-10 years	Rank, Reason and Priority Rep changed based on current observations. Pump has been upgraded and was leak-free at the time of assessment with evidence of previous leaks.
	Jockey Pump	Mechanical Room	1	EA	6	10+ years	·
Sprinkler	System						
Sprinkler	Sprinkler Heads	Entire Building	50,106	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	50,106	SF	6	10+ years	
	Wet Sprinkler System	Entire Building	50,106	SF	6	10+ years	Location changed for clarification.
Catago	ry . Machanical		В	uildina	. Main		
Calego	ry : Mechanical		В	uilding	. IVIAIII	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	itioning						
	Condensing Unit- Roof Mounted - 21-30 tons	Roof	1	EA	7	10+ years	Associated with AHU-3. Rank adjusted as the equipment has been replaced since previous assessment. No CPS Asset Tag present. Location changed for clarification.
	Condensing Unit- Roof Mounted - 21-30 tons	Roof	1	EA	7	10+ years	Associated with AHU-2. Rank adjusted as the equipment has been replaced since previous assessment. No CPS Asset Tag present. Location changed for clarification.
	Condensing Unit- Roof Mounted - 21-30 tons	Roof	1	EA	7	10+ years	Associated with AHU-4. Rank adjusted as the equipment has been replaced since previous assessment. No CPS Asset Tag present. Location changed for clarification.
	Condensing Unit- Roof Mounted - 31-50 tons	Roof	1	EA	7	10+ years	Associated with AHU-1. Rank adjusted as the equipment has been

Campus Name: Walsh Page : 5 of 41 Assessment Date: 07/17/2024



Categor	y : Mechanical		В	uilding	: Main		
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments replaced since previous assessment No CPS Asset Tag present.
Air Handl	ing Systems						
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 4000-8000 cfm	3rd Floor Mechanical Room - AHU-2	1	EA	6	6-10 years	AHU-2, serves library and offices.
	Air Intake	3rd Floor Mechanical Room - AHU-2	1	EA	6	10+ years	
	VAV Box	3rd Floor Mechanical Room - AHU-2	5	EA	5	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 4000-8000 cfm	3rd Floor Mechanical Room - AHU-3	1	EA	6	6-10 years	AHU-3, serves lunchroom.
	Air Intake	3rd Floor Mechanical Room - AHU-3	1	EA	6	10+ years	
	VAV Box	3rd Floor Mechanical Room - AHU-3	1	EA	5	6-10 years	
	Air Handling Unit-Package Single Zone- Indoor- Hot Water and DX Cooling Coils - 4000-8000 cfm	3rd Floor Mechanical Room - AHU-4	1	EA	6	6-10 years	AHU-4 serves Gym
	Air Intake	3rd Floor Mechanical Room - AHU-4	1	EA	6	10+ years	
	Air Handling Unit-Package Single Zone-	Basement Mechanical Room - AHU-	1	EA	6	6-10 years	
	Indoor- Hot Water and DX Cooling Coils - 20001-30000 cfm	1			-	,	
	Air Intake	Basement Mechanical Room - AHU-1	1	EA	6	10+ years	
	VAV Box	Basement Mechanical Room - AHU-1	18	EA	5	6-10 years	
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Entire Building	1	EA	6	10+ years	Associated with AHU-2
	Indoor Return Fans- Centrifugal Squirrel Cage - 5000 - 10000 CFM	Entire Building	1	EA	6	10+ years	Associated with AHU-3
	Indoor Return Fans- Centrifugal Squirrel Cage - Greater than 20000 CFM	Entire Building	1	EA	6	10+ years	Associated with AHU-1
	Make Up Air Unit- Roof Mounted- Gas Heating - Less than 6000 cfm	Lower Roof	1	EA	7	10+ years	Rank and Priority Rep adjusted as the unit has been replaced since previous assessment. Item Type changed to match current observations (4680 cfm). No CPS Asset Tag present.
Boiler Sy:	stems						
	Boiler Auxiliary- Non Condensing Hot Water - 500 - 1000 MBH	Boiler Room	6	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Combustion Dampers	Boiler Room	4	EA	5	10+ years	Manually adjusted
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	,,

Campus Name: Walsh Page : 6 of 41 Assessment Date: 07/17/2024



Catego	Category : Mechanical		В	uilding	: Main		, , , , , , , , , , , , , , , , , , , ,
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Hot Water Pump	Boiler Room	1	EA	6	10+ years	
	Hot Water Pump	Boiler Room	1	EA	6	10+ years	
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	1	EA	5	10+ years	B-1
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	1	EA	5	10+ years	B-5
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	1	EA	5	10+ years	B-4
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	1	EA	5	10+ years	B-6
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	1	EA	5	10+ years	B-2
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	1	EA	5	10+ years	B-3
Heating	Devices						
- 5	Radiator Panels - Hot Water	1st Floor	9	EA	6	6-10 years	Located in offices and in the lunchroom.
	Cabinet Heaters - With Hot Water Coil	1st Floor	1	EA	6	10+ years	
	Fin Tube - Hot Water	Entire Building	250	LF	6	10+ years	
	Unit Heater - Hot Water	Entire Building	2	EA	7	10+ years	Rank changed as control has been replaced since previous assessment and units have been restored to normal operation.
	Unit Heater - Hot Water	Entire Building	2	EA	7	10+ years	
Maabani	ical Plumbing						
_iviecnani	Hydronic Supply and Return - Steel	Mechanical Room	200	LF	6	10+ years	Rank adjusted based on current
		MECHALIICAI ROUIII	200	LF	O	10+ years	observations and per review with Building Engineer that there are no pipe clamps on horizontal runs and there is no major insulation damage.
_Tempera	ature Control						
	DDC System	Entire Building	73,288	SF	4	0-1 year	Rank, Reason and Priority Rep changed based on review with Building Engineer that the system is

Campus Name: Walsh Page : 7 of 41 Assessment Date: 07/17/2024



Category : Mechanical			В	uilding	: Main			
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
_							inoperable. Temperature in all spaces throughout the building are manually controlled.	
	Electric Thermostat	Entire Building	1	EA	6	6-10 years	mandally controlled.	
	Thermostats - DDC	Entire Building	24	EA	6	6-10 years		
entilatio	on							
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	Rank changed as the unit has been replaced since previous assessmen Item Type changed to match curren observations (7200 cfm).	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	7	10+ years	Item Type changed to match current observations. Location changed for clarification. Quantity changed as total has been divided/aggregated. EF-7 (975 cfm) and EF-5 (1050 cfm)	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	1	EA	7	10+ years	EF-8 (600 cfm)	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	7	10+ years	Quantity changed as total has been divided/aggregated. Rank changed as unit has been replaced since previous assessment. EF-1 (225 cfm).	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	3	EA	7	10+ years	EF-2 (75 cfm), EF-6 (365 cfm) and EF-4 (100 cfm).	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	7	10+ years	EF-3 (225 cfm)	
	Roof Mounted Duct Work	Entire Building	10	LF	7	10+ years	Rank and quantity changed as the ductwork has been replaced since previous assessment. Lineal footag confirmed by physical measurement at the time of assessment.	
	Type I Exhaust Hood- Kitchen	Entire Building	2	EA	6	10+ years		
atego	ry : Plumbing		В	uilding	: Main			
iroup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
OL VVAIG	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	2	EA	6	6-10 years	Rank adjusted based on current observations and on the age of the equipment.	



Catego	ry : Plumbing		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Domestic Piping-Hot Water Return Lines	Entire Building	50,106	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	50,106	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	50,106	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	50,106	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	50,106	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	50,106	SF	7	10+ years	
	Sanitary Piping	Entire Building	50,106	SF	7	10+ years	
	Storm Piping	Entire Building	50,106	SF	7	10+ years	
	Vent Piping	Entire Building	50,106	SF	7	10+ years	
Pumps							
	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	5	10+ years	
	Pumps - Sump-Duplex	Entire Building	1	EA	5	10+ years	No CPS Asset Tag present.
	Pumps - Sump-Simplex	Entire Building	1	EA	6	10+ years	Location changed for clarification. Elevator pit sump pump. Inaccessible at the time of assessment. No CPS Asset Tag available. Condition verified by Building Engineer.

Category: Room **Building: Main**

				anamg		Pasammand	
Froup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
dminist	rative Suites/Offices						
	Ceiling - Lay-in	115 Student Services 1st Floor	216	SF	7	10+ years	
	Ceiling - Lay-in	115 Student Services 1st Floor	4	SF	5	1-2 years	Buckling
	Doors - Steel Doors incl hw	115 Student Services 1st Floor	1	EA	7	10+ years	-
	Floor - Carpet	115 Student Services 1st Floor	220	SF	7	6-10 years	
	Lighting - Lay-in	115 Student Services 1st Floor	4	EA	7	6-10 years	
	Power Distribution	115 Student Services 1st Floor	4	EA	7	10+ years	
	Walls - Concrete Block	115 Student Services 1st Floor	560	SF	7	10+ years	
	Ceiling - Plaster/Drywall	119 Reception	294	SF	7	10+ years	
	Doors - Side-lite	119 Reception	16	SF	7	10+ years	
	Doors - Steel Doors incl hw	119 Reception	2	EA	7	10+ years	
	Floor - Tile	119 Reception	294	SF	7	10+ years	
	Lighting - Pendent/Surface	119 Reception	6	EA	7	6-10 years	
	Power Distribution	119 Reception	8	EA	7	10+ years	
	Walls - Concrete Block	119 Reception	400	SF	7	10+ years	
	Ceiling - Plaster/Drywall	120 Counselor Office	150	SF	6	6-10 years	
	Doors - Steel Doors incl hw	120 Counselor Office	1	EA	7	10+ years	

Campus Name: Walsh Page : 9 of 41 Assessment Date: 07/17/2024





Category : Room			Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	120 Counselor Office	150	SF	7	10+ years			
	Lighting - Pendent/Surface	120 Counselor Office	4	EA	7	6-10 years			
	Power Distribution	120 Counselor Office	6	EA	7	10+ years			
	Walls - Concrete Block	120 Counselor Office	300	SF	7	10+ years			
	Walls - Plaster/Drywall	120 Counselor Office	150	SF	7	10+ years			
	Ceiling - Plaster/Drywall	121 Principal	150	SF	7	10+ years			
	Doors - Steel Doors incl hw	121 Principal	1	EA	7	10+ years			
	Floor - Tile	121 Principal	150	SF	7	10+ years			
	Lighting - Pendent/Surface	121 Principal	4	EA	7	6-10 years			
	Power Distribution	121 Principal	6	EA	7	10+ years			
	Walls - Concrete Block	121 Principal	150	SF	7	10+ years			
	Walls - Plaster/Drywall	121 Principal	300	SF	7	10+ years			
	Ceiling - Plaster/Drywall	122 Conference	130	SF	7	10+ years			
	Floor - Tile	122 Conference	130	SF	7	10+ years			
	Lighting - Pendent/Surface	122 Conference	4	EA	7	6-10 years			
	Power Distribution	122 Conference	4	EΑ	7	10+ years			
	Walls - Masonry	122 Conference	150	SF	7	10+ years			
	Walls - Plaster/Drywall	122 Conference	208	SF	7	10+ years			
	Ceiling - Plaster/Drywall	123 Assistant Principal	130	SF	7	10+ years			
	Doors - Steel Doors incl hw	123 Assistant Principal	1	EΑ	7	10+ years			
	Floor - Tile	123 Assistant Principal	130	SF	7	10+ years			
	Lighting - Pendent/Surface	123 Assistant Principal	4	EΑ	7	6-10 years			
	Power Distribution	123 Assistant Principal	4	EA	7	10+ years			
	Walls - Concrete Block	123 Assistant Principal	150	SF	7	10+ years			
	Walls - Plaster/Drywall	123 Assistant Principal	208	SF	7	10+ years			
	Ceiling - Plaster/Drywall	124 Break Room	112	SF	7	10+ years			
	Doors - Steel Doors incl hw	124 Break Room	1	EA	7	10+ years			
	Floor - Concrete	124 Break Room	112	SF	7	10+ years			
	Lighting - Pendent/Surface	124 Break Room	4	EA	7	6-10 years			
	Power Distribution	124 Break Room	4	EA	7	10+ years			
	Walls - Concrete Block	124 Break Room	272	SF	7	10+ years			
	Work SInk	124 Break Room	1	EA	7	10+ years			
	Ceiling - Exposed	202 Gym office	104	SF	7	10+ years			
	Floor - Tile	202 Gym office	100	SF	7	10+ years			
	Floor - Tile	202 Gym office	4	SF	4	1-2 years	Chipped		
	Lighting - Pendent/Surface	202 Gym office	3	EA	6	6-10 years			
	Power Distribution	202 Gym office	4	EA	7	10+ years			
	Walls - Concrete Block	202 Gym office	468	SF	7	10+ years			
	Ceiling - Lay-in	208 Library work room	198	SF	7	10+ years			
	Ceiling - Lay-in	208 Library work room	12	SF	5	1-2 years	Missing tile		
	Doors - Steel Doors incl hw	208 Library work room	1	EA	7	10+ years			
	Floor - Tile/Sheet	208 Library work room	210	SF	7	10+ years			
	Lighting - Pendent/Surface	208 Library work room	6	EA	7	6-10 years			
	Walls - Concrete Block	208 Library work room	682	SF	7	10+ years			

Campus Name: Walsh Page : 10 of 41 Assessment Date: 07/17/2024



Catego	Category : Room		В	uilding	: Main		. 5 :
_						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	210 workout room	345	SF	7	10+ years	
	Doors - Steel Doors incl hw	210 workout room	2	EΑ	7	10+ years	
	Floor - Concrete	210 workout room	345	SF	7	10+ years	
	Lighting - Pendent/Surface	210 workout room	8	EA	7	6-10 years	
	Lighting - Pendent/Surface	210 workout room	1	EA	6	6-10 years	
	Walls - Concrete Block	210 workout room	990	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Kitchen Office 1st Floor	40	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen Office 1st Floor	1	EA	7	10+ years	
	Floor - Concrete Epoxy/ Painted	Kitchen Office 1st Floor	40	SF	7	10+ years	
	Lighting - Pendent/Surface	Kitchen Office 1st Floor	1	EA	7	6-10 years	
	Power Distribution	Kitchen Office 1st Floor	4	EA	7	10+ years	
	Walls - Concrete Block	Kitchen Office 1st Floor	234	SF	7	10+ years	
	Ceiling - Lay-in	Teachers' Lounge 1st Floor	643	SF	7	10+ years	
	Ceiling - Lay-in	Teachers' Lounge 1st Floor	32	SF	5	1-2 years	Water damage
	Doors - Steel Doors incl hw	Teachers' Lounge 1st Floor	2	ĒΑ	7	10+ years	Transfer daminings
	Floor - Tile	Teachers' Lounge 1st Floor	675	SF	7	10+ years	
	Lighting - Pendent/Surface	Teachers' Lounge 1st Floor	9	EΑ	7	6-10 years	
	Power Distribution	Teachers' Lounge 1st Floor	12	EΑ	7	10+ years	
	Walls - Concrete Block	Teachers' Lounge 1st Floor	760	SF	7	10+ years	
	Work SInk	Teachers' Lounge 1st Floor	1	EA	7	10+ years	
	Work Sink	readilloro Eddingo Tot i looi	•	_/\	•	101 youro	
_Gvmnas	ia						
,	Bleacher Seating	2nd Floor	30	EA	7	10+ years	
	Ceiling - Exposed	2nd Floor	4,050	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	4	ĒΑ	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	3,900	SF	7	6-10 years	
	Floor - Tile/Sheet	2nd Floor	100	SF	4	0-1 year	Chipped and cracked
	Floor - Tile/Sheet	2nd Floor	50	SF	4	0-1 year	Cracking floor
	Lighting - Pendent/Surface	2nd Floor	12	EA	7	10+ years	Graciang noon
	Walls - Concrete Block	2nd Floor	6,258	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	30	SF	5	0-1 year	Cracked
	Walle Collecte Blook	2114 1 1001	00	O.	Ü	o i youi	Orabica -
_Kitchen							
	Ceiling - Plaster/Drywall	1st Floor	736	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	3	ĒΑ	7	10+ years	
	Floor - Terrazzo	1st Floor	736	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	11	EA	7	6-10 years	
	Storage/ Closet	1st Floor	128	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,296	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Dishwashing room next to kitchen	170	SF	7	10+ years	
	Floor - Terrazzo	Dishwashing room next to kitchen	170	SF	6	10+ years	
	Lighting - Pendent/Surface	Dishwashing room next to kitchen	4	EA	7	6-10 years	
	Walls - Concrete Block	Dishwashing room next to kitchen	486	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Serving room next to lunch room	384	SF	7	10+ years	
	Jaming Franciscon Dry Wall	Co. Ting room now to land 100m	554	٥.	•	io. youro	



Category : Room			В	uilding	: Main		2013 01 Colla 011(EE1, Ollicago, IE 00000		
3						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor - Tile	Serving room next to lunch room	384	SF	7	10+ years			
	Lighting - Lay-in	Serving room next to lunch room	6	EA	7	6-10 years			
	Serving Line	Serving room next to lunch room	22	LF	7	10+ years			
	Walls - Concrete Block	Serving room next to lunch room	504	SF	7	10+ years			
Library									
,	Casework	2nd Floor	36	LF	7	10+ years			
	Ceiling - Plaster/Drywall	2nd Floor	1,256	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	6	EA	7	10+ years			
	Floor - Carpet	2nd Floor	1,256	SF	6	6-10 years			
	Lighting - Lay-in	2nd Floor	[′] 15	EA	7	6-10 years			
	Walls - Metal Panel	2nd Floor	2,500	SF	7	10+ years			
Lunch &	Multipurpose Room								
	Ceiling - Lay-in	1st Floor	2,738	SF	7	10+ years			
	Ceiling - Lay-in	1st Floor	12	SF	5	1-2 years	Buckling		
	Floor - Tile	1st Floor	2,740	SF	7	10+ years	Dacking		
	Floor - Tile	1st Floor	10	SF	4	1-2 years	Cracked		
	Lighting - Pendent/Surface	1st Floor	42	EA	7	6-10 years	Crusica		
	Market Board	1st Floor	6	LF	4	2-5 years	Marker board		
	Walls - Concrete Block	1st Floor	1,788	SF	7	10+ years	Markor board		
MDE ID	-								
_MDF_ID									
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years			
	Finishes	3rd Floor	80	SF	7	10+ years			
_Mechani	cal/ Service Rooms								
	Janitor's Closet	1st Floor	50	SF	7	10+ years			
	Janitor's Closet	3rd Floor	75	SF	7	10+ years			
	Mechanical/ Service Rooms	3rd Floor	1,800	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	480	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	80	SF	7	10+ years			
	Mechanical/ Service Rooms	Basement	1,800	SF	7	10+ years			
	Storage Room	Basement	120	SF	7	10+ years			
_Restroor	m								
	Accessories	101A	54	SF	7	6-10 years			
	Ceiling - Lay-in	101A	50	SF	7	10+ years			
	Ceiling - Lay-in	101A	4	SF	4	1-2 years	Damaged grid		
	Doors - Steel Doors incl hw	101A	1	EA	7	10+ years	- aagoa g.ia		
	Floor - Tile	101A	54	SF	7	10+ years			
	Floor Drain	101A	1	EA	7	10+ years			
	Lavatory	101A	1	EA	7	10+ years			
	Lavatory	10111	ı	_/ \	,	ioi youis			

Campus Name: Walsh Page : 12 of 41 Assessment Date: 07/17/2024



Category : Room			В	uilding	: Main		
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	101A	1	EA	7	6-10 years	
	Walls - Concrete Block	101A	270	SF	7	10+ years	
	Water Closet	101A	1	EΑ	7	10+ years	
	Accessories	103A	54	SF	7	6-10 years	
	Ceiling - Lay-in	103A	50	SF	7	10+ years	
	Ceiling - Lay-in	103A	4	SF	5	1-2 years	Missing
	Doors - Steel Doors incl hw	103A	1	EA	7	10+ years	3
	Floor - Tile	103A	54	SF	6	10+ years	
	Floor Drain	103A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	103A	1	EA	7	6-10 years	
	Walls - Concrete Block	103A	270	SF	7	10+ years	
	Water Closet	103A	1	ĒΑ	7	10+ years	
	Accessories	104A	54	SF	7	6-10 years	
	Ceiling - Lay-in	104A	54	SF	7	10+ years	
	Doors - Steel Doors incl hw	104A	1	EΑ	7	10+ years	
	Floor - Tile	104A	54	SF	7	10+ years	
	Floor Drain	104A	1	ĒΑ	7	10+ years	
	Lavatory	104A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	104A	1	EA	7	6-10 years	
	Walls - Concrete Block	104A	270	SF	7	10+ years	
	Water Closet	104A	1	ĒΑ	7	10+ years	
	Accessories	105A	54	SF	7	6-10 years	
	Ceiling - Lay-in	105A	54	SF	7	10+ years	
	Doors - Steel Doors incl hw	105A	1	ĒΑ	7	10+ years	
	Floor - Tile	105A	54	SF	7	10+ years	
	Floor Drain	105A	1	EΑ	7	10+ years	
	Lavatory	105A	1	ĒΑ	7	10+ years	
	Lighting - Pendent/Surface	105A	1	EΑ	7	6-10 years	
	Walls - Concrete Block	105A	270	SF	7	10+ years	
	Water Closet	105A	1	EΑ	7	10+ years	
	Accessories	106A	54	SF	7	6-10 years	
	Ceiling - Lay-in	106A	46	SF	7	10+ years	
	Ceiling - Lay-in	106A	8	SF	5	1-2 years	Missing and buckling
	Doors - Steel Doors incl hw	106A	1	EA	7	10+ years	meening and backing
	Floor - Tile	106A	54	SF	7	10+ years	
	Floor Drain	106A	1	EA	7	10+ years	
	Lavatory	106A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	106A	1	EA	7	6-10 years	
	Walls - Concrete Block	106A	270	SF	7	10+ years	
	Water Closet	106A	1	EA	7	10+ years	
	Accessories	1st Floor	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	35	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	35	SF	7	10+ years	
	1 1001 1 110	13(1100)	33	Oi.	,	TOT yours	



Catego	ry : Room		Building : Main						
_						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor Drain	1st Floor	1	EA	7	10+ years			
	Lavatory	1st Floor	1	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years			
	Walls - Concrete Block	1st Floor	192	SF	7	10+ years			
	Water Closet	1st Floor	1	EA	7	10+ years			
	Accessories	1st Floor	153	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	153	SF	7	10+ years			
	Floor - Concrete	1st Floor	153	SF	7	10+ years			
	Floor Drain	1st Floor	1	ĒΑ	7	10+ years			
	Lavatory	1st Floor	2	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years			
	Lighting - Wall Mounted	1st Floor	2	EA	7	6-10 years			
	Partitions	1st Floor	2	EA	7	10+ years			
	Walls - Concrete Block	1st Floor	540	SF	7	10+ years			
	Water Closet	1st Floor	2	EA	7	10+ years			
	Accessories	1st Floor	153	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	153	SF	7	10+ years			
	Floor - Concrete	1st Floor	153	SF	7	10+ years			
	Floor Drain	1st Floor	133	EA	7	10+ years			
	Lavatory	1st Floor	2	EA	7	10+ years			
	Lighting - Lay-in	1st Floor	1	EA	7	6-10 years			
	Lighting - Lay-iii Lighting - Wall Mounted	1st Floor	2	EA	7	6-10 years			
	Partitions	1st Floor	1	EA	7	•			
	Urinals	1st Floor	1	EA	7	10+ years 10+ years			
	Walls - Concrete Block	1st Floor	540	SF	7				
	Water Closet	1st Floor	1	EA	7	10+ years			
	Accessories	2nd Floor	153	SF	7	10+ years 6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	153	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	100	EA	7	,			
	Floor - Concrete	2nd Floor 2nd Floor	153	SF		10+ years			
	Floor Drain	2nd Floor 2nd Floor	100	SF EA	7	10+ years			
			1	EA	7 7	10+ years			
	Hand Dryer	2nd Floor				6-10 years			
	Lavatory	2nd Floor	2	EΑ	7	10+ years			
	Lighting - Lay-in	2nd Floor	1	EΑ	7	6-10 years			
	Lighting - Wall Mounted	2nd Floor	2	EΑ	7	6-10 years			
	Partitions	2nd Floor	2	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	540	SF	7	10+ years			
	Water Closet	2nd Floor	2	EA	7	6-10 years			
	Accessories	2nd Floor	153	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	2nd Floor	153	SF	7	10+ years			
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years			
	Floor - Concrete	2nd Floor	153	SF	7	10+ years			
	Floor Drain	2nd Floor	1	EA	7	10+ years			
	Lavatory	2nd Floor	2	EA	7	10+ years			





Catego	ry : Room		Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	2nd Floor	1	EA	7	6-10 years			
	Lighting - Wall Mounted	2nd Floor	2	EA	7	6-10 years			
	Partitions	2nd Floor	1	EA	7	10+ years			
	Urinals	2nd Floor	1	EA	7	10+ years			
	Walls - Concrete Block	2nd Floor	540	SF	7	10+ years			
	Water Closet	2nd Floor	1	EA	7	6-10 years			
	Accessories	3rd Floor	153	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	153	SF	7	10+ years			
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years			
	Floor - Concrete	3rd Floor	153	SF	7	10+ years			
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Hand Dryer	3rd Floor	1	EA	7	6-10 years			
	Lavatory	3rd Floor	2	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor	1	EA	7	6-10 years			
	Lighting - Wall Mounted	3rd Floor	2	EΑ	7	6-10 years			
	Partitions	3rd Floor	2	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor	540	SF	7	10+ years			
	Water Closet	3rd Floor	2	EA	7	10+ years			
	Accessories	3rd Floor	153	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	153	SF	7	10+ years			
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years			
	Floor - Concrete	3rd Floor	153	SF	7	10+ years			
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Hand Dryer	3rd Floor	1	EA	5	0-1 year	Broken		
	Lavatory	3rd Floor	2	EA	7	10+ years			
	Lighting - Lay-in	3rd Floor	1	EA	7	6-10 years			
	Lighting - Wall Mounted	3rd Floor	2	EA	7	6-10 years			
	Partitions	3rd Floor	1	EΑ	7	10+ years			
	Urinals	3rd Floor	1	EA	7	10+ years			
	Walls - Concrete Block	3rd Floor	540	SF	7	10+ years			
	Water Closet	3rd Floor	1	ĒΑ	7	10+ years			
	Accessories	Restroom in Student Services Room	35	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Restroom in Student Services Room	35	SF	7	10+ years			
	Doors - Steel Doors incl hw	Restroom in Student Services Room	1	EA	7	10+ years			
	Floor - Tile	Restroom in Student Services Room	35	SF	7	10+ years			
	Floor Drain	Restroom in Student Services Room	1	EA	7	10+ years			
	Lavatory	Restroom in Student Services Room	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Restroom in Student Services Room	1	EA	7	6-10 years			
	Walls - Concrete Block	Restroom in Student Services Room	192	SF	7	10+ years			
	Water Closet	Restroom in Student Services Room	132	EA	7	10+ years			
	Accessories	Staff - Basement	90	SF	7	6-10 years			
	Ceiling - Exposed	Staff - Basement	90	SF	7	10+ years			
	Doors - Steel Doors incl hw	Staff - Basement	1	EA	7	10+ years 10+ years			
	Floor - Concrete	Staff - Basement	90	SF	7	10+ years			
	i iooi - Concrete	Stail - Dascillett	90	SГ	1	10+ years			

Campus Name: Walsh Page : 15 of 41 Assessment Date: 07/17/2024



Catego	ry : Room		Building : Main						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Floor Drain	Staff - Basement	1	EA	7	10+ years			
	Lavatory	Staff - Basement	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Staff - Basement	1	EA	7	6-10 years			
	Partitions	Staff - Basement	1	EA	7	10+ years			
	Student Lockers - One Tier	Staff - Basement	5	EA	7	10+ years			
	Walls - Concrete Block	Staff - Basement	90	SF	7	10+ years			
	Walls - Concrete Block	Staff - Basement	200	SF	7	10+ years			
	Water Closet	Staff - Basement	1	EΑ	7	10+ years			
	Accessories	Staff - Lunchroom 1st Floor	50	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Staff - Lunchroom 1st Floor	50	SF	7	10+ years			
	Doors - Steel Doors incl hw	Staff - Lunchroom 1st Floor	1	EA	7	10+ years			
	Floor - Concrete	Staff - Lunchroom 1st Floor	50	SF	7	10+ years			
	Floor Drain	Staff - Lunchroom 1st Floor	1	EA	7	10+ years			
	Lavatory	Staff - Lunchroom 1st Floor	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Staff - Lunchroom 1st Floor	1	EA	7	6-10 years			
	Partitions	Staff - Lunchroom 1st Floor	1	ΕA	7	10+ years			
	Student Lockers - One Tier	Staff - Lunchroom 1st Floor	6	ΕA	7	10+ years			
	Student Lockers - One Tier	Staff - Lunchroom 1st Floor	1	EA	5	1-2 years	Damaged		
	Walls - Concrete Block	Staff - Lunchroom 1st Floor	250	SF	7	10+ years	Damagea		
	Walls - Concrete Block	Staff - Lunchroom 1st Floor	20	SF	5	1-2 years	Cracked		
	Water Closet	Staff - Lunchroom 1st Floor	1	EA	7	10+ years	0.46.164		
	Accessories	Staff Restroom next to 201	45	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Staff Restroom next to 201	45	SF	7	10+ years			
	Doors - Steel Doors incl hw	Staff Restroom next to 201	1	EA	7	10+ years			
	Floor - Concrete	Staff Restroom next to 201	45	SF	7	10+ years			
	Floor Drain	Staff Restroom next to 201	1	EA	7	10+ years			
	Lavatory	Staff Restroom next to 201	1	EA	7	10+ years			
	Lighting - Pendent/Surface	Staff Restroom next to 201	1	EA	7	6-10 years			
	Walls - Concrete Block	Staff Restroom next to 201	224	SF	7	10+ years			
	Water Closet	Staff Restroom next to 201	1	EA	7	10+ years			
	Accessories	Staff Restroom next to 202	45	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	Staff Restroom next to 202	45	SF	7	10+ years			
	Doors - Steel Doors incl hw	Staff Restroom next to 202	1	EA	7	10+ years			
	Floor - Concrete		45	SF	7	•			
	Floor Drain	Staff Restroom next to 202	45 1	EA	7	10+ years			
		Staff Restroom next to 202 Staff Restroom next to 202	1	EA	7	10+ years			
	Lavatory		-	EA	7 7	10+ years			
	Lighting - Pendent/Surface	Staff Restroom next to 202	1			10+ years			
	Walls - Concrete Block	Staff Restroom next to 202	224	SF EA	7	10+ years			
	Water Closet	Staff Restroom next to 202	1	SF	7	10+ years			
	Accessories	Staff Restroom next to 301	45		7	6-10 years			
	Ceiling - Plaster/Drywall	Staff Restroom next to 301	45	SF	7	10+ years			
	Doors - Steel Doors incl hw	Staff Restroom next to 301	1	EA	7	10+ years			
	Floor - Concrete	Staff Restroom next to 301	45	SF	7	10+ years			
	Floor Drain	Staff Restroom next to 301	1	EA	7	10+ years			

Campus Name: Walsh Page : 16 of 41 Assessment Date: 07/17/2024



Cotomo				المانية	. Main		2015 S Peoria STREET, Chicago, IL 60608
Catego	ry : Room		В	uilding	: wain	December	
0	Ham. Tuma	Laatian	O. contitu	HOM	Dank	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lavatory	Staff Restroom next to 301	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	Staff Restroom next to 301	1	EA	7	6-10 years	
	Walls - Concrete Block	Staff Restroom next to 301	224	SF	7	10+ years	
	Water Closet	Staff Restroom next to 301	1	EA	7	10+ years	
	Accessories	Staff Restroom next to 302	45	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	Staff Restroom next to 302	45	SF	7	10+ years	
	Doors - Steel Doors incl hw	Staff Restroom next to 302	1	EA	7	10+ years	
	Floor - Concrete	Staff Restroom next to 302	45	SF	7	10+ years	
	Floor Drain	Staff Restroom next to 302	1	EA	7	10+ years	
	Lavatory	Staff Restroom next to 302	1	EA	7	10+ years	
	Lighting - Pendent/Surface	Staff Restroom next to 302	1	EA	7	6-10 years	
	Walls - Concrete Block	Staff Restroom next to 302	224	SF	7	10+ years	
	Water Closet	Staff Restroom next to 302	1	EA	7	10+ years	
Catego	ry : Classroom		R	uilding	· Main		
Guiogo	.,		_	uag		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	om #101 (Kindergarten)						
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	638	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	362	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	170	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Floor - Concrete	1st Floor	170	SF	7	10+ years	
	Floor - Tile	1st Floor	1,000	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	6	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,155	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	220	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classro	om #102 (Regular Classroom)						
<u> </u>	Casework	1st Floor	42	LF	7	10 L voors	
	Casework Ceiling - Exposed	1st Floor	638	SF	7	10+ years 10+ years	
	Ceiling - Exposed Ceiling - Lay-in	1st Floor	362	SF SF	7		
	Chalk Board			SF LF	4	10+ years	
		1st Floor	12	SF		2-5 years	
	Doors - Side-lite	1st Floor	4	SF EA	7 7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	-			10+ years	
	Floor - Tile	1st Floor	1,000	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	

Campus Name: Walsh Page : 17 of 41 Assessment Date: 07/17/2024



Category : Classroom		В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Storage/ Closet	1st Floor	50	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,386	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	220	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #103 (Kindergarten)						
	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	638	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	362	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	170	SF	7	10+ years	
	Chalk Board	1st Floor	24	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	3	EA	7	10+ years	
	Floor - Concrete	1st Floor	170	SF	7	10+ years	
	Floor - Tile	1st Floor	1,000	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	17,000	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7		
		1st Floor	8	SF		6-10 years	
	Storage/ Closet Walls - Concrete Block	1st Floor	0 1,155	SF SF	7 7	10+ years	
		1st Floor		SF SF		10+ years	
	Walls - Plaster/Drywall		220		7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #104 (Pre School)						
	Casework	1st Floor	42	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	638	SF	6	6-10 years	
	Ceiling - Lay-in	1st Floor	203	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	841	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,100	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	462	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	m #105 (Kindergarten)						
JIGSSIOU	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	638	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	362	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	170	SF	7	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	

Campus Name: Walsh Page : 18 of 41 Assessment Date: 07/17/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Side-lite	1st Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Floor - Concrete	1st Floor	170	SF	7	10+ years	
	Floor - Tile	1st Floor	1,000	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	17	EA	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,155	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	220	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #106 (Pre School)						
	Casework	1st Floor	42	LF	7	10+ years	
	Ceiling - Exposed	1st Floor	638	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	203	SF	7	10+ years	
	Chalk Board	1st Floor	30	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	841	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,342	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	220	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #201 (Regular Classroom)						
	Casework	2nd Floor	42	LF	7	6-10 years	
	Ceiling - Exposed	2nd Floor	638	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	211	SF	6	10+ years	
	Doors - Side-lite	2nd Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	841	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	12	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,089	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	220	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #202 (Computer Lab)						
JIGGGIOC	Ceiling - Exposed	2nd Floor	638	SF	6	10+ years	
	Ceiling - Exposed Ceiling - Lay-in	2nd Floor	268	SF SF	7		
	Doors - Side-lite	2nd Floor		SF SF		10+ years	
	Doors - Steel Doors incl hw	2nd Floor 2nd Floor	4 2	SF EA	7 7	10+ years	
	Doors - Steel Doors linci LIM	2110 F1001	2	EA	1	10+ years	



Catego	ry : Classroom		В	uilding	: Main		· • • • • • • • • • • • • • • • • • • •
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile/Sheet	2nd Floor	906	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	19	EA	6	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,089	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	220	SF	6	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
Classro	om #203 (Regular Classroom)						
	Casework	2nd Floor	42	LF	7	10+ years	
	Ceiling - Exposed	2nd Floor	638	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	245	SF	7	10+ years	
	Chalk Board	2nd Floor	8	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor		SF	7	,	
			4	SF EA		10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2		7	10+ years	
	Floor - Tile/Sheet	2nd Floor	883	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EΑ	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,342	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	220	SF	6	10+ years	
	Work Sink	2nd Floor	1	EA	7	6-10 years	
Classroo	om #204 (Regular Classroom)						
	Casework	2nd Floor	42	LF	7	10+ years	
	Ceiling - Exposed	2nd Floor	638	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	245	SF	7	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	883	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor 2nd Floor	1,122	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	440	SF	7	10+ years	
Classro	om #205 (Regular Classroom)						
_Cia55100	` •	Ond Floor	40	1.5	7	40	
	Casework	2nd Floor	42	LF	7	10+ years	
	Ceiling - Exposed	2nd Floor	638	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	245	SF	7	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	4	SF	7	10+ years	

Campus Name: Walsh Page : 20 of 41 Assessment Date: 07/17/2024



Catego	ry : Classroom		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	2nd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	883	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	50	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	1,342	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	220	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	m #206 (Regular Classroom)						
	Casework	2nd Floor	42	LF	7	10+ years	
	Ceiling - Exposed	2nd Floor	638	SF	6	10+ years	
	Ceiling - Lay-in	2nd Floor	203	SF	7	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	841	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	15	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	8	SF	7	•	
	Walls - Concrete Block	2nd Floor	0 1,122	SF SF	7	10+ years	
	Walls - Concrete Block Walls - Plaster/Drywall	2nd Floor	220	SF SF	6	10+ years	
	Walls - Plaster/Drywall Work Sink	2nd Floor	220	EA	7	10+ years 6-10 years	
						, , , , , , ,	
_Classroc	m #301 (Regular Classroom)						
	Casework	3rd Floor	42	LF	7	10+ years	
	Ceiling - Exposed	3rd Floor	638	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	203	SF	6	10+ years	
	Chalk Board	3rd Floor	14	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	841	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Marker Board	3rd Floor	12	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	8	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,089	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	220	SF	6	10+ years	
Classroo	m #302 (Regular Classroom)						
	Casework	3rd Floor	42	LF	7	10+ years	
	Casework Ceiling - Exposed	3rd Floor	638	SF	, 6	10+ years 10+ years	
	Ceiling - Exposed Ceiling - Lay-in	3rd Floor	203	SF	7	10+ years 10+ years	
	Doors - Side-lite	3rd Floor	203	SF SF	7		
	Doors - Side-life	Siu Fiooi	4	ЭF	,	10+ years	



Catego	ry : Classroom		В	uilding	: Main		2013 01 conta office 11, officego, in occord
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Steel Doors incl hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	841	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	14	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	6-10 years	
	Marker Board	3rd Floor	16	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	8	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,122	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	220	SF	6	10+ years	
Classroo	om #303 (Regular Classroom)						
	Casework	3rd Floor	42	LF	7	10+ years	
	Ceiling - Exposed	3rd Floor	638	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	245	SF	7	10+ years	
	Doors - Side-lite	3rd Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	881	SF	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	2	SF	5	1-2 years	Chipped
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	Спіррса
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	50	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,342	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	220	SF	6	10+ years	
Classro	om #304 (Play Room)						
	Casework	3rd Floor	39	LF	7	10+ years	
	Casework	3rd Floor	3	LF	6	6-10 years	
	Ceiling - Exposed	3rd Floor	638	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	245	SF	7	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	883	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	16	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	50	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,122	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	440	SF	6	10+ years	
	Trans I laston bry wan	010 1 1001	440	Oi.	J	ioi youis	
_Classroo	om #305 (Art Room)	0.15		. –			
	Casework	3rd Floor	50	LF	7	6-10 years	
	Ceiling - Exposed	3rd Floor	638	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	245	SF	7	10+ years	
	Chalk Board	3rd Floor	5	LF	4	2-5 years	

Campus Name: Walsh Page : 22 of 41 Assessment Date: 07/17/2024





Catego	ry : Classroom		R	uilding	· Main		2015 S Peoria STREET, Chicago, IL 60608
Calcgo	i y . Giassi Goili			unung	. Maiii	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
O. Gup	Doors - Side-lite	3rd Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	883	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	13	ĒΑ	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	3	EA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	40	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,342	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	220	SF	6	10+ years	
	Work Sink	3rd Floor	1	EA	5	6-10 years	
Classroo	om #306 (Regular Classroom)						
	Casework	3rd Floor	42	LF	7	10+ years	
	Ceiling - Exposed	3rd Floor	638	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	245	SF	7	10+ years	
	Chalk Board	3rd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	3rd Floor	4	SF	7	10+ years	
	Doors - Steel Doors incl hw	3rd Floor	2	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	883	SF	7	10+ years	
	Lighting - Pendent/Surface	3rd Floor	15	EA	7	6-10 years	
	Lighting - Pendent/Surface	3rd Floor	1	EA	6	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Storage/ Closet	3rd Floor	50	SF	7	10+ years	
	Walls - Concrete Block	3rd Floor	1,122	SF	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	440	SF	7	10+ years	
Catego	ry : Interior		В	uilding	: Main		

C	Ham Time	Landin	O	LIOM	Donk	Recommend	Comments
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor							
	Ceiling - Lay-in	1st Floor	924	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	965	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	1st Floor	4	EΑ	7	6-10 years	
	Floor - Concrete	1st Floor	924	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	15	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,600	SF	7	10+ years	
	Walls - Masonry	1st Floor	1,955	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor - Main Entryway	385	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor - Main Entryway	2	EA	7	10+ years	
	Floor - Tile/Sheet	1st Floor - Main Entryway	365	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor - Main Entryway	20	SF	4	1-2 years	Cracked
	Lighting - Pendent/Surface	1st Floor - Main Entryway	5	ĒΑ	7	6-10 years	
	Walls - Concrete Block	1st Floor - Main Entryway	946	SF	7	10+ years	

Campus Name: Walsh Page : 23 of 41 Assessment Date: 07/17/2024





ıd
nt Comments
Bubbling
<u> </u>
5
,



Catego	ry : Interior		В	uilding			
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Wall Mounted	Stair # 2	6	EA	7	6-10 years	
	Stairs - Concrete	Stair # 2	206	LF	7	10+ years	
	Walls - Concrete Block	Stair # 2	2,668	SF	7	10+ years	
	Ceiling - Exposed	Stair # 4	240	SF	7	10+ years	
	Ceiling - Lay-in	Stair # 4	661	SF	6	6-10 years	
	Floor - Concrete	Stair # 4	601	SF	7	10+ years	
	Handrails	Stair # 4	336	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair # 4	3	EA	7	6-10 years	
	Lighting - Wall Mounted	Stair # 4	4	EA	7	6-10 years	
	Stairs - Concrete	Stair # 4	147	LF	7	10+ years	
	Walls - Concrete Block	Stair # 4	2,838	SF	7	10+ years	
	Ceiling - Exposed	Stair #3	927	SF	7	10+ years	
	Floor - Concrete	Stair #3	721	SF	7	10+ years	
	Handrails	Stair #3	146	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair #3	7	EA	7	6-10 years	
	Stairs - Concrete	Stair #3	206	LF	7	10+ years	
	Walls - Concrete Block	Stair #3	3,128	SF	7	10+ years	
_Vertical	Conveyance						
	Elevator - Elevator- Roped Holeless Hydraulic	N/A	1	EA	7	10+ years	

Page : 25 of 41 Campus Name: Walsh Assessment Date: 07/17/2024



Category : Exterior Building : Addition

Jaicgoi	ry : Exterior	Building : Addition							
						Recommend			
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
ntrance									
	Exterior Doors - Exterior Steel Door	18 - North Roof H	1	EA	7	10+ years			
	Exterior Doors - Store Front	3	2	EA	4	1-2 years	Corroded base		
	Exterior Doors - Side lite	4	2	EA	4	0-1 year	Corroded, multiple repairs		
	Exterior Doors - Store Front	4	2	EA	4	0-1 year	Corroded, doesn't close		
	Exterior Doors - Store Front	5	2	EA	4	1-2 years	Corroded		
oundatio	on								
	Foundation - Concrete	Entire Building	439	LF	7	10+ years			
	Foundation - Concrete	Entire Building	1	LF	5	2-5 years	Chipped corner		
	Superstructure - Metal Deck/ Concrete	Entire Building	23,182	SF	7	10+ years	Chipped como		
	Topping	Entire Ballating	20,102	O.	•	101 youro			
ighting									
annia.	Exterior Lighting - Wall Mounted	Entire Building	13	EA	6	6-10 years			
oof Sys		Dood C	4	ΓΛ	7	10			
	Access Ladder - Metal	Roof G	1	EA	7	10+ years			
	Chimney - Metal Flue	Roof G	40	LF	7	10+ years			
	Coping - Metal	Roof G	178	LF	7	10+ years			
	Downspouts - Exterior Downspouts	Roof G	4	LF	7	10+ years			
	Downspouts - Interior Downspouts	Roof G	76	LF	7	10+ years			
	Parapet - Parapet < 16" Height	Roof G	178	LF	7	10+ years			
	Roof - Modified Bitumen	Roof G	2,766	SF	7	10+ years			
	Roof Structure - Steel / Metal Deck/ Concrete Topping	Roof G	2,766	SF	7	10+ years			
	Coping - Stone	Roof H	450	LF	6	10+ years			
	Downspouts - Interior Downspouts	Roof H	130	LF	7	10+ years			
	Parapet - Parapet < 16" Height	Roof H	450	LF	7	10+ years			
	Roof - Modified Bitumen	Roof H	7,442	SF	7	10+ years			
	Roof Structure - Steel / Metal Deck/	Roof H	7,442 7,442	SF	7				
	Concrete Topping	KOOI FI	7,442	SF	1	10+ years			
/alls									
AIIU	Exterior Walls - Brick	Entire Building	12,200	SF	7	10+ years	Repairs		
	Exterior Walls - Brick	Entire Building	300	SF	5	2-5 years	Efflorescence roof		
	EXIGIOI Walls - DITOR	Entire Dunaing	300	Oi	J	2-0 years	Emolegoence root		
indows/		Fotine Building	247		7	40			
	Lintels - Steel	Entire Building	247	LF	7	10+ years			
	Windows - Louver Windows - Sash Aluminum Double-pane	Entire Building Entire Building	126 1,212	SF SF	6 5	10+ years 2-5 years	Issues opening and closing		

Campus Name: Walsh Page : 26 of 41 Assessment Date: 07/17/2024



Type ctrical Type am atic Transfer Switch lency Battery Packs - Corridors and gns - Corridors and Stairs lency A/C Power - Corridors and ty System - Intrusion Detection	Location Location Electrical Room Entire Building Entire Building Entire Building Entire Building	Quantity B Quantity 1 13 10 9,626 23,182	UOM UOM EA EA SF	Rank Rank 6 6 2	Recommend Replacement On Recommend Replacement 10+ years 6-10 years 0-1 year	Comments Rank, Reason and Priority Rep changed as signs have no backup batteries and the school has no
Type em atic Transfer Switch ency Battery Packs - Corridors and gns - Corridors and Stairs ency A/C Power - Corridors and ty System - Intrusion Detection	Electrical Room Entire Building Entire Building Entire Building	Quantity 1 13 10 9,626	UOM EA EA	6 6 2	Recommend Replacement 10+ years 6-10 years	Rank, Reason and Priority Rep changed as signs have no backup batteries and the school has no
em atic Transfer Switch lency Battery Packs - Corridors and gns - Corridors and Stairs lency A/C Power - Corridors and ty System - Intrusion Detection	Electrical Room Entire Building Entire Building Entire Building	1 13 10 9,626	EA EA	6 6 2	10+ years 6-10 years	Rank, Reason and Priority Rep changed as signs have no backup batteries and the school has no
em atic Transfer Switch lency Battery Packs - Corridors and gns - Corridors and Stairs lency A/C Power - Corridors and ty System - Intrusion Detection	Electrical Room Entire Building Entire Building Entire Building	1 13 10 9,626	EA EA	6 6 2	10+ years 6-10 years	Rank, Reason and Priority Rep changed as signs have no backup batteries and the school has no
atic Transfer Switch lency Battery Packs - Corridors and gns - Corridors and Stairs lency A/C Power - Corridors and ty System - Intrusion Detection	Entire Building Entire Building Entire Building	13 10 9,626	EA EA	6 2	6-10 years	changed as signs have no backup batteries and the school has no
gns - Corridors and Stairs gency A/C Power - Corridors and ty System - Intrusion Detection	Entire Building Entire Building Entire Building	13 10 9,626	EA EA	6 2	6-10 years	changed as signs have no backup batteries and the school has no
ency A/C Power - Corridors and ty System - Intrusion Detection	Entire Building	9,626			0-1 year	changed as signs have no backup batteries and the school has no
ty System - Intrusion Detection	· ·		SF	6		emergency generator.
	Entire Building	23,182		Ü	10+ years	emorgoney gonerators
and and Electrical Commiss for			SF	6	6-10 years	
and and Electrical Commiss for						
endent Electrical Service for ency power	1st Floor	1	EA	7	10+ years	Serves fire sprinkler system
endent Electrical Service for ency power	1st Floor	1	EA	7	10+ years	Serves building EM circuits
stem	Entire Building	23,182	SF	7	10+ years	Served by Main. Rank, Reason at Priority Rep changed as the systet has been replaced since previous assessment.
Electrical Service - 1600 A 08/3PH	Mechanical Room	1	EA	7	10+ years	
on						
ig and Power Panels - 100 A	Entire Building	2	EA	6	10+ years	Location changed for clarification.
ig and Power Panels - 100 A	Entire Building	1	EA	6	10+ years	EM fuse panel
g and Power Panels - Above 100 A	Entire Building	8	EA	7	10+ years	·
g and Power Panels - Above 100 A	Entire Building	1	EA	4	0-1 year	Rank, Reason and Priority Rep changed as open breaker slots expose live conductors presenting live front condition.
Distribution Panels - Greater than 600	Entire Building	1	EA	6	10+ years	
		В	uilding	: Additio	on	
e Protection			_		Recommend	
e Protection			UOM	Rank	Replacement	Comments
	tribution Panels - Greater than 600	tribution Panels - Greater than 600 Entire Building Protection	tribution Panels - Greater than 600 Entire Building 1	tribution Panels - Greater than 600 Entire Building 1 EA Protection Building	tribution Panels - Greater than 600 Entire Building 1 EA 6 Protection Building : Addition	tribution Panels - Greater than 600 Entire Building 1 EA 6 10+ years Protection Building : Addition Recommend

Campus Name: Walsh Page : 27 of 41 Assessment Date: 07/17/2024



Catego	ry : Fire Protection		В	uilding	: Additi	on	-
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group	Fire Alarm Strobe Lights	Entire Building	23,182	SF	7	6-10 years	Comments
	Fire Alarm_System	Entire Building	23,182	SF	4	2-5 years	FACP is in Main. Rank, Reason and Priority Rep changed as the system is 25-plus years old and passes annual inspection, however it employs antiquated technology and has reached the end of its anticipated service life.
	Fire Pump Controller	Entire Building	1	EA	6	10+ years	Location changed for clarification.
_Pump R	oom Assembly						
·	Fire Pump - 25-50 hp	Pump Room	1	EA	5	6-10 years	Seal showing a minor drip at the time of assessment with evidence that it has been leaking since prior to the previous assessment.
	Jockey Pump	Pump Room	1	EA	6	10+ years	
Sprinkle	r Svetam						
_орппкіе	Sprinkler Heads	Entire Building	23,182	SF	7	6-10 years	
	Sprinkler Piping	Entire Building	23,182	SF	7	10+ years	
	Wet Sprinkler System	Entire Building	23,182	SF	6	10+ years	Location changed for clarification.
Catego	ry : Mechanical		В	uilding	: Additi	on	
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Air Cond							
	Condensing Unit- Roof Mounted - 31-50 tons	Roof	1	EA	7	10+ years	Associated with AHU-5. Rank, Reason and Priority Rep changed as the equipment has been replaced since previous assessment. No CPS Asset Tag present.
_Air Hand	lling Systems						
	VAV Box	Entire Building	20	EA	5	6-10 years	
	Indoor Return Fans- Centrifugal Inline - Greater than 20000 CFM	Mechanical Room	1	EA	6	10+ years	Associated with AHU-5.
	Air Handling Unit- Package Multi Zone- Indoor- Hot Water and DX Cooling Coils - 20001-30000 cfm	Mechanical Room - AHU-5	1	EA	5	10+ years	AHU-5 serves Addition (some data labels are incorrectly marked "AHU-1")
	Air Intake	Mechanical Room - AHU-5	1	EA	6	10+ years	
Boiler Sy	ystems						
	Boiler Auxiliary- Non Condensing Hot Water	Boiler Room	2	EA	5	10+ years	

Campus Name: Walsh Page : 28 of 41 Assessment Date: 07/17/2024



John A Walsh Elementary School

XIII S		2015 S Peoria STREET, C Building: Addition						
atego	ry : Mechanical		В	uilding	: Additi			
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
	- 500 - 1000 MBH							
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years		
	Combustion Dampers	Boiler Room	2	EA	6	10+ years		
	Glycol Feed System	Boiler Room	1	EA	6	10+ years		
	Hot Water Pump	Boiler Room	1	EA	6	10+ years		
	Hot Water Pump	Boiler Room	1	EA	6	10+ years		
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	1	EA	6	10+ years		
	Non Condensing- Water Tube- Flexible Tube- Force Draft- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	1	EA	5	10+ years		
leating l	Devices							
- 3	Unit Heater - Gas	3rd Floor	1	EA	6	6-10 years	Location changed for clarification.	
	Radiator Panels - Hot Water	Entire Building	4	ĒĀ	6	10+ years	Quantity changed to match current observations and per review with Building Engineer. One each is ceiling-mounted in the four student restrooms.	
	Cabinet Heaters - With Hot Water Coil	Entire Building	6	EA	6	10+ years		
lechani	cal Plumbing							
	Hydronic Supply and Return - Steel	Entire Building	400	LF	6	10+ years		
empera	ture Control							
	DDC System	Entire Building	23,182	SF	4	0-1 year	System is inoperable. Temperature in all spaces throughout the building are manually controlled.	
	Electric Thermostat	Entire Building	1	EA	7	6-10 years	•	
	Electric Thermostat	Entire Building	1	EA	6	6-10 years		
	Thermostats - DDC	Entire Building	20	EA	6	6-10 years		
entilatio								
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	7	10+ years	Newly installed since previous assessment. 2500 cfm.	
atego	ry : Plumbing		В	uilding	: Additi			
roup	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
ot Wate	· ·							
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years	Rank adjusted based on current observations and on the age of the	

Campus Name: Walsh Page : 29 of 41 Assessment Date: 07/17/2024



Catego	ry : Plumbing		В	uilding	on		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Gas Heater - Less than 150000 BTU/HR	Boiler Room	1	EA	6	6-10 years	equipment. Rank adjusted based on current observations and on the age of the equipment.
Piping							
. 0	Domestic Piping-Hot Water Return Lines	Entire Building	23,182	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	23,182	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	23,182	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	23,182	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	23,182	SF	7	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	23,182	SF	7	10+ years	
	Sanitary Piping	Entire Building	23,182	SF	7	10+ years	
	Storm Piping	Entire Building	23,182	SF	7	10+ years	
	Vent Piping	Entire Building	23,182	SF	7	10+ years	
Pumps							
•	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	10+ years	
	Pumps - Sump-Simplex	Entire Building	1	EA	6	10+ years	Location changed for clarification. Elevator pit sump pump. Inaccessible at the time of assessment. No CPS Asset Tag available. Condition verified by Building Engineer.

Category: Room **Building: Addition**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Administ	rative Suites/Offices						
	Ceiling - Lay-in	217 Office	420	SF	6	6-10 years	
	Ceiling - Lay-in	217 Office	15	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	217 Office	1	EΑ	7	10+ years	-
	Floor - Tile/Sheet	217 Office	435	SF	7	10+ years	
	Lighting - Lay-in	217 Office	6	EΑ	7	6-10 years	
	Power Distribution	217 Office	17	EΑ	7	10+ years	
	Walls - Concrete Block	217 Office	430	SF	7	10+ years	
	Walls - Plaster/Drywall	217 Office	176	SF	7	10+ years	

Campus Name: Walsh Page : 30 of 41 Assessment Date: 07/17/2024



Catego	ry : Room		В	uilding	: Additi		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	90	SF	7	10+ years	
Mechani	ical/ Service Rooms						
	Janitor's Closet	1st Floor	45	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	40	SF	7	10+ years	
	Mechanical/ Service Rooms	1st Floor	225	SF	7	10+ years	
	Storage Room	1st Floor	75	SF	7	10+ years	
	Vaults	1st Floor	180	SF	7	10+ years	
	Janitor's Closet	2nd Floor	28	SF	7	10+ years	
	Mechanical/ Service Rooms	3rd Floor	1,125	SF	7	10+ years	
	Storage Room	3rd Floor	975	SF	7	10+ years	
_	· ·					•	
Restroo	m Accessories	111A	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	111A	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw		1		7		
	Floor - Terrazzo	111A		EA SF		10+ years	
		111A	35		7	10+ years	
	Floor Drain	111A	1	EΑ	7	10+ years	
	Lavatory	111A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	111A	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	111A	192	SF	7	10+ years	
	Water Closet	111A	1	EA	7	10+ years	
	Accessories	113A	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	113A	35	SF	7	10+ years	
	Doors - Transom Window	113A	1	SF	7	10+ years	
	Floor - Terrazzo	113A	35	SF	7	10+ years	
	Floor Drain	113A	1	EA	7	10+ years	
	Lavatory	113A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	113A	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	113A	192	SF	7	10+ years	
	Water Closet	113A	1	EA	7	10+ years	
	Accessories	1st Floor	165	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	165	SF	7	10+ years	
	Floor - Terrazzo	1st Floor	165	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	3	EA	7	10+ years	
		1st Floor	420	SF		•	
	Walls - Structural Glazed Tile Water Closet	1st Floor			7	10+ years	
			3	EA	7	10+ years	
	Accessories	1st Floor	165	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	165	SF	6	6-10 years	



Catego	ategory : Room		Building : Addition				
				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Terrazzo	1st Floor	165	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Hand Dryer	1st Floor	1	EA	7	6-10 years	
	Lavatory	1st Floor	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	3	EA	7	6-10 years	
	Partitions	1st Floor	2	EA	7	10+ years	
	Urinals	1st Floor	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	420	SF	7	10+ years	
	Water Closet	1st Floor	2	EA	7	10+ years	
	Accessories	1st Floor	40	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	40	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	40	SF	7	10+ years	
	Floor Drain	1st Floor	1	EA	7	10+ years	
	Lavatory	1st Floor	1	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	1st Floor	208	SF	7	10+ years	
	Water Closet	1st Floor	1	EA	7	10+ years	
	Accessories	211A	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	211A	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw	211A	1	ĒΑ	7	10+ years	
	Floor - Terrazzo	211A	35	SF	7	10+ years	
	Floor Drain	211A	1	ĒΑ	7	10+ years	
	Lavatory	211A	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	211A	1	EA	7	10+ years	
	Walls - Structural Glazed Tile	211A	35	SF	7	10+ years	
	Water Closet	211A	1	EA	7	10+ years	
	Accessories	213A	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	213A	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw	213A	1	EA	7	10+ years	
	Floor - Terrazzo	213A	35	SF	7	10+ years	
	Floor Drain	213A	1	EA	7	10+ years	
	Lavatory	213A	1	EA	7	10+ years	
	Lighting - Pendent/Surface	213A	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	213A	192	SF	7	10+ years	
	Water Closet	213A 213A	192	EA	7	10+ years	
	Accessories	215A 215A	35	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	215A 215A	35	SF	7	10+ years	
	Doors - Wood Doors inclu hw	215A 215A	ან 1	EA	7	10+ years 10+ years	
	Floor - Terrazzo	215A 215A	35	SF	7 7	-	
	Floor - Terrazzo Floor Drain	215A 215A	ან 1	EA	7	10+ years	
			1			10+ years	
	Lavatory	215A	1	EΑ	7	10+ years	
	Lighting - Pendent/Surface	215A	1	EA	7	6-10 years	
	Walls - Structural Glazed Tile	215A	192	SF	7	10+ years	



Catego	ry : Room			Building : Addition				
						Recommend		
Group	Item - Type	Location	Quantity			Replacement	Comments	
	Water Closet	215A		1 E/		10+ years		
	Accessories	2nd Floor	16			6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	16			10+ years		
	Floor - Terrazzo	2nd Floor	16			10+ years		
	Floor Drain	2nd Floor		1 E		10+ years		
	Hand Dryer	2nd Floor		1 E/		6-10 years		
	Lavatory	2nd Floor		2 E		10+ years		
	Lighting - Pendent/Surface	2nd Floor		3 E/		6-10 years		
	Partitions	2nd Floor		3 E		10+ years		
	Walls - Structural Glazed Tile	2nd Floor	42			10+ years		
	Water Closet	2nd Floor		3 E		10+ years		
	Accessories	2nd Floor	16			6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	16			10+ years		
	Floor - Terrazzo	2nd Floor	16			10+ years		
	Floor Drain	2nd Floor				10+ years		
	Hand Dryer	2nd Floor		1 E/		6-10 years		
	Lavatory	2nd Floor		2 E		10+ years		
	Lighting - Pendent/Surface	2nd Floor		3 E		6-10 years		
	Partitions	2nd Floor		2 E/		6-10 years		
	Urinals	2nd Floor		1 E/		10+ years		
	Walls - Structural Glazed Tile	2nd Floor	42			10+ years		
	Water Closet	2nd Floor		2 E/		6-10 years		
	Accessories	2nd Floor	4			6-10 years		
	Ceiling - Plaster/Drywall	2nd Floor	4			10+ years		
	Doors - Wood Doors inclu hw	2nd Floor		1 E <i>l</i>		10+ years		
	Floor - Terrazzo	2nd Floor	4			10+ years		
	Floor Drain	2nd Floor		1 E		10+ years		
	Lavatory	2nd Floor		1 E <i>l</i>		10+ years		
	Lighting - Pendent/Surface	2nd Floor		1 E/		6-10 years		
	Walls - Structural Glazed Tile	2nd Floor	20			10+ years		
	Water Closet	2nd Floor		1 E/		10+ years		
	Accessories	3rd Floor	4			10+ years		
	Ceiling - Plaster/Drywall	3rd Floor	4			6-10 years		
	Doors - Wood Doors inclu hw	3rd Floor		1 E/		10+ years		
	Floor - Concrete Epoxy/ Painted	3rd Floor	4			6-10 years		
	Floor Drain	3rd Floor		1 E/		10+ years		
	Lavatory	3rd Floor		1 E <i>l</i>		10+ years		
	Lighting - Pendent/Surface	3rd Floor		1 E <i>l</i>		6-10 years		
	Walls - Concrete Block	3rd Floor	19			10+ years		
	Water Closet	3rd Floor		1 E/	A 7	10+ years		



Catego	ry : Classroom		Building : Addition							
	_					Recommend				
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments			
_Classroo	m #110 (Regular Classroom)									
	Casework	1st Floor	50	LF	7	10+ years				
	Ceiling - Lay-in	1st Floor	862	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor	8	SF	5	1-2 years	Water damage			
	Chalk Board	1st Floor	12	LF	4	2-5 years				
	Doors - Side-lite	1st Floor	12	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years				
	Floor - Tile	1st Floor	870	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years				
	Marker Board	1st Floor	12	LF	7	6-10 years				
	Storage/ Closet	1st Floor	6	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	704	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	176	SF	7	10+ years				
	Work Sink	1st Floor	1	EA	7	10+ years				
_Classroo	m #111 (Special Education)									
	Casework	1st Floor	22	LF	7	10+ years				
	Ceiling - Lay-in	1st Floor	468	SF	7	10+ years				
	Chalk Board	1st Floor	10	LF	4	2-5 years				
	Doors - Side-lite	1st Floor	12	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years				
	Floor - Tile	1st Floor	468	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	8	ĒΑ	7	6-10 years				
	Marker Board	1st Floor	10	LF	7	6-10 years				
	Storage/ Closet	1st Floor	10	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	472	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	176	SF	7	10+ years				
Classroo	m #112 (Store Room)									
	Casework	1st Floor	18	LF	7	10+ years				
	Ceiling - Lay-in	1st Floor	870	SF	7	10+ years				
	Ceiling - Lay-in	1st Floor	6	SF	5	1-2 years	Water damage			
	Chalk Board	1st Floor	22	LF	4	2-5 years	Water damage			
	Doors - Side-lite	1st Floor	12	SF	7	10+ years				
	Doors - Wood Doors inclu hw	1st Floor	. <u>-</u> 1	EA	7	10+ years				
	Floor - Tile	1st Floor	870	SF	7	10+ years				
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years				
	Marker Board	1st Floor	12	LF	7	6-10 years				
	Storage/ Closet	1st Floor	6	SF	7	10+ years				
	Walls - Concrete Block	1st Floor	528	SF	7	10+ years				
	Walls - Plaster/Drywall	1st Floor	352	SF	7	10+ years				
	Work Sink	1st Floor	1	EA	7	10+ years				



Category : Classroom			В	uildina	: Additi		2013 OT COMA OTIVEET, Officago, in 00000
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #113 (Special Education)		•			•	
	Casework	1st Floor	22	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	468	SF	7	10+ years	
	Chalk Board	1st Floor	10	LF	4	2-5 years	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	468	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	8	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	472	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	176	SF	7	10+ years	
Classroo	om #114 (Regular Classroom)						
_UIGSSIUU	Ceiling - Lay-in	1st Floor	870	SF	7	10+ years	
	Doors - Side-lite	1st Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor		EA	7	10+ years	
	Floor - Tile	1st Floor	864	SF	7	10+ years	
	Floor - Tile	1st Floor	6	SF	4	1-2 years	Chipped cracked
	Lighting - Lay-in	1st Floor	12	EΑ	7	6-10 years	oppod o.dood
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	704	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	176	SF	7	10+ years	
Classroo	om #115 (Regular Classroom)						
_01000100	Casework	1st Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	1st Floor	970	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	970	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	100	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	528	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	352	SF	7	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
Classroo	om #210 (Science Classroom)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Casework Ceiling - Lay-in	2nd Floor 2nd Floor	935	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor 2nd Floor	35	SF	5	1-2 years	Water damage
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	water damage
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years	
			_			,	

Campus Name: Walsh Page : 35 of 41 Assessment Date: 07/17/2024



Category : Classroom			В	uilding	: Addition	on		
			Recommend					
roup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Floor - Tile/Sheet	2nd Floor	967	SF	7	10+ years		
	Floor - Tile/Sheet	2nd Floor	3	SF	5	1-2 years	Chipped	
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years	•	
	Marker Board	2nd Floor	12	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	100	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	528	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	352	SF	7	10+ years		
	Work Sink	2nd Floor	3	EA	7	6-10 years		
lassroo	om #211 (Special Education)							
1000100	Casework	2nd Floor	22	LF	7	10+ years		
	Casework Ceiling - Lay-in	2nd Floor	468	SF	7	10+ years		
	Chalk Board	2nd Floor 2nd Floor	10	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor 2nd Floor	10	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	2nd Floor	468	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	8	EA	7	6-10 years		
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	10	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	472	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	176	SF	7	10+ years		
lassroc	om #212 (Regular Classroom)							
	Casework	2nd Floor	50	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	856	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	20	SF	5	1-2 years	Water damage	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years		
	Floor - Tile/Sheet	2nd Floor	870	SF	7	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	6-10 years		
	Marker Board	2nd Floor	10	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	6	SF	7	10+ years		
	Walls - Concrete Block	2nd Floor	528	SF	7	10+ years		
	Walls - Plaster/Drywall	2nd Floor	352	SF	7	10+ years		
	Work Sink	2nd Floor	1	EA	7	6-10 years		
	um #242 (Chanial Education)							
assroc	om #213 (Special Education)	0.15						
	Ceiling - Lay-in	2nd Floor	464	SF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	4	SF	5	1-2 years	Water damage	
	Chalk Board	2nd Floor	20	LF	4	2-5 years		
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile/Sheet	2nd Floor	468	SF	7	10+ years		

Campus Name: Walsh Page : 36 of 41 Assessment Date: 07/17/2024



Category : Classroom			В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	2nd Floor	8	EA	7	6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	472	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	176	SF	6	10+ years	
Classroo	om #214 (Regular Classroom)						
	Casework	2nd Floor	50	LF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	870	SF	7	10+ years	
	Chalk Board	2nd Floor	10	LF	4	2-5 years	
	Doors - Side-lite	2nd Floor	12	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	864	SF	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	6	SF	5		Chinned
				EA	7	1-2 years	Chipped
	Lighting - Lay-in	2nd Floor	12			6-10 years	
	Marker Board	2nd Floor	10	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	704	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	176	SF	7	10+ years	
	Work Sink	2nd Floor	1	EA	7	10+ years	
Classroo	om #215 (Special Program)						
	Casework	2nd Floor	20	LF	7	10+ years	Losse door
	Ceiling - Lay-in	2nd Floor	540	SF	7	10+ years	
	Doors - Hardware	2nd Floor	1	EA	6	1-2 years	Handle
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	540	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	8	EA	7	6-10 years	
	Marker Board	2nd Floor	16	LF	7	6-10 years	
	Storage/ Closet	2nd Floor	6	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor	528	SF	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	352	SF	7	10+ years	
Catego	ry : Interior		В	uildina	: Additi	on	
						Recommend	
Group Corridor	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
JUHUUL	Ceiling - Lay-in	1st Floor	1,978	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor	10	SF	5	1-2 years	Water damage
	Doors - Steel Doors incl hw	1st Floor	8	EA	7	10+ years	
	Drinking Fountains - Double Fountain	1st Floor	1	EA	7	6-10 years	
	Floor - Terrazzo	1st Floor	1,988	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	54	EA	7	6-10 years	



Catego	ry : Interior	В	uilding				
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Student Lockers - One Tier	1st Floor	99	EA	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	2,838	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,815	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	40	SF	5	1-2 years	Water damage
	Doors - Steel Doors incl hw	2nd Floor	9	EA	7	10+ years	
	Drinking Fountains - Double Fountain	2nd Floor	1	EA	7	6-10 years	
	Floor - Terrazzo	2nd Floor	1,855	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	54	EA	7	6-10 years	
	Student Lockers - One Tier	2nd Floor	99	EA	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor	2,676	SF	7	10+ years	
_Stairs							
	Ceiling - Exposed	Stair # 5	128	SF	7	10+ years	
	Floor - Terrazzo	Stair # 5	96	SF	7	10+ years	
	Handrails	Stair # 5	90	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair # 5	2	EA	7	6-10 years	
	Stairs - Terrazzo	Stair # 5	73	LF	7	10+ years	
	Walls - Concrete Block	Stair # 5	1,152	SF	7	10+ years	
	Ceiling - Lay-in	Stair # 6	516	SF	7	10+ years	
	Floor - Terrazzo	Stair # 6	744	SF	7	10+ years	
	Handrails	Stair # 6	60	LF	7	10+ years	
	Lighting - Lay-in	Stair # 6	9	EA	7	6-10 years	
	Stairs - Terrazzo	Stair # 6	126	LF	7	10+ years	
	Walls - Structural Glazed Tile	Stair # 6	2,200	SF	7	10+ years	
	Ceiling - Exposed	Stair # 7	240	SF	7	10+ years	
	Floor - Concrete	Stair # 7	120	SF	7	10+ years	
	Handrails	Stair # 7	60	LF	7	10+ years	
	Lighting - Pendent/Surface	Stair # 7	1	EA	7	6-10 years	
	Stairs - Concrete	Stair # 7	63	LF	7	10+ years	
	Walls - Concrete Block	Stair # 7	840	SF	7	10+ years	
Vertical (Conveyance						
	Elevator - Hydraulic Elevator	N/A	1	EA	7	10+ years	



Category : Site Building : Site

Sategory : Site		В					
						Recommend	_
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
vil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	6	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	13	EA	7	10+ years	
ncing							
	Fencing - Guard Rail	Entire Site	81	LF	7	10+ years	
	Fencing - Old Standard Ornamental	Entire Site	1,026	LF	6	6-10 years	Painted
ndsca	•	Entire Site	2	ΓΛ	7	10	
	Benches	Entire Site Entire Site	3	EA SF	7	10+ years	Not working
	Irrigation		33,320	SF SF	4	0-1 year	Not working
	Landscape - Grass	Entire Site	42,463		6	10+ years	
	Landscape - Grass	Entire Site	4,000	SF	5	2-5 years	
	Landscape - Hardscape- Concrete	Entire Site	15	SF	6	6-10 years	
	Landscape - Hardscape- Concrete	Entire Site	15,590	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	175	SF	7	10+ years	
	Parkway trees	Entire Site	32	EA	7	10+ years	
	Parkway trees	Entire Site	3	EA	4	0-1 year	Dead, missing
	Planting Beds/ Area	Entire Site	1,573	SF	7	10+ years	
	Planting Beds/ Area	Entire Site	64	SF	6	6-10 years	New planters
	Retaining Wall - Concrete	Entire Site	60	SF	7	10+ years	
	Trash Receptacles	Entire Site	2	EA	7	10+ years	
	Walking Path - Crushed Stone	Entire Site	1,092	SF	5	2-5 years	
king	Lot						
J	Concrete Curbs	Parking Lot- North	432	LF	7	10+ years	
	Concrete Curbs	Parking Lot- North	10	LF	4	1-2 years	Cracked
	Interior Plantings	Parking Lot- North	2	LF	7	10+ years	
	Lighting - Pole Mounted	Parking Lot- North	4	EA	7	10+ years	
	Surface - Asphalt	Parking Lot- North	40	SF	7	10+ years	
	Surface - Asphalt	Parking Lot- North	8,580	SF	6	10+ years	
	Surface - Asphalt	Parking Lot- North	200	SF	4	1-2 years	Cracks, spalling
	Surface - Concrete	Parking Lot- North	1,200	SF	7	10+ years	3
	Trash Enclosure - Masonry	Parking Lot- North	350	SF	7	10+ years	
	Vehicular Screening	Parking Lot- North	111	LF	7	10+ years	
	•	5				- ,	
laygrou							
aygio	Facilities and Dec I/O F	Northeast/Southeast	1	EA	7	10+ years	
laygro	Equipment - Pre K 3-5					•	
laygro	Equipment - Pre K 3-5 Equipment - School Age 5-12 Surface - Poured Surface	Northeast/Southeast Northeast/Southeast	1 6,548	EA SF	7 6	10+ years 10+ years	



Catego	Category : Site			uilding			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
_Sidewalk	S						
	Sidewalks - Perimeter Sidewalks	Entire Site	2,750	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	18,068	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	1,000	SF	4	0-1 year	Heaving from tree roots
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	7	10+ years	
	Monument - Building Mounted Cut Letter	Entire Site	1	EA	7	10+ years	
	Sign	- -			_		
	Monument - Sign	Entire Site	1	EA	7	10+ years	
	Monument - Sign	Entire Site	1	EA	7	10+ years	

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").

Campus Name: Walsh Page: 40 of 41 Assessment Date: 07/17/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary				1					
			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	monded deage	Noom Location	Italiboi	Italiboi	(0.)	Allou	Alou	Стор	Doura
Art Room	Regular Classroom	3rd Floor	305	NA	923	102	51	Y	Υ
Computer Lab	Computer Lab	2nd Floor	202	NA	914	102	51	N	N
Kindergarten	Kindergarten	1st Floor	101	NA	1,178	270	56	Y	N
Kindergarten	Kindergarten	1st Floor	105	NA	1,178	270	56	Y	N
Kindergarten	Pre School	1st Floor	103	NA	1,178	270	56	Y	N
Play Room	Regular Classroom	3rd Floor	304	NA	883	102	51	Y	N
Pre School	Pre School	1st Floor	104	NA	849	105	48	Y	N
Pre School	Pre School	1st Floor	106	NA	849	105	48	Y	N
Regular Classroom	Regular Classroom	1st Floor	102	NA	1,050	105	48	Y	N
Regular Classroom	Regular Classroom	2nd Floor	201	NA	849	102	51	Y	Υ
Regular Classroom	Regular Classroom	2nd Floor	203	NA	883	102	51	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	204	NA	883	102	51	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	205	NA	883	102	51	Y	N
Regular Classroom	Regular Classroom	2nd Floor	206	NA	849	102	51	N	N
Regular Classroom	Regular Classroom	3rd Floor	301	NA	849	102	51	Y	Υ
Regular Classroom	Regular Classroom	3rd Floor	302	NA	849	102	51	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	303	NA	883	102	51	Υ	N
Regular Classroom	Regular Classroom	3rd Floor	306	NA	883	102	51	N	Υ
Building : Addition	T		T	1		Ţ	T		т
Regular Classroom	Regular Classroom	1st Floor	110	NA	870	102	51	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	114	NA	870	102	51	Y	Υ
Regular Classroom	Regular Classroom	1st Floor	115	NA	970	108	42	N	Υ
Regular Classroom	Regular Classroom	2nd Floor	212	NA	876	102	51	Υ	N
Regular Classroom	Regular Classroom	2nd Floor	214	NA	870	102	51	Υ	Υ
Science Classroom	Regular Classroom	2nd Floor	210	NA	970	102	51	Υ	Υ
Special Education	Special Education	1st Floor	111	NA	468	72	28	Υ	N
Special Education	Special Education	1st Floor	113	NA	468	72	28	Υ	N
Special Education	Special Education	2nd Floor	211	211	468	70	34	Υ	N
Special Education	Special Education	2nd Floor	213	NA	468	68	34	Υ	N
Special Program	Special Education	2nd Floor	215	215	540	70	34	Υ	N
Store Room	Regular Classroom	1st Floor	112	NA	876	102	51	Y	Υ