

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1944	1	24,950
Addition	2015	3	35,068
Campus Total			60,018

Category : Exterior Building : Main

oalegoi	y . Exterior		unung				
	-		0		D	Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio	#1 - S	1	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	#1 - S	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#1 - S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#1 - S	58	LF	6	10+ years	
	Exterior Stairs - Concrete	#1 - S	2	LF	5	0-1 year	Cracked landing, cracked stairs
	Power Door Operator and Controls	#1 - S	1	EA	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#1 - S	105	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#1 - S	5	LF	5	0-1 year	Broken concrete, loose, corroding
							rails
	Ramps - Concrete	#1 - S	50	LF	6	10+ years	
	Ramps - Concrete	#1 - S	5	LF	5	0-1 year	Broken concrete, loose rails
	Stair Handrail - Steel_Stair Handrail	#1 - S	50	LF	6	10+ years	
	Entrance Control - Audio and Video	#2 - N - Main	1	EΑ	6	10+ years	
	Exterior Doors - Exterior AMP Door	#2 - N - Main	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#2 - N - Main	1	EA	6	10+ years	
	Power Door Operator and Controls	#2 - N - Main	1	EA	7	10+ years	
	Exterior Doors - Exterior AMP Door	#3 - N east end	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	#3 - N east end	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#3 - N east end	28	LF	6	10+ years	
	Exterior Stairs - Concrete	#3 - N east end	2	LF	5	0-1 year	Cracked stairs and landing, broker cheek walls
	Ramp Handrail - Steel_Ramp Handrail	#3 - N east end	65	LF	6	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	#3 - N east end	5	LF	5	0-1 year	Loose, corroding handrail



Catego	ry : Exterior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ramps - Concrete	#3 - N east end	25	LF	6	10+ years	
	Ramps - Concrete	#3 - N east end	5	LF	5	0-1 year	Broken concrete
	Stair Handrail - Steel_Stair Handrail	#3 - N east end	25	LF	6	10+ years	
	Stair Handrail - Steel_Stair Handrail	#3 - N east end	2	LF	5	0-1 year	Broken concrete, corroding, news
	Exterior Doors - Exterior AMP Door	#4 - North - Middle	2	EA	6	10+ years	rails
	Exterior Doors - Transom Lite	#4 - North - Middle	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#4 - North - Middle	13	LF	6	10+ years	
	Exterior Doors - Exterior AMP Door	#5 - N - West end	3	EA	6	10+ years	
	Exterior Doors - Transom Lite	#5 - N - West end	3	EA	6	10+ years	
	Exterior Stairs - Concrete	#5 - N - West end	39	LF	6	10+ years	
	Exterior Stairs - Concrete	#5 - N - West end	1	LF	5	1-2 years	Chipped nosing, cracked concrete
	Stair Handrail - Steel_Stair Handrail	#5 - N - West end	18	LF	6	6-10 years	omprou neomy, cracked concrete
	Exterior Doors - Exterior Steel Door	#6 - W	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#6 - W	20	LF	6	10+ years	
	Stair Handrail - Steel Stair Handrail	#6 - W	15	LF	6	6-10 years	
	Entrance Control - Audio and Video	#8 - SW	13	EA	6	10+ years	
	Exterior Doors - Exterior AMP Door	#8 - SW	2	EA	6	10+ years	
	Exterior Doors - Exterior AMF Door Exterior Doors - Transom Lite	#8 - SW	1	EA	6	10+ years	
	Exterior Doors - Transom Lite Exterior Doors - Exterior Steel Door	#6 - 3vv #8.5 - S	2	EA	6	10+ years	
	Exterior Doors - Exterior Steel Door	#8.5 - S	1	EA	6	•	
		#6.5 - 3 #9 - S	· · · · · · · · · · · · · · · · · · ·		_	10+ years	
	Exterior Doors - Exterior Steel Door		1	EΑ	6	10+ years	
	Exterior Doors - Transom Lite	#9 - S	1	EA	6	10+ years	
	Exterior Stairs - Concrete	#9 - S	3	LF	6	10+ years	
Foundat	ion						
	Foundation - Concrete	Entire Building	1,105	LF	7	10+ years	
	Foundation - Concrete	Entire Building	10	LF	6	10+ years	
	Superstructure - Heavy Timber	Entire Building	25,783	SF	7	10+ years	
Liahtina							
ட்டன்	Exterior Lighting - Wall Mounted	Entire Building	23	EA	7	6-10 years	
	Exterior Lighting - Wall Mounted	Entire Building	2	EA	5	2-5 years	
Roof Sy	stem						
	Coping - Metal	Low W roof	122	LF	7	10+ years	
	Downspouts - Exterior Downspouts	Low W roof	45	LF	5	6-10 years	Corroding gutters and some
						•	downspouts
	Parapet - 16" - 30" Height	Low W roof	122	LF	7	10+ years	
	Roof - Modified Bitumen	Low W roof	2,654	SF	6	2-5 years	No access no hatch at this building. No access from adjoining low roof because windows do not open fully.
	Roof Structure - Heavy Timber	Low W roof	2,654	SF	7	10+ years	, ,

Campus Name: Wildwood Page : 2 of 33 Assessment Date: 07/15/2024



Group	Item - Type Chimney - Metal Flue Downspouts - Exterior Downspouts	Location Low roof	Quantity	UOM	Donk	Recommend	
Group	Chimney - Metal Flue		Quantity			Daniacamant	Commonte
		LOW 1001	25	LF	Rank 7	Replacement 10+ years	Comments
		Low roof	100	LF	5	6-10 years	Corroding gutters and some downspouts
	Roof - Modified Bitumen	Low roof	4,430	SF	5	2-5 years	Worn surface throughout, blistering
	Roof - Modified Bitumen	Low roof	200	SF	4	0-1 year	Ponding, Blistering, soft spots, open seams, active leak for engineer. Near door eight and near door 8.5, two locations.
	Roof - Modified Bitumen	Low roof	10	SF	3	0-1 year	Growing vegetation through roof
	Roof Structure - Heavy Timber	Low roof	4,640	SF	7	10+ years	
	Access Ladder - Metal	Main Roof	2	EA	7	10+ years	No additional ladders to exterior seen
	Access Ladder - Wood	Main Roof	1	EA	4	1-2 years	One by four slat nailed ladder. Shakes, does not reach the height of the hatch. Paul extension is poorly. Attached Only one ladder seen
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	21	LF	6	10+ years	
	Chimney - Brick Chimney- Concrete/ Mortar Liner	Main Roof	15	LF	6	10+ years	
	Chimney - Metal Flue	Main Roof	20	LF	6	10+ years	
	Chimney - Metal Flue	Main Roof	20	LF	6	10+ years	
	Downspouts - Exterior Downspouts	Main Roof	225	LF	5	6-10 years	Corroding gutters and some downspouts
	Roof - Asphalt Shingle	Main Roof	13,445	SF	5	2-5 years	
	Roof - Asphalt Shingle	Main Roof	200	SF	4	1-2 years	Missing shingles, broken, ripped tiles. leaks to interior,
	Roof - Modified Bitumen	Main Roof	3,556	SF	6	2-5 years	Surfaces showing signs of where in tear,
	Roof - Modified Bitumen	Main Roof	200	SF	4	1-2 years	Blistering, open seams
	Roof Hatch - Metal	Main Roof	1	EA	7	10+ years	
	Roof Hatch - Metal	Main Roof	1	EA	3	1-2 years	Engineer cannot find the interior access to this hatch. He does not use it.
	Roof Structure - Heavy Timber	Main Roof	17,401	SF	7	10+ years	
	Downspouts - Exterior Downspouts	W roof	36	LF	5	6-10 years	Corroding gutters and some downspouts
	Roof - Asphalt Shingle	W roof	5,687	SF	5	2-5 years	Worn out shingles throughout
	Roof - Asphalt Shingle	W roof	100	SF	3	0-1 year	Missing several shingles towards the ridge
	Roof Structure - Heavy Timber	W roof	5,787	SF	7	10+ years	
Walls							
	Cheek-Wall - Concrete	Entire Building	64	SF	6	6-10 years	
	Cheek-Wall - Concrete	Entire Building	54	SF	5	6-10 years	

Campus Name: Wildwood Page : 3 of 33 Assessment Date: 07/15/2024



ry : Exterior		E	Building	: Main		
					Recommend	
		Quantity		Rank	Replacement	Comments
Cheek-Wall - Concrete	Entire Building	24	SF	4	0-1 year	Broken concrete
Cornice - Wood	Entire Building	1,000	LF	6	10+ years	
Cornice - Wood	Entire Building	115	LF	5	2-5 years	Rotting wood, most paint has flaked off. Possibility of chipping lead paint
Exterior Walls - Brick	Entire Building	17,825	SF	6	10+ years	, , , , ,
Exterior Walls - Brick	Entire Building		SF	4	10+ years	Open joints, cracked brick, bulging walls. What are coming through the walls and damaging the plaster in the music room.
Exterior Walls - Wood Siding	Entire Building	400	SF	6	10+ years	
Exterior Walls - Wood Siding	Entire Building		SF	5	2-5 years	Rotting wood, most paint has flaked off. Possibility of chipping lead paint
				6		
	Entire Building	24		6	10+ years	
Guard - Guards perforated	Entire Building	48		6	10+ years	
Guard - Guards wire guard	Entire Building	68	SF	6	10+ years	
Guard - Guards wire guard	Entire Building	876	SF	6	10+ years	
Lintels - Brick	Entire Building	27	LF	6	10+ years	
Lintels - Steel	Entire Building	375	LF	6	10+ years	
Windows - Decorative	Entire Building	60	SF	6	6-10 years	
Windows - Louver		2	SF	4		Improvised grille
Windows - Sash Aluminum Double-pane	Entire Building	3,044	SF	6	10+ years	
ry : Electrical		Е	Building	: Main		
Itam Tuna	Location	Quantity	HOM	Book		Comments
	Location	Quantity	OCIVI	Italik	Replacement	Comments
	Entire Building	1	ΕΛ	6	6-10 years	In electrical room next to gym
Emergency A/C Power - Corridors and Stairs	Entire Building	4,333	SF	6	10+ years	in electrical room next to gym
Emergency A/C Power - Gym	Entire Building	2,405	SF	6	10+ years	
			SF	6	10+ years	
	Entire Building	1 012		•	ioi youio	
Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and	Entire Building Entire Building	1,012 13	EA	6	6-10 years	
Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose					6-10 years 6-10 years	
Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room	Entire Building Entire Building	13	EA EA	6	6-10 years	
Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets	Entire Building Entire Building Entire Building	13 4 4	EA EA EA	6 6 6	6-10 years	
Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets Exit Signs - Corridors and Stairs	Entire Building Entire Building Entire Building Entire Building	13	EA EA EA	6 6 6	6-10 years 6-10 years 6-10 years	
Emergency A/C Power - Students Toilets Emergency Battery Packs - Corridors and Stairs Emergency Battery Packs - Multipurpose Room Emergency Battery Packs - Students Toilets	Entire Building Entire Building Entire Building	13 4 4 11	EA EA EA	6 6 6	6-10 years	
	Exterior Walls - Brick Exterior Walls - Brick Exterior Walls - Wood Siding Exterior Walls - Wood Siding Exterior Walls - Wood Siding Clerestory - Glass Double-Pane Clerestory - Glass Single-Pane Curtain wall - Louver Guard - Guards perforated Guard - Guards wire guard Guard - Guards wire guard Lintels - Brick Lintels - Steel Windows - Decorative Windows - Louver Windows - Sash Aluminum Double-pane ry: Electrical Item - Type ncy System Automatic Transfer Switch Emergency A/C Power - Corridors and	Cheek-Wall - Concrete Cornice - Wood Cornice - Wood Entire Building Exterior Walls - Brick Exterior Walls - Brick Exterior Walls - Brick Exterior Walls - Brick Exterior Walls - Wood Siding Entire Building Exterior Walls - Wood Siding Entire Building Exterior Walls - Wood Siding Entire Building Entire Building Clerestory - Glass Double-Pane Entire Building Curtain wall - Louver Guard - Guards Perforated Entire Building Guard - Guards wire guard Entire Building Entire Building Entire Building Entire Building Windows - Becorative Windows - Louver Windows - Sash Aluminum Double-pane Entire Building	Cheek-Wall - Concrete Entire Building 1,000 Cornice - Wood Entire Building 1,000 Cornice - Wood Entire Building 115 Exterior Walls - Brick Entire Building 17,825 Exterior Walls - Brick Entire Building 200 Exterior Walls - Brick Entire Building 200 Exterior Walls - Wood Siding Entire Building 400 Exterior Walls - Wood Siding Entire Building 104 Exterior Walls - Wood Siding Entire Building 200 Exterior Walls - Wood Siding Entire Building 104 Exterior Walls - Wood Siding Entire Building 200 Exterior Walls - Wood Siding Entire Building 104 Exterior Walls - Wood Siding Entire Building 200 Exterior Walls - Brick Entir	Cheek-Wall - Concrete Entire Building 24 SF Cornice - Wood Entire Building 1,000 LF Cornice - Wood Entire Building 1,000 LF Exterior Walls - Brick Entire Building 17,825 SF Exterior Walls - Brick Entire Building 200 SF Exterior Walls - Brick Entire Building 200 SF Exterior Walls - Wood Siding Entire Building 104 SF Exterior Walls - Wood Siding Entire Building 104 SF Exterior Walls - Wood Siding Entire Building 104 SF Clerestory - Glass Double-Pane Entire Building 24 SF Clerestory - Glass Single-Pane Entire Building 24 SF Curtain wall - Louver Entire Building 24 SF Guard - Guards perforated Entire Building 48 SF Guard - Guards wire guard Entire Building 68 SF Guard - Guards wire guard Entire Building 876 SF Lintels - Brick Entire Building 27 LF Lintels - Steel Entire Building 375 LF Windows - Decorative Entire Building 375 LF Windows - Louver Entire Building 2 SF Windows - Sash Aluminum Double-pane Entire Building 3,044 SF ry: Electrical Building ltem - Type Location Quantity UOM acy System Automatic Transfer Switch Entire Building 1 EA Emergency A/C Power - Corridors and Entire Building 1 EA Emergency A/C Power - Corridors and Entire Building 1 EA Entire Building 1 EA Entire Building 1 EA Entire Building 1 EA Emergency A/C Power - Corridors and Entire Building 4,333 SF	Cheek-Wall - Concrete Cornice - Wood Entire Building Exterior Walls - Brick Exterior Walls - Wood Siding Exterior Walls - Wood Siding Entire Building Exterior Walls - Wood Siding Exterior Walls - Woo	Item - Type



Catego	ry : Electrical		В	uilding	: Main		o in Filawatila Avenue, Officago, le 00040
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Main Ser		EL IB					
	Main Electrical Service - 2000 A 120/208/3PH	Electrical Room	1	EA	6	10+ years	Engineer reported many outages in electric power
	Independent Electrical Service for emergency power	Entire Building	1	EA	6	10+ years	
	PA System	Entire Building	24,950	SF	6	6-10 years	
Power D	stribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	7	10+ years	
	Lighting and Power Panels - 100 A	Entire Building	3	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	7	2-5 years	
	Lighting and Power Panels - Above 100 A	Entire Building	5	EA	7	10+ years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	7	10+ years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	10+ years	
	Main Distribution Panels - Less than 400 amp	Entire Building	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uilding	: Main		
	,		_			Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Fire Aları	n						
	Fire ALarm Anunciator	Entire Building	1	EA	7	6-10 years	Door 2
	Fire Alarm Panel	Entire Building	1	EA	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	24,950	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	24,950	SF	6	6-10 years	
Catego	ry : Mechanical		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Cond	itioning						
	Chemical Pot Feeder	Site North	1	EA	6	6-10 years	
	Chiller-Air Cooled-Scroll Type-Ground	Site North	1	EA	6	10+ years	
	Mounted - 50 - 100 tons					•	
	Glycol Feed	Site North	1	EA	6	10+ years	
	Pipes - Chilled Water Pipe- Copper	Site North	100	LF	6	10+ years	
	Pressure Fill System	Site North	1	EA	6	6-10 years	
Air Hand	ling Systems						
	Air Handling Unit- Package Single Zone- Indoor- Dual Temperature Coils - 6000- 10000 cfm	Attic	1	EA	6	10+ years	



Catego	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	Air Intake	Attic	1	EΑ	7	10+ years	
	Energy Recovery Unit	Attic	1	EA	7	10+ years	
Boiler Sy	ystems						
•	Boiler Auxiliary- Condensing Hot Water - 500 - 1000 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	6	10+ years	
	Condensing- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	2	EA	6	10+ years	
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	
	Water Fill System	Boiler Room	1	EA	5	6-10 years	
Heating	Devices						
	Fin Tube - Hot Water	Engineer's Office	5	LF	5	6-10 years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	6	EA	5	2-5 years	Leak observed some corrosion observed Cabinet heaters near door 2, 4 and 8 are not working
	Cabinet Heaters - With Hot Water Coil	Entire Building	5	EA	5	6-10 years	
	Wall Heater - Electric	Entire Building	7	EA	6	6-10 years	
	Unit Heater - Electric	Entire Building	2	EA	6	6-10 years	
	Unit Heater - Electric	Entire Building	2	EA	5	6-10 years	
	PTAC - Electric Heating and Self Contained Cooling	Entire Building	6	EA	6	6-10 years	
Mechani	ical Plumbing						
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	5	6-10 years	Water pump is leaking and insulation needs to be replaced
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	5	6-10 years	•
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	5	6-10 years	
	Hydronic Supply and Return - Copper	Entire Building	200	LF	6	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	100	LF	6	10+ years	
Tempera	ature Control						
	DDC System	Entire Building	24,950	SF	5	6-10 years	Does not work well. Siemens is working out the kinks
	Thermostats - DDC	Entire Building	16	EA	6	6-10 years	ŭ
Unit Ven	ntilation						
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	12	EA	6	6-10 years	Security desk dual temp cabinet heater with cooling
	Unit Ventilators- Floor Mounted- Dual Temperature Coils (Hot/Chilled) Water	Entire Building	3	EA	5	2-5 years	Leaks observed



Catego	Category : Mechanical				: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Ventilation	on						
	Exhaust Fans- Indoor - 1501 - 8000 CFM	Entire Building	1	EA	6	10+ years	
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	12	EA	6	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	3	EA	5	6-10 years	
Catego	ry · Plumbing		R	uildina	· Main		

Building: Main Category : Plumbing

Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	24,950	SF	6	6-10 years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	24,950	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	24,950	SF	6	6-10 years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	1	SF	7	10+ years	Lift station, serving annex and main building located outside next to the tennis courts in an aluminum enclosure padlocked
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	24,950	SF	6	6-10 years	Urinals have tanks that run continuously and need to be replaced drinking fountains in the building need to be replaced. Drinking fountain is connected to outside spigot with no backflow preventer that should be installed.
	Sanitary Piping	Entire Building	24,950	SF	5	6-10 years	
	Storm Piping	Entire Building	24,950	SF	5	6-10 years	No downspouts in the main building, causing water to flow on the façade
	Vent Piping	Entire Building	24,950	SF	5	6-10 years	-
Pumps							
·	Pumps - Sump-Simplex	Crawlspace	1	EA	6	6-10 years	In crawlspace, difficult to access an

Campus Name: Wildwood Page : 7 of 33 Assessment Date: 07/15/2024



Building: Main Category: Plumbing

Recommend Group Item - Type Location Quantity UOM Rank Comments Replacement

asset tag is missing

Category: Room **Building: Main**

Calego	ry . Room		ь	unung	. IVIAIII	_	
		1				Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
_Adminis	trative Suites/Offices						
	Ceiling - Plaster/Drywall	105A	139	SF	6	10+ years	
	Doors - Transom Window	105A	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	105A	1	EA	7	10+ years	
	Floor - Tile	105A	139	SF	7	10+ years	
	Lighting - Pendent/Surface	105A	2	EA	7	6-10 years	
	Power Distribution	105A	8	EA	7	10+ years	
	Walls - Plaster/Drywall	105A	480	SF	6	10+ years	Rank changed to match current observations
	Ceiling - Plaster/Drywall	113A Internet room	300	SF	7	10+ years	
	Doors - Wood Doors inclu hw	113A Internet room	1	EA	7	10+ years	
	Floor - Tile	113A Internet room	300	SF	7	10+ years	
	Lighting - Pendent/Surface	113A Internet room	2	EA	7	6-10 years	
	Power Distribution	113A Internet room	8	EA	7	10+ years	
	Walls - Plaster/Drywall	113A Internet room	680	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Counselor's Office next to Room 107	180	SF	7	10+ years	
	Doors - Transom Window	Counselor's Office next to Room 107	32	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Counselor's Office next to Room	2	EA	7	10+ years	
	Floor - Tile	Counselor's Office next to Room	180	SF	7	10+ years	
	Lighting - Pendent/Surface	Counselor's Office next to Room	2	EA	7	6-10 years	
	Power Distribution	Counselor's Office next to Room	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Counselor's Office next to Room	73	SF	7	10+ years	
	AC Unit	Engineer's office inside boiler rm	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	Engineer's office inside boiler rm	112	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Engineer's office inside boiler rm	1	ĒΑ	7	10+ years	
	Floor - Tile	Engineer's office inside boiler rm	112	SF	7	10+ years	
	Lighting - Pendent/Surface	Engineer's office inside boiler rm	2	ĒΑ	7	6-10 years	
	Power Distribution	Engineer's office inside boiler rm	6	EA	7	10+ years	
	Storage/ Closet	Engineer's office inside boiler rm	10	SF	7	10+ years	
	Walls - Concrete Block	Engineer's office inside boiler rm	550	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Main Office	322	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Main Office	2	EΑ	7	10+ years	
			_		•	,	



Catego	ory : Room		В	uilding	: Main		· • • • • • • • • • • • • • • • • • • •
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Floor - Tile	Main Office	322	SF	7	10+ years	
	Lighting - Pendent/Surface	Main Office	3	EA	7	6-10 years	
	Power Distribution	Main Office	6	EA	7	10+ years	
	Storage/ Closet	Main Office	15	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office	921	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Room 115D/110A	120	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 115D/110A	1	EA	7	10+ years	
	Floor - Tile	Room 115D/110A	120	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 115D/110A	1	EA	7	6-10 years	
	Power Distribution	Room 115D/110A	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 115D/110A	120	SF	7	10+ years	
	Ceiling - Plaster/Drywall	Room 115E/110B	68	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Room 115E/110B	1	EA	7	10+ years	
	Floor - Tile	Room 115E/110B	68	SF	7	10+ years	
	Lighting - Pendent/Surface	Room 115E/110B	1	EA	7	6-10 years	
	Power Distribution	Room 115E/110B	4	EA	7	10+ years	
	Walls - Plaster/Drywall	Room 115E/110B	68	SF	7	10+ years	
	•					,	
_Gymnas							
	Ceiling - Splined	1st Floor	2,365	SF	7	10+ years	
	Ceiling - Splined	1st Floor	20	SF	4	1-2 years	Missing tiles, engineer noted that the gym is closed for students until the issue of falling tiles is resolved
	Doors - Wood Doors inclu hw	1st Floor	3	EA	7	10+ years	3
	Floor - Tile	1st Floor	2,405	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	13	EA	7	6-10 years	
	Scoreboards	1st Floor	1	EΑ	7	6-10 years	
	Sound System	1st Floor	1	EA	7	6-10 years	
	Stage	1st Floor	557	SF	7	10+ years	
	Stage Curtain	1st Floor	2	ĒΑ	7	10+ years	
	Stage Lift	1st Floor	_ 1	ΕA	7	10+ years	
	Stage Lighting System	1st Floor	1	EΑ	7	6-10 years	
	Walls - Concrete Block	1st Floor	1,203	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	1,202	SF	7	10+ years	
			.,			, , , , , , , , , , , , , , , , , , , ,	
_MDF_ID)F						
	Doors - Wood Doors inclu hw	Across from 113	1	EA	7	10+ years	
	Finishes	Across from 113	95	SF	7	10+ years	
	Window AC Unit	Across from 113	1	ĒΑ	7	10+ years	Not previously assessed
Mechan	ical/ Service Rooms						
INICCHAL	Boiler Room	1st Floor	1,018	SF	7	10+ years	
	Janitor's Closet	1st Floor	42	SF	7	10+ years	
	Janiiloi 3 Oluset	15(1100)	42	J.	,	10+ years	



Catego	Category : Room		Building : Main					
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Mechanical/ Service Rooms	1st Floor	160	SF	7	10+ years		
	Mechanical/ Service Rooms	1st Floor	100	SF	7	10+ years		
	Storage Room	1st Floor	35	SF	7	10+ years		
	Crawl Space - Unfinished	Basement	8,150	SF	7	10+ years		
Restroor	n							
	Accessories	1st Floor Girl's Room, North end of Buildiing	268	SF	7	6-10 years		
	Ceiling - Lay-in	1st Floor Girl's Room, North end of Buildiing	268	SF	7	10+ years		
	Doors - Transom Window	1st Floor Girl's Room, North end of Buildiing	36	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st Floor Girl's Room, North end of Buildiing	268	SF	7	10+ years		
	Floor Drain	1st Floor Girl's Room, North end of Buildiing	1	EA	7	10+ years		
	Hand Dryer	1st Floor Girl's Room, North end of Buildiing	2	EA	7	6-10 years		
	Lavatory	1st Floor Girl's Room, North end of Buildiing	1	EA	7	10+ years		
	Lighting - Lay-in	1st Floor Girl's Room, North end of Buildiing	2	EA	6	6-10 years		
	Partitions	1st Floor Girl's Room, North end of Buildiing	6	EA	7	10+ years		
	Walls - Structural Glazed Tile	1st Floor Girl's Room, North end of Buildiing	415	SF	7	10+ years		
	Water Closet	1st Floor Girl's Room, North end of Buildiing	6	EA	7	10+ years		
	Accessories	1st flr Boy's South end of corridor	218	SF	7	6-10 years		
	Ceiling - Plaster/Drywall	1st flr Boy's South end of corridor	218	SF	7	10+ years		
	Doors - Transom Window	1st flr Boy's South end of corridor	32	SF	7	10+ years		
	Floor - Tile Ceramic/ Porcelain	1st flr Boy's South end of corridor	218	SF	7	10+ years		
	Floor Drain	1st flr Boy's South end of corridor	1	EA	7	10+ years		
	Hand Dryer	1st flr Boy's South end of corridor	2	EA	7	6-10 years		
	Lavatory	1st flr Boy's South end of corridor	1	EA	7	10+ years		
	Lighting - Pendent/Surface	1st flr Boy's South end of corridor	4	EA	6	6-10 years	Rank updated to match current observations	
	Partitions	1st flr Boy's South end of corridor	2	EA	7	10+ years		
	Urinals	1st flr Boy's South end of corridor	6	EA	7	10+ years		
	Walls - Plaster/Drywall	1st flr Boy's South end of corridor	150	SF	7	10+ years		
	Walls - Structural Glazed Tile	1st flr Boy's South end of corridor	600	SF	7	10+ years		
	Water Closet	1st flr Boy's South end of corridor	1	EA	7	10+ years		
	Water Closet	1st flr Boy's South end of corridor	1	EA	6	1-2 years	Doesn't work	
	Accessories	1st flr east of boiler rm	104	SF	7	6-10 years		

Campus Name: Wildwood Page: 10 of 33 Assessment Date: 07/15/2024



Catego	ry : Room		В	uilding	: Main		Building : Main								
						Recommend									
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments								
	Ceiling - Plaster/Drywall	1st flr east of boiler rm	104	SF	7	10+ years									
	Doors - Wood Doors inclu hw	1st flr east of boiler rm	1	EA	7	10+ years									
	Floor - Tile	1st flr east of boiler rm	104	SF	7	10+ years									
	Lavatory	1st flr east of boiler rm	1	EA	7	10+ years									
	Lighting - Pendent/Surface	1st flr east of boiler rm	1	EA	7	6-10 years									
	Walls - Plaster/Drywall	1st flr east of boiler rm	330	SF	7	10+ years									
	Water Closet	1st flr east of boiler rm	1	EΑ	7	10+ years									
	Accessories	1st flr inside engineer's office	30	SF	7	6-10 years									
	Ceiling - Plaster/Drywall	1st flr inside engineer's office	30	SF	7	10+ years									
	Doors - Wood Doors inclu hw	1st flr inside engineer's office	1	EA	7	10+ years									
	Floor - Tile	1st flr inside engineer's office	30	SF	4	0-1 year	Cracked/loose tiles								
	Lavatory	1st flr inside engineer's office	1	EA	7	6-10 years									
	Lighting - Pendent/Surface	1st flr inside engineer's office	1	EA	7	6-10 years									
	Walls - Concrete Block	1st flr inside engineer's office	219	SF	7	10+ years									
	Water Closet	1st flr inside engineer's office	1	EA	7	10+ years									
	Accessories	Boy's Room In the Gym's Lobby	190	SF	7	6-10 years									
	Ceiling - Plaster/Drywall	Boy's Room In the Gym's Lobby	190	SF	7	10+ years									
	Doors - Wood Doors inclu hw	Boy's Room In the Gym's Lobby	1	ĒΑ	7	10+ years									
	Floor - Tile Ceramic/ Porcelain	Boy's Room In the Gym's Lobby	190	SF	7	10+ years									
	Floor Drain	Boy's Room In the Gym's Lobby	1	ĒΑ	7	10+ years									
	Lavatory	Boy's Room In the Gym's Lobby	1	EA	7	10+ years									
	Lighting - Pendent/Surface	Boy's Room In the Gym's Lobby	3	EA	7	6-10 years									
	Partitions	Boy's Room In the Gym's Lobby	1	EΑ	7	10+ years									
	Urinals	Boy's Room In the Gym's Lobby	1	EΑ	7	10+ years									
	Walls - Plaster/Drywall	Boy's Room In the Gym's Lobby	74	SF	7	10+ years									
	Walls - Structural Glazed Tile	Boy's Room In the Gym's Lobby	221	SF	7	10+ years									
	Water Closet	Boy's Room In the Gym's Lobby	1	EA	7	10+ years									
	Accessories	In Room 110	33	SF	7	6-10 years									
	Ceiling - Plaster/Drywall	In Room 110	33	SF	7	10+ years									
	Doors - Wood Doors inclu hw	In Room 110	1	EA	7	10+ years									
	Floor - Tile	In Room 110	33	SF	7	10+ years									
	Lavatory	In Room 110	1	EA	7	10+ years									
	Lighting - Pendent/Surface	In Room 110	1	EA	7	6-10 years									
	Walls - Plaster/Drywall	In Room 110	121	SF	7	10+ years									
	Water Closet	In Room 110	121	EA	7	10+ years									
	Accessories	Next to 114	81	SF	7	6-10 years									
	Ceiling - Plaster/Drywall	Next to 114	81	SF	7	10+ years									
	Doors - Wood Doors inclu hw	Next to 114	1	EA	7	10+ years									
	Floor - Tile Ceramic/ Porcelain	Next to 114	81	SF	7	10+ years									
	Floor Drain	Next to 114	1	EA	7	-									
	Hand Dryer	Next to 114 Next to 114	1	EA	7	10+ years 6-10 years									
			1	EA EA											
	Lavatory Lighting - Pendent/Surface	Next to 114	1	EA EA	7 7	10+ years									
	•	Next to 114	•	SF	7	6-10 years									
	Walls - Plaster/Drywall	Next to 114	108	SF	1	10+ years									

Campus Name: Wildwood Page : 11 of 33 Assessment Date: 07/15/2024



Catego	ry : Room		Building : Main						
_				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Walls - Tile Ceramic/ Porcelain	Next to 114	252	SF	7	10+ years			
	Water Closet	Next to 114	1	EA	7	10+ years			
	Accessories	Unisex In the Gym	145	SF	7	6-10 years			
	Ceiling - Lay-in	Unisex In the Gym	145	SF	7	10+ years			
	Doors - Wood Doors inclu hw	Unisex In the Gym	1	EA	7	10+ years			
	Floor - Tile	Unisex In the Gym	145	SF	7	10+ years			
	Hand Dryer	Unisex In the Gym	1	EA	7	6-10 years			
	Lavatory	Unisex In the Gym	1	EA	7	10+ years			
	Lighting - Lay-in	Unisex In the Gym	3	EA	7	6-10 years			
	Walls - Plaster/Drywall	Unisex In the Gym	225	SF	7	10+ years			
	Water Closet	Unisex In the Gym	1	EA	7	10+ years			
	Accessories	in Room 114	81	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	in Room 114	81	SF	7	10+ years			
	Doors - Wood Doors inclu hw	in Room 114	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	in Room 114	81	SF	7	10+ years			
	Floor Drain	in Room 114	1	EA	7	10+ years			
	Hand Dryer	in Room 114	1	EA	7	6-10 years			
	Lavatory	in Room 114	1	EA	7	10+ years			
	Lighting - Pendent/Surface	in Room 114	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	in Room 114	108	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	in Room 114	252	SF	7	10+ years			
	Water Closet	in Room 114	1	EA	7	10+ years			

Category : Classroom **Building: Main**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classro	om #101 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	687	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	35	SF	4	1-2 years	Water damage
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	-
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	722	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	34	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,118	SF	7	10+ years	
Classro	om #102 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	722	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	722	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	

Campus Name: Wildwood Page : 12 of 33 Assessment Date: 07/15/2024



Catego	ry : Classroom		В	uilding	: Main		-
	.,		_	<u>.</u>		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Marker Board	1st Floor	34	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,118	SF	7	10+ years	
:lassroc	om #103 (Regular Classroom)						
ZIGOOTOC	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	722	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years	
	Floor - Tile	1st Floor	722	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	62	LF	7	•	
						6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,118	SF	7	10+ years	
lassroc	om #104 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	683	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	683	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	66	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,118	SF	7	10+ years	
lassroo	om #105 (Regular Classroom)						
nassioc	Casework	1st Floor	6	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	712	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	•	
				EA		10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1		7	10+ years	
	Floor - Tile	1st Floor	696	SF	7	10+ years	NAIiAil
	Floor - Tile	1st Floor	16	SF	4	1-2 years	Missing tiles
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	34	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	1,118	SF	7	10+ years	
lassroc	om #106 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	705	SF	6	10+ years	Rank changed to match current observations
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	obool valions
	Doors - Wood Doors inclu hw	1st Floor	10	EA	7	10+ years	
	Floor - Tile	1st Floor	715	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	12	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	

Campus Name: Wildwood Page: 13 of 33 Assessment Date: 07/15/2024



Catego	ory : Classroom		В	uilding	: Main		No NY Hiawatha AVENOE, Officago, IE 00040
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Walls - Plaster/Drywall	1st Floor	1,108	SF	7	10+ years	
Classroo	om #107 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	Recently waxed floors, limited access
	Ceiling - Plaster/Drywall	1st Floor	715	SF	7	10+ years	Recently waxed floors, limited access
	Doors - Side-lite	1st Floor	64	SF	7	10+ years	Recently waxed floors, limited access
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	Recently waxed floors, limited access
	Floor - Tile	1st Floor	715	SF	7	10+ years	Recently waxed floors, limited access
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	Recently waxed floors, limited access
	Marker Board	1st Floor	30	LF	7	6-10 years	Recently waxed floors, limited access
	Storage/ Closet	1st Floor	8	SF	7	10+ years	Recently waxed floors, limited access
	Walls - Plaster/Drywall	1st Floor	1,108	SF	7	10+ years	Recently waxed floors, limited access
_Classroo	om #108 (Regular Classroom)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	673	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	10	SF	5	1-2 years	Water damage
	Chalk Board	1st Floor	12	LF	4	2-5 years	Traiter damage
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	683	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	24	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,108	SF	7	10+ years	
_Classroo	om #109 (Kindergarten)						
	Casework	1st Floor	6	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	683	SF	7	10+ years	
	Chalk Board	1st Floor	12	LF	4	2-5 years	
	Doors - Transom Window	1st Floor	116	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	ĒΑ	7	10+ years	
	Floor - Tile	1st Floor	683	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	ĒΑ	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	8	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,080	SF	7	10+ years	
_Classroo	om #110 (Kindergarten)						
	Ceiling - Plaster/Drywall	1st Floor	718	SF	7	10+ years	
	Doors - Transom Window	1st Floor	16	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	718	SF	7	10+ years	



Catego	Category : Classroom		В	uilding	: Main		· • • • • • • • • • • • • • • • • • • •
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Pendent/Surface	1st Floor	14	EA	7	6-10 years	
	Marker Board	1st Floor	10	LF	7	6-10 years	
	Storage/ Closet	1st Floor	41	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,108	SF	7	10+ years	
Classroo	om #112 (Office)						
	Ceiling - Plaster/Drywall	1st Floor	455	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EΑ	7	10+ years	
	Floor - Tile	1st Floor	455	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	705	SF	7	10+ years	
Classro	om #113 (Faculty Lounge)						
	Ceiling - Plaster/Drywall	1st Floor	400	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	400	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	700	SF	7	10+ years	
	Work Sink	1st Floor	1	EΑ	7	10+ years	
Classro	om #114 (Pre School)						
Classiu	Casework	1st Floor	20	LF	7	10+ years	
	Casework Ceiling - Plaster/Drywall	1st Floor	2,016	SF	7 7		
	Doors - Wood Doors inclu hw	1st Floor	2,016	EA	7	10+ years 10+ years	
	Floor - Tile	1st Floor	2.016	SF	7		
			2,016			10+ years	
	Lighting - Pendent/Surface	1st Floor 1st Floor	9	EA LF	7 7	6-10 years	
	Marker Board		16			6-10 years	
	Walls - Plaster/Drywall	1st Floor	2,160	SF	7	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #116 (Band Room)						
	Ceiling - Plaster/Drywall	1st Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	5	0-1 year	Missing door knob
	Floor - Tile	1st Floor	750	SF	7	10+ years	
	Instrument Storage Casework	1st Floor	15	LF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	12	EA	7	6-10 years	
	Marker Board	1st Floor	16	LF	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor	380	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	20	SF	5	1-2 years	Water damage, bulging plaster
	Walls - Structural Glazed Tile	1st Floor	700	SF	7	10+ years	



Catego	ry : Interior	Building : Main					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Corridor							
	Ceiling - Plaster/Drywall	1st Floor	4,748	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	4	EA	7	10+ years	
	Doors - Wood Doors include hw	1st Floor	8	EA	7	10+ years	
	Drinking Fountains - Double Water Cooler	1st Floor	1	EA	7	6-10 years	
	Drinking Fountains - Double Water Cooler	1st Floor	3	EA	7	6-10 years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	415	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	4,313	SF	7	10+ years	
	Floor - Tile/Sheet	1st Floor	20	SF	4	1-2 years	Broken, cracking
	Lighting - Pendent/Surface	1st Floor	68	EA	7	6-10 years	
	Student Lockers - One Tier	1st Floor	38	EA	7	10+ years	
	Student Lockers - Two Tiers	1st Floor	242	EA	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	9,570	SF	7	10+ years	
	Walls - Structural Glazed Tile	1st Floor	3,658	SF	7	10+ years	



Category : Exterior Building : Addition

cgui	y . Exterior			unung	. Additi	Recommend	
oup	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
nce			444			Tio piaco in one	
ансс	Exterior Doors - Side lite	10	2	EA	6	10+ years	
	Exterior Doors - Store Front	10	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	10	3	EA	6	10+ years	
	Exterior Doors - Exterior FRP Door	10.5 chiller enclosure	2	EA	6	10+ years	
	Exterior Doors - Store Front	11	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	11	1	EA	6	10+ years	
	Entrance Control - Audio and Video	12	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	12	1	EA	6	10+ years	
	Entrance Control - Audio and Video	13	1	EA	6		
	Exterior Doors - Store Front	13	1	EA	6	10+ years	
	Exterior Doors - Store Front Exterior Doors - Transom Lite	13	2		_	10+ years	
			1	EΑ	6	10+ years	
	Power Door Operator and Controls	13	1	EA	7	10+ years	
ndati	on						
	Foundation - Concrete	Entire Building	35,068	LF	7	10+ years	
	Superstructure - Metal Deck/ Concrete	Entire Building	35,068	SF	7	10+ years	
	Topping	· ·					
ing_	E c i li le Mallada e l	F 6 B 7 F	40			0.40	
	Exterior Lighting - Wall Mounted	Entire Building	10	EA	7	6-10 years	
f Sys	tem						
,_	Access Ladder - Metal	1 main roof	1	EA	7	10+ years	
	Coping - Stone	1 main roof	410	LF	6	10+ years	
	Downspouts - Interior Downspouts	1 main roof	40	LF	6	10+ years	
	Parapet - 16" - 30" Height	1 main roof	410	LF	6	10+ years	
	Roof - Modified Bitumen	1 main roof	9,750	SF	6	6-10 years	
	Roof Hatch - Metal	1 main roof	1	EA	7	10+ years	
	Roof Structure - Steel / Metal Deck/	1 main roof	9.750	SF	7	10+ years	
	Concrete Topping	i mani roor	0,100	O.	•	101 youro	
	Coping - Metal	2 low roof	9	LF	6	10+ years	
	Coping - Stone	2 low roof	138	LF	6	10+ years	
	Downspouts - Interior Downspouts	2 low roof	30	LF	6	10+ years	
	Parapet - Parapet < 16" Height	2 low roof	256	LF	6	10+ years	
	Parapet - Parapet > 30"	2 low roof	40	LF	6	10+ years	
	Roof - Modified Bitumen	2 low roof	3,192	SF	6	6-10 years	No access
	Roof Structure - Steel / Metal Deck/	2 low roof	3,192	SF	7	10+ years	110 000000
	Concrete Topping	2 10W 1001	3,192	SI-	,	10+ years	
	Contracte Toppling						
ls							
	Canopy - Concrete/ Stucco	Entire Building	550	SF	6	10+ years	
		-				-	



Catego	ry : Exterior	В	00 N Hiawatha AVENUE, Chicago, IL 60646				
Galogo	. Laterie.			ananig	: Additio	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Cheek-Wall - Stone	Entire Building	1,800	SF	6	10+ years	
	Cornice - Cast Stone	Entire Building	410	LF	6	10+ years	
	Cornice - Metal Projecting	Entire Building	90	LF	6	10+ years	
	Exterior Walls - Brick	Entire Building	20,050	SF	6	10+ years	
Windows							
VVIIIOVVI	Lintels - Steel	Entire Building	396	LF	6	10+ years	
	Storefront Windows	Entire Building	200	SF	6	10+ years	
	Windows - Casement Aluminum Double-	Entire Building	3,240	SF	6	10+ years	
	pane	g	0,2 :0	.	· ·	.o. yeare	
Catego	ry : Electrical		В	uilding	: Additio	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
	Exit Signs - Corridors and Stairs	Entire Building	9	EA	6	6-10 years	
	Exit Signs - Lunchroom	Entire Building	5	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	1	EA	7	6-10 years	Library
	Emergency A/C Power - Corridors and Stairs	Entire Building	7,280	SF	6	10+ years	
	Emergency A/C Power - Lunchrooms	Entire Building	3,320	SF	6	10+ years	
	Emergency A/C Power - Students Toilets	Entire Building	1,890	SF	6	10+ years	
	Emergency Battery Packs - Corridors and Stairs	Entire Building	18	EA	6	6-10 years	
	Emergency Battery Packs - Lunchrooms	Entire Building	4	EA	6	6-10 years	
	Emergency Battery Packs - Students Toilets	Entire Building	6	EA	6	6-10 years	
	Security System - CCTV	Entire Building	35,068	SF	6	6-10 years	
	Security System - Intrusion Detection	Entire Building	35,068	SF	6	6-10 years	
Main Se	vice						
	Main Electrical Service - 1200 A 120/208/3PH	Electrical Room	1	EA	7	10+ years	Many outages has been noted by the engineer recently
	PA System	Entire Building	35,068	SF	6	6-10 years	PA system is located in the office
. -							
Power D	istribution	EL .: 18					
	Lighting and Power Panels - 100 A	Electrical Room	7	EΑ	7	10+ years	
	Lighting and Power Panels - Above 100 A	Electrical Room	2	EΑ	7	10+ years	Includes Elevator room
	Main Distribution Panels - 400 - 600 amp	Electrical Room	2	EΑ	7	10+ years	Mechanical room
	Main Distribution Panels - Less than 400 amp	Electrical Room	1	EA	7	10+ years	
Catego	ry : Fire Protection		В	uildina	: Additio	on	
	Item - Type	Location	Quantity	UOM	Rank		Comments
Jioup		20041011	Quantity	00111	Marin	. tooonimond	Coiiioitto

Campus Name: Wildwood Page: 18 of 33 Assessment Date: 07/15/2024



122-1 00110015						O N Hiawatha Avenue, Chicago, IL
					Replacement	
Fire Alarm						
Fire Alarm Panel	Entire Building	1	EA	6	10+ years	
Fire Alarm Strobe Lights	Entire Building	35,068	SF	6	10+ years	
Fire Alarm_System	Entire Building	35,068	SF	6	10+ years	
Fire Pump Controller	Entire Building	1	EA	6	10+ years	
Pump Room Assembly						
Fire Pump - 25-50 hp	Mechanical Room	1	EA	6	10+ years	
Jockey Pump	Mechanical Room	1	EA	6	10+ years	
ockey i unip	Weenanica Room		LA	Ü	10+ years	
Sprinkler System						
Sprinkler Heads	Entire Building	35,068	SF	7	10+ years	
Sprinkler Piping	Entire Building	35,068	SF	7	10+ years	
Wet Sprinkler System	Entire Building	35,068	SF	6	10+ years	
Category : Mechanical		В	uilding	: Additi	on	
					Recommend	
Group Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Conditioning						
Condensing Unit- Roof Mounted - Less than 5 tons	Roof	1	EA	7	6-10 years	
Chemical Pot Feeder	Site West	1	EA	5	6-10 years	
Chiller-Air Cooled-Scroll Type-Ground	Site West	1	EA	6	6-10 years	
Mounted - 50 - 100 tons	3.13 11 331	·		· ·	0 .0 ,00.0	
Glycol Feed	Site West	1	EA	6	10+ years	
Pipes - Chilled Water Pipe- Steel	Site West	100	LF	6	10+ years	
Pressure Fill System	Site West	1	EA	6	10+ years	
Air Handling Systems						
Fan Coil Unit- Celing Mounted - Electric	Electrical Room	1	EA	7	6-10 years	Serves MDF room
Air Handling Unit- Package Single Zone-	Roof	1	EΑ	6	10+ years	AHU 1
Outdoor Roof Mounted- Dual Temperature	11001	·	_, 、	Ŭ	ioi youlo	7.1.10
Coils - 6000-10000 cfm						
Air Intake	Roof	1	EA	6	10+ years	
VAV Box	Roof	10	EΑ	6	10+ years	Located inside the ceiling tile
· 				-	,	inaccessible
Air Handling Unit- Package Single Zone- Outdoor Roof Mounted- Dual Temperature Coils - 15001-20000 cfm	Roof	1	EA	6	10+ years	
Air Intake	Roof	1	EA	6	10+ years	
VAV Box	Roof	25	EA	6	10+ years	
VAV Box VAV Box	Roof	25 1	EA	5	6-10 years	
VAV DOX	NOOI	ı	EA	ວ	0-10 years	
Boiler Systems						
Name Oyumu						



Catego	ry : Mechanical		В	uilding	: Addition	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Boiler Auxiliary- Condensing Hot Water - 500 - 1000 HP	Boiler Room	2	EA	6	10+ years	
	Chemical Pot Feeder	Boiler Room	1	EA	5	6-10 years	
	Condensing- Hot Water Boiler - 500 - 1000 MBH	Boiler Room	2	EA	6	10+ years	
	Glycol Feed System	Boiler Room	1	EA	6	10+ years	
	Water Fill System	Boiler Room	1	EA	6	10+ years	
-leating	Devices						
	Unit Heater - Hot Water	1st Floor	3	EA	6	10+ years	
	Cabinet Heaters - With Hot Water Coil	Entire Building	7	EA	6	10+ years	
	Radiator Panels - Hot Water	Entire Building	10	EΑ	6	10+ years	In restrooms
	Fin Tube - Hot Water	Entire Building	42	LF	6	10+ years	
<u>Vlechani</u>	cal Plumbing						
	Hydronic Supply and Return - Copper	Entire Building	300	LF	7	10+ years	
	Hydronic Supply and Return - Steel	Entire Building	100	LF	7	10+ years	
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	6	10+ years	
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	6	10+ years	
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	6	10+ years	
	Dual Temperature Pump - Less than 10	Entire Building	1	EA	6	10+ years	
Tempera	ature Control						
•	DDC System	Entire Building	35,068	SF	6	10+ years	Johnson control systems being used
	Electric Thermostat	Entire Building	7	EA	7	10+ years	, ,
	Thermostats - DDC	Entire Building	31	EA	6	10+ years	
/entilatio	on						
	Exhaust Fans- Indoor - 500 - 1500 CFM	Entire Building	1	EA	6	6-10 years	
	Exhaust Fans- Indoor - Less than 500 CFM	Entire Building	3	EA	6	6-10 years	Boiler room
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Entire Building	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Entire Building	3	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Less than 500 CFM	Entire Building	1	EA	6	6-10 years	
	Type II Exhaust Hood- Warming Kitchen	Entire Building	1	EA	6	6-10 years	Ansul system not observed
Category : Plumbing			В	uilding	: Additio	on	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	· ·						
v.vull	Gas Heater - Less than 150000 BTU/HR	Boiler Room	2	EA	6	10+ years	

Campus Name: Wildwood Page : 20 of 33 Assessment Date: 07/15/2024



Catego	Category : Plumbing			Building : Addition					
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
Piping									
	Domestic Piping-Hot Water Return Lines	Entire Building	35,068	SF	7	10+ years			
	Domestic Piping-Hot Water Return Risers	Entire Building	35,068	SF	7	10+ years			
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	35,068	SF	7	10+ years			
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	35,068	SF	7	10+ years			
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	35,068	SF	7	10+ years			
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	35,068	SF	7	10+ years			
	Sanitary Piping	Entire Building	35,068	SF	7	10+ years			
	Storm Piping	Entire Building	35,068	SF	7	10+ years			
	Vent Piping	Entire Building	35,068	SF	7	10+ years			
Pumps									
•	Pumps - Domestic Booster Pump-Duplex	Entire Building	1	EA	6	10+ years			
	Pumps - Sump-Simplex	Entire Building	1	EA	6	10+ years	Inaccessible		

Category: Room **Building: Addition**

						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Adminis	rative Suites/Offices						
	Ceiling - Lay-in	334	304	SF	7	10+ years	
	Doors - Wood Doors inclu hw	334	1	EΑ	7	10+ years	
	Floor - Tile	334	304	SF	6	10+ years	
	Lighting - Lay-in	334	5	EΑ	7	6-10 years	
	Power Distribution	334	12	EΑ	7	10+ years	
	Walls - Plaster/Drywall	334	682	SF	6	10+ years	
	Ceiling - Lay-in	Counselor's Office 142	122	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Counselor's Office 142	1	EA	7	10+ years	
	Floor - Carpet	Counselor's Office 142	122	SF	6	6-10 years	
	Lighting - Lay-in	Counselor's Office 142	2	EA	7	6-10 years	
	Power Distribution	Counselor's Office 142	4	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Counselor's Office 142	457	SF	7	10+ years	
	Ceiling - Lay-in	Kitchen Manager Office - 130	110	SF	7	10+ years	
	Doors - Steel Doors incl hw	Kitchen Manager Office - 130	1	EA	7	10+ years	
	Floor - Tile	Kitchen Manager Office - 130	110	SF	7	10+ years	
	Lighting - Lay-in	Kitchen Manager Office - 130	2	EA	7	6-10 years	
	Power Distribution	Kitchen Manager Office - 130	2	EΑ	7	10+ years	
	Walls - Plaster/Drywall	Kitchen Manager Office - 130	451	SF	7	10+ years	
	Ceiling - Lay-in	Main Office 140	143	SF	7	10+ years	

Page : 21 of 33 Campus Name: Wildwood Assessment Date: 07/15/2024



Catego	ry : Room		В	uilding	: Additi	on	
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Doors - Wood Doors inclu hw	Main Office 140	1	EA	7	10+ years	
	Floor - Carpet	Main Office 140	143	SF	6	6-10 years	
	Lighting - Lay-in	Main Office 140	2	EA	7	6-10 years	
	Power Distribution	Main Office 140	2	EA	7	10+ years	
	Storage/ Closet	Main Office 140	10	SF	7	10+ years	
	Walls - Plaster/Drywall	Main Office 140	481	SF	7	10+ years	
	Ceiling - Lay-in	Principal's Office 141	185	SF	7	10+ years	
	Doors - Wood Doors inclu hw	Principal's Office 141	1	EA	7	10+ years	
	Floor - Carpet	Principal's Office 141	185	SF	6	6-10 years	
	Lighting - Lay-in	Principal's Office 141	2	EA	7	6-10 years	
	Power Distribution	Principal's Office 141	6	EA	7	10+ years	
	Storage/ Closet	Principal's Office 141	55	SF	7	10+ years	
	Walls - Plaster/Drywall	Principal's Office 141	546	SF	7	10+ years	
Kitchen							
	Ceiling - Lay-in	1st Floor	1,531	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	, 6	EA	7	10+ years	
	Floor - Tile Quarry	1st Floor	1,531	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	23	EΑ	7	6-10 years	
	Serving Line	1st Floor	45	LF	7	10+ years	
	Storage/ Closet	1st Floor	339	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,620	SF	7	10+ years	
Library							
	Ceiling - Lay-in	126	1,377	SF	7	10+ years	
	Doors - Wood Doors inclu hw	126	4	ĒΑ	7	10+ years	
	Floor - Carpet	126	1,377	SF	7	6-10 years	
	Lighting - Lay-in	126	20	ĒΑ	7	6-10 years	
	Lighting - Lay-in	126	1	EA	6	6-10 years	Relamp
	Walls - Plaster/Drywall	126	1,306	SF	7	10+ years	
_Lunch &	Multipurpose Room						
	Ceiling - Lay-in	1st Floor	2,242	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	928	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	7	EA	7	10+ years	
	Floor - Tile	1st Floor	3,170	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	60	EA	7	6-10 years	
	Serving Line	1st Floor	45	LF	7	10+ years	
	Storage/ Closet	1st Floor	358	SF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	1,977	SF	7	10+ years	
_MDF_ID	F						
	Doors - Steel Doors incl hw	1st Floor 137	1	EA	7	10+ years	
	Doord Steel Boord Morriw	13(1100) 107	'	L/ \	,	101 yours	

Campus Name: Wildwood Page : 22 of 33 Assessment Date: 07/15/2024



Catego	Category : Room		Building : Addition						
						Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Finishes	1st Floor 137	115	SF	7	10+ years			
	Other Cooling Unit	1st Floor 137	1	EA	7	6-10 years			
_Mechani	cal/ Service Rooms								
	Janitor's Closet	1st Floor	60	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	70	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	110	SF	7	10+ years			
	Mechanical/ Service Rooms	1st Floor	915	SF	7	10+ years			
	Janitor's Closet	2nd Floor	60	SF	7	10+ years			
	Janitor's Closet	3rd Floor	60	SF	7	10+ years			
	Mechanical/ Service Rooms	3rd Floor	170	SF	7	10+ years			
	Storage Room	3rd Floor	82	SF	7	10+ years			
Restroor	n								
	Accessories	1st Floor	118	SF	7	6-10 years			
	Accessories	1st Floor	2	SF	5	1-2 years	Missing toilet paper dispenser cover		
	Ceiling - Plaster/Drywall	1st Floor	254	SF	7	10+ years	g tonet paper dispenses sever		
	Floor - Tile Ceramic/ Porcelain	1st Floor	254	SF	7	10+ years			
	Floor Drain	1st Floor	1	EA	7	10+ years			
	Hand Dryer	1st Floor	3	EA	7	6-10 years			
	Lavatory	1st Floor	3	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years			
	Partitions	1st Floor	4	EA	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	237	SF	7	10+ years			
	Walls - Flaster/Drywaii Walls - Tile Ceramic/ Porcelain	1st Floor	450	SF	7	,			
			450	EA	7	10+ years			
	Water Closet	1st Floor	· · · · · · · · · · · · · · · · · · ·	SF		10+ years			
	Accessories	1st Floor	100		7	6-10 years			
	Ceiling - Plaster/Drywall	1st Floor	254	SF	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor	254	SF	7	10+ years			
	Floor Drain	1st Floor	1	EA	7	10+ years			
	Hand Dryer	1st Floor	3	EA	7	6-10 years			
	Lavatory	1st Floor	3	EA	7	10+ years			
	Lighting - Pendent/Surface	1st Floor	4	EA	7	6-10 years			
	Partitions	1st Floor	2	EA	7	10+ years			
	Urinals	1st Floor	2	EA	7	10+ years			
	Walls - Plaster/Drywall	1st Floor	237	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	1st Floor	450	SF	7	10+ years			
	Water Closet	1st Floor	2	EA	7	10+ years			
	Accessories	1st Floor 133	20	SF	7	6-10 years			
	Ceiling - Lay-in	1st Floor 133	42	SF	7	10+ years			
	Doors - Wood Doors inclu hw	1st Floor 133	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	1st Floor 133	42	SF	7	10+ years			
	Hand Dryer	1st Floor 133	1	ĒΑ	7	6-10 years			
	Lavatory	1st Floor 133	1	EA	7	10+ years			

Campus Name: Wildwood Page : 23 of 33 Assessment Date: 07/15/2024



Catego	Category : Room		В	uilding	: Additi	on	
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Lighting - Lay-in	1st Floor 133	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor 133	87	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor 133	180	SF	7	10+ years	
	Water Closet	1st Floor 133	1	EA	7	10+ years	
	Accessories	1st Floor 135	40	SF	7	6-10 years	
	Ceiling - Lay-in	1st Floor 135	39	SF	7	10+ years	
	Ceiling - Lay-in	1st Floor 135	3	SF	4	1-2 years	Grid falling
	Doors - Wood Doors inclu hw	1st Floor 135	1	EA	7	10+ years	•
	Floor - Tile Ceramic/ Porcelain	1st Floor 135	42	SF	7	10+ years	
	Hand Dryer	1st Floor 135	1	EΑ	7	6-10 years	
	Lavatory	1st Floor 135	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor 135	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor 135	87	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor 135	180	SF	6	10+ years	
	Water Closet	1st Floor 135	1	EA	7	10+ years	
	Accessories	235	60	SF	7	10+ years	
	Ceiling - Lay-in	235	42	SF	7	10+ years	
	Doors - Wood Doors inclu hw	235	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	235	42	SF	7	10+ years	
	Floor Drain	235	1	EA	7	10+ years	
	Hand Dryer	235	1	EA	7	6-10 years	
	Lavatory	235	' 1	EA	7	10+ years	
	Lighting - Lay-in	235	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	235	71	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	235	180	SF	7	-	
	Water Closet	235	100	EA	7	10+ years	
	Accessories	200 2nd Floor	120	SF	7	10+ years 6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor 2nd Floor	254	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor 2nd Floor	254	SF	7	,	
	Floor Drain	2nd Floor 2nd Floor		Sr EA		10+ years	
	Hand Dryer	2nd Floor 2nd Floor	1	EA	7	10+ years	
			3	EA	7 7	6-10 years	
	Lavatory	2nd Floor	3			10+ years	Dalama
	Lighting - Lay-in	2nd Floor	1	EΑ	6	6-10 years	Relamp
	Lighting - Pendent/Surface	2nd Floor	4	EΑ	7	6-10 years	
	Partitions	2nd Floor	4	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	237	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	2nd Floor	450	SF	7	10+ years	
	Water Closet	2nd Floor	4	EA	7	10+ years	
	Accessories	2nd Floor	100	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	254	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor	254	SF	7	10+ years	
	Floor Drain	2nd Floor	1	EA	7	10+ years	
	Hand Dryer	2nd Floor	3	EA	7	6-10 years	
	Lavatory	2nd Floor	3	EA	7	10+ years	



Category : Room			В	Building : Addition					
				_		Recommend			
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments		
	Lighting - Pendent/Surface	2nd Floor	4	EA	7	6-10 years			
	Partitions	2nd Floor	2	EA	7	10+ years			
	Urinals	2nd Floor	2	EA	7	10+ years			
	Walls - Plaster/Drywall	2nd Floor	237	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	2nd Floor	450	SF	7	10+ years			
	Water Closet	2nd Floor	2	EA	7	10+ years			
	Accessories	335	40	SF	7	10+ years			
	Ceiling - Lay-in	335	42	SF	7	10+ years			
	Doors - Wood Doors inclu hw	335	1	EA	7	10+ years			
	Floor - Tile Ceramic/ Porcelain	335	42	SF	7	10+ years			
	Floor Drain	335	1	EA	7	10+ years			
	Hand Dryer	335	1	EΑ	7	6-10 years			
	Lavatory	335	1	EA	7	10+ years			
	Lighting - Lay-in	335	1	EA	7	6-10 years			
	Walls - Plaster/Drywall	335	71	SF	7	10+ years			
	Walls - Tile Ceramic/ Porcelain	335	180	SF	7	10+ years			
	Water Closet	335	1	EA	7	10+ years			
	Accessories	3rd Floor	120	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	254	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	254	SF	7	10+ years			
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Hand Dryer	3rd Floor	3	EΑ	7	6-10 years			
	Lavatory	3rd Floor	3	EA	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	10+ years			
	Partitions	3rd Floor	4	EA	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	237	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	3rd Floor	450	SF	7	10+ years			
	Water Closet	3rd Floor	4	EA	7	10+ years			
	Accessories	3rd Floor	100	SF	7	6-10 years			
	Ceiling - Plaster/Drywall	3rd Floor	254	SF	6	10+ years			
	Floor - Tile Ceramic/ Porcelain	3rd Floor	254	SF	7	10+ years			
	Floor Drain	3rd Floor	1	EA	7	10+ years			
	Hand Dryer	3rd Floor	3	EA	7	6-10 years			
	Lavatory	3rd Floor	3	EA	7	10+ years			
	Lighting - Pendent/Surface	3rd Floor	4	EA	7	6-10 years			
	Partitions	3rd Floor	2	EA	7	10+ years			
	Urinals	3rd Floor	2	EA	7	10+ years			
	Walls - Plaster/Drywall	3rd Floor	237	SF	6	10+ years			
	Walls - Tile Ceramic/ Porcelain	3rd Floor	450	SF	7	10+ years			
	Water Closet	3rd Floor	2	EA	7	10+ years			



Category : Classroom			В	Building : Addition				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
Classroo	m #226 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	756	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	756	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	980	SF	6	10+ years		
Classroo	m #227 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	750	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	750	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	980	SF	6	10+ years		
	·					,		
Classroo	m #228 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	710	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	710	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	947	SF	6	10+ years		
Classroo	m #229 (Regular Classroom)							
	Ceiling - Lay-in	2nd Floor	750	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	2nd Floor	750	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	7	10+ years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	980	SF	6	10+ years		
Classroo	m #230 (Computer Lab)							
	Ceiling - Lay-in	2nd Floor	1,043	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	2	EA	7	10+ years		
	Floor - Tile	2nd Floor	1,043	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	21	EA	7	10+ years		
	Marker Board	2nd Floor	20	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	1,125	SF	6	10+ years		
	Wireless System	2nd Floor	1,123	EA	7	10+ years		
	•		•	<i>_,</i> ,	•	,		
Classroo	m #231 (Regular Classroom)							



Category : Classroom				Building : Addition				
						Recommend		
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments	
	Ceiling - Lay-in	2nd Floor	750	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	750	SF	6	10+ years		
	Lighting - Lay-in	2nd Floor	12	EA	6	6-10 years		
	Marker Board	2nd Floor	8	LF	7	6-10 years		
	Walls - Plaster/Drywall	2nd Floor	980	SF	6	10+ years		
Classroo	om #232 (Art Room)							
	Casework	2nd Floor	20	LF	7	10+ years		
	Ceiling - Lay-in	2nd Floor	900	SF	7	10+ years		
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years		
	Floor - Tile	2nd Floor	900	SF	6	10+ years		
	Kiln	2nd Floor	1	EA	7	10+ years		
	Lighting - Lay-in	2nd Floor	18	EA	6	6-10 years		
	Marker Board	2nd Floor	24	LF	7	6-10 years		
	Storage/ Closet	2nd Floor	160	SF	7	10+ years		
		2nd Floor		SF				
	Walls - Plaster/Drywall Work Sink		1,140 2	Sr EA	6 7	10+ years		
	Work Sink	2nd Floor	2	EA	/	10+ years		
_Classroo	om #326 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	734	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	734	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	966	SF	6	10+ years		
_Classroo	om #327 (Regular Classroom)							
	Ceiling - Lay-in	3rd Floor	750	SF	6	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	ĒΑ	7	10+ years		
	Floor - Tile	3rd Floor	750	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	12	ĒΑ	7	6-10 years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years		
01	(1000 (Danishan Olasana)							
_Classroo	om #328 (Regular Classroom)	0.151						
	Ceiling - Lay-in	3rd Floor	588	SF	7	10+ years		
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years		
	Floor - Tile	3rd Floor	588	SF	6	10+ years		
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years		
	Marker Board	3rd Floor	24	LF	7	6-10 years		
	Walls - Plaster/Drywall	3rd Floor	851	SF	6	10+ years		

Campus Name: Wildwood Page : 27 of 33 Assessment Date: 07/15/2024



Catego	ry : Classroom		В	uilding	: Additi	on	<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroc	om #329 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	750	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years	
Classroo	om #330 (Regular Classroom)						
Oldooroc	Ceiling - Lay-in	3rd Floor	745	SF	7	10+ years	
	Ceiling - Lay-in	3rd Floor	10	SF	5	1-2 years	Water damage
	Doors - Wood Doors inclu hw	3rd Floor	10	EA	7	10+ years	water damage
	Floor - Tile	3rd Floor	755	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	•	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
			980	SF	6	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	960	SF	6	10+ years	
Classroc	om #331 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	750	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	750	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	24	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	980	SF	6	10+ years	
Classroo	om #332 (Regular Classroom)						
	Ceiling - Lay-in	3rd Floor	775	SF	7	10+ years	
	Doors - Wood Doors inclu hw	3rd Floor	1	EA	7	10+ years	
	Floor - Tile	3rd Floor	775	SF	6	10+ years	
	Lighting - Lay-in	3rd Floor	12	EA	7	6-10 years	
	Marker Board	3rd Floor	10	LF	7	6-10 years	
	Walls - Plaster/Drywall	3rd Floor	994	SF	6	10+ years	
Catama			В	به منالماند،	. A al al:4:		
Catego	ry : Interior		Б	ullaing	: Additi	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
<u>Corridor</u>							
	Ceiling - Lay-in	128E Kitchen Corridor	170	SF	7	10+ years	
	Doors - Steel Doors incl hw	128E Kitchen Corridor	1	EA	7	10+ years	
	Floor - Tile Quarry	128E Kitchen Corridor	170	SF	7	10+ years	
	Lighting - Lay-in	128E Kitchen Corridor	3	ĒΑ	7	10+ years	
	Student Lockers - One Tier	128E Kitchen Corridor	11	EA	7	10+ years	
	Walls - Plaster/Drywall	128E Kitchen Corridor	300	SF	7	10+ years	
	,					,	

Campus Name: Wildwood Page : 28 of 33 Assessment Date: 07/15/2024



Catego	ry : Interior		В	uilding	: Additi	on	<u> </u>
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Lay-in	1st Floor	1,701	SF	7	10+ years	
	Doors - Steel Doors incl hw	1st Floor	6	EA	7	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	3	EA	7	6-10 years	
	Floor - Tile/Sheet	1st Floor	1,701	SF	7	10+ years	
	Lighting - Lay-in	1st Floor	12	EA	7	10+ years	
	Stairs - Concrete Stairs	1st Floor	8	LF	7	10+ years	
	Walls - Plaster/Drywall	1st Floor	3,029	SF	7	10+ years	
	Ceiling - Lay-in	2nd Floor	1,360	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	4	EA	7	10+ years	
	Drinking Fountains - Single Fountain	2nd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	2nd Floor	1,360	SF	7	10+ years	
	Lighting - Lay-in	2nd Floor	14	EA	7	10+ years	
	Student Lockers - One Tier	2nd Floor	12	EΑ	7	10+ years	
	Student Lockers - Two Tiers	2nd Floor	86	EA	7	10+ years	
	Walls - Plaster/Drywall	2nd Floor	2,682	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	1,345	SF	6	10+ years	
	Ceiling - Lay-in	3rd Floor	['] 15	SF	5	1-2 years	Water stains
	Doors - Steel Doors incl hw	3rd Floor	4	ĒΑ	7	10+ years	
	Drinking Fountains - Single Fountain	3rd Floor	3	EA	7	10+ years	
	Floor - Tile/Sheet	3rd Floor	1,360	SF	7	10+ years	
	Lighting - Lay-in	3rd Floor	14	EA	6	6-10 years	
	Student Lockers - One Tier	3rd Floor	12	EA	7	10+ years	
	Student Lockers - Two Tiers	3rd Floor	86	EΑ	7	10+ years	
	Walls - Plaster/Drywall	3rd Floor	2,682	SF	6	10+ years	
	Wallo T lablel/DTyWall	014 1 1001	2,002	O.	Ū	101 youro	
Safety							
Carcity	Security Cameras	Entire Building	2	EA	7	6-10 years	
	Security Cameras	Entire Building	2	EΑ	7	6-10 years	
	Security Cameras	Entire Building	4	EA	7	6-10 years	
	Coounty Camoras	Entire Ballating	•		•	o ro youro	
Stairs							
	Ceiling - Lay-in	Stair 1	680	SF	7	10+ years	
	Ceiling - Lay-in	Stair 1	20	SF	5	1-2 years	Water staining
	Floor - Tile	Stair 1	576	SF	6	10+ years	Trailer etag
	Handrails	Stair 1	104	LF	7	10+ years	
	Lighting - Lay-in	Stair 1	6	EA	7	6-10 years	
	Lighting - Pendent/Surface	Stair 1	4	EA	7	10+ years	
	Stairs - Rubber	Stair 1	288	LF	6	10+ years	
	Walls - Concrete Block	Stair 1	2,520	SF	7	10+ years	
	Ceiling - Lay-in	Stair 2	700	SF	7	10+ years	
	Floor - Tile	Stair 2	576	SF	6	10+ years	
	Handrails	Stair 2	104	LF	7	10+ years	
	Lighting - Lay-in	Stair 2	6	EA	7	6-10 years	
	Lighting - Lay-in Lighting - Pendent/Surface	Stair 2	4	EA	7	10+ years	
	Lighting - I endemyodiface	Ciaii Z	4	LA	,	10+ years	

Campus Name: Wildwood Page : 29 of 33 Assessment Date: 07/15/2024



Catego	tegory : Interior Building : Addition						
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	Stairs - Rubber Walls - Concrete Block	Stair 2 Stair 2	288 2,520	LF SF	6 7	10+ years 10+ years	
_Vertical	Conveyance						
	Elevator - Hydraulic Elevator	West	1	EA	6	10+ years	

Campus Name: Wildwood Page : 30 of 33 Assessment Date: 07/15/2024



Category : Site Building : Site

	y . Oilc			unung			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
thletic							
	Surface - Asphalt	West	17,600	SF	6	6-10 years	
	Surface - Asphalt	West	400	SF	4	0-1 year	Large crack
	Surface - Natural	West	54,000	SF	6	10+ years	
Civil/Drai	nage						
	Civil/ Drainage - Catch Basin	Entire Site	4	EA	7	10+ years	
	Civil/ Drainage - Site Manhole	Entire Site	8	EA	7	10+ years	
encing							
Ü	Fencing - Chain Link	Parking Lot- South	48	LF	7	10+ years	Transformer enclosure
	Fencing - Chain Link	Parking Lot- South	168	LF	7	10+ years	
	Fencing - Chain Link	Parking Lot- South	540	LF	6	10+ years	
	Fencing - Chain Link	Parking Lot- South	14	LF	6	6-10 years	
	Fencing - New Standard Ornamental	Parking Lot- South	210	LF	6	10+ years	
Landscar	oe .						
	Benches	Entire Site	12	EA	7	10+ years	
	Landscape - Grass	Entire Site	14,076	SF	6	10+ years	
	Landscape - Hardscape- Concrete	Entire Site	7,500	SF	7	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	100	SF	6	10+ years	
	Landscape - Hardscape- Pavers	Entire Site	100	SF	6	10+ years	
	Parkway trees	Entire Site	9	EA	6	10+ years	
	Parkway trees	Entire Site	6	EA	6	0-1 year	Interior trees-Trees growing onto
							roofs clogging gutters and downspouts
	Planting Beds/ Area	Entire Site	4,006	SF	7	10+ years	downspodis
	Play Area - Hardscape- Asphalt	Entire Site	8,369	SF	6	10+ years	
	Retaining Wall - Concrete	Entire Site	430	SF	7	10+ years	
	Trash Receptacles	Entire Site	1	EA	6	10+ years	
Parking L	ot						
	Concrete Curbs	South	702	LF	6	10+ years	
	Interior Plantings	South	300	LF	6	6-10 years	
	Lighting - Pole Mounted	South	2	ĒΑ	6	10+ years	
	Pavers	South	7,420	SF	6	10+ years	
	Surface - Asphalt	South	9,357	SF	6	6-10 years	
	Trash Compactor	South	1	EA	6	10+ years	
	Trash Enclosure - Masonry	South	975	SF	6	10+ years	
				<u> </u>			



Category : Site			Building : Site					
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments	
Sidewall	(S							
	Sidewalks - Internal Walks	Entire Site	229	LF	6	10+ years		
	Sidewalks - Internal Walks	Entire Site	15	LF	5	0-1 year	Broken sidewalk, holes	
	Sidewalks - Perimeter Sidewalks	Entire Site	6,771	SF	6	10+ years		
Signage								
	Flag Pole - Flag Pole	East	1	EA	6	10+ years		
	Monument - Building Mounted Cut Letter Sign	East	1	EA	6	10+ years		

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("ŚF").

Campus Name: Wildwood Page: 32 of 33 Assessment Date: 07/15/2024

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.



Classroom Summary

Classroom Summary Floor Plan Glazed Operable									
			Room	Room	Area	Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	,	•	'	1		•			
Band Room	Regular Classroom	1st Floor	116	Gym offices	750	64	32		
Faculty Lounge	Science	1st Floor	113	113	400	175	75	N	N
Kindergarten	Kindergarten	1st Floor	110	110	718	168	84	N	N
Kindergarten	Regular Classroom	1st Floor	109	109	683	108	54	N	N
Office	Other Instructional Use	1st Floor	112	112	455	108	54	N	N
Pre School	Other Instructional Use	1st Floor	114	114	2,016	120	60		
Regular Classroom	Regular Classroom	1st Floor	101	101	722	175	75	N	N
Regular Classroom	Regular Classroom	1st Floor	102	102	722	175	75	N	N
Regular Classroom	Regular Classroom	1st Floor	103	103	722	175	75	N	N
Regular Classroom	Regular Classroom	1st Floor	104	104	683	175	75	N	N
Regular Classroom	Regular Classroom	1st Floor	105	105	712	175	75	N	N
Regular Classroom	Regular Classroom	1st Floor	106	106	715	108	54	N	N
Regular Classroom	Regular Classroom	1st Floor	107	107	715	108	54	N	N
Regular Classroom	Regular Classroom	1st Floor	108	108	683	108	54	N	N
Building : Addition									
Art Room	Art Room	2nd Floor	232	232	900	180	27	N	N
Computer Lab	Regular Classroom	2nd Floor	230	230	1,043	180	27	N	N
Regular Classroom	Regular Classroom	2nd Floor	226	226	756	120	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	227	227	750	120	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	228	228	710	120	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	229	229	750	120	18	N	N
Regular Classroom	Regular Classroom	2nd Floor	231	231	750	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	326	326	734	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	327	327	750	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	328	328	588	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	329	329	750	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	330	330	755	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	331	331	750	120	18	N	N
Regular Classroom	Regular Classroom	3rd Floor	332	332	775	120	18	N	N