

Facility Assessment Report

This report contains the detailed findings of the facility condition assessment completed on the date noted in the document footer. Assessors rate each facility item by visual observation only; they do not test the operation of equipment or perform destructive testing of walls, ceilings, or floors. Each facility item is ranked on a 7-point scale: a rank 7 means the item is new or in like-new condition and no work is required while rank 1 means the item has failed and has led to an immediate life safety condition¹. The remaining ranks generally mean that the item requires regular maintenance (rank 5 or 6) or full replacement (rank 2, 3 or 4). To enhance reporting and capital planning analysis, each assessed item must also be assigned a recommended replacement range (used to specify the time span, in years, before replacement is recommended). Definitions for Quantity and Unit of Measure (UOM) can be found at the end of this report.

For additional detail and definition on rank values as they relate to each assessed item or the recommended replacement range, please visit the "CPS Guide to Biennial Facility Assessments" found on the Facilities Standards webpage under CPS Policies and Guidelines at http://www.cps.edu/facilityassessment.

Campus Summary			
BuildingName	Year Constructed	Number of Floors	Building Area (Sq Ft)
Main	1920	2	30,193
Campus Total			30,193

Catego	ry : Exterior	В	uilding	: Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Entrance							
	Entrance Control - Audio and Video	1 - main entrance - Southwest	1	EA	7	10+ years	
	Exterior Doors - Exterior FRP Door	1 - main entrance - Southwest	4	EA	7	10+ years	
	Exterior Doors - Transom Lite	1 - main entrance - Southwest	4	EA	7	10+ years	
	Exterior Stairs - Concrete	1 - main entrance - Southwest	15	LF	5	6-10 years	
	Exterior Stairs - Stone	1 - main entrance - Southwest	12	LF	7	10+ years	
	Exterior Doors - Exterior Steel Door	2 - Northwest	3	EA	7	10+ years	
	Exterior Stairs - Concrete	2 - Northwest	30	LF	5	10+ years	
	Exterior Stairs - Stone	2 - Northwest	9	LF	7	10+ years	
	Entrance Control - Audio and Video	3 - North	1	EA	7	10+ years	
	Exterior Doors - Exterior Steel Door	3 - North	2	EA	6	10+ years	Rust on bottom of door
	Exterior Stairs - Concrete	3 - North	12	LF	7	10+ years	
	Exterior Stairs - Stone	3 - North	6	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	3 - North	8	LF	7	10+ years	
	Ramps - Concrete	3 - North	17	LF	7	10+ years	
	Stair Handrail - Steel_Stair Handrail	3 - North	25	LF	7	10+ years	
	Entrance Control - Audio and Video	4 - Southeast	1	EA	7	6-10 years	
	Exterior Doors - Exterior Steel Door	4 - Southeast	2	EA	6	10+ years	
	Exterior Doors - Transom Lite	4 - Southeast	2	EA	7	10+ years	Repaired
	Exterior Stairs - Concrete	4 - Southeast	6	LF	7	10+ years	
	Ramp Handrail - Steel_Ramp Handrail	4 - Southeast	30	LF	7	10+ years	Repaired
	Ramps - Concrete	4 - Southeast	17	LF	5	10+ years	Repaired
	Stair Handrail - Steel_Stair Handrail	4 - Southeast	8	LF	7	10+ years	Repaired
	Exterior Doors - Exterior Wood Door	5 - Southeast	1	EA	4	0-1 year	Rotting door and transom
	Exterior Doors - Transom Lite	5 - Southeast	1	EA	4	0-1 year	Rotten transom trimming



Catego	ry : Exterior		В	uilding	: Main		
				J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
•	Exterior Doors - Exterior Steel Door	6 - East	1	EA	7	10+ years	Repaired
	Exterior Doors - Transom Lite	6 - East	1	EA	7	10+ years	Repaired
	Exterior Stairs - Concrete	6 - East	6	LF	7	10+ years	Repaired
			-		-	, e , j e e	
oundati	on						
	Foundation - Concrete	Entire Building	1	LF	7	10+ years	Repaired
	Foundation - Concrete	Entire Building	695	LF	7	10+ years	
	Superstructure - Concrete	Entire Building	30,188	SF	7	10+ years	
	Superstructure - Concrete	Entire Building	5	SF	6	1-2 years	Crack at interior wall and floor
			· ·	0.	Ū)	
ahtina							
0 0	Exterior Lighting - Parapet or Roof Mounted	Entire Building	6	EA	5	2-5 years	
	Exterior Lighting - Wall Mounted	Entire Building	1	EA	7	10+ years	Repaired
	Exterior Lighting - Wall Mounted	Entire Building	9	EA	6	6-10 years	·
oof Sys		4		F A	<i>г</i>	2.5.4.6.6.70	
	Access Ladder - Metal	1	2	EA	5	2-5 years	
	Chimney - Brick Chimney- Concrete/ Mortar	1	24	LF	6	10+ years	
	Liner				_		
	Chimney - Brick Chimney- Concrete/ Mortar	1	15	LF	5	0-1 year	Crack's through the chimmey
	Liner		500	. –	0	10	
	Coping - Metal	1	533	LF	6	10+ years	
	Downspouts - Interior Downspouts	1	75	LF	6	10+ years	
	Roof - Modified Bitumen	1	12,481	SF	7	10+ years	New roof
	Roof Hatch - Metal	1	2	EA	7	10+ years	Repaired
	Roof Structure - Concrete	1	12,481	SF	7	10+ years	
	Coping - Metal	2	50	LF	6	10+ years	
	Downspouts - Interior Downspouts	2	12	LF	6	10+ years	
	Roof - Modified Bitumen	2	584	SF	7	10+ years	New roof
	Roof Structure - Concrete	2	584	SF	7	10+ years	
	Access Ladder - Metal	3	1	EA	7	10+ years	
	Coping - Metal	3	147	LF	7	10+ years	
	Downspouts - Interior Downspouts	3	20	LF	6	10+ years	
	Roof - Modified Bitumen	3	2,230	SF	7	10+ years	New roof
	Roof Structure - Concrete	3	2,230	SF	7	10+ years	
	Access Ladder - Metal	4	1	EA	7	10+ years	
	Coping - Metal	4	153	LF	7	10+ years	
	Downspouts - Interior Downspouts	4	12	LF	7	10+ years	
	Roof - Modified Bitumen	4	2,417	SF	7	10+ years	New roof
	Roof Structure - Concrete	4	2,417	SF	7	10+ years	
Valls	Canopy - Concrete/ Stucco	Entire Building	550	SF	6	10+ 1/22/2	
	Canopy - Concrete/ Stucco		550	Sr	Ö	10+ years	



Catego	ry : Exterior		В	uilding	: Main		
_				_		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Canopy - Concrete/ Stucco	Entire Building	5	SF	6	10+ years	
	Cheek-Wall - Concrete	Entire Building	32	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	300	SF	7	10+ years	Repaired
	Exterior Walls - Brick	Entire Building	40	SF	7	10+ years	
	Exterior Walls - Brick	Entire Building	8,525	SF	6	10+ years	
	Exterior Walls - Brick	Entire Building	50	SF	4	1-2 years	Open joints
	Exterior Walls - Stone-Cut	Entire Building	165	SF	7	10+ years	
Windows	3						
	Curtain wall - Insulated Panel	Entire Building	2,191	SF	7	10+ years	
	Curtain wall - Louver	Entire Building	76	SF	7	10+ years	
	Curtain wall - Windows	Entire Building	3,773	SF	7	10+ years	
	Guard - Guards perforated	Entire Building	2,246	SF	7	10+ years	
	Guard - Guards wire guard	Entire Building	22	SF	7	10+ years	
	Lintels - Steel	Entire Building	90	LF	7	10+ years	
	Lintels - Steel	Entire Building	4	LF	7	10+ years	Repaired
	Windows - Decorative	Entire Building	5	SF	7	10+ years	
	Windows - Sash Aluminum Double-pane	Entire Building	855	SF	7	10+ years	
Catego	ry : Electrical		В	uilding	: Main		
Group	ltem - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments

Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Emerger	ncy System						
0	Emergency A/C Power - Corridors and Stairs	1st Floor	5,438	SF	6	6-10 years	
	Emergency A/C Power - Multipurpose Room	1st Floor	2,013	SF	6	6-10 years	
	Emergency A/C Power - Students Toilets	1st Floor	1,076	SF	6	6-10 years	
	Emergency Battery Packs - Corridors and Stairs	1st Floor	7	EA	7	10+ years	Added in 2022.
	Automatic Transfer Switch	Electrical Room	1	EA	6	6-10 years	
	Security System - CCTV	Entire Building	30,193	SF	5	6-10 years	Building & grounds not all covered by cameras.
	Security System - Intrusion Detection	Entire Building	30,193	SF	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	3	EA	6	6-10 years	
	Exit Signs - Corridors and Stairs	Entire Building	6	EA	6	6-10 years	
	Exit Signs - Multipurpose Room	Entire Building	3	EA	6	6-10 years	
	Emergency Generator- Outdoor- Diesel - Below 60 KW	Site - East	1	EA	6	6-10 years	
Main Se	vice						
	PA System	1st Floor	30,193	SF	6	6-10 years	
	Main Electrical Service - 1200 A	Electrical Room	1	EA	4	1-2 years	Older & deteriorated



	ry : Electrical		В	uilding	: Main		
						Recommend	- .
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	120/208/3PH						
Power Di	istribution						
	Lighting and Power Panels - 100 A	Entire Building	1	EA	3	0-1 year	Panel is old and deteriorated.
	Lighting and Power Panels - 100 A	Entire Building	1	EA	3	0-1 year	Older panel
	Lighting and Power Panels - Above 100 A	Entire Building	2	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	6	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	3	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Lighting and Power Panels - Above 100 A	Entire Building	1	EA	6	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	7	6-10 years	
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	0-1 year	Old and deteriorated
	Main Distribution Panels - 400 - 600 amp	Entire Building	1	EA	4	0-1 year	Old and deteriorated
		g					
Categor	ry : Fire Protection		В	uilding	: Main	-	
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Commonto
Group		Location	Quantity		Ralik	Replacement	Comments
Fire Alarn							
	Fire ALarm Anunciator	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Panel	Entire Building	1	EA	7	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	806	SF	7	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	2,272	SF	6	6-10 years	
	Fire Alarm Strobe Lights	Entire Building	6,627	SF	6	6-10 years	
	Fire Alarm_System	Entire Building	30,193	SF	7	6-10 years	
Categor	ry : Mechanical		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Air Condit							
	Condensing Unit- Roof Mounted - Less than 5 tons	Lower Roof	1	EA	7	10+ years	Serves multipurpose room.
	Condensing Unit- Roof Mounted - Less	Lower Roof	1	EA	7	10+ years	Serves MDF room. 2023 install
			1	LA	'	ior years	CEIVES INDI TOUTI. 2023 INSIAII
	than 5 tons						
	than 5 tons						
Air Handli	than 5 tons						
Air Handli	than 5 tons ling Systems Air Handling Unit-Package Single Zone-	2nd Floor	1	EA	6	6-10 years	
Air Handli	than 5 tons ling Systems Air Handling Unit-Package Single Zone- Indoor- Steam Coils and DX Cooling Coils -	2nd Floor	1	EA	6	6-10 years	
Air Handli	than 5 tons ling Systems Air Handling Unit-Package Single Zone-	2nd Floor	1	EA	6	6-10 years	



Catego	ry : Mechanical		В	uilding	: Main		
_			•			Recommend	•
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Boiler S							
	Boiler Auxiliary- Scotch Marine- Steam Low Pressure Boiler - 50 - 75 HP	Boiler Room	2	EA	6	6-10 years	
	Chemical Feed System	Boiler Room	1	EA	6	6-10 years	
	Chemical Feeder	Boiler Room	1	EA	6	6-10 years	
	Combustion Dampers	Boiler Room	2	EA	6	6-10 years	
	Condensate Pump	Boiler Room	1	EA	6	6-10 years	
	Feed Water Pumps and Tank	Boiler Room	1	EA	6	6-10 years	
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP	Boiler Room	1	EA	6	6-10 years	B-1
	Non Condensing- Fire Tube- Scotch Marine- Steam- Low Pressure Boiler - 50 - 75 HP	Boiler Room	1	EA	6	6-10 years	B-2
	Piping - Condensate Pipe- Steel	Boiler Room	300	LF	2	0-1 year	Excessive leaking on piping. Per Engineer, work order in for repair/replacement.
	Piping - Steam Pipe- Steel	Boiler Room	300	LF	6	10+ years	
	Steam Traps	Boiler Room	24	EA	6	6-10 years	
	Vacuum Pump	Boiler Room	1	EA	5	0-1 year	Rusty and leaking, per engineer, worl order in for repair and replacement.
Gas Boo							
	Gas Booster	Boiler Room	2	EA	5	10+ years	Corrosion on shell and associated piping
Heating	Devices						
	Fin Tube - Steam	1st Floor	16	LF	6	6-10 years	Have been painted
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years	•
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	2	EA	6	6-10 years	
	Wall Heater - Electric	Entire Building	3	EA	6	6-10 years	
	Cabinet Heaters - With Steam Coil	Entire Building	12	EA	6	6-10 years	
Mechan	ical Plumbing						
	Condensate-Steel or Galvanized	Entire Building	300	LF	6	6-10 years	
Tempera	ature Control						
	DDC System	Entire Building	30,193	SF	5	0-1 year	Shorts in the system, does not communicate with most of the controls of the building. Work order in for repair, per engineer.
	Electric Thermostat	Entire Building	15	EA	6	6-10 years	
	Thermostats - DDC	Entire Building	21	EA	6	6-10 years	



Catego	ry : Mechanical		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
			,				
Unit Ven	tilation						
	Unit Ventilators- Floor Mounted- Steam Heating Coils Only	Entire Building	21	EA	6	6-10 years	
Ventilatio	on						
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	2	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 1501 - 8000 CFM	Roof	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - 500 - 1500 CFM	Roof	1	EA	6	6-10 years	
	Exhaust Fans- Roof Mounted - Greater than 8000 CFM	Roof	1	EA	6	6-10 years	
	Type I Exhaust Hood- Kitchen	Roof	1	EA	2	0-1 year	No fire suppression system installed
Catego	ry : Plumbing		В	uilding	: Main		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Hot Wate	er						
	Gas Heater - 150000 - 300000 BTU/HR	Boiler Room	1	EA	6	6-10 years	
Piping							
	Domestic Piping-Hot Water Return Lines	Entire Building	30,193	SF	6	10+ years	
	Domestic Piping-Hot Water Return Risers	Entire Building	30,193	SF	6	10+ years	
	Domestic Piping-Hot Water from Risers to Fixtures	Entire Building	30,193	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Horizontal Lines)	Entire Building	30,193	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (Risers)	Entire Building	30,193	SF	6	10+ years	
	Domestic Piping-Hot/Cold Water Supply (from Risers to Fixtures)	Entire Building	30,193	SF	6	10+ years	
	Sanitary Piping	Entire Building	30,193	SF	6	10+ years	
	Storm Piping	Entire Building	30,193	SF	6	10+ years	
	Vent Piping	Entire Building	30,193	SF	6	10+ years	
Catego	ry : Room		В	uilding	: Main		
	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Group			Quantity		Ndlik	Replacement	Comments
Administ	rative Suites/Offices			F ^	~	0.5.	
	AC Unit	1st Floor- Office 102	1	EA	5	2-5 years	



Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Ceiling - Plaster/Drywall	1st Floor- Office 102	384	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor- Office 102	1	EA	6	10+ years	
	Floor - Tile	1st Floor- Office 102	369	SF	7	10+ years	
	Floor - Tile	1st Floor- Office 102	15	SF	4	0-1 year	Damaged tiles
	Lighting - Pendent/Surface	1st Floor- Office 102	6	EA	7	6-10 years	-
	Power Distribution	1st Floor- Office 102	6	EA	6	10+ years	
	Walls - Concrete Block	1st Floor- Office 102	651	SF	6	10+ years	
	Work SInk	1st Floor- Office 102	1	EA	7	10+ years	
	AC Unit	1st Floor-Engineer's Office in Boiler Room	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Engineer's Office in Boiler	86	SF	5	10+ years	
	.	Room				-	
	Doors - Steel Doors incl hw	1st Floor-Engineer's Office in Boiler Room	3	EA	6	10+ years	
	Floor - Tile	1st Floor-Engineer's Office in Boiler Room	86	SF	5	10+ years	
	Lighting - Pendent/Surface	1st Floor-Engineer's Office in Boiler Room	1	EA	6	6-10 years	
	Power Distribution	1st Floor-Engineer's Office in Boiler Room	4	EA	6	10+ years	
	Storage/ Closet	1st Floor-Engineer's Office in Boiler Room	18	SF	5	10+ years	
	Walls - Concrete Block	1st Floor-Engineer's Office in Boiler Room	316	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor-Lunch Room Manager Office	81	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Lunch Room Manager Office	1	EA	7	10+ years	
	Floor - Carpet	1st Floor-Lunch Room Manager Office	81	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Lunch Room Manager Office	1	EA	7	2-5 years	
	Power Distribution	1st Floor-Lunch Room Manager Office	4	EA	6	10+ years	
	Walls - Concrete Block	1st Floor-Lunch Room Manager Office	272	SF	6	10+ years	
	AC Unit	1st Floor-Main Office	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Main Office	425	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Main Office	5	EA	6	10+ years	
	Floor - Carpet	1st Floor-Main Office	425	SF	6	6-10 years	FACTS won't let me add a line. Should be 120 sf of terrazzo and 305 sf of carpet 7/Normal/10+
	Lighting - Pendent/Surface	1st Floor-Main Office	6	EA	7	6-10 years	•
	Power Distribution	1st Floor-Main Office	10	EA	6	10+ years	



Catago			B	ممالما	Main	00	57 5 KINDAIK AVENUE, CHIG
Catego	ry : Room		В	uilding	: Main	December	
Crown	Hom Tuno	Location	Quantitu	UOM	Donk	Recommend	Commonto
Group	Item - Type	1st Floor-Main Office	Quantity	UOM SF	Rank	Replacement	Comments
	Storage/ Closet Walls - Concrete Block	1st Floor-Main Office	60 672	SF	7 6	10+ years	
			-			10+ years	
	AC Unit	1st Floor-Principal's Office	1	EA SF	7 6	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Principal's Office	165	EA	-	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Principal's Office	1		6	10+ years	
	Floor - Carpet	1st Floor-Principal's Office	165	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Principal's Office	2	EA	7	6-10 years	
	Power Distribution	1st Floor-Principal's Office	6	EA	7	10+ years	
	Storage/ Closet	1st Floor-Principal's Office	6	SF	7	10+ years	
	Walls - Concrete Block	1st Floor-Principal's Office	374	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor-Workroom in Main Office	80	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Workroom in Main Office	1	EA	6	10+ years	
	Floor - Carpet	1st Floor-Workroom in Main Office	80	SF	6	6-10 years	
	Lighting - Pendent/Surface	1st Floor-Workroom in Main Office	1	EA	7	6-10 years	
	Power Distribution	1st Floor-Workroom in Main Office	4	EA	6	10+ years	
	Walls - Concrete Block	1st Floor-Workroom in Main Office	279	SF	6	10+ years	
	AC Unit	2nd Floor-Office 200	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Office 200	360	SF	7	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Office 200	2	EA	7	10+ years	
	Floor - Tile	2nd Floor-Office 200	360	SF	6	10+ years	
	Lighting - Lay-in	2nd Floor-Office 200	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor-Office 200	4	EA	7	6-10 years	
	Power Distribution	2nd Floor-Office 200	14	EA	7	10+ years	
	Storage/ Closet	2nd Floor-Office 200	45	SF	7	10+ years	
	Walls - Concrete Block	2nd Floor-Office 200	578	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor-Office 200	82	SF	7	10+ years	
	AC Unit	2nd Floor-Office 201	1	EA	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Office 201	300	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor-Office 201	2	EA	7	10+ years	
	Floor - Carpet	2nd Floor-Office 201	300	SF	6	6-10 years	
	Lighting - Lay-in	2nd Floor-Office 201	1	ĒA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor-Office 201	3	EA	7	6-10 years	
						, , .	

2nd Floor-Office 201

2nd Floor-Office 201

2nd Floor-Office 201

1st Floor

Floor - Tile

Floor - Tile

Serving Line

Kitchen

Power Distribution

Walls - Concrete Block

Walls - Plaster/Drywall

Ceiling - Plaster/Drywall

Doors - Steel Doors incl hw

Lighting - Pendent/Surface

Walls - Structural Glazed Tile

8

628

346

336

10

6

10

709

1

50

ΕA

SF

SF

SF

ΕA

SF

SF

ΕA

LF

SF

7

7

6

6

7

6

4

7

7

6

10+ years

10+ years

10+ years

10+ years

10+ years

10+ years

1-2 years

6-10 years

10+ years

10+ years

Damaged tiles



Catego	ry : Room		Building : Main				
	,			J		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Library							
	AC Unit	2nd Floor-Library 202	1	EA	7	6-10 years	
	Casework	2nd Floor-Library 202	60	LF	6	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor-Library 202	755	SF	6	10+ years	
	Doors - Steel Doors incl hw	2nd Floor-Library 202	1	EA	7	10+ years	
	Floor - Carpet	2nd Floor-Library 202	755	SF	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor-Library 202	16	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor-Library 202	980	SF	6	10+ years	
Lunch &	Multipurpose Room						
	Ceiling - Splined	1st Floor	2,013	SF	6	10+ years	
	Doors - Steel Doors incl hw	1st Floor	_,0.0	EA	6	10+ years	
	Floor - Tile/Sheet	1st Floor	2,013	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	ĒA	7	6-10 years	
	Storage/ Closet	1st Floor	200	SF	5	10+ years	
	Walls - Concrete Block	1st Floor	2,272	SF	6	10+ years	
			_,		-	, e e e e e e e e e e e e e e e e e e e	
MDF_ID	F						
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Finishes	2nd Floor	125	SF	5	10+ years	
	Other Cooling Unit	2nd Floor	1	EA	7	10+ years	Ductless split system.
Mechani	cal/ Service Rooms						
	Boiler Room	1st Floor	806	SF	5	10+ years	
	Crawl Space - Unfinished	1st Floor	2,215	SF	5	10+ years	
	Janitor's Closet	1st Floor	45	SF	5	10+ years	
	Storage Room	1st Floor	115	SF	5	10+ years	
	Vaults	1st Floor	70	SF	7	10+ years	
	Janitor's Closet	2nd Floor	42	SF	7	6-10 years	
	Mechanical/ Service Rooms	2nd Floor	150	SF	7	10+ years	Inside 201
	Storage Room	2nd Floor	42	SF	7	10+ years	Patch and paint ceiling Former
	Ĵ					2	Restroom inside 201; now a storage closet
Restroor	n						
RESHOOL	Accessories	100A Restroom	50	SF	7	6-10 years	
	Ceiling - Splined	100A Restroom	50	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	100A Restroom	50	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	100A Restroom	50	SF	6	•	
	Floor Drain	100A Restroom	50 1	EA	6 7	6-10 years	
			1		7	10+ years	
	Hand Dryer	100A Restroom	1	EA EA	7	6-10 years	
	Lavatory	100A Restroom	1	EA	1	6-10 years	



Catego	ry : Room		R	uilding	Main	00	57 S KIMDARK AVENUE, Chicago, IL 60637
Calego	ly . Room		J	unung		Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
0.000	Lighting - Pendent/Surface	100A Restroom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	100A Restroom	60	SF	7	6-10 years	
	Walls - Tile Ceramic/ Porcelain	100A Restroom	80	SF	7	6-10 years	
	Water Closet	100A Restroom	1	ĒA	7	6-10 years	
	Accessories	1st Floor Main Office	57	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor Main Office	57	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor Main Office	1	EA	6	10+ years	
	Floor - Tile	1st Floor Main Office	57	SF	6	10+ years	
	Lavatory	1st Floor Main Office	1	EA	7	10+ years	
	Lighting - Lay-in	1st Floor Main Office	1	EA	6	6-10 years	Replace cover
	Partitions	1st Floor Main Office	1	EA	7	10+ years	
	Walls - Concrete Block	1st Floor Main Office	144	SF	6	10+ years	
	Water Closet	1st Floor Main Office	1	EA	6	10+ years	
	Accessories	1st Floor- Lunch Room Manager	14	SF	7	6-10 years	
		Office				-	
	Ceiling - Plaster/Drywall	1st Floor- Lunch Room Manager	14	SF	6	10+ years	
		Office					
	Doors - Wood Doors inclu hw	1st Floor- Lunch Room Manager	1	EA	6	10+ years	
		Office					
	Floor - Concrete Epoxy/ Painted	1st Floor- Lunch Room Manager	14	SF	5	2-5 years	
		Office					
	Lavatory	1st Floor- Lunch Room Manager	1	EA	6	10+ years	
		Office					
	Lighting - Pendent/Surface	1st Floor- Lunch Room Manager	1	EA	7	6-10 years	
		Office					
	Walls - Concrete Block	1st Floor- Lunch Room Manager	25	SF	6	10+ years	
		Office					
	Water Closet	1st Floor- Lunch Room Manager	1	EA	6	10+ years	
		Office					
	Accessories	1st Floor-Boy's Restroom	215	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Boy's Restroom	135	SF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor-Boy's Restroom	80	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor-Boy's Restroom	2	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Boy's Restroom	215	SF	7	10+ years	
	Floor Drain	1st Floor-Boy's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Boy's Restroom	1	EA	7	10+ years	
	Lavatory	1st Floor-Boy's Restroom	2	EA	7	10+ years	
	Lighting - Pendent/Surface	1st Floor-Boy's Restroom	3	EA	7	6-10 years	
	Partitions	1st Floor-Boy's Restroom	2	EA	7	10+ years	
	Urinals	1st Floor-Boy's Restroom	4	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Boy's Restroom	96	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor-Boy's Restroom	200	SF	6	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor-Boy's Restroom	300	SF	6	10+ years	
	Water Closet	1st Floor-Boy's Restroom	2	EA	7	10+ years	



					66	57 S KIMDARK AVENUE, Chicago, IL 60637	
Catego	ry : Room		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Accessories	1st Floor-Engineer's Office Restroom	25	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Engineer's Office Restroom	25	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor-Engineer's Office Restroom	1	EA	6	10+ years	
	Floor - Tile	1st Floor-Engineer's Office Restroom	25	SF	6	10+ years	
	Lavatory	1st Floor-Engineer's Office Restroom	1	EA	6	10+ years	
	Lighting - Lay-in	1st Floor-Engineer's Office Restroom	1	EA	7	6-10 years	
	Lighting - Wall Mounted	1st Floor-Engineer's Office Restroom	1	EA	7	6-10 years	
	Walls - Concrete Block	1st Floor-Engineer's Office Restroom	50	SF	6	10+ years	
	Water Closet	1st Floor-Engineer's Office Restroom	1	EA	6	10+ years	
	Accessories	1st Floor-Girl's Restroom	240	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Girl's Restroom	240	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor-Girl's Restroom	1	EA	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Girl's Restroom	240	SF	7	10+ years	
	Floor Drain	1st Floor-Girl's Restroom	1	EA	7	10+ years	
	Hand Dryer	1st Floor-Girl's Restroom	1	EA	7	6-10 years	
	Lavatory	1st Floor-Girl's Restroom	2	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-Girl's Restroom	2	EA	7	6-10 years	
	Partitions	1st Floor-Girl's Restroom	5	EA	7	10+ years	
	Walls - Concrete Block	1st Floor-Girl's Restroom	56	SF	6	10+ years	
	Walls - Structural Glazed Tile	1st Floor-Girl's Restroom	550	SF	6	10+ years	
	Walls - Structural Glazed The Water Closet	1st Floor-Girl's Restroom	550	EA	7	10+ years	
			32	SF	7		
	Accessories	1st Floor-Kindergarten Restrooom				6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Kindergarten Restrooom	32	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Kindergarten Restrooom	1	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor-Kindergarten Restrooom	32	SF	6	10+ years	
	Lavatory	1st Floor-Kindergarten Restrooom	1	EA	6	10+ years	
	Lighting - Pendent/Surface	1st Floor-Kindergarten Restrooom	1	EA	7	6-10 years	
	Walls - Plaster/Drywall	1st Floor-Kindergarten Restrooom	68	SF	7	10+ years	
	Walls - Tile Ceramic/ Porcelain	1st Floor-Kindergarten Restrooom	113	SF	7	10+ years	Corrected quantity
	Water Closet	1st Floor-Kindergarten Restrooom	1	EA	7	10+ years	
	Accessories	1st Floor-Staff Restroom, across from Classroom 106	40	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor-Staff Restroom, across from Classroom 106	40	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor-Staff Restroom, across	1	EA	6	10+ years	



atego	ry : Room		В	uilding	: Main		
3-	·			3		Recommend	
roup	Item - Type	Location	Quantity	UOM	Rank		Comments
		from Classroom 106	,				
	Floor - Tile Ceramic/ Porcelain	1st Floor-Staff Restroom, across	40	SF	6	10+ years	
		from Classroom 106			•	, , , , , , , , , , , , , , , , , , ,	
	Floor Drain	1st Floor-Staff Restroom, across	1	EA	7	10+ years	
		from Classroom 106			-	, , , , , , , , , , , , , , , , , , ,	
	Hand Dryer	1st Floor-Staff Restroom, across	1	EA	7	6-10 years	
		from Classroom 106	·	_/ \	•	0 10 900.0	
	Lavatory	1st Floor-Staff Restroom, across	1	EA	7	10+ years	
		from Classroom 106			-	, , , , , , , , , , , , , , , , , , ,	
	Lighting - Lay-in	1st Floor-Staff Restroom, across	1	EA	7	6-10 years	
		from Classroom 106	·	-/ (•	o ro youro	
	Walls - Tile Ceramic/ Porcelain	1st Floor-Staff Restroom, across	80	SF	6	10+ years	
		from Classroom 106	00	01	Ū	ior youro	
	Water Closet	1st Floor-Staff Restroom, across	1	EA	6	10+ years	
		from Classroom 106	•	L/\	Ũ	ior youro	
	Accessories	2nd Floor-Boy's Restroom 211	245	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Boy's Restroom 211	245	SF	6	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor-Boy's Restroom 211	4	EA	7	10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Boy's Restroom 211	245	SF	7	10+ years	
	Floor Drain	2nd Floor-Boy's Restroom 211	243	EA	7	10+ years	
	Lavatory	2nd Floor-Boy's Restroom 211	2	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor-Boy's Restroom 211	2	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor-Boy's Restroom 211	2	EA	7	6-10 years	
	Partitions	2nd Floor-Boy's Restroom 211	2	EA	7	10+ years	
	Urinals	2nd Floor-Boy's Restroom 211	2	EA	7		
	Walls - Concrete Block	2nd Floor-Boy's Restroom 211	75	SF	7	10+ years	
	Walls - Concrete Block Walls - Structural Glazed Tile	2nd Floor-Boy's Restroom 211	73 510	SF	7	10+ years	
	Walls - Structural Glazed The Water Closet	2nd Floor-Boy's Restroom 211		EA	7	10+ years 10+ years	
		2nd Floor-Girl's Restroom	2 245	SF	7		
	Accessories			SF		6-10 years	
	Ceiling - Plaster/Drywall Doors - Wood Doors inclu hw	2nd Floor-Girl's Restroom	245 4	EA	6 7	10+ years	
		2nd Floor-Girl's Restroom	-			10+ years	
	Floor - Tile Ceramic/ Porcelain	2nd Floor-Girl's Restroom	245	SF	7	10+ years	
	Floor Drain	2nd Floor-Girl's Restroom	1	EA	7	10+ years	
	Hand Dryer	2nd Floor-Girl's Restroom	1	EA	7	6-10 years	
	Lavatory	2nd Floor-Girl's Restroom	2	EA	7	10+ years	
	Lighting - Lay-in	2nd Floor-Girl's Restroom	1	EA	7	6-10 years	
	Lighting - Pendent/Surface	2nd Floor-Girl's Restroom	2	EA	7	6-10 years	
	Partitions	2nd Floor-Girl's Restroom	_6	EA	7	6-10 years	
	Walls - Concrete Block	2nd Floor-Girl's Restroom	75	SF	7	10+ years	
	Walls - Structural Glazed Tile	2nd Floor-Girl's Restroom	510	SF	7	10+ years	
	Water Closet	2nd Floor-Girl's Restroom	6	EA	7	10+ years	
	Accessories	2nd Floor-Office 201 Restroom	42	SF	5	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor-Office 201 Restroom	42	SF	6	10+ years	
	Doors - Wood Doors inclu hw	2nd Floor-Office 201 Restroom	1	EA	6	6-10 years	



Building : Main Category : Room Recommend Location Group Item - Type Quantity UOM Rank **Replacement** Comments Floor - Tile 2nd Floor-Office 201 Restroom SF 42 6 10+ years 2nd Floor-Office 201 Restroom ΕA 6 6-10 years Lighting - Wall Mounted 1 Walls - Concrete Block 2nd Floor-Office 201 Restroom 84 SF 6 10+ years Accessories 2nd Floor-Staff Restroom across 40 SF 7 6-10 years from Classroom 206 Ceiling - Plaster/Drywall 2nd Floor-Staff Restroom across SF 40 7 10+ years from Classroom 206 Doors - Wood Doors inclu hw 2nd Floor-Staff Restroom across 1 ΕA 7 10+ years from Classroom 206 Floor - Tile 2nd Floor-Staff Restroom across SF 40 6 10+ years from Classroom 206 Hand Dryer 2nd Floor-Staff Restroom across 1 ΕA 7 6-10 years from Classroom 206 2nd Floor-Staff Restroom across Lavatory 1 ΕA 7 10+ years from Classroom 206 Lighting - Lay-in 2nd Floor-Staff Restroom across FΑ 7 1 6-10 years from Classroom 206 Lighting - Wall Mounted 2nd Floor-Staff Restroom across 1 ΕA 7 6-10 years from Classroom 206 2nd Floor-Staff Restroom across Partitions 1 ΕA 7 10+ years from Classroom 206 Walls - Concrete Block 2nd Floor-Staff Restroom across SF 82 7 10+ years from Classroom 206 2nd Floor-Staff Restroom across Water Closet 1 ΕA 7 10+ years from Classroom 206

Catego	ry : Classroom	В	uilding				
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Classroo	m #100 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	AC Units	1st Floor	1	EA	7	2-5 years	
	Casework	1st Floor	58	LF	7	10+ years	
	Ceiling - Splined	1st Floor	1,102	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	6	10+ years	
	Floor - Tile	1st Floor	1,102	SF	7	6-10 years	
	Lighting - Pendent/Surface	1st Floor	20	EA	7	6-10 years	
	Storage/ Closet	1st Floor	9	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,288	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	80	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	m #104 (Faculty Lounge)						
	AC Units	1st Floor	1	EA	7	6-10 years	



Catego	ry : Classroom		B	Building : Main			
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Casework	1st Floor	16	LF	6	0-1 year	
	Ceiling - Plaster/Drywall	1st Floor	745	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	6	10+ years	
	Floor - Tile	1st Floor	745	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	13	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	829	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	60	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassroo	m #105 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	720	SF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	25	SF	6	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	745	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	38	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	829	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	60	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	6-10 years	
lassroo	m #106/108 (Regular Classroom)						
1233100	AC Units	1st Floor	2	EA	7	6-10 years	
	Casework	1st Floor	36	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	1,102	SF	7	6-10 years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	1,097	SF	7	10+ years	
	Floor - Tile	1st Floor	1,097	SF	4	1-2 years	Damaged tiles
	Lighting - Pendent/Surface	1st Floor	24	EA	7	6-10 years	Damaged lifes
	Marker Board	1st Floor	13	LF	7	6-10 years	
		1st Floor	175	SF			
	Storage/ Closet			SF	5	10+ years	
	Walls - Concrete Block	1st Floor	1,261		6 7	10+ years	
	Work Sink	1st Floor	1	EA	/	10+ years	
assroo	m #107 (Regular Classroom)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	745	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	
	Floor - Tile	1st Floor	745	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	



Catego	ry : Classroom		В	Building : Main			
						Recommend	-
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
	Marker Board	1st Floor	38	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	829	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	60	SF	6	10+ years	
lassroc	m #109 (Store Room)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	16	LF	6	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	445	SF	7	6-10 years	
	Ceiling - Plaster/Drywall	1st Floor	300	SF	6	6-10 years	Peeling paint
	Doors - Wood Doors inclu hw	1st Floor	1	EA	7	10+ years	01
	Floor - Tile	1st Floor	745	SF	7	10+ years	
	Lighting - Pendent/Surface	1st Floor	16	EA	7	6-10 years	
	Marker Board	1st Floor	38	LF	7	6-10 years	
	Walls - Concrete Block	1st Floor	829	SF	6	10+ years	
	Walls - Plaster/Drywall	1st Floor	60	SF	6	10+ years	
	Work Sink	1st Floor	1	EA	7	10+ years	
lassroc	m #110 (Kindergarten)						
	AC Units	1st Floor	1	EA	7	6-10 years	
	Casework	1st Floor	7	LF	7	10+ years	
	Ceiling - Plaster/Drywall	1st Floor	950	SF	6	10+ years	
	Doors - Wood Doors inclu hw	1st Floor	2	EA	7	10+ years	
	Floor - Tile	1st Floor	2	SF	7	10+ years	
	Floor - Tile	1st Floor	948	SF	6	10+ years	
	Lighting - Pendent/Surface	1st Floor	10	EA	7	6-10 years	
	Marker Board	1st Floor	13	LF	7	6-10 years	
	Storage/ Closet	1st Floor	65	SF	7	10+ years	
	Walls - Concrete Block	1st Floor	1,152	SF	6	10+ years	
	Work Sink	1st Floor	2	EA	7	10+ years	
Classroo	om #203 (Art Room)						
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	24	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	745	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	965	SF	7	10+ years	
	Work Sink	2nd Floor	903 1	EA	7	6-10 years	



Catego	ry : Classroom		R	Building : Main			557 S Kimbark AVENUE, Chicago, IL 6063
Jaieyo				Dunung . Main			
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	6	6-10 years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	7	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor		EA	7	10+ years	
	Floor - Tile	2nd Floor	745	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	965	SF	7	10+ years	
lassroo	om #205 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	745	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	965	SF	7	10+ years	
lassroo	om #206 (Computer Lab)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	10+ years	
	Chalk Board	2nd Floor	18	LF	4	2-5 years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	745	SF	6	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	25	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	965	SF	7	10+ years	
	Wireless System	2nd Floor	1	EA	7	6-10 years	
lassroo	om #207 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	5	0-1 year	Warm air.
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	745	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
			965	SF	7	10+ years	



Catego	Category : Classroom		Building : Main				57 5 KINDAR AVENUE, CHICAGO, IE 00057
Jaiego				anang	. mann	Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
-	<i></i>	Loodion	Quantity	00111	Nam	Replacement	
Classion	om #208 (Regular Classroom)	2nd Floor	4		7	0.10	
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	7	10+ years	
	Doors - Steel Doors incl hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	745	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	965	SF	7	10+ years	
Classroo	om #209 (Regular Classroom)						
	AC Units	2nd Floor	1	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	745	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LA	7	6-10 years	
	Walls - Concrete Block	2nd Floor	965	SF	7	10+ years	
0	"010 (D					·	
Classroo	om #210 (Regular Classroom)			= .			
	AC Units	2nd Floor	2	EA	7	6-10 years	
	Casework	2nd Floor	20	LF	7	10+ years	
	Ceiling - Plaster/Drywall	2nd Floor	745	SF	6	10+ years	
	Chalk Board	2nd Floor	20	LF	4	2-5 years	
	Doors - Wood Doors inclu hw	2nd Floor	1	EA	7	10+ years	
	Floor - Tile	2nd Floor	745	SF	7	10+ years	
	Lighting - Pendent/Surface	2nd Floor	16	EA	7	6-10 years	
	Marker Board	2nd Floor	20	LF	7	6-10 years	
	Walls - Concrete Block	2nd Floor	965	SF	7	10+ years	
Catego	ry : Interior		В	uilding	: Main		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Corridor				e –	-		
	Ceiling - Plaster/Drywall	1st Floor	50	SF	6	6-10 years	
	Ceiling - Splined	1st Floor	3,136	SF	6	10+ years	
	Ceiling - Splined	1st Floor	3	SF	4	1-2 years	Water damage
	Doors - Wood Doors include hw	1st Floor	4	EA	6	10+ years	
	Drinking Fountains - Single Water Cooler	1st Floor	2	EA	7	10+ years	
	Floor - Terrazzo	1st Floor	602	SF	6	10+ years	
	Floor - Tile Ceramic/ Porcelain	1st Floor	50	SF	7	10+ years	
						-	



6657 S Kimbark AVENUE, Chicago, IL 60637 **Building : Main** Category : Interior Recommend Group Item - Type Location Quantity UOM Rank **Replacement** Comments Floor - Tile/Sheet 1st Floor 2.537 SF 10+ vears 7 Lighting - Pendent/Surface 1st Floor 22 ΕA 6-10 vears 5 Lighting - Wall Mounted 1st Floor FΑ 7 6-10 years 1 Student Lockers - Two Tiers 220 1st Floor ΕA 6 10+ years SF Walls - Concrete Block 1st Floor 3,166 6 10+ years SF Walls - Structural Glazed Tile 1st Floor 848 6 10+ years Ceiling - Plaster/Drywall 1st Floor Main Office Corridor SF 6 10+ years 59 Doors - Steel Doors incl hw 1st Floor Main Office Corridor 1 ΕA 6 6-10 years Floor - Tile/Sheet 1st Floor Main Office Corridor 59 SF 7 6-10 years Lighting - Pendent/Surface 1st Floor Main Office Corridor 1 ΕA 7 6-10 years Walls - Concrete Block 1st Floor Main Office Corridor 280 SF 6 10+ vears Ceiling - Splined 2nd Floor 1.682 SF 6 6-10 years Drinking Fountains - Single Water Cooler 2nd Floor 2 ΕA 7 6-10 years SF 7 Floor - Tile/Sheet 2nd Floor 1,682 10+ years Lighting - Pendent/Surface 2nd Floor ΕA 7 6-10 years 12 Student Lockers - Two Tiers 2nd Floor 225 FΑ 7 6-10 years Student Lockers - Two Tiers 2nd Floor 5 ΕA 5 1-2 years Damaged/ missing doors SF Walls - Concrete Block 2nd Floor 2,897 7 10+ years SF Walls - Structural Glazed Tile 2nd Floor 425 7 10+ years Safety Camera Viewing Station Entire Building 4 ΕA 7 6-10 vears **Camera Viewing Station** 1 ΕA 4 1-2 years Not functioning Entire Building ΕA 7 6-10 vears Security Cameras Entire Building 9 Stairs Ceiling - Splined SF N Stairs 295 7 10+ years Floor - Terrazzo SF 7 N Stairs 170 10+ years Handrails N Stairs 40 LF 7 10+ years 2 ΕA Lighting - Pendent/Surface N Stairs 7 6-10 years Stairs - Terrazzo LF 7 N Stairs 120 10+ years SF 7 Walls - Concrete Block N Stairs 575 10+ years Ceiling - Splined 295 SF 7 S Stairs 10+ years Floor - Terrazzo S Stairs 170 SF 7 10+ years LF Handrails S Stairs 40 7 10+ vears Lighting - Pendent/Surface S Stairs 2 ΕA 7 6-10 years Stairs - Terrazzo LF 7 S Stairs 120 10+ vears Walls - Concrete Block S Stairs 575 SF 7 10+ years



Catego	ry : Site		В	uilding	: Site		
						Recommend	
Group	Item - Type	Location	Quantity	UOM	Rank	Replacement	Comments
Civil/Dra	inage						
	Civil/ Drainage - Catch Basin	Entire Site	2	EA	7	6-10 years	
	Civil/ Drainage - Site Manhole	Entire Site	2	EA	7	10+ years	Repaired
	Civil/ Drainage - Site Manhole	Entire Site	3	EA	7	6-10 years	·
Fencina							
0	Fencing - Chain Link	Entire Site	100	LF	7	10+ years	
	Fencing - Chain Link	Entire Site	65	LF	7	10+ years	Repaired
	Fencing - Chain Link	Entire Site	350	LF	7	10+ years	
	Fencing - Chain Link	Entire Site	660	LF	7	10+ years	
	Fencing - Chain Link	Entire Site	330	LF	5	1-2 years	Corroding fence, 50 ft are also bent
	Forloing Chain Link		000		Ũ		out of shape
	Fencing - Old Standard Ornamental	Entire Site	220	LF	7	10+ years	•
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	32	LF	7	10+ years	Repaired.
	Fencing - Wood Fencing w/ Steel Frame	Entire Site	130	LF	7	10+ years	Repaired.
Landsca	pe						
	Landscape - Grass	Entire Site	5,500	SF	7	10+ years	
	Landscape - Grass	Entire Site	500	SF	4	1-2 years	Damaged.
	Parkway trees	Entire Site	11	EA	7	10+ years	Dumugou.
	Planting Beds/ Area	Entire Site	1,489	SF	7	10+ years	
	Play Area - Synthetic Turf	Entire Site	6,367	SF	7	10+ years	
	Trash Receptacles	Entire Site	3	EA	7	10+ years	
Parking	l et						
Farking	Concrete Curbs	Parking Lot- East	40	LF	6	10+ years	
	Surface - Asphalt	Parking Lot- East	8,000	SF	4	0-1 year	Damaged asphalt, cracks, alligatore
	Surface - Asphalt	Parking Lot- East	8,000	SF	4	0-1 year	surface. Vegetation throughout
	Surface - Asphalt	Parking Lot- West	12,766	SF	6	10+ years	5 5
	Surface - Asphalt	Parking Lot- West	3,000	SF	4	1-2 years	Potholes, alligator in surface
	Trash Enclosure - Chain Links	Parking Lot- West	45	SF	7	10+ years	, C
Playgrou	Ind						
	Equipment - Pre K 3-5	North	1	EA	7	10+ years	
	Equipment - School Age 5-12	North	1	EA	7	10+ years	
	Surface - Poured Surface	North	2,600	SF	7	10+ years	
Sidewalł	(S						
	Sidewalks - Internal Walks	Entire Site	60	LF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	3,718	SF	7	10+ years	
	Sidewalks - Perimeter Sidewalks	Entire Site	100	SF	4	1-2 years	Cracks, broken concrete
			100	0.	•	;00.0	



Catego	ry : Site		В	uilding	: Site		
Group	Item - Type	Location	Quantity	UOM	Rank	Recommend Replacement	Comments
Signage							
	Flag Pole - Flag Pole	Entire Site	1	EA	6	10+ years	
	Marquee - Free Standing Back Lighted	Entire Site	1	EA	7	6-10 years	
	Monument - Building Mounted Cut Letter Sign	Entire Site	2	EA	7	10+ years	Repaired

¹ It is very rare for assessors to find a feature in this condition. If assessors do, they are required to report it to CPS right away, and CPS facilities will address it immediately. As a result, no features should be ranked "1" in this report; by the time the report is compiled, they will have been resolved.

Definitions

- Quantity means, for each item, the total number (or amount) of that item that exists and was evaluated
- Unit means the generally accepted standard unit of measure for each item. Some items, like doors, are measured individually and use the unit of measurement "EA" for "each." Other items, like chimneys, are measured in terms of linear feet ("LF"). Still other items, like flooring, are generally measured in square feet ("SF").



Classroom Summary

			Room	Floor Plan Room	Area	Glazed Window	Operable Window	Window	Smart-
Current Usage	Intended Usage	Room Location	Number	Number	(SF)	Area	Area	Stop	Board
Building : Main	·							·	
Art Room	Regular Classroom	2nd Floor	203	203	745	120	40	Y	Y
Computer Lab	Regular Classroom	2nd Floor	206	206	745	120	40	Y	N
Faculty Lounge	Regular Classroom	1st Floor	104	104	745	160	64	Y	N
Kindergarten	Regular Classroom	1st Floor	100	100	1,102	340	136	Y	N
Kindergarten	Regular Classroom	1st Floor	110	110	950	200	80	N	Y
Regular Classroom	Regular Classroom	1st Floor	105	105	745	160	64	Y	Y
Regular Classroom	Regular Classroom	1st Floor	106/108	108/108	1,102	240	96	Y	Y
Regular Classroom	Regular Classroom	1st Floor	107	107	745	160	64	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	204	204	745	120	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	205	205	745	120	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	207	207	745	120	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	208	208	745	120	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	209	209	745	120	40	Y	Y
Regular Classroom	Regular Classroom	2nd Floor	210	210	745	120	40	Y	Y
Store Room	Regular Classroom	1st Floor	109	109	745	160	64	Y	Y