ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: UNKNOWN
SCHOOL NAME: Chicago Virtual Academy
ADDRESS OF SCHOOL: 38 Peoria
CITY: Chicago, IL, 60607

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 4/25/2016 ENROLLMENT 663

IDPH INSPECTOR LICENSE NUMBER: 100-08864

IDPH LICENSED INSPECTOR NAME (Please Print): Robert DeBord

IDPH MP LICENSE NUMBER: 100-03613

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Daniel Juneau

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



4/25/2016

Signature of Designated Person *Date*

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale:

School has been closed. Date closed:

School building has been demolished. Date:

School building is asbestos free since last reinspection:

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either and exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE–YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Chicago Virtual Academy

38 Peoria
Chicago, IL, 60607

Unit: 66481
Building ID: 7700

IDPH ID Number: UNKNOWN

REPORT DATE:
Monday, April 25, 2016

Prepared for:
Chicago Public Schools
125 S. Clark Street
Chicago, IL 60603

Prepared by:
Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone (312) 762-2900

Fax (312) 782-5145

DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW

April 1, 2016

Mr. R. Kent Cook
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2016 Three-Year Reinspections

Dear Mr. Cook:

Carnow, Conibear and Associates, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 3,4,5 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66481 Region: 03 IDPH ID: UNKNOWN

School: Chicago Virtual Academy Building ID: 7700

Address: 38 Peoria

Chicago, IL, 60607

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 04/25/2016

Inspector: Robert DeBord Inspector IDPH License: 100-08864
Management Planner: Daniel Juneau Management Planner IDPH License: 100-03613

If you have any questions or comments, please contact us at (312) 762-2900

Sincerely,
Carnow, Conibear and Associates



Daniel Juneau
100-03613

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: April 01, 2016

RE: Chicago Virtual Academy, Unit 66481
38 Peoria
Chicago, IL, 60607

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2016 asbestos three year re-inspection has been completed at Chicago Virtual Academy , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Chicago Virtual Academy, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

I. School and Inspection Information

II. Executive Summary

III. Methodology

IV. Abatement History

V. Reassessments and Recommendations

VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

Appendix A: Assessment Sheets, Drawings and Photos

Appendix B: Inspector and Management Planner Licenses

Appendix C: Laboratory Accreditations

Appendix D: Laboratory Results

Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Chicago Virtual Academy Unit: 66481 Region: 03
Address: 38 Peoria Chicago, IL, 60607
IDPH ID: UNKNOWN Building ID: 7700
Contact: Phone:

2. Description of Facility

Original Construction: Additional Construction:
Total Square Footage: 12000 No of Floors:
Current Occupancy: 663

3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197
Address: 125 South Clark Street, 17th Floor
Chicago, IL 60603

4. Managing Environmental Consultant

MEC: Carnow, Conibear and Associates
Contact: Dan Juneau
Address 600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145


5. Inspector

Inspector Name: Robert DeBord

Signature:
Inspector IDPH license # 100-08864 Date: 4/1/2016

6. Management Planner

Management Planner Name: Daniel Juneau



Signature:
Management Planner IDPH license # 100-03613 Date: 04/25/2016

7. Review Date: 04/25/2016

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:  Date: 4/25/2016

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

Carnow, Conibear and Associates was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Chicago Virtual Academy. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 7700:

CT1	2'x2' white dot-fissure ceiling tile
CT2	2'x2' white textured ceiling tile
FP	Gray spray-on fireproofing
MVI	Mud on fiberglass valve insulation

B. The following new homogenous areas have been identified for Building 7700:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

BAWP	Brown accoustical wall panels
BBB	4" beige baseboard
BBBM	Mastic behind 4" beige baseboard
BDC	Brown caulk on duct seams
BGMT	Gray grout for 12"x12" green marble ceramic tile
BSF	3'x3' black safety flooring
BSFM	Mastic below 3'x3' black safety flooring
BST	Beige vinyl stiar tread flooring
BSTM	Mastic below beige vinyl stair tread flooring
BVT	2'x2' beige vinyl floor tile
CGGH	Glue below brown with black accents carpet
CGLH	Glue below black/brown/green/gray carpet
CT1	2'x2' white dot-fissure ceiling tile
CT2	2'x2' white textured ceiling tile
CTG	Glue below 2'x2' multi-patterned carpet
DGVT	2'x2' dark gray vinyl floor tile
DW	Drywall walls and ceilings
DWJ	Drywall joint compound on walls and ceilings
FP	Gray spray-on fireproofing
GBB	4" green baseboard
GBBM	Mastic behind 4" green baseboard
GG12T	Gray grout for 12"x12" olive green and gray granite floor tiles
GG1T	Gray grout for 1"x 1" multi-colored ceramic wall/floor tile
GSPVT	12"x12" gray stone-pattern vinyl floor tile
LGVT	2'x2' light gray vinyl floor tile
MFD	Metal fire door insulation
MVI	Mud on fiberglass valve insulation
OGSPVT	12"x12" olive green stone-pattern vinyl floor tile
OGVT	2'x2' olive green vinyl floor tile
RPC	Red caulk as penetrations
RST	Red vinyl stair tread/landing flooring
RSTM	Mastic below red vinyl stair tread/landing flooring
SAWP	Silver accoustical wall panels
SPVTM	Mastic below 12"x12" stone-pattern vinyl floor tile
TWC	Tan interior window caulk
TZ	White terrazzo flooring
VTM	Mastic below 2'x2' vinyl floor tile
WFD	Wood fire door insulation
WG	Glue below wood floor
WSPVT	12"x12" white stone patterned vinyl floor tile

The following areas were deemed to be inaccessible:

BBBM	Mastic behind 4" beige baseboard
BDC	Brown caulk on duct seams
BSFM	Mastic below 3'x3' black safety flooring
BSTM	Mastic below beige vinyl stair tread flooring
CGGH	Glue below brown with black accents carpet
CGLH	Glue below black/brown/green/gray carpet
CT2	2'x2' white textured ceiling tile
FP	Gray spray-on fireproofing
GBBM	Mastic behind 4" green baseboard
MFD	Metal fire door insulation
RSTM	Mastic below red vinyl stair tread/landing flooring
WFD	Wood fire door insulation
WG	Glue below wood floor

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Robert DeBord, IDPH License # 100-08864. The Management Plan was updated by Daniel Juneau, IDPH License # 100-03613. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Chicago Virtual Academy Building 7700 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I

Inspector's Reinspection Findings

Chicago Public Schools

School Chicago Virtual Academy **Unit** 66481 **Building ID** 7700
Address 38 Peoria **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
BAWP	Brown accoustical wall panels	864	SF	Foreman Hall	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BBB	4" beige baseboard	6,810	LF	Corridors, classrooms, offices, storage rooms, closets with vinyl carpet tile or carpet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BBBM	Mastic behind 4" beige baseboard	6,810	LF	Corridors, classrooms, offices, storage rooms, closets with vinyl tile or carpet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BDC	Brown caulk on duct seams	500	LF	At seams of ductwork above ceilings and in mechanical spaces	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BGMT	Gray grout for 12"x12" green marble ceramic tile	325	SF	Reception desk and wall behind	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BSF	3'x3' black safety flooring	756	SF	kindergarden (133)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BSFM	Mastic below 3'x3' black safety flooring	756	SF	Kindergarden (133)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BST	Beige vinyl stiar tread flooring	32	SF	Room 124	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BSTM	Mastic below beige vinyl stair tread flooring	32	SF	Room 124	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
BVT	2'x2' beige vinyl floor tile	25,256	SF	corridors,classrooms , offices, storage rooms, and closets	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CGGH	Glue below brown with black accents carpet	3,832	SF	Gottlieb Hall and balcony	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CGLH	Glue below black/brown/green/gray carpet	625	SF	Southeast corridor near library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
CT1	2'x2' white dot-fissure ceiling tile	34,435	SF	Classrooms, offices, hallways, stairwells, bathrooms	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
CT2	2'x2' white textured ceiling tile	3,700	SF	Foreman hall (114), Polk Bros Hall (115, 107B, 107C, 111, 112	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
CTG	Glue below 2'x2' multi-patterned carpet	5,560	SF	Library, 2nd floor administrative offices	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
DGVT	2'x2' dark gray vinyl floor tile	112	SF	Foreman Hall (114)	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Chicago Virtual Academy **Unit** 66481 **Building ID** 7700
Address 38 Peoria **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												potential for damage		
DW	Drywall walls and ceilings	72,625	SF	Walls throughout the building and partial ceilings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
DWJ	Drywall joint compound on walls and ceilings	72,625	SF	Walls throughout the building, partial ceilings	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
FP	Gray spray-on fireproofing	52,000	SF	Hallways, classrooms, offices, mechanical, utility	ASSUMED	SURFACE	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
GBB	4" green baseboard	45	LF	Fire pump room (100B)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
GBBM	Mastic behind 4" green baseboard	45	LF	Fire pump room (100B)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
GG12T	Gray grout for 12"x12" olive green and gray granite floor tiles	2,367	SF	Main lobby and corridor, north end of Community Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
GG1T	Gray grout for 1"x 1" multi-colored ceramic wall/floor tile	1,600	SF	Restrooms throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
GSPVT	12"x12" gray stone-pattern vinyl floor tile	237	SF	1st floor south corridor, Community Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
LGVT	2'x2' light gray vinyl floor tile	684	SF	Forman Hall (114)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
MFD	Metal fire door insulation	36	EA	Mechanical spaces, exterior exits, hallways, stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
MVI	Mud on fiberglass valve insulation	10	SF	Fire Pump Room (100B)	ASSUMED	TSI	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
OGSPVT	12"x12" olive green stone-pattern vinyl floor tile	733	SF	1st floor south corridor, Community Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
OGVT	2'x2' olive green vinyl floor tile	296	SF	Foreman Hall (114)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
RPC	Red caulk as penetrations	750	SF	At wall/floor/ceiling penetrations in mechanical spaces, janitor's closets, corridors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
RST	Red vinyl stair tread/landing flooring	392	SF	Northeast and south stairwells	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
RSTM	Mastic below red vinyl stair tread/landing	392	SF	Northeast and south	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School Chicago Virtual Academy **Unit** 66481 **Building ID** 7700
Address 38 Peoria **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
	flooring			stairwells								potential for damage		
SAWP	Silver accoustical wall panels	544	SF	Gottlieb Hall and balcony	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
SPVTM	Mastic below 12"x12" stone-pattern vinyl floor tile	2,064	SF	1st floor south corridor, Community Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
TWC	Tan interior window caulk	806	LF	Windows of all rooms on outside perimeter	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
TZ	White terrazzo flooring	9	SF	Shower in bathroom 119	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
VTM	Mastic below 2'x2' vinyl floor tile	26,348	SF	Foreman Hall, corridors, classrooms, offices, storage rooms, closets	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
WFD	Wood fire door insulation	92	EA	Classrooms, offices,practice rooms,performance spaces	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
WG	Glue below wood floor	1,250	SF	Gottlieb Hall Stage	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
WSPVT	12"x12" white stone patterned vinyl floor tile	1,094	SF	1st floor south corridor, Community Room	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Chicago Virtual Academy **Unit** 66481 **Building ID** 7700
Address 38 Peoria **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

Reinspection Date **4/1/2016**
Inspector Name **Robert DeBord**
100-08864 **5/15/2016**
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
BAWP	
BBB	
BBBM	
BDC	
BGMT	
BSF	
BSFM	
BST	
BSTM	
BVT	
CGGH	
CGLH	
CT1	
CT2	
CTG	
DGVT	
DW	
DWJ	
FP	
GBB	
GBBM	
GG12T	
GG1T	
GSPVT	

Chicago Public Schools

School Chicago Virtual Academy **Unit** 66481 **Building ID** 7700
Address 38 Peoria **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates
600 West Van Buren St., Ste 500
Phone: (312) 762-2900 Fax: (312) 782-5145

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
LGVT	
MFD	
MVI	
OGSPVT	
OGVT	
RPC	
RST	
RSTM	
SAWP	
SPVTM	
TWC	
TZ	
VTM	
WFD	
WG	
WSPVT	

Table II

Management Planner's Review

Chicago Public Schools

School Chicago Virtual Academy **Unit** 66481 **Building ID** 7700

Address 38 Peoria Chicago, IL, 60607 **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
BAWP	Brown accoustical wall panels	864	SF	Foreman Hall	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BBB	4" beige baseboard	6,810	LF	Corridors, classrooms, offices, storage rooms, closets with vinyl carpet tile or carpet	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BBBM	Mastic behind 4" beige baseboard	6,810	LF	Corridors, classrooms, offices, storage rooms, closets with vinyl tile or carpet	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BDC	Brown caulk on duct seams	500	LF	At seams of ductwork above ceilings and in mechanical spaces	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
BGMT	Gray grout for 12"x12" green marble ceramic tile	325	SF	Reception desk and wall behind	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BSF	3'x3' black safety flooring	756	SF	kindergarden (133)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BSFM	Mastic below 3'x3' black safety flooring	756	SF	Kindergarden (133)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BST	Beige vinyl stiar tread flooring	32	SF	Room 124	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BSTM	Mastic below beige vinyl stair tread flooring	32	SF	Room 124	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
BVT	2'x2' beige vinyl floor tile	25,256	SF	corridors,classrooms, offices, storage rooms, and closets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CGGH	Glue below brown with black accents carpet	3,832	SF	Gottlieb Hall and balcony	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CGLH	Glue below black/brown/green/gray carpet	625	SF	Southeast corridor near library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
CT1	2'x2' white dot-fissure ceiling tile	34,435	SF	Classrooms, offices, hallways, stairwells, bathrooms	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
CT2	2'x2' white textured ceiling tile	3,700	SF	Foreman hall (114), Polk Bros Hall (115, 107B, 107C, 111, 112	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
CTG	Glue below 2'x2' multi-patterned carpet	5,560	SF	Library, 2nd floor administrative offices	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
DGVT	2'x2' dark gray vinyl floor tile	112	SF	Foreman Hall (114)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
DW	Drywall walls and ceilings	72,625	SF	Walls throughout the building and partial ceilings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
DWJ	Drywall joint compound on walls and ceilings	72,625	SF	Walls throughout the building, partial ceilings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
FP	Gray spray-on fireproofing	52,000	SF	Hallways, classrooms, offices, mechanical, utility	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
GBB	4" green baseboard	45	LF	Fire pump room (100B)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
GBBM	Mastic behind 4" green baseboard	45	LF	Fire pump room (100B)	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
GG12T	Gray grout for 12"x12" olive green and gray granite floor tiles	2,367	SF	Main lobby and corridor, north end of Community Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
GG1T	Gray grout for 1"x 1" multi-colored ceramic wall/floor tile	1,600	SF	Restrooms throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
GSPVT	12"x12" gray stone-pattern vinyl floor tile	237	SF	1st floor south corridor, Community	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Chicago Virtual Academy **Unit** 66481 **Building ID** 7700

Address 38 Peoria Chicago, IL, 60607 **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Room							
LGVT	2'x2' light gray vinyl floor tile	684	SF	Forman Hall (114)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
MFD	Metal fire door insulation	36	EA	Mechanical spaces, exterior exits, hallways, stairwells	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
MVI	Mud on fiberglass valve insulation	10	SF	Fire Pump Room (100B)	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
OGSPVT	12"x12" olive green stone-pattern vinyl floor tile	733	SF	1st floor south corridor, Community Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
OGVT	2'x2' olive green vinyl floor tile	296	SF	Foreman Hall (114)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
RPC	Red caulk as penetrations	750	SF	At wall/floor/ceiling penetrations in mechanical spaces, janitor's closets, corridors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
RST	Red vinyl stair tread/landing flooring	392	SF	Northeast and south stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
RSTM	Mastic below red vinyl stair tread/landing flooring	392	SF	Northeast and south stairwells	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
SAWP	Silver accoustical wall panels	544	SF	Gottlieb Hall and balcony	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
SPVTM	Mastic below 12"x12" stone-pattern vinyl floor tile	2,064	SF	1st floor south corridor, Community Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
TWC	Tan interior window caulk	806	LF	Windows of all rooms on outside perimeter	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
TZ	White terrazzo flooring	9	SF	Shower in bathroom 119	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
VTM	Mastic below 2'x2' vinyl floor tile	26,348	SF	Foreman Hall, corridors, classrooms, offices, storage rooms, closets	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
WFD	Wood fire door insulation	92	EA	Classrooms, offices,practice rooms,performance spaces	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
WG	Glue below wood floor	1,250	SF	Gottlieb Hall Stage	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
WSPVT	12"x12" white stone patterned vinyl floor tile	1,094	SF	1st floor south corridor, Community Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Chicago Virtual Academy **Unit** 66481 **Building ID** 7700

Address 38 Peoria Chicago, IL, 60607 **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Review Date	4/25/2016
Manager Planner Name	Daniel Juneau
100-03613	5/15/2016
Manager IDPH License No/Expiration	

HA Number	Management Comments
BAWP	
BBB	
BBBM	
BDC	
BGMT	
BSF	
BSFM	
BST	
BSTM	
BVT	
CGGH	
CGLH	
CT1	

Chicago Public Schools

School Chicago Virtual Academy **Unit** 66481 **Building ID** 7700

Address 38 Peoria Chicago, IL, 60607 **Region** 03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
CT2	
CTG	
DGVT	
DW	
DWJ	
FP	
GBB	
GBBM	
GG12T	
GG1T	
GSPVT	
LGVT	
MFD	
MVI	
OGSPVT	
OGVT	
RPC	
RST	
RSTM	
SAWP	
SPVTM	
TWC	
TZ	
VTM	
WFD	
WG	
WSPVT	

Chicago Public Schools

School	Chicago Virtual Academy	**Unit**	66481	**Building ID**	7700
Address	38 Peoria	Chicago, IL, 60607		**Region**	03

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) Carnow, Conibear and Associates

600 West Van Buren St., Ste 500

Phone: (312) 762-2900 Fax: (312) 782-5145

Management Planner's Comments Summarized at the End of the Report

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**BAWP**		
MATERIAL DESCRIPTION:	**Brown accoustical wall panels**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Foreman Hall**		
MATERIAL QUANTITY:	**864**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**BAWP**		
MATERIAL DESCRIPTION:	**Brown accoustical wall panels**		
MATERIAL LOCATION:	**Foreman Hall**		
MATERIAL QUANTITY:	**864**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**BBB**		
MATERIAL DESCRIPTION:	**4" beige baseboard**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Corridors, classrooms, offices, storage rooms, closets with vinyl carpet tile or carpet**		
MATERIAL QUANTITY:	**6810**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**BBB**		
MATERIAL DESCRIPTION:	**4" beige baseboard**		
MATERIAL LOCATION:	**Corridors, classrooms, offices, storage rooms, closets with vinyl carpet tile or carpet**		
MATERIAL QUANTITY:	**6810**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**BBBM**		
MATERIAL DESCRIPTION:	**Mastic behind 4" beige baseboard**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Corridors, classrooms, offices, storage rooms, closets with vinyl tile or carpet**		
MATERIAL QUANTITY:	**6810**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**BBBM**		
MATERIAL DESCRIPTION:	**Mastic behind 4'' beige baseboard**		
MATERIAL LOCATION:	**Corridors, classrooms, offices, storage rooms, closets with vinyl tile or carpet**		
MATERIAL QUANTITY:	**6810**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**BDC**		
MATERIAL DESCRIPTION:	**Brown caulk on duct seams**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**At seams of ductwork above ceilings and in mechanical spaces**		
MATERIAL QUANTITY:	**500**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**BDC**		
MATERIAL DESCRIPTION:	**Brown caulk on duct seams**		
MATERIAL LOCATION:	**At seams of ductwork above ceilings and in mechanical spaces**		
MATERIAL QUANTITY:	**500**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**BGMT**		
MATERIAL DESCRIPTION:	**Gray grout for 12"x12" green marble ceramic tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Reception desk and wall behind**		
MATERIAL QUANTITY:	**325**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**BGMT**		
MATERIAL DESCRIPTION:	**Gray grout for 12''x12'' green marble ceramic tile**		
MATERIAL LOCATION:	**Reception desk and wall behind**		
MATERIAL QUANTITY:	**325**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**BSF**		
MATERIAL DESCRIPTION:	**3'x3' black safety flooring**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**kindergarden (133)**		
MATERIAL QUANTITY:	**756**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**BSF**		
MATERIAL DESCRIPTION:	**3'x3' black safety flooring**		
MATERIAL LOCATION:	**kindergarden (133)**		
MATERIAL QUANTITY:	**756**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**BSFM**		
MATERIAL DESCRIPTION:	**Mastic below 3'x3' black safety flooring**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Kindergarden (133)**		
MATERIAL QUANTITY:	**756**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**BSFM**		
MATERIAL DESCRIPTION:	**Mastic below 3'x3' black safety flooring**		
MATERIAL LOCATION:	**Kindergarden (133)**		
MATERIAL QUANTITY:	**756**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**BST**		
MATERIAL DESCRIPTION:	**Beige vinyl stiar tread flooring**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 124**		
MATERIAL QUANTITY:	**32**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**BST**		
MATERIAL DESCRIPTION:	**Beige vinyl stiar tread flooring**		
MATERIAL LOCATION:	**Room 124**		
MATERIAL QUANTITY:	**32**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**BSTM**		
MATERIAL DESCRIPTION:	**Mastic below beige vinyl stair tread flooring**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 124**		
MATERIAL QUANTITY:	**32**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**BSTM**		
MATERIAL DESCRIPTION:	**Mastic below beige vinyl stair tread flooring**		
MATERIAL LOCATION:	**Room 124**		
MATERIAL QUANTITY:	**32**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**BVT**		
MATERIAL DESCRIPTION:	**2'x2' beige vinyl floor tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**corridors,classrooms, offices, storage rooms, and closets**		
MATERIAL QUANTITY:	**25256**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**BVT**		
MATERIAL DESCRIPTION:	**2'x2' beige vinyl floor tile**		
MATERIAL LOCATION:	**corridors,classrooms, offices, storage rooms, and closets**		
MATERIAL QUANTITY:	**25256**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**CGGH**		
MATERIAL DESCRIPTION:	**Glue below brown with black accents carpet**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Gottlieb Hall and balcony**		
MATERIAL QUANTITY:	**3832**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**CGGH**		
MATERIAL DESCRIPTION:	**Glue below brown with black accents carpet**		
MATERIAL LOCATION:	**Gottlieb Hall and balcony**		
MATERIAL QUANTITY:	**3832**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**CGLH**		
MATERIAL DESCRIPTION:	**Glue below black/brown/green/gray carpet**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Southeast corridor near library**		
MATERIAL QUANTITY:	**625**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**CGLH**		
MATERIAL DESCRIPTION:	**Glue below black/brown/green/gray carpet**		
MATERIAL LOCATION:	**Southeast corridor near library**		
MATERIAL QUANTITY:	**625**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**CT1**		
MATERIAL DESCRIPTION:	**2'x2' white dot-fissure ceiling tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Classrooms, offices, hallways, stairwells, bathrooms**		
MATERIAL QUANTITY:	**34435**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**CT1**		
MATERIAL DESCRIPTION:	**2'x2' white dot-fissure ceiling tile**		
MATERIAL LOCATION:	**Classrooms, offices, hallways, stairwells, bathrooms**		
MATERIAL QUANTITY:	**34435**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**CT2**		
MATERIAL DESCRIPTION:	**2'x2' white textured ceiling tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Foreman hall (114), Polk Bros Hall (115, 107B, 107C, 111, 112**		
MATERIAL QUANTITY:	**3700**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**CT2**		
MATERIAL DESCRIPTION:	**2'x2' white textured ceiling tile**		
MATERIAL LOCATION:	**Foreman hall (114), Polk Bros Hall (115, 107B, 107C, 111, 112**		
MATERIAL QUANTITY:	**3700**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**CTG**		
MATERIAL DESCRIPTION:	**Glue below 2'x2' multi-patterned carpet**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Library, 2nd floor administrative offices**		
MATERIAL QUANTITY:	**5560**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**CTG**		
MATERIAL DESCRIPTION:	**Glue below 2'x2' multi-patterned carpet**		
MATERIAL LOCATION:	**Library, 2nd floor administrative offices**		
MATERIAL QUANTITY:	**5560**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**DGVT**		
MATERIAL DESCRIPTION:	**2'x2' dark gray vinyl floor tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Foreman Hall (114)**		
MATERIAL QUANTITY:	**112**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**DGVT**		
MATERIAL DESCRIPTION:	**2'x2' dark gray vinyl floor tile**		
MATERIAL LOCATION:	**Foreman Hall (114)**		
MATERIAL QUANTITY:	**112**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**DW**		
MATERIAL DESCRIPTION:	**Drywall walls and ceilings**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Walls throughout the building and partial ceilings**		
MATERIAL QUANTITY:	**72625**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**DW**		
MATERIAL DESCRIPTION:	**Drywall walls and ceilings**		
MATERIAL LOCATION:	**Walls throughout the building and partial ceilings**		
MATERIAL QUANTITY:	**72625**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**DWJ**		
MATERIAL DESCRIPTION:	**Drywall joint compound on walls and ceilings**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Walls throughout the building, partial ceilings**		
MATERIAL QUANTITY:	**72625**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**DWJ**		
MATERIAL DESCRIPTION:	**Drywall joint compound on walls and ceilings**		
MATERIAL LOCATION:	**Walls throughout the building, partial ceilings**		
MATERIAL QUANTITY:	**72625**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**FP**		
MATERIAL DESCRIPTION:	**Gray spray-on fireproofing**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Damaged friable surfacing ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Hallways, classrooms, offices, mechanical, utility**		
MATERIAL QUANTITY:	**52000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**FP**		
MATERIAL DESCRIPTION:	**Gray spray-on fireproofing**		
MATERIAL LOCATION:	**Hallways, classrooms, offices, mechanical, utility**		
MATERIAL QUANTITY:	**52000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**GBB**		
MATERIAL DESCRIPTION:	**4" green baseboard**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Fire pump room (100B)**		
MATERIAL QUANTITY:	**45**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**GBB**		
MATERIAL DESCRIPTION:	**4" green baseboard**		
MATERIAL LOCATION:	**Fire pump room (100B)**		
MATERIAL QUANTITY:	**45**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**GBBM**		
MATERIAL DESCRIPTION:	**Mastic behind 4" green baseboard**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Fire pump room (100B)**		
MATERIAL QUANTITY:	**45**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**GBBM**		
MATERIAL DESCRIPTION:	**Mastic behind 4'' green baseboard**		
MATERIAL LOCATION:	**Fire pump room (100B)**		
MATERIAL QUANTITY:	**45**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**GG12T**		
MATERIAL DESCRIPTION:	**Gray grout for 12"x12" olive green and gray granite floor tiles**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Main lobby and corridor, north end of Community Room**		
MATERIAL QUANTITY:	**2367**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**GG12T**		
MATERIAL DESCRIPTION:	**Gray grout for 12''x12'' olive green and gray granite floor tiles**		
MATERIAL LOCATION:	**Main lobby and corridor, north end of Community Room**		
MATERIAL QUANTITY:	**2367**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**GG1T**		
MATERIAL DESCRIPTION:	**Gray grout for 1"x 1" multi-colored ceramic wall/floor tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Restrooms throughout**		
MATERIAL QUANTITY:	**1600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**GG1T**		
MATERIAL DESCRIPTION:	**Gray grout for 1''x 1'' multi-colored ceramic wall/floor tile**		
MATERIAL LOCATION:	**Restrooms throughout**		
MATERIAL QUANTITY:	**1600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**GSPVT**		
MATERIAL DESCRIPTION:	**12"x12" gray stone-pattern vinyl floor tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**1st floor south corridor, Community Room**		
MATERIAL QUANTITY:	**237**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**GSPVT**		
MATERIAL DESCRIPTION:	**12''x12'' gray stone-pattern vinyl floor tile**		
MATERIAL LOCATION:	**1st floor south corridor, Community Room**		
MATERIAL QUANTITY:	**237**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**LGVT**		
MATERIAL DESCRIPTION:	**2'x2' light gray vinyl floor tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Forman Hall (114)**		
MATERIAL QUANTITY:	**684**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**LGVT**		
MATERIAL DESCRIPTION:	**2'x2' light gray vinyl floor tile**		
MATERIAL LOCATION:	**Forman Hall (114)**		
MATERIAL QUANTITY:	**684**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**MFD**		
MATERIAL DESCRIPTION:	**Metal fire door insulation**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Mechanical spaces, exterior exits, hallways, stairwells**		
MATERIAL QUANTITY:	**36**	MATERIAL UNITS:	**EA**
DAMAGE QUANTITY:		DAMAGE UNITS:	**EA**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**MFD**		
MATERIAL DESCRIPTION:	**Metal fire door insulation**		
MATERIAL LOCATION:	**Mechanical spaces, exterior exits, hallways, stairwells**		
MATERIAL QUANTITY:	**36**	MATERIAL UNITS:	**EA**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**MVI**		
MATERIAL DESCRIPTION:	**Mud on fiberglass valve insulation**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Damaged or significantly damaged friable thermal system insulating ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Fire Pump Room (100B)**		
MATERIAL QUANTITY:	**10**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**MVI**		
MATERIAL DESCRIPTION:	**Mud on fiberglass valve insulation**		
MATERIAL LOCATION:	**Fire Pump Room (100B)**		
MATERIAL QUANTITY:	**10**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**OGSPVT**		
MATERIAL DESCRIPTION:	**12"x12" olive green stone-pattern vinyl floor tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**1st floor south corridor, Community Room**		
MATERIAL QUANTITY:	**733**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**OGSPVT**		
MATERIAL DESCRIPTION:	**12''x12'' olive green stone-pattern vinyl floor tile**		
MATERIAL LOCATION:	**1st floor south corridor, Community Room**		
MATERIAL QUANTITY:	**733**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**OGVT**		
MATERIAL DESCRIPTION:	**2'x2' olive green vinyl floor tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Foreman Hall (114)**		
MATERIAL QUANTITY:	**296**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**OGVT**		
MATERIAL DESCRIPTION:	**2'x2' olive green vinyl floor tile**		
MATERIAL LOCATION:	**Foreman Hall (114)**		
MATERIAL QUANTITY:	**296**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**RPC**		
MATERIAL DESCRIPTION:	**Red caulk as penetrations**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**At wall/floor/ceiling penetrations in mechanical spaces, janitor's closets, corridors**		
MATERIAL QUANTITY:	**750**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**RPC**		
MATERIAL DESCRIPTION:	**Red caulk as penetrations**		
MATERIAL LOCATION:	**At wall/floor/ceiling penetrations in mechanical spaces, janitor's closets, corridors**		
MATERIAL QUANTITY:	**750**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**RST**		
MATERIAL DESCRIPTION:	**Red vinyl stair tread/landing flooring**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Northeast and south stairwells**		
MATERIAL QUANTITY:	**392**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**RST**		
MATERIAL DESCRIPTION:	**Red vinyl stair tread/landing flooring**		
MATERIAL LOCATION:	**Northeast and south stairwells**		
MATERIAL QUANTITY:	**392**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**RSTM**		
MATERIAL DESCRIPTION:	**Mastic below red vinyl stair tread/landing flooring**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:			
DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Northeast and south stairwells**		
MATERIAL QUANTITY:	**392**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**
COMMENTS:			

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**RSTM**		
MATERIAL DESCRIPTION:	**Mastic below red vinyl stair tread/landing flooring**		
MATERIAL LOCATION:	**Northeast and south stairwells**		
MATERIAL QUANTITY:	**392**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**SAWP**		
MATERIAL DESCRIPTION:	**Silver accoustical wall panels**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Gottlieb Hall and balcony**		
MATERIAL QUANTITY:	**544**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**SAWP**		
MATERIAL DESCRIPTION:	**Silver accoustical wall panels**		
MATERIAL LOCATION:	**Gottlieb Hall and balcony**		
MATERIAL QUANTITY:	**544**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**SPVTM**		
MATERIAL DESCRIPTION:	**Mastic below 12"x12" stone-pattern vinyl floor tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**1st floor south corridor, Community Room**		
MATERIAL QUANTITY:	**2064**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**SPVTM**		
MATERIAL DESCRIPTION:	**Mastic below 12"x12" stone-pattern vinyl floor tile**		
MATERIAL LOCATION:	**1st floor south corridor, Community Room**		
MATERIAL QUANTITY:	**2064**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**TWC**		
MATERIAL DESCRIPTION:	**Tan interior window caulk**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Windows of all rooms on outside perimeter**		
MATERIAL QUANTITY:	**806**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**TWC**		
MATERIAL DESCRIPTION:	**Tan interior window caulk**		
MATERIAL LOCATION:	**Windows of all rooms on outside perimeter**		
MATERIAL QUANTITY:	**806**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**TZ**		
MATERIAL DESCRIPTION:	**White terrazzo flooring**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Shower in bathroom 119**		
MATERIAL QUANTITY:	**9**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**TZ**		
MATERIAL DESCRIPTION:	**White terrazzo flooring**		
MATERIAL LOCATION:	**Shower in bathroom 119**		
MATERIAL QUANTITY:	**9**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**VTM**		
MATERIAL DESCRIPTION:	**Mastic below 2'x2' vinyl floor tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Foreman Hall, corridors, classrooms, offices, storage rooms, closets**		
MATERIAL QUANTITY:	**26348**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**VTM**		
MATERIAL DESCRIPTION:	**Mastic below 2'x2' vinyl floor tile**		
MATERIAL LOCATION:	**Foreman Hall, corridors, classrooms, offices, storage rooms, closets**		
MATERIAL QUANTITY:	**26348**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**WFD**		
MATERIAL DESCRIPTION:	**Wood fire door insulation**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Classrooms, offices,practice rooms,performance spaces**		
MATERIAL QUANTITY:	**92**	MATERIAL UNITS:	**EA**
DAMAGE QUANTITY:		DAMAGE UNITS:	**EA**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**WFD**		
MATERIAL DESCRIPTION:	**Wood fire door insulation**		
MATERIAL LOCATION:	**Classrooms, offices,practice rooms,performance spaces**		
MATERIAL QUANTITY:	**92**	MATERIAL UNITS:	**EA**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**EA**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**WG**		
MATERIAL DESCRIPTION:	**Glue below wood floor**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Gottlieb Hall Stage**		
MATERIAL QUANTITY:	**1250**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**WG**		
MATERIAL DESCRIPTION:	**Glue below wood floor**		
MATERIAL LOCATION:	**Gottlieb Hall Stage**		
MATERIAL QUANTITY:	**1250**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Robert DeBord**		
SCHOOL NAME:	**Chicago Virtual Academy**	INSPECTION DATE:	**4/1/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**WSPVT**		
MATERIAL DESCRIPTION:	**12"x12" white stone patterned vinyl floor tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**1st floor south corridor, Community Room**		
MATERIAL QUANTITY:	**1094**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **04/01/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

Management Planner Review Form


LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66481**	BUIDLING ID:	**7700**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Daniel Juneau**		
SCHOOL NAME:	**Chicago Virtual Academy**	REVIEW DATE:	**4/25/2016**		
ADDRESS:	**38 Peoria**	IDPH LICENSE NO:	**100-08864**		

HOMOGENEOUS AREA:	**WSPVT**		
MATERIAL DESCRIPTION:	**12''x12'' white stone patterned vinyl floor tile**		
MATERIAL LOCATION:	**1st floor south corridor, Community Room**		
MATERIAL QUANTITY:	**1094**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature:  Date: **04/25/2016**

Chicago Public Schools

Carnow, Conibear and Associates

2016 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

2015

OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Robert DeBord

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024160

Kathy DeSalvo, Director

Robert De Bord

Illinois Licensed Asbestos Inspector, Project Manager, and Air Sampling Professional

IDPH

ASBESTOS PROFESSIONAL LICENSE

ID NUMBER	ISSUED	EXPIRES
100 - 08864	5/27/2015	05/15/2016

ROBERT W DE BORD
301 MIAMI ST
PARK FOREST, IL 60466

Environmental Health



ENDORSEMENTS	TC EXPIRES
INSPECTOR	2/13/2016
PROJECT MANAGER	2/12/2016
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois Department of Public Health
This license is valid only when accompanied by a valid training course certificate.

CARNOW CONIBEAR

2016

OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Daniel Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 1/6/2016

Exam Date: 1/6/2016

Expiration Date: 1/6/2017

Certificate Number: MPR1601060038

Kathy DeSalvo

Kathy DeSalvo, Director

Daniel Juneau

Illinois Licensed Asbestos Inspector, Management Planner, Project Manager, and Air Sampling Professional

IDPH

ASBESTOS PROFESSIONAL LICENSE

ID NUMBER	ISSUED	EXPIRES
100 - 03613	3/16/2015	05/15/2016

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

Environmental Health



ENDORSEMENTS	TC EXPIRES
INSPECTOR	12/2/2015
MANAGEMENT PLANNER	1/20/2016
PROJECT MANAGER	12/11/2015
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois Department of Public Health
This license is valid only when accompanied by a valid training course certificate.

CARNOW CONIBEAR

2015

OCCUPATIONAL TRAINING & SUPPLY, INC.

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Daniel Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 12/2/2015

Exam Date: 12/2/2015

Expiration Date: 12/2/2016

Certificate Number: BIR1512024163

Kathy DeSalvo, Director

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed