ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 14-016-2990-002S
SCHOOL NAME: LEGAL PREP CHTR - ACADEMY
ADDRESS OF SCHOOL: 4319 W Washington
CITY: Chicago, IL, 60624

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: _____ ENROLLMENT 174

IDPH INSPECTOR LICENSE NUMBER: _____

IDPH LICENSED INSPECTOR NAME (Please Print): _____

IDPH MP LICENSE NUMBER: _____

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): _____

DESIGNATED PERSON (Please Print): _____ PHONE: _____

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either and exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE–YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

LEGAL PREP CHTR - ACADEMY

4319 W Washington
Chicago, IL, 60624

Unit: 66641
Building ID: 1720

IDPH ID Number: 14-016-2990-002S

REPORT DATE:

Prepared for:
Chicago Public Schools
42 W. Madison Street
Chicago, IL 60602

Prepared by:

, ,

Phone

Fax

DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW

Mr.Eric Culbertson
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2025 Three-Year Reinspections

Dear Mr.Culbertson:

, Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66031 Region: 02 IDPH ID: 14-016-2990-002S

School: LEGAL PREP CHTR - ACADEMY Building ID: 1720

Address: 4319 W Washington

Chicago, IL, 60624

Building Contact: Schmidt, Robert Contact Phone: 6305596094

Current Building Owners: Chicago Public Schools

Reinspection Date:

Review Date:

Inspector: Inspector IDPH License:
Management Planner: Management Planner IDPH License:

If you have any questions or comments, please contact us at

Sincerely,

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date:

RE: LEGAL PREP CHTR - ACADEMY, Unit 66641
4319 W Washington
Chicago, IL, 60624

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2025 asbestos three year re-inspection has been completed at LEGAL PREP CHTR - ACADEMY , following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing building materials have been identified at LEGAL PREP CHTR - ACADEMY, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing building materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact , the designated Local Education Authority's Designated Person at .

Table of Contents

I. School and Inspection Information

II. Executive Summary

III. Methodology

IV. Abatement History

V. Reassessments and Recommendations

VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

Appendix A: Assessment Sheets, Drawings and Photos

Appendix B: Inspector and Management Planner Licenses

Appendix C: Laboratory Accreditations

Appendix D: Laboratory Results

Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: LEGAL PREP CHTR - ACADEMY | Unit: 66031 | Region: 02
Address: 4319 W Washington | Chicago, IL, 60624
IDPH ID: 14-016-2990-002S | Building ID: 1720
Contact: Schmidt, Robert | Phone: 6305596094

2. Description of Facility

Original Construction: 1972 | Additional Construction:
Total Square Footage: 35633 | No of Floors: 3
Current Occupancy: 174

3. LEA Designated Person

Contact: | Phone:
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC:
Contact:
Address
Phone: | Fax:

5. Inspector

Inspector Name:

Signature:
Inspector IDPH license # | Date:
Reinspection Date:

6. Management Planner

Management Planner Name:

Signature:
Management Planner IDPH license # | Date:

7. Review Date:

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Name:

II. EXECUTIVE SUMMARY

was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the LEGAL PREP CHTR - ACADEMY. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.92 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 1720:

001	9" x 9" Red and Brown w/Beige Streaks Floor Tile
017	12" x 12" Pink w/Black Specks Floor Tile
019	12" x 12" Black & White Specks Floor Tile
025	2' x 4' Medium Fissured Ceiling Tile
031	12' X 12" Orange w/Brown Specks Floor Tile
032	12' X 12" Orange w/Brown Specks Floor Tile Mastic
047	Boiler Gaskets
048	Boiler Jacketing
66	2' X 4' White Ceiling Tile

B. The following new homogenous areas have been identified for Building 1720:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

003	12" x 12" Lt. Beige w/Brown & White Streaks FT
004	12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT Mastic
005	12" x 12" Beige, Brown & White Speckles Floor Tile
006	12" x 12" Beige, Brown & White Speckles FT Mastic
007	12 x 12" Brown, Orange & Beige Speckled Floor Tile
009	12"x12" Lt. Brn w/Beige & Brown Speckles FT
011	4" Black Baseboard
012	4" Black Baseboard Adhesive
013	1' x 1' Fissured Ceiling Tile
014	1' x 1' Fissured Ceiling Tile Adhesive
015	Plaster
016	Transite Lab Table
017	12" x 12" Pink w/Black Specks Floor Tile
018	12" x 12" Pink w/Black Specks Floor Tile Mastic
019	12" x 12" Black & White Specks Floor Tile
020	12" x 12" Black & White Specks Floor Tile Mastic
021	12"x12"Lt. Beige,Lt. Brn & Wt. Speckled Floor Tile
022	12"x12"Lt. Beige,Lt. Brn. & Wt. Speckled FT Mastic
024	9" x 9" Red Floor Tile Mastic
025	2' x 4' Medium Fissured Ceiling Tile
026	Carpet Adhesive
027	12' X 12" White w/Black Specks Floor Tile
028	12' X 12" White w/Black Specks Floor Tile Mastic
029	12' X 12" Gray Speckled Floor Tile
030	12' X 12" Gray Speckled Floor Tile Mastic
031	12' X 12" Orange w/Brown Specks Floor Tile
032	12' X 12" Orange w/Brown Specks Floor Tile Mastic
033	12' X 12" Purple w/White Specks Floor Tile
034	12' X 12" Purple w/White Specks Floor Tile Mastic
037	12" x 12" White w/Multi-Colored Specks Floor Tile
038	12" x 12" White w/Multi-Colored Specks FT Mastic
039	12" x 12" Dk. Blue Speckled Floor Tile
040	12" x 12" Dk. Blue Speckled Floor Tile Mastic
043	Paperwrap Pipe Insulation
044	Fittings on Paperwrap Insulation
045	Mag Pipe Insulation

046	Fittings on Mag Pipe Insulation
048	Boiler Jacketing
050	Drywall Compound
052	Fire Door Insulation
49	Incinerator Insulation
53	12"X12"Brown w/Dark Brown Floor Tile
54	12"X12"Brown w/Dark Brown Floor Tile Mastic
55	Black, Brown & White Terrazzo
56	Tan & Red Terrazzo
57	Light Brown Carpet Mastic
58	12 X 12 Blue Floor Tile
59	12 X 12 Blue Floor Tile Mastic
60	12 X 12 Light Gray Floor Tile
61	12 X 12 Light Gray Floor Tile Mastic
62	12 X 12 Dark Grey Floor Tile
63	12 X 12 Dark Grey Floor Tile Mastic
64	12 X 12 Beige Floor Tile
65	12 X 12 Beige Floor Tile Mastic
66	2' X 4' White Ceiling Tile
67	2' X 4' White Ceiling Tile Adhesive
68	4" Grey Baseboard
69	4" Grey Baseboard Adhesive

The following areas were deemed to be inaccessible:

004	12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT Mastic
006	12" x 12" Beige, Brown & White Speckles FT Mastic
012	4" Black Baseboard Adhesive
014	1' x 1' Fissured Ceiling Tile Adhesive
018	12" x 12" Pink w/Black Specks Floor Tile Mastic
020	12" x 12" Black & White Specks Floor Tile Mastic
022	12"x12"Lt. Beige,Lt. Brn. & Wt. Speckled FT Mastic
028	12' X 12" White w/Black Specks Floor Tile Mastic
030	12' X 12" Gray Speckled Floor Tile Mastic
032	12' X 12" Orange w/Brown Specks Floor Tile Mastic
034	12' X 12" Purple w/White Specks Floor Tile Mastic
038	12" x 12" White w/Multi-Colored Specks FT Mastic
040	12" x 12" Dk. Blue Speckled Floor Tile Mastic
052	Fire Door Insulation
49	Incinerator Insulation
57	Light Brown Carpet Mastic
59	12 X 12 Blue Floor Tile Mastic

61	12 X 12 Light Gray Floor Tile Mastic
63	12 X 12 Dark Grey Floor Tile Mastic
65	12 X 12 Beige Floor Tile Mastic
67	2' X 4' White Ceiling Tile Adhesive
69	4" Grey Baseboard Adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by , IDPH License # . The Management Plan was updated by , IDPH License # . Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard Ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The LEGAL PREP CHTR - ACADEMY Building 1720 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable ACBM. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inserted in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I

Inspector's Reinspection Findings

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720
Address 4319 W Washington **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
001	9" x 9" Red and Brown w/Beige Streaks Floor Tile	5,700	SF	1st, 2nd and 3rd Floor Corridors, Entrance Landing, 112A, 120A, 321A	CHR	MISC	N	DIST	150		Yes	ACBM with the potential for damage	2	LOW
002	9" x 9" Red and Brown w/Beige Streaks FT Mastic	5,700	SF	1st, 2nd and 3rd Floor Corridors, Entrance Landing, 112A, 120A, 321A	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
003	12" x 12" Lt. Beige w/Brown & White Streaks FT	2,400	SF	Rooms 113, 118, 120, 111, 113, 110, 103	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
004	12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT Mastic	2,400	SF	Rooms 113, 118 & 120	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
005	12" x 12" Beige, Brown & White Speckles Floor Tile	850	SF	Room 116, 102, 1st Floor Girl's Bathroom Vestibule, 1st Floor Boy's Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
006	12" x 12" Beige, Brown & White Speckles FT Mastic	850	SF	Room 116, 102, 1st Floor Girl's Bathroom Vestibule, 1st floor Boy's Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
007	12 x 12" Brown, Orange & Beige Speckled Floor Tile	5,600	SF	Rooms 114, 119, 1st - 3rd W. Stair Landings, 119A, 216, 215, 213, 327, 325, 323 & 326	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
008	12 x 12" Brown, Orange & Beige Speckled FT Mastic	5,600	SF	Rooms 114, 119, 1st - 3rd W. Stair Landings, 119A, 216, 215, 213, 327, 325, 323 & 326	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
009	12"x12" Lt. Brn w/Beige & Brown Speckles FT	260	SF	Room 115, 108 Closet	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
010	12"x12" Lt.Brn w/Beige & Brown Speckles FT Mastic	260	SF	Room 115, 108 Closet	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
011	4" Black Baseboard	900	LF	1st and 2nd Floor Corridors, Room 110, Janitor Closet (1st Fl), 1st Floor unisex Toilet and 1st Floor Boy's Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
012	4" Black Baseboard Adhesive	900	LF	1st and 2nd Floor	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720
Address 4319 W Washington **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Corridors, Room 110, Janitor Closet (1st Fl), 1st Floor unisex Toilet and 1st Floor Boy's Bathroom								potential for damage		
013	1' x 1' Fissured Ceiling Tile	4,000	SF	Rooms 111, 113, 119, 120, 330 & 329	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
014	1' x 1' Fissured Ceiling Tile Adhesive	4,000	SF	Rooms 111, 113, 119, 120, 330 & 329	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
015	Plaster	101,000	SF	Throughout	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
016	Transite Lab Table			Room 216	ASSUMED	MISC								Low
017	12" x 12" Pink w/Black Specks Floor Tile	1,600	SF	Rooms 001 & 111, 100, 101, 011	ASSUMED	MISC	N	DIST	10		Yes	ACBM with the potential for damage	2	LOW
018	12" x 12" Pink w/Black Specks Floor Tile Mastic	1,600	SF	Rooms 001 & 111, 100, 101, 011	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
019	12" x 12" Black & White Specks Floor Tile	1,800	SF	Rooms 001 & 111, 100, 101, 011	ASSUMED	MISC	N	DIST	10		Yes	ACBM with the potential for damage	2	LOW
020	12" x 12" Black & White Specks Floor Tile Mastic	1,800	SF	Rooms 001 & 111, 100, 101, 011	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
021	12"x12"Lt. Beige,Lt. Brn & Wt. Speckled Floor Tile	1,600	SF	Rooms 001, 111 & 112, 100, 101, 001	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
022	12"x12"Lt. Beige,Lt. Brn. & Wt. Speckled FT Mastic	1,600	SF	Rooms 001, 111 & 112, 100, 101, 011	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
023	9" x 9" Red Floor Tile			Rooms 219, 220, 218, 216, 214, 218, 212 A&B, 311, 211A, 213, 215 and the 2nd Floor Corridor	CHR	MISC		None						
024	9" x 9" Red Floor Tile Mastic			Rooms 219, 220, 218, 216, 214, 218, 212 A&B, 311, 211A, 213, 215 and the 2nd Floor Corridor	ASSUMED	MISC								
025	2' x 4' Medium Fissured Ceiling Tile	6,500	SF	Rooms 219, 220, 218, 216, 214, 212 A&B, 211, 211A, 213, 215,1st & 2nd floor corridors,	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720
Address 4319 W Washington **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room 214, 210, 208, 204, 202, 202A, 202B, 207, 203, 200, 201, 108, 107, 104, 103, 100, 101										
026	Carpet Adhesive	3,400	SF	Rooms 220, 219, 212B, 211A, 211 and Basement 004, 212, 214, 202B, 201, 150	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
027	12' X 12" White w/Black Specks Floor Tile	200	SF	Rooms 212A & 212 Closet, 202A, 202B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
028	12' X 12" White w/Black Specks Floor Tile Mastic	200	SF	Rooms 212A & 212 Closet, 202A, 202B	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
029	12' X 12" Gray Speckled Floor Tile	1,800	SF	Rooms 212 & 214, 202, 204, 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
030	12' X 12" Gray Speckled Floor Tile Mastic	1,800	SF	Rooms 212 & 214, 204, 204, 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
031	12' X 12" Orange w/Brown Specks Floor Tile	2,350	SF	Room 218, 207, SE, SW Landings	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
032	12' X 12" Orange w/Brown Specks Floor Tile Mastic	2,350	SF	Room 218, 207, SE, SW Landings	ASSUMED	MISC	N	NONE	0		Yes	ACBM with the potential for damage		LOW
033	12' X 12" Purple w/White Specks Floor Tile	500	SF	Basement West Landing, Room 203, 208, 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
034	12' X 12" Purple w/White Specks Floor Tile Mastic	500	SF	Basement West Landing, Room 203, 208, 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
035	9" x 9" Black Floor Tile			Room 004	CHR	MISC		None						Low
036	9" x 9" Black Floor Tile Mastic			Room 004	CHR	MISC		None						
037	12" x 12" White w/Multi-Colored Specks Floor Tile	2,400	SF	Basement Cafeteria, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
038	12" x 12" White w/Multi-Colored Specks FT Mastic	2,400	SF	Basement Cafeteria, Kitchen	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
039	12" x 12" Dk. Blue Speckled Floor Tile	2,700	SF	Basement Cafeteria, Kitchen, Room 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
040	12" x 12" Dk. Blue Speckled Floor Tile Mastic	2,400	SF	Basement Cafeteria, Kitchen, Room 210	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
041	Aircell Pipe Insulation	500	LF	Throughout and Boiler Room	CHR	TSI	Y	DIST	20		No	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
042	Fittings on Aircell Pipe Insulation	200	LF	Throughout	CHR	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable		LOW

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720
Address 4319 W Washington **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
												suspect ACBM		
043	Paperwrap Pipe Insulation	400	LF	Throughout Basement	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
044	Fittings on Paperwrap Insulation	50	LF	Throughout	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
045	Mag Pipe Insulation	120	LF	Concealed in Chases, 2nd Floor Room 212	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
046	Fittings on Mag Pipe Insulation	120	LF	Concealed in Chases, 2nd Floor Room 212	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
047	Boiler Gaskets	150	LF	Basement Room 008A	CHR	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
048	Boiler Jacketing	200	LF	Basement Room 008A	ASSUMED	TSI	Y	LOC	3		Yes	Damaged or significantly damaged friable thermal system insulating ACBM	3	LOW
050	Drywall Compound	12,000	SF	Throughout	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
051	Floor Leveling Compound	1,800	SF	1st Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
052	Fire Door Insulation	48	SF	2 Doors - Basement Boiler Room	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
49	Incinerator Insulation	120	SF	Boiler Room 008	ASSUMED	TSI	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
53	12"X12"Brown w/Dark Brown Floor Tile	800	SF	Room 004	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	12"X12"Brown w/Dark Brown Floor Tile Mastic	800	SF	Room 004	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
55	Black, Brown & White Terrazzo	1,150	SF	2nd floor South Boys, Girls & Teachers Bathrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
56	Tan & Red Terrazzo	1,620	SF	1st floor South Boys, Girls, and Teachers Bathroom	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	Light Brown Carpet Mastic	1,296	SF	Room 010	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	12 X 12 Blue Floor Tile	1,125	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720
Address 4319 W Washington **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
59	12 X 12 Blue Floor Tile Mastic	1,125	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	12 X 12 Light Gray Floor Tile	1,125	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	12 X 12 Light Gray Floor Tile Mastic	1,125	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	12 X 12 Dark Grey Floor Tile	1,125	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	12 X 12 Dark Grey Floor Tile Mastic	1,125	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	12 X 12 Beige Floor Tile	1,125	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	12 X 12 Beige Floor Tile Mastic	1,125	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	2' X 4' White Ceiling Tile	1,200	SF	Cafeteria	ASSUMED	MISC	Y	NONE	0		Yes	Any remaining friable ACBM or friable suspect ACBM		LOW
67	2' X 4' White Ceiling Tile Adhesive	1,200	SF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	4" Grey Baseboard	400	LF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	4" Grey Baseboard Adhesive	400	LF	Cafeteria	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720
Address 4319 W Washington **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

Reinspection Date
Inspector Name

Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
001	
002	
003	
004	
005	
006	
007	
008	
009	
010	
011	
012	
013	
014	
015	
016	
017	
018	
019	
020	
021	
022	
023	
024	

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720
Address 4319 W Washington **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
025	
026	
027	
028	
029	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
050	
051	
052	
49	
53	

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720
Address 4319 W Washington **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC)

Phone: Fax:

Inspector's Comments are Summarized at the End of the Report

HA Number:	Inspector Comments:
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	

Table II

Management Planner's Review

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720

Address 4319 W Washington Chicago, IL, 60624 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone: Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
001	9" x 9" Red and Brown w/Beige Streaks Floor Tile	5,700	SF	1st, 2nd and 3rd Floor Corridors, Entrance Landing, 112A, 120A, 321A	Chrysotile	MISC	No	150	SF	6 ACBM with the potential for damage	
002	9" x 9" Red and Brown w/Beige Streaks FT Mastic	5,700	SF	1st, 2nd and 3rd Floor Corridors, Entrance Landing, 112A, 120A, 321A	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
003	12" x 12" Lt. Beige w/Brown & White Streaks FT	2,400	SF	Rooms 113, 118, 120, 111, 113, 110, 103	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
004	12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT Mastic	2,400	SF	Rooms 113, 118 & 120	Assumed	MISC	No		SF	6 ACBM with the potential for damage	
005	12" x 12" Beige, Brown & White Speckles Floor Tile	850	SF	Room 116, 102, 1st Floor Girl's Bathroom Vestibule, 1st Floor Boy's Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
006	12" x 12" Beige, Brown & White Speckles FT Mastic	850	SF	Room 116, 102, 1st Floor Girl's Bathroom Vestibule, 1st floor Boy's Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
007	12 x 12" Brown, Orange & Beige Speckled Floor Tile	5,600	SF	Rooms 114, 119, 1st - 3rd W. Stair Landings, 119A, 216, 215, 213, 327, 325, 323 & 326	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
008	12 x 12" Brown, Orange & Beige Speckled FT Mastic	5,600	SF	Rooms 114, 119, 1st - 3rd W. Stair Landings, 119A, 216, 215, 213, 327, 325, 323 & 326	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
009	12"x12" Lt. Brn w/Beige & Brown Speckles FT	260	SF	Room 115, 108 Closet	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
010	12"x12" Lt.Brn w/Beige & Brown Speckles FT Mastic	260	SF	Room 115, 108 Closet	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
011	4" Black Baseboard	900	LF	1st and 2nd Floor Corridors, Room 110, Janitor Closet (1st Fl), 1st Floor unisex Toilet and 1st Floor Boy's Bathroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
012	4" Black Baseboard Adhesive	900	LF	1st and 2nd Floor Corridors, Room 110, Janitor Closet (1st Fl), 1st Floor unisex Toilet and 1st Floor Boy's Bathroom	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
013	1' x 1' Fissured Ceiling Tile	4,000	SF	Rooms 111, 113, 119, 120, 330 & 329	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
014	1' x 1' Fissured Ceiling Tile Adhesive	4,000	SF	Rooms 111, 113, 119, 120, 330 & 329	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
015	Plaster	101,000	SF	Throughout	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
016	Transite Lab Table			Room 216	Assumed	MISC					

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720

Address 4319 W Washington Chicago, IL, 60624 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone: Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
017	12" x 12" Pink w/Black Specks Floor Tile	1,600	SF	Rooms 001 & 111, 100, 101, 011	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	
018	12" x 12" Pink w/Black Specks Floor Tile Mastic	1,600	SF	Rooms 001 & 111, 100, 101, 011	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
019	12" x 12" Black & White Specks Floor Tile	1,800	SF	Rooms 001 & 111, 100, 101, 011	Assumed	MISC	No	10	SF	6 ACBM with the potential for damage	
020	12" x 12" Black & White Specks Floor Tile Mastic	1,800	SF	Rooms 001 & 111, 100, 101, 011	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
021	12"x12"Lt. Beige,Lt. Brn & Wt. Speckled Floor Tile	1,600	SF	Rooms 001, 111 & 112, 100, 101, 001	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
022	12"x12"Lt. Beige,Lt. Brn. & Wt. Speckled FT Mastic	1,600	SF	Rooms 001, 111 & 112, 100, 101, 011	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
023	9" x 9" Red Floor Tile			Rooms 219, 220, 218, 216, 214, 218, 212 A&B, 311, 211A, 213, 215 and the 2nd Floor Corridor	Chrysotile	MISC					
024	9" x 9" Red Floor Tile Mastic			Rooms 219, 220, 218, 216, 214, 218, 212 A&B, 311, 211A, 213, 215 and the 2nd Floor Corridor	Assumed	MISC					
025	2' x 4' Medium Fissured Ceiling Tile	6,500	SF	Rooms 219, 220, 218, 216, 214, 212 A&B, 211, 211A, 213, 215,1st & 2nd floor corridors, Room 214, 210, 208, 204, 202, 202A, 202B, 207, 203, 200, 201, 108, 107, 104, 103, 100, 101	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
026	Carpet Adhesive	3,400	SF	Rooms 220, 219, 212B, 211A, 211 and Basement 004, 212, 214, 202B, 201, 150	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
027	12' X 12" White w/Black Specks Floor Tile	200	SF	Rooms 212A & 212 Closet, 202A, 202B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
028	12' X 12" White w/Black Specks Floor Tile Mastic	200	SF	Rooms 212A & 212 Closet, 202A, 202B	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
029	12' X 12" Gray Speckled Floor Tile	1,800	SF	Rooms 212 & 214, 202, 204, 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
030	12' X 12" Gray Speckled Floor Tile Mastic	1,800	SF	Rooms 212 & 214, 204, 204, 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
031	12' X 12" Orange w/Brown Specks Floor Tile	2,350	SF	Room 218, 207, SE, SW Landings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
032	12' X 12" Orange w/Brown Specks Floor Tile Mastic	2,350	SF	Room 218, 207, SE, SW Landings	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
033	12' X 12" Purple w/White Specks Floor Tile	500	SF	Basement West Landing, Room 203, 208, 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
034	12' X 12" Purple w/White Specks Floor Tile Mastic	500	SF	Basement West Landing, Room 203, 208, 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
035	9" x 9" Black Floor Tile			Room 004	Chrysotile	MISC					
036	9" x 9" Black Floor Tile Mastic			Room 004	Chrysotile	MISC					
037	12" x 12" White w/Multi-Colored Specks Floor Tile	2,400	SF	Basement Cafeteria, Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
038	12" x 12" White w/Multi-Colored Specks FT Mastic	2,400	SF	Basement Cafeteria, Kitchen	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
039	12" x 12" Dk. Blue Speckled Floor Tile	2,700	SF	Basement Cafeteria, Kitchen, Room	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720

Address 4319 W Washington Chicago, IL, 60624 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone: Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				210							
040	12" x 12" Dk. Blue Speckled Floor Tile Mastic	2,400	SF	Basement Cafeteria, Kitchen, Room 210	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
041	Aircell Pipe Insulation	500	LF	Throughout and Boiler Room	Chrysotile	TSI	Yes	20	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	
042	Fittings on Aircell Pipe Insulation	200	LF	Throughout	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
043	Paperwrap Pipe Insulation	400	LF	Throughout Basement	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
044	Fittings on Paperwrap Insulation	50	LF	Throughout	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
045	Mag Pipe Insulation	120	LF	Concealed in Chases, 2nd Floor Room 212	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
046	Fittings on Mag Pipe Insulation	120	LF	Concealed in Chases, 2nd Floor Room 212	Assumed	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
047	Boiler Gaskets	150	LF	Basement Room 008A	Chrysotile	MISC	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	
048	Boiler Jacketing	200	LF	Basement Room 008A	Assumed	TSI	Yes	3	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	
050	Drywall Compound	12,000	SF	Throughout	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
051	Floor Leveling Compound	1,800	SF	1st Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	
052	Fire Door Insulation	48	SF	2 Doors - Basement Boiler Room	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
49	Incinerator Insulation	120	SF	Boiler Room 008	Assumed	TSI	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
53	12"X12"Brown w/Dark Brown Floor Tile	800	SF	Room 004	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
54	12"X12"Brown w/Dark Brown Floor Tile Mastic	800	SF	Room 004	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
55	Black, Brown & White Terrazzo	1,150	SF	2nd floor South Boys, Girls & Teachers Bathrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
56	Tan & Red Terrazzo	1,620	SF	1st floor South Boys, Girls, and Teachers Bathroom	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
57	Light Brown Carpet Mastic	1,296	SF	Room 010	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
58	12 X 12 Blue Floor Tile	1,125	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
59	12 X 12 Blue Floor Tile Mastic	1,125	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
60	12 X 12 Light Gray Floor Tile	1,125	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720

Address 4319 W Washington Chicago, IL, 60624 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone: Fax:

Management Planner's Comments Summarized at the End of the Report

HA Num	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
61	12 X 12 Light Gray Floor Tile Mastic	1,125	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
62	12 X 12 Dark Grey Floor Tile	1,125	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
63	12 X 12 Dark Grey Floor Tile Mastic	1,125	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
64	12 X 12 Beige Floor Tile	1,125	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
65	12 X 12 Beige Floor Tile Mastic	1,125	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
66	2' X 4' White Ceiling Tile	1,200	SF	Cafeteria	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	
67	2' X 4' White Ceiling Tile Adhesive	1,200	SF	Cafeteria	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	
68	4" Grey Baseboard	400	LF	Cafeteria	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	
69	4" Grey Baseboard Adhesive	400	LF	Cafeteria	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720

Address 4319 W Washington Chicago, IL, 60624 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone: Fax:

Management Planner's Comments Summarized at the End of the Report

Review Date	
Manager Planner Name	
Manager IDPH License No/Expiration	

HA Number	Management Comments
001	
002	
003	
004	
005	
006	
007	
008	
009	
010	
011	
012	
013	
014	
015	
016	
017	
018	
019	
020	
021	
022	
023	

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720

Address 4319 W Washington Chicago, IL, 60624 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone: Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
024	
025	
026	
027	
028	
029	
030	
031	
032	
033	
034	
035	
036	
037	
038	
039	
040	
041	
042	
043	
044	
045	
046	
047	
048	
050	

Chicago Public Schools

School LEGAL PREP CHTR - ACADEMY **Unit** 66031 **Building ID** 1720

Address 4319 W Washington Chicago, IL, 60624 **Region** 02

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC)

Phone: Fax:

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
051	
052	
49	
53	
54	
55	
56	
57	
58	
59	
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	

APPENDIX A

Assessment Sheets, Drawings and Photos

Chicago Public Schools

2025 AHERA REINSPECTION

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**001**		
MATERIAL DESCRIPTION:	**9" x 9" Red and Brown w/Beige Streaks Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:	**Delamination** **Physical Damage**		
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Chrysotile**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:	**Delamination** **Physical Damage**		
DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**1st, 2nd and 3rd Floor Corridors, Entrance Landing, 112A, 120A, 321A**		
MATERIAL QUANTITY:	**5700**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**
COMMENTS:			

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**001**		
MATERIAL DESCRIPTION:	**9" x 9" Red and Brown w/Beige Streaks Floor Tile**		
MATERIAL LOCATION:	**1st, 2nd and 3rd Floor Corridors, Entrance Landing, 112A, 120A, 321A**		
MATERIAL QUANTITY:	**5700**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**150**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**002**		
MATERIAL DESCRIPTION:	**9" x 9" Red and Brown w/Beige Streaks FT Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Chrysotile**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**1st, 2nd and 3rd Floor Corridors, Entrance Landing, 112A, 120A, 321A**		
MATERIAL QUANTITY:	**5700**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**002**		
MATERIAL DESCRIPTION:	**9" x 9" Red and Brown w/Beige Streaks FT Mastic**		
MATERIAL LOCATION:	**1st, 2nd and 3rd Floor Corridors, Entrance Landing, 112A, 120A, 321A**		
MATERIAL QUANTITY:	**5700**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**003**		
MATERIAL DESCRIPTION:	**12" x 12" Lt. Beige w/Brown & White Streaks FT**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 113, 118, 120, 111, 113, 110, 103**		
MATERIAL QUANTITY:	**2400**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**003**		
MATERIAL DESCRIPTION:	**12" x 12" Lt. Beige w/Brown & White Streaks FT**		
MATERIAL LOCATION:	**Rooms 113, 118, 120, 111, 113, 110, 103**		
MATERIAL QUANTITY:	**2400**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**004**		
MATERIAL DESCRIPTION:	**12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 113, 118 & 120**		
MATERIAL QUANTITY:	**2400**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**004**		
MATERIAL DESCRIPTION:	**12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT Mastic**		
MATERIAL LOCATION:	**Rooms 113, 118 & 120**		
MATERIAL QUANTITY:	**2400**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**005**		
MATERIAL DESCRIPTION:	**12" x 12" Beige, Brown & White Speckles Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 116, 102, 1st Floor Girl's Bathroom Vestibule, 1st Floor Boy's Bathroom**		
MATERIAL QUANTITY:	**850**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**005**		
MATERIAL DESCRIPTION:	**12" x 12" Beige, Brown & White Speckles Floor Tile**		
MATERIAL LOCATION:	**Room 116, 102, 1st Floor Girl's Bathroom Vestibule, 1st Floor Boy's Bathroom**		
MATERIAL QUANTITY:	**850**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**006**		
MATERIAL DESCRIPTION:	**12" x 12" Beige, Brown & White Speckles FT Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 116, 102, 1st Floor Girl's Bathroom Vestibule, 1st floor Boy's Bathroom**		
MATERIAL QUANTITY:	**850**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**006**		
MATERIAL DESCRIPTION:	**12" x 12" Beige, Brown & White Speckles FT Mastic**		
MATERIAL LOCATION:	**Room 116, 102, 1st Floor Girl's Bathroom Vestibule, 1st floor Boy's Bathroom**		
MATERIAL QUANTITY:	**850**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**007**		
MATERIAL DESCRIPTION:	**12 x 12" Brown, Orange & Beige Speckled Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 114, 119, 1st - 3rd W. Stair Landings, 119A, 216, 215, 213, 327, 325, 323 & 326**		
MATERIAL QUANTITY:	**5600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**007**		
MATERIAL DESCRIPTION:	**12 x 12" Brown, Orange & Beige Speckled Floor Tile**		
MATERIAL LOCATION:	**Rooms 114, 119, 1st - 3rd W. Stair Landings, 119A, 216, 215, 213, 327, 325, 323 & 326**		
MATERIAL QUANTITY:	**5600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**008**		
MATERIAL DESCRIPTION:	**12 x 12" Brown, Orange & Beige Speckled FT Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Chrysotile**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 114, 119, 1st - 3rd W. Stair Landings, 119A, 216, 215, 213, 327, 325, 323 & 326**		
MATERIAL QUANTITY:	**5600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**008**		
MATERIAL DESCRIPTION:	**12 x 12" Brown, Orange & Beige Speckled FT Mastic**		
MATERIAL LOCATION:	**Rooms 114, 119, 1st - 3rd W. Stair Landings, 119A, 216, 215, 213, 327, 325, 323 & 326**		
MATERIAL QUANTITY:	**5600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**009**		
MATERIAL DESCRIPTION:	**12"x12" Lt. Brn w/Beige & Brown Speckles FT**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 115, 108 Closet**		
MATERIAL QUANTITY:	**260**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**009**		
MATERIAL DESCRIPTION:	**12"x12" Lt. Brn w/Beige & Brown Speckles FT**		
MATERIAL LOCATION:	**Room 115, 108 Closet**		
MATERIAL QUANTITY:	**260**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**010**		
MATERIAL DESCRIPTION:	**12"x12" Lt.Brn w/Beige & Brown Speckles FT Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Chrysotile**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:			
DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 115, 108 Closet**		
MATERIAL QUANTITY:	**260**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**
COMMENTS:			

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**010**		
MATERIAL DESCRIPTION:	**12"x12" Lt.Brn w/Beige & Brown Speckles FT Mastic**		
MATERIAL LOCATION:	**Room 115, 108 Closet**		
MATERIAL QUANTITY:	**260**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**011**		
MATERIAL DESCRIPTION:	**4" Black Baseboard**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**1st and 2nd Floor Corridors, Room 110, Janitor Closet (1st Fl), 1st Floor unisex Toilet and 1st Floor Boy's Bathroom**		
MATERIAL QUANTITY:	**900**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**011**		
MATERIAL DESCRIPTION:	**4" Black Baseboard**		
MATERIAL LOCATION:	**1st and 2nd Floor Corridors, Room 110, Janitor Closet (1st Fl), 1st Floor unisex Toilet and 1st Floor Boy's Bathroom**		
MATERIAL QUANTITY:	**900**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**012**		
MATERIAL DESCRIPTION:	**4" Black Baseboard Adhesive**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**1st and 2nd Floor Corridors, Room 110, Janitor Closet (1st Fl), 1st Floor unisex Toilet and 1st Floor Boy's Bathroom**		
MATERIAL QUANTITY:	**900**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**012**		
MATERIAL DESCRIPTION:	**4" Black Baseboard Adhesive**		
MATERIAL LOCATION:	**1st and 2nd Floor Corridors, Room 110, Janitor Closet (1st Fl), 1st Floor unisex Toilet and 1st Floor Boy's Bathroom**		
MATERIAL QUANTITY:	**900**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**013**		
MATERIAL DESCRIPTION:	**1' x 1' Fissured Ceiling Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 111, 113, 119, 120, 330 & 329**		
MATERIAL QUANTITY:	**4000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**013**		
MATERIAL DESCRIPTION:	**1' x 1' Fissured Ceiling Tile**		
MATERIAL LOCATION:	**Rooms 111, 113, 119, 120, 330 & 329**		
MATERIAL QUANTITY:	**4000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**014**		
MATERIAL DESCRIPTION:	**1' x 1' Fissured Ceiling Tile Adhesive**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 111, 113, 119, 120, 330 & 329**		
MATERIAL QUANTITY:	**4000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**014**		
MATERIAL DESCRIPTION:	**1' x 1' Fissured Ceiling Tile Adhesive**		
MATERIAL LOCATION:	**Rooms 111, 113, 119, 120, 330 & 329**		
MATERIAL QUANTITY:	**4000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**015**		
MATERIAL DESCRIPTION:	**Plaster**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Throughout**		
MATERIAL QUANTITY:	**101000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**015**		
MATERIAL DESCRIPTION:	**Plaster**		
MATERIAL LOCATION:	**Throughout**		
MATERIAL QUANTITY:	**101000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**016**		
MATERIAL DESCRIPTION:	**Transite Lab Table**		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 216**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**016**		
MATERIAL DESCRIPTION:	**Transite Lab Table**		
MATERIAL LOCATION:	**Room 216**		
MATERIAL QUANTITY:		MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**017**		
MATERIAL DESCRIPTION:	**12" x 12" Pink w/Black Specks Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:	**Delamination** **Physical Damage**		
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:	**Delamination** **Physical Damage**		
DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 001 & 111, 100, 101, 011**		
MATERIAL QUANTITY:	**1600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**
COMMENTS:			

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**017**		
MATERIAL DESCRIPTION:	**12" x 12" Pink w/Black Specks Floor Tile**		
MATERIAL LOCATION:	**Rooms 001 & 111, 100, 101, 011**		
MATERIAL QUANTITY:	**1600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**10**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**018**		
MATERIAL DESCRIPTION:	**12" x 12" Pink w/Black Specks Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 001 & 111, 100, 101, 011**		
MATERIAL QUANTITY:	**1600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**018**		
MATERIAL DESCRIPTION:	**12" x 12" Pink w/Black Specks Floor Tile Mastic**		
MATERIAL LOCATION:	**Rooms 001 & 111, 100, 101, 011**		
MATERIAL QUANTITY:	**1600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**019**		
MATERIAL DESCRIPTION:	**12" x 12" Black & White Specks Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:	**Delamination** **Physical Damage**		
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:	**Delamination** **Physical Damage**		
DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 001 & 111, 100, 101, 011**		
MATERIAL QUANTITY:	**1800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**
COMMENTS:			

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**019**		
MATERIAL DESCRIPTION:	**12" x 12" Black & White Specks Floor Tile**		
MATERIAL LOCATION:	**Rooms 001 & 111, 100, 101, 011**		
MATERIAL QUANTITY:	**1800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**10**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**020**		
MATERIAL DESCRIPTION:	**12" x 12" Black & White Specks Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:			
DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 001 & 111, 100, 101, 011**		
MATERIAL QUANTITY:	**1800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**
COMMENTS:			

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**020**		
MATERIAL DESCRIPTION:	**12" x 12" Black & White Specks Floor Tile Mastic**		
MATERIAL LOCATION:	**Rooms 001 & 111, 100, 101, 011**		
MATERIAL QUANTITY:	**1800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**021**		
MATERIAL DESCRIPTION:	**12"x12"Lt. Beige,Lt. Brn & Wt. Speckled Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 001, 111 & 112, 100, 101, 001**		
MATERIAL QUANTITY:	**1600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**021**		
MATERIAL DESCRIPTION:	**12"x12"Lt. Beige,Lt. Brn & Wt. Speckled Floor Tile**		
MATERIAL LOCATION:	**Rooms 001, 111 & 112, 100, 101, 001**		
MATERIAL QUANTITY:	**1600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**022**		
MATERIAL DESCRIPTION:	**12"x12"Lt. Beige,Lt. Brn. & Wt. Speckled FT Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:			
DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 001, 111 & 112, 100, 101, 011**		
MATERIAL QUANTITY:	**1600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**
COMMENTS:			

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**022**		
MATERIAL DESCRIPTION:	**12"x12"Lt. Beige,Lt. Brn. & Wt. Speckled FT Mastic**		
MATERIAL LOCATION:	**Rooms 001, 111 & 112, 100, 101, 011**		
MATERIAL QUANTITY:	**1600**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **023**

MATERIAL DESCRIPTION: **9" x 9" Red Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 219, 220, 218, 216, 214, 218, 212 A&B, 311, 211A, 213, 215 and the 2nd Floor Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**023**
MATERIAL DESCRIPTION:	**9" x 9" Red Floor Tile**
MATERIAL LOCATION:	**Rooms 219, 220, 218, 216, 214, 218, 212 A&B, 311, 211A, 213, 215 and the 2nd Floor Corridor**
MATERIAL QUANTITY:	MATERIAL UNITS:
DAMAGE QUANTITY:	DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**024**		
MATERIAL DESCRIPTION:	**9" x 9" Red Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY			
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Rooms 219, 220, 218, 216, 214, 218, 212 A&B, 311, 211A, 213, 215 and the 2nd Floor Corridor**

MATERIAL QUANTITY:	MATERIAL UNITS:
DAMAGE QUANTITY:	DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**024**
MATERIAL DESCRIPTION:	**9" x 9" Red Floor Tile Mastic**
MATERIAL LOCATION:	**Rooms 219, 220, 218, 216, 214, 218, 212 A&B, 311, 211A, 213, 215 and the 2nd Floor Corridor**
MATERIAL QUANTITY:	MATERIAL UNITS:
DAMAGE QUANTITY:	DAMAGE UNITS:

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**025**		
MATERIAL DESCRIPTION:	**2' x 4' Medium Fissured Ceiling Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 219, 220, 218, 216, 214, 212 A&B, 211, 211A, 213, 215,1st & 2nd floor corridors, Room 214, 210, 208, 204, 202, 202A, 202B, 207, 203, 200, 201, 108, 107, 104, 103, 100, 101**		
MATERIAL QUANTITY:	**6500**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**025**		
MATERIAL DESCRIPTION:	**2' x 4' Medium Fissured Ceiling Tile**		
MATERIAL LOCATION:	**Rooms 219, 220, 218, 216, 214, 212 A&B, 211, 211A, 213, 215,1st & 2nd floor corridors, Room 214, 210, 208, 204, 202, 202A, 202B, 207, 203, 200, 201, 108, 107, 104, 103, 100, 101**		
MATERIAL QUANTITY:	**6500**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**026**		
MATERIAL DESCRIPTION:	**Carpet Adhesive**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 220, 219, 212B, 211A, 211 and Basement 004, 212, 214, 202B, 201, 150**		
MATERIAL QUANTITY:	**3400**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**026**		
MATERIAL DESCRIPTION:	**Carpet Adhesive**		
MATERIAL LOCATION:	**Rooms 220, 219, 212B, 211A, 211 and Basement 004, 212, 214, 202B, 201, 150**		
MATERIAL QUANTITY:	**3400**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**027**		
MATERIAL DESCRIPTION:	**12' X 12" White w/Black Specks Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 212A & 212 Closet, 202A, 202B**		
MATERIAL QUANTITY:	**200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**027**		
MATERIAL DESCRIPTION:	**12' X 12" White w/Black Specks Floor Tile**		
MATERIAL LOCATION:	**Rooms 212A & 212 Closet, 202A, 202B**		
MATERIAL QUANTITY:	**200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**028**		
MATERIAL DESCRIPTION:	**12' X 12" White w/Black Specks Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 212A & 212 Closet, 202A, 202B**		
MATERIAL QUANTITY:	**200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**028**		
MATERIAL DESCRIPTION:	**12' X 12" White w/Black Specks Floor Tile Mastic**		
MATERIAL LOCATION:	**Rooms 212A & 212 Closet, 202A, 202B**		
MATERIAL QUANTITY:	**200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**029**		
MATERIAL DESCRIPTION:	**12' X 12" Gray Speckled Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 212 & 214, 202, 204, 210**		
MATERIAL QUANTITY:	**1800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**029**		
MATERIAL DESCRIPTION:	**12' X 12" Gray Speckled Floor Tile**		
MATERIAL LOCATION:	**Rooms 212 & 214, 202, 204, 210**		
MATERIAL QUANTITY:	**1800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**030**		
MATERIAL DESCRIPTION:	**12' X 12" Gray Speckled Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 212 & 214, 204, 204, 210**		
MATERIAL QUANTITY:	**1800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**030**		
MATERIAL DESCRIPTION:	**12' X 12" Gray Speckled Floor Tile Mastic**		
MATERIAL LOCATION:	**Rooms 212 & 214, 204, 204, 210**		
MATERIAL QUANTITY:	**1800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**031**		
MATERIAL DESCRIPTION:	**12' X 12" Orange w/Brown Specks Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 218, 207, SE, SW Landings**		
MATERIAL QUANTITY:	**2350**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**031**		
MATERIAL DESCRIPTION:	**12' X 12" Orange w/Brown Specks Floor Tile**		
MATERIAL LOCATION:	**Room 218, 207, SE, SW Landings**		
MATERIAL QUANTITY:	**2350**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**032**		
MATERIAL DESCRIPTION:	**12' X 12" Orange w/Brown Specks Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 218, 207, SE, SW Landings**		
MATERIAL QUANTITY:	**2350**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**032**		
MATERIAL DESCRIPTION:	**12' X 12" Orange w/Brown Specks Floor Tile Mastic**		
MATERIAL LOCATION:	**Room 218, 207, SE, SW Landings**		
MATERIAL QUANTITY:	**2350**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**033**		
MATERIAL DESCRIPTION:	**12' X 12" Purple w/White Specks Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Basement West Landing, Room 203, 208, 210**		
MATERIAL QUANTITY:	**500**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**033**		
MATERIAL DESCRIPTION:	**12' X 12" Purple w/White Specks Floor Tile**		
MATERIAL LOCATION:	**Basement West Landing, Room 203, 208, 210**		
MATERIAL QUANTITY:	**500**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**034**		
MATERIAL DESCRIPTION:	**12' X 12" Purple w/White Specks Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Basement West Landing, Room 203, 208, 210**		
MATERIAL QUANTITY:	**500**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**034**		
MATERIAL DESCRIPTION:	**12' X 12" Purple w/White Specks Floor Tile Mastic**		
MATERIAL LOCATION:	**Basement West Landing, Room 203, 208, 210**		
MATERIAL QUANTITY:	**500**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **035**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL: **Low**

MATERIAL LOCATION: **Room 004**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**035**		
MATERIAL DESCRIPTION:	**9" x 9" Black Floor Tile**		
MATERIAL LOCATION:	**Room 004**		
MATERIAL QUANTITY:		MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **036**

MATERIAL DESCRIPTION: **9" x 9" Black Floor Tile Mastic**

HISTORICAL AHERA DAMAGE CATEGORY

HISTORICAL DAMAGE REASON:

HISTORICAL RESPONSE ACTION:

ASBESTOS TYPE: **Chrysotile** FRIABLE:

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 004**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**036**		
MATERIAL DESCRIPTION:	**9" x 9" Black Floor Tile Mastic**		
MATERIAL LOCATION:	**Room 004**		
MATERIAL QUANTITY:		MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**037**		
MATERIAL DESCRIPTION:	**12" x 12" White w/Multi-Colored Specks Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Basement Cafeteria, Kitchen**		
MATERIAL QUANTITY:	**2400**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**037**		
MATERIAL DESCRIPTION:	**12" x 12" White w/Multi-Colored Specks Floor Tile**		
MATERIAL LOCATION:	**Basement Cafeteria, Kitchen**		
MATERIAL QUANTITY:	**2400**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**038**		
MATERIAL DESCRIPTION:	**12" x 12" White w/Multi-Colored Specks FT Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Basement Cafeteria, Kitchen**		
MATERIAL QUANTITY:	**2400**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**038**		
MATERIAL DESCRIPTION:	**12" x 12" White w/Multi-Colored Specks FT Mastic**		
MATERIAL LOCATION:	**Basement Cafeteria, Kitchen**		
MATERIAL QUANTITY:	**2400**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**039**		
MATERIAL DESCRIPTION:	**12" x 12" Dk. Blue Speckled Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Basement Cafeteria, Kitchen, Room 210**		
MATERIAL QUANTITY:	**2700**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**039**		
MATERIAL DESCRIPTION:	**12" x 12" Dk. Blue Speckled Floor Tile**		
MATERIAL LOCATION:	**Basement Cafeteria, Kitchen, Room 210**		
MATERIAL QUANTITY:	**2700**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**040**		
MATERIAL DESCRIPTION:	**12" x 12" Dk. Blue Speckled Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Basement Cafeteria, Kitchen, Room 210**		
MATERIAL QUANTITY:	**2400**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**040**		
MATERIAL DESCRIPTION:	**12" x 12" Dk. Blue Speckled Floor Tile Mastic**		
MATERIAL LOCATION:	**Basement Cafeteria, Kitchen, Room 210**		
MATERIAL QUANTITY:	**2400**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**041**		
MATERIAL DESCRIPTION:	**Aircell Pipe Insulation**		
HISTORICAL AHERA DAMAGE CATEGORY	**1 Damaged or significantly damaged friable thermal system insulating ACBM**		
HISTORICAL DAMAGE REASON:	**Deterioration** **Delamination**		
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Chrysotile**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1**. **Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	**Deterioration** **Delamination**		
DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Throughout and Boiler Room**		
MATERIAL QUANTITY:	**500**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**
COMMENTS:			

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**041**		
MATERIAL DESCRIPTION:	**Aircell Pipe Insulation**		
MATERIAL LOCATION:	**Throughout and Boiler Room**		
MATERIAL QUANTITY:	**500**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**20**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**042**		
MATERIAL DESCRIPTION:	**Fittings on Aircell Pipe Insulation**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Chrysotile**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:			
DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Throughout**		
MATERIAL QUANTITY:	**200**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**
COMMENTS:			

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**042**		
MATERIAL DESCRIPTION:	**Fittings on Aircell Pipe Insulation**		
MATERIAL LOCATION:	**Throughout**		
MATERIAL QUANTITY:	**200**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**043**		
MATERIAL DESCRIPTION:	**Paperwrap Pipe Insulation**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Throughout Basement**		
MATERIAL QUANTITY:	**400**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**043**		
MATERIAL DESCRIPTION:	**Paperwrap Pipe Insulation**		
MATERIAL LOCATION:	**Throughout Basement**		
MATERIAL QUANTITY:	**400**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**044**		
MATERIAL DESCRIPTION:	**Fittings on Paperwrap Insulation**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Throughout**		
MATERIAL QUANTITY:	**50**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**044**		
MATERIAL DESCRIPTION:	**Fittings on Paperwrap Insulation**		
MATERIAL LOCATION:	**Throughout**		
MATERIAL QUANTITY:	**50**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**045**		
MATERIAL DESCRIPTION:	**Mag Pipe Insulation**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Concealed in Chases, 2nd Floor Room 212**		
MATERIAL QUANTITY:	**120**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**045**		
MATERIAL DESCRIPTION:	**Mag Pipe Insulation**		
MATERIAL LOCATION:	**Concealed in Chases, 2nd Floor Room 212**		
MATERIAL QUANTITY:	**120**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**046**		
MATERIAL DESCRIPTION:	**Fittings on Mag Pipe Insulation**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Concealed in Chases, 2nd Floor Room 212**		
MATERIAL QUANTITY:	**120**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**046**		
MATERIAL DESCRIPTION:	**Fittings on Mag Pipe Insulation**		
MATERIAL LOCATION:	**Concealed in Chases, 2nd Floor Room 212**		
MATERIAL QUANTITY:	**120**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**047**		
MATERIAL DESCRIPTION:	**Boiler Gaskets**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Chrysotile**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Basement Room 008A**		
MATERIAL QUANTITY:	**150**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**047**		
MATERIAL DESCRIPTION:	**Boiler Gaskets**		
MATERIAL LOCATION:	**Basement Room 008A**		
MATERIAL QUANTITY:	**150**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**048**		
MATERIAL DESCRIPTION:	**Boiler Jacketing**		
HISTORICAL AHERA DAMAGE CATEGORY	**1 Damaged or significantly damaged friable thermal system insulating ACBM**		
HISTORICAL DAMAGE REASON:	**Deterioration** **Physical Damage**		
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1**. **Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON:	**Deterioration** **Physical Damage**		
DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Basement Room 008A**		
MATERIAL QUANTITY:	**200**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**
COMMENTS:			

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**048**		
MATERIAL DESCRIPTION:	**Boiler Jacketing**		
MATERIAL LOCATION:	**Basement Room 008A**		
MATERIAL QUANTITY:	**200**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**3**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**050**		
MATERIAL DESCRIPTION:	**Drywall Compound**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Throughout**		
MATERIAL QUANTITY:	**12000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**050**		
MATERIAL DESCRIPTION:	**Drywall Compound**		
MATERIAL LOCATION:	**Throughout**		
MATERIAL QUANTITY:	**12000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**051**		
MATERIAL DESCRIPTION:	**Floor Leveling Compound**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Chrysotile**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**1st Floor Corridor**		
MATERIAL QUANTITY:	**1800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**051**		
MATERIAL DESCRIPTION:	**Floor Leveling Compound**		
MATERIAL LOCATION:	**1st Floor Corridor**		
MATERIAL QUANTITY:	**1800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**052**		
MATERIAL DESCRIPTION:	**Fire Door Insulation**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**2 Doors - Basement Boiler Room**		
MATERIAL QUANTITY:	**48**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**052**		
MATERIAL DESCRIPTION:	**Fire Door Insulation**		
MATERIAL LOCATION:	**2 Doors - Basement Boiler Room**		
MATERIAL QUANTITY:	**48**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**49**		
MATERIAL DESCRIPTION:	**Incinerator Insulation**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Boiler Room 008**		
MATERIAL QUANTITY:	**120**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**49**		
MATERIAL DESCRIPTION:	**Incinerator Insulation**		
MATERIAL LOCATION:	**Boiler Room 008**		
MATERIAL QUANTITY:	**120**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**53**		
MATERIAL DESCRIPTION:	**12"X12"Brown w/Dark Brown Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 004**		
MATERIAL QUANTITY:	**800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**53**		
MATERIAL DESCRIPTION:	**12"X12"Brown w/Dark Brown Floor Tile**		
MATERIAL LOCATION:	**Room 004**		
MATERIAL QUANTITY:	**800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**54**		
MATERIAL DESCRIPTION:	**12"X12"Brown w/Dark Brown Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 004**		
MATERIAL QUANTITY:	**800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**54**		
MATERIAL DESCRIPTION:	**12"X12"Brown w/Dark Brown Floor Tile Mastic**		
MATERIAL LOCATION:	**Room 004**		
MATERIAL QUANTITY:	**800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**55**		
MATERIAL DESCRIPTION:	**Black, Brown & White Terrazzo**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**2nd floor South Boys, Girls & Teachers Bathrooms**		
MATERIAL QUANTITY:	**1150**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**55**		
MATERIAL DESCRIPTION:	**Black, Brown & White Terrazzo**		
MATERIAL LOCATION:	**2nd floor South Boys, Girls & Teachers Bathrooms**		
MATERIAL QUANTITY:	**1150**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**56**		
MATERIAL DESCRIPTION:	**Tan & Red Terrazzo**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**1st floor South Boys, Girls, and Teachers Bathroom**		
MATERIAL QUANTITY:	**1620**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**56**		
MATERIAL DESCRIPTION:	**Tan & Red Terrazzo**		
MATERIAL LOCATION:	**1st floor South Boys, Girls, and Teachers Bathroom**		
MATERIAL QUANTITY:	**1620**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**57**		
MATERIAL DESCRIPTION:	**Light Brown Carpet Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 010**		
MATERIAL QUANTITY:	**1296**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**57**		
MATERIAL DESCRIPTION:	**Light Brown Carpet Mastic**		
MATERIAL LOCATION:	**Room 010**		
MATERIAL QUANTITY:	**1296**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**58**		
MATERIAL DESCRIPTION:	**12 X 12 Blue Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**58**		
MATERIAL DESCRIPTION:	**12 X 12 Blue Floor Tile**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**59**		
MATERIAL DESCRIPTION:	**12 X 12 Blue Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**59**		
MATERIAL DESCRIPTION:	**12 X 12 Blue Floor Tile Mastic**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**60**		
MATERIAL DESCRIPTION:	**12 X 12 Light Gray Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**60**		
MATERIAL DESCRIPTION:	**12 X 12 Light Gray Floor Tile**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**61**		
MATERIAL DESCRIPTION:	**12 X 12 Light Gray Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**61**		
MATERIAL DESCRIPTION:	**12 X 12 Light Gray Floor Tile Mastic**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**62**		
MATERIAL DESCRIPTION:	**12 X 12 Dark Grey Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**62**		
MATERIAL DESCRIPTION:	**12 X 12 Dark Grey Floor Tile**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**63**		
MATERIAL DESCRIPTION:	**12 X 12 Dark Grey Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**63**		
MATERIAL DESCRIPTION:	**12 X 12 Dark Grey Floor Tile Mastic**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**64**		
MATERIAL DESCRIPTION:	**12 X 12 Beige Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**64**		
MATERIAL DESCRIPTION:	**12 X 12 Beige Floor Tile**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**65**		
MATERIAL DESCRIPTION:	**12 X 12 Beige Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**65**		
MATERIAL DESCRIPTION:	**12 X 12 Beige Floor Tile Mastic**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1125**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**66**		
MATERIAL DESCRIPTION:	**2' X 4' White Ceiling Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**66**		
MATERIAL DESCRIPTION:	**2' X 4' White Ceiling Tile**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**67**		
MATERIAL DESCRIPTION:	**2' X 4' White Ceiling Tile Adhesive**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**67**		
MATERIAL DESCRIPTION:	**2' X 4' White Ceiling Tile Adhesive**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**1200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**68**		
MATERIAL DESCRIPTION:	**4" Grey Baseboard**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**400**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**68**		
MATERIAL DESCRIPTION:	**4" Grey Baseboard**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**400**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	INSPECTION DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**69**		
MATERIAL DESCRIPTION:	**4" Grey Baseboard Adhesive**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:			
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was reinspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**400**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66031**	BUIDLING ID:	**1720**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:			
SCHOOL NAME:	**LEGAL PREP CHTR - ACADEMY**	REVIEW DATE:			
ADDRESS:	**4319 W Washington**	IDPH LICENSE NO:			

HOMOGENEOUS AREA:	**69**		
MATERIAL DESCRIPTION:	**4" Grey Baseboard Adhesive**		
MATERIAL LOCATION:	**Cafeteria**		
MATERIAL QUANTITY:	**400**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:	**0**	DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: _____ Date: _____

Chicago Public Schools

2025 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed