ILLINOIS DEPARTMENT OF PUBLIC HEALTH
AHERA THREE YEAR REINSPECTION
ASBESTOS ABATEMENT PROGRAM
SCHOOL INFORMATION FORM

SECTION I

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299
SCHOOL ID NUMBER: 15-016-2990-HANS
SCHOOL NAME: Noble Street Charter School-Hansberry College Prep
ADDRESS OF SCHOOL: 8748 Aberdeen
CITY: Chicago, IL, 60620

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **4/27/2016**

If the address on this form is different than the address of the building, submit a written explanation.

SECTION II *(Please type or print)*

PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 477

IDPH INSPECTOR LICENSE NUMBER: 100-03613

IDPH LICENSED INSPECTOR NAME(Please Print): Daniel Juneau

IDPH MP LICENSE NUMBER: 100-01784

IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Steven Geneser

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

Signature of Designated Person *Date*

SECTION III

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: _____

School has been closed. Date closed: _____

School building has been demolished. Date: _____

School building is asbestos free since last reinspection: _____

Please explain in writing why the school building is now asbestos free and include the supporting documentation.

If a new school building has been added to the district, submit either and exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

Explain in writing if the address of the building is different than the address on this form:

THREE–YEAR REINSPECTION

CHICAGO SCHOOL DIST 299

Noble Street Charter School-Hansberry College Prep

8748 Aberdeen
Chicago, IL, 60620

Unit: 66574
Building ID: 59883

IDPH ID Number: 15-016-2990-HANS

REPORT DATE:
Tuesday, October 01, 2019

Prepared for:
Chicago Public Schools
42 West Madison Street
Chicago, IL 60602

Prepared by:
TEM Environmental, Inc.

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

DO NOT REMOVE FROM SCHOOL
REQUIRED BY FEDERAL LAW

June 20, 2019

Mr. Glen E. Garner
Asbestos Program
Illinois Department of Public Health
525 West Jefferson Street
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299 Unit: 66574 Region: IDPH ID:15-016-2990-HANS

School: Noble Street Charter School-Hansberry College Prep Building ID: 59883

Address: 8748 Aberdeen

Chicago, IL, 60620

Building Contact: Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 07/18/2019

Inspector: Daniel Juneau Inspector IDPH License: 100-03613
Management Planner: Steven Geneser Management Planner IDPH License: 100-01784

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,
TEM Environmental, Inc.

Steven Geneser
100-01784

Environmental Notification to Occupants

To: Faculty, Staff and Parents
From: Chicago Public Schools
Date: June 20, 2019

RE: Noble Street Charter School-Hansberry College Prep, Unit 66574
8748 Aberdeen
Chicago, IL, 60620

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Noble Street Charter School-Hansberry College Prep, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Noble Street Charter School-Hansberry College Prep, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

Table of Contents

I. School and Inspection Information

II. Executive Summary

III. Methodology

IV. Abatement History

V. Reassessments and Recommendations

VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

APPENDICES:

Appendix A: Assessment Sheets, Drawings and Photos

Appendix B: Inspector and Management Planner Licenses

Appendix C: Laboratory Accreditations

Appendix D: Laboratory Results

Appendix E: Chain of Custody Forms

SCHOOL AND INSPECTION INFORMATION

1. School Information

School: Noble Street Charter School-Hansberry College Prep | Unit: 66574 | Region:
Address: 8748 Aberdeen | Chicago, IL, 60620
IDPH ID: 15-016-2990-HANS | Building ID: 59883
Contact: | Phone:

2. Description of Facility

Original Construction: 2012 | Additional Construction:
Total Square Footage: 35137 | No of Floors: 1
Current Occupancy: 477

3. LEA Designated Person

Contact: Robert Christlieb | Phone: (773) 553-3197
Address: 42 West Madison Street
Chicago, IL 60602

4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.
Contact: Steven Geneser
Address 174 N. Brandon Drive
Glendale Heights, IL, 60139
Phone: 630-790-0880 | Fax: 630-790-0882

5. Inspector

Inspector Name: Daniel Juneau

Inspector IDPH license # 100-03613 | Signature:
Date: 6/20/2019

6. Management Planner

Management Planner Name: Steven Geneser

Management Planner IDPH license # 100-01784 | Signature:
Date: 07/18/2019

7. Review Date:07/18/2019

8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:  Date: 10/1/2019

Name: Robert Christlieb

II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Noble Street Charter School-Hansberry College Prep. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 59883:

B. The following new homogenous areas have been identified for Building 59883:

C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

01	MJP on Non-Suspect Pipe
02	Wrapped Paper Pipe Cover
03	MJP on Wrapped Pipe Cover
04	Pipe Covering
05	MJP on Pipe Covering
06	1' x 1' Acoustical Ceiling Tile
07	Vinyl Floor Tile
08	12x12 Beige w/ Dark Spots Floor Tile
09	12x12 Beige w/Dark Spots Floor Tile Mastic
10	2'x4' Smooth Ceiling Tile
11	12x12 Gray w/Black & Beige Floor Tile
12	12x12 Gray w/Black & Beige Floor Tile Mastic
13	2'x4' Flat Ceiling Tile
14	Spray-On Insulation
15	Glue Associated w/Rubber Floor
16	12x12 Dark Gray w/Beige Spots Floor Tile
17	12x12 Dark Gray w/ Beige Spots Floor Tile Mastic
18	Gray/Black Carpet Adhesive
19	Gray Baseboard Adhesive
20	Drywall
21	Drywall Compound

The following areas were deemed to be inaccessible:

01	MJP on Non-Suspect Pipe
02	Wrapped Paper Pipe Cover
03	MJP on Wrapped Pipe Cover
04	Pipe Covering
05	MJP on Pipe Covering
06	1' x 1' Acoustical Ceiling Tile
07	Vinyl Floor Tile
09	12x12 Beige w/Dark Spots Floor Tile Mastic
12	12x12 Gray w/Black & Beige Floor Tile Mastic
15	Glue Associated w/Rubber Floor
17	12x12 Dark Gray w/ Beige Spots Floor Tile Mastic
18	Gray/Black Carpet Adhesive
19	Gray Baseboard Adhesive

Materials were also listed as "assumed" if they were in good condition and sampling was not

conducted to avoid damage.

This reinspection was conducted by Daniel Juneau, IDPH License # 100-03613. The Management Plan was updated by Steven Geneser, IDPH License # 100-01784. Inspector and Management Planner Licenses are included in Appendix B.

III. METHODOLOGY

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touchand visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findingsand submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

IV. ABATEMENT HISTORY

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

V. REASSESSMENTS AND RECOMMENDATIONS

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

VI. CONCLUSIONS

The Noble Street Charter School-Hansberry College Prep Building 59883 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activitiesin areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

Table I

Inspector's Reinspection Findings

Chicago Public Schools

School Noble Street Charter School-Hansberry College Prep **Unit** 66574 **Building ID** 59883

Address 8748 Aberdeen **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
01	MJP on Non-Suspect Pipe			All Floors in Building	ASSUMED	TSI	Y				No	ACBM with the potential for damage		LOW
02	Wrapped Paper Pipe Cover			All Floors in Building	ASSUMED	TSI	Y				No	ACBM with the potential for damage		LOW
03	MJP on Wrapped Pipe Cover			Boiler Room #1	ASSUMED	TSI	Y				No	ACBM with the potential for damage		LOW
04	Pipe Covering			All Floors in Building	ASSUMED	TSI	Y				No	ACBM with the potential for damage		LOW
05	MJP on Pipe Covering			All Floors in Building	ASSUMED	TSI	Y				No	ACBM with the potential for damage		LOW
06	1' x 1' Acoustical Ceiling Tile			Ground Floor	ASSUMED	MISC	Y				No	ACBM with the potential for damage		LOW
07	Vinyl Floor Tile			Ground Floor	ASSUMED	MISC	N				No	ACBM with the potential for damage		LOW
08	12x12 Beige w/ Dark Spots Floor Tile	300	SF	Room 185	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
09	12x12 Beige w/Dark Spots Floor Tile Mastic	300	SF	Room 185	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
10	2'x4' Smooth Ceiling Tile	5,000	SF	Rooms 171, 175, 176, 178, 180, 181, 181, 185, Boy's and Girl's Washroom and Hallways	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
11	12x12 Gray w/Black & Beige Floor Tile	1,500	SF	Hallways	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
12	12x12 Gray w/Black & Beige Floor Tile Mastic	1,500	SF	Hallways	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
13	2'x4' Flat Ceiling Tile	800	SF	Kitchen	ASSUMED	MISC	Y	NONE			No	Any remaining friable ACBM or friable suspect ACBM		LOW
14	Spray-On Insulation	300	SF	Storage Room West of Gym	ASSUMED	MISC	Y	NONE	5		No	Any remaining friable ACBM or friable suspect ACBM	3	LOW
15	Glue Associated w/Rubber Floor	800	SF	Room 171	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
16	12x12 Dark Gray w/Beige Spots Floor Tile	1,200	SF	Rooms 175 and 176	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
17	12x12 Dark Gray w/ Beige Spots Floor Tile Mastic	1,200	SF	Rooms 175 and 176	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
18	Gray/Black Carpet Adhesive	1,200	SF	Rooms 180, 181 & 182	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
19	Gray Baseboard Adhesive	1,500	LF	Throughout Building	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW
20	Drywall	10,000	SF	Throughout	ASSUMED	MISC	N	NONE			No	ACBM with the		LOW

Chicago Public Schools

School Noble Street Charter School-Hansberry College Prep **Unit** 66574 **Building ID** 59883
Address 8748 Aberdeen **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139
Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Building								potential for damage		
21	Drywall Compound	2,000	SF	Throughout Building	ASSUMED	MISC	N	NONE			No	ACBM with the potential for damage		LOW

Chicago Public Schools

School Noble Street Charter School-Hansberry College Prep **Unit** 66574 **Building ID** 59883
Address 8748 Aberdeen **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139
Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Reinspection Date **6/20/2019**
Inspector Name **Daniel Juneau**

100-03613 **5/15/2020**
Inspector's IDPH License Number / Expiration Date

Inspector's Comments

HA Number:	Inspector Comments:
01	Not Observed 2019- Might be hidden in inaccessible areas within the building
02	Not Observed 2019- Might be hidden in inaccessible areas within the building
03	Not Observed 2019- Might be hidden in inaccessible areas within the building
04	Not Observed 2019- Might be hidden in inaccessible areas within the building
05	Not Observed 2019- Might be hidden in inaccessible areas within the building
06	Not Observed 2019
07	Not Observed 2019
08	
09	
10	
11	
12	
13	
14	Damage on Column- Installed after 2000
15	
16	
17	
18	
19	
20	
21	

Chicago Public Schools

School Noble Street Charter School-Hansberry College Prep **Unit** 66574 **Building ID** 59883
Address 8748 Aberdeen **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.
174 N. Brandon Drive Glendale Heights, IL, 60139
Phone: 630-790-0880 Fax: 630-790-0882

Inspector's Comments are Summarized at the End of the Report

Table II

Management Planner's Review

Chicago Public Schools

School Noble Street Charter School-Hansberry College Prep **Unit** 66574 **Building ID** 59883

Address 8748 Aberdeen Chicago, IL, 60620 **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
01	MJP on Non-Suspect Pipe			All Floors in Building	Assumed	TSI	Yes			6 ACBM with the potential for damage	Follow O&M Plan
02	Wrapped Paper Pipe Cover			All Floors in Building	Assumed	TSI	Yes			6 ACBM with the potential for damage	Follow O&M Plan
03	MJP on Wrapped Pipe Cover			Boiler Room #1	Assumed	TSI	Yes			6 ACBM with the potential for damage	Follow O&M Plan
04	Pipe Covering			All Floors in Building	Assumed	TSI	Yes			6 ACBM with the potential for damage	Follow O&M Plan
05	MJP on Pipe Covering			All Floors in Building	Assumed	TSI	Yes			6 ACBM with the potential for damage	Follow O&M Plan
06	1' x 1' Acoustical Ceiling Tile			Ground Floor	Assumed	MISC	Yes			6 ACBM with the potential for damage	Follow O&M Plan
07	Vinyl Floor Tile			Ground Floor	Assumed	MISC	No			6 ACBM with the potential for damage	Follow O&M Plan
08	12x12 Beige w/ Dark Spots Floor Tile	300	SF	Room 185	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
09	12x12 Beige w/Dark Spots Floor Tile Mastic	300	SF	Room 185	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
10	2'x4' Smooth Ceiling Tile	5,000	SF	Rooms 171, 175, 176, 178, 180, 181, 181, 185, Boy's and Girl's Washroom and Hallways	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
11	12x12 Gray w/Black & Beige Floor Tile	1,500	SF	Hallways	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
12	12x12 Gray w/Black & Beige Floor Tile Mastic	1,500	SF	Hallways	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
13	2'x4' Flat Ceiling Tile	800	SF	Kitchen	Assumed	MISC	Yes		SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
14	Spray-On Insulation	300	SF	Storage Room West of Gym	Assumed	MISC	Yes	5	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
15	Glue Associated w/Rubber Floor	800	SF	Room 171	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
16	12x12 Dark Gray w/Beige Spots Floor Tile	1,200	SF	Rooms 175 and 176	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12x12 Dark Gray w/ Beige Spots Floor Tile Mastic	1,200	SF	Rooms 175 and 176	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
18	Gray/Black Carpet Adhesive	1,200	SF	Rooms 180, 181 & 182	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
19	Gray Baseboard Adhesive	1,500	LF	Throughout Building	Assumed	MISC	No		LF	6 ACBM with the potential for damage	Follow O&M Plan
20	Drywall	10,000	SF	Throughout Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan
21	Drywall Compound	2,000	SF	Throughout Building	Assumed	MISC	No		SF	6 ACBM with the potential for damage	Follow O&M Plan

Chicago Public Schools

School Noble Street Charter School-Hansberry College Prep **Unit** 66574 **Building ID** 59883

Address 8748 Aberdeen Chicago, IL, 60620 **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

Review Date	07/18/2019
Manager Planner Name	Steven Geneser
100-01784	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
01	
02	
03	
04	
05	
06	
07	
08	
09	

Chicago Public Schools

School Noble Street Charter School-Hansberry College Prep **Unit** 66574 **Building ID** 59883

Address 8748 Aberdeen Chicago, IL, 60620 **Region**

ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

Management Planner's Review Table II

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

Management Planner's Comments Summarized at the End of the Report

HA Number	Management Comments
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**01**		
MATERIAL DESCRIPTION:	**MJP on Non-Suspect Pipe**		
HISTORICAL AHERA DAMAGE CATEGORY	**6**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All Floors in Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019- Might be hidden in inaccessible areas within the building**

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**01**		
MATERIAL DESCRIPTION:	**MJP on Non-Suspect Pipe**		
MATERIAL LOCATION:	**All Floors in Building**		
MATERIAL QUANTITY:		MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**02**		
MATERIAL DESCRIPTION:	**Wrapped Paper Pipe Cover**		
HISTORICAL AHERA DAMAGE CATEGORY	**6**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All Floors in Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019- Might be hidden in inaccessible areas within the building**

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**02**		
MATERIAL DESCRIPTION:	**Wrapped Paper Pipe Cover**		
MATERIAL LOCATION:	**All Floors in Building**		
MATERIAL QUANTITY:		MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**03**		
MATERIAL DESCRIPTION:	**MJP on Wrapped Pipe Cover**		
HISTORICAL AHERA DAMAGE CATEGORY	**6**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler Room #1**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019- Might be hidden in inaccessible areas within the building**

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**03**		
MATERIAL DESCRIPTION:	**MJP on Wrapped Pipe Cover**		
MATERIAL LOCATION:	**Boiler Room #1**		
MATERIAL QUANTITY:		MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**04**		
MATERIAL DESCRIPTION:	**Pipe Covering**		
HISTORICAL AHERA DAMAGE CATEGORY	**6**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All Floors in Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019- Might be hidden in inaccessible areas within the building**

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**04**		
MATERIAL DESCRIPTION:	**Pipe Covering**		
MATERIAL LOCATION:	**All Floors in Building**		
MATERIAL QUANTITY:		MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**05**		
MATERIAL DESCRIPTION:	**MJP on Pipe Covering**		
HISTORICAL AHERA DAMAGE CATEGORY	**6**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All Floors in Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019- Might be hidden in inaccessible areas within the building**

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**05**		
MATERIAL DESCRIPTION:	**MJP on Pipe Covering**		
MATERIAL LOCATION:	**All Floors in Building**		
MATERIAL QUANTITY:		MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**06**		
MATERIAL DESCRIPTION:	**1' x 1' Acoustical Ceiling Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Ground Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**06**		
MATERIAL DESCRIPTION:	**1' x 1' Acoustical Ceiling Tile**		
MATERIAL LOCATION:	**Ground Floor**		
MATERIAL QUANTITY:		MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**07**		
MATERIAL DESCRIPTION:	**Vinyl Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Ground Floor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **Not Observed 2019**

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**07**		
MATERIAL DESCRIPTION:	**Vinyl Floor Tile**		
MATERIAL LOCATION:	**Ground Floor**		
MATERIAL QUANTITY:		MATERIAL UNITS:	
DAMAGE QUANTITY:		DAMAGE UNITS:	

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**08**		
MATERIAL DESCRIPTION:	**12x12 Beige w/ Dark Spots Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 185**		
MATERIAL QUANTITY:	**300**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**08**		
MATERIAL DESCRIPTION:	**12x12 Beige w/ Dark Spots Floor Tile**		
MATERIAL LOCATION:	**Room 185**		
MATERIAL QUANTITY:	**300**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**09**		
MATERIAL DESCRIPTION:	**12x12 Beige w/Dark Spots Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 185**		
MATERIAL QUANTITY:	**300**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**09**		
MATERIAL DESCRIPTION:	**12x12 Beige w/Dark Spots Floor Tile Mastic**		
MATERIAL LOCATION:	**Room 185**		
MATERIAL QUANTITY:	**300**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**10**		
MATERIAL DESCRIPTION:	**2'x4' Smooth Ceiling Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 171, 175, 176, 178, 180, 181, 181, 185, Boy's and Girl's Washroom and Hallways**		
MATERIAL QUANTITY:	**5000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**10**		
MATERIAL DESCRIPTION:	**2'x4' Smooth Ceiling Tile**		
MATERIAL LOCATION:	**Rooms 171, 175, 176, 178, 180, 181, 181, 185, Boy's and Girl's Washroom and Hallways**		
MATERIAL QUANTITY:	**5000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**11**		
MATERIAL DESCRIPTION:	**12x12 Gray w/Black & Beige Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Hallways**		
MATERIAL QUANTITY:	**1500**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**11**		
MATERIAL DESCRIPTION:	**12x12 Gray w/Black & Beige Floor Tile**		
MATERIAL LOCATION:	**Hallways**		
MATERIAL QUANTITY:	**1500**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**12**		
MATERIAL DESCRIPTION:	**12x12 Gray w/Black & Beige Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Hallways**		
MATERIAL QUANTITY:	**1500**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**12**		
MATERIAL DESCRIPTION:	**12x12 Gray w/Black & Beige Floor Tile Mastic**		
MATERIAL LOCATION:	**Hallways**		
MATERIAL QUANTITY:	**1500**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**13**		
MATERIAL DESCRIPTION:	**2'x4' Flat Ceiling Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Kitchen**		
MATERIAL QUANTITY:	**800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**13**		
MATERIAL DESCRIPTION:	**2'x4' Flat Ceiling Tile**		
MATERIAL LOCATION:	**Kitchen**		
MATERIAL QUANTITY:	**800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**14**		
MATERIAL DESCRIPTION:	**Spray-On Insulation**		
HISTORICAL AHERA DAMAGE CATEGORY	**7 Any remaining friable ACBM or friable suspect ACBM**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**Yes**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:	**Deterioration**		
DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Storage Room West of Gym**		
MATERIAL QUANTITY:	**300**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**5**	DAMAGE UNITS:	**SF**

COMMENTS: **Damage on Column- Installed after 2000**

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**14**		
MATERIAL DESCRIPTION:	**Spray-On Insulation**		
MATERIAL LOCATION:	**Storage Room West of Gym**		
MATERIAL QUANTITY:	**300**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:	**5**	DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**15**		
MATERIAL DESCRIPTION:	**Glue Associated w/Rubber Floor**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Room 171**		
MATERIAL QUANTITY:	**800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**15**		
MATERIAL DESCRIPTION:	**Glue Associated w/Rubber Floor**		
MATERIAL LOCATION:	**Room 171**		
MATERIAL QUANTITY:	**800**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**16**		
MATERIAL DESCRIPTION:	**12x12 Dark Gray w/Beige Spots Floor Tile**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 175 and 176**		
MATERIAL QUANTITY:	**1200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**16**		
MATERIAL DESCRIPTION:	**12x12 Dark Gray w/Beige Spots Floor Tile**		
MATERIAL LOCATION:	**Rooms 175 and 176**		
MATERIAL QUANTITY:	**1200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**17**		
MATERIAL DESCRIPTION:	**12x12 Dark Gray w/ Beige Spots Floor Tile Mastic**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 175 and 176**		
MATERIAL QUANTITY:	**1200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**17**		
MATERIAL DESCRIPTION:	**12x12 Dark Gray w/ Beige Spots Floor Tile Mastic**		
MATERIAL LOCATION:	**Rooms 175 and 176**		
MATERIAL QUANTITY:	**1200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**18**		
MATERIAL DESCRIPTION:	**Gray/Black Carpet Adhesive**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Rooms 180, 181 & 182**		
MATERIAL QUANTITY:	**1200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**18**		
MATERIAL DESCRIPTION:	**Gray/Black Carpet Adhesive**		
MATERIAL LOCATION:	**Rooms 180, 181 & 182**		
MATERIAL QUANTITY:	**1200**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**19**		
MATERIAL DESCRIPTION:	**Gray Baseboard Adhesive**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Throughout Building**		
MATERIAL QUANTITY:	**1500**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**19**		
MATERIAL DESCRIPTION:	**Gray Baseboard Adhesive**		
MATERIAL LOCATION:	**Throughout Building**		
MATERIAL QUANTITY:	**1500**	MATERIAL UNITS:	**LF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**LF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**20**		
MATERIAL DESCRIPTION:	**Drywall**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Throughout Building**		
MATERIAL QUANTITY:	**10000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**20**		
MATERIAL DESCRIPTION:	**Drywall**		
MATERIAL LOCATION:	**Throughout Building**		
MATERIAL QUANTITY:	**10000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Inspector Assessment Form (REASSESSMENT)

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	AHERA INSPECTOR:	**Daniel Juneau**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	INSPECTION DATE:	**6/20/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA:	**21**		
MATERIAL DESCRIPTION:	**Drywall Compound**		
HISTORICAL AHERA DAMAGE CATEGORY	**6 ACBM with the potential for damage**		
HISTORICAL DAMAGE REASON:			
HISTORICAL RESPONSE ACTION:	**Follow O&M Plan**		
ASBESTOS TYPE:	**Assumed**	FRIABLE:	**No**

RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6**. **ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL:	**LOW**		
MATERIAL LOCATION:	**Throughout Building**		
MATERIAL QUANTITY:	**2000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

COMMENTS:

Inspector's Signature: _____ Date: **06/20/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

Management Planner Review Form

LEA NAME:	**Chicago Public Schools**	UNIT NUMBER:	**66574**	BUIDLING ID:	**59883**
CITY/STATE:	**Chicago, Illinois**	MANAGEMENT PLANNER:	**Steven Geneser**		
SCHOOL NAME:	**Noble Street Charter School-Hansberry College Prep**	REVIEW DATE:	**7/18/2019**		
ADDRESS:	**8748 Aberdeen**	IDPH LICENSE NO:	**100-03613**		

HOMOGENEOUS AREA:	**21**		
MATERIAL DESCRIPTION:	**Drywall Compound**		
MATERIAL LOCATION:	**Throughout Building**		
MATERIAL QUANTITY:	**2000**	MATERIAL UNITS:	**SF**
DAMAGE QUANTITY:		DAMAGE UNITS:	**SF**

In accordance with Sections 763.88 and763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Follow O&M Plan

Comments:

Management Planner's Signature: _____ Date: **07/18/2019**

Chicago Public Schools

TEM Environmental, Inc.

2019 AHERA REINSPECTION

APPENDIX B

Inspector and Management Planner Licenses

2018

OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/20/2018

Exam Date: 11/20/2018

Expiration Date: 11/20/2019

Certificate Number: BIR1811203167

Kathy DeSalvo, Director

2018

OCCUPATIONAL TRAINING & SUPPLY, INC.
7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ www.otssafety.com

Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

Dan Juneau

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 11/20/2018

Exam Date: 11/20/2018

Expiration Date: 11/20/2019

Certificate Number: MPR1811203186

Kathy DeSalvo, Director

IDPH

ASBESTOS PROFESSIONAL LICENSE

ID NUMBER	ISSUED	EXPIRES
100 - 03613	**4/17/2019**	05/15/2020

DANIEL J JUNEAU
1408 OAKWOOD AVENUE
DES PLAINES, IL 60016

Environmental Health



ENDORSEMENTS	TC EXPIRES
INSPECTOR	11/20/2019
MANAGEMENT PLANNER	11/20/2019
PROJECT MANAGER	11/6/2019
AIR SAMPLING PROFESSIONAL	

Alteration of this license shall result in legal action
This license issued under authority of the State of Illinois
Department of Public Health
This license is valid only when accompanied by a valid
training course certificate.

APPENDIX C

Laboratory Accreditations

APPENDIX D

Laboratory Results

APPENDIX E

Chain of Custody Forms

Three-Year Reinspection Key to Terms

	CODE	KEY
MATERIAL		
	ACBM	Asbestos Containing Building Materials
MATERIAL CATEGORY		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
MATERIAL UNITS		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
DAMAGE TYPE		
	Loc	Localized
	Dist	Distributed