

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2016 - Fall

**School:** Michelle Clark Academic Prep Magnet High School  
**Address:** 5101 W. Harrison

**Oracle Unit:** 41051  
**Region:** 03

**Building ID:** 6620  
**Mail Room:** 36

**Asbestos Surveyor:** Johnson, Miss Rosie Ann

**Survey Date:** 12/6/2016

**Email Address:** rajohnson4@cps.edu

**CHECK HERE IF NO CHANGE TO ASBESTOS**

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

Each child's backpack    
 Notice printed in school's newsletter    
 Notice printed in school's calendar    
 Other | Email

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	12"x12" Brown Floor Tile w/Pink and White Streaks	19500	SF	107, 115, 116, 122,142, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	12" x 12" Yellow Floor Tile			Elevator by Faculty Lounge		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3	12" x 12" Beige Floor Tile			2nd Floor Corridor							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	12" x 12" White Floor Tile w/Grey Streaks	1728	SF	Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Eng Office, Rooms 230 and 232		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	12" x 12" Brown Speckled Floor Tile	50	SF	Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	12" x 12" Wormy Ceiling Tile			Basement, Activity Circle, 1st Floor Men's & Women's Washrooms							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	Plaster Ceilings and Walls			Throughout Facility							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	Lab Table Tops	400	SF	Rooms 122,		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	Mag Block Duct Insulation			Kitchen & Storage area in Basement		TSI					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Spray On Fire Proofing			Inaccessible		Surface					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Cementitious Fitting Insulation on Cold Water Line			Throughout							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Cementitious Fitting Insulation on Hot Water Lines			Throughout							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Water Tank Insulation	280	SF	Basement		TSI	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Tank Breeching on Domestic Hot Water Tank			Pool Mechanical Room							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Metal 2' x 4' Lay In Ceiling Panels			Throughout Facility		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17A	12" x 12" Yellow Floor Tile Mastic	15	SF	Elevator by Faculty Lounge		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17B	12" x 12" Brown Speckled Floor Tile Mastic	30000	SF	1st & 2nd Floor Corridors		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2016 - Fall: Repaired  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Water Heater Breeching			Mechanical Room							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	Water Inlet Pipe Insulation			Mechanical Room							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Block Inside Water Heater			Mechanical Room		Miscellaneous		None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Mud Inside Water Heater			Mechanical Room		Miscellaneous		None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Orange Rubber Flooring			Gym							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:wood floor

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Mastic Beneath Orange Rubber Flooring	1500	SF	Gym		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:wood floor

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12" x 12" Maroon Floor Tile w/White Flecks	1000	SF	Girls & Boys Locker Rooms, Coaches Offices		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12" x 12" Maroon Floor Tile w/White Flecks Mastic	1000	SF	Girls & Boys Locker Rooms, Coaches Offices		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	Brown Baseboard			Gym, Girls & Boys Locker Rooms, Coaches Offices							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Brown Baseboard Mastic			Gym, Girls & Boys Locker Rooms, Coaches Offices							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	Ceramic Wall Base Grout			Pool Room, Girl's and Boy's Locker Rooms							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Ceramic Floor Tile Grout			Pool Room, Girl's and Boy's Locker Rooms							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Cinder Block			Throughout Facility							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Cinder Block Mortar			Throughout Facility							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Wall Tile Adhesive			Boy's Pool Locker Room							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Wall Tile Caulk			Boy's Pool Locker Room							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Clay Floor Tile			Kitchen							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Clay Floor Tile Mortar			Kitchen							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
 Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Ceramic Wall Grout			Kitchen							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
 Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12" x 12" White Floor Tile w/Grey Streaks Mastic	1728	SF	Corridor Between Kitchen and Pool, Industrial Arts, Receiving Room, Engineer Office, Rooms 230 and 232		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
 Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Terrazzo			Stairways and Landings		Surface					<input checked="" type="checkbox"/> YES   <input type="checkbox"/> NO

2016 - Fall: Damaged  
 Comments:Damaged terrazzo stair

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Brown Ceramic Tile Grout			Boy's Washrooms, Men's Washrooms							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Yellow Ceramic Tile Grout			Girl's Washrooms, Women's Washrooms							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	White Ceramic Wall Tile Grout			Custodial Rooms in Boy's Washrooms							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Terrazzo Basins			Custodial Rooms in Boy's Washrooms							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	4" Black Vinyl Baseboard			Throughout Facility							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
 Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	4" Black Vinyl Baseboard Mastic			Throughout Facility							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
 Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" x 12" Brown w/Pink & White Streaks FT Mastic	20000	SF	Rooms 107, 115, 116, 122, 205, 215, 217, 222, 242, 248, B&G Locker Rooms, Storages and Basement		Miscellaneous	No	Loc	20		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
 Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	4" Light Brown Vinyl Baseboard (Cove Base)			Rooms 102 and 148							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
 Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	4" Light Brown Vinyl Baseboard (Cove Base) Mastic			Rooms 102 and 148							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Drywall			Room 220, Industrial Arts Corridor							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Interior Brick			Throughout Facility							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Interior Brick Mortar			Throughout Facility							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Interior Door Caulk	10	LF	Corridor by 241		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Interior Window Caulk			Throughout Facility							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Interior Window Glazing Non Ahera			Throughout Facility							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Purple/Lavender/Tan Ceramic Tile Grout	100	SF	Office Washroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	Wall Tile Caulk	100	SF	Office Washroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	Wall Tile Adhesive	100	SF	Office Washroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	Blue Carpet Mastic	6500	SF	Rooms 101-103, 202 and 214, and LRC Offices		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	Orange Carpet Mastic	4600	SF	Activity Circle		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Gray Carpet Mastic	6200	SF	Activity Circle, Rms. 122, 142, 241		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	12" x 12" Light Gray Floor Tile	100	SF	At Doors of Commons 1+2		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	12" x 12" Light Gray Floor Tile Mastic	100	SF	At Doors of Commons 1+2		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Exterior Door Caulk (Not AHERA)			Building Exterior							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	12"x12"Light Brown Floor Tile w/Dark Brown Streaks			Room 217		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	12"x12" Lt Brn Floor Tile w/Dk Brn Streaks Mastic			Room 217		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	Exterior Brick - Not AHERA			Building Exterior							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	Exterior Brick Mortar - Not AHERA			Building Exterior							<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12" x 12" Blue Floor Tile	200	SF	MDF Room in 116,212		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	12" x 12" Blue Floor Tile Mastic	200	SF	MDF Room in 116		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	Purple Carpet Mastic	556	SF	Room 107,110		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	Purple Carpet Mastic			1st & 2nd Floor Corridors, Faculty Lounge, 1211, 123-125, 130-134, 141, 143-145, 147, 149, 152-155, 150-154, Lockers		Miscellaneous		None			<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12" x 12" Beige Floor Tile Mastic	500	SF	2nd Floor Corridor		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	Transite panel in floor radiators	4000	SF	Rooms		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	Blue Linoleum Flooring	3600	SF	Rooms 142, 223, 223A, 221, 241, 241 and 243		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	Blue Linoleum Mastic	3600	SF	Rooms 142, 223, 223A, 221, 241, 241A, 243		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	12"x12" Dark Brown w/Lt. Grey Spec's FT	400	SF	1st Floor Activity Center Nr. Stairs		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	12"x12" Dark Brown w/Lt. Grey Spec's Mastic	400	SF	1st Floor Activity Center Nr. Stairs		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
80	Ceramic Floor Grout	4500	SF	Pool, 1st & 2nd Fl. Girl's/Boy's Rest Rooms and Lockers		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	12"x12" Brown w/White-Grey Spec's Floor Tile	3800	SF	Front Entrance Hallway		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
82M	12"x12" Brown w/White-Grey FT Mastic	3800	SF	Front Entrance Hallway		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
83	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile	1000	SF	Rms. 109 and 205		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
84	12" x 12" Dark Blue, Light Blue, Yellow Mottled Floor Tile	1000	SF	Rms. 109 and 205		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
85	1' x 1' Smooth Ceiling Tiles	2000	SF	Kitchen		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
86	Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile	2000	SF	Kitchen		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AA	Pink/white flooring material			Rooms 241, 122, 142,		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BB	Mastic associate with HA# AA			Rooms 221, 241, 122, 142, 222, 242		Miscellaneous					<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CC	Panels over moveable doors room divide	2850	SF	123/121, 132/134, 152/154,232/234, 252/254, House commons 1,2 and Gym		Miscellaneous	No	None	0		<input type="checkbox"/> YES   <input checked="" type="checkbox"/> NO

2016 - Fall: No Change  
Comments:N/A

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*



---

Robert Christlieb

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Michelle Clark Academic Prep Magnet High School

Date: 12/6/2016

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. Email
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**