## **Chicago Public Schools**

### 6 Month Asbestos Surveillance

2016 - Fall

School:	Albert G Lane Technical High School		Oracle Unit:	46221	Building ID:	1440
Address:	2501 W. Addison		Region:	01	Mail Room:	31
CHECK HERE IF	NO CHANGE TO ASBESTOS	Asbestos Surveyor: Survey Date: Email Address:	3/3/2017	-		

	A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:											
	Each child's backpack		Notice printed in school's newsletter			Notice prin	ol's calendar	Other				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
12	Aircell Pipe Insulation	1300	LF	Unexcavated Areas, Pipe Chases - Rms 253, and 153D (not observed in 251) -1931		TSI	Yes	Loc	4		YES	X NO

2016 - Fall: No Change
Comments:

Χ

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	MJP E/F/V on Aircell Pipe Insulation	98	LF	Unexcavated Areas, Pipe Chases - 1931; Rms 251, 253, and 153D		TSI	Yes	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Light Blue w/ Dark Spots Linoleum	1200	SF	Room 115 - 1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Light Blue w/ Dark Spots Linoleum Mastic	1200	SF	Room 115 - 1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	2'x4' White w/ Holes & Grooves Ceiling Tile	1200	SF	Room 115 - 1931		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Drywall	500	SF	Room 115 - 1931		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Drywall Joint Compound	100	LF	Room 115 - 1931		Miscellaneous	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Vinyl Baseboard	150	LF	Room 115 - 1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Vinyl Baseboard Mastic	150	LF	Room 115 - 1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"X12" Light beige w/ white and brown streaks VFT	1800	SF	Locker rm & office & storage rm and toilet (361A), 153 A- 1931 bldg		Miscellaneous	No	Loc	40		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36A	12"x12" light beige w/ white and brown streaks VFT MASTIC	1800	SF	Locker rm & office & storage rm and toilet (361A), 153A- 1931 bdlg		Miscellaneous	No	Loc	40		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" dark gray w/white streaks VFT	800	SF	Room 340		Miscellaneous	No	Loc	25		YES XNO
2016 - Fall: No Change											

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37A	12"x12" dark gray w/ white streaks VFT MASTIC		SF	Room 340		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12"x12" gray w/ gray and white streaks VFT	1900	SF	Rooms 133, (Not observed 129, 147)		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38A	12"x12" gray w/ gray and white streaks VFT MASTIC	1900	SF	Rooms 133, (Not observed 129, 147)		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"x12" light green streaked VFT	3500	SF	Serving line room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
	-

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39A	12"x12" light green streaked VFT MASTIC	3500	SF	Serving line room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	9"x9" Tan w/ brown & white streaks VFT	40	SF	Library stairs landings- 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40A	9"x9" Tan w/brown & white streaks VFT MASTIC	40	SF	Library stairs landings- 1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" Green w/ white & black streaks VFT	600	SF	Room 117 - 1931 bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41A	12"x12" Green w/ white & black streaks	600	SF	Room 117 - 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	Black/gray lab counter tops	5400	SF	Rooms 439, 435, 431, 438		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
216-FT6	12x12 Dark brown W/black streaks VFT	4400	SF	Main Corridors 12s, 2nd, 3rd, 4th floors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-BBM1	Brown Vinyl Baseboard Mastic	600	SF	Rooms 119, 123, 125		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-CT1	2x2 White W/pinhole dots ceiling tile	3900	SF	Rooms 119, 123, 125, 215B		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-CT2	2x2 white Rought with dots ceiling tile	2500	SF	Rooms 145A, 138A, 115A, 213, 242A, 2nd floor boys washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-CT3	2x4 White smooth ceiling tile	3000	SF	Rooms 120A, 123A, 220A, 214A, 323C, 320A, 487A, 2nd floor boys bathroom, 4th floor ADA bathroom		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016- DWS1	Drywall system	6700	SF	Rooms 119, 123, 125, 129, 130, 148, 150		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FD1	Fire Doors rated 3/4 hour	180	SF	2nd Floor boys bathroom, rooms 342A, 437A boys, 4th floor ADA bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change					
Comments:					

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FDR1	Dark Gray fire proofed cloth draperies	3000	SF	Room 209 Auditorium balcony		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FDR2	LT. Green fire proofed cloth draperies	1000	SF	Room 300 Gymnasium #2		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT1	2x2 Yellow w/yellow streaks VFT	10170	SF	Rooms 119, 123, 125, 215, 219, 223, 225, 234, 243, 247, 322, 322A, 335, 336, 430, 434, 449		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT1M	2x2 Yellow w/yellow streaks VFT Mastic	10170	SF	Rooms 119, 123, 125, 215, 219, 223, 225, 234, 243, 247, 322, 322A, 335, 336, 430, 434, 449		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT2	2x2 Gray W/Gray streaks VFT	4000	SF	Rooms 119, 123, 125, 215, 219, 223, 225, 234, 243, 247, 322 322A, 335, 336, 430, 434, 449,4th Eloor ADA elevator pump		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT2M	2x2 Gray W/Gray streaks VFT Mastic	4000	SF	Rooms 119, 123, 125, 215, 219, 223, 225. 234, 243, 247, 322 322A, 335, 336, 430, 434, 449,4th Floor ADA elevator pump		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT3	2x2 Green W/green streaks VFT	4000	SF	Rooms 119, 123, 125, 215, 219, 223, 225, 234, 243, 247, 322, 322A, 335, 336, 430, 434, 449		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT3M	2x2 Green W/green streaks VFT Mastic	4000	SF	Rooms 119, 123, 125, 215, 219, 223, 225, 234, 243, 247, 322, 322A, 335, 336, 430, 434, 449		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT	1 2x2 Blue W/blue gray streaks VFT	150	SF	Rooms 441B, 430, 434		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	٦
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT4M	2x2 Blue W/blue gray streaks VFT Mastic	150	SF	Rooms 441B, 430, 434		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT5	12x12 Beige W/brown and white specks VFT	5000	SF	Rooms 435, 245,(1st, 2nd, 3rd, 4th floor corridors)		Miscellaneous	No	None	0		YES XNO
2016 - Fall: N	o Change										

(	20	n	٦r	ne	er	nts	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT5M	12x12 Beige W/brown and white specks VFT Mastic	5000	SF	Rooms 435, 245,(1st, 2nd, 3rd, 4th floor corridors)		Miscellaneous	No	None	0		YES XNO
2016 - Fall: N Comments:	lo Change				-						

HA No Ma	Aaterial Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	2x12 Dark brown W/black treaks VFT Mastic	4400	SF	Main Corridors 12s, 2nd, 3rd, 4th floors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AA	Stage Door (Fire curtain)	1000	SF	Auditorium Stage - 1931		Miscellaneous	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
AAA	2'x 2' ceiling tile; fissured, White	800	SF	Room 445, Art Area corridor		Miscellaneous	Yes	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BB	1'x1' White Wormy Ceiling Tile			Room 241, 437, Main Office - 1931; 113, 134, Auditorium, 252, 335, 433, 442, 444 (bandroom), 446, 400, 402, 403							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
BBB	Acoustical Wall tile, fissured	450	SF	Room 252		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
сс	1'x1' White Wormy Ceiling Tile Mastic			Room 241, 437, Main Office - 1931: 113, 134, Auditorium, 252, 335, 433, 442, 444 (bandroom), 446, 400, 402, 403							YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CCC	Textured Plaster, Walls and Ceiling	4500	SF	1st floor corridor by main office, Auditorium, Room 202		Surface	Yes	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
CT1	2 x 4 ft Ceiling Tiles with Grooves	800	SF	Engineer's Office		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DD	2'x2' White Wormy Ceiling Tile			Serving Area, Lunchroom - 1931; 213, 252, Toilet rooms; 138A, 115A, 145A, 242A, 214A, 215B, 245A, 320A							

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DDD	Terrazzo Floor	30000	SF	All corridors, stairwells, auditorium vestibule, main office lobby		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
EE	2'x4' White Wormy Ceiling Tile (Not observed)			Room 125, 447, 112, 117, 119, 123, 205, 330 - 1931							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
FF	Aircell Duct Insulation	2000	SF	SW Unexcavated Area - 1931		TSI	Yes	Loc	10		YES	X NO
2016 - Fall: No Change Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT10	12"x12" White w/ Tan Streaks VFT	1200	SF	Room 443 - 1931		Miscellaneous	No	None	0		YES X NO
	2010 Fall Na Ohanna										

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT11	12"x12" Dark Brown w/ Black Streaks VFT	16270	SF	All corridors and auditorium - 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT12	12"x12" Peach VFT	1600	SF	Rooms 132, 203 -1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT13	12"x12" Off White w/ Brown Specks VFT	1600	SF	Room 220 -1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT14	9"x9" Off White w/ Gray Streaks VFT (ABATED)			Lunchroom - 1931		Miscellaneous	No				YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT15	9"x9" Green VFT (ABATED)			Lunchroom - 1931		Miscellaneous	No				YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT16	9"x9" Beige w/ Brown Streaks VFT (ABATED)	1000	SF	(Serving Area - ABATED) Rm 134 - 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT17	12"x12" White w/ Brown Specks VFT	650	SF	Kitchen - 1931		Miscellaneous	No	Loc	500		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT18	12"x12" Beige w/ Wavy Brown VFT	3500	SF	Kitchen - 1931		Miscellaneous	No	Loc	30		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT19	9"x9" Black w/ White Streaks VFT	600	SF	Lunchroom Storage, & Engineer's Office - 1931		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT20	9"x9" Maroon w/ White Streaks VFT	1500	SF	Lunchroom Storage, & Engineer's Office - 1931 Gym III 361 mezzanine locker rm.		Miscellaneous	No	Loc	10		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT21	12"x12" Green w/ White Streaks VFT	200	SF	Engineers Locker Room - 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT22	12"x12" Gray w/ White & Brown Specks VFT	2737	SF	Girl's Locker Room Office, Shower Office, Storage, Laundry, 439, 431, 438 - 1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT23	6"x6" Black VFT	500	SF	Library Loft (balcony) - 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT29	12 x 12 inch White w/Tan Streaks VFT	800	SF	Engineer's Office		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT30	12 x 12 inch Pink VFT	1500	SF	Room 146		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT4	12"x12" Beige w/ Brown & White Specks VFT	44600	SF	1931- Corridors all floors, 441B, 435, 245, 125 work room, auditorium, men and women toilets		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT5	9"x9" Peach w/ cream streaks VFT	5200	SF	Vaults in rooms 131, 435, 438, 439, 217, 221, 241, 302A		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT6	6"x6" White VFT	500	SF	Library Loft - 1931 (balcony)		Miscellaneous	No	None	0		YES XNO
2016 - Fall: N	lo Change										

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
FT7	12"x12" Green VFT	1884	SF	Driver's Education Building room 199 simulator room- 1975		Miscellaneous	No	Loc	100		YES	XNO
2016 - Fall: N Comments:	lo Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT8	12"x12" Gray w/ White Streaks VFT	800	SF	Rooms 144 -1931		Miscellaneous	No	None	0		YES X NO
	o Ohan na										

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT9	12"x12" Sand VFT	3000	SF	Room 447, 116 (not observed in 145, 143) - 1931		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
GG	Interior Window Caulk			Throughout - 1931							YES	X NO
2016 - Fall: N Comments:	lo Change				]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
НН	Exterior Window Caulk			Throughout - 1931							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	MJP E/F/V on Fiberglass Pipe Insulation			Boiler Room, Bathroom Pipe Chases, Janitors Closets - 1931							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
II	MJP E/F/V on Fiberglass Pipe Insulation			Janitors Closet, Bathroom Pipe Chases - 1975							

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
JJ	2'x4' White Ceiling Tile			Drivers Education Building - 1975							YES XNO
2016 - Fall: N	lo Change				]						

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
КК	Tan Rubber Flooring	600	SF	Old Dishwasher Room		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L8	Brown Linoleum- ABATED			Room 124, 128, 133 - 1931							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L9	Green & White Linoleum			Stage Crew Office - 1931							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
LM10	Brown Linoleum Mastic- ABATED			Rooms 128, - 1931		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
LM11	Green & White Linoleum Mastic			Stage Crew Office - 1931							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M10	9"x9" Peach w/ cream streaks VFT Mastic	4800	SF	Vaults in rooms 435, 438, 439, 217, 221, 241		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M11	6"x6" White VFT Mastic	500	SF	Library Loft (balcony) - 1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M12	12"x12" Green VFT Mastic	5000	SF	Driver's Education Building - 1975		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M13	12"x12" Gray w/ White Streaks VFT Mastic	800	SF	Rooms 144 -1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M14	12"x12" Sand VFT Mastic	5150	SF	Rooms 447, 116 (Not observed in 145, 143) - 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M15	12"x12" White w/ Tan Streaks VFT Mastic	1200	SF	Room 443 - 1931		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M16	12"x12" Dark Brown w/ Black Streaks VFT Mastic	16270	SF	Corridors & Auditorium - 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M17	12"x12" Peach VFT Mastic	1450	SF	Rooms 203, 132 -1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M18	12"x12" Off White w/ Brown Streaks VFT Mastic	1600	SF	Room 335, 220 -1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M19	9"x9" Off White w/ Gray Streaks VFT Mastic - ABATED			Lunchroom - 1931		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
M20	9"x9" Green VFT Mastic - ABATED			Lunchroom - 1931		Miscellaneous	No				YES	X NO
2016 - Fall: N Comments:	lo Change				]							

HA No Material Description Change in Assessment Category Material Material Material Location Asbestos Material Friable Damage Damage Damage Туре Quantity Quantity Units Туре Category Units (Serving Area - ABATED) Rm 134 - 1931 9"x9" Beige w/ Brown Streaks VFT Mastic YES X NO M21 SF 2000 Miscellaneous No None 0

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M22	12"x12" White w/ Brown Specks VFT Mastic	650	SF	Kitchen - 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M23	12"x12" Beige w/ Wavy Brown VFT Mastic	3500	SF	Kitchen - 1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M24	9"x9" Black w/ White Streaks VFT Mastic	600	SF	Lunchroom Storage, & Engineer's Office - 1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M25	9"x9" Maroon w/ White Streaks VFT Mastic	1500	SF	Lunchroom Storage & Engineer's Offices - 1931 Gym III 361 Mezzanine locker rm.		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M26	12"x12" Green w/ White Streaks VFT Mastic	200	SF	Engineers Locker Room - 1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M27	12"x12" Gray w/ White & Brown Specks VFT Mastic	2737	SF	Girls' Locker Room & Office, Shower Office, Storage & Laundry, Rooms 439, 431, 438 - 1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M28	6"x6" Black VFT Mastic	500	SF	Library Loft (balcony) - 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M29	12 x 12 inch White w/Tan Streaks VFT Mastic	800	SF	Engineer's Office		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M30	12 x 12 inch Pink VFT Mastic	1500	SF	Room 146		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M31	Carpet Mastic	2400		Rooms: 130, 210, 235, 330, 205, 212, 213		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M9	12"x12" Beige w/ Brown & White Specks VFT Mastic	44600	SF	Corridors all floors, 441B, 435, 245, 125 work room, auditorium men & women toilets - 1931		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Alunhu /2

Robert Christlieb

#### NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Albert G Lane Technical High School
-	

Date: 11/8/2016

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

#### CHECK ONE

A copy of this notice was sent home in each child's backpack

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

# A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.