

Chicago Public Schools

6 Month Asbestos Surveillance

2017 - Fall

School: John T McCutcheon Elementary School
Address: 4850 N Kenmore Avenue

Oracle Unit: 26201
Region: 01

Building ID: 6911
Mail Room: 32

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: Dye, Ms. Venguanette
Survey Date: 2/2/2018
Email Address: vdye@cps.edu

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 01 | 9"x 9" White w/Brown Speckles VFT (ABATED) | | | Gym / Lunchroom (Abated in Summer 2015 by heat method) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 02 | 12"x 12" White w/Brown Speckles VFT (ABATED) | | | North & South Vestibules (Abated in Summer 2015 by Heat Method) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 04 | 12" x 12" White W/ Brown speckles VFT Mastic (ABATED) | | | North & South Vestibules (Abated in Summer 2015 by heat method) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 05 | 9"x 9" White w/Brown Speckles VFT Mastic (ABATED) | | | Gym / Lunchroom (Abated in Summer 2015 by heat method) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 06 | Baseboard Mastic | 1800 | LF | Throughout Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 07 | 2' x 4' Ceiling Tile w/Dots | 15000 | SF | Throughout Building | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 08 | Carpet Mastic (ABATED IN SUMMER 2015) | | | Throughout classrooms, corridors & offices REMOVED IN SUMMER 2015 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 09 | New Carpet Mastic | 1800 | SF | Rms 301 and 307 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10 | 12"x12" Brown Streaked VFT | 12500 | SF | Cafeteria; Main office (314); Faculty Lounge (313); Hallways; North & South Vestibules; Rooms 302, 303, 304, 305, 306, 308, 309, 310, 311, 315 and 317. | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10A | 12"x12" Brown Streaked VFT Mastic | 12500 | SF | Cafeteria; Main Office (314); Faculty Lounge (313); Hallways; North & South Vestibules; Rooms 302, 303, 304, 305, 306, 308, 309, 310, 311, 315 and 317 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| B | MJP E/F/V on Fiberglass Pipe Insulation | 90 | LF | Chases & Engineer's Office (above ceiling tiles) | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C | Pre-Formed Insulation on Water Main - (ABATED IN JULY 2013) | | | Lunchroom Office Storage ABATED | | TSI | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.



Robert Christlieb

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: John T McCutcheon Elementary School

Date: 2/2/2018

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.