

Chicago Public Schools

6 Month Asbestos Surveillance

2018 - Fall

School: CICS - Basil
Address: 1800 W. Garfield

Oracle Unit: 66231
Region: 02

Building ID: 7130-East
Mail Room: 43

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: JTORRES214
Survey Date: 12/18/2018
Email Address: jtorres@chicagointl.org

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Acoustical Ceiling Plaster	20000	SF	Throughout Building		Surface	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2	Hard Coat Plaster			Store Rooms, Boiler Rooms and Washrooms		Surface					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3.1	9" x 9" Off-White Floor Tile w/ Brown Streaks	1900	SF	Rooms 106, 107 and 108, Corridors and Lunchroom		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3.2	9" x 9" Green Floor Tile w/ White Streaks	1500	SF	Rooms 200, 204, 208		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3.3	9" x 9" Pink Floor Tile w/Brown Streaks	500	SF	Rooms 202 and 204		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3.4	9" x 9" Grey Floor Tile w/ Wh, Brn & Blk Streaks	2210	SF	Room 202, the 2nd Floor Corridor and the 2nd Floor SW Stair Landing		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	Interior Window Glaze	7500	LF	Throughout Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	Canvas			Lunchroom		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	Exterior Brick - Not AHERA			Exterior of Building		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	Exterior Brick Mortar - Not AHERA			Exterior of Building		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	Exterior Window Caulk - Not AHERA	7000	LF	Exterior of Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	Exterior Window Glaze - Not AHERA	7500	LF	Exterior of Building		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Drywall			Lunchroom and Corridors Above Ceiling Tile and Hallways Leading to Rooms 107, 108, 212 & 213		Miscellaneous					<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Drywall Compound	1000	SF	Lunchroom and Corridors Above Ceiling Tile and Hallways Leading to Rooms 107, 108, 212 & 213		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12.3	9" x 9" Pink Floor Tile w/ Brn Streaks Mastic - not observed			Rooms 202 and 204, and the Gym		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12.4	9" x 9" Grey Floor Tile w/White, Brn & Blk Mastic - not observed			Rooms 202, 2nd Floor Corridor & 2nd Floor SW Stair Landing		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Carpet Mastic - not observed			Room 108		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	9" x 9" Blue Floor Tile w/Black Streaks - not observed			Gym		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	9" x 9" Blue Floor Tile w/ Black Streaks Mastic - not observed			Gym		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	9" x 9" Lt. Brown Floor Tile w/Blue & Wh Streaks - not observed			Storage 130		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" Lt Brn Floor Tile w/Blue & Wh Streaks Mastic - not observed			Storage 130		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	4" Brown Vinyl Baseboard	600	LF	Throughout Facility		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	4" Brown Vinyl Baseboard Adhesive	600	SF	Throughout Facility		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9" x 9" Light Brown Floor Tile w/Wh & Brn Streaks - not observed			Room 201 and 206		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9"x9" Lt Brn Floor Tile w/Wh & Brn Streaks Mastic - not observed			Room 201 and 206		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	Pegboard	700	SF	Classrooms		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12" x 12" Gray/Black Mix Floor Tile	280	SF	Gym, Rooms 124 and 201		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12" x 12" Gray/Black Floor Tile Mastic	180	SF	Gym, Rooms 124 and 201		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12" x 12" Lt. Beige Mix Floor Tile (patching)	89	SF	SW Stairwell, Rooms 204, 206 and 200		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12" x 12" Lt. Beige Mix FT Mastic (patching)	89	SF	SW Stairwell, Rooms 204, 206 and 200		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12" x 12" Lt. Gray w/Wt. Streaks FT (Patching)	65	SF	SW Stairwell		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12"Lt. Gray w/Wt. Streaks FT (Patching) Mastic	65	SF	SW Stairwell		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12" x 12" OliveGrn w/Wt. &BlkStreaks FT (Patching)	36	SF	Room 200		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12"OliveGrnw/Wt. &BlkStreaksFTMastic (Patching)	36	SF	Room 200		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12" x 12" Black Floor Tile (Patching)	100	SF	Room 200, Gym and Stage		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Black Floor Tile (Patching) Mastic	100	SF	Room 200, Gym and Stage		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12" x 12" White w/Beige Mix Floor Tile (Patching)	42	SF	Room 200		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12" x 12" White w/Beige Mix FT (Patching) Mastic	42	SF	Room 200		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12" x 12" Blue/Green Floor Tile (Patching)	120	SF	Rooms 200 & 204		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12" x 12" Blue/Green Floor Tile (Patching) Mastic	120	SF	Rooms 200 and 204		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12" x 12" Lt. Brown w/Wt. Mix FT (Patching)	60	SF	Room 208		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12" x 12" Lt. Brown w/Wt. Mix FT (Patching) Mastic	60	SF	Room 208		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	9" x 9" Grn w/Lt. & Dk. Grn Streaks FT (Patching) - not observed			Room 200		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	9" x 9" Grnw/Lt. &DkGrnStreaksFT (Patching) Mastic - not observed			Room 200		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12" x 12" White w/Tan Speckles FT (Patching)	60	SF	Room 208		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" White w/Tan Specks FT (Patching) Mastic	60	SF	Room 208		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12" x 12" Blue Mix Floor Tile (Patching)	20	SF	Room 126		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Blue Mix Floor Tile (Patching) Mastic	20	SF	Room 208		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12" x 12" Dk. Blue Mix & (9x9 pieces) FT (Patching)	1500	SF	Gym		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12"x12"Dk.BlueMix&(9x9 piece)FT(Patching) Mastic	1500	SF	Gym		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12" x 12" Orange Floor Tile (Patching)	40	SF	Room 124		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12" x 12" Orange Floor Tile (Patching) Mastic	40	SF	Room 124		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	9" x 9" Green w/Brown Streaks Floor Tile - not observed			2nd Floor Hallway		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	9" x 9" Green w/Brown Streaks Floor Tile Mastic - not observed			2nd Floor Hallway		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12" x 12" Off-White Floor Tile	13000	SF	Throughout		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	12" x 12" Off-White Floor Tile Mastic	13000	SF	Throughout		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12" x 12" Lime Green Floor Tile	1500	SF	Throughout		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	12" x 12" Lime Green Floor Tile Mastic	3000	SF	Throughout		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	4" Black Baseboard	4000	LF	Throughout		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	4" Black Baseboard Adhesive	4000	SF	All Classrooms and Hallways		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	Brown Carpet Mastic	575	SF	Room 203,113		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	Greenish Brown Carpet Mastic	1300	SF	Room 103 and Library		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	Marker/Chalk Board Adhesive	3500	SF	All Classrooms		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	2' x 4' (w/2' x 2' Pattern) Ceiling Tile	8000	SF	Rooms 100-102,104,105,111-113,203,213,212,Library, 107 & 108		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	Spray-On	200	SF	Attic Entrance Room 207 Janitor's Closet 2nd Floor		Surface	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
62	Elevator Brake Shoes	6	SF	Elevator		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
63	Caulk on Steam Boiler	35	LF	Room E128		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
64	Fire Doors	660	SF	Interior Doors		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
65	OLIVE LINOLEUM FLOORING	4000	SF	GYM		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
66	MASTIC BENEATH OLIVE LINOLEUM FLOORING	4000	SF	GYM		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	9" X 9" BEIGE W/RED STRIPES FLOOR TILE - not observed			STAIRWELLS #1 AND 2		Miscellaneous	No				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	MASTIC BENEATH 9" X 9" BEIGE W/RED STRIPES FLOOR - not observed			STAIRWELLS #1 AND 2		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	12" X 12" BEIGE FLOOR TILE	90	SF	SECOND FLOOR LANDING		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	MASTIC BENEATH 12" X 12" BEIGE FLOOR TILE	90	SF	SECOND FLOOR LANDING		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12" X 12" ORANGE FLOOR TILE	150	SF	FIRST FLOOR CORRIDOR		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	MASTIC BENEATH 12" X 12" ORANGE FLOOR TILE	150	SF	FIRST FLOOR CORRIDOR		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12" X 12" DARK GREEN FLOOR TILE	15	SF	ROOM 208		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
74	MASTIC BENEATH 12" X 12" DARK GREEN FLOOR TILE	15	SF	ROOM 208		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
75	THERMAL SYSTEM INSULATION (TSI)	500	LF	TUNNELS		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	JOINT COMPOUND ON THERMAL PIPE INSULATION	200	LF	TUNNELS		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	12" x 12" BLUE FLOOR TILE	80	SF	ROOM 124, 105		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
78	MASTIC BENEATH 12" X 12" BLUE FLOOR TILE	80	SF	ROOM 124,205		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
93	12" x 12" tan with Brown Floor tile	5000	SF	East building 2nd floor hallway, 201, 202, 204, 206,208, 2nd floor janitors closet		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
94	Mastic for 12" x 12" tan with brown floor tile	5000	SF	East building 2nd floor hallway, 201, 202, 204, 206,208, 2nd floor janitors closet		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
95	Blue carpet mastic	1000	SF	Room 106		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Fiberglass Pipe Insulation			Throughout Building							<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	Fiberglass Pipe Joint Insulation	160	LF	Boiler Room, Store Room, Pipe Chases		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.



Robert Christlieb

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: CICS - Basil
Date: 12/18/2018

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.