

Chicago Public Schools

6 Month Asbestos Surveillance

2018 - Fall

School: Pathways in Education- Brighton Park
Address: 3124 47

Oracle Unit: 66801
Region:

Building ID: 59894
Mail Room: 43

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: McCormick, Douglas
Survey Date: _____
Email Address: dmccormick@ccaltd.com

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 1 | Drywall | | | Throughout Ground Floor | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2 | Drywall Joint Compound | | | Throughout Ground Floor | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 3 | Gray Carpet Mastic | 11000 | SF | Rms. 2, 3, 6, 7, 11-14, 20-27 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 4 | 4" Gray Vinyl Baseboard | 1500 | LF | Throughout Ground Floor | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 5 | 4" Gary Vinyl Baseboard Mastic | 1500 | LF | Throughout Ground Floor | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6 | Beige Stone Pattern Sheet Flooring | 1500 | SF | Vestibule, Restrooms, Custodial Room, Breakroom, Classroom 15 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7 | Mastic Associated w/ Beige Stone Pattern Sheet Flooring | 1500 | SF | Vestibule, Restrooms, Custodial Room, Breakroom, Classroom 15 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8 | 1' x 1' Ceiling Tile w/ Dots | 20 | SF | Basement Corridor | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 9 | Adhesive Associated w/ 1' x 1' Smooth Ceiling Tile w/ Dots | 20 | SF | Basement Corridor | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10 | Splash Guard Mastic | 30 | SF | Restrooms, Custodial Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|---------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2018 - Spring : No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Pathways in Education- Brighton Park
Date: 6/6/2018

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.