

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Alcott School
Address 2625 N. Orchard Street

Oracle Unit 22041 **Building ID** 2040
Region 2 **General Services Route** 33

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|----------------------------------------------------------------------|----------------------------------|-------------------|----------------|------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|--------------------------------------|
| 07 | Spray Applied Acoustical Plaster | 10000 | SF | Hallways & Classrooms - 1961 Bldg. | Chrysotile | SURFAC E | Yes | Loc | 50 | SF | |
| <small>3YR Inspector Comments: water damage - 3rd floor Hall</small> | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | SURFAC E | | | | SF | |
| <small>Comments:</small> | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | SURFAC E | | | | SF | |
| <small>Comments:</small> | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 22041

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|----------------------------------------------------------------------------------------|--------------------------------------|-------------------|----------------|------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 10 | MJP E/F/V on Aircell Pipe Insulation | 150 | LF | Fan Rms, Boiler Rm, Shower, Break Rm, S. & W. Unex. Area, Main Pump/Fan Rm, Coal Rm-1936 Bldg. | Chrysotile | TSI | Yes | Dist | 20 | LF | |
| 3YR Inspector Comments: 20 LF damage unexcavated areas | | | | | | | | | | | |
| Condition Changed in Fall 2010 | | | LF | | Chrysotile | TSI | | | | LF | |
| Comments: All these areas abated in 2008/2009 boiler project except unexcavated areas. | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | LF | | Chrysotile | TSI | | | | LF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|----------------------------------------------------------------------------------------|-------------------------|-------------------|----------------|------------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 11 | Aircell Pipe Insulation | 1150 | LF | Fan Rms, Boiler Rm, Shower, Break Rm, S. & W. Unex. Area, Main Pump/Fan Rm, Coal Rm-1936 Bldg. | Chrysotile | TSI | Yes | Dist | 20 | LF | |
| 3YR Inspector Comments: 20 LF damage unexcavated areas | | | | | | | | | | | |
| Condition Changed in Fall 2010 | | | LF | | Chrysotile | TSI | | | | LF | |
| Comments: All these areas abated in 2008/2009 boiler project except unexcavated areas. | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | LF | | Chrysotile | TSI | | | | LF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|-------------------------|-------------------|----------------|--------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 12 | Aircell Duct Insulation | 1500 | SF | Unexcavated Areas - 1936 Bldg. | Chrysotile | TSI | Yes | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | TSI | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | TSI | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|-------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 14 | Boiler #1 Insulation (ABATED) | | | Boiler Room, 1936 Building | Chrysotile | TSI | | | | | |
| 3YR Inspector Comments: Abated | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | | | Chrysotile | TSI | | | | | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | | | Chrysotile | TSI | | | | | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|-------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 15 | Boiler #2 Insulation (ABATED) | | | Boiler Room, 1936 Building | Chrysotile | TSI | | | | | |
| 3YR Inspector Comments: Abated | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | | | Chrysotile | TSI | | | | | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | | | Chrysotile | TSI | | | | | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|--------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 16 | Tank Insulation (ABATED) | | | Boiler Rm, 1936 Building | Chrysotile | TSI | | | | | |
| 3YR Inspector Comments: Abated | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | | | Chrysotile | TSI | | | | | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | | | Chrysotile | TSI | | | | | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|---------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 17 | 9"x9" Tan w/ Black Streaks Floor Tile | 10225 | SF | Throughout - 1961 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|----------------------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 18 | 9"x9" Tan w/ Black Streaks Floor Tile Mastic | 10225 | SF | Throughout - 1961 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|------------------------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 19 | 12"x12" White w/ Grey Streaks Floor Tile | 700 | SF | Room 109 - 1936 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|-----------------------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 20 | 9"x9" Green w/ White Streaks Floor Tile | | | Storage in Room 109 - 1936 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|-------------------------------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 21 | 12"x12" White w/ Grey Streaks Floor Tile Mastic | 700 | SF | Room 109 - 1936 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|-----------------------------------------|-------------------|----------------|----------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 29 | 9"x9" Brown w/ White Streaks Floor Tile | 900 | SF | 1st through 3rd Floor Corridors - 1961 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|------------------------------------------------|-------------------|----------------|-------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 30 | 9"x9" Brown w/ White Streaks Floor Tile Mastic | 900 | SF | 1st through 3rd Floor Corridors, Teachers Lunchroom in Cafeteria - 1961 Bldg. | Chrysotile | MISC | | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|-----------------------------------------|-------------------|----------------|-------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 32 | MJP E/F/V on Fiberglass Pipe Insulation | 100 | LF | North and SE Crawlspace, Bathroom Chases - 1961 Bldg. | Chrysotile | TSI | Yes | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | LF | | Chrysotile | TSI | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | LF | | Chrysotile | TSI | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|-----------------------------------------|-------------------|----------------|-------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 33 | MJP E/F/V on Fiberglass Pipe Insulation | 50 | LF | Boiler Room, Bathroom Chases - 1936 Bldg. | Chrysotile | TSI | Yes | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | LF | | Chrysotile | TSI | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | LF | | Chrysotile | TSI | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|---------------------------------------------------------------|-----------------------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 34 | 12"x12" Off White w/ Brown Streaks Floor Tile | 2600 | SF | 3rd FI Corridor - 1936 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: 25 SF of broken tiles throughout area | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|------------------------------------------------------|-------------------|----------------|------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 35 | 12"x12" Off White w/ Brown Streaks Floor Tile Mastic | 2600 | SF | 3rd FI Corridor - 1936 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|---------------------------------------------------------------|-------------------------------------|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 36 | 9"x9" Tan w/ Red Streaks Floor Tile | 3000 | SF | 1st & 2nd Floor Hallways - 1936 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: 20 SF of broken Tiles throughout area | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|--------------------------------------------|-------------------|----------------|----------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 37 | 9"x9" Tan w/ Red Streaks Floor Tile Mastic | 3000 | SF | 1st & 2nd Floor Corridors - 1936 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|---------------------------------------------------------------------------------------|--------------------------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 38 | 12" x 12" White w/ Yellow Spots Floor Tile | 480 | SF | Main Office, Rm 202 - 1936 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: Entire Main Office retiled. Covered with 3/4" plywood and tile underlayment | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|---------------------------------------------------------------------------------------|-------------------------------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 39 | 12"x12" White w/ Yellow Spots Floor Tile Mastic | 480 | SF | Main Office, Rm 202 - 1936 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: Entire Main Office retiled. Covered with 3/4" plywood and tile underlayment | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|----------------------------------------------------------|---------------------------------------|-------------------|----------------|----------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 40 | 9"x9" Tan w/ White Streaks Floor Tile | 150 | SF | Bathroom Within Cafeteria - 1961 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: 50 SF of missing and broken Tile | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|----------------------------------------------|-------------------|----------------|----------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 41 | 9"x9" Tan w/ White Streaks Floor Tile Mastic | 150 | SF | Bathroom Within Cafeteria - 1961 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|------------------------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 42 | 12"x12" White w/ Grey Streaks Floor Tile | 700 | SF | Room 109 - 1936 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|-------------------------------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 43 | 12"x12" White w/ Grey Streaks Floor Tile Mastic | 700 | SF | Room 109 - 1936 Bldg. | Chrysotile | MISC | No | | | | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|--------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 44 | 12"x12" White Floor Tile | 900 | SF | Rm 109 (Under Tile) - 1936 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|---------------------------------|-------------------|----------------|----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 45 | 12"x12" White Floor Tile Mastic | 900 | SF | Rm 109 (Under Tile) - 1936 Bldg. | Chrysotile | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Chrysotile | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-----------------------------------------------------------------------------------------------|----------------------------------------|-------------------|----------------|----------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 46 | MJP E/F/V on Cardboard Pipe Insulation | 8 | LF | Boiler Room, Shower Room, Break Room, South Unexcavated Area, Main Pump/Fan Room- 1936 Bldg. | Chrysotile | TSI | Yes | None | 0 | LF | |
| 3YR Inspector Comments: Abatement 8/31/09 - Boiler Room, Fan Rooms, Oil Tank Room and Tunnels | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | LF | | Chrysotile | TSI | | | | LF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | LF | | Chrysotile | TSI | | | | LF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-----------------------------------------------------------------------------------------------|---------------------------|-------------------|----------------|----------------------------------------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 47 | Cardboard Pipe Insulation | 25 | LF | Boiler Room, Shower Room, Break Room, South Unexcavated Area, Main Pump/Fan Room- 1936 Bldg. | Chrysotile | TSI | Yes | None | 0 | SF | |
| 3YR Inspector Comments: Abatement 8/31/09 - Boiler Room, Fan Rooms, Oil Tank Room and Tunnels | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | LF | | Chrysotile | TSI | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | LF | | Chrysotile | TSI | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|-----------------------------------|-------------------|----------------|-----------------------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 50 | 12"x12" Beige Speckled Floor Tile | 700 | SF | 1961 Building - Old Teacher Lunchroom in Cafeteria, New Kitchen | Assumed | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Assumed | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Assumed | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|------------------------------------------|-------------------|----------------|-------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 51 | 12"x12" Beige Speckled Floor Tile mastic | 700 | SF | Kitchen (Former Teacher Lunchroom) - 1961 | Assumed | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Assumed | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Assumed | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------------------------------------------------------------|--------------------------------|-------------------|----------------|------------------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 52 | Cardboard Pipe Wrap Insulation | 300 | LF | 1961 Crawlspace (classroom and lunchroom side) | Assumed | TSI | Yes | None | 0 | LF | |
| 3YR Inspector Comments: No O&M or abatement records on site | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | LF | | Assumed | TSI | | | | LF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | LF | | Assumed | TSI | | | | LF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 53 | 9"x9" Black Floor Tile (ABATED) | | | Engineers Office | Assumed | MISC | | | | | |
| 3YR Inspector Comments: Abated | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | | | Assumed | MISC | | | | | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | | | Assumed | MISC | | | | | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|----------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 53A | 9"x9" Black Floor Tile Mastic (ABATED) | | | Engineers Office | Assumed | MISC | | | | | |
| 3YR Inspector Comments: Abated | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | | | Assumed | MISC | | | | | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | | | Assumed | MISC | | | | | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | YES | NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 54 | 9"x9" Maroon Floor Tile (ABATED) | | | Engineers Office | Assumed | MISC | | | | | |
| 3YR Inspector Comments: Abated | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | | | Assumed | MISC | | | | | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | | | Assumed | MISC | | | | | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | YES | NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|-----------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 54A | 9"x9" Maroon Floor Tile Mastic (ABATED) | | | Engineers Office | Assumed | MISC | | | | | |
| 3YR Inspector Comments: Abated | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | | | Assumed | MISC | | | | | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | | | Assumed | MISC | | | | | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | YES | NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 55 | Boiler Gasket | 50 | LF | Boiler Room | Assumed | MISC | No | None | 0 | LF | |
| 3YR Inspector Comments: New material | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | LF | | Assumed | MISC | | | | LF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | LF | | Assumed | MISC | | | | LF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 56 | 12 x 12 Black Floor Tile | 200 | SF | Engineer's Office | Assumed | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: New material | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Assumed | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Assumed | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|-------------------------------|
| 57 | 12 x 12 Black Floor Tile Mastic | 200 | SF | Engineer's Office | Assumed | MISC | No | None | 0 | SF | |
| 3YR Inspector Comments: New material | | | | | | | | | | | |
| Condition Not Changed in Fall 2010 | | | SF | | Assumed | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Condition Not Changed in Spring 2011 | | | SF | | Assumed | MISC | | | | SF | |
| Comments: | | | | | | | | | | | |
| Fall 2011 | | | | | | | | | | | YES NO |
| Comment: | | | | | | | | | | | |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

All LEA Responsibilities, for this school, will be met.



Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 22041

Page 15

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.