

Chicago Public Schools

6 Month Asbestos Surveillance

2015 - Fall

School: Christian Ebinger
Address: 7350 W Pratt Avenue

Oracle Unit: 23051
Region: 01

Building ID: 3150
Mail Room: 30

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: Clancy, Miss June Helen
Survey Date: 10/16/2015
Email Address: jhclancy@cps.edu

A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via:

Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other POSTED

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2A	12"x12" White w/ Beige Streaks VFT	850	SF	Kitchen Under Existing VFT (Room 100), Lunchroom (Room 101 & 103)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2B	12"x12" Gray w/ Beige Streaks VFT	850	SF	Kitchen Under Existing VFT (Room 100), Lunchroom (Room 101 & 103)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2C	12"x12" White VFT	600	SF	Faculty Lounge (1st floor)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2D	12"x12" Tan w/ White Spots VFT	800	SF	Kitchen (Room 100)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2E	12"x12" White w/ Gray Streaks VFT	7500	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3A	12"x12" White w/ Beige Streaks VFT Mastic	850	SF	Kitchen Under Existing VFT (Room 100), Lunchroom (Room 101 & 103)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3B	12"x12" Gray w/ Beige Streaks VFT Mastic	850	SF	Kitchen Under Existing VFT (Room 100), Lunchroom (Room 101 & 103)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3C	12"x12" White VFT Mastic	600	SF	Faculty Lounge		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3D	12"x12" Tan w/ White Spots VFT Mastic	800	SF	Kitchen (Room 100)		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3E	12"x12" White w/ Gray Streaks VFT Mastic	7500	SF	1st & 2nd Floor Corridors		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	Exterior Caulk			Exterior Windows							<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Interior Caulk			Interior Windows							<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	Terrazzo Flooring	5000	SF	All Stairwells, 2nd Floor Corridors Around Boarders, 1st Floor Corridors Around Boarders, Stage Stairs, Assembly Hall Stairs and Vestibule, Room 200		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	Textured Plaster	2000	SF	Stage Walls		Surface	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:new paint

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
8	Carpet Mastic - Removed 12/2010			Assembly Hall - Removed 12/2010		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	12"X12" White w/Specks VFT	5000	SF	Throughout Mobile Units A and B, Except Boys and Girls Toilets		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9A	12"X12" White w/Specks VFT Mastic	5000	SF	Throughout Mobile Units A and B, Except Boys and Girls Toilets		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	2'X2' White Ceiling Tiles	5000	SF	Throughout Mobile Units A and B		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Linoleum Flooring	400	SF	Boys and Girls Toilets, Mobile Unit B		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	Linoleum Flooring Mastic	400	SF	Boys and Girls Toilets, Mobile Unit B		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Pink Linoleum Flooring	200	SF	Womens Toilet, Mobile Unit A		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12A	Pink Linoleum Flooring Mastic	200	SF	Womens Toilet, Mobile Unit A		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Blue Linoleum Flooring	200	SF	Men's Toilet, Mobile Unit A		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13A	Blue Linoleum Flooring Mastic	200	SF	Men's Toilet, Mobile Unit A		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Drywall and Joint Compound	5000	SF	Throughout Mobile Units A and B		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Dark Blue VFT	600	SF	Assembly Hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:capita 04/1 2015

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Dark Blue Mastic	600	SF	Assembly Hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capital

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Light blue w/white, red and blue speckles VFT	600	SF	Assembly Hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capital

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Light blue w/white, red and blue speckles Mastic	600	SF	Assembly Hall		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capital

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Blue w/black and white speckles VFT	24	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capital

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	12"x12" Blue w/black and white speckles Mastic	24	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capital

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Sand VFT	24	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capital

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Sand Mastic	24	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capital

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Tan VFT	25	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments: ""under capital

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Tan Mastic	25	SF	Engineer's Office		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments: ""under capital

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" White w/ gray speckles VFT	24	SF	Engineer's Office Toilet		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments: ""under capital

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" White w/gray speckles Mastic	24	SF	Engineer's Office Toilet		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments: ""under capital

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Gray w/black and white streaks VFT	12	SF	Engineer's Office Toilet		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:"under capital

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Gray w/black and white streaks Mastic	12	SF	Engineer's Office Toilet		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:"under capital

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Blown-In Insulation on Duct Work	2500	SF	Attic		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:"

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
A	Mag Block Tank Insulation (Two)	250	SF	Boiler Room		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capita improvementl

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	Mag Block Condensation Tank Insulation	125	SF	Boiler Room		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capital

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Aircell Pipe Insulation	40	LF	Unex. Spaces, Boiler Rm, & Boiler Tunnel, Basement NE and NW Corner Spaces, Basement S. Center Hall		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capital

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Aircell Pipe Insulation	30	LF	Unex. Spaces, Boiler Rm, & Boiler Tunnel, Basement NE and NW Corner Spaces, Basement S. Center Hall		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"04/2015 capital improvement

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Aircell Duct Wrap Insulation	800	SF	East and Main Unexcavated Crawl Space		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"capital04/2015

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	Cardboard Pipe Insulation	100	LF	Boiler Rm, & Boiler Tunnel, Basement NE and NW Corner Spaces, Basement S. Center Hall		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capital

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	MJP E/F/V on Cardboard Pipe Insulation	45	LF	Boiler Rm, & Boiler Tunnel, Basement NE and NW Corner Spaces, Basement S. Center Hall		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capital

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Mag Pipe Insulation	60	LF	Basement S. Center Hall, Boiler Room & Tunnel, NE & NW Corners Of Basement		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capiyal

2015 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	MJP E/F/V on Mag Pipe Insulation	20	LF	Basement S. Center Hall, Boiler Room & Tunnel, NE & NW Corners Of Basement		TSI	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: Abated
Comments:"under capital

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	MJP E/F/V on Fiberglass Pipe Insulation			Throughout		TSI	Yes				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change
Comments:

2014- Spring: No Change
Comments:

2014 - Fall: No Change
Comments:

2015- Spring: No Change
Comments:"under capital 2015

2015 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.

Lynn A. Crivello

Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Christian Ebinger

Date: 10/16/2015

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. POSTED
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.