

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Goethe School
Address 2236 N. Rockwell Avenue

Oracle Unit 23341 **Building ID** 3560
Region 2 **General Services Route** 35

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	12"x12" Brown VFT	16700	SF	Throughout (See Hatching Maps) - 1885 Building	Chrysotile	MISC	No	None	0	SF	
<i>3YR Inspector Comments: 900 SF of Tile removed from social lunchroom</i>											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
<i>Comments:</i>											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
<i>Comments:</i>											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 23341

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	Air Cell Pipe Insulation	180	LF	Rooms 001, 002, 003, 004, Boiler Room, Coal Room- 1885 Building	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					LF
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					LF
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	MJP E/F/V on Aircell Pipe Insulation	35	LF	Rooms 001, 002, 003, 004, Boiler Room, Coal Room- 1885 Building	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					LF
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					LF
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	Cardboard Pipe Insulation	320	LF	Coal Room, Room 003, Room 004 and 004 Storage Room, Basement Corridor, South Fan Room- 1885 Building	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI					LF
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI					LF
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	MJP E/F/V on Cardboard Pipe Insulation	21	LF	Coal Room, Room 003, Room 004 and 004 Storage Room, Basement Corridor, South Fan Room- 1885 Building	Chrysotile	TSI	Yes	None	0	LF	

3YR Inspector Comments:

Condition Not Changed in Fall 2010		LF		Chrysotile	TSI					LF	
------------------------------------	--	----	--	------------	-----	--	--	--	--	----	--

Comments:

Condition Not Changed in Spring 2011		LF		Chrysotile	TSI					LF	
--------------------------------------	--	----	--	------------	-----	--	--	--	--	----	--

Comments:

Fall 2011											YES NO
------------------	--	--	--	--	--	--	--	--	--	--	--------

Comment:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	MJP E/F/V on Fiberglass Pipe Insulation	123	LF	Basement Girls Toilet, Rooms 001, 003, 004, Basement Corridor, Pump Room, N. Fan Room- 1885 Building	Chrysotile	TSI	Yes	Dist	16	LF	

3YR Inspector Comments:

Condition Not Changed in Fall 2010		LF		Chrysotile	TSI					LF	
------------------------------------	--	----	--	------------	-----	--	--	--	--	----	--

Comments:

Condition Not Changed in Spring 2011		LF		Chrysotile	TSI					LF	
--------------------------------------	--	----	--	------------	-----	--	--	--	--	----	--

Comments:

Fall 2011											YES NO
------------------	--	--	--	--	--	--	--	--	--	--	--------

Comment:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Aircell Duct Insulation	480	SF	Basement Corridor- 1885 Building	Chrysotile	TSI	Yes	None	0	SF	

3YR Inspector Comments:

Condition Not Changed in Fall 2010		SF		Chrysotile	TSI					SF	
------------------------------------	--	----	--	------------	-----	--	--	--	--	----	--

Comments:

Condition Not Changed in Spring 2011		SF		Chrysotile	TSI					SF	
--------------------------------------	--	----	--	------------	-----	--	--	--	--	----	--

Comments:

Fall 2011											YES NO
------------------	--	--	--	--	--	--	--	--	--	--	--------

Comment:

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Brown VFT Mastic	18450	SF	Throughout (See Hatching Maps) - 1885 Building	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: 900 SF of Tile removed from social lunchroom											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Beige w/ Brown Spots VFT Mastic	1350	SF	Rooms 106 & 206- 1885 Building	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" White VFT Mastic	2500	SF	First and Second Floor Hallways- 1885 Building	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12" x12" Brown w/ White Spots VFT Mastic	2500	SF	First and Second Floor Corridors-1885 Building	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9" x 9" Brown w/ Streaks VFT	180	SF	Room 308 Wardrobe- 1885 Building	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9" x 9" Brown w/ Streaks VFT Mastic	180	SF	Room 308 Wardrobe- 1885 Building	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12" x 12" Brown w/ Wht. & Black Specks VFT Mastic (ABATED)	6935	SF	Throughout (See Hatching Maps) - 1987 Annex	Chrysotile						
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile						
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile						
Comments:											
Fall 2011											YES NO
Comment:											


HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12 x 12 White with Gray and Brown Specs Floor Tile	900	SF	Lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12 x 12 White with Gray and Brown Specs Floor Tile	900	SF	Lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

All LEA Responsibilities, for this school, will be met.



Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 23341

Page 7

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125