

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Jahn School
Address 3149 N. Wolcott Avenue

Oracle Unit 23921 **Building ID** 4170
Region 2 **General Services Route** 33

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01	12"x12" White w/ Brown Streaks VFT	2426	SF	3rd Flr. Tchrs Toilet & Lounge, Rm 004, 108, Main Off., Tchrs Tlt Across from 109, Lunchroom	Chrysotile	MISC	No	None	0	SF	
<i>3YR Inspector Comments: Not observed in Teacher's Toilets on 3rd and 1st Floors</i>											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
<i>Comments:</i>											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
<i>Comments:</i>											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 23921

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
02	12"x12" Beige w/ White Streaks VFT	800	SF	Room 301 & Wardrobe	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	12"x12" Brown w/ Tan Streaks VFT	120	SF	Room 205 & Library Wardrobe (Under Carpet)	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	9"x9" Gray w/ Black Streaks VFT - NOT OBSERVED	460	SF	Principal's Office & Vestibule (Under Carpet)	Chrysotile	MISC	No				
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9"x9" Beige w/ Brown Streaks VFT	450	SF	Auditorium Stage and Stage Stairs, Room 003	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Light Green w/ Brown Streaks VFT - NOT OBSERVED	500	SF	Room 001	Chrysotile	MISC	No				
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	9"x9" Red VFT	100	SF	Room 003	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	2'x4' White Wormy Ceiling Tile (Tectum)	750	SF	Room 302	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" White w/ Brown Streaks VFT Mastic	1302	SF	3rd Flr. Tchrs Toilet & Lounge, Rm 004., 108, Main Off., Tchrs Tlt Across from 109, Lunchroom	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Not observed in Teacher's Toilets on 3rd and 1st Floors. No abatement records on-site.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9"x9" Gray w/ Black Streaks VFT Mastic - NOT OBSERVED	420	SF	Principal's Office & Vestibule (under carpet)	Chrysotile	MISC	No				
3YR Inspector Comments: Not observed - wood floors instead - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Battleship Green Linoleum Mastic (Not Observed)	750	SF	Room 107	Assumed	MISC					
3YR Inspector Comments: Not Observed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Transite Wall Panel	640	SF	Kitchen Storage, Tank Room (Behind Drywall)	Chrysotile	TSI	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	2"x18" Border Black VFT	25	SF	Room 003	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" Brown w/ Red Streaks VFT - NOT OBSERVED	50	SF	Room 002 (Under Tile/Wood)	Chrysotile	MISC	No				
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9"x9" Green w/ White Streaks VFT	1000	SF	Room 205 Library (Under Carpet), Room 001 (Under HA # 07 & 26)	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Beige w/ White Streaks VFT Mastic	800	SF	Room 301 & Wardrobe	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Green w/ White Streaks VFT Mastic	1000	SF	Room 205 Library (Under Carpet), Room 001 (Under HA # 07 & 26)	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" Brown w/Tan Streaks VFT Mastic	1000	SF	Room 205 & Library Wardrobe	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Beige w/ Brown Streaks VFT Mastic	450	SF	Auditorium Stage and Stage Stairs, Room 003	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	2"x18" Border Black VFT Mastic	25	SF	Room 003	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9"x9" Red VFT Mastic	750	SF	Room 003	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	9"x9" Brown w/ Red Streaks VFT Mastic (Under Wood) - NOT OBSERVED	50	SF	Room 002	Chrysotile	MISC	No				
3YR Inspector Comments: 2005 Survey indicates abatement in Room 002											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Light Green w/ Brown Streaks VFT Mastic - NOT OBSERVED	500	SF	Room 002, 001	Chrysotile	MISC	No				
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12" x 12" Blue VFT	50	SF	Principals Toilet	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12" x 12" Blue VFT Mastic			Principals Toilet	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12" x 12" Peach VFT	1500	SF	Lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12" x 12" Peach VFT Mastic	1500		Lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011					Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12 x 12 inch Light Blue w/White Specks VFT	650	SF	Room 002	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31A	12 x 12 inch Light Blue w/White Specks VFT Mastic	650	SF	Room 002	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Carpet Mastic	1000	SF	Main Office, Rooms 005, 205	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: Not observed in Room 005 - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12 x 12 Tan Floor Tile	750	SF	Room 108	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Previous inspections identifies a different type of tile in this location											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12 x 12 Tan Floor Tile Mastic	750	SF	Room 108	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Previous inspections identifies a different type of tile in this location											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12 x 12 Grey Floor Tile	60	SF	Main Office, 1st and 2nd Floor Corridors	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12 x 12 Grey Floor Tile Mastic	60	SF	Main Office, 1st and 2nd Floor Corridors	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12 x 12 White Floor Tile	2500	SF	1st and 2nd Floor Corridors, 1st Boys and Girls Washrooms	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12 x 12 White Floor Tile Mastic	2500	SF	1st and 2nd Floor Corridors, 1st Boys and Girls Washrooms	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12 x 12 Yellow Floor Tile	24	SF	1st and 2nd Floor Corridors	Amosite	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Amosite	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Amosite	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12 x 12 Floor Tile Mastic	24	SF	1st and 2nd Floor Corridors	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12 x 12 Blue Floor Tile	24	SF	1st and 2nd Floor Corridors	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12 x 12 Blue Floor Tile Mastic	24	SF	1st and 2nd Floor Corridors	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12 x 12 Green Floor Tile	250	SF	Teacher's Toilets across Romm 109	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Area identified as a different tile											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12 x 12 Green Floor Tile Mastic	250	SF	Teacher's Toilets across Romm 109	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Area identified as a different tile											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12 x 12 Light Blue Floor Tile	650	SF	Room 002	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12 x 1 2 Light Floor Tile Mastic	650	SF	Room 002	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12 x 12 Royal Blue Floor Tile	1500	SF	Lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12 x 12 Royal Blue Floor Tile Mastic	1500	SF	Lunchroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Not previously identified											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12 x 12 Off White Floor Tile	900	SF	Room 001	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Area identified as a different tile											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12 x 12 Off White Floor Tile Mastic	900	SF	Room 001	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Area identified as a different tile											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Terrazzo	1800	SF	Room 005, vestibules, 1st Floor Toilet	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Not previously identified											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Ceramic Tile Grout	1300	SF	2nd Floor Restroom (206) and Basement Restroom	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments: New HA - Not previously identified											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Ceramic Tile Adhesive	1300	SF	2nd Floor Restroom (206) and Basement Restroom	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Not previously identified											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Mag Block Breeching	128	SF	Boiler Room	Chrysotile	TSI	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Aircell Pipe Insulation	150	LF	Passage by Rm. 003, Tank Room, Lunchroom/Kitchen	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: No damage - No abatement or O&M records on-site											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Aircell Pipe Insulation	40	LF	Passage by Rm. 003, Tank Room, Lunchroom/Kitchen	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: No damage - No abatement or O&M records on-site											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Mag Block Insulation	40	LF	Tank Room, Kitchen/Lunchroom, Engine Room, Boiler Room	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 23921

Page 19

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	MJP E/F/V on Mag Block Insulation	5	LF	Tank Room, Kitchen/Lunchroom, Engine Room, Boiler Room	Chrysotile	TSI	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Cardboard Pipe Insulation	90	LF	Passage by Room 003, Girls Play Room, Tank Room, Boiler Room Toilets	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	MJP E/F/V on Cardboard Pipe Insulation	7	LF	Passage by Room 003, Girls Play Room, Tank Room, Boiler Room Toilets	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
K	MJP E/F/V on Fiberglass Pipe Insulation	100	SF	Throughout (See Hatching)	Assumed	TSI	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											


HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Aircell Duct Insulation	1200	SF	Lunchroom/Kitchen	Chrysotile	TSI	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M	Mag Block Duct Insulation	1070	SF	Boiler Room	Chrysotile	TSI	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	TSI				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	TSI				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

All LEA Responsibilities, for this school, will be met.



Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125