

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Libby School
Address 5330 S. Loomis

Oracle Unit 24171 **Building ID** 4470
Region 4 **General Services Route** 43

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
10	Felt Packing	50	LF	Boiler Room	Assumed	MISC	Yes	None	0	LF		
<i>3YR Inspector Comments:</i>												
Condition Not Changed in Fall 2010			LF		Assumed	MISC				LF		
<i>Comments:</i>												
Condition Not Changed in Spring 2011			LF		Assumed	MISC				LF		
<i>Comments:</i>												
Fall 2011											YES	NO
Comment:												

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	Terra Blanca		SF	Attic	Assumed	MISC		Unknown	0	SF	
3YR Inspector Comments: 2007 Comment: Material was not located during this inspection.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	White Vapor Barrier Paper		SF	Attic	Assumed	MISC		Unknown			
3YR Inspector Comments: 2007 Comment: Material was not located during inspection.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9" x 9" Green Vinyl Floor Tile- ABATED 2002		SF	Room 406	Chrysotile	MISC	No				
3YR Inspector Comments: 2004 Comments - Removed on 01/02 by Luse Company.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1A2	12" x 12" Brown Vinyl Floor Tile w/White Speckles	800	SF	Rooms 401 and 401 Storage	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: Removed from Rooms 404 and 405 in Jan of 2002.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1A3	12"x12" Off-White Vinyl Floor Tile w/White & Brown	350	SF	Room 403	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9" x 9" Green Vinyl Floor Tile Mastic-ABATED 2002	0	SF	Room 406	Chrysotile	MISC	No				
3YR Inspector Comments: 2004 Comments - Removed on 01/02 by Luse Company.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12" x 12" Vinyl Floor Tile Mastic	6050	SF	Classrooms, Teacher's Lunchroom	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: This HA has been separated to correlate the mastic to the associated floor tiles.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Linoleum Mastic	1600	SF	Rooms 102 and 402	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Carpet Mastic	750	SF	Rooms 101	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New 12" x 12" Mint Green Floor Tile have been installed in Room 110. New carpet has been installed in the Main Office in January of 2002.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	Fire Door	2	SF	Basement	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Boiler Gasket	8	SF	Boiler Room	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Drywall Joint Compound	300	SF	Basement W. Corridor, Rooms 402 and 403, Office Supplies, Washrooms	Assumed	SURFACE	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	SURFACE				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	SURFACE				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Felt Under 12" x 12" Vinyl Floor Tile	0	SF	Room 401	Assumed	MISC	No	Unknown	0	SF	
3YR Inspector Comments: 2007 Comment: This material was not observed during this re-inspection.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Cardboard Pipe Insulation	100	LF	South Lunchroom, Storage, Pump Room	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments: 2004 Comment: Significant damage inside pump room tunnel; 2007 Comment: Material not observed in the tunnel.											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Fittings on Cardboard Pipe Insulation	25	LF	South Lunchroom, Storage, Pump Room	Assumed	TSI	Yes	None	0	LF	
3YR Inspector Comments: 2007 Comment: Material not observed in the tunnel.											
Condition Not Changed in Fall 2010			LF		Assumed	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Assumed	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Roof Flashing - Not AHERA	800	LF	Exterior Roof	Chrysotile	MISC	No				
3YR Inspector Comments: This material is not regulated by AHERA.											
Condition Not Changed in Fall 2010			LF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" Red Vinyl FT w/White Speckles Mastic	2700	SF	Rooms 201, 205, 208, and 2nd Floor Central West Corridor	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: This mastic was previously part of HA #25, but has been separated to correspond to the associated floor tile.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12" x 12" Brown Vinyl Floor Tile w/White Speckles	800	SF	Rooms 401 and 401 Storage	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: This mastic was previously part of HA #25, but has been separated to correspond to the associated floor tile; 2007 Comment: Material not observed in rooms 404 & 405 (previously identified).											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12"x12" Off-White Vinyl FT w/White & Brown Mastic	350	SF	Room 403	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: This mastic was previously part of HA #25, but has been separated to correspond to the associated floor tile.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12"x12" Off-White Vinyl FT w/Brown & White Mastic - REMOVED			Teacher's Lunchroom (402)	Chrysotile	MISC	No				
3YR Inspector Comments: 2001 Comments - This mastic was previously part of HA #25, but has been separated to correspond to the associated floor tile. 2004 Comments - Removed from Room 406 in 01/02 by Luse Company.; 2007 Comment: Material not observed during the 2007 re-inspection. 2010 - Material Removed, no new finishes											
Condition Not Changed in Fall 2010					Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	MISC					
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12" x 12" Mint Green Floor Tile	350	SF	Room 110	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12" x 12" Mint Green Floor Tile Mastic	350	SF	Room 110	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Carpet Adhesive	300	SF	Principle's Office (old Main Office)	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New Carpet was installed in January of 2002.											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
9	Felt Covering	50	LF	Boiler Room	Assumed	MISC	No	None	0	LF		
3YR Inspector Comments:												
Condition Not Changed in Fall 2010			LF		Assumed	MISC				LF		
Comments:												
Condition Not Changed in Spring 2011			LF		Assumed	MISC				LF		
Comments:												
Fall 2011											YES	NO
Comment:												

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

All LEA Responsibilities, for this school, will be met.

Lynn A. Crivello

Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 24171

Page 11

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125