

# Chicago Public Schools

## 6 Month Asbestos Surveillance

### 2015 - Fall

**School:** Henry D Lloyd School  
**Address:** 2103 N. Lamon Avenue

**Oracle Unit:** 24221  
**Region:** 02

**Building ID:** 4500  
**Mail Room:** 29

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**Asbestos Surveyor:** \_\_\_\_\_  
**Survey Date:** 11/13/2015  
**Email Address:** \_\_\_\_\_

A copy of the 2013/2014 notice to parents and staff regarding the asbestos management plan notifications was distributed via:  
 Each child's backpack   
 Notice printed in school's newsletter   
 Notice printed in school's calendar   
 Other website

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	9"x9" Brown VFT (NOT OBSERVED)	1000	SF	B-8(012) + Hall South of B-8 (012), 1907		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" Tan w/ White Speckles VFT	2200	SF	Rooms: 004, 208A, 307A, Gym 2nd Flr Boys & Girls Toilet and 2nd Flr Teachers Lounge & Toilet 1907		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged  
Comments:Gym floor to be abated and new floor put down over holiday. 004 has a few bubbles on tile.

2014- Spring: No Change  
Comments:small cracks

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:gym floor abated dec 2013

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	Green Swirl Linoleum	1000	SF	Room 010, 1913		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06	9"x 9" Brown VFT Mastic (NOT OBSERVED)	4500	SF	B-8(012) + Hall South of B-8 (012), 1907		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	12"x12" Tan w/ White Speckles VFT Mastic	550	SF	Room 102, 1913		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: Damaged  
Comments:breaking apart

2014 - Fall: Damaged  
Comments:TILES POPPING UP

2015- Spring: Damaged  
Comments:tiles breaking apart and underlayment is damaged

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	Green Swirl Linoleum Mastic	1000	SF	Room 010, 1913		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12"x12" Tan w/ White Speckles VFT Mastic	2200	SF	Rooms: 004, 208A, 307A, Gym, 2nd Flr Boys & Girls Toilet and 2nd Flr Teachers Lounge & Toilet 1907		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged  
Comments:see 04

2014- Spring: Abated  
Comments:gym was abated and new floor layed down

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Tan w/ White Speckles VFT	550	SF	Room 102, 1913		Miscellaneous		None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: Damaged  
Comments:breaking apart

2014 - Fall: No Change  
Comments:

2015- Spring: Damaged  
Comments:tiles breaking apart and underlayment damaged

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Hard Coat Plaster	100000	SF	Throughout, 1907		Miscellaneous	Yes	None			<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged  
Comments:310 has plaster damage

2014- Spring: Deteriorated  
Comments:plaster breaking up in multiple mplaces

2014 - Fall: Damaged  
Comments:PLASTER BREAKING UP IN MULTIPLE ROOMS

2015- Spring: Damaged  
Comments:most plaster is in poor condition

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Hard Coat Plaster	20000	SF	Throughout, 1913		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: Deteriorated  
Comments:plaster breaking up in multiple mplaces

2014 - Fall: Damaged  
Comments:PLASTER BREAKING UP IN MULTIPLE ROOMS

2015- Spring: Damaged  
Comments:most plaster is in poor condition

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" White w/ Brown Speckles VFT	800	SF	Room 308, 1907		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" White w/ Brown Speckles VFT Mastic	800	SF	Room 308, 1907		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Gray w/ White Speckled VFT	600	SF	Room 004 (Parents Room), 1907		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Gray w/ White Speckled VFT Mastic	600	SF	Room 004 (Parents Room), 1907		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9"x9" Green w/ White Streaks VFT(ABATED)			Room 106, 1907							<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Abated  
Comments:not in room

2014- Spring: Other  
Comments:no longer in room

2014 - Fall: Other  
Comments:NOT 9 X 9

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x9" Green w/ White Streaks VFT Mastic (ABATED)			Room 106, 1907							<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Abated  
Comments: not in room

2014- Spring: Other  
Comments: no longer in room

2014 - Fall: Other  
Comments: NOT 9X9

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9"x9" Orange w/ White Streaks VFT (ABATED)			Room 106, 1907							<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Abated  
Comments: not in room

2014- Spring: Other  
Comments: no longer in room

2014 - Fall: Other  
Comments: NOT 9X9

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	9"x9" Orange w/ White Streaks VFT Mastic (ABATED)			Room 106, 1907							<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Abated  
Comments: not in room

2014- Spring: Other  
Comments: no longer in room

2014 - Fall: Other  
Comments: NOT 9X9

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Gray w/ White Streaks VFT	500	SF	Lunch Room Office, Room 310 & Wardrobe, 1913		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged  
Comments: t310 tile and underlayment starting to pop up.

2014- Spring: No Change  
Comments:

2014 - Fall: Damaged  
Comments: 310 TILES POPPING. 15-NW-06030748 PENDING LFM

2015- Spring: Damaged  
Comments: 9x9 tiles missing in spots and black mastic is exposed

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9"x9" Gray w/ White Streaks VFT Mastic	1250	SF	Lunch Room Office, Room 310 & Wardrobe, 1913		Miscellaneous	No	None	0		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

2013 - Fall: Damaged  
Comments:310 tile and underlayment popping up.

2014- Spring: No Change  
Comments:

2014 - Fall: Damaged  
Comments:310 TILES POPPING MASTIC EXPOSED.14-NW-0155927 CANCELED LFM

2015- Spring: Damaged  
Comments:310

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Gray w/ White Speckled VFT (NOT OBSERVED)			Kitchen, Lunchroom 1913							<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: Damaged  
Comments:tiles listed not observed but floors in 006-007 is in bad condition. FM called perry and associates to inspect.

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Gray w/ White Speckled VFT Mastic - NOT OBSERVED			Kitchen, Lunchroom 1913							<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: Damaged  
Comments:floor in bad condition

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	2'x4' Groove Pattern Ceiling Tile	300	SF	2nd Floor: Boy's Toliet, Lounge, & Teacher's Toliet 1907		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	2'x4' Dot/Groove Pattern Ceiling Tile	50	SF	2nd Floor: Boy's Toilet, & Teacher's Lounge, Teacher's Toilet 1907		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	2'x4' Horizontal Groove Pattern Ceiling Tile	20	SF	2nd Floor Boy's Toilet 1907		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	2'x4' White Textured Speckled Ceiling Tile	80	SF	Room 004 - 1907		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	2' x 4' Dot/Groove Pattern Ceiling Tile	32000	SF	Throughout, 1999 Annex		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12" x 12" Black with Light Grey Streaks VFT	9000	SF	Throughout, 1999 Annex		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31 A	12" x 12" Black with Light Grey Streaks VFT Mastic	9000	SF	Throughout, 1999 Annex		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Orange with White Streaks VFT	2000	SF	Throughout, 1999 Annex		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32 A	12" x 12" Orange with White Streaks VFT Mastic	2000	SF	Throughout, 1999 Annex		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12" x 12" Gray with Dark Gray Streaks VFT	10000	SF	Throughout, 1999 Annex		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33 A	12" x 12" Gray with Dark Gray Streaks VFT Mastic	10000	SF	Throughout, 1999 Annex		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Drywall	1400	SF	Room 313, 314, 315, 213, 214, 215, 2nd and 3rd Floor Boy's/Girl's/Teacher's Toilets, 1999 Annex		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Drywall Joint Compound	100	LF	Room 313, 314, 315, 213, 214, 215, 2nd and 3rd Floor Boy's/Girl's/Teacher's Toilets, 1999 Annex		Miscellaneous	Yes	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Baseboard Mastic	5000	LF	Throughout, 1999 Annex		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36 A	Baseboard	5000	LF	Throughout, 1999 Annex		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Carpet Mastic	3200	SF	Room 226, 125, 125 A, 125 B, 126 A, 1999 Annex		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12 x 12 Maroon VFT	750	SF	Room 106, 1907		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38A	12 x 12 Maroon VFT Mastic	750	SF	Room 106		Miscellaneous	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	2' x 4' Ceiling Tile with 2' x 2' Patern	400	SF	2nd and 3rd Floor Corridors to Annex Building 1907		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	Carpet Mastic (Red Carpet)	500	SF	Auditorium - 1907		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: Damaged  
Comments:carpet bubbling up and needs to be replaced

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**  
**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12" x 12" White with Gray Specks	1200	SF	Room 102 & Corridor to Room 012 - 1907		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: Damaged  
Comments:breaking apart

2014 - Fall: Damaged  
Comments:TILES POPPING UP

2015- Spring: Damaged  
Comments:tiles popping up and underlayment is damaged

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12" x 12" White with Gray Specks Matic	1200	SF	Room 102 & Corridor to Room 102 - 1907		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: Damaged  
Comments:breaking apart

2014 - Fall: Damaged  
Comments:TILES POPPING UP

2015- Spring: Damaged  
Comments:tiles popping up and underlayment is damaged

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	Terrazo White with Brown Specks		SF	Throughout - Annex 1999		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	Terrazo Gray with Black Specks		SF	Throughout - Annex 1999		Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**



HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Terrazo Red with Gray Specks		SF			Miscellaneous	No	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Aircell Pipe Insulation	15	LF	Boiler Room-Toilet & Storage Room, 1907		TSI	Yes	Loc	3		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Fireproofing	10000	SF	Above Ceiling on I-Beams, 1999 Annex		Surface	No	None	0		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2015- Spring: No Change  
Comments:

2015 - Fall: No Change  
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
H	Boiler Gasket	30	LF	Boiler Room		Miscellaneous	Yes	None			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2013 - Fall: No Change  
Comments:

2014- Spring: No Change  
Comments:

2014 - Fall: No Change  
Comments:

2015 - Fall: No Change  
Comments:

2015- Spring: No Change  
Comments:

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*ALL LEA Responsibilities, for this school, will be met.*

  

---

Lynn A. Crivello

***VFT = Vinyl Floor Tile***

***Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.***

NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Henry D Lloyd School

Date: 11/16/2015

---

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2013. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other. website
- 

A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**