

# Chicago Public Schools

## 6 Month Asbestos Surveillance

Fall 2011

**School**    Otis School  
**Address**    525 N. Armour Street

**Oracle Unit** 24791    **Building ID** 5220  
**Region** 2    **General Services Route** 35

*Asbestos Surveyor:* \_\_\_\_\_

*Survey Date:* \_\_\_\_\_

*E-mail Address:* \_\_\_\_\_

**CHECK HERE IF NO CHANGE TO ASBESTOS**

**A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:**

*Each child's backpack*   
  *Notice printed in school's newsletter/calendar*   
  *Other* \_\_\_\_\_

**Principal Signature** \_\_\_\_\_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	<b>Change in Assessment Category</b>
09	12"x12" Gray with White Streaks Floor Tile	2400	SF	1st, 2nd & 3rd Floor Corridors - 1916 Bldg.	Chrysotile	MISC	No	None	0	SF	
<i>3YR Inspector Comments: These tiles are deteriorating by stairs</i>											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
<i>Comments:</i>											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
<i>Comments:</i>											
<b>Fall 2011</b>											<b>YES      NO</b>
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 24791

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Multiple Color Linoleum (NOT OBSERVED)	550	SF	Girl's Playroom & Ladies Dressing Room near Girl's Playroom - 1916 Bldg.	Chrysotile	MISC					
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Gray with White Streaks Floor Tile Mastic	2400	SF	1st, 2nd & 3rd Floor Corridors - 1916 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	Multiple Color Linoleum Mastic (NOT OBSERVED)	550	SF	Girl's Playroom & Ladies Dressing Room near Girl's Playroom - 1916 Bldg.	Chrysotile	MISC					
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Green Linoleum	750	SF	Room 205 - 1893 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Green Linoleum Mastic	750	SF	Room 205 - 1893 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12"x12" Off-White with Speckles Floor Tile	1000	SF	Basement Corridor - 1893 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Off-White with Speckles Floor Tile Mastic	1000	SF	Basement Corridor - 1893 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	Hard Coat Plaster	20000	SF	Throughout Building - 1893 Bldg.	Assumed	SURFACE	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	SURFACE				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	SURFACE				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Hard Coat Plaster	15000	SF	Throughout Building - 1916 Bldg.	Assumed	SURFACE	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	SURFACE				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	SURFACE				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	MJP E/F/V on Fiberglass Pipe Insulation	150	LF	Boys Basement Toilet	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Light Brown with Speckles Floor Tile	3000	SF	1st, 2nd & 3rd Floor Corridors - 1893 Bldg.	Assumed	MISC	No	Dist	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Light Brown with Speckles Floor Tile Mastic	3000	SF	1st, 2nd & 3rd Floor Corridors - 1893 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Gray with White Streaks Floor Tile (NOT OBSERVED)	3600	SF	Room 205 - 1893 Bldg.	Chrysotile	MISC					
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Gray with White Streaks Floor Tile Mastic (NOT OBSERVED)	3600	SF	Room 205 - 1893 Bldg.	Chrysotile	MISC					
3YR Inspector Comments: Not observed - No abatement records on-site											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC					
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC					
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" Light Brown with Pink & Dark Streaks Floor Tile	1200	SF	Rooms 204 & 408 - 1893 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Light Brown with Pink & Dark Streaks Floor Tile Mastic	1200	SF	Rooms 204 & 408 - 1893 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	2x4' White Ceiling Tile	750	SF	Room 407 - 1893 Bldg.	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12"x12" Light Beige w/Speckles Floor Tile	1500	SF	Room 105 & Primary Gymnasium (110) - 1893 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	12"x12" Light Beige with Speckles Floor Tile Mastic	1500	SF	Room 105 & Primary Gymnasium (110) - 1893 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" Dark Gray with White Streaks Floor Tile	700	SF	Lunchroom 3 - 1916 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" Dark Gray with White Streaks Floor Tile Mastic	700	SF	Lunchroom 3 - 1916 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Burlap/Canvas	20000	SF	2nd & 3rd Floor Corridors, 2nd & 3rd Floor Staircase - 1916 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" Light Brown w/Speckles VFT	2100	SF	Room 213 & Closet - 1916 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" Light Brown with Speckles Floor Tile Mastic	2100	SF	Room 213 & Closet - 1916 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12"x12" Off-White Floor Tile	1500	SF	Basement Corridor & Girl's Playroom - 1916 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Off-White Floor Tile Mastic	1500	SF	Basement Corridor & Girl's Playroom - 1916 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	MJP E/F/V on Fiberglass Pipe Insulation	50	LF	Girls Playroom - 1916 Bldg.	Chrysotile	TSI	Yes	None	0	LF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			LF		Chrysotile	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011			LF		Chrysotile	TSI				LF	
Comments:											
<b>Fall 2011</b>											YES NO
Comment:											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Particle Board	1800	SF	Boiler Room - Field House	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12"x12" Ceiling Tile	750	SF	Room 304 (Library) - 1893 Bldg.	Assumed	MISC	Yes	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53A	12"x12" Ceiling Tile Adhesive	1200	SF	Room 304 (Library) - 1893 Bldg.	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: See drawing for HA 53 for location											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	12"x12" Brown with White Streaks Floor Tile	2500	SF	Kitchen, Lunch Room Store Room - 1916 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments: The lunchroom tiles show deterioration											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12"x12" Brown with White Streaks Floor Tile Mastic	2500	SF	Kitchen, Lunch Room Store Room- 1916 Bldg.	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	12"x12" Sand Floor Tile	2500	SF	Main Office, Principals Office & Storage, 1st through 4th Floor Faculty Toilet, Room 201 - 1916 Bldg	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**


HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	12"x12" Sand Floor Tile Mastic	2500	SF	Main Office, Principals Office & Storage, 1st through 4th Floor Faculty Toilet, Room 201 - 1916 Bldg	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	Blue Multicolored Carpet Mastic	1400	SF	Teachers Lounge and Room 104	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments: New HA - Newly installed											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
<b>Fall 2011</b>											YES NO
<b>Comment:</b>											

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

*All LEA Responsibilities, for this school, will be met.*



*Lynn A. Crivello*

**VFT = Vinyl Floor Tile**

**Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.**

Oracle Unit: 24791

Page 14

**Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125**

**NOTICE TO PARENTS AND STAFF REGARDING THE  
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: \_\_\_\_\_

Date: \_\_\_\_\_

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE  
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

*VFT = Vinyl Floor Tile*

*Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.*

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125