

Chicago Public Schools

6 Month Asbestos Surveillance

Fall 2011

School Reavis School
Address 834 E. 50th St.

Oracle Unit 25091 **Building ID** 5580
Region 4 **General Services Route** 42

Asbestos Surveyor: _____

Survey Date: _____

E-mail Address: _____

CHECK HERE IF NO CHANGE TO ASBESTOS

A copy of the 2011/2012 notice to parents and staff regarding the asbestos management plan notification was distributed via:

Each child's backpack
 Notice printed in school's newsletter/calendar
 Other _____

Principal Signature _____

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
1	Plaster	500	SF	Boiler Room and Some Janitor Closets and Storage Rooms	Chrysotile	SURFACE	No	None		SF	
<i>3YR Inspector Comments:</i>											
Condition Not Changed in Fall 2010			SF		Chrysotile	SURFACE				SF	
<i>Comments:</i>											
Condition Not Changed in Spring 2011			SF		Chrysotile	SURFACE				SF	
<i>Comments:</i>											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 25091

Page 1

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	9"x9" White Floor Tile w/Grey & Blk Specks Mastic	100	SF	Office Vault	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9" x 9" White Floor Tile w/Black Specks Mastic	500	SF	Eng.'s Office, Storage, Washroom , 1962 Storage Adjacent to Teachers Lounge, Gym Offices, & Store R	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12" x 12" Grey/White Floor Tile	80	SF	Room 101 Washroom 1st floor Teacher's Restroom	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12" x 12" Grey/White Floor Tile Mastic	80	SF	Room 101 Washroom and 2nd Floor Janitor's Closet in 1958 Building	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12" x 12" Brown Floor Tile	1200	SF	1958 Building 2nd Floor Corridor & Stairwells	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12" x 12" Brown Floor Tile Mastic	1200	SF	1958 Building 2nd Floor Corridor & Stairwells	Chrysotile	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	Interior Caulk			1958 Boiler Room	Chrysotile	MISC	No	None	0	LF	
3YR Inspector Comments: 2007 Comment: This material was not located during the 2007 re-inspection.					2010- Not observed.						
Condition Not Changed in Fall 2010					Chrysotile	MISC					LF
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	MISC					LF
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Exterior Caulk Non AHERA			1958 Building	Chrysotile						
3YR Inspector Comments:											
Condition Not Changed in Fall 2010					Chrysotile						
Comments:											
Condition Not Changed in Spring 2011					Chrysotile						
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Chalkboard/Posterboard Adhesive	3500	SF	Throughout All Classrooms	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC					SF
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC					SF
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	9" x 9" White Floor Tile w/Grey & Black Specks	100	SF	Office Vault	Assumed	MISC	No	None	0	SF	
3YR Inspector Comments:											
Condition Not Changed in Fall 2010			SF		Assumed	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Assumed	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	Acoustical Plaster			1962 Building	Chrysotile	SURFACE	No	None	0	SF	
3YR Inspector Comments: 2004/2007 Comments - Found no exposed plaster. This plaster may be above the ceiling panels.											
Condition Not Changed in Fall 2010					Chrysotile	SURFACE				SF	
Comments:											
Condition Not Changed in Spring 2011					Chrysotile	SURFACE				SF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
9	9" x 9" White Floor Tile w/Black Specks	500	SF	Eng.'s Office, Storage, Washroom, 1962 Storage Adjacent to Teachers Lounge, Gym Offices, Store Rms	Chrysotile	MISC	No	Loc	8	SF	
3YR Inspector Comments: Damage in washroom storage room.											
Condition Not Changed in Fall 2010			SF		Chrysotile	MISC				SF	
Comments:											
Condition Not Changed in Spring 2011			SF		Chrysotile	MISC				SF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Oracle Unit: 25091

Page 5

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B	Insulation on Joints of Fiberglass Pipe Insulation			1958 Building	Assumed	TSI	Yes	None	0	LF	
3YR Inspector Comments: 2007 Comment: This material was not located during the 2007 re-inspection. This material may exist in inaccessible locations.											
Condition Not Changed in Fall 2010					Assumed	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011					Assumed	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	Paperwrap Pipe Insulation			1958 Building	Assumed	TSI	Yes	None	0	LF	
3YR Inspector Comments: 2007 Comment: This material was not located during the 2007 re-inspection. This material may exist in inaccessible locations.											
Condition Not Changed in Fall 2010					Assumed	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011					Assumed	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Insulation on Joints of Paperwrap Pipe Insulation			1958 Building	Assumed	TSI	Yes	None	0	LF	
3YR Inspector Comments: 2007 Comment: This material was not located during the 2007 re-inspection. This material may exist in inaccessible locations.											
Condition Not Changed in Fall 2010					Assumed	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011					Assumed	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Aircell Pipe Insulation			1958 Building	Assumed	TSI	Yes	None	0	LF	
3YR Inspector Comments: 2007 Comment: This material was not located during the 2007 re-inspection. This material may exist in inaccessible locations.											
Condition Not Changed in Fall 2010					Assumed	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011					Assumed	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Insulation on Joints of Aircell Pipe Insulation			1958 Building	Assumed	TSI	Yes	None	0	LF	
3YR Inspector Comments: 2007 Comment: This material was not located during the 2007 re-inspection. This material may exist in inaccessible locations.											
Condition Not Changed in Fall 2010					Assumed	TSI				LF	
Comments:											
Condition Not Changed in Spring 2011					Assumed	TSI				LF	
Comments:											
Fall 2011											YES NO
Comment:											

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

All LEA Responsibilities, for this school, will be met.

Lynn A. Crivello

Lynn A. Crivello

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

**NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION**

School: _____

Date: _____

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all schools every three years. The last inspection was completed in 2010. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter or calendar and sent home with each child.
- Other – Please indicate how this notice was delivered to parents and staff.

**A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.**

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Please send a copy of this report to Lynn Crivello, 125 S. Clark St., 17th Floor, GSR #125